

The EDR Corridor Study Report

**Study Area 1
I-275
Tampa, Florida**

April 10, 1996

Inquiry number 48314



**Environmental
Data
Resources, Inc.**

Creators of Toxicheck/®

The Source For Environmental Risk Management Data

3530 Post Road
Southport, Connecticut 06490

Nationwide Customer Service

Telephone: 1-800-352-0050

Fax: 1-800-231-6802

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer

This Report contains information obtained from a variety of public sources and EDR makes no representation or warranty regarding the accuracy, reliability, quality, or completeness of said information or the information contained in this report. The customer shall assume full responsibility for the use of this report.

No warranty of merchantability or of fitness for a particular purpose, expressed or implied, shall apply and EDR specifically disclaims the making of such warranties. In no event shall EDR be liable to anyone for special, incidental, consequential or exemplary damages.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM RECORDS:

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

Source: EPA/NTIS

Telephone: 703-603-8904

CERCLIS: CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 11/30/95

Date Made Active at EDR: 02/26/96

Date of Data Arrival at EDR: 01/15/96

Elapsed ASTM days: 42

ERNS: Emergency Response Notification System

Source: EPA/NTIS

Telephone: 202-260-2342

ERNS: Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/95

Date Made Active at EDR: 02/19/96

Date of Data Arrival at EDR: 01/26/96

Elapsed ASTM days: 24

NPL: National Priority List

Source: EPA

Telephone: 703-603-8852

NPL: National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, it is EDR's policy to plot NPL sites greater than approximately 500 acres in size as areas (polygons). Sites smaller in size are point-geocoded at the site's address.

Date of Government Version: 09/01/95

Date Made Active at EDR: 10/25/95

Date of Data Arrival at EDR: 10/17/95

Elapsed ASTM days: 8

RCRIS: Resource Conservation and Recovery Information System

Source: EPA/NTIS

Telephone: 703-308-7907

RCRIS: Resource Conservation and Recovery Information System. RCRIS includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Date of Government Version: 10/31/95

Date Made Active at EDR: 01/12/96

Date of Data Arrival at EDR: 12/15/95

Elapsed ASTM days: 28

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FEDERAL NON-ASTM RECORDS:

CONSENT: Superfund (CERCLA) Consent Decrees

Source: EPA Regional Offices

Telephone: Varies

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: Varies

Date of Next Scheduled Update: 09/01/95

CORRACTS: Corrective Action Report

Source: EPA

Telephone: 703-308-7907

CORRACTS: CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 04/10/95

Date of Next Scheduled Update: 06/17/96

FINDS: Facility Index System

Source: EPA/NTIS

Telephone: 800-908-2493

FINDS: Facility Index System. FINDS contains both facility information and "pointers" to other sources that contain more detail. These include: RCRIS, PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]), CERCLIS, DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), FRDS (Federal Reporting Data System), SIA (Surface Impoundments), CICS (TSCA Chemicals in Commerce Information System), PADS, RCRA-J (medical waste transporters/disposers), TRIS and TSCA.

Date of Government Version: 09/30/95

Date of Next Scheduled Update: 07/08/96

HMIRS: Hazardous Materials Information Reporting System

Source: U.S. Department of Transportation

Telephone: 202-366-4555

HMIRS: Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/95

Date of Next Scheduled Update: 07/29/96

MLTS: Material Licensing Tracking System

Source: Nuclear Regulatory Commission

Telephone: 301-415-7169

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/01/95

Date of Next Scheduled Update: 07/15/96

NPL LIENS: Federal Superfund Liens

Source: EPA

Telephone: 205-564-4267

NPL LIENS: Federal Superfund Liens. Under the authority granted the USEPA by the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner receives notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/91

Date of Next Scheduled Update: 05/27/96

PADS: PCB Activity Database System

Source: EPA

Telephone: 202-260-3992

PADS: PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 10/14/94

Date of Next Scheduled Update: 05/20/96

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

RAATS: RCRA Administrative Action Tracking System

Source: EPA

Telephone: 202-564-4104

RAATS: RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA.

Date of Government Version: 04/17/95

Date of Next Scheduled Update: 06/17/96

ROD: Records Of Decision

Source: NTIS

Telephone: 703-416-0703

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 03/31/95

Date of Next Scheduled Update: 06/17/96

TRIS: Toxic Chemical Release Inventory System

Source: EPA/NTIS

Telephone: 202-260-2320

TRIS: Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/92

Date of Next Scheduled Update: 07/01/96

TSCA: Toxic Substances Control Act

Source: EPA/NTIS

Telephone: 202-260-1444

TSCA: Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site. USEPA has no current plan to update and/or re-issue this database.

Date of Government Version: 01/31/95

Date of Next Scheduled Update: 06/17/96

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STATE OF FLORIDA ASTM RECORDS:

LUST: PCT01 - Petroleum Contamination Detail Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

LUST: Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 01/23/96

Date Made Active at EDR: 03/25/96

Date of Data Arrival at EDR: 02/12/96

Elapsed ASTM days: 42

SHWS: Florida's State-Funded Action Sites

Source: Department of Environmental Protection

Telephone: 904-488-0190

SHWS: State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 08/24/95

Date Made Active at EDR: 09/13/95

Date of Data Arrival at EDR: 09/05/95

Elapsed ASTM days: 8

SWF/LS: Facility Directory (Solid Waste Facilities)

Source: Department of Environmental Protection

Telephone: 904-922-7121

SWF/LS: Solid Waste Facilities/Landfill Sites. SWF/LS type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Section 2004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 01/16/96

Date Made Active at EDR: 03/01/96

Date of Data Arrival at EDR: 02/05/96

Elapsed ASTM days: 25

UST: ST102 - Facility/Owner/Tank Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

UST: Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 01/23/96

Date Made Active at EDR: 03/14/96

Date of Data Arrival at EDR: 02/12/96

Elapsed ASTM days: 31

STATE OF FLORIDA NON-ASTM RECORDS:

AST: ST102 - Facility/Owner/Tank Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

AST: Registered Aboveground Storage Tanks.

Date of Government Version: 01/23/96

Date of Next Scheduled Update: 05/06/96

CATTLE DIPPING VATS: Cattle Dipping Vats

Source: Department of Environmental Protection

Telephone: 904-488-3601

Date of Government Version: 05/01/94

Date of Next Scheduled Update: 05/20/96

FL SITES: Sites List

Source: Department of Environmental Protection

Telephone: 904-922-7121

Date of Government Version: 12/31/89

Date of Next Scheduled Update: N/A

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FLORIDA COUNTY RECORDS

DADE COUNTY:

Dade County Storage Tanks

Source: Department of Environmental Resource Management
Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

Dade County Enforcement Case Tracking System

Source: Department of Environmental Resources Management
Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

Dade County Industrial Waste Type 2-4

Source: Department of Environmental Resources Management
Telephone: 305-372-6755

Facilities which generate, dispose of, store, use, discharge, handle or reclaim any liquid waste other than domestic sewage, any hazardous waste or any hazardous material (except factory prepackaged products intended primarily for domestic use or consumption).

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

Dade County Industrial Waste Type 5

Source: Department of Environmental Resources Management
Telephone: 305-372-6755

Facilities which generate, dispose of, store, use, discharge, handle or reclaim any liquid waste other than domestic sewage, any hazardous waste or any hazardous material (except factory prepackaged products intended primarily for domestic use or consumption).

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

Industrial Waste Type 6

Source: Department of Environmental Resources Management
Telephone: 305-372-6755

Sites located on a septic tank inside a well field protection area.

Date of Government Version: 11/01/95

Date of Next Scheduled Update: 07/01/96

Dade County Industrial Waste Permit

Source: Department of Environmental Resources Management
Telephone: 305-372-6755

Date of Government Version: 11/01/95

Date of Next Scheduled Update: 07/01/96

Dade County Air Permit

Source: Department of Environmental Resources Management
Telephone: 305-372-6755

Date of Government Version: 11/01/95

Date of Next Scheduled Update: 07/01/96

Dade County Fuel Spill Cases

Source: Department of Environmental Resources Management
Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Dade County Hazardous Waste

Source: Department of Environmental Resources Management

Telephone: 305-372-6755

Sites with documented soil or groundwater contamination.

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

BROWARD COUNTY:

Broward County Storage Tanks

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

Date of Government Version: 08/12/94

Date of Next Scheduled Update: 06/10/96

Early Detection Incentive

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

EDI sites are leaking underground petroleum tanks covered under the state cleanup program.

Date of Government Version: 01/01/96

Date of Next Scheduled Update: 06/10/96

Environmental Assessment

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

EA sites are contaminated sites (non-leaking underground petroleum tanks) under the state cleanup program.

Date of Government Version: 01/01/96

Date of Next Scheduled Update: 06/10/96

Hazmat

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

HM sites use or store greater than 25 gallons of hazardous materials per month.

Date of Government Version: 01/01/96

Date of Next Scheduled Update: 06/10/96

Notice Of Violation

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

Date of Government Version: 08/12/94

Date of Next Scheduled Update: 06/10/96

ESCAMBIA COUNTY:

Facility/Owner/Tank/Contamination Information Report

Source: Environmental Health Services

Telephone: 904-444-8990

Date of Government Version: 02/05/96

Date of Next Scheduled Update: 05/06/96

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Historical and Other Database(s)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Former Manufactured Gas (Coal Gas) Sites: The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

DELISTED NPL: Delisted NPL Sites

Source: EPA

Telephone: 703-603-8769

DELISTED NPL: The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

NFRAP: No Further Remedial Action Planned

Source: EPA/NTIS

Telephone: 703-416-0702

NFRAP: As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

FRDS: Federal Reporting Data System

Source: EPA/Office of Drinking Water

Telephone: 202-260-2805

FRDS provides information regarding public water supplies and their compliance with monitoring requirements, maximum contaminant levels (MCL's), and other requirements of the Safe Drinking Water Act of 1986.

Area Radon Information: The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

Oil/Gas Pipelines/Electrical Transmission Lines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines and electrical transmission lines.

Sensitive Receptors: There are individuals who, due to their fragile immune systems, are deemed to be especially sensitive to environmental discharges. These typically include the elderly, the sick, and children. While the exact location of these sensitive receptors cannot be determined, EDR indicates those facilities, such as schools, hospitals, day care centers, and nursing homes, where sensitive receptors are likely to be located.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

USGS Water Wells: In November 1971 the United States Geological Survey (USGS) implemented a national water resource information tracking system. This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on more than 900,000 wells, springs, and other sources of groundwater.

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1994 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Water Dams: National Inventory of Dams
Source: Federal Emergency Management Agency
Telephone: 202-646-2801
WATER DAMS: National computer database of more than 74,000 dams maintained by the Federal Emergency Management Agency.

Wetlands Data: This data was obtained by EDR from the National Wetlands Inventory (NWI) in 1994. Data depicts wetland areas as defined by NWI.

State of Florida Water Well and Sample Database
Source: FL Department of Environmental Protection, Groundwater Quality Monitoring

St. Johns River District Well Data
Source: St. Johns River Water Management District

Southwest District Water Use Data
Source: Southwest Water Management District

Well Construction Permitting System: Water Well Locations in Northwest Florida Water Management District
Source: Northwest Florida Water Management District
Telephone: 904-539-5999

Florida Sinkholes
Source: Department of Environmental Protection, Geological Survey
The sinkhole data was gathered by the Florida Sinkhole Research Institute, University of Florida.

MAP FINDINGS SUMMARY

<u>Database</u>	<u>Total Plotted</u>
NPL	0
Delisted NPL	0
RCRIS-TSD	1
State Haz. Waste	0
CERCLIS	0
CERC-NFRAP	0
CORRACTS	0
State Landfill	0
LUST	90
UST	132
AST	7
RAATS	0
RCRIS Sm. Quan. Gen.	53
RCRIS Lg. Quan. Gen.	0
HMIRS	0
PADS	1
ERNS	0
FINDS	63
TRIS	0
NPL Liens	0
TSCA	0
MLTS	0
Florida Sites	0
Florida Enforcement	0
Florida Ind. Waste	0
Env. Assessment	0
Florida Cattle	0
FL Haz. Mat.	0
FL Notice of Viol.	0
FL Air Permit	0
Industrial Waste Permits	0
ROD	0
CONSENT	0
Coal Gas	0

* Sites may be listed in more than one database

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Coal Gas Site Search: No site was found in a search of Real Property Scan's ENVIROHAZ database.

1	TAMPA,CITY-DPW FLEET MAINT.-DIV. #3 2609 N ROME AVE TAMPA, FL 33607	UST	U001354875 N/A
---	---	-----	-------------------

UST:

Facility ID:	298625669	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238765
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Instal. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT.-DIV. #3 (Continued)

U001354875

Facility ID:	298625669	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238765
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT.-DIV. #3 (Continued)

U001354875

Facility ID:	298625669	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238765
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT.-DIV. #3 (Continued)

U001354875

Facility ID:	298625669	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238765
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

2

TERRELL OIL
2101 N BOULEVARD
TAMPA, FL 33602

UST
LUST

U001356315
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TERRELL OIL (Continued)

U001356315

LUST:

Facility ID:	9101587	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	01/25/91
Tracking Number:	Not reported	Score:	026 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05033		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

2

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TERRELL OIL (Continued)

U001356315

UST:

Facility ID:	299101587	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TERRELL, GRADY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910404	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	MATASSINI, PASQUALE		
	PO BOX 2652		
	TAMPA, FL 336012652		
Owner's Phone:	8132290829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TERRELL OIL (Continued)

U001356315

Facility ID:	299101587	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TERRELL, GRADY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910404	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	MATASSINI, PASQUALE		
	PO BOX 2652		
	TAMPA, FL 336012652		
Owner's Phone:	8132290829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

2

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TERRELL OIL (Continued)

U001356315

Facility ID:	299101587	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TERRELL, GRADY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910404	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	Not reported		
Owner:	MATASSINI, PASQUALE		
	PO BOX 2652		
	TAMPA, FL 336012652		
Owner's Phone:	8132290829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TERRELL OIL (Continued)

U001356315

Facility ID:	299101587	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TERRELL, GRADY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910404	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	Not reported		
Owner:	MATASSINI, PASQUALE		
	PO BOX 2652		
	TAMPA, FL 336012652		
Owner's Phone:	8132290829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

2

MATASSINI PROPERTY
2121 N BOULEVARD
TAMPA, FL 33602

UST
LUST

U001354679
N/A

2

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MATASSINI PROPERTY (Continued)

U001354679

LUST:

Facility ID:	8625460	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132290829	Discovery Date:	01/25/91
Tracking Number:	Not reported	Score:	021 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05497		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

2

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MATASSINI PROPERTY (Continued)

U001354679

UST:

Facility ID:	298625460	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MAT'S SERVICE STATION, INC.		
Contact:	Not reported	Facility Phone:	8132290829
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PAT MATASSINI		
Owner:	MATS SERVICE STATION INC PO BOX 2652 TAMPA, FL 336012652		
Owner's Phone:	8132290829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

2

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MATASSINI PROPERTY (Continued)

U001354679

Facility ID:	298625460	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MAT'S SERVICE STATION, INC.		
Contact:	Not reported	Facility Phone:	8132290829
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	PAT MATASSINI		
Owner:	MATS SERVICE STATION INC PO BOX 2652 TAMPA, FL 336012652		
Owner's Phone:	8132290829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MATASSINI PROPERTY (Continued)

U001354679

Facility ID:	298625460	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MAT'S SERVICE STATION, INC.		
Contact:	Not reported	Facility Phone:	8132290829
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	PAT MATASSINI		
Owner:	MATS SERVICE STATION INC		
	PO BOX 2652		
	TAMPA, FL 336012652		
Owner's Phone:	8132290829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MATASSINI PROPERTY (Continued)

U001354679

Facility ID:	298625460	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MAT'S SERVICE STATION, INC.		
Contact:	Not reported	Facility Phone:	8132290829
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	PAT MATASSINI		
Owner:	MATS SERVICE STATION INC		
	PO BOX 2652		
	TAMPA, FL 336012652		
Owner's Phone:	8132290829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

3

MARTINS TRANSMISSION SVC
3723 W PALMETTO ST
TAMPA, FL 33607

RCRIS-SQG 1000413555
FINDS FLD982157372

RCRIS:

Owner: MARTIN JERRY OWNER
(813) 875-5352

Contact: MARTIN JERRY
(813) 875-5352

Waste	Quantity	Info Source
F002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

4

TAMPA, CITY-FORMER FIRE STATION #5
1910 N FLORIDA AVE
TAMPA, FL 33602

UST U001355981
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-FORMER FIRE STATION #5 (Continued)

U001355981

UST:

Facility ID:	298943538	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY-REAL ESTATE DIVISION		
Contact:	Not reported	Facility Phone:	8132238624
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890314	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE MCCOY		
Owner:	TAMPA,CITY-REAL ESTATE DIVISION		
	201 E KENNEDY BLVD,STE 415		
	TAMPA, FL 336025823		
Owner's Phone:	8132238624	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000300	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

5

HERO PLUMBING CO.
122 W PALM AVE
TAMPA, FL 33602

UST

U001355522
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HERO PLUMBING CO. (Continued)

U001355522

UST:

Facility ID:	298734731	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	HERO PLUMBING SUPPLY		
Contact:	Not reported	Facility Phone:	8138765522
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870813	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES HERO		
Owner:	HERO, CHARLES		
	122 W PALM AVE		
	TAMPA, FL 336022120		
Owner's Phone:	3360265522	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	87/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Cath prot-sac anode		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

6

BAY CON INDUSTRIES INC-GATEWAY MARINA
420 W OAK AVE
TAMPA, FL 33602

AST

A100008709
N/A

6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BAY CON INDUSTRIES INC-GATEWAY MARINA (Continued)

A100008709

AST:

Facility ID:	298625431	Facility Type:	Marine facility
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAYCON INDUSTRIES INC		
Facility Phone:	8132299302	Permit Section:	Not reported
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	W R CHITTENDEN		
Owner:	BAY CON INDUSTRIES INC		
	PO BOX 1484		
	TAMPA, FL 336011484		
Owner's Phone:	8138224797	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00007182
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, int lined steel, Fiberglass, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

7

HARRIS CORP ROOFING & SHEET METAL INC
3702 W CHERRY ST
TAMPA, FL 33607

UST
LUST

U001356088
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HARRIS CORP ROOFING & SHEET METAL INC (Continued)

U001356088

LUST:

Facility ID:	9045569	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138790950	Discovery Date:	03/05/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HARRIS CORP ROOFING & SHEET METAL INC (Continued)

U001356088

UST:

Facility ID:	299045569	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HARRIS CORP		
Contact:	Not reported	Facility Phone:	8138790950
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900103	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE HARRIS		
Owner:	HARRIS, GEORGE J		
	404 S PINEHURST AVE		
	TEMPLE TERRACE, FL 336177220		
Owner's Phone:	8139853680	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HARRIS CORP ROOFING & SHEET METAL INC (Continued)

U001356088

Facility ID:	299045569	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HARRIS CORP		
Contact:	Not reported	Facility Phone:	8138790950
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900103	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE HARRIS		
Owner:	HARRIS, GEORGE J 404 S PINEHURST AVE TEMPLE TERRACE, FL 336177220		
Owner's Phone:	8139853680	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

7

USE 299045569
3702 W CHERRY ST
TAMPA, FL 33607

UST
LUST

U001356290
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299045569 (Continued)

U001356290

LUST:

Facility ID:	9101257	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138790950	Discovery Date:	03/15/91
Tracking Number:	Not reported	Score:	013 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05873		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299045569 (Continued)

U001356290

UST:

Facility ID:	299101257	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HARRIS ROOFING & SHEET METAL		
Contact:	Not reported	Facility Phone:	8138790950
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910328	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE HARRIS		
Owner:	HARRIS, GEORGE		
	3702 W CHERRY ST		
	TAMPA, FL 336072529		
Owner's Phone:	8138790950	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299045569 (Continued)

U001356290

Facility ID:	299101257	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HARRIS ROOFING & SHEET METAL		
Contact:	Not reported	Facility Phone:	8138790950
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910328	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE HARRIS		
Owner:	HARRIS, GEORGE		
	3702 W CHERRY ST		
	TAMPA, FL 336072529		
Owner's Phone:	8138790950	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

8

DRIVELINE BY ACB INC
2211 N HOWARD AVE
TAMPA, FL 33607

RCRIS-SQG 1000429994
FINDS FLD984167056

RCRIS:

Owner: FRANK SUCHON, OWNER
(813) 254-4133

Contact:FRANK SUCHON
(813) 254-4133

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

9

GRAND PRIX CAR WASH
2230 N DALE MABRY HWY
TAMPA, FL 33607

UST U001354042
LUST N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRAND PRIX CAR WASH (Continued)

U001354042

LUST:

Facility ID:	8624779	Facility Type:	RETAIL STATION
Alias Name:	EL DORADO CAR WASH		
Telephone:	8138762278	Discovery Date:	08/15/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

9

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRAND PRIX CAR WASH (Continued)

U001354042

UST:

Facility ID:	298624779	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EL DORADO CAR WASH		
Contact:	Not reported	Facility Phone:	8138762278
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PAUL L HUNTER		
Owner:	ELDORADO CAR WASH		
	2230 N DALE MABRY AVE		
	TAMPA, FL 33607		
Owner's Phone:	8138762278	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil, Fiberglass		
Petro. Monitoring:	Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRAND PRIX CAR WASH (Continued)

U001354042

Facility ID:	298624779	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EL DORADO CAR WASH		
Contact:	Not reported	Facility Phone:	8138762278
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	PAUL L HUNTER		
Owner:	ELDORADO CAR WASH 2230 N DALE MABRY AVE TAMPA, FL 33607		
Owner's Phone:	8138762278	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRAND PRIX CAR WASH (Continued)

U001354042

Facility ID:	298624779	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EL DORADO CAR WASH		
Contact:	Not reported	Facility Phone:	8138762278
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	PAUL L HUNTER		
Owner:	ELDORADO CAR WASH 2230 N DALE MABRY AVE TAMPA, FL 33607		
Owner's Phone:	8138762278	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrnd-no contact w/soil, Fiberglass		
Petro. Monitoring:	Piping/flow restrictor		

10

TAMPA,CITY-MARTIN L KING REC DEPT
2300 N OREGON AVE
TAMPA, FL 33607

UST

U001356054
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-MARTIN L KING REC DEPT (Continued)

U001356054

UST:

Facility ID:	298944955	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAPY, WAYNE		
Contact:	Not reported	Facility Phone:	8132238018
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890929	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

11

TAMPA ARMATURE WORKS INC
1910 OLA AVENUE
TAMPA, FL 33619

RCRIS-SQG 1000701018
FLD984166967

RCRIS:

Owner: ARNOLD HARRINGTON
(813) 621-5661

Contact: ARNOLD HARRINGTON
(813) 621-5661

Waste	Quantity	Info Source	Waste	Quantity	Info Source
F001	.00000 (T)	Notification	F003	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

11

TAMPA ARMATURE WORKS INC
1910 OLA AVE
TAMPA, FL 33619

FINDS 1000735863
FLD984166967

12

TAMPA RADIATOR & AIR CONDITION
1912 N TAMPA ST
TAMPA, FL 33602

RCRIS-SQG 1000344909
FINDS FLD982136368

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

13	TAMPA,CITY-POLICE DEPT 1810 N HIGHLAND AVE TAMPA, FL 33602	UST LUST	U001355932 N/A
----	--	-------------	-------------------

LUST:

Facility ID:	8942562	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132255918	Discovery Date:	12/29/88
Tracking Number:	297810	Score:	021 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05497		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

13

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355932

UST:

Facility ID:	298942562	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY-POLICE DEPT		
Contact:	Not reported	Facility Phone:	8132255918
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT		
	1710 N TAMPA ST		
	TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297810
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355932

Facility ID:	298942562	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY-POLICE DEPT		
Contact:	Not reported	Facility Phone:	8132255918
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297810
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

- | | | | |
|----|---|--------------|--|
| 13 | TAMPA WTP
1810 HIGHLAND AVE
TAMPA, FL 33610

Other Pertinent Environmental Activity Identified at Site:
facility has active water discharge permits | FINDS | 1000496814
FLD000865469 |
| 14 | AUTOMOTIVE CLUTCH
1805 N FRANKLIN
TAMPA, FL 33602

Other Pertinent Environmental Activity Identified at Site:
facility has an emission permit under the Clean Air Act | FINDS | 1000497140
FLD032762262 |
| 15 | GSA MOTOR POOL FUELING STATION
1705 N FLORIDA AVE
TAMPA, FL 33602 | UST | U001355408
N/A |

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GSA MOTOR POOL FUELING STATION (Continued)

U001355408

UST:

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GSA MOTOR POOL FUELING STATION (Continued)

U001355408

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GSA MOTOR POOL FUELING STATION (Continued)

U001355408

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GSA MOTOR POOL FUELING STATION (Continued)

U001355408

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GSA MOTOR POOL FUELING STATION (Continued)

U001355408

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GSA MOTOR POOL FUELING STATION (Continued)

U001355408

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GSA MOTOR POOL FUELING STATION (Continued)

U001355408

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

16

DIAZ PROPERTY
2101 N HOWARD AVE
TAMPA, FL

UST
LUST

U001378109
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DIAZ PROPERTY (Continued)

U001378109

LUST:

Facility ID:	9201458	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132511886	Discovery Date:	11/13/91
Tracking Number:	Not reported	Score:	021 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05497		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

16

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DIAZ PROPERTY (Continued)

U001378109

UST:

Facility ID:	299201458	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DIAZ, JOSEPH		
Contact:	Not reported	Facility Phone:	8132511886
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920604	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	JOSEPH DIAZ		
Owner:	DIAZ, JOSEPH		
	2213 N HOWARD AVE		
	TAMPA, FL 33622		
Owner's Phone:	8132511886	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

17

GTE OF FL WESTSIDE EAX
3712 W WALNUT ST
TAMPA, FL 33607

UST
AST

U001355330
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GTE OF FL WESTSIDE EAX (Continued)

U001355330

UST:

Facility ID:	298628063	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001600	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	3
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GTE OF FL WESTSIDE EAX (Continued)

U001355330

Facility ID:	298628063	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

AST:

Facility ID:	298628063	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO OF FL		
Facility Phone:	8136214931	Permit Section:	Not reported
Date entered:	861107	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005200
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	92/05
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, UST synthetic liner, Op-tight fill		
Tank Piping:	Abvgrnd-no contact w/soil, Suction piping, Dblwall=2nd material		
Petro. Monitoring:	Tank liner space		

18

RIVER HEIGHTS MARINA & DRYDOCK
2305 N WILLOW AVE
TAMPA, FL 33607

UST
LUST

U001354758
N/A

14

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RIVER HEIGHTS MARINA & DRYDOCK (Continued)

U001354758

LUST:

Facility ID:	8625545	Facility Type:	MARINE FACILITY
Alias Name:	RIVER HEIGHTS MARINA		
Telephone:	8132515980	Discovery Date:	09/13/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NO C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

18

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RIVER HEIGHTS MARINA & DRYDOCK (Continued)

U001354758

UST:

Facility ID:	298625545	Facility Type:	Marine facility
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MILLARD, MICHAEL		
Contact:	Not reported	Facility Phone:	8132515980
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE OR SUSAN MILLARD		
Owner:	WARD OIL		
	2701 LOUISIANA		
	TAMPA, FL 33601		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Auto sample wells, Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RIVER HEIGHTS MARINA & DRYDOCK (Continued)

U001354758

Facility ID:	298625545	Facility Type:	Marine facility
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MILLARD, MICHAEL		
Contact:	Not reported	Facility Phone:	8132515980
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE OR SUSAN MILLARD		
Owner:	WARD OIL		
	2701 LOUISIANA		
	TAMPA, FL 33601		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Auto sample wells, Man sample wells		

19

SOUTHERN TRUCK BODY CORP
3924 SPRUCE ST
TAMPA, FL 33607

RCRIS-SQG 1000408362
FINDS FLD982130049

RCRIS:

Owner: DAN NOVISK
(813) 879-8110

Contact: DAN NOVISK
(813) 879-8110

Waste	Quantity	Info Source	Waste	Quantity	Info Source
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

20

US POSTAL SERVICE
4009 W SPRUCE ST
TAMPA, FL 33607

UST U001355218
LUST N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

US POSTAL SERVICE (Continued)

U001355218

LUST:

Facility ID:	8627457	Facility Type:	FEDERAL GOVERNMENT
Alias Name:	Not reported		
Telephone:	8138723709	Discovery Date:	11/10/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

26

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

US POSTAL SERVICE (Continued)

U001355218

UST:

Facility ID:	298627457	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WAYNE ROBERTS		
Contact:	Not reported	Facility Phone:	8138723709
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	RON GRZYMALA		
Owner:	US POSTAL SERVICE		
	11902 N FLORIDA AVE		
	TAMPA, FL 336125222		
Owner's Phone:	4044540631	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	84/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Op-tight fill		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

20

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

US POSTAL SERVICE (Continued)

U001355218

Facility ID:	298627457	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WAYNE ROBERTS		
Contact:	Not reported	Facility Phone:	8138723709
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	RON GRZYMALA		
Owner:	US POSTAL SERVICE		
	11902 N FLORIDA AVE		
	TAMPA, FL 336125222		
Owner's Phone:	4044540631	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	84/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Op-tight fill		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

20

SEARS ROEBUCK & CO #8095
4005 W SPRUCE ST
TAMPA, FL 33607

UST

U001355222
N/A

20

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SEARS ROEBUCK & CO #8095 (Continued)

U001355222

UST:

Facility ID:	298627461	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEARS ROEBUCK & CO #8095		
Contact:	Not reported	Facility Phone:	8138798820
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	FRANK PATRICK		
Owner:	SEARS ROEBUCK & CO		
	4005 W SPRUCE ST		
	TAMPA, FL 336072328		
Owner's Phone:	8138798820	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

20

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SEARS ROEBUCK & CO #8095 (Continued)

U001355222

Facility ID:	298627461	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEARS ROEBUCK & CO #8095		
Contact:	Not reported	Facility Phone:	8138798820
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	FRANK PATRICK		
Owner:	SEARS ROEBUCK & CO 4005 W SPRUCE ST TAMPA, FL 336072328		
Owner's Phone:	8138798820	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000300	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

21 HW BLAKE JUNIOR HIGH SCHOOL
1125 SPRUCE STREET
TAMPA, FL 33607

FINDS

1000738371
FLD984230029

21 HILLSBOROUGH CO H W BLAKE JR HIGH S
1125 SPRUCE ST
TAMPA, FL 33605

RCRIS-SQG

1000703412
FLD984230029

RCRIS:

Owner: PHILLIP GUFFEY, DEALER
(813) 626-0806

Contact: PHILLIP GUFFEY
(813) 626-0806

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D002	.00000 (T)	Notification	D003	.00000 (T)	Notification
D004	.00000 (T)	Notification	D005	.00000 (T)	Notification
D006	.00000 (T)	Notification	D007	.00000 (T)	Notification
D008	.00000 (T)	Notification	D009	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

22	EXXON CO USA #44452 1930 N DALE MABRY TAMPA, FL 77210	FINDS	1000736458 FLD984185702
----	---	-------	----------------------------

22	EXXON #4452 1930 N DALE MABRY HWY TAMPA, FL 33607	UST LUST	U001354919 N/A
----	---	-------------	-------------------

LUST:

Facility ID:	8625715	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	4076473776	Discovery Date:	05/06/88
Tracking Number:	290339	Score:	032
Facility Code:	Not reported	Status:	Not reported
Rank:	03819		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

22

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4452 (Continued)

U001354919

UST:

Facility ID:	298625715	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	NORMA DANIELS		
Owner:	EXXON CO USA		
	PO BOX 4386		
	HOUSTON, TX 772104386		
Owner's Phone:	7136567059	Tracking #:	290339
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, DW piping space, GW monitoring		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4452 (Continued)

U001354919

Facility ID:	298625715	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	NORMA DANIELS		
Owner:	EXXON CO USA		
	PO BOX 4386		
	HOUSTON, TX 772104386		
Owner's Phone:	7136567059	Tracking #:	290339
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, DW piping space, GW monitoring		

22

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4452 (Continued)

U001354919

Facility ID:	298625715	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	NORMA DANIELS		
Owner:	EXXON CO USA		
	PO BOX 4386		
	HOUSTON, TX 772104386		
Owner's Phone:	7136567059	Tracking #:	290339
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	8/1/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, DW piping space, GW monitoring		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4452 (Continued)

U001354919

Facility ID:	298625715	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	NORMA DANIELS		
Owner:	EXXON CO USA		
	PO BOX 4386		
	HOUSTON, TX 772104386		
Owner's Phone:	7136567059	Tracking #:	290339
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Db/wall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, DW piping space, GW monitoring		

22

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4452 (Continued)

U001354919

Facility ID:	298625715	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	NORMA DANIELS		
Owner:	EXXON CO USA		
	PO BOX 4386		
	HOUSTON, TX 772104386		
Owner's Phone:	7136567059	Tracking #:	290339
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, DW piping space, GW monitoring		

23

JOY AMERICA #613
1907 N HIMES AVE
TAMPA, FL 33607

UST
LUST

U002313164
N/A

23

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

JOY AMERICA #613 (Continued)

U002313164

LUST:

Facility ID:	8625256	Facility Type:	RETAIL STATION
Alias Name:	CARGO STATION		
Telephone:	8132862323	Discovery Date:	02/01/86
Tracking Number:	298691	Score:	080 (HIGH)
Facility Code:	Not reported	Status:	Not reported
Rank:	00288		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

23

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

JOY AMERICA #613 (Continued)

U002313164

UST:

Facility ID:	298625256	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	J STYLES WILSON		
Contact:	Not reported	Facility Phone:	8132862323
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	REPUBLIC OIL CO		
	205 S HOOVER ST #400		
	TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	298691
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

23

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

JOY AMERICA #613 (Continued)

U002313164

Facility ID:	298625256	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	J STYLES WILSON		
Contact:	Not reported	Facility Phone:	8132862323
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	REPUBLIC OIL CO 205 S HOOVER ST #400 TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	298691
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

23

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

JOY AMERICA #613 (Continued)

U002313164

Facility ID:	298625256	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	J STYLES WILSON		
Contact:	Not reported	Facility Phone:	8132862323
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	REPUBLIC OIL CO		
	205 S HOOVER ST #400		
	TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	298691
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Gasohol	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

23

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

JOY AMERICA #613 (Continued)

U002313164

Facility ID:	298625256	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	J STYLES WILSON		
Contact:	Not reported	Facility Phone:	8132862323
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	REPUBLIC OIL CO 205 S HOOVER ST #400 TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	298691
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Gasohol	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

24

TAMPA CITY FIRE DEPT MAINTENANCE #9
2519 W CHESTNUT ST
TAMPA, FL

AST

A100009021
N/A

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY FIRE DEPT MAINTENANCE #9 (Continued)

A100009021

AST:

Facility ID:	299103159	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	WASHINGTON, BOBBY	Permit Section:	Not reported
Facility Phone:	8138781067	Financial responsibility:	Oth Apprvd Coverage
Date entered:	911021	District:	Southwest
Tank ID:	5		
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00000550
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	93/04
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Spill cnmt, Op-tight fill, dbiwall=2nd material		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

24

TAMPA CITY FIRE DEPT MAINTENANCE #9
2519 CHESTNUT ST
TAMPA, FL

UST
LUST

U001378079
N/A

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY FIRE DEPT MAINTENANCE #9 (Continued)

U001378079

LUST:

Facility ID:	9103159	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8138781067	Discovery Date:	12/12/88
Tracking Number:	Not reported	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY FIRE DEPT MAINTENANCE #9 (Continued)

U001378079

UST:

Facility ID:	299103159	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	WASHINGTON, BOBBY		
Contact:	Not reported	Facility Phone:	8138781067
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911021	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	86/05
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Auto tank gauging		

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY FIRE DEPT MAINTENANCE #9 (Continued)

U001378079

Facility ID:	299103159	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	WASHINGTON, BOBBY		
Contact:	Not reported	Facility Phone:	8138781067
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911021	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY FIRE DEPT MAINTENANCE #9 (Continued)

U001378079

Facility ID:	299103159	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	WASHINGTON, BOBBY		
Contact:	Not reported	Facility Phone:	8138781067
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911021	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY FIRE DEPT MAINTENANCE #9 (Continued)

U001378079

Facility ID:	299103159	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	WASHINGTON, BOBBY		
Contact:	Not reported	Facility Phone:	8138781067
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911021	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	GW monitoring		

24

USE 299103159
2525 W CHESTNUT ST
TAMPA, FL 33607

UST
LUST

U001355925
N/A

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299103159 (Continued)

U001355925

LUST:

Facility ID:	8842515	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132255729	Discovery Date:	Not reported
Tracking Number:	295182	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04266		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	Not reported
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

INCIDENT PROGRAM INFORMATION -

Incident Program:	Not reported
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299103159 (Continued)

U001355925

UST:

Facility ID:	298842515	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BRIAN GUMMOE		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295182
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

24

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

USE 299103159 (Continued)

U001355925

Facility ID:	298842515	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BRIAN GUMMOE		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295182
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299103159 (Continued)

U001355925

Facility ID:	298842515	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BRIAN GUMMOE		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295182
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	GW monitoring		

24

KOTLER FALK PARTNERSHIP
1906 N ARMENIA AVE
TAMPA, FL 33607

UST
LUST

U001356313
N/A

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KOTLER FALK PARTNERSHIP (Continued)

U001356313

LUST:

Facility ID:	9101537	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	03/25/91
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KOTLER FALK PARTNERSHIP (Continued)

U001356313

UST:

Facility ID:	299101537	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KOTLER FALK PARTNERSHIP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910403	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	KOTLER FALK PARTNERSHIP		
	PO BOX 66		
	TAMPA, FL 336010066		
Owner's Phone:	8138777511	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KOTLER FALK PARTNERSHIP (Continued)

U001356313

Facility ID:	299101537	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KOTLER FALK PARTNERSHIP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910403	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	KOTLER FALK PARTNERSHIP PO BOX 66 TAMPA, FL 336010066		
Owner's Phone:	8138777511	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KOTLER FALK PARTNERSHIP (Continued)

U001356313

Facility ID:	299101537	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KOTLER FALK PARTNERSHIP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910403	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	Not reported		
Owner:	KOTLER FALK PARTNERSHIP PO BOX 66 TAMPA, FL 336010066		
Owner's Phone:	8138777511	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KOTLER FALK PARTNERSHIP (Continued)

U001356313

Facility ID:	299101537	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KOTLER FALK PARTNERSHIP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910403	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	Not reported		
Owner:	KOTLER FALK PARTNERSHIP PO BOX 66 TAMPA, FL 336010066		
Owner's Phone:	8138777511	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KOTLER FALK PARTNERSHIP (Continued)

U001356313

Facility ID:	299101537	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KOTLER FALK PARTNERSHIP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910403	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	Not reported		
Owner:	KOTLER FALK PARTNERSHIP PO BOX 66 TAMPA, FL 336010066		
Owner's Phone:	8138777511	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KOTLER FALK PARTNERSHIP (Continued)

U001356313

Facility ID:	299101537	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KOTLER FALK PARTNERSHIP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910403	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	Not reported		
Owner:	KOTLER FALK PARTNERSHIP		
	PO BOX 66		
	TAMPA, FL 336010066		
Owner's Phone:	8138777511	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

25

M & J PROPERTIES
3707 CHESTNUT ST
TAMPA, FL

UST

U001378053
N/A

25

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

M & J PROPERTIES (Continued)

U001378053

UST:

Facility ID:	299102312	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MICHAEL WARD		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910615	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MICHAEL WARD		
Owner:	M & J PROPERTY MANAGEMENT CO 3333 W KENNEDY BLVD SUITE 205 TAMPA, FL 33606		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

25

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

M & J PROPERTIES (Continued)

U001378053

Facility ID:	299102312	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MICHAEL WARD		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910615	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MICHAEL WARD		
Owner:	M & J PROPERTY MANAGEMENT CO 3333 W KENNEDY BLVD SUITE 205 TAMPA, FL 33606		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

25

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

M & J PROPERTIES (Continued)

U001378053

Facility ID:	299102312	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MICHAEL WARD		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910615	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MICHAEL WARD		
Owner:	M & J PROPERTY MANAGEMENT CO 3333 W KENNEDY BLVD SUITE 205 TAMPA, FL 33606		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

25

**KWIK PEP STATION
3707 W CHESTNUT ST
TAMPA, FL 33607**

**UST
LUST**

**U001356210
N/A**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KWIK PEP STATION (Continued)

U001356210

LUST:

Facility ID:	9100286	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8139321779	Discovery Date:	01/04/90
Tracking Number:	Not reported	Score:	041
Facility Code:	Not reported	Status:	Not reported
Rank:	02138		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE

25

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KWIK PEP STATION (Continued)

U001356210

UST:

Facility ID:	299100286	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRAND CENTRAL INVESTMENT		
Contact:	Not reported	Facility Phone:	8139321779
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910214	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE WARD		
Owner:	GRAND CENTRAL INVESTMENT		
	1308 W SLIGH AVE		
	TAMPA, FL 336045902		
Owner's Phone:	8139321779	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	84/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

25

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KWIK PEP STATION (Continued)

U001356210

Facility ID:	299100286	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRAND CENTRAL INVESTMENT		
Contact:	Not reported	Facility Phone:	8139321779
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910214	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE WARD		
Owner:	GRAND CENTRAL INVESTMENT		
	1308 W SLIGH AVE		
	TAMPA, FL 336045902		
Owner's Phone:	8139321779	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	84/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

25

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

KWIK PEP STATION (Continued)

U001356210

Facility ID:	299100286	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRAND CENTRAL INVESTMENT		
Contact:	Not reported	Facility Phone:	8139321779
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910214	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE WARD		
Owner:	GRAND CENTRAL INVESTMENT		
	1308 W SLIGH AVE		
	TAMPA, FL 336045902		
Owner's Phone:	8139321779	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	84/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

26 TAMPA,CITY-DPW FLEET MAINT-DIV #4
1710 DOYLE CARLTON DR
TAMPA, FL 33607

UST
LUST

U001354379
N/A

26

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT-DIV #4 (Continued)

U001354379

LUST:

Facility ID:	8625142	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132238248	Discovery Date:	12/24/88
Tracking Number:	298173	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN	Est. Gallons Lost:	UNKNOWN
------------	---------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

26

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT-DIV #4 (Continued)

U001354379

UST:

Facility ID:	298625142	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238248
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298173
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

26

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT-DIV #4 (Continued)

U001354379

Facility ID:	298625142	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238248
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298173
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

26

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT-DIV #4 (Continued)

U001354379

Facility ID:	298625142	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238248
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298173
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT-DIV #4 (Continued)

U001354379

Facility ID:	298625142	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238248
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298173
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

26

TAMPA FLEET DIV, CITY OF
1710 DOYLE CARLTON DRIVE
TAMPA, FL 33607

RCRIS-SQG 1000440423
FINDS FLD982162810

RCRIS:

Owner: GENE TAYLOR
(813) 877-0566

Contact: GENE TAYLOR
(813) 877-0566

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F002	.00000 (T)	Notification
F003	.00000 (T)	Notification	F004	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

27

TAMPA,CITY-POLICE DEPT
1710 N TAMPA ST
TAMPA, FL 33602

UST
LUST U001355933
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

LUST:

Facility ID:	8942565	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132255986	Discovery Date:	12/28/88
Tracking Number:	297812	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06571		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	8942563	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132255986	Discovery Date:	12/28/88
Tracking Number:	297811	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		
INCIDENT GENERAL INFORMATION -			
Source Description:	EDI		
Lead:	LOCAL PROGRAM		
Incident 17-770 Cleanup:	NEW C/U REQUIRED		
INCIDENT POLLUTANT INFORMATION -			
Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
INCIDENT PROGRAM INFORMATION -			
Incident Program:	EARLY DETECTION INCENTIVE		
Incident Program Type:	STATE CLEANUP		
Incident Eligible Status:	ELIGIBLE		
Incident Ineligible Reason:	Not Reported		
Incident Ineligible Description:	Not reported		
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:	Cleanup Responsible:	STATE	
Soil Removal:	Alt. Process Date:	Not reported	
Soil Treatment:	Alternative Status:	Not reported	
Other Treatment:			
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:	Not reported		
Response Record Type:	Not reported		
Response Remedial Action Plan Type:	Not reported		
Response Status:	Not reported		
Extension Record Type:	Not reported		
Extension Status:	Not reported		
Extension Comments:	Not reported		
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:	Not reported		
Response Record Type:	Not reported		
Response Remedial Action Plan Type:	Not reported		
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:	Not reported		
Estimated Completion Year:	Not reported		
Actual Year to Complete:	Not reported		
Report Type:	Not reported		
Report Comments:	Not reported		
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:	Not reported		
Region:	STATE		

27

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

UST:

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

27

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Not required		

27

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942563	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	OSTING, DAVID		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT		
	1710 N TAMPA ST		
	TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297811
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

27

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942563	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	OSTING, DAVID		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT		
	1710 N TAMPA ST		
	TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297811
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	60/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942563	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	OSTING, DAVID		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT		
	1710 N TAMPA ST		
	TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297811
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942563	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	OSTING, DAVID		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT		
	1710 N TAMPA ST		
	TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297811
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

28

TAMPA CITY DPW FLEET MAINT DIV #5
1508 N CLARK AVE
TAMPA, FL 33607

UST
LUST

U002313172
N/A

28

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DPW FLEET MAINT DIV #5 (Continued)

U002313172

LUST:

Facility ID:	8625676	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	TAMPA,CITY-DPW FLEET MAINT DIV #5		
Telephone:	8138781001	Discovery Date:	12/24/88
Tracking Number:	298298	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN	Est. Gallons Lost:	UNKNOWN
------------	---------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

28

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DPW FLEET MAINT DIV #5 (Continued)

U002313172

UST:

Facility ID:	298625676	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHARLES C SWARENS		
Contact:	Not reported	Facility Phone:	8138781001
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298298
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DPW FLEET MAINT DIV #5 (Continued)

U002313172

Facility ID:	298625676	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHARLES C SWARENS		
Contact:	Not reported	Facility Phone:	8138781001
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298298
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnrmt, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DPW FLEET MAINT DIV #5 (Continued)

U002313172

Facility ID:	298625676	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHARLES C SWARENS		
Contact:	Not reported	Facility Phone:	8138781001
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298298
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

28

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DPW FLEET MAINT DIV #5 (Continued)

U002313172

Facility ID:	298625676	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHARLES C SWARENS		
Contact:	Not reported	Facility Phone:	8138781001
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298298
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Misc. Petro-base product	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man tank gauging		

29

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DPW FLEET MAINT DIV #5 (Continued)

U002313172

Facility ID:	298625676	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHARLES C SWARENS		
Contact:	Not reported	Facility Phone:	8138781001
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298298
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DPW FLEET MAINT DIV #5 (Continued)

U002313172

Facility ID:	298625676	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHARLES C SWARENS		
Contact:	Not reported	Facility Phone:	8138781001
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	6	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298298
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	64/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DPW FLEET MAINT DIV #5 (Continued)

U002313172

Facility ID:	298625676	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHARLES C SWARENS		
Contact:	Not reported	Facility Phone:	8138781001
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	7	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298298
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man tank gauging		

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DPW FLEET MAINT DIV #5 (Continued)

U002313172

Facility ID:	298625676	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHARLES C SWARENS		
Contact:	Not reported	Facility Phone:	8138781001
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	8	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298298
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man tank gauging		

28	TAMPA FLEET DIV, CITY OF 1508 N CLARK AVE TAMPA, FL 33607	RCRIS-SQG FINDS	1000440414 FLD982118051
29	SPEEDLINE ATHLETIC WEAR INC 1804 N HABANA AVE TAMPA, FL 33607	FINDS	1000738757 FLD984240515
30	TAMPA HOUSING AUTH 1514 UNION ST TAMPA, FL 33607	RCRIS-SQG FINDS	1000344881 FLD982105132

RCRIS:
Owner: JAIME ANDERSON, SITE SUPERVISOR
(813) 622-8311

Contact: WALLAE C
(813) 253-0551

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D008	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
31	AUTO HOST 1810 N WESTSHORE BLVD TAMPA, FL 33607	UST	U001355363 N/A
	UST:		
	Facility ID: 298631383	Facility Type: Non-retail Business	
	Is fac. regulated: Not regulated facility	Is facility open: Closed	
	Operator: MARY MUNSON-R.C.RYAN		
	Contact: Not reported	Facility Phone: 8138730215	
	Permit Section: Not reported	Region: Not reported	
	Facility Code: No violation		
	Date entered: 861230	Financial responsibility: Not reported	
	Tank ID: 1	District: Southwest	
	Owner's Contact: MARVIN HOLLOWAY		
	Owner: HOLLOWAY, MARVIN		
	29244 WHIPPORWILL LN		
	WESLEY CHAPEL, FL 335434328		
	Owner's Phone: 8139730580	Tracking #: Not reported	
	Cleanup Status: Not reported	Any contaminated soil: Not reported	
	Drink. Wat. Well: Not reported	Any contaminated surface water: Not reported	
	Tank Cap. (Gals): 00020000	Any monit. wells: Not reported	
	Tank position: Underground	Any contam. groundwater: Not reported	
	Tank Content: Unknown/not reported	Contaminated media indicator: No	
	Disposal Method: Removed	Install. Date: Not reported	
	Is tank regulated: Not regulated tank	Content Category: Vehicular	
	Facility Status: Not reported	Last used Date: 92/06	
	RPT Tank #: Not reported	RPT by Tank #: Not reported	
	Eligibility: Not reported	Eligible Date: Not reported	
	Permit Number: Not reported		
	Class: Not reported		
	Category: Not reported		
	Tank Constr.: Unknown/not reported		
	Tank Piping: Unknown/not reported		
	Petro. Monitoring: Unknown/not reported		
31	INTERCONTINENTAL RENT A CAR 1820 N WESTSHORE BLVD TAMPA, FL 33607	UST LUST	U001713409 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

INTERCONTINENTAL RENT A CAR (Continued)

U001713409

LUST:

Facility ID:	9400177	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	INTERCONTINENTAL RENT A CAR		
Telephone:	8132895080	Discovery Date:	01/07/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	OTHER
Incident Ineligible Description:	OTHER

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

21

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

INTERCONTINENTAL RENT A CAR (Continued)

U001713409

UST:

Facility ID:	299400177	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HAROLD LORENTSON		
Contact:	Not reported	Facility Phone:	8132895080
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940215	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	HAROLD LORENTSON		
Owner:	HOLLOWAY, MARVIN J		
	1515 N WESTSHORE BLVD		
	TAMPA, FL 33607		
Owner's Phone:	8132895030	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Misc. Petro-base product	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	94/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

32

TAMPA CITY DEPT OF PUBLIC WORKS
1550 N GRADY AVE
TAMPA, FL 33602

UST
LUST

U001823388
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DEPT OF PUBLIC WORKS (Continued)

U001823388

LUST:

Facility ID:	9400334	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	CITY OF TAMPA - DEPT OF PUBLIC WORKS		
Telephone:	8132748082	Discovery Date:	12/10/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
------------	------------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NONCOMPLAINEE 17-769 RULE
Incident Ineligible Description:	NONCOMPLIANCE 1

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

32

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DEPT OF PUBLIC WORKS (Continued)

U001823388

UST:

Facility ID:	299400334	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HALLIE CALIG		
Contact:	Not reported	Facility Phone:	8132748082
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940325	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HALLIE CALIG		
Owner:	TAMPA, CITY OF CITY HALL PLAZA TAMPA, FL 33602		
Owner's Phone:	8132238282	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000110	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

32

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY DEPT OF PUBLIC WORKS (Continued)

U001823388

Facility ID:	299400334	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HALLIE CALIG		
Contact:	Not reported	Facility Phone:	8132748082
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940325	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	HALLIE CALIG		
Owner:	TAMPA, CITY OF CITY HALL PLAZA TAMPA, FL 33602		
Owner's Phone:	8132238282	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

33	ELEGAUNT CORP 1700 N DALE MABRY HWY #K-19 TAMPA, FL 33607	FINDS	1000933335 FL0000676221
----	--	--------------	--

33	DON R SPORTS 1700 N DALE MABRY HWY TAMPA, FL 33614	RCRIS-SQG RCRIS-TSD	1000921740 FLD984194712
----	---	--------------------------------------	--

RCRIS:

Owner: DON SPORTS
(813) 239-1554

Contact: DON SPORTS
(813) 239-1554

Waste	Quantity	Info Source
D000	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

33	DON R SPORTS 1700 N DALE MABRY HWY TAMPA, FL 33604	FINDS	1000500418 FLD984205104
----	---	--------------	--

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
33	HOME DEPOT #256 1712 N DALE MABRY TAMPA, FL 33607	UST LUST	U001823398 N/A
	LUST:		
	Facility ID: 9400477	Facility Type: OTHER	
	Alias Name: Not reported		
	Telephone: Not reported	Discovery Date: 11/05/93	
	Tracking Number: Not reported	Score: 000 (LOW)	
	Facility Code: Not reported	Status: Not reported	
	Rank: 00000		
	Class: Not reported		
	Category: Not reported		
	INCIDENT GENERAL INFORMATION -		
	Source Description:	CLOSURE REPORT	
	Lead:	LOCAL PROGRAM	
	Incident 17-770 Cleanup:	NO C/U REQUIRED	
	INCIDENT POLLUTANT INFORMATION -		
	Pollutant: VEHIC DIESEL	Est. Gallons Lost: UNKNOWN	
	INCIDENT PROGRAM INFORMATION -		
	Incident Program:	RESPONSIBLE PARTY-NO CLAIM	
	Incident Program Type:	Not reported	
	Incident Eligible Status:	Not reported	
	Incident Ineligible Reason:	Not Reported	
	Incident Ineligible Description:	Not reported	
	INCIDENT INITIAL REMEDIAL ACTION INFORMATION -		
	Free Product:	Cleanup Responsible: Not reported	
	Soil Removal:	Alt. Process Date: Not reported	
	Soil Treatment:	Alternative Status: Not reported	
	Other Treatment:		
	INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -		
	Cleanup Responsible:	Not reported	
	Response Record Type:	Not reported	
	Response Remedial Action Plan Type:	Not reported	
	Response Status:	Not reported	
	Extension Record Type:	Not reported	
	Extension Status:	Not reported	
	Extension Comments:	Not reported	
	INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -		
	Cleanup Responsible:	Not reported	
	Response Record Type:	Not reported	
	Response Remedial Action Plan Type:	Not reported	
	INCIDENT REMEDIAL ACTION REPORT INFORMATION -		
	Cleanup Responsible:	Not reported	
	Estimated Completion Year:	Not reported	
	Actual Year to Complete:	Not reported	
	Report Type:	Not reported	
	Report Comments:	Not reported	
	INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -		
	Site Rehab. Completion Action:	Not reported	
	Region:	STATE	

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HOME DEPOT #256 (Continued)

U001823398

UST:

Facility ID:	299400477	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MIKE QUARLES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940404	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LARRY SMITH		
Owner:	HOME DEPOT USA INC		
	3030 N ROCKY POINT DR W #300		
	TAMPA, FL 336075903		
Owner's Phone:	8132822058	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	None		

34

CAPITANO'S AUTO SERVICE
2501 W MAIN ST
TAMPA, FL 33607

UST
LUST

U001354742
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CAPITANO'S AUTO SERVICE (Continued)

U001354742

LUST:

Facility ID:	8625529	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8138772967	Discovery Date:	07/01/93
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

CLOSURE REPORT

Not reported

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant: LEADED GAS

Pollutant 2: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

RESPONSIBLE PARTY-NO CLAIM

Not reported

Not reported

Not Reported

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

34

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CAPITANO'S AUTO SERVICE (Continued)

U001354742

UST:

Facility ID:	298625529	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CAPITANOS AUTO SERVICE		
Contact:	Not reported	Facility Phone:	8138772967
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	FANO CAPITANO		
Owner:	CAPITANO AUTO SERVICE		
	8637 LEIGHTON DR		
	TAMPA, FL 336141723		
Owner's Phone:	8138772967	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

34

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CAPITANO'S AUTO SERVICE (Continued)

U001354742

Facility ID:	298625529	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CAPITANOS AUTO SERVICE		
Contact:	Not reported	Facility Phone:	8138772967
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	FANO CAPITANO		
Owner:	CAPITANO AUTO SERVICE		
	8637 LEIGHTON DR		
	TAMPA, FL 336141723		
Owner's Phone:	8138772967	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

34

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CAPITANO'S AUTO SERVICE (Continued)

U001354742

Facility ID:	298625529	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CAPITANOS AUTO SERVICE		
Contact:	Not reported	Facility Phone:	8138772967
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	FANO CAPITANO		
Owner:	CAPITANO AUTO SERVICE		
	8637 LEIGHTON DR		
	TAMPA, FL 336141723		
Owner's Phone:	8138772967	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

34

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CAPITANO'S AUTO SERVICE (Continued)

U001354742

Facility ID:	298625529	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CAPITANOS AUTO SERVICE		
Contact:	Not reported	Facility Phone:	8138772967
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	FANO CAPITANO		
Owner:	CAPITANO AUTO SERVICE		
	8637 LEIGHTON DR		
	TAMPA, FL 336141723		
Owner's Phone:	8138772967	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

34

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CAPITANO'S AUTO SERVICE (Continued)

U001354742

Facility ID:	298625529	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CAPITANOS AUTO SERVICE		
Contact:	Not reported	Facility Phone:	8138772967
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	FANO CAPITANO		
Owner:	CAPITANO AUTO SERVICE		
	8637 LEIGHTON DR		
	TAMPA, FL 336141723		
Owner's Phone:	8138772967	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

35 MAIN ST GAS STATION
2345 W MAIN ST
TAMPA, FL 33607

UST
LUST

U001354792
N/A

35

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MAIN ST GAS STATION (Continued)

U001354792

LUST:

Facility ID:	8625580	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132544009	Discovery Date:	09/23/92
Tracking Number:	296239	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS

Est. Gallons Lost: 00000015

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

RESPONSIBLE PARTY-NO CLAIM

Not reported

Not reported

Not Reported

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

35

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MAIN ST GAS STATION (Continued)

U001354792

UST:

Facility ID:	298625580	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JAGMOHAN,PHULMOTI		
Contact:	Not reported	Facility Phone:	8132544009
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LEE JAGMOHAN		
Owner:	JAGHOMAN, CHANDIKA		
	2345 MAIN ST		
	TAMPA, FL 33607		
Owner's Phone:	8132544009	Tracking #:	296239
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, DW piping space		

35

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MAIN ST GAS STATION (Continued)

U001354792

Facility ID:	298625580	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JAGMOHAN,PHULMOTI		
Contact:	Not reported	Facility Phone:	8132544009
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	LEE JAGMOHAN		
Owner:	JAGHOMAN, CHANDIKA		
	2345 MAIN ST		
	TAMPA, FL 33607		
Owner's Phone:	8132544009	Tracking #:	296239
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Dbt/wall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, DW piping space		

39

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MAIN ST GAS STATION (Continued)

U001354792

Facility ID:	298625580	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JAGMOHAN,PHULMOTI		
Contact:	Not reported	Facility Phone:	8132544009
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	LEE JAGMOHAN		
Owner:	JAGHOMAN, CHANDIKA		
	2345 MAIN ST		
	TAMPA, FL 33607		
Owner's Phone:	8132544009	Tracking #:	296239
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, DW piping space		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MAIN ST GAS STATION (Continued)

U001354792

Facility ID:	298625580	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JAGMOHAN,PHULMOTI		
Contact:	Not reported	Facility Phone:	8132544009
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	LEE JAGMOHAN		
Owner:	JAGHOMAN, CHANDIKA		
	2345 MAIN ST		
	TAMPA, FL 33607		
Owner's Phone:	8132544009	Tracking #:	296239
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

29

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MAIN ST GAS STATION (Continued)

U001354792

Facility ID:	298625580	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JAGMOHAN,PHULMOTI		
Contact:	Not reported	Facility Phone:	8132544009
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	LEE JAGMOHAN		
Owner:	JAGHOMAN, CHANDIKA		
	2345 MAIN ST		
	TAMPA, FL 33607		
Owner's Phone:	8132544009	Tracking #:	296239
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000250	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

35

MAIN ST GAS STATION USE 298625580
2345 W MAIN ST
TAMPA, FL 33607

UST
LUST

U001355937
N/A

35

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MAIN ST GAS STATION USE 298625580 (Continued)

U001355937

LUST:

Facility ID:	8942586	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132544009	Discovery Date:	08/02/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

235

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MAIN ST GAS STATION USE 298625580 (Continued)

U001355937

UST:

Facility ID:	298942586	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JAGMOHAN C P		
Contact:	Not reported	Facility Phone:	8132544009
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	C P JAGMOHAN		
Owner:	JAGMOHAN, C P		
	2345 W MAIN ST		
	TAMPA, FL 336073418		
Owner's Phone:	8132544009	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	1
Tank position:	Not reported	Any contam. groundwater:	No
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

36

FELICIONE AUTO SERVICE
1746 W MAIN ST
TAMPA, FL 33607

UST
LUST

U001356056
N/A

36

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FELICIONE AUTO SERVICE (Continued)

U001356056

LUST:

Facility ID:	8945082	Facility Type:	INLAND BULK PETROLEUM
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	04/29/92
Tracking Number:	Not reported	Score:	045
Facility Code:	Not reported	Status:	Not reported
Rank:	02212		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	KEROSENE	Est. Gallons Lost:	UNKNOWN
------------	----------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FELICIONE AUTO SERVICE (Continued)

U001356056

UST:

Facility ID:	298945082	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FELICIONE AUTO SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891016	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	FELICIONE AUTO SERVICE		
	1746 W MAIN ST		
	TAMPA, FL 336074320		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Unprotect metal		
Petro. Monitoring:	Unknown/not reported		

36

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FELICIONE AUTO SERVICE (Continued)

U001356056

Facility ID:	298945082	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FELICIONE AUTO SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891016	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	FELICIONE AUTO SERVICE 1746 W MAIN ST TAMPA, FL 336074320		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

37

A & A AUTO PARTS
3334 W MAIN ST
TAMPA, FL 33607

RCRIS-SQG 1000500641
FINDS FLD984207373

RCRIS:

Owner: EDWARD RADCLIFF, OWNER
(813) 876-9531

Contact: EDWARD RADCLIFF
(813) 876-9531

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F001	.00000 (T)	Notification
F002	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

38

SUPERIOR CAR RENTAL
1700 N WESTSHORE BLVD
TAMPA, FL 33607

UST
LUST

U001356314
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SUPERIOR CAR RENTAL (Continued)

U001356314

LUST:

Facility ID:	9101570	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132898129	Discovery Date:	01/16/92
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

38

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SUPERIOR CAR RENTAL (Continued)

U001356314

UST:

Facility ID:	299101570	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SUSAN MULLIGAN		
Contact:	Not reported	Facility Phone:	8132898129
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910404	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN B PROVENZANO		
Owner:	PROVENZANO, JOHN B PO BOX 23271 TAMPA, FL 336233271		
Owner's Phone:	8138888087	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SUPERIOR CAR RENTAL (Continued)

U001356314

Facility ID:	299101570	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SUSAN MULLIGAN		
Contact:	Not reported	Facility Phone:	8132898129
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910404	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN B PROVENZANO		
Owner:	PROVENZANO, JOHN B PO BOX 23271 TAMPA, FL 336233271		
Owner's Phone:	8138888087	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000200	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Diesel-gen/pump	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

38

PARAGON GROUP INC
1715 N WESTSHORE BLVD
TAMPA, FL 33607

UST
LUST

U001356240
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PARAGON GROUP INC (Continued)

U001356240

LUST:

Facility ID:	9100551	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132891727	Discovery Date:	12/28/90
Tracking Number:	Not reported	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06571		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	DIESEL-GEN/PUMP	Est. Gallons Lost:	UNKNOWN
------------	-----------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PARAGON GROUP INC (Continued)

U001356240

UST:

Facility ID:	299100551	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GALAN, PHYLLIS		
Contact:	Not reported	Facility Phone:	8132891727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PHYLLIS GALAN		
Owner:	PARAGON GROUP INC		
	1715 N WESTSHORE BLVD		
	TAMPA, FL 336073904		
Owner's Phone:	8132891727	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

38

USE 299101570
1720 N WESTSHORE BLVD
TAMPA, FL 33607

UST
LUST

U001356379
N/A

38

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299101570 (Continued)

U001356379

LUST:

Facility ID:	9200199	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132898129	Discovery Date:	12/30/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

38

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299101570 (Continued)

U001356379

UST:

Facility ID:	299200199	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SUPERIOR CAR RENTAL		
Contact:	Not reported	Facility Phone:	8132898129
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920121	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	KATHY LESER		
Owner:	BARNETT BANK INC		
	PO BOX 30014		
	TAMPA, FL 33611		
Owner's Phone:	8132558143	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

39

SALEMIS BODY SHOP INC
1602 N ARMENIA AVE
TAMPA, FL 33607

RCRIS-SQG
FINDS

1000206008
FLD982155418

RCRIS:

Owner: SAM SALEMI JR
(813) 879-2723

Contact: SAM SALEMI
(813) 879-2723

Waste	Quantity	Info Source
-------	----------	-------------

F003	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

39

SALEMI'S BODY SHOP
1602 N ARMENIA AVE
TAMPA, FL 33636

UST
LUST

U001356373
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SALEMI'S BODY SHOP (Continued)

U001356373

LUST:

Facility ID:	9103217	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138792723	Discovery Date:	03/29/91
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

39

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SALEMI'S BODY SHOP (Continued)

U001356373

UST:

Facility ID:	299103217	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SALEMI, SAM		
Contact:	Not reported	Facility Phone:	8138792723
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911101	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	SAM SALEMI JR		
Owner:	SALEMI, SAM JR		
	1602 N ARMENIA AVE		
	TAMPA, FL 33636		
Owner's Phone:	8138792723	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	75/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

39

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SALEMI'S BODY SHOP (Continued)

U001356373

Facility ID:	299103217	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SALEMI, SAM		
Contact:	Not reported	Facility Phone:	8138792723
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911101	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	SAM SALEMI JR		
Owner:	SALEMI, SAM JR		
	1602 N ARMENIA AVE		
	TAMPA, FL 33636		
Owner's Phone:	8138792723	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	75/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

40

USE #298944533
2135 W GREEN ST
TAMPA, FL 33607

UST
LUST

U001354517
N/A

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE #298944533 (Continued)

U001354517

LUST:

Facility ID:	8625289	Facility Type:	RETAIL STATION
Alias Name:	EXXON #4-5298-INTERSTATE		
Telephone:	8132530824	Discovery Date:	12/04/88
Tracking Number:	294565	Score:	031
Facility Code:	Not reported	Status:	Not reported
Rank:	03984		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE #298944533 (Continued)

U001354517

UST:

Facility ID:	298625289	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	COOPER, R W		
Contact:	Not reported	Facility Phone:	8132530824
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	NORMA DANIELS		
Owner:	EXXON CO USA		
	PO BOX 4386		
	HOUSTON, TX 772104386		
Owner's Phone:	7136567059	Tracking #:	294565
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	1
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

40

ALPINE TRUCK STOP INC
2135 W GREEN ST
TAMPA, FL 33603

UST
LUST

U001356030
N/A

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

LUST:

Facility ID:	8944533	Facility Type:	RETAIL STATION
Alias Name:	EXXON #4-5298		
Alias Name 2:	ALPINE TRUCK STOP INC.		
Telephone:	8132544011	Discovery Date:	05/18/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	ANNUAL
Report Comments:	YR 1 (QTR 1,2,3)

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

UST:

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Op-flow shut off		
Tank Piping:	Fiberglass, Pressurized piping, Unknown/not reported, Appv alt material		
Petro. Monitoring:	Auto sample wells, DW tank space, Not required, Auto tank gauging, GW monitoring		

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	10	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Op-flow shut off		
Tank Piping:	Fiberglass, Pressurized piping, Unknown/not reported, Appv alt material		
Petro. Monitoring:	Auto sample wells, DW tank space, Not required, Auto tank gauging, GW monitoring		

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Op-flow shut off		
Tank Piping:	Fiberglass, Pressurized piping, Unknown/not reported, Appv alt material		
Petro. Monitoring:	Auto sample wells, DW tank space, Not required, Auto tank gauging, GW monitoring		

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Op-flow shut off		
Tank Piping:	Fiberglass, Pressurized piping, Unknown/not reported, Appv alt material		
Petro. Monitoring:	Auto sample wells, DW tank space, Not required, Auto tank gauging, GW monitoring		

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/12
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Op-flow shut off		
Tank Piping:	Fiberglass, Pressurized piping, Unknown/not reported, Appv alt material		
Petro. Monitoring:	Auto sample wells, DW tank space, Not required, Auto tank gauging, GW monitoring		

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	6	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Cath prot-imp curr		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Man sample wells		

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	7	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

40

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	8	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

410

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	9	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

41

KENTUCKY FRIED CHICKEN
1602 N HOWARD AVE
TAMPA, FL

UST
LUST

U002217722
N/A

41

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KENTUCKY FRIED CHICKEN (Continued)

U002217722

LUST:

Facility ID:	9501915	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	5024548027	Discovery Date:	07/01/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant: LEADED GAS

Pollutant 2: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION

REIMBURSEMENT CLEANUP

ELIGIBLE

Not Reported

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

APPROVED

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

41

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KENTUCKY FRIED CHICKEN (Continued)

U002217722

UST:

Facility ID:	299501915	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	5024548027
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950606	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	DAVID CATTELL		
Owner:	KFC NATIONAL MANAGEMENT CO		
	PO BOX 34550		
	LOUISVILLE, KY 402324550		
Owner's Phone:	5024548027	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	1
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

42

WALTER INDUSTRIES INC
1500 N DALE MABRY HWY
TAMPA, FL 33607

UST
LUST

U001356165
N/A

42

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WALTER INDUSTRIES INC (Continued)

U001356165

LUST:

Facility ID:	9047096	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138714274	Discovery Date:	03/04/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

42

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WALTER INDUSTRIES INC (Continued)

U001356165

UST:

Facility ID:	299047096	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WALTER INDUSTRIES INC		
Contact:	Not reported	Facility Phone:	8138714274
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900926	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	M C KLEITZ		
Owner:	WALTER INDUSTRIES INC		
	PO BOX 31601		
	TAMPA, FL 336313601		
Owner's Phone:	8138714755	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/01
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill, Level gauges/hi level alarms, dblwall=2nd material		
Tank Piping:	Unprotec metal, Fiberglass, Suction piping, Dblwall=2nd material		
Petro. Monitoring:	DW tank space, DW piping space		

42

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

WALTER INDUSTRIES INC (Continued)

U001356165

Facility ID:	299047096	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WALTER INDUSTRIES INC		
Contact:	Not reported	Facility Phone:	8138714274
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900926	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	M C KLEITZ		
Owner:	WALTER INDUSTRIES INC		
	PO BOX 31601		
	TAMPA, FL 336313601		
Owner's Phone:	8138714755	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

43	LAW ENGINEERING 4919 WEST LAUREL STREET TAMPA, FL 33607	RCRIS-SQG FINDS	1000112500 FLD982111528
44	TEXACO STATION 2502 W LAUREL ST TAMPA, FL 33607	UST	U001355384 N/A

4/4

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO STATION (Continued)

U001355384

UST:

Facility ID:	298732178	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FORMER TEXACO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870217	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DYVONNE JONES		
Owner:	STAR ENTERPRISE		
	333 RESEARCH CT		
	NORCROSS, GA 30092		
Owner's Phone:	4044535443	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

49

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO STATION (Continued)

U001355384

Facility ID:	298732178	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FORMER TEXACO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870217	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DYVONNE JONES		
Owner:	STAR ENTERPRISE 333 RESEARCH CT NORCROSS, GA 30092		
Owner's Phone:	4044535443	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

44

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO STATION (Continued)

U001355384

Facility ID:	298732178	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FORMER TEXACO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870217	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DYVONNE JONES		
Owner:	STAR ENTERPRISE		
	333 RESEARCH CT		
	NORCROSS, GA 30092		
Owner's Phone:	4044535443	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

24

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO STATION (Continued)

U001355384

Facility ID:	298732178	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FORMER TEXACO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870217	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DYVONNE JONES		
Owner:	STAR ENTERPRISE		
	333 RESEARCH CT		
	NORCROSS, GA 30092		
Owner's Phone:	4044535443	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

45

TAMPA CITY - PUBLICATION/RECREATION
1420 N TAMPA ST
TAMPA, FL 33602

UST

U001823387
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY - PUBLICATION/RECREATION (Continued)

U001823387

UST:

Facility ID:	299400333	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HALLIE CALIG		
Contact:	Not reported	Facility Phone:	8132748082
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940325	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HALLIE CALIG		
Owner:	TAMPA, CITY OF CITY HALL PLAZA TAMPA, FL 33602		
Owner's Phone:	8132238282	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

46

HILLSBOROUGH CNTY-MORGAN ST JAIL
1301 N MORGAN ST
TAMPA, FL 33602

UST

U001356353
N/A

46

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-MORGAN ST JAIL. (Continued)

U001356353

UST:

Facility ID:	299102571	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FARMER, J R		
Contact:	Not reported	Facility Phone:	8132478425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910806	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT		
	PO BOX 3371		
	TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	63/10
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

46

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-MORGAN ST JAIL (Continued)

U001356353

Facility ID:	299102571	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FARMER, J R		
Contact:	Not reported	Facility Phone:	8132478425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910806	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	6/3/10
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

4/6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-MORGAN ST JAIL (Continued)

U001356353

Facility ID:	299102571	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FARMER, J R		
Contact:	Not reported	Facility Phone:	8132478425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910806	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	79/10
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

46

HILLSBOROUGH CNTY-JAIL SYSTEM
1308 N MORGAN ST
TAMPA, FL 33602

UST
LUST

U001355249
N/A

46

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-JAIL SYSTEM (Continued)

U001355249

LUST:

Facility ID:	8627689	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132476411	Discovery Date:	12/19/88
Tracking Number:	297405	Score:	020 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05520		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

46

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-JAIL SYSTEM (Continued)

U001355249

UST:

Facility ID:	298627689	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HILLS CNTY SHERIFFS JAIL-SYSTEM		
Contact:	Not reported	Facility Phone:	8132476411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	297405
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

46

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HILLSBOROUGH CNTY-JAIL SYSTEM (Continued)

U001355249

Facility ID:	298627689	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HILLS CNTY SHERIFFS JAIL-SYSTEM		
Contact:	Not reported	Facility Phone:	8132476411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	297405
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

47

CONVENIENT FOOD MART #5503
1424 N HOWARD AVE
TAMPA, FL 33607

UST
LUST

U001354336
N/A

47

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CONVENIENT FOOD MART #5503 (Continued)

U001354336

LUST:

Facility ID:	8625096	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132516776	Discovery Date:	01/27/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

47

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CONVENIENT FOOD MART #5503 (Continued)

U001354336

UST:

Facility ID:	298625096	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COX CARL & VICKI		
Contact:	Not reported	Facility Phone:	8132516776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES FELTZ		
Owner:	REMOTE SERVICES INC		
	ONE VISION DR		
	ENFIELD, CT 06082		
Owner's Phone:	2037414444	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

47

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CONVENIENT FOOD MART #5503 (Continued)

U001354336

Facility ID:	298625096	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COX CARL & VICKI		
Contact:	Not reported	Facility Phone:	8132516776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JAMES FELTZ		
Owner:	REMOTE SERVICES INC		
	ONE VISION DR		
	ENFIELD, CT 06082		
Owner's Phone:	2037414444	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

47

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CONVENIENT FOOD MART #5503 (Continued)

U001354336

Facility ID:	298625096	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COX CARL & VICKI		
Contact:	Not reported	Facility Phone:	8132516776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JAMES FELTZ		
Owner:	REMOTE SERVICES INC		
	ONE VISION DR		
	ENFIELD, CT 06082		
Owner's Phone:	2037414444	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

48

AUTOMAN INC
1406 N ARMENIA
TAMPA, FL 33607

RCRIS-SQG
FINDS

1000500500
FLD984205948

RCRIS:

Owner: DON GARNER, MGR
(813) 875-2000

Contact: DON GARNER
(813) 875-2000

Waste	Quantity	Info Source
D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

48

CITGO-ARMENIA
1415 N ARMENIA AVE
TAMPA, FL 33607

UST
LUST

U001354700
N/A

46

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CITGO-ARMENIA (Continued)

U001354700

LUST:

Facility ID:	8625485	Facility Type:	RETAIL STATION
Alias Name:	PHILLIPS 66-ARMENIA		
Telephone:	8136814279	Discovery Date:	11/16/87
Tracking Number:	292169	Score:	031
Facility Code:	Not reported	Status:	Not reported
Rank:	03984		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

4/8

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CITGO-ARMENIA (Continued)

U001354700

UST:

Facility ID:	298625485	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P KNIGHTLY		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	292169
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

218

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CITGO-ARMENIA (Continued)

U001354700

Facility ID:	298625485	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P KNIGHTLY		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	292169
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

48

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CITGO-ARMENIA (Continued)

U001354700

Facility ID:	298625485	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P KNIGHTLY		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	292169
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

476

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CITGO-ARMENIA (Continued)

U001354700

Facility ID:	298625485	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P KNIGHTLY		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	292169
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

48

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CITGO-ARMENIA (Continued)

U001354700

Facility ID:	298625485	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P KNIGHTLY		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	292169
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging, GW monitoring		

418

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CITGO-ARMENIA (Continued)

U001354700

Facility ID:	298625485	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P KNIGHTLY		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	292169
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging, GW monitoring		

42

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CITGO-ARMENIA (Continued)

U001354700

Facility ID:	298625485	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P KNIGHTLY		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	292169
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging, GW monitoring		

49

DREW TILE SUPPLY CO
1401 N HIMES AVE
TAMPA, FL 33607

UST
LUST

U001354589
N/A

49

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DREW TILE SUPPLY CO (Continued)

U001354589

LUST:

Facility ID:	8625369	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138762483	Discovery Date:	10/29/91
Tracking Number:	Not reported	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06571		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

49

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DREW TILE SUPPLY CO (Continued)

U001354589

UST:

Facility ID:	298625369	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DREW TILE SUPPLY CO		
Contact:	Not reported	Facility Phone:	8138762483
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES COOPER		
Owner:	SPARTAN OIL CO.,INC. P O BOX 25858 TAMPA, FL 33622		
Owner's Phone:	8132473417	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

50

WESTERN WATERPROOFING CO OF AMERICA
4924 LASALLE ST
TAMPA, FL 33607

RCRIS-SQG 1000402329
FINDS FLD982087736

RCRIS:

Owner: BORCHERT FRITZ MGR
(813) 877-7646

Contact: BORCHERT FRITZ
(813) 877-7646

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

51

BLANCO FUEL OIL
1701 W LA SALLE ST
TAMPA, FL 33607

UST U001355550
LUST N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

LUST:

Facility ID:	8735467	Facility Type:	INLAND BULK PETROLEUM
Alias Name:	Not reported		
Telephone:	8132530230	Discovery Date:	03/19/91
Tracking Number:	Not reported	Score:	038
Facility Code:	Not reported	Status:	Not reported
Rank:	02755		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	KEROSENE	Est. Gallons Lost:	UNKNOWN
------------	----------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	OTHER

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

51

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

UST:

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	68/02
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

51

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	73/08
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	7/1/05
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	9/1/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

51

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink, Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

52

XEROX CORP
1308 N WARD ST
TAMPA, FL 33607

UST

U001355082
N/A

52

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

XEROX CORP (Continued)

U001355082

UST:

Facility ID:	298627008	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	XEROX CORP		
Contact:	Not reported	Facility Phone:	8138798150
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RICHARD L REISENWEBER		
Owner:	XEROX CORP		
	800 PHILLIPS RD #317		
	WEBSTER, NY 145809720		
Owner's Phone:	7164229443	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	81/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

53

MOBIL #02-CNH
1101 N DALE MABRY HWY & I-275
TAMPA, FL 33607

UST
LUST

U001354244
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL #02-CNH (Continued)

U001354244

LUST:

Facility ID:	8624998	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8138701187	Discovery Date:	04/04/91
Tracking Number:	293176	Score:	020 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05520		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL #02-CN (Continued)

U001354244

UST:

Facility ID:	298624998	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8138701187
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	293176
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL #02-CNH (Continued)

U001354244

Facility ID:	298624998	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8138701187
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	293176
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

53

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL #02-CNH (Continued)

U001354244

Facility ID:	298624998	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8138701187
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	293176
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

43

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL #02-CN (Continued)

U001354244

Facility ID:	298624998	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8138701187
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	293176
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

53

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL #02-CNH (Continued)

U001354244

Facility ID:	298624998	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8138701187
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	293176
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL #02-CNH (Continued)

U001354244

Facility ID:	298624998	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8138701187
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	293176
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

43

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL #02-CNH (Continued)

U001354244

Facility ID:	298624998	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8138701187
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	293176
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

53

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL #02-CN (Continued)

U001354244

Facility ID:	298624998	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8138701187
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	4R1	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	293176
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

53

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL #02-CNH (Continued)

U001354244

Facility ID:	298624998	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8138701187
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	293176
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

43

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

MOBIL #02-CN (Continued)

U001354244

Facility ID:	298624998	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8138701187
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	5R1	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	293176
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/12
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Suction piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

54	TRAMMEL BUILDING 1313 TAMPA STREET TAMPA, FL 33602	PADS	1000855724 FL0000060509
54	TRAMMEL BUILDING 1313 TAMPA ST TAMPA, FL 33602	FINDS	1000931308 FL0000060509
54	FL DEPT OF MGMT SERVICES-PK TRAMMEL 1313 N TAMPA ST TAMPA, FL 33602	UST	U001355829 N/A

54

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FL DEPT OF MGMT SERVICES-PK TRAMMEL (Continued)

U001355829

UST:

Facility ID:	298841073	Facility Type:	State Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BOB MORALES		
Contact:	Not reported	Facility Phone:	8132722313
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880805	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CARL L MORGAN		
Owner:	FL DEPT MGMT SERVICES BUREAU OF 4050 ESPLANADE WAY BLCG 4030 #38 TALLAHASSEE, FL 323990950		
Owner's Phone:	9044885332	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Not required		

55

FINA STATION
1301 N HOWARD AVE
TAMPA, FL 33607

UST
LUST

U001037423
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

LUST:

Facility ID:	8737181	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132543090	Discovery Date:	03/29/87
Tracking Number:	291132	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN	Est. Gallons Lost:	UNKNOWN
------------	---------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	REC DRAW
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

55

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

UST:

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Dbl walled=primary matl, Spill cnmt		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Aprvd alt sys		

55

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	11	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Dbl walled=primary matl, Spill cnmt		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Aprvd alt sys		

SS

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

SS

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

SS

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

SS

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC		
	1301 N HOWARD AVE		
	TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC		
	1301 N HOWARD AVE		
	TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

SS

MAP FINDINGS

Map ID
Direction
Distance

Site


Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC		
	1301 N HOWARD AVE		
	TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man tank gauging		



MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC		
	1301 N HOWARD AVE		
	TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man tank gauging		

55

GUNN PRINTING & LITHOGRAPHY INC
1313 N HOWARD AVE
TAMPA, FL 33607

RCRIS-SQG 1000450175
FINDS FLD984179705

RCRIS:

Owner: MIKE GUNN, PRES
(813) 254-2513

Contact: MIKE GUNN
(813) 254-2513

Waste	Quantity	Info Source
D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

56

SCHLICHTE PROPERTY
1301 N ROME AVE
TAMPA, FL 33607

UST

U001823399
N/A

56

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SCHLICHTE PROPERTY (Continued)

U001823399

UST:

Facility ID:	299400491	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MRS SCHLICHTE		
Contact:	Not reported	Facility Phone:	8138371646
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940405	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	FRED W. SCHLICHTE		
Owner:	SCHLICHTE, FRED W 5122 W POE AVE TAMPA, FL 336297527		
Owner's Phone:	8138371646	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

56	RECHEM TRANSPORT CORP 1301 N ROME AVE TAMPA, FL 33617	FINDS	1000931530 FL0000260729
----	---	-------	----------------------------

56	RECHEM TRANSPORT CORP 1301 NORTH ROME AVENUE TAMPA, FL 33617	RCRIS-SQG	1000687747 FLD991304619
----	--	-----------	----------------------------

57	JAMES WICKER IMPORTS 5005 NASSAU ST TAMPA, FL 33607	RCRIS-SQG FINDS	1000498605 FLD982159220
----	---	--------------------	----------------------------

RCRIS:

Owner: RUSSO MORRIS V PRES
(813) 873-7129

Contact:RUSSO MORRIS
(813) 873-7129

Waste	Quantity	Info Source
D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

57

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number												
57	RFD INC 5024 NASSAU ST TAMPA, FL 33607 RCRIS: Owner: RICHARDSON PAULA INV CONT MGR (813) 872-1502 Contact:RICHARDSON PAULA (813) 872-1502 <table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>F001</td><td>.00000 (T)</td><td>Notification</td><td>F003</td><td>.00000 (T)</td><td>Notification</td></tr></table> (P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported	Waste	Quantity	Info Source	Waste	Quantity	Info Source	F001	.00000 (T)	Notification	F003	.00000 (T)	Notification	RCRIS-SQG FINDS	1000118806 FLD982121386
Waste	Quantity	Info Source	Waste	Quantity	Info Source										
F001	.00000 (T)	Notification	F003	.00000 (T)	Notification										
58	TAMPA AUTOMOTIVE PROTECTION IN 3808 W NASSAU AVE TAMPA, FL 33607	RCRIS-SQG FINDS	1000344832 FLD982116998												
59	AUTOBOND IMPORTS 1112 N FLORIDA AVE TAMPA, FL 33602	UST LUST	U001356103 N/A												

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AUTOBOND IMPORTS (Continued)

U001356103

LUST:

Facility ID:	9045730	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	01/08/90
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AUTOBOND IMPORTS (Continued)

U001356103

UST:

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AUTOBOND IMPORTS (Continued)

U001356103

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E		
	1101 RAVENWOOD DR		
	VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AUTOBOND IMPORTS (Continued)

U001356103

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AUTOBOND IMPORTS (Continued)

U001356103

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AUTOBOND IMPORTS (Continued)

U001356103

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AUTOBOND IMPORTS (Continued)

U001356103

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AUTOBOND IMPORTS (Continued)

U001356103

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

59

USE 299045730
1112 N FLORIDA AVE
TAMPA, FL 33602

UST
LUST

U001355893
N/A

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299045730 (Continued)

U001355893

LUST:

Facility ID:	8842270	Facility Type:	RETAIL STATION
Alias Name:	TELANDER'S STATION		
Telephone:	Not reported	Discovery Date:	01/08/90
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:	TANK REMOVAL	

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299045730 (Continued)

U001355893

UST:

Facility ID:	298842270	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TELANDER'S,INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881207	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER'S,INC		
	1101 RAVENWOOD DR		
	VALRICO, FL 335942946		
Owner's Phone:	8136858340	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	65/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299045730 (Continued)

U001355893

Facility ID:	298842270	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TELANDER'S,INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881207	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER'S,INC		
	1101 RAVENWOOD DR		
	VALRICO, FL 335942946		
Owner's Phone:	8136858340	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

59

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299045730 (Continued)

U001355893

Facility ID:	298842270	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TELANDER'S,INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881207	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER'S,INC		
	1101 RAVENWOOD DR		
	VALRICO, FL 335942946		
Owner's Phone:	8136858340	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

60

TAMPA,CITY-ROYAL ST PARKING LOT
ROYAL ST / TAMPA ST
TAMPA, FL

UST
LUST

U001378004
N/A

60

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

LUST:

Facility ID:	8841046	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	09/29/87
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

60

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

UST:

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS 1601 N MARION ST TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS		
	1601 N MARION ST		
	TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink, Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS		
	1601 N MARION ST		
	TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS		
	1601 N MARION ST		
	TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		



MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS		
	1601 N MARION ST		
	TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS		
	1601 N MARION ST		
	TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

10

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS		
	1601 N MARION ST		
	TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

61

MIAMI ELEVATOR CO.
5100 W GRACE ST
TAMPA, FL 33607

AST

A100008838
N/A

61

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MIAMI ELEVATOR CO. (Continued)

A100008838

AST:

Facility ID:	298736801	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MIAMI ELEVATOR CO.		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	871218	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM LEONARD		
Owner:	MIAMI ELEVATOR CO 7481 NW 66TH ST MIAMI, FL 331662801		
Owner's Phone:	3055927722	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000500
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298736801	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MIAMI ELEVATOR CO.		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	871218	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JIM LEONARD		
Owner:	MIAMI ELEVATOR CO 7481 NW 66TH ST MIAMI, FL 331662801		
Owner's Phone:	3055927722	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000250
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

62

SHAHEEN/ALBERT
4901 W GRACE ST
TAMPA, FL 33607

UST

U001354935
N/A

62

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHAHEEN/ALBERT (Continued)

U001354935

UST:

Facility ID:	298625732	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ALBERT SHAHEEN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ALBERT SHAHEEN		
Owner:	R. CARLTON WARD		
	P O BOX 349		
	TAMPA, FL 33601		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

62

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHAHEEN/ALBERT (Continued)

U001354935

Facility ID:	298625732	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ALBERT SHAHEEN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ALBERT SHAHEEN		
Owner:	R. CARLTON WARD P O BOX 349 TAMPA, FL 33601		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

62

CREATIVE COLOR INC
4911 W GRACE
TAMPA, FL 33607

RCRIS-SQG 1000159436
FINDS FLD073216301

RCRIS:

Owner: ALDO MICHELETTI, MGR
(813) 289-4385

Contact:ALDO MICHELETTI
(813) 289-4385

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

63

C G JONES & SONS DBA ALGAE EATERS
3709 GRACE ST
TAMPA, FL 33629

FINDS 1000932636
FL0000632505

64

MOBIL OIL CORP SS# CNH
1101 N DALE MABRY
TAMPA, FL 33607

FINDS 1000737481
FLD984203638

64

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

65			CRITIKON INC 5830 WEST CYPRESS STREET TAMPA, FL 33607	RCRIS-SQG FINDS	1000411683 FLD021714100	
----	--	--	--	----------------------------------	----------------------------	--

65			DAMON CLINICAL LABORATORIES 5850 W CYPRESS ST TAMPA, FL 33607	RCRIS-SQG FINDS	1000335906 FLD982078131	
----	--	--	--	----------------------------------	----------------------------	--

RCRIS:

Owner: BRADLEY BONDANZA, BRANCH OPER MGR
(813) 289-5400

Contact: BONDANZA BRADLEY
(813) 289-5400

Waste	Quantity	Info Source	Waste	Quantity	Info Source
F003	.00000 (T)	Notification	U002	.00000 (T)	Notification
U122	.00000 (T)	Notification	U154	.00000 (T)	Notification
U161	.00000 (T)	Notification	U239	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

65			BAY REPROGRAPHICS INC 5850 W CYPRESS ST TAMPA, FL 33607	UST	U002113428 N/A	
----	--	--	--	------------	-------------------	--

UST:

Facility ID:	299300168	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MARTHA KORMAN		
Contact:	Not reported	Facility Phone:	8132868300
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930302	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	WAYNE CARMICHAEL		
Owner:	BOWER AMMONIA & CHEMICAL CO 5811 TACONY ST PHILADELPHIA, PA 19135		
Owner's Phone:	2158311717	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	C	Any contam. groundwater:	Not reported
Tank Content:	Ammonia compound	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	89/10
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Op-flow shut off, Op-tight fill, dblwall=2nd material, Built on supports		
Tank Piping:	Pressurized piping		
Petro. Monitoring:	Piping/flow restrictor, Man tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

66	BAY CENTER CORP 5100 W CYPRESS TAMPA, FL 33607	RCRIS-SQG FINDS	1000106354 FLD067223404
----	---	----------------------------------	--

RCRIS:

Owner: MIKE STETINA ASST MGR
(813) 879-1980

Contact: MIKE STETINA
(813) 879-1980

Waste	Quantity	Info Source
-------	----------	-------------

D001	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

66	PAYLESS CAR RENTAL SYSTEM INC 5105 W CYPRESS ST TAMPA, FL 33607	UST	U001355390 N/A
----	--	------------	---------------------------------

UST:

Facility ID:	298732393	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAYLESS CAR RENTAL SYSTEM		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870410	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DALE SMITH		
Owner:	SMITH, DALE 5105 W CYPRESS ST TAMPA, FL 33607		
Owner's Phone:	8132896554	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	87/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

66	7-ELEVEN FOOD STORE #24305 5125 W CYPRESS ST TAMPA, FL 33607	UST LUST	U001355234 N/A
----	---	---------------------------	---------------------------------

66

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

7-ELEVEN FOOD STORE #24305 (Continued)

U001355234

LUST:

Facility ID:	8627491	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	4072953076	Discovery Date:	11/30/89
Tracking Number:	294794	Score:	036
Facility Code:	Not reported	Status:	Not reported
Rank:	02970		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	CONTAMINATION ASSESSMENT REPORT
Extension Status:	APPROVED
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	O.K.

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

66

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

7-ELEVEN FOOD STORE #24305 (Continued)

U001355234

UST:

Facility ID:	298627491	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLO SMITH		
Contact:	Not reported	Facility Phone:	4072953076
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLO SMITH		
Owner:	SOUTHLAND CORP		
	1304 LEE RD		
	ORLANDO, FL 32810		
Owner's Phone:	4072950979	Tracking #:	294794
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

66

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

7-ELEVEN FOOD STORE #24305 (Continued)

U001355234

Facility ID:	298627491	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLO SMITH		
Contact:	Not reported	Facility Phone:	4072953076
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLO SMITH		
Owner:	SOUTHLAND CORP		
	1304 LEE RD		
	ORLANDO, FL 32810		
Owner's Phone:	4072950979	Tracking #:	294794
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

66

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

7-ELEVEN FOOD STORE #24305 (Continued)

U001355234

Facility ID:	298627491	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLO SMITH		
Contact:	Not reported	Facility Phone:	4072953076
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLO SMITH		
Owner:	SOUTHLAND CORP		
	1304 LEE RD		
	ORLANDO, FL 32810		
Owner's Phone:	4072950979	Tracking #:	294794
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

66

VELDA FARMS
5124 W CYPRESS ST
TAMPA, FL 33607

UST
LUST
AST

U001354687
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

VELDA FARMS (Continued)

U001354687

LUST:

Facility ID:	8625469	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	03/27/86
Tracking Number:	290678	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05851		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	00000050
------------	------------	--------------------	----------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE

66

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

VELDA FARMS (Continued)

U001354687

UST:

Facility ID:	298625469	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VELDA FARMS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLO SMITH		
Owner:	SOUTHLAND CORP 1304 LEE RD ORLANDO, FL 32810		
Owner's Phone:	4072950979	Tracking #:	290678
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

VELDA FARMS (Continued)

U001354687

Facility ID:	298625469	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VELDA FARMS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLO SMITH		
Owner:	SOUTHLAND CORP 1304 LEE RD ORLANDO, FL 32810		
Owner's Phone:	4072950979	Tracking #:	290678
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Piping/flow restrictor		

AST:

Facility ID:	298625469	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VELDA FARMS		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLO SMITH		
Owner:	SOUTHLAND CORP 1304 LEE RD ORLANDO, FL 32810		
Owner's Phone:	4072950979	Tracking #:	290678
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Completed	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/08
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, Cath prot-sac anode		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Piping/flow restrictor		

67

CARSON PLUMBING CO., INC.
5045 W CYPRESS ST
TAMPA, FL 33607

UST
LUST

U001355142
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CARSON PLUMBING CO., INC. (Continued)

U001355142

LUST:

Facility ID:	8627214	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138761327	Discovery Date:	12/14/88
Tracking Number:	295750	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

67

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CARSON PLUMBING CO., INC. (Continued)

U001355142

UST:

Facility ID:	298627214	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CARSON PLUMBING CO., INC.		
Contact:	Not reported	Facility Phone:	8138761327
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	SCOTT STROMBERGER		
Owner:	CARSON, WILLIAM G 5045 W CYPRESS ST TAMPA, FL 336073803		
Owner's Phone:	8138761327	Tracking #:	295750
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/10
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CARSON PLUMBING CO., INC. (Continued)

U001355142

Facility ID:	298627214	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CARSON PLUMBING CO., INC.		
Contact:	Not reported	Facility Phone:	8138761327
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	SCOTT STROMBERGER		
Owner:	CARSON, WILLIAM G 5045 W CYPRESS ST TAMPA, FL 336073803		
Owner's Phone:	8138761327	Tracking #:	295750
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

68	ANACOMP 4920 W CYPRESS ST TAMPA, FL 33607	RCRIS-SQG	1001023470 FLR000003673
----	---	-----------	----------------------------

RCRIS:

Owner: OWEN MILES, OPERATIONS MGR
(813) 289-1608

Contact: Not reported

Waste	Quantity	Info Source
-------	----------	-------------

D011	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

68	ANACOMP 4920 W CYPRESS ST TAMPA, FL 33607	FINDS	1000999521 FL0001209865
----	---	-------	----------------------------

69	MARRIOTT-WESTSHORE 1001 N WESTSHORE BLVD TAMPA, FL 33607	UST	U001355377 N/A
----	--	-----	-------------------

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARRIOTT-WESTSHORE (Continued)

U001355377

UST:

Facility ID:	298731836	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RUNYON, DON		
Contact:	Not reported	Facility Phone:	8132872555
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870116	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DON RUNYON		
Owner:	POTOMAC HOTELS LTD PARTNERSHIP		
	1001 N WESTSHORE BLVD		
	TAMPA, FL 336074707		
Owner's Phone:	8132872555	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/05
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Op-tight fill		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Not required		

69

SHELL-SHEP SERVICE
1002 N WESTSHORE BLVD
TAMPA, FL 33607

UST
LUST

U001354321
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-SHEP SERVICE (Continued)

U001354321

LUST:

Facility ID:	8625080	Facility Type:	RETAIL STATION
Alias Name:	SHELL-MANSOUR		
Alias Name 2:	SHELL-SHEP SERVICE		
Telephone:	8138776446	Discovery Date:	03/22/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	OTHER
Incident Ineligible Description:	OTHER

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

69

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-SHEP SERVICE (Continued)

U001354321

UST:

Facility ID:	298625080	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DYOLL E. SHEPLER		
Contact:	Not reported	Facility Phone:	8138776446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO		
	PO BOX 20427		
	TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010152	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-SHEP SERVICE (Continued)

U001354321

Facility ID:	298625080	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DYOLL E. SHEPLER		
Contact:	Not reported	Facility Phone:	8138776446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009728	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-SHEP SERVICE (Continued)

U001354321

Facility ID:	298625080	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DYOLL E. SHEPLER		
Contact:	Not reported	Facility Phone:	8138776446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00007896	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-SHEP SERVICE (Continued)

U001354321

Facility ID:	298625080	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DYOLL E. SHEPLER		
Contact:	Not reported	Facility Phone:	8138776446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009728	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-SHEP SERVICE (Continued)

U001354321

Facility ID:	298625080	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DYOLL E. SHEPLER		
Contact:	Not reported	Facility Phone:	8138776446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005830	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-SHEP SERVICE (Continued)

U001354321

Facility ID:	298625080	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DYOLL E. SHEPLER		
Contact:	Not reported	Facility Phone:	8138776446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009728	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

69

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-SHEP SERVICE (Continued)

U001354321

Facility ID:	298625080	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DYOLL E. SHEPLER		
Contact:	Not reported	Facility Phone:	8138776446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/04
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

70

BARNETT BANK BLDG
4600 W CYPRESS ST
TAMPA, FL 33607

UST

U001356162
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BARNETT BANK BLDG (Continued)

U001356162

UST:

Facility ID:	299047048	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BARNETT BANK		
Contact:	Not reported	Facility Phone:	8132258236
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900924	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	KATHY LESER		
Owner:	BARNETT BANK INC		
	PO BOX 30014		
	TAMPA, FL 33611		
Owner's Phone:	8132558143	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	77/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

71

SHELL STATION
1001 N DALE MABRY HWY
TAMPA, FL 33607

UST
LUST

U001354348
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL STATION (Continued)

U001354348

LUST:

Facility ID:	8625108	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	07/01/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	DISTRICT OFFICE
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL STATION (Continued)

U001354348

Facility ID:	8623573	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8139389897	Discovery Date:	01/31/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		
INCIDENT GENERAL INFORMATION -			
Source Description:		DISCHARGE NOTIFICATION	
Lead:		DISTRICT OFFICE	
Incident 17-770 Cleanup:		NEW C/U REQUIRED	
INCIDENT POLLUTANT INFORMATION -			
Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
INCIDENT PROGRAM INFORMATION -			
Incident Program:		PETRO. LIABILITY INS. & RESTOR.	
Incident Program Type:		REIMBURSEMENT CLEANUP	
Incident Eligible Status:		PARTIAL	
Incident Ineligible Reason:		OTHER	
Incident Ineligible Description:		OTHER	
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:		Cleanup Responsible:	Not reported
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:		Not reported	
Response Record Type:		Not reported	
Response Remedial Action Plan Type:		Not reported	
Response Status:		Not reported	
Extension Record Type:		Not reported	
Extension Status:		Not reported	
Extension Comments:		Not reported	
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:		Not reported	
Response Record Type:		Not reported	
Response Remedial Action Plan Type:		Not reported	
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:		Not reported	
Estimated Completion Year:		Not reported	
Actual Year to Complete:		Not reported	
Report Type:		Not reported	
Report Comments:		Not reported	
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:		Not reported	
Region:		STATE	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL STATION (Continued)

U001354348

UST:

Facility ID:	298625108	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ROBERT MOORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009886	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL STATION (Continued)

U001354348

Facility ID:	298625108	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ROBERT MOORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009886	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL STATION (Continued)

U001354348

Facility ID:	298625108	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ROBERT MOORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009886	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL STATION (Continued)

U001354348

Facility ID:	298625108	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ROBERT MOORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005036	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL STATION (Continued)

U001354348

Facility ID:	298625108	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ROBERT MOORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	66/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		



MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL STATION (Continued)

U001354348

Facility ID:	528623573	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALTMAN, P J		
Contact:	Not reported	Facility Phone:	8139389897
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860404	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO		
	PO BOX 20427		
	TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009438	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL STATION (Continued)

U001354348

Facility ID:	528623573	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALTMAN, P J		
Contact:	Not reported	Facility Phone:	8139389897
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860404	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO		
	PO BOX 20427		
	TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009438	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL STATION (Continued)

U001354348

Facility ID:	528623573	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALTMAN, P J		
Contact:	Not reported	Facility Phone:	8139389897
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860404	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009438	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

71

EXXON #7484
1004 N DALE MABRY HWY
TAMPA, FL 33607

UST
LUST

U001354770
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #7484 (Continued)

U001354770

LUST:

Facility ID:	8625557	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8138798811	Discovery Date:	04/15/88
Tracking Number:	292883	Score:	013 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05873		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	00000100
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #7484 (Continued)

U001354770

UST:

Facility ID:	298625557	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	EXXON COMPANY USA		
Contact:	Not reported	Facility Phone:	8138798811
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	NORMA DANIELS		
Owner:	EXXON CO USA		
	PO BOX 4386		
	HOUSTON, TX 772104386		
Owner's Phone:	7136567059	Tracking #:	292883
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #7484 (Continued)

U001354770

Facility ID:	298625557	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	EXXON COMPANY USA		
Contact:	Not reported	Facility Phone:	8138798811
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	NORMA DANIELS		
Owner:	EXXON CO USA		
	PO BOX 4386		
	HOUSTON, TX 772104386		
Owner's Phone:	7136567059	Tracking #:	292883
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #7484 (Continued)

U001354770

Facility ID:	298625557	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	EXXON COMPANY USA		
Contact:	Not reported	Facility Phone:	8138798811
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	NORMA DANIELS		
Owner:	EXXON CO USA PO BOX 4386 HOUSTON, TX 772104386		
Owner's Phone:	7136567059	Tracking #:	292883
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #7484 (Continued)

U001354770

Facility ID:	298625557	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	EXXON COMPANY USA		
Contact:	Not reported	Facility Phone:	8138798811
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	NORMA DANIELS		
Owner:	EXXON CO USA		
	PO BOX 4386		
	HOUSTON, TX 772104386		
Owner's Phone:	7136567059	Tracking #:	292883
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #7484 (Continued)

U001354770

Facility ID:	298625557	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	EXXON COMPANY USA		
Contact:	Not reported	Facility Phone:	8138798811
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	NORMA DANIELS		
Owner:	EXXON CO USA		
	PO BOX 4386		
	HOUSTON, TX 772104386		
Owner's Phone:	7136567059	Tracking #:	292883
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

72 HILLSBOROUGH CO JEFFERSON HIGH SCHO
4001 W CYPRESS ST
TAMPA, FL 33605

RCRIS-SQG 1000687530
FLD984237909

RCRIS:

Owner: PHILLIP GUFFEY, COORD
(813) 626-0806

Contact: PHILLIP GUFFEY
(813) 626-0806

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D002	.00000 (T)	Notification	D003	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

72 HILLSBOROUGH CO JEFFERSON HIGH SCHO
4001 W CYPRESS ST
TAMPA, FL 33605

FINDS 1000738656
FLD984237909

73 PASS RENT A CAR
3830 W CYPRESS ST
TAMPA, FL 33607

UST
LUST U001354485
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PASS RENT A CAR (Continued)

U001354485

LUST:

Facility ID:	8625254	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132513218	Discovery Date:	03/29/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

73

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PASS RENT A CAR (Continued)

U001354485

UST:

Facility ID:	298625254	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BARRS, CARRINGTON		
Contact:	Not reported	Facility Phone:	8132513218
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CARRINGTON BARRS		
Owner:	DAYTON ANDREWS INC		
	3830 W CYPRESS ST		
	TAMPA, FL 33607		
Owner's Phone:	8138729148	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

74

CRAYS BODY SHOP
3632 CYPRESS ST
TAMPA, FL 33607

RCRIS-SQG 1000450173
FINDS FLD984175901

RCRIS:

Owner: ROBERT CRAYS, OWNER
(813) 877-6763

Contact: ROBERT CRAYS
(813) 877-6763

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F003	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

75

UNITED AUTO CLINIC INC
1002 N HOWARD AVE
TAMPA, FL 33607

UST U001354098
LUST N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED AUTO CLINIC INC (Continued)

U001354098

LUST:

Facility ID:	8624839	Facility Type:	RETAIL STATION
Alias Name:	UNITED AUTO SERVICE		
Telephone:	8132544459	Discovery Date:	09/23/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NONCOMPLAINEE 17-769 RULE
Incident Ineligible Description:	NONCOMPLIANCE 1

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED AUTO CLINIC INC (Continued)

U001354098

UST:

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	RADIANT OIL CO TAMPA INC. P O BOX 5751 TAMPA, FL 33675		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Airport/seaport hydrant, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED AUTO CLINIC INC (Continued)

U001354098

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	RADIANT OIL CO TAMPA INC. P O BOX 5751 TAMPA, FL 33675		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Airport/seaport hydrant, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED AUTO CLINIC INC (Continued)

U001354098

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	RADIANT OIL CO TAMPA INC. P O BOX 5751 TAMPA, FL 33675		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Airport/seaport hydrant, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED AUTO CLINIC INC (Continued)

U001354098

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	RADIANT OIL CO TAMPA INC. P O BOX 5751 TAMPA, FL 33675		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Airport/seaport hydrant, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED AUTO CLINIC INC (Continued)

U001354098

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	RADIANT OIL CO TAMPA INC. P O BOX 5751 TAMPA, FL 33675		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	69/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Airport/seaport hydrant, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED AUTO CLINIC INC (Continued)

U001354098

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	RADIANT OIL CO TAMPA INC. P O BOX 5751 TAMPA, FL 33675		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED AUTO CLINIC INC (Continued)

U001354098

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	RADIANT OIL CO TAMPA INC. P O BOX 5751 TAMPA, FL 33675		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

76

CASTELLANO PROPERTY
512 E CASS ST
TAMPA, FL 33602

UST
LUST

U001356301
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CASTELLANO PROPERTY (Continued)

U001356301

LUST:

Facility ID:	9101375	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8139497776	Discovery Date:	02/26/91
Tracking Number:	Not reported	Score:	021 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05497		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CASTELLANO PROPERTY (Continued)

U001356301

UST:

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	6	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000560	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

77

GAS KWICK #256
4136 W CYPRESS ST
TAMPA, FL 33607

UST
LUST

U001354659
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GAS KWICK #256 (Continued)

U001354659

LUST:

Facility ID:	8625440	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132474731	Discovery Date:	07/25/88
Tracking Number:	294450	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06571		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GAS KWICK #256 (Continued)

U001354659

UST:

Facility ID:	298625440	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	RIDLEY SCOTT		
Owner:	HIGHWAY OIL INC		
	1200 BANK IV FLOOR 12		
	TOPEKA, KS 666033434		
Owner's Phone:	9133576161	Tracking #:	294450
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	69/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Op-tight fill		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GAS KWICK #256 (Continued)

U001354659

Facility ID:	298625440	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	RIDLEY SCOTT		
Owner:	HIGHWAY OIL INC		
	1200 BANK IV FLOOR 12		
	TOPEKA, KS 666033434		
Owner's Phone:	9133576161	Tracking #:	294450
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	69/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Op-tight fill		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GAS KWICK #256 (Continued)

U001354659

Facility ID:	298625440	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	RIDLEY SCOTT		
Owner:	HIGHWAY OIL INC		
	1200 BANK IV FLOOR 12		
	TOPEKA, KS 666033434		
Owner's Phone:	9133576161	Tracking #:	294450
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	69/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Op-tight fill		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		



MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GAS KWICK #256 (Continued)

U001354659

Facility ID:	298625440	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	RIDLEY SCOTT		
Owner:	HIGHWAY OIL INC		
	1200 BANK IV FLOOR 12		
	TOPEKA, KS 666033434		
Owner's Phone:	9133576161	Tracking #:	294450
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	93/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Dbl walled=primary matl, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

78

AMOCO STATION
2324 W CYPRESS ST
TAMPA, FL 33609

UST
LUST

U001354573
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO STATION (Continued)

U001354573

LUST:

Facility ID:	8625352	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8134743880	Discovery Date:	09/14/88
Tracking Number:	293739	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

746

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO STATION (Continued)

U001354573

UST:

Facility ID:	298625352	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BROSNAN,ED		
Contact:	Not reported	Facility Phone:	8134743880
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ED BROSNAN		
Owner:	SMITH/MICHELLE		
	4144 PINELAKE LN #102		
	TAMPA, FL 33624		
Owner's Phone:	3054743880	Tracking #:	293739
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO STATION (Continued)

U001354573

Facility ID:	298625352	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BROSNAN,ED		
Contact:	Not reported	Facility Phone:	8134743880
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ED BROSNAN		
Owner:	SMITH/MICHELLE		
	4144 PINELAKE LN #102		
	TAMPA, FL 33624		
Owner's Phone:	3054743880	Tracking #:	293739
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO STATION (Continued)

U001354573

Facility ID:	298625352	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BROSNAN,ED		
Contact:	Not reported	Facility Phone:	8134743880
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ED BROSNAN		
Owner:	SMITH/MICHELLE		
	4144 PINELAKE LN #102		
	TAMPA, FL 33624		
Owner's Phone:	3054743880	Tracking #:	293739
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

79

WESTSHORE PLACE
4350 W CYPRESS ST
TAMPA, FL

UST

U001378076
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WESTSHORE PLACE (Continued)

U001378076

UST:

Facility ID:	299103064	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SIMON OZER		
Contact:	Not reported	Facility Phone:	8138761515
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911009	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHUCK VOGEL		
Owner:	ALSCOR INVESTOR JOINT VENTURE		
	9900 BREN RD E		
	MINNETONKA, MN 55343		
Owner's Phone:	6129364600	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Dbl walled=primary matl		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Not required		

80

ELLIS CONSTRUCTION CO INC
1714 W CYPRESS ST
TAMPA, FL 33606

UST
LUST

U001356132
N/A

460

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ELLIS CONSTRUCTION CO INC (Continued)

U001356132

LUST:

Facility ID:	9046106	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132518473	Discovery Date:	08/13/90
Tracking Number:	Not reported	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

80

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ELLIS CONSTRUCTION CO INC (Continued)

U001356132

UST:

Facility ID:	299046106	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ELLIS, GILBERT		
Contact:	Not reported	Facility Phone:	8132518473
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GILBERT ELLIS		
Owner:	ELLIS, GILBERT		
	PO BOX 1132		
	TAMPA, FL 336011132		
Owner's Phone:	8132518473	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

81

GRAYBAR ELECTRIC CO INC
1502 W CYPRESS ST
TAMPA, FL 33606

UST

U001355507
N/A

61

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GRAYBAR ELECTRIC CO INC (Continued)

U001355507

UST:

Facility ID:	298733895	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRAYBAR ELECTRIC CO INC		
Contact:	Not reported	Facility Phone:	8132538881
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	C E JENKINS		
Owner:	GRAYBAR ELECTRIC CO INC		
	801 N ROME AVE		
	TAMPA, FL 336061037		
Owner's Phone:	8132538881	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

82

ALSCOR INVESTOR JOINT VENTURE
4200 W CYPRESS ST
TAMPA, FL 33607

UST

U001356367
N/A

82

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALSCOR INVESTOR JOINT VENTURE (Continued)

U001356367

UST:

Facility ID:	299103063	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SIMON OZER		
Contact:	Not reported	Facility Phone:	8138761515
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911008	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHUCK VOGEL		
Owner:	ALSCOR INVESTOR JOINT VENTURE		
	9900 BREN RD E		
	MINNETONKA, MN 55343		
Owner's Phone:	6129364600	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	88/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Dbl walled=primary matl		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Not required		

82

PRICE, T ROWE
4200 W CYPRESS ST
TAMPA, FL

UST

U002038443
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PRICE, T ROWE (Continued)

U002038443

UST:

Facility ID:	299401825	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	4105472253
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940930	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	CHUCK VOGEL		
Owner:	ALSCOR INVESTOR JOINT VENTURE		
	9900 BREN RD E		
	MINNETONKA, MN 55343		
Owner's Phone:	6129364600	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

83

ALSCOR INVESTOR JOINT VENTURE
4300 W CYPRESS ST
TAMPA, FL

UST

U001378077
N/A

463

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALSCOR INVESTOR JOINT VENTURE (Continued)

U001378077

UST:

Facility ID:	299103065	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MCQUIRE, PAT		
Contact:	Not reported	Facility Phone:	8138733675
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911009	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHUCK VOGEL		
Owner:	ALSCOR INVESTOR JOINT VENTURE		
	9900 BREN RD E		
	MINNETONKA, MN 55343		
Owner's Phone:	6129364600	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	86/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Dbl walled=primary matl		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Not required		

84

PIONEER AUTO SERVICE CENTER INC
1004 N TAMPA ST
TAMPA, FL 33602

UST

U001354493
N/A

464

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PIONEER AUTO SERVICE CENTER INC (Continued)

U001354493

UST:

Facility ID:	298625262	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BARR JOHN		
Contact:	Not reported	Facility Phone:	8132297772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RON MOORE		
Owner:	PIONEER TIRE		
	106 E TYLER		
	TAMPA, FL 33602		
Owner's Phone:	8132291951	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	71/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PIONEER AUTO SERVICE CENTER INC (Continued)

U001354493

Facility ID:	298625262	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BARR JOHN		
Contact:	Not reported	Facility Phone:	8132297772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	RON MOORE		
Owner:	PIONEER TIRE		
	106 E TYLER		
	TAMPA, FL 33602		
Owner's Phone:	8132291951	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	71/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

84

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PIONEER AUTO SERVICE CENTER INC (Continued)

U001354493

Facility ID:	298625262	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BARR JOHN		
Contact:	Not reported	Facility Phone:	8132297772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	RON MOORE		
Owner:	PIONEER TIRE		
	106 E TYLER		
	TAMPA, FL 33602		
Owner's Phone:	8132291951	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	71/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PIONEER AUTO SERVICE CENTER INC (Continued)

U001354493

Facility ID:	298625262	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BARR JOHN		
Contact:	Not reported	Facility Phone:	8132297772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	RON MOORE		
Owner:	PIONEER TIRE		
	106 E TYLER		
	TAMPA, FL 33602		
Owner's Phone:	8132291951	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink, Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000400	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

601

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PIONEER AUTO SERVICE CENTER INC (Continued)

U001354493

Facility ID:	298625262	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BARR JOHN		
Contact:	Not reported	Facility Phone:	8132297772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	B	District:	Southwest
Owner's Contact:	RON MOORE		
Owner:	PIONEER TIRE		
	106 E TYLER		
	TAMPA, FL 33602		
Owner's Phone:	8132291951	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	71/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

84

PIONEER AUTO SERVICE CENTER
1004 N TAMPA ST
TAMPA, FL 33602

RCRIS-SQG 1000500578
FINDS FLD984206730

RCRIS:

Owner: JOHN BARR, OWNER
(813) 229-7772

Contact: JOHN BARR
(813) 229-7772

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D002	.00000 (T)	Notification	D018	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

85

ATTMORE MENCH INC
2310 STATE ST
TAMPA, FL 33677

RCRIS-SQG 1000698737
FLD032762098

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	ATTMORE MENCH INC (Continued)		1000698737
	There are 2 compliance/violation record(s) reported at this site:		
	Evaluation	Date	Violations
	OTHER EVALUATION	09-APR-87	YES
	OTHER EVALUATION	09-APR-87	YES
85	ATTMORE-MENCH INC 2310 STATE ST TAMPA, FL 33609	FINDS	1000733176 FLD032762098
86	RADIANT DISCOUNT TIRES 911 N DALE MABRY TAMPA, FL 33675	FINDS	1000734415 FLD981748239
86	EXXON #4-9113 911 N DALE MABRY HWY TAMPA, FL 33609	UST LUST	U001354057 N/A

56

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4-9113 (Continued)

U001354057

LUST:

Facility ID:	8624794	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8138798079	Discovery Date:	09/09/88
Tracking Number:	293730	Score:	035
Facility Code:	Not reported	Status:	Not reported
Rank:	03361		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4-9113 (Continued)

U001354057

UST:

Facility ID:	298624794	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8138798079
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293730
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4-9113 (Continued)

U001354057

Facility ID:	298624794	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8138798079
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293730
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4-9113 (Continued)

U001354057

Facility ID:	298624794	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8138798079
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293730
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

5/6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4-9113 (Continued)

U001354057

Facility ID:	298624794	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8138798079
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293730
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4-9113 (Continued)

U001354057

Facility ID:	298624794	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8138798079
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293730
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

5/6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4-9113 (Continued)

U001354057

Facility ID:	298624794	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8138798079
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293730
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4-9113 (Continued)

U001354057

Facility ID:	298624794	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8138798079
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293730
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

506

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4-9113 (Continued)

U001354057

Facility ID:	298624794	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8138798079
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293730
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4-9113 (Continued)

U001354057

Facility ID:	298624794	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8138798079
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293730
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	91/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Dbl walled=primary matl, Spill		
	cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser		
	liners		
Petro. Monitoring:	DW tank space, Piping/flow restrictor, DW piping space, Man tank		
	gauging		

87

SHUTTERS UNLIMITED FLORIDA
902 N ROME AVENUE
TAMPA, FL 33606

RCRIS-SQG
FINDS

1000421767
FLD041495284

88

CHEVRON #48084
701 N WESTSHORE BLVD
TAMPA, FL 33609

UST
LUST

U001354883
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48084 (Continued)

U001354883

LUST:

Facility ID:	8625677	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8138753211	Discovery Date:	05/25/88
Tracking Number:	295244	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07038		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48084 (Continued)

U001354883

UST:

Facility ID:	298625677	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MUHAMMED HAI A		
Contact:	Not reported	Facility Phone:	8138753211
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	295244
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	84/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

06

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48084 (Continued)

U001354883

Facility ID:	298625677	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MUHAMMED HAI A		
Contact:	Not reported	Facility Phone:	8138753211
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	295244
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	84/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

50

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CHEVRON #48084 (Continued)

U001354883

Facility ID:	298625677	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MUHAMMED HAI A		
Contact:	Not reported	Facility Phone:	8138753211
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	295244
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	84/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48084 (Continued)

U001354883

Facility ID:	298625677	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MUHAMMED HAI A		
Contact:	Not reported	Facility Phone:	8138753211
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	295244
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	84/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

88

HOLIDAY INN CROWNE PLAZA
700 N WESTSHORE BLVD
TAMPA, FL

UST
LUST

U002038448
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HOLIDAY INN CROWNE PLAZA (Continued)

U002038448

LUST:

Facility ID:	9401942	Facility Type:	TANKLESS FACILITY
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	08/29/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

086

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HOLIDAY INN CROWNE PLAZA (Continued)

U002038448

UST:

Facility ID:	299401942	Facility Type:	Tankless facility
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	941101	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	DARREN L STOWE		
Owner:	ROSSMORE TAMPA LP 700 N WESTSHORE BLVD TAMPA, FL 33609		
Owner's Phone:	3107726110	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

89

TAMPA,CITY-PERFORMING ARTS CENTER
1010 N W C MACINNES PL
TAMPA, FL 33602

UST
AST

U001355940
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-PERFORMING ARTS CENTER (Continued)

U001355940

UST:

Facility ID:	298942611	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOFTEN, STEVE		
Contact:	Not reported	Facility Phone:	8132221000
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE MCCAY		
Owner:	TAMPA,CITY-REAL ESTATE 201 E KENNEDY BLVD STE 415 TAMPA, FL 336025823		
Owner's Phone:	8132238624	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	86/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

AST:

Facility ID:	298942611	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOFTEN, STEVE		
Facility Phone:	8132221000	Permit Section:	Not reported
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE MCCAY		
Owner:	TAMPA,CITY-REAL ESTATE 201 E KENNEDY BLVD STE 415 TAMPA, FL 336025823		
Owner's Phone:	8132238624	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000320
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-PERFORMING ARTS CENTER (Continued)

U001355940

Facility ID:	298942611	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOFTEN, STEVE		
Facility Phone:	8132221000	Permit Section:	Not reported
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE MCCAY		
Owner:	TAMPA,CITY-REAL ESTATE 201 E KENNEDY BLVD STE 415 TAMPA, FL 336025823		
Owner's Phone:	8132238624	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000050
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

90

SIR SPEEDY PRINTING #5041
202 E CASS STREET
TAMPA, FL 33602

RCRIS-SQG
FINDS

1000132111
FLD982079873

RCRIS:

Owner: ROBERT DOLAN
(813) 273-0027

Contact:ROBERT DOLAN
(813) 273-0027

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

91

FL CLARKLIFT, INC.
811 N HUBERT AVE
TAMPA, FL 33609

UST

U001354560
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FL CLARKLIFT, INC. (Continued)

U001354560

UST:

Facility ID:	298625338	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL CLARKLIFT, INC.		
Contact:	Not reported	Facility Phone:	8138778341
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	70/02
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FL CLARKLIFT, INC. (Continued)

U001354560

Facility ID:	298625338	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL CLARKLIFT, INC.		
Contact:	Not reported	Facility Phone:	8138778341
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	46/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

92

US COURTHOUSE
801 N FLORIDA AVE
TAMPA, FL 33602

UST

U002217718
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

US COURTHOUSE (Continued)

U002217718

UST:

Facility ID:	299501854	Facility Type:	Tankless facility
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950510	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	KLOU MANCUSO		
Owner:	GENERAL SERVICES ADMINISTRATION		
	401 W PEACHTREE ST		
	ATLANTA, GA 303652550		
Owner's Phone:	4043313125	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

93

RENT ALL OF TAMPA, INC.
722 N DALE MABRY HWY
TAMPA, FL 33609

UST
LUST

U001355084
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RENT ALL OF TAMPA, INC. (Continued)

U001355084

LUST:

Facility ID:	8627011	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138779461	Discovery Date:	03/04/92
Tracking Number:	Not reported	Score:	031
Facility Code:	Not reported	Status:	Not reported
Rank:	03984		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

9/3

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RENT ALL OF TAMPA, INC. (Continued)

U001355084

UST:

Facility ID:	298627011	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RENT ALL OF TAMPA, INC.		
Contact:	Not reported	Facility Phone:	8138779461
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOAN CROWDER		
Owner:	RENT ALL OF TAMPA INC 722 N DALE MABRY HWY TAMPA, FL 336091247		
Owner's Phone:	8138779461	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Concrete		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

0/3

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

RENT ALL OF TAMPA, INC. (Continued)

U001355084

Facility ID:	298627011	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RENT ALL OF TAMPA, INC.		
Contact:	Not reported	Facility Phone:	8138779461
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOAN CROWDER		
Owner:	RENT ALL OF TAMPA INC 722 N DALE MABRY HWY TAMPA, FL 336091247		
Owner's Phone:	8138779461	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Concrete		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

913

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RENT ALL OF TAMPA, INC. (Continued)

U001355084

Facility ID:	298627011	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RENT ALL OF TAMPA, INC.		
Contact:	Not reported	Facility Phone:	8138779461
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOAN CROWDER		
Owner:	RENT ALL OF TAMPA INC 722 N DALE MABRY HWY TAMPA, FL 336091247		
Owner's Phone:	8138779461	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

03

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RENT ALL OF TAMPA, INC. (Continued)

U001355084

Facility ID:	298627011	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RENT ALL OF TAMPA, INC.		
Contact:	Not reported	Facility Phone:	8138779461
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOAN CROWDER		
Owner:	RENT ALL OF TAMPA INC 722 N DALE MABRY HWY TAMPA, FL 336091247		
Owner's Phone:	8138779461	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

94

MAHONEY, MIKE
1719 W LEMON ST
TAMPA, FL 33606

UST

U001355267
N/A

94

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MAHONEY, MIKE (Continued)

U001355267

UST:

Facility ID:	298627773	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MAHONEY, MIKE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MICHAEL MAHONEY		
Owner:	MAHONEY, MICHAEL		
	3241 BAYSHORE BLVD NE		
	ST PETERSBURG, FL 33703		
Owner's Phone:	8132533424	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	79/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MAHONEY, MIKE (Continued)

U001355267

Facility ID:	298627773	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MAHONEY, MIKE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MICHAEL MAHONEY		
Owner:	MAHONEY, MICHAEL 3241 BAYSHORE BLVD NE ST PETERSBURG, FL 33703		
Owner's Phone:	8132533424	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000600	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	79/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

95

DOLLAR RENT-A-CAR OLD SERVICE AREA
5012 W LEMON ST
TAMPA, FL 33609

UST
LUST

U001354832
N/A

95

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DOLLAR RENT-A-CAR OLD SERVICE AREA (Continued)

U001354832

LUST:

Facility ID:	8625625	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	DOLLAR RENT-A-CAR		
Alias Name 2:	DOLLAR RENT-A-CAR USE #298624920		
Telephone:	8133963640	Discovery Date:	04/13/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	00000112
------------	--------------	--------------------	----------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

95

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DOLLAR RENT-A-CAR OLD SERVICE AREA (Continued)

U001354832

UST:

Facility ID:	298625625	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DOLLAR RENT A CAR		
Contact:	Not reported	Facility Phone:	8133963640
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID GIBBS		
Owner:	HILLSBOROUGH CNTY AVIATION AUTH		
	PO BOX 22287		
	TAMPA, FL 336222287		
Owner's Phone:	8138708700	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00020000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

96

AUTOMATIC DATA PROCESSING
4900 W LEMON ST
TAMPA, FL 33609

UST
LUST

U001355758
N/A

96

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AUTOMATIC DATA PROCESSING (Continued)

U001355758

LUST:

Facility ID:	8838703	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132876600	Discovery Date:	06/22/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

96

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AUTOMATIC DATA PROCESSING (Continued)

U001355758

UST:

Facility ID:	298838703	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WAYNE PIERCE		
Contact:	Not reported	Facility Phone:	8132876600
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880208	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LEROY SMITH		
Owner:	AUTOMATIC DATA PROCESSING TAMPA PO BOX 30500 TAMPA, FL 336300500		
Owner's Phone:	8132876600	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/02
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

9/6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AUTOMATIC DATA PROCESSING (Continued)

U001355758

Facility ID:	298838703	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WAYNE PIERCE		
Contact:	Not reported	Facility Phone:	8132876600
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880208	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	LEROY SMITH		
Owner:	AUTOMATIC DATA PROCESSING TAMPA PO BOX 30500 TAMPA, FL 336300500		
Owner's Phone:	8132876600	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	85/02
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

97

FRIENDLY AMC
700 N DALE MABRY
TAMPA, FL 33609

RCRIS-SQG 1000207532
UST FLD981918576

97

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FRIENDLY AMC (Continued)

1000207532

UST:

Facility ID:	298945514	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FERMAN J L JR		
Contact:	Not reported	Facility Phone:	8132530681
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891219	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	STEVE UITERWYK		
Owner:	SCHULSTADD MOTORS 700 N DALE MABRY HWY TAMPA, FL 336091247		
Owner's Phone:	8132530681	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	84/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

97

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FRIENDLY AMC (Continued)

1000207532

Facility ID:	298945514	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FERMAN J L JR		
Contact:	Not reported	Facility Phone:	8132530681
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891219	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	STEVE UITERWYK		
Owner:	SCHULSTADD MOTORS		
	700 N DALE MABRY HWY		
	TAMPA, FL 336091247		
Owner's Phone:	8132530681	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

97

SCHULSTAD MOTOR CO
700 N DALE MABRY HWY
TAMPA, FL 33609

UST
LUST

U001355071
N/A

97

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SCHULSTAD MOTOR CO (Continued)

U001355071

LUST:

Facility ID:	8626984	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132725960	Discovery Date:	09/08/89
Tracking Number:	Not reported	Score:	060
Facility Code:	Not reported	Status:	Not reported
Rank:	01316		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

97

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SCHULSTAD MOTOR CO (Continued)

U001355071

UST:

Facility ID:	298626984	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCHULSTAD MOTOR CO		
Contact:	Not reported	Facility Phone:	8132725960
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	FRANK GONZALEZ		
Owner:	SCHULSTAD MOTOR CO. 700 N DALE MABRY TAMPA, FL 33609		
Owner's Phone:	8132381183	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	85/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		



MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SCHULSTAD MOTOR CO (Continued)

U001355071

Facility ID:	298626984	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCHULSTAD MOTOR CO		
Contact:	Not reported	Facility Phone:	8132725960
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	FRANK GONZALEZ		
Owner:	SCHULSTAD MOTOR CO. 700 N DALE MABRY TAMPA, FL 33609		
Owner's Phone:	8132381183	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Not required		

97

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SCHULSTAD MOTOR CO (Continued)

U001355071

Facility ID:	298626984	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCHULSTAD MOTOR CO		
Contact:	Not reported	Facility Phone:	8132725960
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	FRANK GONZALEZ		
Owner:	SCHULSTAD MOTOR CO. 700 N DALE MABRY TAMPA, FL 33609		
Owner's Phone:	8132381183	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000300	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SCHULSTAD MOTOR CO (Continued)

U001355071

Facility ID:	298626984	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCHULSTAD MOTOR CO		
Contact:	Not reported	Facility Phone:	8132725960
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	FRANK GONZALEZ		
Owner:	SCHULSTAD MOTOR CO. 700 N DALE MABRY TAMPA, FL 33609		
Owner's Phone:	8132381183	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000300	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

97	FRIENDLY AMC JEEP RENAULT 700 N DALE MABRY HIGHWAY TAMPA, FL 33609	RCRIS-SQG FINDS	1000207534 FLD982169823
98	FREE PRESS PUBLISHING COMPANY 1010 WEST CASS STREET TAMPA, FL 33606	FINDS	1000735254 FLD982115735
98	FREE PRESS PUBLISHING CO INC 1010 WEST CASS STREET TAMPA, FL 33601	RCRIS-SQG	1000700497 FLD982115735
99	D&V GARAGE 1301 W CASS ST TAMPA, FL 33606	UST LUST	U001355351 N/A

99

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

D&V GARAGE (Continued)

U001355351

LUST:

Facility ID:	8629068	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	12/04/91
Tracking Number:	Not reported	Score:	023 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05472		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

99

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

D&V GARAGE (Continued)

U001355351

UST:

Facility ID:	298629068	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	D&V GARAGE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID MORENO		
Owner:	D & V GARAGE		
	3037 W KENNEDY BLVD		
	TAMPA, FL 336093136		
Owner's Phone:	8132518177	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

94

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

D&V GARAGE (Continued)

U001355351

Facility ID:	298629068	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	D&V GARAGE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVID MORENO		
Owner:	D & V GARAGE 3037 W KENNEDY BLVD TAMPA, FL 336093136		
Owner's Phone:	8132518177	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

99

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

D&V GARAGE (Continued)

U001355351

Facility ID:	298629068	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	D&V GARAGE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DAVID MORENO		
Owner:	D & V GARAGE		
	3037 W KENNEDY BLVD		
	TAMPA, FL 336093136		
Owner's Phone:	8132518177	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

49

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

D&V GARAGE (Continued)

U001355351

Facility ID:	298629068	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	D&V GARAGE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DAVID MORENO		
Owner:	D & V GARAGE		
	3037 W KENNEDY BLVD		
	TAMPA, FL 336093136		
Owner's Phone:	8132518177	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	85/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

100

MATACS HAZARDOUS WASTE RECYCLING CO
1333 W CASS ST
TAMPA, FL 33606

RCRIS-SQG 1000985928
FINDS FL0001000652

RCRIS:

Owner: JULIAN BELLEAU SR, PROCUREMT SPEC
(813) 932-4407

Contact: Not reported

Waste	Quantity	Info Source
-------	----------	-------------

NONE	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

101

UNITED CAB CO OF TAMPA-OFFICE COMPLEX
1701 W CASS ST
TAMPA, FL 33606

UST U001354809
LUST N/A

101

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED CAB CO OF TAMPA-OFFICE COMPLEX (Continued)

U001354809

LUST:

Facility ID:	8625600	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132532424	Discovery Date:	09/19/90
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	DISTRICT OFFICE
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	Q1

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE

101

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED CAB CO OF TAMPA-OFFICE COMPLEX (Continued)

U001354809

UST:

Facility ID:	298625600	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN CASTELLANO		
Contact:	Not reported	Facility Phone:	8132532424
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN CASTELLANO		
Owner:	UNITED CAB CO. 1701 W CASS ST TAMPA, FL 336061229		
Owner's Phone:	8132532424	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	73/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

101

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED CAB CO OF TAMPA-OFFICE COMPLEX (Continued)

U001354809

Facility ID:	298625600	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN CASTELLANO		
Contact:	Not reported	Facility Phone:	8132532424
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN CASTELLANO		
Owner:	UNITED CAB CO. 1701 W CASS ST TAMPA, FL 336061229		
Owner's Phone:	8132532424	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	7/3/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

101

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED CAB CO OF TAMPA-OFFICE COMPLEX (Continued)

U001354809

Facility ID:	298625600	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN CASTELLANO		
Contact:	Not reported	Facility Phone:	8132532424
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN CASTELLANO		
Owner:	UNITED CAB CO. 1701 W CASS ST TAMPA, FL 336061229		
Owner's Phone:	8132532424	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000700	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	73/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

101

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED CAB CO OF TAMPA-OFFICE COMPLEX (Continued)

U001354809

Facility ID:	298625600	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN CASTELLANO		
Contact:	Not reported	Facility Phone:	8132532424
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN CASTELLANO		
Owner:	UNITED CAB CO. 1701 W CASS ST TAMPA, FL 336061229		
Owner's Phone:	8132532424	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

101

STEVES RADIATORS
1702 W CASS ST
TAMPA, FL 33606

UST
LUST

U001546651
N/A

101

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STEVES RADIATORS (Continued)

U001546651

LUST:

Facility ID:	9102162	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132532060	Discovery Date:	01/08/91
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	OTHER

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

101

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STEVES RADIATORS (Continued)

U001546651

UST:

Facility ID:	299102162	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STEVES RADIATORS		
Contact:	Not reported	Facility Phone:	8132532060
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910529	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT BODE		
Owner:	BODE, SECUNDINO & ROBERT		
	3308 GRAY ST		
	TAMPA, FL 33609		
Owner's Phone:	8138767544	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STEVES RADIATORS (Continued)

U001546651

Facility ID:	299102162	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STEVES RADIATORS		
Contact:	Not reported	Facility Phone:	8132532060
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910529	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	ROBERT BODE		
Owner:	BODE, SECUNDINO & ROBERT		
	3308 GRAY ST		
	TAMPA, FL 33609		
Owner's Phone:	8138767544	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

101

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STEVES RADIATORS (Continued)

U001546651

Facility ID:	299102162	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STEVES RADIATORS		
Contact:	Not reported	Facility Phone:	8132532060
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910529	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	ROBERT BODE		
Owner:	BODE, SECUNDINO & ROBERT		
	3308 GRAY ST		
	TAMPA, FL 33609		
Owner's Phone:	8138767544	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

101

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STEVES RADIATORS (Continued)

U001546651

Facility ID:	299102162	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STEVES RADIATORS		
Contact:	Not reported	Facility Phone:	8132532060
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910529	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	ROBERT BODE		
Owner:	BODE, SECUNDINO & ROBERT		
	3308 GRAY ST		
	TAMPA, FL 33609		
Owner's Phone:	8138767544	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

101

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STEVES RADIATORS (Continued)

U001546651

Facility ID:	299102162	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STEVES RADIATORS		
Contact:	Not reported	Facility Phone:	8132532060
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910529	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	ROBERT BODE		
Owner:	BODE, SECUNDINO & ROBERT		
	3308 GRAY ST		
	TAMPA, FL 33609		
Owner's Phone:	8138767544	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

101	A RONNIE BOSWELL COLISION 1702 W CASS ST TAMPA, FL 33606	FINDS	1000999520 FL0001209857
-----	--	-------	----------------------------

101	A RONNIE BOSWELL COLISION 1702 W CASS ST TAMPA, FL 33606	RCRIS-SQG	1000985791 FLR000002923
-----	--	-----------	----------------------------

RCRIS:

Owner: ALEXIS RIVERA, MGR
(813) 254-4171

Contact: Not reported

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D035	.00000 (T)	Notification
D039	.00000 (T)	Notification	F003	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

102	ART ROMANY TILE DIST, INC. 3707 W CARMEN ST TAMPA, FL 33609	UST	U001355253 N/A
-----	---	-----	-------------------

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ART ROMANY TILE DIST,INC. (Continued)

U001355253

UST:

Facility ID:	298627707	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LEROY J. FREEDOM		
Contact:	Not reported	Facility Phone:	8138779554
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GENE TESTON		
Owner:	ART ROMANY TILE DIST INC		
	3707 W CARMEN ST		
	TAMPA, FL 336091303		
Owner's Phone:	8138779554	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	71/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

103

INDEPENDENT ICE CO INC
602 N ALBANY
TAMPA, FL 33606

UST
LUST

U001356377
N/A

1023

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

INDEPENDENT ICE CO INC (Continued)

U001356377

LUST:

Facility ID:	9103664	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138687617	Discovery Date:	12/20/91
Tracking Number:	Not reported	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

103

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

INDEPENDENT ICE CO INC (Continued)

U001356377

UST:

Facility ID:	299103664	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RAYNOR, MARIE		
Contact:	Not reported	Facility Phone:	8138687617
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911226	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	MARIE RAYNOR		
Owner:	RAYNOR, MARIE		
	10745 FALLEN LEAF LN		
	PORT RICHEY, FL 34662		
Owner's Phone:	8138687617	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

103

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

INDEPENDENT ICE CO INC (Continued)

U001356377

Facility ID:	299103664	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RAYNOR, MARIE		
Contact:	Not reported	Facility Phone:	8138687617
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911226	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	MARIE RAYNOR		
Owner:	RAYNOR, MARIE		
	10745 FALLEN LEAF LN		
	PORT RICHEY, FL 34662		
Owner's Phone:	8138687617	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

104

GAYLORD MILLER ELECTRIC CORP
602 N OREGON AVE
TAMPA, FL 33606

RCRIS-SQG **1000985555**
FLR000000547

RCRIS:

Owner: DONALD MILLER, PRES
(813) 254-4681

Contact: Not reported

Waste	Quantity	Info Source
NONE	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

105

PAUL SMITH CONTRACTING CO INC
1202 W CARMEN ST
TAMPA, FL 33606

UST **U001354520**
LUST **N/A**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PAUL SMITH CONTRACTING CO INC (Continued)

U001354520

LUST:

Facility ID:	8625292	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132535321	Discovery Date:	04/30/90
Tracking Number:	Not reported	Score:	022 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05478		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

105

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PAUL SMITH CONTRACTING CO INC (Continued)

U001354520

UST:

Facility ID:	298625292	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VERNON FLANAGAN		
Contact:	Not reported	Facility Phone:	8132535321
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PAUL H. SMITH, JR.		
Owner:	PAUL SMITH CONTRACTING CO INC		
	1202 W CARMEN ST		
	TAMPA, FL 336061303		
Owner's Phone:	8132535321	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

105

GRIFFIN SERVICE CORP
606 N GILCHRIST AVE
TAMPA, FL 33606

UST

U001354944
N/A

105

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRIFFIN SERVICE CORP (Continued)

U001354944

UST:

Facility ID:	298625741	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LINGERFELT, BRYAN		
Contact:	Not reported	Facility Phone:	8132816946
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	THEODORE E. WADE		
Owner:	GRIFFIN SERVICE CORP		
	606 N GILCHRIST AVE		
	TAMPA, FL 336061320		
Owner's Phone:	8132516942	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	82/04
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

106

ANNELLO TILE & TERRAZZO, INC.
1116 W CARMEN ST
TAMPA, FL 33606

UST

U001355252
N/A

106

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ANSELLO TILE & TERRAZZO, INC. (Continued)

U001355252

UST:

Facility ID:	298627702	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VITO J. ANELLO		
Contact:	Not reported	Facility Phone:	8132533458
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	VITO J. ANELLO		
Owner:	ANELLO TILE & TERRAZZO INC		
	1116 W CARMEN ST		
	TAMPA, FL 336061302		
Owner's Phone:	8132533458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	74/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

107

CARDINALS BODY SHOP 606 N NEWPORT TAMPA, FL 33606

RCRIS-SQG 1000189328
FINDS FLD982153652

RCRIS:

Owner: CHARLES CAMPER
(813) 253-5961

Contact: CHARLES CAMPER
(813) 253-5961

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

108

NATIONAL GUARD ARMORY-FT HESTERLY 514 N HOWARD AVE TAMPA, FL 33606

UST U001354507
LUST N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL GUARD ARMORY-FT HESTERLY (Continued)

U001354507

LUST:

Facility ID:	8625278	Facility Type:	FEDERAL GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132511329	Discovery Date:	02/27/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

1086

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL GUARD ARMORY-FT HESTERLY (Continued)

U001354507

UST:

Facility ID:	298625278	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	POST COMMANDER		
Contact:	Not reported	Facility Phone:	8132511329
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LTC RICHARD T POWERS		
Owner:	FL DEPT OF MILITARY AFFAIRS		
	PO BOX 1008		
	ST AUGUSTINE, FL 320851008		
Owner's Phone:	9048248461	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

108

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL GUARD ARMORY-FT HESTERLY (Continued)

U001354507

Facility ID:	298625278	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	POST COMMANDER		
Contact:	Not reported	Facility Phone:	8132511329
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	LTC RICHARD T POWERS		
Owner:	FL DEPT OF MILITARY AFFAIRS PO BOX 1008 ST AUGUSTINE, FL 320851008		
Owner's Phone:	9048248461	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	91/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Dbl walled=primary matl, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	DW tank space, DW piping space		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL GUARD ARMORY-FT HESTERLY (Continued)

U001354507

Facility ID:	298625278	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	POST COMMANDER		
Contact:	Not reported	Facility Phone:	8132511329
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	LTC RICHARD T POWERS		
Owner:	FL DEPT OF MILITARY AFFAIRS PO BOX 1008 ST AUGUSTINE, FL 320851008		
Owner's Phone:	9048248461	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	91/12
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Dbl walled=primary matl, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	DW tank space, DW piping space		

1086

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL GUARD ARMORY-FT HESTERLY (Continued)

U001354507

Facility ID:	298625278	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	POST COMMANDER		
Contact:	Not reported	Facility Phone:	8132511329
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	LTC RICHARD T POWERS		
Owner:	FL DEPT OF MILITARY AFFAIRS PO BOX 1008 ST AUGUSTINE, FL 320851008		
Owner's Phone:	9048248461	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, DW tank space		

1086

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL GUARD ARMORY-FT HESTERLY (Continued)

U001354507

Facility ID:	298625278	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	POST COMMANDER		
Contact:	Not reported	Facility Phone:	8132511329
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	LTC RICHARD T POWERS		
Owner:	FL DEPT OF MILITARY AFFAIRS PO BOX 1008 ST AUGUSTINE, FL 320851008		
Owner's Phone:	9048248461	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Gasohol	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, DW tank space		

1086

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL GUARD ARMORY-FT HESTERLY (Continued)

U001354507

Facility ID:	298625278	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	POST COMMANDER		
Contact:	Not reported	Facility Phone:	8132511329
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	LTC RICHARD T POWERS		
Owner:	FL DEPT OF MILITARY AFFAIRS PO BOX 1008 ST AUGUSTINE, FL 320851008		
Owner's Phone:	9048248461	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000300	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

108

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL GUARD ARMORY-FT HESTERLY (Continued)

U001354507

Facility ID:	298625278	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	POST COMMANDER		
Contact:	Not reported	Facility Phone:	8132511329
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	LTC RICHARD T POWERS		
Owner:	FL DEPT OF MILITARY AFFAIRS PO BOX 1008 ST AUGUSTINE, FL 320851008		
Owner's Phone:	9048248461	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	91/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Dbl walled=primary matl, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	DW tank space, DW piping space		

108	OMS 2 518 N HOWARD AVE TAMPA, FL 33606	FINDS	1000734814 FLD982076895
108	R T SADD SILVERSMITH 525 N HOWARD AVENUE TAMPA, FL 33606	RCRIS-SQG FINDS	1000140745 FLD119250835
109	MARK MOORE COMMERCIAL STUDIOS 3803 GRAY ST TAMPA, FL 33609	RCRIS-SQG FINDS	1000266846 FLD982122574

109

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARK MOORE COMMERCIAL STUDIOS (Continued)

1000266846

RCRIS:

Owner: MARK MOORE, OWNER
(813) 874-0410

Contact: MARK MOORE
(813) 874-0410

Waste	Quantity	Info Source
D011	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

109

ALL TUNE & LUBE 415 N DALE MABRY HWY TAMPA, FL 33609

UST

U001355481
N/A

UST:

Facility ID:	298733858	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MANAGER		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	SPEEDY MUFFLER KING 415 N DALE MABRY TAMPA, FL 33609		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	85/12
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

110

YELLOW CAB CO OF TAMPA INC 502 NORTH OREGON AVENUE TAMPA, FL 33601

RCRIS-SQG

1000700968
FLD982170482

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

YELLOW CAB CO OF TAMPA INC (Continued)

1000700968

RCRIS:

Owner: TRIGG, J C SHOP FOREMAN
(813) 251-3691

Contact: TRIGG J C
(813) 251-3691

Waste	Quantity	Info Source
-------	----------	-------------

D001	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

110

YELLOW CAB COMPANY OF TAMPA, I
502 NORTH OREGON AVENUE
TAMPA, FL 33606

FINDS
UST
LUST

1000735805
FLD982170482

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

YELLOW CAB COMPANY OF TAMPA, I (Continued)

1000735805

LUST:

Facility ID:	8625621	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132538871	Discovery Date:	03/20/91
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

YELLOW CAB COMPANY OF TAMPA, I (Continued)

1000735805

UST:

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

YELLOW CAB COMPANY OF TAMPA, I (Continued)

1000735805

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

YELLOW CAB COMPANY OF TAMPA, I (Continued)

1000735805

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

116

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

YELLOW CAB COMPANY OF TAMPA, I (Continued)

1000735805

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

110

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

YELLOW CAB COMPANY OF TAMPA, I (Continued)

1000735805

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

110

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

YELLOW CAB COMPANY OF TAMPA, I (Continued)

1000735805

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

111

HI GRADE FOOD SPECIALTIES OF FL
1705 GRAY ST
TAMPA, FL

UST
LUST

U001963223
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HI GRADE FOOD SPECIALTIES OF FL (Continued)

U001963223

LUST:

Facility ID:	9401696	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136211222	Discovery Date:	04/08/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	30 RA STATUS REPORT

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HI GRADE FOOD SPECIALTIES OF FL (Continued)

U001963223

UST:

Facility ID:	299401696	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	8136211222
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940902	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	ROBERT CUTTING		
Owner:	DISTRIBUTION PLUS INC		
	9860 CURRIE DAVIS DR		
	TAMPA, FL 33619		
Owner's Phone:	8136211222	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	1
Tank position:	Not reported	Any contam. groundwater:	No
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

112

PHOTO ENGRAVING INC
502 N WILLOW AVE
TAMPA, FL 33606

RCRIS-SQG 1000859175
FINDS FL0000123125

RCRIS:

Owner: JOHN ALESSANDRINI, PROCESS ENG
(813) 253-3427

Contact: JOHN ALESSANDRINI
(813) 253-3427

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D007	.00000 (T)	Notification	F005	.00000 (T)	Notification
F006	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

112

PHOTOENGRAVING, INC.
502 N WILLOW AVE
TAMPA, FL 33606

UST

U001355463
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PHOTOENGRAVING, INC. (Continued)

U001355463

UST:

Facility ID:	298733831	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PHOTENGRAVING, INC.		
Contact:	Not reported	Facility Phone:	8132533427
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870729	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ED DALTON, JR.		
Owner:	PHOTENGRAVING INC		
	502 N WILLOW AVE		
	TAMPA, FL 336061338		
Owner's Phone:	8132533427	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Kerosene	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

112

NATIONAL LINEN SERVICE
507 N WILLOW AVE
TAMPA, FL 33606

UST
LUST

U001354545
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL LINEN SERVICE (Continued)

U001354545

LUST:

Facility ID:	8625323	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132530431	Discovery Date:	01/06/93
Tracking Number:	297414	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	CONTAMINATION ASSESSMENT REPORT
Extension Status:	APPROVED
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL LINEN SERVICE (Continued)

U001354545

UST:

Facility ID:	298625323	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	RAY HINSON		
Contact:	Not reported	Facility Phone:	8132530431
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PAT SNIDER		
Owner:	NATIONAL LINEN SERVICE		
	507 N WILLOW AVE		
	TAMPA, FL 336061337		
Owner's Phone:	8132530431	Tracking #:	297414
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	70/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

112

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL LINEN SERVICE (Continued)

U001354545

Facility ID:	298625323	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	RAY HINSON		
Contact:	Not reported	Facility Phone:	8132530431
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	PAT SNIDER		
Owner:	NATIONAL LINEN SERVICE		
	507 N WILLOW AVE		
	TAMPA, FL 336061337		
Owner's Phone:	8132530431	Tracking #:	297414
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	5
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

112

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL LINEN SERVICE (Continued)

U001354545

Facility ID:	298625323	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	RAY HINSON		
Contact:	Not reported	Facility Phone:	8132530431
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	PAT SNIDER		
Owner:	NATIONAL LINEN SERVICE		
	507 N WILLOW AVE		
	TAMPA, FL 336061337		
Owner's Phone:	8132530431	Tracking #:	297414
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

112

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL LINEN SERVICE (Continued)

U001354545

Facility ID:	298625323	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	RAY HINSON		
Contact:	Not reported	Facility Phone:	8132530431
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	PAT SNIDER		
Owner:	NATIONAL LINEN SERVICE 507 N WILLOW AVE TAMPA, FL 336061337		
Owner's Phone:	8132530431	Tracking #:	297414
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Dbl walled=primary matl		
Tank Piping:	Secondary containment		
Petro. Monitoring:	Man sample wells		

112

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

NATIONAL LINEN SERVICE (Continued)

U001354545

Facility ID:	298625323	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	RAY HINSON		
Contact:	Not reported	Facility Phone:	8132530431
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	PAT SNIDER		
Owner:	NATIONAL LINEN SERVICE		
	507 N WILLOW AVE		
	TAMPA, FL 336061337		
Owner's Phone:	8132530431	Tracking #:	297414
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	2	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Dbl walled=primary matl		
Tank Piping:	Secondary containment		
Petro. Monitoring:	Man sample wells		

113

PROFESSIONAL SERVICE INDUSTRIES INC
512 N DELAWARE AVE
TAMPA, FL 33606

UST
LUST

U001355948
N/A

113

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PROFESSIONAL SERVICE INDUSTRIES INC (Continued)

U001355948

LUST:

Facility ID:	8942650	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132533485	Discovery Date:	11/01/88
Tracking Number:	296240	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NO C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

113

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PROFESSIONAL SERVICE INDUSTRIES INC (Continued)

U001355948

UST:

Facility ID:	298942650	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PROFESSIONAL SERVICE INDUSTRIES		
Contact:	Not reported	Facility Phone:	8132533485
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT WATKINS		
Owner:	PROFESSIONAL SERVICE INDUSTRIES		
	512 N DELAWARE AVE		
	TAMPA, FL 336061313		
Owner's Phone:	8132533485	Tracking #:	296240
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

114

AMOCO #665
301 N DALE MABRY HWY
TAMPA, FL 33609

UST
LUST

U001354224
N/A

114

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #665 (Continued)

U001354224

LUST:

Facility ID:	8624975	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8138767661	Discovery Date:	11/30/88
Tracking Number:	295862	Score:	035
Facility Code:	Not reported	Status:	Not reported
Rank:	03338		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

114

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #665 (Continued)

U001354224

UST:

Facility ID:	298624975	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HANAN KARPUGH		
Contact:	Not reported	Facility Phone:	8138767661
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS		
	600 CORPORATE DR #500		
	FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	295862
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Instal. Date:	83/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #665 (Continued)

U001354224

Facility ID:	298624975	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HANAN KARPUGH		
Contact:	Not reported	Facility Phone:	8138767661
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS 600 CORPORATE DR #500 FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	295862
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #665 (Continued)

U001354224

Facility ID:	298624975	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HANAN KARPUGH		
Contact:	Not reported	Facility Phone:	8138767661
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS 600 CORPORATE DR #500 FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	295862
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

114

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #665 (Continued)

U001354224

Facility ID:	298624975	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HANAN KARPUCH		
Contact:	Not reported	Facility Phone:	8138767661
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS 600 CORPORATE DR #500 FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	295862
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Instal. Date:	83/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

114

AMOCO SERVICE STATION #665
301 N DALE MABRY HWY
TAMPA, FL 33609

RCRIS-SQG
FINDS

1000501235
FLD984213629

RCRIS:

Owner: HANAN KARPUCH, DEALER
(813) 875-9303

Contact: HANAN KARPUCH
(813) 875-9303

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D018	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

114

MIDAS MUFFLER
315 NORTH DALE MABRY
TAMPA, FL 33609

FINDS

1000735917
FLD984168922

115

DICK A B CO
5502 EXECUTIVE DR
TAMPA, FL 33622

FINDS

1000733251
FLD043052331

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

115	A B DICK CO 5502 EXECUTIVE DR TAMPA, FL 33609	RCRIS-SQG	1000189157 FLD043052331
-----	--	------------------	--

RCRIS:

Owner: DAVID SPANG, SV MGR
(813) 289-4174

Contact: DAVID SPANG
(813) 289-4174

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

116	INTERNATIONAL TECHNOLOGY SERVICE, INC 402 N HOOVER ST TAMPA, FL 33609	UST	U001355965 N/A
-----	--	------------	---------------------------------

UST:

Facility ID:	298943066	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	INTERNATIONAL TECHNOLOGY SERVICE		
Contact:	Not reported	Facility Phone:	4122433230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890201	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LES REHM		
Owner:	INTL TECHNOLOGY SERVICE INC		
	2790 MOSSIDE BLVD		
	MONROEVILLE, PA 151462735		
Owner's Phone:	4122433230	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000280	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

INTERNATIONAL TECHNOLOGY SERVICE, INC (Continued)

U001355965

Facility ID:	298943066	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	INTERNATIONAL TECHNOLOGY SERVICE		
Contact:	Not reported	Facility Phone:	4122433230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890201	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	LES REHM		
Owner:	INTL TECHNOLOGY SERVICE INC		
	2790 MOSSIDE BLVD		
	MONROEVILLE, PA 151462735		
Owner's Phone:	4122433230	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

116

NCR CORP.
402 N HOOVER ST
TAMPA, FL 33609

UST

U001355315
N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

NCR CORP. (Continued)

U001355315

UST:

Facility ID:	298628006	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCR CORP.		
Contact:	Not reported	Facility Phone:	8138765193
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DON WHITEMAN		
Owner:	N C R CORP		
	402 N HOOVER ST		
	TAMPA, FL 336091009		
Owner's Phone:	8138765193	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Unknown/not reported		

117	TEXACO #242031382 301 N WESTSHORE BLVD TAMPA, FL 32794	FINDS	1000736671 FLD984191296
117	TAMPA GAS STATION 301 N WESTSHORE BLVD TAMPA, FL 33609	UST LUST	U001354598 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA GAS STATION (Continued)

U001354598

LUST:

Facility ID:	8625378	Facility Type:	RETAIL STATION
Alias Name:	TEXACO FOOD MART #302-08-24-203-1382		
Alias Name 2:	TENNECO #302		
Telephone:	8132867929	Discovery Date:	06/08/85
Tracking Number:	290105	Score:	014 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05757		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Y	Alt. Process Date:	Not reported
Soil Treatment:	Y	Alternative Status:	Not reported
Other Treatment:	SOIL TO BE USED UNDE		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	ANNUAL
Report Comments:	Y1

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA GAS STATION (Continued)

U001354598

UST:

Facility ID:	298625378	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY ROEOL		
Contact:	Not reported	Facility Phone:	8132867929
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE CONVEY		
Owner:	TAMPA GAS INC		
	301 N WESTSHORE BLVD		
	TAMPA, FL 33609		
Owner's Phone:	8132867929	Tracking #:	290105
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA GAS STATION (Continued)

U001354598

Facility ID:	298625378	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY ROEOL		
Contact:	Not reported	Facility Phone:	8132867929
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE CONVEY		
Owner:	TAMPA GAS INC 301 N WESTSHORE BLVD TAMPA, FL 33609		
Owner's Phone:	8132867929	Tracking #:	290105
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA GAS STATION (Continued)

U001354598

Facility ID:	298625378	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY ROEOL		
Contact:	Not reported	Facility Phone:	8132867929
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE CONVEY		
Owner:	TAMPA GAS INC 301 N WESTSHORE BLVD TAMPA, FL 33609		
Owner's Phone:	8132867929	Tracking #:	290105
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

118

SHELL-ANDERSON'S
201 N WESTSHORE BLVD
TAMPA, FL 33609

UST
LUST

U001354320
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-ANDERSON'S (Continued)

U001354320

LUST:

Facility ID:	8625079	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132862454	Discovery Date:	10/17/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-ANDERSON'S (Continued)

U001354320

UST:

Facility ID:	298625079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDERSON, CHESTER		
Contact:	Not reported	Facility Phone:	8132862454
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO		
	PO BOX 20427		
	TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006134	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-ANDERSON'S (Continued)

U001354320

Facility ID:	298625079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDERSON, CHESTER		
Contact:	Not reported	Facility Phone:	8132862454
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009728	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-ANDERSON'S (Continued)

U001354320

Facility ID:	298625079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDERSON, CHESTER		
Contact:	Not reported	Facility Phone:	8132862454
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO		
	PO BOX 20427		
	TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003970	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-ANDERSON'S (Continued)

U001354320

Facility ID:	298625079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDERSON, CHESTER		
Contact:	Not reported	Facility Phone:	8132862454
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2R1	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO		
	PO BOX 20427		
	TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009728	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

1/96

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-ANDERSON'S (Continued)

U001354320

Facility ID:	298625079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDERSON, CHESTER		
Contact:	Not reported	Facility Phone:	8132862454
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003970	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-ANDERSON'S (Continued)

U001354320

Facility ID:	298625079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDERSON, CHESTER		
Contact:	Not reported	Facility Phone:	8132862454
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3R1	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009728	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

1146

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-ANDERSON'S (Continued)

U001354320

Facility ID:	298625079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDERSON, CHESTER		
Contact:	Not reported	Facility Phone:	8132862454
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO		
	PO BOX 20427		
	TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003970	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-ANDERSON'S (Continued)

U001354320

Facility ID:	298625079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDERSON, CHESTER		
Contact:	Not reported	Facility Phone:	8132862454
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4R4	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-ANDERSON'S (Continued)

U001354320

Facility ID:	298625079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDERSON, CHESTER		
Contact:	Not reported	Facility Phone:	8132862454
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003970	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Piping/flow restrictor		

119

OFFICE DEPOT
201 N DALE MABRY HWY
TAMPA, FL 33609

UST

U001823400
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

OFFICE DEPOT (Continued)

U001823400

UST:

Facility ID:	299400493	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JIM COFER		
Contact:	Not reported	Facility Phone:	2052856500
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940405	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM COFER		
Owner:	JIM COFER PROPERTIES INC 605 SPRING LN DEATSCILLE, AL 36022		
Owner's Phone:	2052856500	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

120

CHEVRON #48101-M.R. HACKWORTH
5350 W KENNEDY BLVD
TAMPA, FL 33609

UST
LUST

U001354797
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48101-M.R. HACKWORTH (Continued)

U001354797

LUST:

Facility ID:	8625586	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	07/06/89
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS
Pollutant 2:	UNLEADED GAS
Pollutant 3:	WASTE OIL

Est. Gallons Lost:	UNKNOWN
Est. Gallons Lost:	UNKNOWN
Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION

REIMBURSEMENT CLEANUP

PARTIAL

NOT PETROL/PETROL PRODUCT

NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal: Y

Soil Treatment:

Other Treatment:

Cleanup Responsible: RESPONSIBLE PARTY

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

INCOMPLETE

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

RESPONSIBLE PARTY

REMEDIAL ACTION PLAN

GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

RESPONSIBLE PARTY

00

00

QUARTERLY

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48101-M.R. HACKWORTH (Continued)

U001354797

UST:

Facility ID:	298625586	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HACKWORTH		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48101-M.R. HACKWORTH (Continued)

U001354797

Facility ID:	298625586	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HACKWORTH		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

120

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48101-M.R. HACKWORTH (Continued)

U001354797

Facility ID:	298625586	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HACKWORTH		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48101-M.R. HACKWORTH (Continued)

U001354797

Facility ID:	298625586	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HACKWORTH		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

121

LINCOLN CENTER
5401 W KENNEDY BLVD #161
TAMPA, FL 33609

RCRIS-SQG
FINDS

1000821348
FLD984242677

RCRIS:

Owner: BILL ANDERSON, OPS FOREMAN
(813) 287-1430

Contact: BILL ANDERSON
(813) 287-1430

Waste	Quantity	Info Source
D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

122

CHEVRON #48100-HACKWORTH
4801 W KENNEDY BLVD
TAMPA, FL 33609

UST
LUST

U001354663
N/A

122

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48100-HACKWORTH (Continued)

U001354663

LUST:

Facility ID:	8625444	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	11/14/83
Tracking Number:	290181	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	00001185
------------	-------------	--------------------	----------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Y	Alt. Process Date:	Not reported
Soil Treatment:	Y	Alternative Status:	Not reported
Other Treatment:	GROUNDWATER TREATMEN		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE

122

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48100-HACKWORTH (Continued)

U001354663

UST:

Facility ID:	298625444	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HACKWORTH H W		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	290181
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

122

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48100-HACKWORTH (Continued)

U001354663

Facility ID:	298625444	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HACKWORTH H W		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	290181
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

122

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48100-HACKWORTH (Continued)

U001354663

Facility ID:	298625444	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HACKWORTH H W		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	290181
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

123

LINDELL MOTORS INC
3900 W KENNEDY BLVD
TAMPA, FL 33609

RCRIS-SQG 1000186024
FINDS FLD032787228
UST
LUST

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC (Continued)

1000186024

LUST:

Facility ID:	8625118	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138724841	Discovery Date:	02/19/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

CLOSURE REPORT

LOCAL PROGRAM

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS

Pollutant 2: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION

REIMBURSEMENT CLEANUP

INELIGIBLE

APPLICATION SUBMIT AFTER 063092

APPLICATION SUB

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

INCOMPLETE

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

RESPONSIBLE PARTY

REMEDIAL ACTION PLAN

MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

RESPONSIBLE PARTY

00

00

ANNUAL

MOP - Q1,Q2,Q3,&Q4

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

123

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC (Continued)

1000186024

UST:

Facility ID:	298625118	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM MORSE		
Contact:	Not reported	Facility Phone:	8138724841
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	SAM MORSE		
Owner:	LINDELL MOTORS INC 3900 W KENNEDY BLVD TAMPA, FL 336092722		
Owner's Phone:	8138724841	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Unknown/not reported		

123

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC (Continued)

1000186024

Facility ID:	298625118	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM MORSE		
Contact:	Not reported	Facility Phone:	8138724841
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	SAM MORSE		
Owner:	LINDELL MOTORS INC 3900 W KENNEDY BLVD TAMPA, FL 336092722		
Owner's Phone:	8138724841	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Spill cnmt		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells		

123

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC (Continued)

1000186024

Facility ID:	298625118	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM MORSE		
Contact:	Not reported	Facility Phone:	8138724841
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	SAM MORSE		
Owner:	LINDELL MOTORS INC		
	3900 W KENNEDY BLVD		
	TAMPA, FL 336092722		
Owner's Phone:	8138724841	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC (Continued)

1000186024

Facility ID:	298625118	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM MORSE		
Contact:	Not reported	Facility Phone:	8138724841
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	SAM MORSE		
Owner:	LINDELL MOTORS INC 3900 W KENNEDY BLVD TAMPA, FL 336092722		
Owner's Phone:	8138724841	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Unknown/not reported		

123

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC (Continued)

1000186024

Facility ID:	298625118	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM MORSE		
Contact:	Not reported	Facility Phone:	8138724841
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	SAM MORSE		
Owner:	LINDELL MOTORS INC 3900 W KENNEDY BLVD TAMPA, FL 336092722		
Owner's Phone:	8138724841	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

123

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC (Continued)

1000186024

Facility ID:	298625118	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM MORSE		
Contact:	Not reported	Facility Phone:	8138724841
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	SAM MORSE		
Owner:	LINDELL MOTORS INC 3900 W KENNEDY BLVD TAMPA, FL 336092722		
Owner's Phone:	8138724841	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC (Continued)

1000186024

Facility ID:	298625118	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM MORSE		
Contact:	Not reported	Facility Phone:	8138724841
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	SAM MORSE		
Owner:	LINDELL MOTORS INC 3900 W KENNEDY BLVD TAMPA, FL 336092722		
Owner's Phone:	8138724841	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

123

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC (Continued)

1000186024

Facility ID:	298625118	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM MORSE		
Contact:	Not reported	Facility Phone:	8138724841
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	SAM MORSE		
Owner:	LINDELL MOTORS INC 3900 W KENNEDY BLVD TAMPA, FL 336092722		
Owner's Phone:	8138724841	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/04
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	94/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

123

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC (Continued)

1000186024

Facility ID:	298625118	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM MORSE		
Contact:	Not reported	Facility Phone:	8138724841
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	SAM MORSE		
Owner:	LINDELL MOTORS INC 3900 W KENNEDY BLVD TAMPA, FL 336092722		
Owner's Phone:	8138724841	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/04
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	94/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

123

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC (Continued)

1000186024

Facility ID:	298625118	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM MORSE		
Contact:	Not reported	Facility Phone:	8138724841
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	SAM MORSE		
Owner:	LINDELL MOTORS INC 3900 W KENNEDY BLVD TAMPA, FL 336092722		
Owner's Phone:	8138724841	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/04
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	94/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

123

LINDELL MOTORS INC-CASTROL INC
3900 W KENNEDY BLVD
TAMPA, FL

AST

A100009012
N/A

123

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LINDELL MOTORS INC-CASTROL INC (Continued)

A100009012

AST:

Facility ID:	299102991	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LINDELL MOTORS INC		
Facility Phone:	8138724841	Permit Section:	Not reported
Date entered:	911003	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLIAM C KELLOG		
Owner:	CASTROL NORTH AMERICA		
	PO BOX 6220		
	JACKSONVILLE, FL 32205		
Owner's Phone:	9047814661	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	New/lube oil	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	88/07
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	94/03	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man tank gauging		

124

TEXACO STATION
4671 W KENNEDY BLVD
TAMPA, FL 33609

UST
LUST

U001354066
N/A

124

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO STATION (Continued)

U001354066

LUST:

Facility ID:	8624803	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132474731	Discovery Date:	09/09/88
Tracking Number:	293779	Score:	018 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05566		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

124

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO STATION (Continued)

U001354066

UST:

Facility ID:	298624803	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GAS KWICK INC		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293779
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

124

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO STATION (Continued)

U001354066

Facility ID:	298624803	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GAS KWICK INC		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293779
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

124

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO STATION (Continued)

U001354066

Facility ID:	298624803	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GAS KWICK INC		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293779
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

129

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO STATION (Continued)

U001354066

Facility ID:	298624803	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GAS KWICK INC		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293779
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000150	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	94/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	None		

129

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO STATION (Continued)

U001354066

Facility ID:	298624803	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GAS KWICK INC		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293779
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000150	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	94/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	None		

125

BEACH PARK TIRE & BATTERY
4650 W KENNEDY BLVD
TAMPA, FL 33609

UST
LUST

U001354580
N/A

125

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BEACH PARK TIRE & BATTERY (Continued)

U001354580

LUST:

Facility ID:	8625360	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8138767777	Discovery Date:	01/25/88
Tracking Number:	293397	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

125

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BEACH PARK TIRE & BATTERY (Continued)

U001354580

UST:

Facility ID:	298625360	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TONY PARRADO		
Contact:	Not reported	Facility Phone:	8138767777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	293397
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	7
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BEACH PARK TIRE & BATTERY (Continued)

U001354580

Facility ID:	298625360	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TONY PARRADO		
Contact:	Not reported	Facility Phone:	8138767777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	293397
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	8
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

125

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BEACH PARK TIRE & BATTERY (Continued)

U001354580

Facility ID:	298625360	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TONY PARRADO		
Contact:	Not reported	Facility Phone:	8138767777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	293397
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	9
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

1255

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BEACH PARK TIRE & BATTERY (Continued)

U001354580

Facility ID:	298625360	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TONY PARRADO		
Contact:	Not reported	Facility Phone:	8138767777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	293397
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	59/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

125

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BEACH PARK TIRE & BATTERY (Continued)

U001354580

Facility ID:	298625360	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TONY PARRADO		
Contact:	Not reported	Facility Phone:	8138767777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	293397
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	59/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BEACH PARK TIRE & BATTERY (Continued)

U001354580

Facility ID:	298625360	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TONY PARRADO		
Contact:	Not reported	Facility Phone:	8138767777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	293397
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	84/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Auto sample wells, Piping/flow restrictor, Man tank gauging		

125

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BEACH PARK TIRE & BATTERY (Continued)

U001354580

Facility ID:	298625360	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TONY PARRADO		
Contact:	Not reported	Facility Phone:	8138767777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	293397
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Auto sample wells, Piping/flow restrictor, Man tank gauging		

125

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BEACH PARK TIRE & BATTERY (Continued)

U001354580

Facility ID:	298625360	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TONY PARRADO		
Contact:	Not reported	Facility Phone:	8138767777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	293397
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	2	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Auto sample wells, Piping/flow restrictor, Man tank gauging		

125

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BEACH PARK TIRE & BATTERY (Continued)

U001354580

Facility ID:	298625360	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TONY PARRADO		
Contact:	Not reported	Facility Phone:	8138767777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	293397
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/11
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	3	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Auto sample wells, Man tank gauging		

126	SHELL SERVICE STATION 4918 WEST KENNEDY BOULEVARD TAMPA, FL 33622	RCRIS-SQG	1000699350 FLD980711006
126	SHELL SVC STA 4918 W KENNEDY BLVD TAMPA, FL 33622	FINDS	1000733908 FLD980711006
126	SHELL-KENNEDY SQUARE 4918 W KENNEDY BLVD TAMPA, FL 33609	UST LUST	U001354270 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-KENNEDY SQUARE (Continued)

U001354270

LUST:

Facility ID:	8625025	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8138798902	Discovery Date:	07/15/88
Tracking Number:	296120	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07179		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	O.K.

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-KENNEDY SQUARE (Continued)

U001354270

UST:

Facility ID:	298625025	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MICHAEL BURNS		
Contact:	Not reported	Facility Phone:	8138798902
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CARL LINDELL		
Owner:	LINDELL, CARL JR 3900 W KENNEDY BLVD TAMPA, FL 33609		
Owner's Phone:	8138724841	Tracking #:	296120
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009520	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotac metal		
Petro. Monitoring:	Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-KENNEDY SQUARE (Continued)

U001354270

Facility ID:	298625025	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MICHAEL BURNS		
Contact:	Not reported	Facility Phone:	8138798902
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CARL LINDELL		
Owner:	LINDELL, CARL JR 3900 W KENNEDY BLVD TAMPA, FL 33609		
Owner's Phone:	8138724841	Tracking #:	296120
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00007734	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Piping/flow restrictor		

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-KENNEDY SQUARE (Continued)

U001354270

Facility ID:	298625025	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MICHAEL BURNS		
Contact:	Not reported	Facility Phone:	8138798902
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CARL LINDELL		
Owner:	LINDELL, CARL JR 3900 W KENNEDY BLVD TAMPA, FL 33609		
Owner's Phone:	8138724841	Tracking #:	296120
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006134	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-KENNEDY SQUARE (Continued)

U001354270

Facility ID:	298625025	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MICHAEL BURNS		
Contact:	Not reported	Facility Phone:	8138798902
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CARL LINDELL		
Owner:	LINDELL, CARL JR 3900 W KENNEDY BLVD TAMPA, FL 33609		
Owner's Phone:	8138724841	Tracking #:	296120
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	62/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	87/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-KENNEDY SQUARE (Continued)

U001354270

Facility ID:	298625025	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MICHAEL BURNS		
Contact:	Not reported	Facility Phone:	8138798902
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	CARL LINDELL		
Owner:	LINDELL, CARL JR 3900 W KENNEDY BLVD TAMPA, FL 33609		
Owner's Phone:	8138724841	Tracking #:	296120
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	62/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-KENNEDY SQUARE (Continued)

U001354270

Facility ID:	298625025	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MICHAEL BURNS		
Contact:	Not reported	Facility Phone:	8138798902
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	CARL LINDELL		
Owner:	LINDELL, CARL JR 3900 W KENNEDY BLVD TAMPA, FL 33609		
Owner's Phone:	8138724841	Tracking #:	296120
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	62/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-KENNEDY SQUARE (Continued)

U001354270

Facility ID:	298625025	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MICHAEL BURNS		
Contact:	Not reported	Facility Phone:	8138798902
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	CARL LINDELL		
Owner:	LINDELL, CARL JR		
	3900 W KENNEDY BLVD		
	TAMPA, FL 33609		
Owner's Phone:	8138724841	Tracking #:	296120
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	62/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL-KENNEDY SQUARE (Continued)

U001354270

Facility ID:	298625025	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MICHAEL BURNS		
Contact:	Not reported	Facility Phone:	8138798902
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	CARL LINDELL		
Owner:	LINDELL, CARL JR		
	3900 W KENNEDY BLVD		
	TAMPA, FL 33609		
Owner's Phone:	8138724841	Tracking #:	296120
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	62/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

126 MOBIL OIL CORP SS# CPP
4843 W KENNEDY BLVD
TAMPA, FL 22037

RCRIS-SQG 1000702536
FLD984203646

RCRIS:

Owner: DAN HORTON
(703) 849-3330

Contact: DAN HORTON
(703) 849-3330

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D018	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

126 FIRESTONE #19FN-014583
4901 W KENNEDY BLVD
TAMPA, FL 33609

UST
LUST

U001355451
N/A

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FIRESTONE #19FN-014583 (Continued)

U001355451

LUST:

Facility ID:	8733808	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138751182	Discovery Date:	03/28/91
Tracking Number:	297376	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
------------	-----------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	OPERATING AFTER 3/90
Incident Ineligible Description:	OPERATING AFTER

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FIRESTONE #19FN-014583 (Continued)

U001355451

UST:

Facility ID:	298733808	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JERRY L. SNOUFFER		
Contact:	Not reported	Facility Phone:	8138751182
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870729	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	J C PENNEY FIRESTONE #19FN014583		
	4901 W KENNEDY BLVD		
	TAMPA, FL 33609		
Owner's Phone:	Not reported	Tracking #:	297376
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

126

MOBIL OIL CORP SS# CPP
4843 W KENNEDY BLVD
TAMPA, FL 22037

FINDS
UST
LUST

1000737482
FLD984203646

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS# CPP (Continued)

1000737482

LUST:

Facility ID:	8624980	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132871425	Discovery Date:	03/09/94
Tracking Number:	297387	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06571		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS# CPP (Continued)

1000737482

UST:

Facility ID:	298624980	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132871425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWES RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297387
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS# CPP (Continued)

1000737482

Facility ID:	298624980	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132871425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297387
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS# CPP (Continued)

1000737482

Facility ID:	298624980	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132871425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297387
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	74/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS# CPP (Continued)

1000737482

Facility ID:	298624980	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132871425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297387
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/11
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

120

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS# CPP (Continued)

1000737482

Facility ID:	298624980	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132871425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	5	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297387
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/11
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL OIL CORP SS# CPP (Continued)

1000737482

Facility ID:	298624980	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132871425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	6	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP.		
	3225 GALLOWS RD		
	FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297387
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

126

KEYSTOP #501
4901 W KENNEDY BLVD
TAMPA, FL 33609

UST

U001354396
N/A

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KEYSTOP #501 (Continued)

U001354396

UST:

Facility ID:	298625159	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIRESTONE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVE AUGUSTINE		
Owner:	KEY ENERGY ENTERPRISE		
	9250 BAY PLAZA BLVD		
	TAMPA, FL 33617		
Owner's Phone:	8136235666	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Gasohol	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

126

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KEYSTOP #501 (Continued)

U001354396

Facility ID:	298625159	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIRESTONE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVE AUGUSTINE		
Owner:	KEY ENERGY ENTERPRISE		
	9250 BAY PLAZA BLVD		
	TAMPA, FL 33617		
Owner's Phone:	8136235666	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Gasohol	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

127

AMOCO SVC STA #628
5109 W KENNEDY BLVD
TAMPA, FL 33609

RCRIS-SQG
FINDS

1000501053
FLD984211722

RCRIS:

Owner: WILLIAM JEANFILS, DEALER
(813) 879-3566

Contact: WILLIAM JEANFILS
(813) 879-3566

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D002	.00000 (T)	Notification	D008	.00000 (T)	Notification
D018	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

127

AMOCO #628
5109 W KENNEDY BLVD
TAMPA, FL 33609

UST
LUST

U001354001
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #628 (Continued)

U001354001

LUST:

Facility ID:	8521236	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132860152	Discovery Date:	06/20/91
Tracking Number:	295863	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
------------	-----------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

127

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #628 (Continued)

U001354001

UST:

Facility ID:	298521236	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL JEANFILLS		
Contact:	Not reported	Facility Phone:	8132860152
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	851031	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS		
	600 CORPORATE DR #500		
	FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	295863
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	73/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off		
Tank Piping:	Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

127

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #628 (Continued)

U001354001

Facility ID:	298521236	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL JEANFILLS		
Contact:	Not reported	Facility Phone:	8132860152
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	851031	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS		
	600 CORPORATE DR #500		
	FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	295863
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	73/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off		
Tank Piping:	Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

127

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #628 (Continued)

U001354001

Facility ID:	298521236	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL JEANFILLS		
Contact:	Not reported	Facility Phone:	8132860152
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	851031	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS 600 CORPORATE DR #500 FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	295863
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	73/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off		
Tank Piping:	Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

127

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #628 (Continued)

U001354001

Facility ID:	298521236	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL JEANFILLS		
Contact:	Not reported	Facility Phone:	8132860152
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	851031	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS 600 CORPORATE DR #500 FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	295863
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	73/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off		
Tank Piping:	Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

127

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #628 (Continued)

U001354001

Facility ID:	298521236	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL JEANFILLS		
Contact:	Not reported	Facility Phone:	8132860152
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	851031	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS 600 CORPORATE DR #500 FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	295863
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	73/08
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	6
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

127

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #628 (Continued)

U001354001

Facility ID:	298521236	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL JEANFILLS		
Contact:	Not reported	Facility Phone:	8132860152
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	851031	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	6	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS		
	600 CORPORATE DR #500		
	FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	295863
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	91/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	5	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Dbl walled=primary matl, Spill cnmt		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	DW tank space		

128

MARQUIS CLEANERS
4532 W KENNEDY BLVD
TAMPA, FL 33609

UST

U002314293
N/A

1286

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARQUIS CLEANERS (Continued)

U002314293

UST:

Facility ID:	529502365	Facility Type:	1
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	S MARK POLING		
Contact:	Not reported	Facility Phone:	8132898974
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950728	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	RUBENSTEIN, IRENE		
Owner:	BRANDA VISTA		
	4805 BEACH PARK DR		
	TAMPA, FL 33609		
Owner's Phone:	8132862725	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

129

GOODYEAR TIRE CENTER
5002 W KENNEDY BLVD
TAMPA, FL 33609

UST
LUST

U001355450
N/A

129

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GOODYEAR TIRE CENTER (Continued)

U001355450

LUST:

Facility ID:	8733807	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	03/09/92
Tracking Number:	Not reported	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06461		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
------------	-----------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

129

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

GOODYEAR TIRE CENTER (Continued)

U001355450

UST:

Facility ID:	298733807	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GOODYEAR TIRE CENTER		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870729	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	C PUTZIER		
Owner:	GOODYEAR TIRE & RUBBER CO D 824		
	1144 E MARKET ST		
	AKRON, OH 44305		
Owner's Phone:	2167961900	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000400	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

129

BRAZZEAL TIRE AND SERVICE CENT
5002 W KENNEDY BLVD
TAMPA, FL 33609

RCRIS-SQG
FINDS

1000443633
FLD982161176

RCRIS:

Owner: BRAZZEAL CHARLES MGR
(813) 877-9155

Contact: BRAZZEAL CHARLES
(813) 877-9155

Waste	Quantity	Info Source
-------	----------	-------------

D001	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

130

WTW INC WASH THE WORLD
4438 W KENNEDY BLVD
TAMPA, FL 33609

UST
LUST

U001355717
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WTW INC WASH THE WORLD (Continued)

U001355717

LUST:

Facility ID:	8737086	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132540533	Discovery Date:	12/01/90
Tracking Number:	Not reported	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	00000025
------------	--------------	--------------------	----------

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	DISTRICT OFFICE
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

130

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WTW INC WASH THE WORLD (Continued)

U001355717

UST:

Facility ID:	298737086	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	THOMAS J BROWN		
Contact:	Not reported	Facility Phone:	8132540533
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871228	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	THOMAS J BROWN		
Owner:	WASH THE WORLD WESTSHORE INC		
	4438 W KENNEDY BLVD		
	TAMPA, FL 336092024		
Owner's Phone:	8132290533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WTW INC WASH THE WORLD (Continued)

U001355717

Facility ID:	298737086	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	THOMAS J BROWN		
Contact:	Not reported	Facility Phone:	8132540533
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871228	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	THOMAS J BROWN		
Owner:	WASH THE WORLD WESTSHORE INC		
	4438 W KENNEDY BLVD		
	TAMPA, FL 336092024		
Owner's Phone:	8132290533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WTW INC WASH THE WORLD (Continued)

U001355717

Facility ID:	298737086	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	THOMAS J BROWN		
Contact:	Not reported	Facility Phone:	8132540533
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871228	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	THOMAS J BROWN		
Owner:	WASH THE WORLD WESTSHORE INC		
	4438 W KENNEDY BLVD		
	TAMPA, FL 336092024		
Owner's Phone:	8132290533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

131

KWIKIE DUPLICATION CENTERS
4227 W KENNEDY BLVD
TAMPA, FL 33609

RCRIS-SQG
FINDS

1000461023
FLD984187179

RCRIS:

Owner: PAUL DIETSH, VP
(813) 879-3921

Contact: PAUL DIETSH
(813) 879-3921

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D002	.00000 (T)	Notification	D011	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

132

BARNETT BANK
4202 W KENNEDY BLVD
TAMPA, FL 33601

UST
LUST

U002113432
N/A

132

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BARNETT BANK (Continued)

U002113432

LUST:

Facility ID:	9501496	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132734200	Discovery Date:	06/07/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	GASOHOL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

132

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BARNETT BANK (Continued)

U002113432

UST:

Facility ID:	299501496	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BARNETT BANKS INC		
Contact:	Not reported	Facility Phone:	8132734200
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950302	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	CARTER MCCAIN		
Owner:	BARNETT BANKS INC		
	PO BOX 1531		
	TAMPA, FL 33601		
Owner's Phone:	8132734200	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	1
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

132

FOOD MART & SHELLEY DELI-BCH PARK
4205 W KENNEDY BLVD
TAMPA, FL 33609

UST
LUST

U001354794
N/A

132

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FOOD MART & SHELLEY DELI-BCH PARK (Continued)

U001354794

LUST:

Facility ID:	8625582	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8138790523	Discovery Date:	05/26/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	CA
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

132

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FOOD MART & SHELLEY DELI-BCH PARK (Continued)

U001354794

UST:

Facility ID:	298625582	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM F. JENKINS		
Contact:	Not reported	Facility Phone:	8138790523
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	FRANK JENKINS		
Owner:	JENKINS, WILLIAM F 4205 W KENNEDY BLVD TAMPA, FL 336092230		
Owner's Phone:	8138790523	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Airport/seaport hydrant, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FOOD MART & SHELLEY DELI-BCH PARK (Continued)

U001354794

Facility ID:	298625582	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM F. JENKINS		
Contact:	Not reported	Facility Phone:	8138790523
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	FRANK JENKINS		
Owner:	JENKINS, WILLIAM F 4205 W KENNEDY BLVD TAMPA, FL 336092230		
Owner's Phone:	8138790523	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Airport/seaport hydrant, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FOOD MART & SHELLEY DELI-BCH PARK (Continued)

U001354794

Facility ID:	298625582	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM F. JENKINS		
Contact:	Not reported	Facility Phone:	8138790523
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	FRANK JENKINS		
Owner:	JENKINS, WILLIAM F 4205 W KENNEDY BLVD TAMPA, FL 336092230		
Owner's Phone:	8138790523	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Airport/seaport hydrant, Pressurized piping		
Petro. Monitoring:	Man sample wells		

132

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FOOD MART & SHELLEY DELI-BCH PARK (Continued)

U001354794

Facility ID:	298625582	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM F. JENKINS		
Contact:	Not reported	Facility Phone:	8138790523
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	FRANK JENKINS		
Owner:	JENKINS, WILLIAM F 4205 W KENNEDY BLVD TAMPA, FL 336092230		
Owner's Phone:	8138790523	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Airport/seaport hydrant, Pressurized piping		
Petro. Monitoring:	Man sample wells		

133 SUNOCO SVC STA
4139 W KENNEDY BLVD
TAMPA, FL 33609

RCRIS-SQG
FINDS 1000496563
FLD000654087

133 BP-LOIS & KENNEDY
4139 W KENNEDY BLVD
TAMPA, FL 33609

UST
LUST U001354222
N/A

133

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-LOIS & KENNEDY (Continued)

U001354222

LUST:

Facility ID:	8624973	Facility Type:	RETAIL STATION
Alias Name:	PHILLIPS 66-LOIS		
Telephone:	8136814279	Discovery Date:	03/18/87
Tracking Number:	290581	Score:	014 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05757		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-LOIS & KENNEDY (Continued)

U001354222

UST:

Facility ID:	298624973	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	290581
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/auto shut off		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-LOIS & KENNEDY (Continued)

U001354222

Facility ID:	298624973	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	10	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	290581
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	91/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Dbl walled=primary matl, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	DW tank space, Piping/flow restrictor, DW piping space		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-LOIS & KENNEDY (Continued)

U001354222

Facility ID:	298624973	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	290581
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/auto shut off		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-LOIS & KENNEDY (Continued)

U001354222

Facility ID:	298624973	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	290581
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/auto shut off		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-LOIS & KENNEDY (Continued)

U001354222

Facility ID:	298624973	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	290581
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/auto shut off		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-LOIS & KENNEDY (Continued)

U001354222

Facility ID:	298624973	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	290581
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/auto shut off		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-LOIS & KENNEDY (Continued)

U001354222

Facility ID:	298624973	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	290581
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	9/1/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-LOIS & KENNEDY (Continued)

U001354222

Facility ID:	298624973	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	290581
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-LOIS & KENNEDY (Continued)

U001354222

Facility ID:	298624973	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	290581
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	9/1/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Dbl walled=primary matl, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	DW tank space, Piping/flow restrictor, DW piping space		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BP-LOIS & KENNEDY (Continued)

U001354222

Facility ID:	298624973	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	9	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	290581
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	91/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Dbl walled=primary matl, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	DW tank space, Piping/flow restrictor, DW piping space		

134

NELSONS ONE HOUR MARTINIZING
122 S WESTSHORE BLVD
TAMPA, FL 33609

UST

U002313187
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NELSONS ONE HOUR MARTINIZING (Continued)

U002313187

UST:

Facility ID:	299500189	Facility Type:	1
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	NELSON FIGUEROA		
Contact:	Not reported	Facility Phone:	8132870004
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	941001	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	LATONE, SAMUEL P		
Owner:	TOWN SQUARE ASSOCIATES LTD %BRAN		
	400 COLONY SQUARE #1600		
	ATLANTA, GA 30361		
Owner's Phone:	4048920500	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

134

1 HOUR MARTINIZING
122 S WESTSHORE BLVD
TAMPA, FL 33609

RCRIS-SQG
FINDS

1000117524
FLD982126401

RCRIS:

Owner: JERRY MCCALLIE
(813) 287-0004

Contact: JERRY MCCALLIE
(813) 287-0004

Waste	Quantity	Info Source
-------	----------	-------------

F002	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

135

TAMPA BAY MARINA
205 S HOOVER ST
TAMPA, FL 33609

UST
LUST

U001355899
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA BAY MARINA (Continued)

U001355899

LUST:

Facility ID:	8842337	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132862525	Discovery Date:	12/22/88
Tracking Number:	297422	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA BAY MARINA (Continued)

U001355899

UST:

Facility ID:	298842337	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA BAY MARINA, INC		
Contact:	Not reported	Facility Phone:	8132862525
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881216	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LARRY HARJO		
Owner:	PHILLIPS PETROLEUM CO		
	PO BOX 2400		
	BARTLESVILLE, OK 74004		
Owner's Phone:	9186617439	Tracking #:	297422
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA BAY MARINA (Continued)

U001355899

Facility ID:	298842337	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA BAY MARINA, INC		
Contact:	Not reported	Facility Phone:	8132862525
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881216	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	LARRY HARJO		
Owner:	PHILLIPS PETROLEUM CO		
	PO BOX 2400		
	BARTLESVILLE, OK 74004		
Owner's Phone:	9186617439	Tracking #:	297422
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA BAY MARINA (Continued)

U001355899

Facility ID:	298842337	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA BAY MARINA,INC		
Contact:	Not reported	Facility Phone:	8132862525
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881216	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	LARRY HARJO		
Owner:	PHILLIPS PETROLEUM CO		
	PO BOX 2400		
	BARTLESVILLE, OK 74004		
Owner's Phone:	9186617439	Tracking #:	297422
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA BAY MARINA (Continued)

U001355899

Facility ID:	298842337	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA BAY MARINA,INC		
Contact:	Not reported	Facility Phone:	8132862525
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881216	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	LARRY HARJO		
Owner:	PHILLIPS PETROLEUM CO		
	PO BOX 2400		
	BARTLESVILLE, OK 74004		
Owner's Phone:	9186617439	Tracking #:	297422
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA BAY MARINA (Continued)

U001355899

Facility ID:	298842337	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA BAY MARINA,INC		
Contact:	Not reported	Facility Phone:	8132862525
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881216	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	LARRY HARJO		
Owner:	PHILLIPS PETROLEUM CO		
	PO BOX 2400		
	BARTLESVILLE, OK 74004		
Owner's Phone:	9186617439	Tracking #:	297422
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA BAY MARINA (Continued)

U001355899

Facility ID:	298842337	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA BAY MARINA,INC		
Contact:	Not reported	Facility Phone:	8132862525
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881216	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	LARRY HARJO		
Owner:	PHILLIPS PETROLEUM CO		
	PO BOX 2400		
	BARTLESVILLE, OK 74004		
Owner's Phone:	9186617439	Tracking #:	297422
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
BRANDON	94244483	SE CORNER OF MYRTLE AND BELL SHOALS RDS				
FORT MYERS	1000734692	SMALLEY TRANSP CO	2950 GWYN ST	33602	ERNS	
FORT MYERS	1000699998	SMALLEY TRANSPORTATION CO	2950 GWYN STREET	33609	FINDS	
JACKSONVILLE	1000699981	SMALLEY TRANSPORTATION CO	7577 SPORTSMAN CLUB RD	33609	RCRIS-SQG	
LAKELAND	1000700000	SMALLEY TRANSPORTATION CO	1150 NEW TAMPA HWY	33609	RCRIS-SQG	
MADERA BEACH	95305083			33606	ERNS	
MIAMI	1000700005	SMALLEY TRANSPORTATION CO	11405 N W 36TH AVENUE	33609	RCRIS-SQG	
MULBERRY	1000905916	TAMPA ELECTRIC CO POLK POWER STATIO	9995 SR 37 SOUTH	33602	RCRIS-SQG, FINDS	
OCALA	1000700003	SMALLEY TRANSPORTATION CO	1740 N E JACKSONVILLE RD	33609	RCRIS-SQG	
ORLANDO	1000699988	SMALLEY TRANSPORTATION CO	9100 SIDNEY HAYES RD	33609	RCRIS-SQG	
PANAMA CITY	1000699980	SMALLEY TRANSPORTATION CO	1837 INDUSTRIAL DRIVE	33609	RCRIS-SQG	
PENSACOLA	1000699982	SMALLEY TRANSPORTATION CO	600 S "N" STREET	33609	RCRIS-SQG	
PLANT CITY	94236289	HIGHWAY 37 AND HARPER		33602	ERNS	
POMPANO BEACH	1000498418	SMALLEY TRANSPORTATION CO	1801 BLOUNT ROAD	33609	RCRIS-SQG, FINDS	
RIVIERA BEACH	1000699991	SMALLEY TRANSPORTATION CO	1301 A-3 W 15TH STREET	33609	RCRIS-SQG	
ST. PETERSBURG	94240064			33602	ERNS	
TALLAHASSEE	1000700001	SMALLEY TRANSPORTATION CO	4855 GUM ROAD	33609	RCRIS-SQG	
TAMPA	95316504				ERNS	
TAMPA	95316502				ERNS	
TAMPA	95315777				ERNS	
TAMPA	95315498				ERNS	
TAMPA	95315014				ERNS	
TAMPA	95312952				ERNS	
TAMPA	95311412				ERNS	
TAMPA	95311403				ERNS	
TAMPA	95308988				ERNS	
TAMPA	95309793				ERNS	
TAMPA	95308987				ERNS	
TAMPA	95308064				ERNS	
TAMPA	95306689				ERNS	
TAMPA	95306185				ERNS	
TAMPA	95306184				ERNS	
TAMPA	95304245				ERNS	
TAMPA	95303902				ERNS	
TAMPA	95302927				ERNS	
TAMPA	95300771				ERNS	
TAMPA	95296922				ERNS	
TAMPA	95291801				ERNS	
TAMPA	95293250				ERNS	
TAMPA	95285083				ERNS	
TAMPA	95279210				ERNS	
TAMPA	95282435				ERNS	
TAMPA	95277769				ERNS	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	S100021000	SPE RECYCLING C & D FACIL			SWFLF	
TAMPA	8806506	TAMPA GENERAL HOSPITAL			ERNS	
TAMPA	9001491	MARITIME BLVD AND SHORELINE			ERNS	
TAMPA	9003707	MARITIME AND SHORELINE AVENUE			ERNS	
TAMPA	9003701	I-275/HOWARD AVENUE			ERNS	
TAMPA	9101451	ANCLOTE ICE PLANT ANCLOTE RIVER			ERNS	
TAMPA	9009719	HOOKER'S POINT STATION HEMLOCH ST.			ERNS	
TAMPA	9007043	STATE ROUTE 41 AND BIG BEND RD.			ERNS	
TAMPA	9006743	5881 IMGRAHM ST			ERNS	
TAMPA	9003271	FILTER CLEAN INC.			ERNS	
TAMPA	9001049	YEOMAN YARD			ERNS	
TAMPA	9002940	NORTH OF 275			ERNS	
TAMPA	9001875	HIMES AND COLUMBUS			ERNS	
TAMPA	93001510	4700 WHITEWAY DR.			ERNS	
TAMPA	94254708	3701 CAUSEWAY BLVD			ERNS	
TAMPA	9202434	RESIDENCE-161 GROVE ST			ERNS	
TAMPA	8705033	TRANSUS TRUCKING CO. 9801 PALM RIVER RD.			ERNS	
TAMPA	8701952	800 BLOCK WEST BRADDOCK AND ALFRED			ERNS	
TAMPA	8806268	I-4 AT 36TH STREET WEST BOUND LANES			ERNS	
TAMPA	8905286	GARDINIER FERTILIZER PLANT			ERNS	
TAMPA	8911109	22ND STREET OF BUFFALO AVENUE			ERNS	
TAMPA	8911118	ADAMS & 50TH STREET			ERNS	
TAMPA	8911094	SAN PADREO STREET AND CHURCH AVENUE			ERNS	
TAMPA	8904757	SAN PADRO ST AND CHURCH AVE			ERNS	
TAMPA	8911063	NORTH WEST SHORE BOULEVARD AND WEST GRA			ERNS	
TAMPA	93000920	ROCK PORT			ERNS	
TAMPA	95010228				HMIRS	
TAMPA	8800753	15746 GARDENSIDE LN			ERNS	
TAMPA	8804062	AL LOPEZ STADIUM			ERNS	
TAMPA	94215061				ERNS	
TAMPA	94257720	TOWN AND COUNTRY 6707 LEEWARD ISLAND WAY			ERNS	
TAMPA	8705439	CORK RD AND THONOASSASSO RD			ERNS	
TAMPA	8704914	40TH ST AND 21ST AVE			ERNS	
TAMPA	8701807	INTERSECTION OF GUNN HWY AND HENDERSON RI			ERNS	
TAMPA	8702450	J.D. SMITH EXTERMINATORS			ERNS	
TAMPA	8901968	DALE MABRY EXIT RAMP ONTO BUSH BLVD			ERNS	
TAMPA	8705049	CAMELOT APARTMENTS			ERNS	
TAMPA	8700833	3000FT SOUTH OF RUNWAY 22			ERNS	
TAMPA	9200444	HWY 361			ERNS	
TAMPA	8705674	MACINTOSH RD AND US 301			ERNS	
TAMPA	8705671	NEBRASKA AVE AND BEARESS RD			ERNS	
TAMPA	94236234	YULMAN YARD			ERNS	
TAMPA	9110837	88 E HAMLIN ST EAST SHORE OF LAKE UNION			ERNS	
TAMPA	8800210	PARKING LOT OF AYRES DINER, CORNER OF DALE			ERNS	
		MAVRY RD AND GRAC				
TAMPA	92050480				HMIRS	
TAMPA	9200518	PO BOX 547			ERNS	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	94252488				ERNS	
TAMPA	8800445	ON HIWAY 674			ERNS	
TAMPA	9109740	2600 FEDERAL AVE			ERNS	
TAMPA	9108829	PO BOX 849 HWY 366 AND 32ND ST.			ERNS	
TAMPA	94247034	MANATEE PORT			ERNS	
TAMPA	8702464	NITRAN			ERNS	
TAMPA	8701693	TAMPA AIR PORT, NEAR POLICEMAN HANGER			ERNS	
TAMPA	9108869	1150 MURPHY AVE GROUND/PARKING LOT/SEWER			ERNS	
TAMPA	9106525	PLATFORM A			ERNS	
TAMPA	94272866	200 MILES OUT OF COZUMEL ENROUTE TO TAMPA			ERNS	
TAMPA	94267760	PEIR 251			ERNS	
TAMPA	94269396	5881 INGRAHAM			ERNS	
TAMPA	90020086				HMIRS	
TAMPA	94120774				HMIRS	
TAMPA	8703308	7512 PAULA DRIVE AND TOWN AND COUNTRY BLVD			ERNS	
TAMPA	94242206	TAMPA PORT AUTHORITY BERTH 227			ERNS	
TAMPA	94241873	INTERSTATE 4 EASTBOUND AT MILE 13-14			ERNS	
TAMPA	94263239	AMERADA HESS TERMINAL			ERNS	
TAMPA	94263238	ARMADA HESS CORP 504 NORTH 19TH STREET			ERNS	
TAMPA	94272690	AGRICO BIG BEN TERMINAL			ERNS	
TAMPA	94260843	PORT MANATEE			ERNS	
TAMPA	8705589	INTERSECTION OF STATE RD 39 AND SAM ALLUN			ERNS	
		RD, NE SECTION OF				
TAMPA	94266954	INTERSTATE 75 NORTHBOUND MILE MARKER 277			ERNS	
TAMPA	94266514	SADCO NO 220			ERNS	
TAMPA	94264027	ENROUTE FM PUERTO RICO TO TAMPA			ERNS	
TAMPA	94234604	CF INDUSTRIES AMMONIA TERMINAL 3222			ERNS	
		MARITIME BLVD				
TAMPA	95318546			33602	ERNS	
TAMPA	95318539			33602	ERNS	
TAMPA	95317009			33602	ERNS	
TAMPA	95315360			33602	ERNS	
TAMPA	95313273			33602	ERNS	
TAMPA	95312631			33602	ERNS	
TAMPA	95294931			33602	ERNS	
TAMPA	94251595	ROY JENKINS POOL 154 COLUMBIA DR			ERNS	
TAMPA	U001355079	BRINKS OF FL	1102 N "B" ST		UST, LUST	8627003
TAMPA	S100021008	WASTE MANAGMT INC HW TRANSFER STA	US301 / I-4		SWF/LF	
TAMPA	U001377986	COCA-COLA BOTTLING CO-TAMPA	13TH & YORK ST		UST, LUST	8626344
TAMPA	94020790		22ND ST CAUSEWAY		HMIRS	
TAMPA	90050311		22ND ST CAUSEWAY		HMIRS	
TAMPA	U001963249	FL DEPT OF TRANSPORTATION CROSSTOWN EX	39TH ST EASTBOUND EXIT RAMP		UST	299401656
TAMPA	U001045078	FL ROCK & TANK LINES	US 41 S		UST, LUST, AST	8519988
TAMPA	U001377984	MCKESSON CHEMICAL CO.	6051 HWY 41-A		UST	298625120
TAMPA	9106962	530 N. WITTER ST.	HWY 49		ERNS	
TAMPA	U001963247	FL DEPT OF TRANSPORTATION CROSSTOWN EX	50TH ST EASTBOUND EXIT RAMP		UST	299401651
TAMPA	U002217714	USE 9401651	50TH ST EASTBOUND EXIT RAMP		UST	299501714

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	U001963246	FL DEPT OF TRANSPORTATION-S CROSSTOWN	50TH ST WESTBOUND ENTRY RAMP		UST	299401649
TAMPA	U001378058	FL DEPT OF TRANSPORTATION	SR 580 - PIPER'S MARINE		UST, LUST	9102666
TAMPA	U001378030	CSX TRANSPORTATION INC-JACOB'S TRUCK	78TH ST		UST, LUST	9101415
TAMPA	9103256	7016 WINONA DRIVE	MP 84.5		ERNS	
TAMPA	94060625		S 86TH ST		HMIRS	
TAMPA	U001378113	ACCENT MARINE	10410 HWY 92 E		UST, LUST	9201893
TAMPA	1000735187	CONSUMER PRODUCTS INC	10824 US 92 E		FINDS	
TAMPA	S101011579	A & D RECYCLING TRANSFER STATION	7006 E 9TH AVE	33602	SWF/LF	
TAMPA	8901982	MARINA N OF SKYWAY BRIDGE,EAST OF I-275	ON A DOCK PILING		ERNS	
		BRIDGE				
TAMPA	1000931642	BEACH PARK PRIVATE SCH	4200 N A ST	33609	FINDS	
TAMPA	92080269		5100 ACLINE AVE		HMIRS	
TAMPA	92080115		5100 ACLINE AVE		HMIRS	
TAMPA	U001546606	DEROSE INDUSTRIES	8504 E ADAMO DR		UST, LUST	9103587
TAMPA	91040182		5056 ADAMS DR		HMIRS	
TAMPA	U001356163	NORTHWEST AIRLINES	AIRSIDE D TAMPA INTL AIRPORT	33607	UST, Ind Waste	299047054
TAMPA	1000412548	CONTINENTAL AIRLINES	AIRSIDE E TAMPA INTL AIRPORT	33607	RCRIS-SQG, FINDS	
TAMPA	91080614		ANDERSON RD		HMIRS	
TAMPA	S100990555	GARRISON CHANNEL	631 S ASHLEY ST		LUST	9301000
TAMPA	U001378037	BARNETT BANK BLDG-FORMER	2000 ASHLEY DR		UST, LUST	9101785
TAMPA	1000161395	NCNB TYPESETTING & COPY CENTER	400 N ASHLEY ST 16 FLOOR	33602	RCRIS-SQG, FINDS, UST	299045676
TAMPA	1000248424	DIXIE LIME & STONE COMPANY FL	ATTN V D CHAPNERKAR MKT MGR	33609	TSCA	
TAMPA	U002113431	ALL POINTS WAREHOUSE-OLD GAS STATION	4701 7TH AVE		UST, LUST	9501491
TAMPA	U001378101	USE 9201677	3001 NORTH BLVD		UST, LUST	9200783
TAMPA	1000243419	PATHOLOGISTS REFERENCE LAB	402 SOUTH BLVD	33606	RCRIS-SQG, FINDS	
TAMPA	S100020977	BOUGAINVILLEA TRASH LF	BOUGAINVILLEA / 46TH ST		SWF/LF	
TAMPA	U001355730	GENERAL RENT-A-CAR	4606 W BOY SCOUT BLVD	33607	UST, LUST	8837593
TAMPA	U001355309	J CLIFFORD MACDONALD CENTER	4304 W BOYSCOUT BLVD	33607	UST, LUST	8627987
TAMPA	U001354081	TEXACO #208-24-203-1332	2720 W BUFFALO AVE	33607	UST, LUST	8624821
TAMPA	94110828		41S CARGILL		HMIRS	
TAMPA	90020623		CAUSEWAY BLVD		HMIRS	
TAMPA	U001378008	TAMPA DOWNTOWN INVEST LTD PROPERTY	CITY BLK WASHINGTON N MORGAN W		UST, LUST	8943604
TAMPA	U001378083	CONTINENTAL AIRLINES RESERVATIONS	4101 W COLUMBUS DR		UST	299103404
TAMPA	90030513		COMMERCE BLVD		HMIRS	
TAMPA	S100563782	KASSOUF KIMMERLING/AKA TIMBERLAKE	NE COR 58 / COLUMBUS DR		SHWS	
TAMPA	S101137001	SIXTY-SECOND STREET DUMP	NW COR OF COLUMBUS / 62 ST		SHWS	
TAMPA	1000450177	XEROX CORP	5680 W CYPRESS SUITE A	33607	RCRIS-SQG, FINDS	
TAMPA	1000261528	ENVIRONMENTAL SCIENCE & ENGINEERING	5840 WEST CYPRESS ST SUITE A	33607	RCRIS-SQG, FINDS	
TAMPA	U001355241	CONTINENTAL BAKING CO	420 S DAKOTA AVE	33606	UST, LUST, AST	
TAMPA	U001378078	YOUR ATTIC	4510 S DALE MABRY AVE		UST	8627646
TAMPA	U001356342	FL GENERAL LINEN SUPPLY	324 N DALE MABRY	33609	UST	299103154
TAMPA	U001355881	TIME CUSTOMER SERVICE INC	1 N DALE MABRY	33609	UST	299102226
TAMPA	1000906108	ALLIED TIRE SALES INC #28	3603 S DALE MABRY	33609	RCRIS-SQG, FINDS	298842140
TAMPA	1000497987	POOL SHACK	3222 S DALE MABRY	33609	FINDS	
TAMPA	1000248802	ALLIED TIRE SALES INC	3643 S DALE MABRY	33609	RCRIS-SQG, FINDS	
TAMPA	1000222695	FIRESTONE	1205 S DALE MABRY	33609	RCRIS-SQG, FINDS	
TAMPA	1000333237	JERRY ULM DODGE	2966 N DALE MABRY HWY	33607	RCRIS-SQG, FINDS	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	90030047	HILLSBOROUGH CNTY HOSP AUTH DBA TAMPA GEN HSP	DAVIS ISLAND		HMIRS	
TAMPA	1000732921	JEWISH CENTER TOWERS INC	DAVIS ISLAND	33606	FINDS	
TAMPA	U001544419	TAMPA INTERNATIONAL AIRPORT EAST SIDE OF AIRPORT	3001 DELEON ST		UST, LUST	9301024
TAMPA	8802523		DELTA MAINTENANCE HANGAR		ERNS	
TAMPA	94091101	EDWARD DOROUGH SITE	6 DOING RACK		HMIRS	
TAMPA	S101547649	CHEVRON #48083	1806 DOWNING CIR		SHWS	
TAMPA	U001353965	REDWING CARRIERS INC	2735 W DR MARTIN LUTHER KING JR	33607	UST, LUST	8509058
TAMPA	U001378041	TAMPA CITY-S REGIONAL PARKING FACILITY	ELLA MAE ST		UST	239101830
TAMPA	U001378026	TAMPA PORT AUTHORITY-GARRISON CHANNEL	1301 ELLA MAE ST		UST	239100404
TAMPA	U001378110	TWIN LAKES	E END OF BLOOMINGDALE AVE		UST, LUST	9201835
TAMPA	U002217727		ERLICH & HUTCHENSON		HMIRS	9502111
TAMPA	91090759	ELI WITT CO	EUNICE		UST, LUST	9101430
TAMPA	U001378033	NORTHEAST HILLSBOROUGH LF	EUREKA SP RD / HAMILTON RD		SWF/LF	
TAMPA	S100020986	FALKENBURG RD YARD TRASH PROCESSING	FALKENBURG RD, 1MI N SR-60		SWF/LF	
TAMPA	S100300529	DUTCH HARBOR MAGONE MARINE SERVICE	FALLS		ERNS	
TAMPA	9106432	HILLS COUNTY WASTE-TO-ENERGY PLANT	210 FAULKENBURG RD		SWF/LF	
TAMPA	S100020982	CRAFTSMAN ROOFERS	4704 N FL AVE		UST, LUST	9301008
TAMPA	U001544418	RENFROE PROPERTY	9402 E FOWLER AVE		UST	299100524
TAMPA	U001378027	COLONY SHOPS OF FL INC	3415 E FRONTAGE RD	33607	UST, LUST	9063924
TAMPA	U000136451	AUTHORIZED APPLIANCE RECLAIMING CTR	2420 GELMAN PLACE, 5MI E US41		SWF/LF	
TAMPA	S101011580	HILLSBOROUGH CNTY SCHOOL BD-FURNITURE	1801 N HABANA & UNION		UST, LUST	8736478
TAMPA	U001377993	BUCCANEER POOL SUPPLY & SERVIC	3648A HENDERSON BLVD		FINDS	
TAMPA	1000498182	STERLING CLEANERS	3710 HENDERSON AVE	33609	FINDS	
TAMPA	1000735829	MOBIL OIL CORP SS# A67	902 E HILLSBORO AVE	33602	FINDS	
TAMPA	1000737480	DISCOUNT TIRE TOWN	701 HILLSBOROUGH AVE	33606	FINDS, UST, LUST	8625031
TAMPA	U001378035	EXXON #4-0490	11292 HILLSBOROUGH BLVD		UST, LUST	9101815
TAMPA	U001546669	TAMPA UNKNOWN SPILL	HILLSBOROUGH COUNTY		UST	299102024
TAMPA	1000344927	HILLSBOROUGH RIVER ABANDONED D	HILLSBOROUGH COUNTY		CERCLIS, FINDS	
TAMPA	1000292187		HOOKERS POINT	33602	CERCLIS, FINDS	
TAMPA	91070743	U S VIGGO INC	4700 N HOOVER BLVD		HMIRS	
TAMPA	94120986	KWIK PEP STATION	7906 HOPI PLACE	33607	FINDS	
TAMPA	1000734634	HUMBLE OIL CORP	US HWY 301 N & ALONZO RD	33606	UST, LUST	9100288
TAMPA	U001356211	TAMPA CITY-FIRE STATION #19	4916 INGRAM		UST, LUST	9101724
TAMPA	U001378036	HALL OF FAME INN-GOLF COURSE MAINT	INTERBAY AND DALE MABRY	33602	UST, LUST	8842519
TAMPA	U001355929	REDWING CARRIERS FUEL SPILL	INTERNATIONAL PLAZA		HMIRS	
TAMPA	90020271	DAVE MITCHELL'S GRAND CENTRAL GARAGE	INTERSECTION EISENHOWER BLVD & FL S.R. 6	33607	FINDS, CERC-NFRAP	8627185
TAMPA	U001355133	PORT OF BEAUMONT CARROL ST. WHARF	1901 W. JF KENNEDY BLVD	33606	UST, LUST	9201715
TAMPA	1000436895	SHERWIN WILLIAMS CO	ST. JOHN ST.		ERNS	
TAMPA	U001046264	1220 U.S. STATE ROAD 301 AT	4125 W JOHN F KENNEDY BLVD	33609	RCRIS-SQG, FINDS	
TAMPA	9100947	WAREHOUSE SUPPLY 813-621-3	JUST EAST OF TAMPA		ERNS	
TAMPA	1000497449	KINGSWAY RD LF (DAVID J JOSEPH)	KINGSWAY RD, 0.5MI N OF 14		SWF/LF	
TAMPA	8700298	PATHOLOGY ASSOC	5415 LAUREL BLVD	33607	RCRIS-SQG, FINDS	
TAMPA	S100020984					
TAMPA	1000335902					

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	U001354638	CIRCLE K #7470	6303 W LINEBAUGH AVE	33609	UST, LUST	8625419
TAMPA	S101716587	NORTHWEST HILLSBORO CLASS III LF	LINEBAUGH AVE. E OF SHELDON RD		SWF/LF	
TAMPA	S100020988	NORTHWEST HILLSBOROUGH SLF	LINEBAUGH AVE		SWF/LF	
TAMPA	S101011591	RECYCLED WOOD PRODUCTS COMPOST FAC	S LOIS AVE. .25MI N INTERBAY		SWF/LF	
TAMPA	U001356382	PALMA CEIA VILLAGE SHOPPING CTR	3225 MACDILL AVE	33606	UST, LUST	9200229
TAMPA	S101011588	OLD MANHATTAN AVE CLASS I LF	S MANAHATTAN AVE / RICHARDSON		SWF/LF	
TAMPA	1000699637	INTERPAK INC	6932 SOUTH MANHATTEN STREET		RCRIS-SQG	
TAMPA	9101545	OFF OF I-70 BOX BURGER LEASE	MARINA DR		ERNS	
TAMPA	U001378034	MARIANI ASPHALT PARCEL	MARITIME BLVD		UST, LUST	9101518
TAMPA	90080774		MARITIME BLVD		HMIRS	
TAMPA	91060740		8950 MARSLIN DR		HMIRS	
TAMPA	94051530		MARTIN LUTHER KING BLVD		HMIRS	
TAMPA	U001378107	GOOD SHEPHERD BAPTIST CHURCH INC	8119 E MARTIN LUTHER KING JR		UST, LUST	9201207
TAMPA	1000736103	TEXACO #242041342	3102 S MCDILL AVE	33606	FINDS	
TAMPA	U001378052	RISSER PETROLEUM TANKER SPILL	I-275 MILE MARKER 57		UST	299102311
TAMPA	94070231		14 MILE MARKER 13		HMIRS	
TAMPA	S100020990	NORTHWEST REGIONAL SLUDGE MGMT FAC	NEAR SHELDON RD / MOBLEY RD		SWF/LF	
TAMPA	U001355878	COMMERCE PLAZA	12811 N NEBRASKA AVE	33602	UST, LUST	8842069
TAMPA	U001356274	CSX TRANSPORTATION-UNION STATION	601 NEBRASKA AVE	33602	UST, LUST	9101044
TAMPA	1000344857	TAMPA ELECTRIC CO CENTRAL TEST	1898 NUCCIO PKY	33607	RCRIS-SQG, FINDS	
TAMPA	8802486	PAY-LESS SERVICE STATION	SOUTH OF COOPER'S POND APARTMENT BUILDING		ERNS	
TAMPA	S100021003	TECO COMPOSTING FACILITY	W OF SHELDON RD N OF WATERS AV		SWF/LF	
TAMPA	9105702	EAST LEVEE OF THE CHAIN OF ROCKS CANAL	OHIO RIVER MILE 241.5		ERNS	
TAMPA	U001378012	GTE OF FL OLDSMAR	12750 OLD MEMORIAL HWY		UST	299045723
TAMPA	90040283		OLD HOPEWELL RD		HMIRS	
TAMPA	1000498843	REED MINERALS	OLD HWY 41 & JENSEN		FINDS	
TAMPA	U001356447	HARBOR ISLAND	ONE HARBOUR PLACE #270		UST, LUST, AST	9202003
TAMPA	U001378105	SHELL STATION	8210 PARKEDGE DR	33602	UST	299201084
TAMPA	91080428		PENDOLA POINT RD		HMIRS	
TAMPA	91050674		PENDOLA POINT DRIVE		HMIRS	
TAMPA	1000497834	IDEAL BASIC IND	PENNDOLA POINT RD		FINDS	
TAMPA	1000344923	TAMPA TRIBUNE	1712 N PLATT	33602	FINDS	
TAMPA	1000740400	TECNUM	2411 PLYMOUTH RD		RCRIS-SQG, FINDS	
TAMPA	1000843480	GENERAL SERVICES ADMINISTRATION	501 E POLK ST ROOM 600	33602	FINDS	
TAMPA	U001378002	GRACE, W.R.	PORT SUTTON RD	33602	FINDS	
TAMPA	8905271	IMC TERMINAL	PORT SUTTON AREA		UST	298840906
TAMPA	92100051		PORT TAMPA		ERNS	
TAMPA	8805677	MP AZA886.9	POWELL MEADOW SUBDIVISION		HMIRS	
TAMPA	U001379124	HUMANA GAS STATION	SEMINOLE BLVD / BLOSSOM LAKE DR		ERNS	
TAMPA	8910558	SHELDON RD. SUBSTATION	SHELDON RD. AND LINEBAUGH AVE.		UST, LUST	9103454
TAMPA	8805616		SHELL TERMINAL		ERNS	
TAMPA	1000859667	PEERLESS PUMP	505 W SHERILL	33609	RCRIS-SQG	
TAMPA	1000843292	PEERLESS PUMP	505 N SHERILL	33609	FINDS	
TAMPA	U001378011	TAMPA, CITY-NW REPUMP STATION	5602 SITKA		UST, AST	298945433
TAMPA	U001356092	VALUE RENT-A-CAR	5202/5210 SPRUCE ST	33607	UST, LUST	9045619
TAMPA	U001355159	ALAMO RENT-A-CAR	5124 W SPRUCE ST	33607	UST, LUST	8627265

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	U001354879	ENTERPRISE RENT A CAR	4912 W SPRUCE ST	33607	UST, LUST	8625673
TAMPA	U001354876	CENTRAL TRUCK LINES	3902 W SPRUCE ST	33607	UST, LUST	8625670
TAMPA	U001354812	ALAMO RENT-A-CAR #030	5402 W SPRUCE ST	33607	UST, LUST	8625604
TAMPA	U001354138	DOLLAR RENT-A-CAR	4720 W SPRUCE ST	33607	UST, LUST	8624882
TAMPA	U001378122	CENTRAL SOD & LANDSCAPING	4419 SOUTH ST	33607	UST, LUST	9202389
TAMPA	95020737		14516 22ND ST SKIPPER RD		HMIRS	
TAMPA	U001378024	USE 298841046	N TAMPA ST		UST, LUST	9100014
TAMPA	U002313169	DELTA AIR LINES AIRSIDES	TAMPA INTERNATIONAL AIRPORT	33607	UST, LUST, AST	8625408
TAMPA	S101264751	TAMPA CITY-AIRPORT PUMPING STATION	4450 S TAMPA AIRPORT BLVD	33607	LUST, AST	8841127
TAMPA	1000687596	AMERICAN AIRLINES	TAMPA INTL AIRPORT AIRSIDE E	33607	RCRIS-SQG, FINDS	
TAMPA	U001545547	PIONEER PROPERTIES ASSOCIATES, LTD	100 TAMPA ST	33602	UST, LUST	8942888
TAMPA	1000821146	HYATT REGENCY TAMPA	2 TAMPA CITY CENTER	33602	RCRIS-SQG, FINDS	
TAMPA	8705675	8401 N. HWY 301	TEXACO GAS STATION		ERNS	
TAMPA	8703010	1333 W. BRANDEN BLVD	THE PATO SHOP BEHIND ABOVE ADDRESS		ERNS	
TAMPA	9108492	140 SILVESTER RD.	ON THE JAMES RIVER		ERNS	
TAMPA	U001544411	VETERANS EXHWY ROW SITES	NORTH TO SOUTH TO TAMPA		UST	299300656
TAMPA	92110135		4537 TRANSPORT DR		HMIRS	
TAMPA	94030979		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92070317		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91030415		4537 TRANSPORT DR		HMIRS	
TAMPA	92060357		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	93010192		4537 TRANSPORT DR		HMIRS	
TAMPA	92070304		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	90070446		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	U001545548	COURIER DISPATCH	4111 TRASK AVE		UST, LUST	8942841
TAMPA	1000700432	CONSUMER PRODUCTS INC	10824 US92E		RCRIS-SQG	
TAMPA	S100563798	UNIVERSAL DOOR / DOT LF	VETERANS EXPWY @ BENJAMIN RD		SWFLF	
TAMPA	S101136987	PEAK OIL/BAY DRUM	1/4 MI W OF FAULKENBERG RD, S OF SR 574		SHWS	
TAMPA	U001378016	BUDGET RENT A CAR	1110 N WEST SHORE BLVD		UST, LUST	9046115
TAMPA	92110055		WESTSHORE BLVD. & TYSON ST		HMIRS	
TAMPA	1000738722	OKLAHOMA-INSTALLATION CO	347 WESTSHORE PLAZA		FINDS	
TAMPA	U001356392	EMBASSY HOTEL	555 WESTSHORE BLVD	33609	FINDS	
TAMPA	S100020989	NORTHWEST HILLSBOROUGH TRANSFER STA	WILSKY RD / LINEBAUGH AVE	33602	UST, LUST, AST	9200540
TAMPA	92040092		YARD		SWFLF	
TAMPA	95318564			33602	HMIRS	
TAMPA					ERNS	

EPA Waste Codes Addendum

Code	Description
D000	NOT DEFINED
D001	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
D002	A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
D003	A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.
D004	ARSENIC
D005	BARIUM
D006	CADMIUM
D007	CHROMIUM
D008	LEAD
D009	MERCURY
D011	SILVER
D018	BENZENE
D035	METHYL ETHYL KETONE
D039	TETRACHLOROETHYLENE
F001	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F002	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

EPA Waste Codes Addendum

Code	Description
	CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F003	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F004	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: CRESOLS AND CRESYLIC ACID, AND NITROBENZENE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F005	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F006	WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.
NONE	NONE
U002	ACETONE (I)
U002	2-PROPANONE (I)
U122	FORMALDEHYDE
U154	METHANOL (I)
U154	METHYL ALCOHOL (I)
U161	METHYL ISOBUTYL KETONE (I)
U161	4-METHYL-2-PENTANONE (I)

EPA Waste Codes Addendum

Code	Description
------	-------------

U161	PENTANOL, 4-METHYL-
------	---------------------

U239	BENZENE, DIMETHYL- (I,T)
------	--------------------------

U239	XYLENE (I)
------	------------