

# **The EDR Corridor Study Report**

**Study Area 2 & 4  
I-275 / 31st Street  
Tampa, Florida**

**April 10, 1996**

**Inquiry number 48312**



**Environmental  
Data  
Resources, Inc.**

Creators of Toxicheck/®

## ***The Source For Environmental Risk Management Data***

3530 Post Road  
Southport, Connecticut 06490

**Nationwide Customer Service**

Telephone: 1-800-352-0050

Fax: 1-800-231-6802

***Thank you for your business.***  
Please contact EDR at 1-800-352-0050  
with any questions or comments.

**Disclaimer**

This Report contains information obtained from a variety of public sources and EDR makes no representation or warranty regarding the accuracy, reliability, quality, or completeness of said information or the information contained in this report. The customer shall assume full responsibility for the use of this report.

**No warranty of merchantability or of fitness for a particular purpose, expressed or implied, shall apply and EDR specifically disclaims the making of such warranties. In no event shall EDR be liable to anyone for special, incidental, consequential or exemplary damages.**

## GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

**Elapsed ASTM days:** Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

### FEDERAL ASTM RECORDS:

**CERCLIS:** Comprehensive Environmental Response, Compensation, and Liability Information System

Source: EPA/NTIS

Telephone: 703-603-8904

CERCLIS: CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 11/30/95

Date Made Active at EDR: 02/26/96

Date of Data Arrival at EDR: 01/15/96

Elapsed ASTM days: 42

**ERNS:** Emergency Response Notification System

Source: EPA/NTIS

Telephone: 202-260-2342

ERNS: Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/95

Date Made Active at EDR: 02/19/96

Date of Data Arrival at EDR: 01/26/96

Elapsed ASTM days: 24

**NPL:** National Priority List

Source: EPA

Telephone: 703-603-8852

NPL: National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, it is EDR's policy to plot NPL sites greater than approximately 500 acres in size as areas (polygons). Sites smaller in size are point-geocoded at the site's address.

Date of Government Version: 09/01/95

Date Made Active at EDR: 10/25/95

Date of Data Arrival at EDR: 10/17/95

Elapsed ASTM days: 8

**RCRIS:** Resource Conservation and Recovery Information System

Source: EPA/NTIS

Telephone: 703-308-7907

RCRIS: Resource Conservation and Recovery Information System. RCRIS includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Date of Government Version: 10/31/95

Date Made Active at EDR: 01/12/96

Date of Data Arrival at EDR: 12/15/95

Elapsed ASTM days: 28

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## FEDERAL NON-ASTM RECORDS:

### **CONSENT:** Superfund (CERCLA) Consent Decrees

Source: EPA Regional Offices

Telephone: Varies

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: Varies

Date of Next Scheduled Update: 09/01/95

### **CORRACTS:** Corrective Action Report

Source: EPA

Telephone: 703-308-7907

CORRACTS: CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 04/10/95

Date of Next Scheduled Update: 06/17/96

### **FINDS:** Facility Index System

Source: EPA/NTIS

Telephone: 800-908-2493

FINDS: Facility Index System. FINDS contains both facility information and "pointers" to other sources that contain more detail. These include: RCRIS, PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS (FIFRA/TSCA Tracking System)), CERCLIS, DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), FRDS (Federal Reporting Data System), SIA (Surface Impoundments), CICIS (TSCA Chemicals in Commerce Information System), PADS, RCRA-J (medical waste transporters/disposers), TRIS and TSCA.

Date of Government Version: 09/30/95

Date of Next Scheduled Update: 07/08/96

### **HMIRS:** Hazardous Materials Information Reporting System

Source: U.S. Department of Transportation

Telephone: 202-366-4555

HMIRS: Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/95

Date of Next Scheduled Update: 07/29/96

### **MLTS:** Material Licensing Tracking System

Source: Nuclear Regulatory Commission

Telephone: 301-415-7169

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/01/95

Date of Next Scheduled Update: 07/15/96

### **NPL LIENS:** Federal Superfund Liens

Source: EPA

Telephone: 205-564-4267

NPL LIENS: Federal Superfund Liens. Under the authority granted the USEPA by the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner receives notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/91

Date of Next Scheduled Update: 05/27/96

### **PADS:** PCB Activity Database System

Source: EPA

Telephone: 202-260-3992

PADS: PCB Activity Database. PADS identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 10/14/94

Date of Next Scheduled Update: 05/20/96



## GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

**RAATS:** RCRA Administrative Action Tracking System

Source: EPA

Telephone: 202-564-4104

RAATS: RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA.

Date of Government Version: 04/17/95

Date of Next Scheduled Update: 06/17/96

**ROD:** Records Of Decision

Source: NTIS

Telephone: 703-416-0703

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 03/31/95

Date of Next Scheduled Update: 06/17/96

**TRIS:** Toxic Chemical Release Inventory System

Source: EPA/NTIS

Telephone: 202-260-2320

TRIS: Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/92

Date of Next Scheduled Update: 07/01/96

**TSCA:** Toxic Substances Control Act

Source: EPA/NTIS

Telephone: 202-260-1444

TSCA: Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site. USEPA has no current plan to update and/or re-issue this database.

Date of Government Version: 01/31/95

Date of Next Scheduled Update: 06/17/96

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## STATE OF FLORIDA ASTM RECORDS:

### LUST: PCT01 - Petroleum Contamination Detail Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

LUST: Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 01/23/96

Date Made Active at EDR: 03/25/96

Date of Data Arrival at EDR: 02/12/96

Elapsed ASTM days: 42

### SHWS: Florida's State-Funded Action Sites

Source: Department of Environmental Protection

Telephone: 904-488-0190

SHWS: State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 08/24/95

Date Made Active at EDR: 09/13/95

Date of Data Arrival at EDR: 09/05/95

Elapsed ASTM days: 8

### SWF/LS: Facility Directory (Solid Waste Facilities)

Source: Department of Environmental Protection

Telephone: 904-922-7121

SWF/LS: Solid Waste Facilities/Landfill Sites. SWF/LS type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Section 2004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 01/16/96

Date Made Active at EDR: 03/01/96

Date of Data Arrival at EDR: 02/05/96

Elapsed ASTM days: 25

### UST: STI02 - Facility/Owner/Tank Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

UST: Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 01/23/96

Date Made Active at EDR: 03/14/96

Date of Data Arrival at EDR: 02/12/96

Elapsed ASTM days: 31

## STATE OF FLORIDA NON-ASTM RECORDS:

### AST: STI02 - Facility/Owner/Tank Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

AST: Registered Aboveground Storage Tanks.

Date of Government Version: 01/23/96

Date of Next Scheduled Update: 05/06/96

### CATTLE DIPPING VATS: Cattle Dipping Vats

Source: Department of Environmental Protection

Telephone: 904-488-3601

Date of Government Version: 05/01/94

Date of Next Scheduled Update: 05/20/96

### FL SITES: Sites List

Source: Department of Environmental Protection

Telephone: 904-922-7121

Date of Government Version: 12/31/89

Date of Next Scheduled Update: N/A

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## FLORIDA COUNTY RECORDS

### DADE COUNTY:

#### Dade County Storage Tanks

Source: Department of Environmental Resource Management  
Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Enforcement Case Tracking System

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Industrial Waste Type 2-4

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Facilities which generate, dispose of, store, use, discharge, handle or reclaim any liquid waste other than domestic sewage, any hazardous waste or any hazardous material (except factory prepackaged products intended primarily for domestic use or consumption).

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Industrial Waste Type 5

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Facilities which generate, dispose of, store, use, discharge, handle or reclaim any liquid waste other than domestic sewage, any hazardous waste or any hazardous material (except factory prepackaged products intended primarily for domestic use or consumption).

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

#### Industrial Waste Type 6

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Sites located on a septic tank inside a well field protection area.

Date of Government Version: 11/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Industrial Waste Permit

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Date of Government Version: 11/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Air Permit

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Date of Government Version: 11/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Fuel Spill Cases

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

## GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

### Dade County Hazardous Waste

Source: Department of Environmental Resources Management

Telephone: 305-372-6755

Sites with documented soil or groundwater contamination.

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

### BROWARD COUNTY:

#### Broward County Storage Tanks

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

Date of Government Version: 08/12/94

Date of Next Scheduled Update: 06/10/96

#### Early Detection Incentive

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

EDI sites are leaking underground petroleum tanks covered under the state cleanup program.

Date of Government Version: 01/01/96

Date of Next Scheduled Update: 06/10/96

#### Environmental Assessment

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

EA sites are contaminated sites (non-leaking underground petroleum tanks) under the state cleanup program.

Date of Government Version: 01/01/96

Date of Next Scheduled Update: 06/10/96

#### Hazmat

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

HM sites use or store greater than 25 gallons of hazardous materials per month.

Date of Government Version: 01/01/96

Date of Next Scheduled Update: 06/10/96

#### Notice Of Violation

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

Date of Government Version: 08/12/94

Date of Next Scheduled Update: 06/10/96

### ESCAMBIA COUNTY:

#### Facility/Owner/Tank/Contamination Information Report

Source: Environmental Health Services

Telephone: 904-444-8990

Date of Government Version: 02/05/96

Date of Next Scheduled Update: 05/06/96

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## Historical and Other Database(s)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

**Former Manufactured Gas (Coal Gas) Sites:** The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

## Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

### **DELISTED NPL:** Delisted NPL Sites

Source: EPA

Telephone: 703-603-8769

DELISTED NPL: The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425(e), sites may be deleted from the NPL where no further response is appropriate.

### **NFRAP:** No Further Remedial Action Planned

Source: EPA/NTIS

Telephone: 703-416-0702

NFRAP: As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

### **FRDS:** Federal Reporting Data System

Source: EPA/Office of Drinking Water

Telephone: 202-260-2805

FRDS provides information regarding public water supplies and their compliance with monitoring requirements, maximum contaminant levels (MCL's), and other requirements of the Safe Drinking Water Act of 1986.

**Area Radon Information:** The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

**Oil/Gas Pipelines/Electrical Transmission Lines:** This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines and electrical transmission lines.

**Sensitive Receptors:** There are individuals who, due to their fragile immune systems, are deemed to be especially sensitive to environmental discharges. These typically include the elderly, the sick, and children. While the exact location of these sensitive receptors cannot be determined, EDR indicates those facilities, such as schools, hospitals, day care centers, and nursing homes, where sensitive receptors are likely to be located.

## GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

**USGS Water Wells:** In November 1971 the United States Geological Survey (USGS) implemented a national water resource information tracking system. This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on more than 900,000 wells, springs, and other sources of groundwater.

**Flood Zone Data:** This data, available in select counties across the country, was obtained by EDR in 1994 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

**Epicenters:** World earthquake epicenters, Richter 5 or greater  
Source: Department of Commerce, National Oceanic and Atmospheric Administration

**Water Dams:** National Inventory of Dams  
Source: Federal Emergency Management Agency  
Telephone: 202-646-2801  
WATER DAMS: National computer database of more than 74,000 dams maintained by the Federal Emergency Management Agency.

**Wetlands Data:** This data was obtained by EDR from the National Wetlands Inventory (NWI) in 1994. Data depicts wetland areas as defined by NWI.

**State of Florida Water Well and Sample Database**  
Source: FL Department of Environmental Protection, Groundwater Quality Monitoring

**St. Johns River District Well Data**  
Source: St. Johns River Water Management District

**Southwest District Water Use Data**  
Source: Southwest Water Management District

**Well Construction Permitting System:** Water Well Locations in Northwest Florida Water Management District  
Source: Northwest Florida Water Management District  
Telephone: 904-539-5999

**Florida Sinkholes**  
Source: Department of Environmental Protection, Geological Survey  
The sinkhole data was gathered by the Florida Sinkhole Research Institute, University of Florida.

# MAP FINDINGS SUMMARY

<u>Database</u>	<u>Total Plotted</u>
NPL	0
Delisted NPL	0
RCRIS-TSD	1
State Haz. Waste	1
CERCLIS	1
CERC-NFRAP	2
CORRACTS	0
State Landfill	3
LUST	60
UST	102
AST	23
RAATS	0
RCRIS Sm. Quan. Gen.	42
RCRIS Lg. Quan. Gen.	4
HMIRS	1
PADS	0
ERNS	1
FINDS	72
TRIS	2
NPL Liens	0
TSCA	0
MLTS	0
Florida Sites	3
Florida Enforcement	0
Florida Ind. Waste	0
Env. Assessment	0
Florida Cattle	0
FL Haz. Mat.	0
FL Notice of Viol.	0
FL Air Permit	0
Industrial Waste Permits	0
ROD	0
CONSENT	0
Coal Gas	0

\* Sites may be listed in more than one database

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

Coal Gas Site Search: No site was found in a search of Real Property Scan's ENVIROHAZ database.

1

**TERRY CRAMER & SONS**  
**6201 N NEBRASKA AVE**  
**TAMPA, FL 33604**

**RCRIS-SQG 1000821147**  
**FINDS FLD984240606**  
**UST**  
**LUST**

## RCRIS:

Owner: JIM MURPHY  
(813) 238-8451

Contact: JIM MURPHY  
(813) 238-8451

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D006	.00000 (T)	Notification	D007	.00000 (T)	Notification
D008	.00000 (T)	Notification	D018	.00000 (T)	Notification
D039	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TERRY CRAMER & SONS (Continued)

1000821147

### LUST:

Facility ID:	8943017	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	CRAMER & SONS INC, TERRY		
Telephone:	8132388451	Discovery Date:	06/30/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TERRY CRAMER & SONS (Continued)

1000821147

### UST:

Facility ID:	298943017	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	CRAMER & SONS INC,TERRY		
Contact:	Not reported	Facility Phone:	8132388451
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890131	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TERRY CRAMER		
Owner:	TERRY CRAMER & SONS INC		
	13815 LAKE VILLAGE PL		
	TAMPA, FL 336244414		
Owner's Phone:	8132388451	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

1

FANCY NANCY'S LIMOUSINE SERVICE  
6201 N NEBRASKA AVE  
TAMPA, FL 33604

UST

U001355391  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FANCY NANCY'S LIMOUSINE SERVICE (Continued)

U001355391

### UST:

Facility ID:	298732408	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NANCY KRAMER		
Contact:	Not reported	Facility Phone:	8132388451
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870413	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	CHARTER MARKETING CO. P O BOX 4726 JACKSONVILLE, FL 32232		
Owner's Phone:	9043507737	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FANCY NANCY'S LIMOUSINE SERVICE (Continued)

U001355391

Facility ID:	298732408	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NANCY KRAMER		
Contact:	Not reported	Facility Phone:	8132388451
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870413	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	CHARTER MARKETING CO. P O BOX 4726 JACKSONVILLE, FL 32232		
Owner's Phone:	9043507737	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink, Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FANCY NANCY'S LIMOUSINE SERVICE (Continued)

U001355391

Facility ID:	298732408	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NANCY KRAMER		
Contact:	Not reported	Facility Phone:	8132388451
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870413	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	Not reported		
Owner:	CHARTER MARKETING CO. P O BOX 4726 JACKSONVILLE, FL 32232		
Owner's Phone:	9043507737	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FANCY NANCY'S LIMOUSINE SERVICE (Continued)

U001355391

Facility ID:	298732408	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NANCY KRAMER		
Contact:	Not reported	Facility Phone:	8132388451
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870413	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	Not reported		
Owner:	CHARTER MARKETING CO. P O BOX 4726 JACKSONVILLE, FL 32232		
Owner's Phone:	9043507737	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FANCY NANCY'S LIMOUSINE SERVICE (Continued)

U001355391

Facility ID:	298732408	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NANCY KRAMER		
Contact:	Not reported	Facility Phone:	8132388451
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870413	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	Not reported		
Owner:	CHARTER MARKETING CO. P O BOX 4726 JACKSONVILLE, FL 32232		
Owner's Phone:	9043507737	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

1

VANCES ALIGNMENT  
6200 N NEBRASKA AVE  
TAMPA, FL 33604

UST  
LUST

U001356328  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## VANCES ALIGNMENT (Continued)

U001356328

### LUST:

Facility ID:	9101764	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132382777	Discovery Date:	03/23/91
Tracking Number:	Not reported	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## VANCES ALIGNMENT (Continued)

U001356328

### UST:

Facility ID:	299101764	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VANCE, EDWARD		
Contact:	Not reported	Facility Phone:	8132382777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910412	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	VANCE, EDWARD		
Owner:	VANCE, EDWARD		
	6200 N NEBRASKA AVE		
	TAMPA, FL 336046257		
Owner's Phone:	8132382777	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## VANCES ALIGNMENT (Continued)

U001356328

Facility ID:	299101764	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VANCE, EDWARD		
Contact:	Not reported	Facility Phone:	8132382777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910412	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	VANCE, EDWARD		
Owner:	VANCE, EDWARD		
	6200 N NEBRASKA AVE		
	TAMPA, FL 336046257		
Owner's Phone:	8132382777	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## VANCES ALIGNMENT (Continued)

U001356328

Facility ID:	299101764	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VANCE, EDWARD		
Contact:	Not reported	Facility Phone:	8132382777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910412	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	VANCE, EDWARD		
Owner:	VANCE, EDWARD		
	6200 N NEBRASKA AVE		
	TAMPA, FL 336046257		
Owner's Phone:	8132382777	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## VANCES ALIGNMENT (Continued)

U001356328

Facility ID:	299101764	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VANCE, EDWARD		
Contact:	Not reported	Facility Phone:	8132382777
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910412	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	VANCE, EDWARD		
Owner:	VANCE, EDWARD		
	6200 N NEBRASKA AVE		
	TAMPA, FL 336046257		
Owner's Phone:	8132382777	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

2

TAMPA,CITY-DPW FLEET MAINT.-FIRE #7  
6129 N NEBRASKA AVE  
TAMPA, FL 33604

UST

U001354369  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT.-FIRE #7 (Continued)

U001354369

### UST:

Facility ID:	298625131	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA FIRE DEPT.		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT		
	808 E ZACK ST		
	TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT.-FIRE #7 (Continued)

U001354369

Facility ID:	298625131	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA FIRE DEPT.		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT		
	808 E ZACK ST		
	TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

3	TEXACO #242041320 5921 N NEBRASKA AVE TAMPA, FL 32794	FINDS	1000735997 FLD984172494
3	DRAKE PROPERTY 5921 N NEBRASKA AVE TAMPA, FL 33604	UST LUST AST	U001354793 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DRAKE PROPERTY (Continued)

U001354793

### LUST:

Facility ID:	8625581	Facility Type:	RETAIL STATION
Alias Name:	TEXACO #142		
Telephone:	Not reported	Discovery Date:	12/30/87
Tracking Number:	292413	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN	Est. Gallons Lost:	UNKNOWN
------------	---------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	OTHER
Incident Ineligible Description:	OTHER

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DRAKE PROPERTY (Continued)

U001354793

### UST:

Facility ID:	298625581	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID R DRAKE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ANGIE STORCH		
Owner:	TEXACO REFINING & MARKETING INC. P.O.BOX 20734 ORLANDO, FL 32814		
Owner's Phone:	3058946411	Tracking #:	292413
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DRAKE PROPERTY (Continued)

U001354793

Facility ID:	298625581	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID R DRAKE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	ANGIE STORCH		
Owner:	TEXACO REFINING & MARKETING INC. P.O.BOX 20734 ORLANDO, FL 32814		
Owner's Phone:	3058946411	Tracking #:	292413
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Cath prot-sac anode		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## DRAKE PROPERTY (Continued)

U001354793

Facility ID:	298625581	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID R DRAKE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ANGIE STORCH		
Owner:	TEXACO REFINING & MARKETING INC. P.O.BOX 20734 ORLANDO, FL 32814		
Owner's Phone:	3058946411	Tracking #:	292413
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DRAKE PROPERTY (Continued)

U001354793

Facility ID:	298625581	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID R DRAKE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	ANGIE STORCH		
Owner:	TEXACO REFINING & MARKETING INC. P.O.BOX 20734 ORLANDO, FL 32814		
Owner's Phone:	3058946411	Tracking #:	292413
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Cath prot-sac anode		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DRAKE PROPERTY (Continued)

U001354793

Facility ID:	298625581	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID R DRAKE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ANGIE STORCH		
Owner:	TEXACO REFINING & MARKETING INC. P.O.BOX 20734 ORLANDO, FL 32814		
Owner's Phone:	3058946411	Tracking #:	292413
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DRAKE PROPERTY (Continued)

U001354793

Facility ID:	298625581	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID R DRAKE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	ANGIE STORCH		
Owner:	TEXACO REFINING & MARKETING INC. P.O.BOX 20734 ORLANDO, FL 32814		
Owner's Phone:	3058946411	Tracking #:	292413
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Cath prot-sac anode		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

### AST:

Facility ID:	298625581	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID R DRAKE		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ANGIE STORCH		
Owner:	TEXACO REFINING & MARKETING INC. P.O.BOX 20734 ORLANDO, FL 32814		
Owner's Phone:	3058946411	Tracking #:	292413
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Completed	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000575
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

4

QUALITY AUTO PAINTING  
5910 N FLORIDA AVE  
TAMPA, FL 33604

RCRIS-SQG 1000287015  
FINDS FLD982169062

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## QUALITY AUTO PAINTING (Continued)

1000287015

RCRIS:

Owner: RAY MORRIS  
(813) 238-7223

Contact: RAY MORRIS  
(813) 238-7223

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

5 7-ELEVEN FOOD STORE #10343  
5701 N NEBRASKA AVE  
TAMPA, FL 33604

UST  
LUST

U001353859  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## 7-ELEVEN FOOD STORE #10343 (Continued)

U001353859

### LUST:

Facility ID:	8508889	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	4072950979	Discovery Date:	09/07/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	CONTAMINATION ASSESSMENT REPORT
Extension Status:	APPROVED
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## 7-ELEVEN FOOD STORE #10343 (Continued)

U001353859

### UST:

Facility ID:	298508889	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	WILLO SMITH		
Contact:	Not reported	Facility Phone:	4072950979
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLO SMITH		
Owner:	SOUTHLAND CORP 1304 LEE RD ORLANDO, FL 32810		
Owner's Phone:	4072950979	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## 7-ELEVEN FOOD STORE #10343 (Continued)

U001353859

Facility ID:	298508889	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	WILLO SMITH		
Contact:	Not reported	Facility Phone:	4072950979
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLO SMITH		
Owner:	SOUTHLAND CORP		
	1304 LEE RD		
	ORLANDO, FL 32810		
Owner's Phone:	4072950979	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

6

**BRADYS AUTO SALES INC**  
**5701 N FLORIDA AVE**  
**TAMPA, FL 33604**

**UST**  
**LUST**

**U001356439**  
**N/A**

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BRADYS AUTO SALES INC (Continued)

U001356439

### LUST:

Facility ID:	9201803	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	BRADYS AUTO SALES INC		
Telephone:	8132388441	Discovery Date:	06/29/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BRADYS AUTO SALES INC (Continued)

U001356439

### UST:

Facility ID:	299201803	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	WATSON, W L		
Contact:	Not reported	Facility Phone:	8132388441
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920630	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CATHY GILBERT		
Owner:	WATSON, LOUISE %KEY BANK		
	360 W WATERS AVE		
	TAMPA, FL 33604		
Owner's Phone:	8139337851	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BRADYS AUTO SALES INC (Continued)

U001356439

Facility ID:	299201803	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	WATSON, W L		
Contact:	Not reported	Facility Phone:	8132388441
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920630	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CATHY GILBERT		
Owner:	WATSON, LOUISE %KEY BANK		
	360 W WATERS AVE		
	TAMPA, FL 33604		
Owner's Phone:	8139337851	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

7

MIDDLETON ESTATE  
5609 N NEBRASKA AVE  
TAMPA, FL

UST

U001378089  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MIDDLETON ESTATE (Continued)

U001378089

### UST:

Facility ID:	299200414	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MIDDLETON, ALBERT D		
Contact:	Not reported	Facility Phone:	5187937398
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920205	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	SID COOPER		
Owner:	MIDDLETON, ALBERT D		
	RR1 BOX 1289		
	WEST FORT ANN, NY 12827		
Owner's Phone:	8136462644	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MIDDLETON ESTATE (Continued)

U001378089

Facility ID:	299200414	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MIDDLETON, ALBERT D		
Contact:	Not reported	Facility Phone:	5187937398
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920205	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	SID COOPER		
Owner:	MIDDLETON, ALBERT D		
	RR1 BOX 1289		
	WEST FORT ANN, NY 12827		
Owner's Phone:	8136462644	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000250	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MIDDLETON ESTATE (Continued)

U001378089

Facility ID:	299200414	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MIDDLETON, ALBERT D		
Contact:	Not reported	Facility Phone:	5187937398
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920205	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	SID COOPER		
Owner:	MIDDLETON, ALBERT D		
	RR1 BOX 1289		
	WEST FORT ANN, NY 12827		
Owner's Phone:	8136462644	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MIDDLETON ESTATE (Continued)

U001378089

Facility ID:	299200414	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MIDDLETON, ALBERT D		
Contact:	Not reported	Facility Phone:	5187937398
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920205	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	SID COOPER		
Owner:	MIDDLETON, ALBERT D		
	RR1 BOX 1289		
	WEST FORT ANN, NY 12827		
Owner's Phone:	8136462644	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

## 8 PROFESSIONAL AUTO BODY 5509 N NEBRASKA AVE TAMPA, FL 33612

RCRIS-SQG 1000498599  
FINDS FLD982148926

RCRIS:

Owner: CRISTIE LOU  
(813) 238-5860

Contact: CRISTIE LOU  
(813) 238-5860

Waste	Quantity	Info Source	Waste	Quantity	Info Source
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

## 9 GTE OF FL SEMINOLE CO 103 E HILLSBOROUGH AVE TAMPA, FL 33604

UST U001355019  
LUST N/A  
AST



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GTE OF FL SEMINOLE CO (Continued)

U001355019

### LUST:

Facility ID:	8626303	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	GENERAL TELEPHONE CO OF FL-SEMINOLE CO		
Telephone:	8136214931	Discovery Date:	03/11/86
Tracking Number:	290019	Score:	031
Facility Code:	Not reported	Status:	Not reported
Rank:	03694		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GTE OF FL SEMINOLE CO (Continued)

U001355019

### UST:

Facility ID:	298626303	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO. OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861008	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	290019
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GTE OF FL SEMINOLE CO (Continued)

U001355019

Facility ID:	298626303	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO. OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861008	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	290019
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GTE OF FL SEMINOLE CO (Continued)

U001355019

Facility ID:	298626303	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO. OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861008	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	290019
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Dbl walled=primary matl		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Piping/auto shut off		

### AST:

Facility ID:	298626303	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO. OF FL		
Facility Phone:	8136214931	Permit Section:	Not reported
Date entered:	861008	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	290019
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Completed	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	91/02
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, Dbl walled=primary matl, Spill cnrnt		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

9

M&H STATION  
5402 N FLORIDA AVE  
TAMPA, FL 33604

UST  
LUST

U001354383  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## M&H STATION (Continued)

U001354383

### LUST:

Facility ID:	8625146	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132384827	Discovery Date:	03/10/87
Tracking Number:	290862	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## M&H STATION (Continued)

U001354383

### UST:

Facility ID:	298625146	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	LAWRENCE M. FIMBEL		
Contact:	Not reported	Facility Phone:	8132384827
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	A. B. VAN AMPTING		
Owner:	MILLER & HOLMES		
	501 LAFAYETTE RD N		
	SAINT PAUL, MN 551012427		
Owner's Phone:	6122245874	Tracking #:	290862
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00015000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	62/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, SPCC plan, DW piping space, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## M&H STATION (Continued)

U001354383

Facility ID:	298625146	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	LAWRENCE M. FIMBEL		
Contact:	Not reported	Facility Phone:	8132384827
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	A. B. VAN AMPTING		
Owner:	MILLER & HOLMES 501 LAFAYETTE RD N SAINT PAUL, MN 551012427		
Owner's Phone:	6122245874	Tracking #:	290862
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	62/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, SPCC plan, DW piping space, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## M&H STATION (Continued)

U001354383

Facility ID:	298625146	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	LAWRENCE M. FIMBEL		
Contact:	Not reported	Facility Phone:	8132384827
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	A. B. VAN AMPTING		
Owner:	MILLER & HOLMES		
	501 LAFAYETTE RD N		
	SAINT PAUL, MN 551012427		
Owner's Phone:	6122245874	Tracking #:	290862
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00015000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	74/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, SPCC plan, DW piping space, Auto tank gauging		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## M&H STATION (Continued)

U001354383

Facility ID:	298625146	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	LAWRENCE M. FIMBEL		
Contact:	Not reported	Facility Phone:	8132384827
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	A. B. VAN AMPTING		
Owner:	MILLER & HOLMES		
	501 LAFAYETTE RD N		
	SAINT PAUL, MN 551012427		
Owner's Phone:	6122245874	Tracking #:	290862
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00015000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	70/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt		
Tank Piping:	Fiberglass, Dbiwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, SPCC plan, DW piping space, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## M&H STATION (Continued)

U001354383

Facility ID:	298625146	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	LAWRENCE M. FIMBEL		
Contact:	Not reported	Facility Phone:	8132384827
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	A. B. VAN AMPTING		
Owner:	MILLER & HOLMES		
	501 LAFAYETTE RD N		
	SAINT PAUL, MN 551012427		
Owner's Phone:	6122245874	Tracking #:	290862
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	77/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, SPCC plan, DW piping space, Auto tank gauging		

9	HUGHLETT DENTAL LABORATORIES 5420 N FLORIDA AVE TAMPA, FL 33604	FINDS	1000502061 FLD984222109
---	---	-------	----------------------------

10	COTTSMAN TRANSMISSION 1262 E HILLSBOROUGH AVE TAMPA, FL 33607	UST	U001823434 N/A
----	---	-----	-------------------

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## COTTSMAN TRANSMISSION (Continued)

U001823434

### UST:

Facility ID:	299400640	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CINDY		
Contact:	Not reported	Facility Phone:	8132298507
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940411	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CINDY		
Owner:	HYMAN, DAVID		
	501 E KENNEDY BLVD #707		
	TAMPA, FL 336024933		
Owner's Phone:	8132298507	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	73/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## COTTSMAN TRANSMISSION (Continued)

U001823434

Facility ID:	299400640	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CINDY		
Contact:	Not reported	Facility Phone:	8132298507
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940411	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CINDY		
Owner:	HYMAN, DAVID		
	501 E KENNEDY BLVD #707		
	TAMPA, FL 336024933		
Owner's Phone:	8132298507	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	7/3/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	9/3/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## COTTSMAN TRANSMISSION (Continued)

U001823434

Facility ID:	299400640	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CINDY		
Contact:	Not reported	Facility Phone:	8132298507
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940411	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CINDY		
Owner:	HYMAN, DAVID		
	501 E KENNEDY BLVD #707		
	TAMPA, FL 336024933		
Owner's Phone:	8132298507	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	73/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

10	SHERWIN WILLIAMS CO 1249 E HILLSBOROUGH AVE TAMPA, FL 44115	FINDS	1000732897 FLD0000827576
11	ROYAL POOLS INC 1308 HILLSBOROUGH AVE TAMPA, FL 33604	FINDS	1000932272 FL0000608091
12	SUNOCO SERVICE STATION 902 EAST HILLSBOROUGH AVE TAMPA, FL 19103	RCRIS-SQG	1000687162 FLD000654012
12	SUNOCO SVC STA 902 E HILLSBOROUGH AVE TAMPA, FL 33604	FINDS	1000931580 FL0000271106
12	FUEL SAVER OIL SHOPS INC 5402 N NEBRASKA AVE TAMPA, FL	AST	A100009011 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FUEL SAVER OIL SHOPS INC (Continued)

A100009011

### AST:

Facility ID:	299102988	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FUEL SAVER OIL SHOPS INC		
Facility Phone:	8136842575	Permit Section:	Not reported
Date entered:	911003	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLIAM C KELLOG		
Owner:	CASTROL NORTH AMERICA		
	PO BOX 6220		
	JACKSONVILLE, FL 32205		
Owner's Phone:	9047814661	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000705
Tank Content:	New/lube oil	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	89/04
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Man tank gauging		

13

JIM MCCARN AUTOS  
1101 EAST HILLSBOROUGH AVE  
TAMPA, FL 33604

RCRIS-SQG  
FINDS

1000287005  
FLD981747876

14

BP-MIDTOWN  
806 E HILLSBOROUGH AVE  
TAMPA, FL 33604

UST  
LUST

U001356013  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BP-MIDTOWN (Continued)

U001356013

### LUST:

Facility ID:	8944280	Facility Type:	RETAIL STATION
Alias Name:	SHELL STATION-INTERSTATE		
Telephone:	8132399648	Discovery Date:	05/11/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BP-MIDTOWN (Continued)

U001356013

### UST:

Facility ID:	298944280	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DOKUMACI UNSAL		
Contact:	Not reported	Facility Phone:	8132399648
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890531	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAN WHITESIDE		
Owner:	DOKUMACI, DR OZDEMIR		
	806 E HILLSBOROUGH AVE		
	TAMPA, FL 336047140		
Owner's Phone:	8132384509	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BP-MIDTOWN (Continued)

U001356013

Facility ID:	298944280	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DOKUMACI UNSAL		
Contact:	Not reported	Facility Phone:	8132399648
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890531	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JAN WHITESIDE		
Owner:	DOKUMACI, DR OZDEMIR 806 E HILLSBOROUGH AVE TAMPA, FL 336047140		
Owner's Phone:	8132384509	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BP-MIDTOWN (Continued)

U001356013

Facility ID:	298944280	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DOKUMACI UNSAL		
Contact:	Not reported	Facility Phone:	8132399648
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890531	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JAN WHITESIDE		
Owner:	DOKUMACI, DR OZDEMIR 806 E HILLSBOROUGH AVE TAMPA, FL 336047140		
Owner's Phone:	8132384509	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BP-MIDTOWN (Continued)

U001356013

Facility ID:	298944280	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DOKUMACI UNSAL		
Contact:	Not reported	Facility Phone:	8132399648
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890531	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JAN WHITESIDE		
Owner:	DOKUMACI, DR OZDEMIR 806 E HILLSBOROUGH AVE TAMPA, FL 336047140		
Owner's Phone:	8132384509	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BP-MIDTOWN (Continued)

U001356013

Facility ID:	298944280	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DOKUMACI UNSAL		
Contact:	Not reported	Facility Phone:	8132399648
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890531	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JAN WHITESIDE		
Owner:	DOKUMACI, DR OZDEMİR 806 E HILLSBOROUGH AVE TAMPA, FL 336047140		
Owner's Phone:	8132384509	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

15

CUMBERLAND FARMS #1011  
414 E HILLSBOROUGH AVE  
TAMPA, FL 33604

UST  
LUST

U001354864  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CUMBERLAND FARMS #1011 (Continued)

U001354864

### LUST:

Facility ID:	8625657	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	4078924706	Discovery Date:	05/21/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	DIESEL-EMERG GENE	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO INSURANCE
Incident Ineligible Description:	NO INSURANCE

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	QTR 1

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CUMBERLAND FARMS #1011 (Continued)

U001354864

### UST:

Facility ID:	298625657	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROYCE CAMP		
Contact:	Not reported	Facility Phone:	4078924706
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	RICHARD LONGTON		
Owner:	CUMBERLAND FARMS INC		
	777 DEDHAM ST		
	CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CUMBERLAND FARMS #1011 (Continued)

U001354864

Facility ID:	298625657	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROYCE CAMP		
Contact:	Not reported	Facility Phone:	4078924706
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	RICHARD LONGTON		
Owner:	CUMBERLAND FARMS INC		
	777 DEDHAM ST		
	CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CUMBERLAND FARMS #1011 (Continued)

U001354864

Facility ID:	298625657	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROYCE CAMP		
Contact:	Not reported	Facility Phone:	4078924706
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	RICHARD LONGTON		
Owner:	CUMBERLAND FARMS INC		
	777 DEDHAM ST		
	CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CUMBERLAND FARMS #1011 (Continued)

U001354864

Facility ID:	298625657	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROYCE CAMP		
Contact:	Not reported	Facility Phone:	4078924706
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	RICHARD LONGTON		
Owner:	CUMBERLAND FARMS INC		
	777 DEDHAM ST		
	CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	87/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CUMBERLAND FARMS #1011 (Continued)

U001354864

Facility ID:	298625657	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROYCE CAMP		
Contact:	Not reported	Facility Phone:	4078924706
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	RICHARD LONGTON		
Owner:	CUMBERLAND FARMS INC		
	777 DEDHAM ST		
	CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	87/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CUMBERLAND FARMS #1011 (Continued)

U001354864

Facility ID:	298625657	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROYCE CAMP		
Contact:	Not reported	Facility Phone:	4078924706
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	6	District:	Southwest
Owner's Contact:	RICHARD LONGTON		
Owner:	CUMBERLAND FARMS INC		
	777 DEDHAM ST		
	CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	87/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CUMBERLAND FARMS #1011 (Continued)

U001354864

Facility ID:	298625657	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROYCE CAMP		
Contact:	Not reported	Facility Phone:	4078924706
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	7	District:	Southwest
Owner's Contact:	RICHARD LONGTON		
Owner:	CUMBERLAND FARMS INC		
	777 DEDHAM ST		
	CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

16 LEROYS 4 X 4 & AUTO CENTER  
512 E HILLSBOROUGH AVE.  
TAMPA, FL 33604

FINDS 1000344349  
RCRIS-LQG FLD087753893

16 MOBIL #02-CNG  
502 E HILLSBOROUGH AVE  
TAMPA, FL 33604

UST U001354232  
LUST N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MOBIL #02-CNG (Continued)

U001354232

## LUST:

Facility ID:	8624985	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132393055	Discovery Date:	12/27/88
Tracking Number:	297386	Score:	036
Facility Code:	Not reported	Status:	Not reported
Rank:	02970		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	REC DRAW
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL #02-CNG (Continued)

U001354232

### UST:

Facility ID:	298624985	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132393055
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	1A	District:	Southwest
Owner's Contact:	JOHN MOORE		
Owner:	GULF PRODUCTS DIV; B.P. OIL, INC		
	P O DRAWER 38		
	MAITLAND, FL 32751		
Owner's Phone:	4046412400	Tracking #:	297386
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**MOBIL #02-CNG (Continued)**

**U001354232**

Facility ID:	298624985	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132393055
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	1B	District:	Southwest
Owner's Contact:	JOHN MOORE		
Owner:	GULF PRODUCTS DIV; B.P. OIL, INC P O DRAWER 38 MAITLAND, FL 32751		
Owner's Phone:	4046412400	Tracking #:	297386
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MOBIL #02-CNG (Continued)

U001354232

Facility ID:	298624985	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132393055
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	2A	District:	Southwest
Owner's Contact:	JOHN MOORE		
Owner:	GULF PRODUCTS DIV; B.P. OIL, INC		
	P O DRAWER 38		
	MAITLAND, FL 32751		
Owner's Phone:	4046412400	Tracking #:	297386
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MOBIL #02-CNG (Continued)

U001354232

Facility ID:	298624985	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132393055
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	2B	District:	Southwest
Owner's Contact:	JOHN MOORE		
Owner:	GULF PRODUCTS DIV; B.P. OIL, INC P O DRAWER 38 MAITLAND, FL 32751		
Owner's Phone:	4046412400	Tracking #:	297386
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MOBIL #02-CNG (Continued)

U001354232

Facility ID:	298624985	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132393055
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	3A	District:	Southwest
Owner's Contact:	JOHN MOORE		
Owner:	GULF PRODUCTS DIV; B.P. OIL, INC P O DRAWER 38 MAITLAND, FL 32751		
Owner's Phone:	4046412400	Tracking #:	297386
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL #02-CNG (Continued)

U001354232

Facility ID:	298624985	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132393055
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	3B	District:	Southwest
Owner's Contact:	JOHN MOORE		
Owner:	GULF PRODUCTS DIV; B.P. OIL, INC		
	P O DRAWER 38		
	MAITLAND, FL 32751		
Owner's Phone:	4046412400	Tracking #:	297386
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## MOBIL #02-CNG (Continued)

U001354232

Facility ID:	298624985	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132393055
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN MOORE		
Owner:	GULF PRODUCTS DIV; B.P. OIL, INC		
	P O DRAWER 38		
	MAITLAND, FL 32751		
Owner's Phone:	4046412400	Tracking #:	297386
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL #02-CNG (Continued)

U001354232

Facility ID:	298624985	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132393055
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN MOORE		
Owner:	GULF PRODUCTS DIV; B.P. OIL, INC		
	P O DRAWER 38		
	MAITLAND, FL 32751		
Owner's Phone:	4046412400	Tracking #:	297386
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	88/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL #02-CNG (Continued)

U001354232

Facility ID:	298624985	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132393055
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	JOHN MOORE		
Owner:	GULF PRODUCTS DIV; B.P. OIL, INC		
	P O DRAWER 38		
	MAITLAND, FL 32751		
Owner's Phone:	4046412400	Tracking #:	297386
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	88/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## MOBIL #02-CNG (Continued)

U001354232

Facility ID:	298624985	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132393055
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	JOHN MOORE		
Owner:	GULF PRODUCTS DIV; B.P. OIL, INC		
	P O DRAWER 38		
	MAITLAND, FL 32751		
Owner's Phone:	4046412400	Tracking #:	297386
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	88/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## MOBIL #02-CNG (Continued)

U001354232

Facility ID:	298624985	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8132393055
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	JOHN MOORE		
Owner:	GULF PRODUCTS DIV; B.P. OIL, INC		
	P O DRAWER 38		
	MAITLAND, FL 32751		
Owner's Phone:	4046412400	Tracking #:	297386
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	88/10
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

16	<b>RALPHS SERVICE CTR</b> <b>502 E HILLSBOROUGH AVE</b> <b>TAMPA, FL 33604</b>	<b>FINDS</b>	<b>1000733643</b> <b>FLD085096303</b>
16	<b>AMOCO SVC STA #463</b> <b>501 E HILLSBOROUGH</b> <b>TAMPA, FL 33604</b>	<b>RCRIS-SQG</b> <b>FINDS</b> <b>UST</b> <b>LUST</b>	<b>1000501049</b> <b>FLD984211672</b>

### RCRIS:

Owner: WILLIAM JEANFILS, DEALER  
(813) 238-4755

Contact: WILLIAM JEANFILS  
(813) 238-4755

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D018	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO SVC STA #463 (Continued)

1000501049

### LUST:

Facility ID:	8624974	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132384755	Discovery Date:	11/30/88
Tracking Number:	296840	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06571		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	REC DRAW
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO SVC STA #463 (Continued)

1000501049

### UST:

Facility ID:	298624974	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM JEANFILS		
Contact:	Not reported	Facility Phone:	8132384755
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS 600 CORPORATE DR #500 FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	296840
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/02
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO SVC STA #463 (Continued)

1000501049

Facility ID:	298624974	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM JEANFILS		
Contact:	Not reported	Facility Phone:	8132384755
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1R1	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS		
	600 CORPORATE DR #500		
	FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	296840
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## AMOCO SVC STA #463 (Continued)

1000501049

Facility ID:	298624974	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM JEANFILS		
Contact:	Not reported	Facility Phone:	8132384755
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS 600 CORPORATE DR #500 FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	296840
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/02
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## AMOCO SVC STA #463 (Continued)

1000501049

Facility ID:	298624974	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM JEANFILS		
Contact:	Not reported	Facility Phone:	8132384755
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2R1	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS		
	600 CORPORATE DR #500		
	FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	296840
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO SVC STA #463 (Continued)

1000501049

Facility ID:	298624974	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM JEANFILS		
Contact:	Not reported	Facility Phone:	8132384755
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS		
	600 CORPORATE DR #500		
	FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	296840
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	65/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## AMOCO SVC STA #463 (Continued)

1000501049

Facility ID:	298624974	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM JEANFILS		
Contact:	Not reported	Facility Phone:	8132384755
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3R1	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS		
	600 CORPORATE DR #500		
	FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	296840
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## AMOCO SVC STA #463 (Continued)

1000501049

Facility ID:	298624974	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM JEANFILS		
Contact:	Not reported	Facility Phone:	8132384755
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS		
	600 CORPORATE DR #500		
	FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	296840
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	65/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO SVC STA #463 (Continued)

1000501049

Facility ID:	298624974	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM JEANFILS		
Contact:	Not reported	Facility Phone:	8132384755
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4R1	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS 600 CORPORATE DR #500 FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	296840
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## AMOCO SVC STA #463 (Continued)

1000501049

Facility ID:	298624974	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAM JEANFILS		
Contact:	Not reported	Facility Phone:	8132384755
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	RICARDO ALVEAR		
Owner:	AMOCO PETROLEUM PRODUCTS		
	600 CORPORATE DR #500		
	FORT LAUDERDALE, FL 333343607		
Owner's Phone:	3052742521	Tracking #:	296840
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	65/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

17

RENTAL TOOL CO.  
111 W HILLSBOROUGH AVE  
TAMPA, FL 33604

LUST  
AST

S101264750  
N/A

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RENTAL TOOL CO. (Continued)

S101264750

### LUST:

Facility ID:	8839211	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	05/08/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RENTAL TOOL CO. (Continued)

S101264750

### AST:

Facility ID:	298839211	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RENTAL TOOL CO.	Permit Section:	Not reported
Facility Phone:	Not reported	Financial responsibility:	Not reported
Date entered:	880218	District:	Southwest
Tank ID:	1		
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000550
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	92/06	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

18

CIRCLE K #7961  
5320 N FLORIDA AVENUE  
TAMPA, FL 33603

FINDS  
UST  
LUST

1000740307  
FLD984256206

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CIRCLE K #7961 (Continued)

1000740307

## LUST:

Facility ID:	8627032	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132383889	Discovery Date:	05/16/88
Tracking Number:	293052	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CIRCLE K #7961 (Continued)

1000740307

### UST:

Facility ID:	298627032	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CIRCLE K CORP		
Contact:	Not reported	Facility Phone:	8132383889
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	STEVE BELIN		
Owner:	CIRCLE K STORES INC		
	5650 BRECKENRIDGE PARK DR #300		
	TAMPA, FL 33610		
Owner's Phone:	8136215528	Tracking #:	293052
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	85/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**CIRCLE K #7961 (Continued)**

**1000740307**

Facility ID:	298627032	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CIRCLE K CORP		
Contact:	Not reported	Facility Phone:	8132383889
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	STEVE BELIN		
Owner:	CIRCLE K STORES INC		
	5650 BRECKENRIDGE PARK DR #300		
	TAMPA, FL 33610		
Owner's Phone:	8136215528	Tracking #:	293052
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	85/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CIRCLE K #7961 (Continued)

1000740307

Facility ID:	298627032	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CIRCLE K CORP		
Contact:	Not reported	Facility Phone:	8132383889
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	STEVE BELIN		
Owner:	CIRCLE K STORES INC		
	5650 BRECKENRIDGE PARK DR #300		
	TAMPA, FL 33610		
Owner's Phone:	8136215528	Tracking #:	293052
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	85/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

19

NEBRASKA AVE BODY SHOP  
5301 N NEBRASKA AVE  
TAMPA, FL

UST  
LUST

U002038449  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## NEBRASKA AVE BODY SHOP (Continued)

U002038449

### LUST:

Facility ID:	9401978	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132393484	Discovery Date:	10/10/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## NEBRASKA AVE BODY SHOP (Continued)

U002038449

### UST:

Facility ID:	299401978	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	8132393484
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	941115	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	DELL CARRARA		
Owner:	CARRARA, DELL		
	5301 N NEBRASKA AVE		
	TAMPA, FL 33603		
Owner's Phone:	8132393484	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	1
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

20

FABIAN ENTERPRISES  
5236 N FLORIDA AVE  
TAMPA, FL 33603

UST

U001354061  
N/A

# MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

## FABIAN ENTERPRISES (Continued)

U001354061

### UST:

Facility ID:	298624798	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ALERT A/C & HEATING CO.INC.		
Contact:	Not reported	Facility Phone:	8132383191
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	EDGAR W.SAPP		
Owner:	J. H. WILLIAMS OIL CO.,INC. 1237 E TWIGGS TAMPA, FL 33602		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	70/11
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

21	GATOR RENTAL & REPAIR CO 5218 NEBRASKA AVE TAMPA, FL 33603	RCRIS-SQG FINDS	1000340615 FLD052906708
22	ALHAMBRA INC 5132 N FLORIDA AVE TAMPA, FL 33603	FINDS	1000933052 FL0000658112
23	BLOUNT CO., INC./F. T. 5101 N NEBRASKA AVE TAMPA, FL 33603	UST LUST	U001354959 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BLOUNT CO., INC./F. T. (Continued)

U001354959

## LUST:

Facility ID:	8625756	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136263136	Discovery Date:	02/02/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BLOUNT CO., INC./F. T. (Continued)

U001354959

## UST:

Facility ID:	298625756	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GARDEN OF MEMORIES, INC.		
Contact:	Not reported	Facility Phone:	8136263136
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARK A PANTER		
Owner:	GARDEN OF MEMORIES		
	4207 E LAKE AVE		
	TAMPA, FL 336108035		
Owner's Phone:	8136263161	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/11
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## BLOUNT CO., INC./F. T. (Continued)

U001354959

Facility ID:	298625756	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GARDEN OF MEMORIES, INC.		
Contact:	Not reported	Facility Phone:	8136263136
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	MARK A PANTER		
Owner:	GARDEN OF MEMORIES		
	4207 E LAKE AVE		
	TAMPA, FL 336108035		
Owner's Phone:	8136263161	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Cath prot-sac anode, Spill cnmt		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

24

SOMOZA TIRE STORE  
5020 N FLORIDA AVE  
TAMPA, FL 33603

UST  
LUST

U001356456  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**SOMOZA TIRE STORE (Continued)**

**U001356456**

**LUST:**

Facility ID:	9202175	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132383762	Discovery Date:	09/28/92
Tracking Number:	Not reported	Score:	023 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05472		
Class:	Not reported		
Category:	Not reported		

**INCIDENT GENERAL INFORMATION -**

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION  
LOCAL PROGRAM  
COMBINED C/U REQUIRED

**INCIDENT POLLUTANT INFORMATION -**

Pollutant: LEADED GAS  
Pollutant 2: WASTE OIL  
Pollutant 3: FUEL OIL-ON SITE

Est. Gallons Lost: UNKNOWN  
Est. Gallons Lost: UNKNOWN  
Est. Gallons Lost: UNKNOWN

**INCIDENT PROGRAM INFORMATION -**

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

RESPONSIBLE PARTY-NO CLAIM  
Not reported  
Not reported  
Not Reported  
Not reported

**INCIDENT INITIAL REMEDIAL ACTION INFORMATION -**

Free Product:

Soil Removal: Y

Soil Treatment: Y

Other Treatment:

Cleanup Responsible: RESPONSIBLE PARTY  
Alt. Process Date: Not reported  
Alternative Status: Not reported

**INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -**

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY  
CONTAMINATION ASSESSMENT REPORT  
Not reported  
INCOMPLETE  
Not reported  
Not reported  
Not reported

**INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -**

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

RESPONSIBLE PARTY  
REMEDIAL ACTION PLAN  
OTHER

**INCIDENT REMEDIAL ACTION REPORT INFORMATION -**

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported  
Not reported  
Not reported  
Not reported  
Not reported

**INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -**

Site Rehab. Completion Action:

Region:

NO FURTHER ACTION  
STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SOMOZA TIRE STORE (Continued)

U001356456

### UST:

Facility ID:	299202175	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOMOZA, OSVALDO		
Contact:	Not reported	Facility Phone:	8132383762
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920728	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	OSVALDO SOMOZA		
Owner:	SOMOZA, OSVALDO		
	5020 N FLORIDA AVE		
	TAMPA, FL 33603		
Owner's Phone:	8139859428	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SOMOZA TIRE STORE (Continued)

U001356456

Facility ID:	299202175	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOMOZA, OSVALDO		
Contact:	Not reported	Facility Phone:	8132383762
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920728	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	OSVALDO SOMOZA		
Owner:	SOMOZA, OSVALDO 5020 N FLORIDA AVE TAMPA, FL 33603		
Owner's Phone:	8139859428	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SOMOZA TIRE STORE (Continued)

U001356456

Facility ID:	299202175	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOMOZA, OSVALDO		
Contact:	Not reported	Facility Phone:	8132383762
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920728	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	OSVALDO SOMOZA		
Owner:	SOMOZA, OSVALDO		
	5020 N FLORIDA AVE		
	TAMPA, FL 33603		
Owner's Phone:	8139859428	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

25

## SOUTHPRINT CORPORATION 4907 NORTH FLORIDA AVE TAMPA, FL 33603

RCRIS-SQG 1000409900  
FINDS FLD982122186

### RCRIS:

Owner: CINDY MARKS, PERS ADM  
(813) 237-8000

Contact: CINDY MARKS  
(813) 237-8000

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

26

## AUTO RANCH USED CARS 4829 N FLORIDA AVE TAMPA, FL 33603

UST U001355465  
N/A

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## AUTO RANCH USED CARS (Continued)

U001355465

### UST:

Facility ID:	298733836	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTO RANCH USED CARS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870729	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	AUTO RANCH USED CARS		
	4829 N FLORIDA AVE		
	TAMPA, FL 336032117		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	install. Date:	65/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

26

HOME ROOFING, INC.  
4839 N FLORIDA AVE  
TAMPA, FL 33603

UST  
LUST

U001355096  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HOME ROOFING, INC. (Continued)

U001355096

### LUST:

Facility ID:	8627035	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132385078	Discovery Date:	05/11/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HOME ROOFING, INC. (Continued)

U001355096

### UST:

Facility ID:	298627035	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BYRON O. CURRY		
Contact:	Not reported	Facility Phone:	8132385078
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BYRON O. CURRY		
Owner:	HOME ROOFING INC 4839 N FLORIDA AVE TAMPA, FL 336032117		
Owner's Phone:	8132385078	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

27

**SHELLY'S TEXACO**  
**4802 N NEBRASKA AVE**  
**TAMPA, FL 33603**

UST  
LUST

U001353976  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SHELLY'S TEXACO (Continued)

U001353976

### LUST:

Facility ID:	8509078	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132474731	Discovery Date:	09/14/88
Tracking Number:	293760	Score:	037
Facility Code:	Not reported	Status:	Not reported
Rank:	02372		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SHELLY'S TEXACO (Continued)

U001353976

### UST:

Facility ID:	298509078	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293760
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	7
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SHELLY'S TEXACO (Continued)

U001353976

Facility ID:	298509078	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293760
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	8
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SHELLY'S TEXACO (Continued)

U001353976

Facility ID:	298509078	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293760
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SHELLY'S TEXACO (Continued)

U001353976

Facility ID:	298509078	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293760
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SHELLY'S TEXACO (Continued)

U001353976

Facility ID:	298509078	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293760
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SHELLY'S TEXACO (Continued)

U001353976

Facility ID:	298509078	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293760
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SHELLY'S TEXACO (Continued)

U001353976

Facility ID:	298509078	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293760
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SHELLY'S TEXACO (Continued)

U001353976

Facility ID:	298509078	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293760
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	2	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Compartmented, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

28	JAMIESON CHEMICAL CO INC 818 E OSBORNE AVE TAMPA, FL 33603	FINDS	1000496925 FLD004108627
----	--	-------	----------------------------

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

29	SINCLAIR & VALENTINE CO. 4711 NORTH FLORIDA AVE. TAMPA, FL 33603	FI Sites	S100889043 N/A
----	--	----------	-------------------

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SINCLAIR & VALENTINE CO. (Continued)

S100889043

### FL Sites:

Facility ID:	000381	EPA ID:	FLD062450697
Facility District:	SOUTHWEST	Monthly Update:	May
Lead Unit:	Not reported	Support Unit:	3012
Air Contam:	Not reported	Soil Contam:	Not reported
Surface Water Contam:	Not reported	Ground Water Contam:	Not reported
Cleanup Started ?:	No	Cleanup Completed ?:	No
Deletion Recommended ?:	No	Other:	Not reported
Warning Letter Status:	Not reported	Notice of Violation Status:	No
Consent Order Status:	No	Admin Hearing Status:	No
Court Status:	No	Final Order Status:	No

Comments: EPA PRELIMINARY ASSESSMENT COMPLETED 11-82. EPA/CERCLA SITE SCREENING CATEGORIZATION REVIEW COMPLETED 11/87 RESULTED IN A MEDIUM PRIORITY DETERMINATION FOR SITE SCREENING INVESTIGATION. EPA/FDER INVESTIGATION TO BE SCHEDULED ON A PRIORITY BASIS. SITE ACCESS FOR SCREENING INVESTIGATION REQUESTED 4/88. SAMPLING TO BE CONDUCTED BY 6/88.

29

**SINCLAIR & VALENTINE CO**  
**4711 N FLORIDA AVE**  
**TAMPA, FL 33603**

**FINDS** 1000173802  
**CERC-NFRAP** FLD980559439

### CERCLIS-NFRAP Classification Data:

Site Incident Category:	Not reported	Federal Facility:	NO
Ownership Status:	OTHER	NPL Status:	NOT ON NPL
EPA Notes:	Not reported		

### CERCLIS-NFRAP Assessment History:

Assessment:	PRELIMINARY ASSESSMENT	Completed:	11/01/82
Assessment:	DISCOVERY	Completed:	06/01/81
Assessment:	SCREENING SITE INSPECTION	Completed:	10/10/89

CERCLIS-NFRAP Alias Name(s):  
SINCLAIR & VALENTINE CO

29

**PEREZ GENE BODY REPAIR**  
**4710 FLORIDA AVE**  
**TAMPA, FL 33603**

**RCRIS-SQG** 1000226488  
**FINDS** FLD078315710

30

**JAMIESON CHEMICAL COMPANY, INC**  
**4719 N NEBRASKA AVE**  
**TAMPA,, FL 33603**

**FINDS** 1000932258  
FL0000606467

31

**LEWIS PAINT CO INC**  
**4634 N FLORIDA AVE**  
**TAMPA, FL 33604**

**RCRIS-SQG** 1000501856  
**FINDS** FLD984219980

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## LEWIS PAINT CO INC (Continued)

1000501856

### RCRIS:

Owner: ROBERT INGALLS, STORE MGR  
(813) 236-1221

Contact: CHARLES LEWIS  
(813) 231-0541

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F001	.00000 (T)	Notification
F002	.00000 (T)	Notification	F003	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

32

## **JUSTER'S RITE-WAY SERVICE** **4402 N NEBRASKA AVE** **TAMPA, FL 33603**

UST

U001354179  
N/A

### UST:

Facility ID:	298624926	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JUSTER PETRALIA		
Contact:	Not reported	Facility Phone:	8132399119
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JUSTER PETRALIA		
Owner:	JUSTERS RITE WAY SERVICE 4402 N NEBRASKA AVE TAMPA, FL 336034147		
Owner's Phone:	8132399119	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## JUSTER'S RITE-WAY SERVICE (Continued)

U001354179

Facility ID:	298624926	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JUSTER PETRALIA		
Contact:	Not reported	Facility Phone:	8132399119
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JUSTER PETRALIA		
Owner:	JUSTERS RITE WAY SERVICE 4402 N NEBRASKA AVE TAMPA, FL 336034147		
Owner's Phone:	8132399119	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## JUSTER'S RITE-WAY SERVICE (Continued)

U001354179

Facility ID:	298624926	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JUSTER PETRALIA		
Contact:	Not reported	Facility Phone:	8132399119
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JUSTER PETRALIA		
Owner:	JUSTERS RITE WAY SERVICE		
	4402 N NEBRASKA AVE		
	TAMPA, FL 336034147		
Owner's Phone:	8132399119	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## JUSTER'S RITE-WAY SERVICE (Continued)

U001354179

Facility ID:	298624926	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JUSTER PETRALIA		
Contact:	Not reported	Facility Phone:	8132399119
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JUSTER PETRALIA		
Owner:	JUSTERS RITE WAY SERVICE 4402 N NEBRASKA AVE TAMPA, FL 336034147		
Owner's Phone:	8132399119	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## **JUSTER'S RITE-WAY SERVICE (Continued)**

**U001354179**

Facility ID:	298624926	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JUSTER PETRALIA		
Contact:	Not reported	Facility Phone:	8132399119
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JUSTER PETRALIA		
Owner:	JUSTERS RITE WAY SERVICE		
	4402 N NEBRASKA AVE		
	TAMPA, FL 336034147		
Owner's Phone:	8132399119	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000350	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

33

**CAR LOT**  
**4404 N FLORIDA AVE**  
**TAMPA, FL 33630**

**UST**

**U001713407**  
**N/A**

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CAR LOT (Continued)

U001713407

### UST:

Facility ID:	299400166	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CAR LOT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940210	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	BARNETT BANK OF PINELLAS CNTY PO BOX 30318 ATTN TIM MARTIN TAMPA, FL 336303318		
Owner's Phone:	8132252929	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	None		

33

**FORMER CAR LOT**  
4404 N FLORIDA AVE  
TAMPA, FL 33603

UST

U001823384  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FORMER CAR LOT (Continued)

U001823384

### UST:

Facility ID:	299400302	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BARNETT BANK		
Contact:	Not reported	Facility Phone:	8132252909
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940314	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TRICIA HOFFMAN		
Owner:	BARNETT BANK INC		
	PO BOX 30318		
	TAMPA, FL 33630		
Owner's Phone:	8132552909	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	None		

33

TAMPA AUTO MART INC  
4404 N FLORIDA AVE  
TAMPA, FL 33603

RCRIS-SQG 1000344831  
FINDS FLD981866643

34

PAINTERS SUPPLY  
4312 N NEBRASKA AVE  
TAMPA, FL 33603

RCRIS-SQG 1000886662  
FINDS FL0000228767

### RCRIS:

Owner: BOB INGALLS, STORE MGR  
(813) 238-9733

Contact: BOB INGALLS  
(813) 238-9733

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	U002	.00000 (T)	Notification
U112	.00000 (T)	Notification	U159	.00000 (T)	Notification
U220	.00000 (T)	Notification	U359	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

35

STREET SOUND, INC.  
4221 N FLORIDA AVE  
TAMPA, FL 33603

UST U001355349  
LUST N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## STREET SOUND, INC. (Continued)

U001355349

### LUST:

Facility ID:	8629021	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132373991	Discovery Date:	12/14/88
Tracking Number:	295749	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NO C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## STREET SOUND, INC. (Continued)

U001355349

### UST:

Facility ID:	298629021	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	STREET SOUND INC.		
Contact:	Not reported	Facility Phone:	8132373991
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	STREET SOUND INC. 4221 N FLORIDA AVE TAMPA, FL 336033819		
Owner's Phone:	8132373991	Tracking #:	295749
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## STREET SOUND, INC. (Continued)

U001355349

Facility ID:	298629021	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	STREET SOUND INC.		
Contact:	Not reported	Facility Phone:	8132373991
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	STREET SOUND INC. 4221 N FLORIDA AVE TAMPA, FL 336033819		
Owner's Phone:	8132373991	Tracking #:	295749
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## STREET SOUND, INC. (Continued)

U001355349

Facility ID:	298629021	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	STREET SOUND INC.		
Contact:	Not reported	Facility Phone:	8132373991
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	Not reported		
Owner:	STREET SOUND INC. 4221 N FLORIDA AVE TAMPA, FL 336033819		
Owner's Phone:	8132373991	Tracking #:	295749
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

35

## BOB OLSENS ENGINE EXCHANGE 4230 N FLORIDA AVE TAMPA, FL 33603

RCRIS-SQG 1000821347  
FINDS FLD984242669

### RCRIS:

Owner: LOUISE OLSEN  
(813) 238-0517

Contact: LOUISE OLSEN  
(813) 238-0517

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D006	.00000 (T)	Notification
D007	.00000 (T)	Notification	D008	.00000 (T)	Notification
D018	.00000 (T)	Notification	D021	.00000 (T)	Notification
D027	.00000 (T)	Notification	D039	.00000 (T)	Notification
D040	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

36

## STERLING CLEANERS 4214 NEBRASKA AVE. TAMPA, FL 33603

FINDS 1000735828  
UST FLD982173528

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## STERLING CLEANERS (Continued)

1000735828

### UST:

Facility ID:	299502046	Facility Type:	1
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MICHAEL GRUBBS		
Contact:	Not reported	Facility Phone:	8138223159
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950705	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	GRUBBS, MICHAEL		
Owner:	PACER INC		
	2300 9TH ST N		
	SAINT PETERSBURG, FL 33704		
Owner's Phone:	8138223159	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

37

W C RAY SERVICE STATION  
4102 N CENTRAL AVE  
TAMPA, FL 33603

UST  
LUST

U001356250  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## W C RAY SERVICE STATION (Continued)

U001356250

### LUST:

Facility ID:	9100814	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	6157810206	Discovery Date:	03/11/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NO C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	NO CONTAMINATION	Est. Gallons Lost:	UNKNOWN
------------	------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## W C RAY SERVICE STATION (Continued)

U001356250

### UST:

Facility ID:	299100814	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FORMAN, EUGENIA CLOUD		
Contact:	Not reported	Facility Phone:	6157810206
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910312	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	EUGENIA FORMAN		
Owner:	FORMAN, EUGENIA CLOUD 5453 VILLAGE WAY NASHVILLE, TN 372116239		
Owner's Phone:	6153602921	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	20/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Suction piping		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## W C RAY SERVICE STATION (Continued)

U001356250

Facility ID:	299100814	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FORMAN, EUGENIA CLOUD		
Contact:	Not reported	Facility Phone:	6157810206
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910312	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	EUGENIA FORMAN		
Owner:	FORMAN, EUGENIA CLOUD		
	5453 VILLAGE WAY		
	NASHVILLE, TN 372116239		
Owner's Phone:	6153602921	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	20/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Suction piping		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## W C RAY SERVICE STATION (Continued)

U001356250

Facility ID:	299100814	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FORMAN, EUGENIA CLOUD		
Contact:	Not reported	Facility Phone:	6157810206
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910312	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	EUGENIA FORMAN		
Owner:	FORMAN, EUGENIA CLOUD 5453 VILLAGE WAY NASHVILLE, TN 372116239		
Owner's Phone:	6153602921	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	20/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Suction piping		
Petro. Monitoring:	Unknown/not reported		

38      **ANSWERRITE PROFESSIONAL TEL SERVICE**  
**510 MARTIN LUTHER KING BLVD**  
**TAMPA, FL 33603**

UST  
LUST

U001355401  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANSWERRITE PROFESSIONAL TEL SERVICE (Continued)

U001355401

### LUST:

Facility ID:	8732454	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	ANSWERRITE CAR PHONE		
Telephone:	8132375500	Discovery Date:	09/30/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
------------	-----------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANSWERRITE PROFESSIONAL TEL SERVICE (Continued)

U001355401

### UST:

Facility ID:	298732454	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANSWERRITE CAR PHONE		
Contact:	Not reported	Facility Phone:	8132375500
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870420	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BOB STEEDE		
Owner:	SMITH, EDWARD C 401 W FAIRBANKS AVE WINTER PARK, FL 32781		
Owner's Phone:	4076443300	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANSWERRITE PROFESSIONAL TEL SERVICE (Continued)

U001355401

Facility ID:	298732454	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANSWERRITE CAR PHONE		
Contact:	Not reported	Facility Phone:	8132375500
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870420	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BOB STEEDE		
Owner:	SMITH, EDWARD C 401 W FAIRBANKS AVE WINTER PARK, FL 32781		
Owner's Phone:	4076443300	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANSWERRITE PROFESSIONAL TEL SERVICE (Continued)

U001355401

Facility ID:	298732454	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANSWERRITE CAR PHONE		
Contact:	Not reported	Facility Phone:	8132375500
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870420	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BOB STEEDE		
Owner:	SMITH, EDWARD C		
	401 W FAIRBANKS AVE		
	WINTER PARK, FL 32781		
Owner's Phone:	4076443300	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANSWERRITE PROFESSIONAL TEL SERVICE (Continued)

U001355401

Facility ID:	298732454	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANSWERRITE CAR PHONE		
Contact:	Not reported	Facility Phone:	8132375500
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870420	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	BOB STEEDE		
Owner:	SMITH, EDWARD C 401 W FAIRBANKS AVE WINTER PARK, FL 32781		
Owner's Phone:	4076443300	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANSWERRITE PROFESSIONAL TEL SERVICE (Continued)

U001355401

Facility ID:	298732454	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANSWERRITE CAR PHONE		
Contact:	Not reported	Facility Phone:	8132375500
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870420	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	BOB STEEDE		
Owner:	SMITH, EDWARD C 401 W FAIRBANKS AVE WINTER PARK, FL 32781		
Owner's Phone:	4076443300	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ANSWERRITE PROFESSIONAL TEL SERVICE (Continued)

U001355401

Facility ID:	298732454	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANSWERRITE CAR PHONE		
Contact:	Not reported	Facility Phone:	8132375500
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870420	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	BOB STEEDE		
Owner:	SMITH, EDWARD C		
	401 W FAIRBANKS AVE		
	WINTER PARK, FL 32781		
Owner's Phone:	4076443300	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

39

HUTTO'S CORNER  
642 W BUFFALO AVE  
TAMPA, FL 33603

UST  
LUST

U001354172  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HUTTO'S CORNER (Continued)

U001354172

### LUST:

Facility ID:	8624919	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132292550	Discovery Date:	07/20/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HUTTO'S CORNER (Continued)

U001354172

### UST:

Facility ID:	298624919	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HUTTO'S CORNER		
Contact:	Not reported	Facility Phone:	8132292550
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	MARK BAKER		
Owner:	HUTTOS CORNER		
	642 W BUFFALO AVE		
	TAMPA, FL 336033452		
Owner's Phone:	8132292550	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HUTTO'S CORNER (Continued)

U001354172

Facility ID:	298624919	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HUTTO'S CORNER		
Contact:	Not reported	Facility Phone:	8132292550
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	MARK BAKER		
Owner:	HUTTOS CORNER		
	642 W BUFFALO AVE		
	TAMPA, FL 336033452		
Owner's Phone:	8132292550	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

40

**ZEPHYRHILLS WATER CO**  
**3919 N HIGHLAND AVE**  
**TAMPA, FL 33603**

UST

U001355078  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ZEPHYRHILLS WATER CO (Continued)

U001355078

### UST:

Facility ID:	298627002	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ZEPHYRHILLS WATER CO		
Contact:	Not reported	Facility Phone:	8132287761
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM LARSON		
Owner:	SUNSHINE WATER CO.		
	5404 CYPRESS CENTER DR. STE. 220		
	TAMPA, FL 33609		
Owner's Phone:	8138758680	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Instalf. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

41

**TAMPA HOUSING AUTHORITY ROBLES PK**  
**3814 CENTRAL AVE**  
**TAMPA, FL 33603**

**FINDS** 1000886549  
**RCRIS-LQG** FL0000079921

### RCRIS:

Owner: ANGELO DEPAUL, DIR  
(813) 253-0551

Contact: ANGELO DEPAUL  
(813) 253-0551

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (N)	State Inspection	D000	.00000 (T)	Notification
D002	.00000 (T)	Notification	D008	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

42

**JESSE HONDA CAR SVC**  
**3816 NEBRASKA AVE**  
**TAMPA, FL 33603**

**RCRIS-SQG** 1000498501  
**FINDS** FLD982081317

# MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

## JESSE HONDA CAR SVC (Continued)

1000498501

### RCRIS:

Owner: PAUL JESSE  
(813) 229-6218

Contact: PAUL JESSE  
(813) 229-6218

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F002	.00000 (T)	Notification
F004	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

43

**SHERWIN WILLIAMS 920**  
**3721 N FLORIDA AVE**  
**TAMPA, FL 33603**

**RCRIS-SQG**  
**FINDS**

1000499386  
FLD984194514

### RCRIS:

Owner: JAMES DUNN

Contact: JAMES DUNN

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F003	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

43

**HASBROUCK, JERRY**  
**3802 N FLORIDA AVE**  
**TAMPA, FL**

**UST**  
**LUST**

U001378123  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

HASBROUCK, JERRY (Continued)

U001378123

## LUST:

Facility ID:	9202418	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132370780	Discovery Date:	09/28/92
Tracking Number:	Not reported	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	------------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HASBROUCK, JERRY (Continued)

U001378123

### UST:

Facility ID:	299202418	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132370780
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920819	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JERRY HASBROUCK		
Owner:	HASBROUCK, JERRY		
	7304 N NEBRASKA AVE		
	TAMPA, FL 33604		
Owner's Phone:	8138889779	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Misc. Petro-base product	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HASBROUCK, JERRY (Continued)

U001378123

Facility ID:	299202418	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132370780
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920819	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JERRY HASBROUCK		
Owner:	HASBROUCK, JERRY		
	7304 N NEBRASKA AVE		
	TAMPA, FL 33604		
Owner's Phone:	8138889779	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Misc. Petro-base product	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HASBROUCK, JERRY (Continued)

U001378123

Facility ID:	299202418	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132370780
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920819	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JERRY HASBROUCK		
Owner:	HASBROUCK, JERRY 7304 N NEBRASKA AVE TAMPA, FL 33604		
Owner's Phone:	8138889779	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Misc. Petro-base product	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HASBROUCK, JERRY (Continued)

U001378123

Facility ID:	299202418	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132370780
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920819	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JERRY HASBROUCK		
Owner:	HASBROUCK, JERRY		
	7304 N NEBRASKA AVE		
	TAMPA, FL 33604		
Owner's Phone:	8138889779	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Misc. Petro-base product	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

44

## KEVINS FRONT WHEEL DRIVE 3707 N NEBRASKA AVE TAMPA, FL 33603

RCRIS-SQG  
FINDS

1000859171  
FL0000121137

RCRIS:

Owner: KEVIN KIRKLAND, OWNER

Contact: KEVIN KIRKLAND

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D006	.00000 (T)	Notification	D007	.00000 (T)	Notification
D008	.00000 (T)	Notification	D018	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

45

## LAKE AND CENTRAL PLAZA 3701 N CENTRAL AVE TAMPA, FL 33603

UST  
LUST

U001356296  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## LAKE AND CENTRAL PLAZA (Continued)

U001356296

### LUST:

Facility ID:	9101311	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8139209702	Discovery Date:	02/24/93
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	CONTAMINATION ASSESSMENT REPORT
Extension Status:	APPROVED
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## LAKE AND CENTRAL PLAZA (Continued)

U001356296

### UST:

Facility ID:	299101311	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MEISTER, HENRY W II		
Contact:	Not reported	Facility Phone:	8139209702
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910329	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	SCOTT MEISTER		
Owner:	MEISTER, ANNE B & HENRY W		
	PO BOX 151529		
	TAMPA, FL 336841529		
Owner's Phone:	8138798825	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## LAKE AND CENTRAL PLAZA (Continued)

U001356296

Facility ID:	299101311	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MEISTER, HENRY W II		
Contact:	Not reported	Facility Phone:	8139209702
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910329	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	SCOTT MEISTER		
Owner:	MEISTER, ANNE B & HENRY W PO BOX 151529 TAMPA, FL 336841529		
Owner's Phone:	8138798825	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

46

**BORRELL ELECTRIC CO INC**  
**3601 N NEBRASKA AVE**  
**TAMPA, FL 33603**

UST

U001354929  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BORRELL ELECTRIC CO INC (Continued)

U001354929

### UST:

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC		
	3601 N NEBRASKA AVE		
	TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BORRELL ELECTRIC CO INC (Continued)

U001354929

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC 3601 N NEBRASKA AVE TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BORRELL ELECTRIC CO INC (Continued)

U001354929

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC		
	3601 N NEBRASKA AVE		
	TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BORRELL ELECTRIC CO INC (Continued)

U001354929

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC		
	3601 N NEBRASKA AVE		
	TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BORRELL ELECTRIC CO INC (Continued)

U001354929

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC		
	3601 N NEBRASKA AVE		
	TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BORRELL ELECTRIC CO INC (Continued)

U001354929

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC 3601 N NEBRASKA AVE TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## BORRELL ELECTRIC CO INC (Continued)

U001354929

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC 3601 N NEBRASKA AVE TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man tank gauging		

46	<b>BORRELL INC</b> 3601 N NEBRASKA AVE TAMPA, FL 33603	RCRIS-SQG	1001023678 FLR000006296
47	<b>CIRCLE AUTO SERVICE OF TAMPA</b> 3602 N FLORIDA AVE TAMPA, FL 33603	UST LUST	U001354795 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CIRCLE AUTO SERVICE OF TAMPA (Continued)

U001354795

### LUST:

Facility ID:	8625584	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132249442	Discovery Date:	02/03/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

Not reported

Incident 17-770 Cleanup:

Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

PETRO. LIABILITY INS. & RESTOR.

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

INELIGIBLE

Incident Ineligible Reason:

OTHER

Incident Ineligible Description:

OTHER

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Region:

STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CIRCLE AUTO SERVICE OF TAMPA (Continued)

U001354795

### UST:

Facility ID:	298625584	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CIRCLE AUTO SERVICE OF TAMPA		
Contact:	Not reported	Facility Phone:	8132249442
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TED LUTZ		
Owner:	TED'S SERVICE CENTER, INC. 3602 N FLORIDA AVE TAMPA, FL 336035819		
Owner's Phone:	8132249442	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, GW mon plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CIRCLE AUTO SERVICE OF TAMPA (Continued)

U001354795

Facility ID:	298625584	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CIRCLE AUTO SERVICE OF TAMPA		
Contact:	Not reported	Facility Phone:	8132249442
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	TED LUTZ		
Owner:	TED'S SERVICE CENTER, INC. 3602 N FLORIDA AVE TAMPA, FL 336035819		
Owner's Phone:	8132249442	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, GW mon plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CIRCLE AUTO SERVICE OF TAMPA (Continued)

U001354795

Facility ID:	298625584	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CIRCLE AUTO SERVICE OF TAMPA		
Contact:	Not reported	Facility Phone:	8132249442
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	TED LUTZ		
Owner:	TED'S SERVICE CENTER, INC. 3602 N FLORIDA AVE TAMPA, FL 336035819		
Owner's Phone:	8132249442	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, GW mon plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CIRCLE AUTO SERVICE OF TAMPA (Continued)

U001354795

Facility ID:	298625584	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CIRCLE AUTO SERVICE OF TAMPA		
Contact:	Not reported	Facility Phone:	8132249442
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	TED LUTZ		
Owner:	TED'S SERVICE CENTER, INC. 3602 N FLORIDA AVE TAMPA, FL 336035819		
Owner's Phone:	8132249442	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, GW mon plan		

48

## **SQUARE DEAL BATTERY** **3512 N FLORIDA AVE** **TAMPA, FL 33603**

**RCRIS-SQG**  
**FINDS**  
**RCRIS-TSD**

**1000155255**  
**FLD984166116**

### RCRIS:

Owner: LARRY CALHOUN, MGR  
(813) 223-3303

Contact: LARRY CALHOUN  
(813) 223-3303

Waste	Quantity	Info Source
D002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

49

## **SAFETY SCHOOL TRANSPORTATION** **3401 N FLORIDA AVE** **TAMPA, FL 33603**

**UST**  
**AST**

**U001354068**  
**N/A**

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SAFETY SCHOOL TRANSPORTATION (Continued)

U001354068

### UST:

Facility ID:	298624807	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SAFETY SCHOOL TRANSPORTATION		
Contact:	Not reported	Facility Phone:	8132235389
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	AHMED KAMEL		
Owner:	SAFETY SCHOOL TRANSPORTATION		
	3401 N FLORIDA AVE		
	TAMPA, FL 336035852		
Owner's Phone:	8132235389	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	4
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SAFETY SCHOOL TRANSPORTATION (Continued)

U001354068

Facility ID:	298624807	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SAFETY SCHOOL TRANSPORTATION		
Contact:	Not reported	Facility Phone:	8132235389
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	AHMED KAMEL		
Owner:	SAFETY SCHOOL TRANSPORTATION		
	3401 N FLORIDA AVE		
	TAMPA, FL 336035852		
Owner's Phone:	8132235389	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SAFETY SCHOOL TRANSPORTATION (Continued)

U001354068

Facility ID:	298624807	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SAFETY SCHOOL TRANSPORTATION		
Contact:	Not reported	Facility Phone:	8132235389
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	AHMED KAMEL		
Owner:	SAFETY SCHOOL TRANSPORTATION		
	3401 N FLORIDA AVE		
	TAMPA, FL 336035852		
Owner's Phone:	8132235389	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	77/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

### AST:

Facility ID:	298624807	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SAFETY SCHOOL TRANSPORTATION		
Facility Phone:	8132235389	Permit Section:	Not reported
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	AHMED KAMEL		
Owner:	SAFETY SCHOOL TRANSPORTATION		
	3401 N FLORIDA AVE		
	TAMPA, FL 336035852		
Owner's Phone:	8132235389	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001500
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	92/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Dbl walled=primary matl, Spill cnmt		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Suction piping		
Petro. Monitoring:	DW tank space		

49

**ALL AMERICAN WRECKER**  
3400 N FLORIDA AVE  
TAMPA, FL 33603

**RCRIS-SQG** 1000821349  
**FINDS** FLD984242685

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ALL AMERICAN WRECKER (Continued)

1000821349

RCRIS:

Owner: L W CABLE  
(800) 940-8689

Contact: L W  
(800) 940-8689

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D007	.00000 (T)	Notification	D008	.00000 (T)	Notification
D018	.00000 (T)	Notification	D021	.00000 (T)	Notification
D027	.00000 (T)	Notification	D039	.00000 (T)	Notification
D040	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

50

TEXACO-GREENE'S  
3301 N FLORIDA AVE  
TAMPA, FL 33603

UST  
LUST

U001355003  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEXACO-GREENE'S (Continued)

U001355003

### LUST:

Facility ID:	8625804	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	08/24/90
Tracking Number:	Not reported	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEXACO-GREENE'S (Continued)

U001355003

### UST:

Facility ID:	298625804	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GREENE,ROBERT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT GREENE		
Owner:	GREENE, ROBERT		
	3301 N FLORIDA AVE		
	TAMPA, FL 336035850		
Owner's Phone:	8132291307	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEXACO-GREENE'S (Continued)

U001355003

Facility ID:	298625804	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GREENE,ROBERT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ROBERT GREENE		
Owner:	GREENE, ROBERT		
	3301 N FLORIDA AVE		
	TAMPA, FL 336035850		
Owner's Phone:	8132291307	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEXACO-GREENE'S (Continued)

U001355003

Facility ID:	298625804	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GREENE,ROBERT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ROBERT GREENE		
Owner:	GREENE, ROBERT		
	3301 N FLORIDA AVE		
	TAMPA, FL 336035850		
Owner's Phone:	8132291307	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TEXACO-GREENE'S (Continued)

U001355003

Facility ID:	298625804	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GREENE,ROBERT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ROBERT GREENE		
Owner:	GREENE, ROBERT		
	3301 N FLORIDA AVE		
	TAMPA, FL 336035850		
Owner's Phone:	8132291307	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

50	LINDELL MOTORS INC 3319 N FLORIDA AVE TAMPA, FL 33606	FINDS	1000734481 FLD981755846
50	LINDELL MOTORS INC 3319 NORTH FLORIDA AVE TAMPA, FL 33606	RCRIS-SQG	1000699819 FLD981755846
51	HILLSBOROUGH CNTY-E TAMPA SERVICE CEN. 3419 N NEBRASKA AVE TAMPA, FL 33603	UST LUST AST	U001354209 N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-E TAMPA SERVICE CEN. (Continued)

U001354209

### LUST:

Facility ID:	8624958	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132725220	Discovery Date:	12/15/88
Tracking Number:	295247	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	04990		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NO C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-E TAMPA SERVICE CEN. (Continued)

U001354209

### UST:

Facility ID:	298624958	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA NEIGHBORHOOD SERVICE CENT.		
Contact:	Not reported	Facility Phone:	8132725220
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	295247
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-E TAMPA SERVICE CEN. (Continued)

U001354209

Facility ID:	298624958	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA NEIGHBORHOOD SERVICE CENT.		
Contact:	Not reported	Facility Phone:	8132725220
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	295247
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-E TAMPA SERVICE CEN. (Continued)

U001354209

Facility ID:	298624958	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA NEIGHBORHOOD SERVICE CENT.		
Contact:	Not reported	Facility Phone:	8132725220
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	295247
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-E TAMPA SERVICE CEN. (Continued)

U001354209

Facility ID:	298624958	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA NEIGHBORHOOD SERVICE CENT.		
Contact:	Not reported	Facility Phone:	8132725220
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	295247
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000600	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

### AST:

Facility ID:	298624958	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA NEIGHBORHOOD SERVICE CENT.		
Facility Phone:	8132725220	Permit Section:	Not reported
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	295247
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Completed	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000600
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	88/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

52

CIRCLE K #4060  
3315 N NEBRASKA AVE  
TAMPA, FL 33603

UST

U001353918  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CIRCLE K #4060 (Continued)

U001353918

### UST:

Facility ID:	298508984	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CIRCLE K CORP		
Contact:	Not reported	Facility Phone:	8136898161
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	STEVE BELIN		
Owner:	CIRCLE K STORES INC		
	5650 BRECKENRIDGE PARK DR #300		
	TAMPA, FL 33610		
Owner's Phone:	8136215528	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CIRCLE K #4060 (Continued)

U001353918

Facility ID:	298508984	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CIRCLE K CORP		
Contact:	Not reported	Facility Phone:	8136898161
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	STEVE BELIN		
Owner:	CIRCLE K STORES INC		
	5650 BRECKENRIDGE PARK DR #300		
	TAMPA, FL 33610		
Owner's Phone:	8136215528	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Gasohol	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

53

**KNI LABORATORIES**  
**3209 TAMPA ST**  
**TAMPA, FL 33603**

**RCRIS-SQG**  
**FINDS**

**1000121828**  
**FLD981021454**

54

**FORD PLUMBING CO., INC.**  
**3201 N FLORIDA AVE**  
**TAMPA, FL 33603**

**UST**

**U001355466**  
**N/A**

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## FORD PLUMBING CO., INC. (Continued)

U001355466

### UST:

Facility ID:	298733837	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FORD PLUMBING CO., INC.		
Contact:	Not reported	Facility Phone:	8132233638
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870729	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	FORD PLUMBING CO INC		
	3201 N FLORIDA AVE		
	TAMPA, FL 336035936		
Owner's Phone:	8132233638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	56/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

55

**C MART #649**  
**3115 N NEBRASKA AVE**  
**TAMPA, FL 33603**

**UST**  
**LUST**

**U001354465**  
**N/A**



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

C MART #649 (Continued)

U001354465

## LUST:

Facility ID:	8625232	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8136844183	Discovery Date:	12/30/88
Tracking Number:	297053	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN	Est. Gallons Lost:	UNKNOWN
------------	---------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C MART #649 (Continued)

U001354465

### UST:

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TROY DALTON		
Owner:	COASTAL CORP		
	9 GREENWAY PLAZA		
	HOUSTON, TX 77046		
Owner's Phone:	7138771400	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**C MART #649 (Continued)**

**U001354465**

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	TROY DALTON		
Owner:	COASTAL CORP		
	9 GREENWAY PLAZA		
	HOUSTON, TX 77046		
Owner's Phone:	7138771400	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C MART #649 (Continued)

U001354465

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	TROY DALTON		
Owner:	COASTAL CORP 9 GREENWAY PLAZA HOUSTON, TX 77046		
Owner's Phone:	7138771400	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C MART #649 (Continued)

U001354465

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	TROY DALTON		
Owner:	COASTAL CORP 9 GREENWAY PLAZA HOUSTON, TX 77046		
Owner's Phone:	7138771400	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C MART #649 (Continued)

U001354465

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	TROY DALTON		
Owner:	COASTAL CORP		
	9 GREENWAY PLAZA		
	HOUSTON, TX 77046		
Owner's Phone:	7138771400	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Gasohol	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**C MART #649 (Continued)**

**U001354465**

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	TROY DALTON		
Owner:	COASTAL CORP		
	9 GREENWAY PLAZA		
	HOUSTON, TX 77046		
Owner's Phone:	7138771400	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C MART #649 (Continued)

U001354465

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	TROY DALTON		
Owner:	COASTAL CORP		
	9 GREENWAY PLAZA		
	HOUSTON, TX 77046		
Owner's Phone:	7138771400	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Gasohol	Contaminated media indicator:	Yes
Disposal Method:	Removed	Instal. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, SPCC plan		

56

CARLSTEDT FLORIST  
3116 N FLORIDA AVE  
TAMPA, FL 33603

UST

U001823435  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CARLSTEDT FLORIST (Continued)

U001823435

### UST:

Facility ID:	299400641	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MARK INGERMAN		
Contact:	Not reported	Facility Phone:	8132249731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940411	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARK INGERMAN		
Owner:	CARLSTEDT CO		
	3116 N FLORIDA AVE		
	TAMPA, FL 33603		
Owner's Phone:	8132249731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	None		

57

TAMPA,CITY-FIRE STATION #10  
3108 N 34TH ST  
TAMPA, FL 33605

UST

U001355924  
N/A

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA,CITY-FIRE STATION #10 (Continued)

U001355924

### UST:

Facility ID:	298842514	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DANIEL A. PAGE		
Owner:	TAMPA CITY DEPT SANITARY SEWERS		
	2700 MARITIME BLVD		
	TAMPA, FL 336056744		
Owner's Phone:	8132473451	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	29/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

58

**SPECIALIZED TRANSPORT**  
**3001 N 36TH ST**  
**TAMPA, FL 33605**

AST

A100008975  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPECIALIZED TRANSPORT (Continued)

A100008975

### AST:

Facility ID:	299100518	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LARRY, L W		
Facility Phone:	8136264166	Permit Section:	Not reported
Date entered:	910225	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	L W LARRY		
Owner:	SPECIALIZED TRANSPORT PO BOX 310716 TAMPA, FL 336800716		
Owner's Phone:	8136264166	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	76/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	92/12	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Dbl walled=primary matl, AST containment area, Concrete		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man tank gauging		

Facility ID:	299100518	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LARRY, L W		
Facility Phone:	8136264166	Permit Section:	Not reported
Date entered:	910225	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	L W LARRY		
Owner:	SPECIALIZED TRANSPORT PO BOX 310716 TAMPA, FL 336800716		
Owner's Phone:	8136264166	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	74/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	92/12	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Dbl walled=primary matl, AST containment area, Concrete		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man tank gauging		

59

SUPREME MOTORS  
3000 N FLORIDA AVE  
TAMPA, FL 33634

UST  
LUST

U002217723  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUPREME MOTORS (Continued)

U002217723

### LUST:

Facility ID:	9501949	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132375289	Discovery Date:	05/11/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	BUREAU OF WASTE CLEANUP
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUPREME MOTORS (Continued)

U002217723

### UST:

Facility ID:	299501949	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM A WEINEL		
Contact:	Not reported	Facility Phone:	8132375289
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950609	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	WILLIAM A WEINEL		
Owner:	WEINEL, WILLIAM A & PEREZ, RICK		
	6430 LARMON ST		
	TAMPA, FL 33634		
Owner's Phone:	8132375289	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	No
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

59

**SUPREME AUTO CTR**  
**3016 N FLORIDA AVE**  
**TAMPA, FL 33603**

**RCRIS-SQG 1000355758**  
**FINDS FLD982162281**

### RCRIS:

Owner: HAWKINS JIM OWNER  
(813) 229-7470

Contact: HAWKINS JIM  
(813) 229-7470

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

60

**SPRING PROPERTY**  
**502 E FLORIBRASKA AVE**  
**TAMPA, FL 33603**

**UST U001356308**  
**LUST N/A**

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPRING PROPERTY (Continued)

U001356308

### LUST:

Facility ID:	9101452	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	4078748184	Discovery Date:	03/29/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
------------	-----------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPRING PROPERTY (Continued)

U001356308

### UST:

Facility ID:	299101452	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SPRING, BRAD		
Contact:	Not reported	Facility Phone:	4078748184
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	BRAD SPRING		
Owner:	SPRING, BRAD		
	601 S ARMENIA AVE		
	TAMPA, FL 336094123		
Owner's Phone:	4078748184	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPRING PROPERTY (Continued)

U001356308

Facility ID:	299101452	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SPRING, BRAD		
Contact:	Not reported	Facility Phone:	4078748184
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	BRAD SPRING		
Owner:	SPRING, BRAD		
	601 S ARMENIA AVE		
	TAMPA, FL 336094123		
Owner's Phone:	4078748184	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPRING PROPERTY (Continued)

U001356308

Facility ID:	299101452	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SPRING, BRAD		
Contact:	Not reported	Facility Phone:	4078748184
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	BRAD SPRING		
Owner:	SPRING, BRAD		
	601 S ARMENIA AVE		
	TAMPA, FL 336094123		
Owner's Phone:	4078748184	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SPRING PROPERTY (Continued)

U001356308

Facility ID:	299101452	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SPRING, BRAD		
Contact:	Not reported	Facility Phone:	4078748184
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	BRAD SPRING		
Owner:	SPRING, BRAD		
	601 S ARMENIA AVE		
	TAMPA, FL 336094123		
Owner's Phone:	4078748184	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

61

**CENTRO ASTURIANO HOSPITAL**  
**1302 E 21ST AVE**  
**TAMPA, FL 33605**

UST

U001355509  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CENTRO ASTURIANO HOSPITAL (Continued)

U001355509

### UST:

Facility ID:	298733897	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	CENTRO ASTURIANO HOSPITAL		
Contact:	Not reported	Facility Phone:	8132474771
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	IGNACIO FERNANDEZ		
Owner:	CENTRO ASTURIANO HOSPITAL 1302 E 21ST AVE TAMPA, FL 336051714		
Owner's Phone:	8132474771	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CENTRO ASTURIANO HOSPITAL (Continued)

U001355509

Facility ID:	298733897	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	CENTRO ASTURIANO HOSPITAL		
Contact:	Not reported	Facility Phone:	8132474771
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	IGNACIO FERNANDEZ		
Owner:	CENTRO ASTURIANO HOSPITAL		
	1302 E 21ST AVE		
	TAMPA, FL 336051714		
Owner's Phone:	8132474771	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

62 ALLSTATE AUTO-RALPH PEREZ  
2926 N NEBRASKA AVE  
TAMPA, FL 33602

UST

U001823430  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ALLSTATE AUTO-RALPH PEREZ (Continued)

U001823430

### UST:

Facility ID:	299400636	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GUILLERMO CONSUEGRA		
Contact:	Not reported	Facility Phone:	8138864158
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940408	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GUILLERMO CONSUEGRA		
Owner:	CONSUEGRA, GUILLERMO		
	7208 N THATCHER AVE		
	TAMPA, FL 33614		
Owner's Phone:	8138864158	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ALLSTATE AUTO-RALPH PEREZ (Continued)

U001823430

Facility ID:	299400636	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GUILLERMO CONSUEGRA		
Contact:	Not reported	Facility Phone:	8138864158
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940408	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GUILLERMO CONSUEGRA		
Owner:	CONSUEGRA, GUILLERMO 7208 N THATCHER AVE TAMPA, FL 33614		
Owner's Phone:	8138864158	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

ALLSTATE AUTO-RALPH PEREZ (Continued)

U001823430

Facility ID:	299400636	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GUILLERMO CONSUEGRA		
Contact:	Not reported	Facility Phone:	8138864158
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940408	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	GUILLERMO CONSUEGRA		
Owner:	CONSUEGRA, GUILLERMO		
	7208 N THATCHER AVE		
	TAMPA, FL 33614		
Owner's Phone:	8138864158	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ALLSTATE AUTO-RALPH PEREZ (Continued)

U001823430

Facility ID:	299400636	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GUILLERMO CONSUEGRA		
Contact:	Not reported	Facility Phone:	8138864158
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940408	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	GUILLERMO CONSUEGRA		
Owner:	CONSUEGRA, GUILLERMO		
	7208 N THATCHER AVE		
	TAMPA, FL 33614		
Owner's Phone:	8138864158	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

63

**JOHNT OF TAMPA**  
**2905 N FLORIDA AVE**  
**TAMPA, FL 33602**

**FINDS**  
**RCRIS-LQG**

**1000219636**  
**FLD073409146**

RCRIS:

Owner: TERRY MCDONALD, MGR  
(813) 229-1949

Contact: TERRY MCDONALD  
(813) 229-1949

Waste	Quantity	Info Source
F001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

64

**TAMPA,CITY-FIRE DEPT COMMUNICATIONS**  
**2904 N MITCHELL AVE**  
**TAMPA, FL 33602**

**UST**  
**LUST**  
**AST**

**U001355890**  
**N/A**



MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

TAMPA,CITY-FIRE DEPT COMMUNICATIONS (Continued)

U001355890

LUST:

Facility ID:	8842212	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132277011	Discovery Date:	12/12/88
Tracking Number:	295180	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT COMMUNICATIONS (Continued)

U001355890

### UST:

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	53/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT COMMUNICATIONS (Continued)

U001355890

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	53/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT COMMUNICATIONS (Continued)

U001355890

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	53/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA,CITY-FIRE DEPT COMMUNICATIONS (Continued)

U001355890

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	6	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

### AST:

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Facility Phone:	8132277011	Permit Section:	Not reported
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	83/11
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	91/03	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA,CITY-FIRE DEPT COMMUNICATIONS (Continued)

U001355890

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Facility Phone:	8132277011	Permit Section:	Not reported
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	5	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	82/04
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	91/03	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Piping/auto shut off		

  

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Facility Phone:	8132277011	Permit Section:	Not reported
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	7	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	88/11
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Level gauges/hi level alarms, Small use tank		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal		
Petro. Monitoring:	DW piping space, Man tank gauging		

65

HOWARD AUTOMOTIVE SERVICE  
2917 N 34TH ST  
TAMPA, FL 33605

UST  
LUST

U001356081  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

### LUST:

Facility ID:	8945488	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132479533	Discovery Date:	06/24/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
------------	-----------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

### UST:

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD 2917 N 34TH ST TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD		
	2917 N 34TH ST		
	TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD		
	2917 N 34TH ST		
	TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD		
	2917 N 34TH ST		
	TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

66

SEACOAST SUPPLY  
2817 N 36TH ST  
TAMPA, FL 33605

UST

U001354849  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SEACOAST SUPPLY (Continued)

U001354849

### UST:

Facility ID:	298625642	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WALT JACKSON		
Contact:	Not reported	Facility Phone:	8132475402
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ED VAN BRUNT		
Owner:	L & W SUPPLY CORP 2817 N 36TH ST TAMPA, FL 336053127		
Owner's Phone:	8132475402	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	74/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SEACOAST SUPPLY (Continued)

U001354849

Facility ID:	298625642	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WALT JACKSON		
Contact:	Not reported	Facility Phone:	8132475402
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ED VAN BRUNT		
Owner:	L & W SUPPLY CORP		
	2817 N 36TH ST		
	TAMPA, FL 336053127		
Owner's Phone:	8132475402	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	79/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

67

ARATEX SERVICES INC  
2817 N 35TH ST  
TAMPA, FL 33605

UST  
LUST

U001355270  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ARATEX SERVICES INC (Continued)

U001355270

### LUST:

Facility ID:	8627781	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132472116	Discovery Date:	12/14/88
Tracking Number:	295372	Score:	035
Facility Code:	Not reported	Status:	Not reported
Rank:	03338		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Y	Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ARATEX SERVICES INC (Continued)

U001355270

### UST:

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotect metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ARATEX SERVICES INC (Continued)

U001355270

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ARATEX SERVICES INC (Continued)

U001355270

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ARATEX SERVICES INC (Continued)

U001355270

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ARATEX SERVICES INC (Continued)

U001355270

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC		
	16001 VENTURA BLVD		
	ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

67

ARAMARK UNIFORM SERVICES  
2817 N 35TH ST  
TAMPA, FL 33605

UST

U002313284  
N/A

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ARAMARK UNIFORM SERVICES (Continued)

U002313284

### UST:

Facility ID:	299502463	Facility Type:	4
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KREJCI, PHIL		
Contact:	Not reported	Facility Phone:	7083979500
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950810	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	KREJCI, PHIL		
Owner:	ARAMARK UNIFORM SERVICES		
	PO BOX 7891		
	BURBANK, CA 91510		
Owner's Phone:	7083979500	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

67

**CHEMEX PAINT & COATINGS INC**  
**2822 N 35TH ST**  
**TAMPA, FL 33605**

UST  
AST

U001355417  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

### UST:

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC		
	PO BOX 5449 % TONY FOSTER		
	TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Instal. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006400	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006400	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

### AST:

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	11	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001500
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	12	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00001500
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	13	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00001500
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	14	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000750
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	15	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00010000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC		
	PO BOX 5449 % TONY FOSTER		
	TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

67	<b>CHEMEX PAINT &amp; COATINGS CO</b> <b>2822 N 35TH ST</b> <b>TAMPA, FL 33675</b>	<b>FINDS</b>	<b>1000733512</b> <b>FLD067222265</b>
	Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production		
68	<b>2818 NORTH ELMOORE AV</b> <b>TAMPA, FL</b>	<b>ERNS</b>	<b>8801808</b> <b>N/A</b>
69	<b>KNL</b> <b>2742 N FLORIDA AVE</b> <b>TAMPA, FL 33601</b>	<b>RCRIS-SQG</b> <b>FINDS</b>	<b>1000100140</b> <b>FLD981025869</b>
70	<b>TEAGARDEN, JEFF</b> <b>2706 N TAMPA ST</b> <b>TAMPA, FL 33602</b>	<b>UST</b>	<b>U001356259</b> <b>N/A</b>



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEAGARDEN, JEFF (Continued)

U001356259

### UST:

Facility ID:	299100904	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TEAGARDEN, JEFF		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910313	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT G LESTER		
Owner:	TEAGARDEN, JEFF		
	2706 N TAMPA ST		
	TAMPA, FL 336021428		
Owner's Phone:	8139962121	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Kerosene	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	40/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TEAGARDEN, JEFF (Continued)

U001356259

Facility ID:	299100904	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TEAGARDEN, JEFF		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910313	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ROBERT G LESTER		
Owner:	TEAGARDEN, JEFF		
	2706 N TAMPA ST		
	TAMPA, FL 336021428		
Owner's Phone:	8139962121	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	40/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TEAGARDEN, JEFF (Continued)

U001356259

Facility ID:	299100904	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TEAGARDEN, JEFF		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910313	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ROBERT G LESTER		
Owner:	TEAGARDEN, JEFF		
	2706 N TAMPA ST		
	TAMPA, FL 336021428		
Owner's Phone:	8139962121	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	40/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

71

**CLOROX CO**  
**3601 E COLUMBUS DR**  
**TAMPA, FL 33605**

**FINDS**  
**TRIS**  
**UST**  
**LUST**  
**AST**

**1000732997**  
**FLD004097945**

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CLOROX CO (Continued)

1000732997

### LUST:

Facility ID:	8627500	Facility Type:	INDUSTRIAL PLANT
Alias Name:	Not reported		
Telephone:	8132481161	Discovery Date:	12/21/89
Tracking Number:	Not reported	Score:	029 (LOW)
Facility Code:	Not reported	Status:	Not reported

Rank: 04761

Class: Not reported

Category: Not reported

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

PLIRP (INSURANCE)

LOCAL PROGRAM

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: UNKNOWN/NOT REPOR

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

PETRO. LIABILITY INS. & RESTOR.

REIMBURSEMENT CLEANUP

ELIGIBLE

Not Reported

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

INCOMPLETE

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CLOROX CO (Continued)

1000732997

### UST:

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Contact:	Not reported	Facility Phone:	8132481161
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO 3601 E COLUMBUS DR TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotc metal		
Petro. Monitoring:	SPCC plan		

### AST:

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO 3601 E COLUMBUS DR TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00015000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	82/12
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CLOROX CO (Continued)

1000732997

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO 3601 E COLUMBUS DR TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	86/04
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrrnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO 3601 E COLUMBUS DR TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	92/09
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrrnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CLOROX CO (Continued)

1000732997

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	5	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	89/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	6	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	86/04
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Secondary containment, Pressurized piping		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CLOROX CO (Continued)

1000732997

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	7	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00016000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	52/07
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Pressurized piping		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	8	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00016000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	52/07
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Pressurized piping		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

71

VAN LEEUWEN PIPE & TUBE OF THE SE INC  
2721 N 36TH ST  
TAMPA, FL 33605

UST  
LUST

U001354634  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

### LUST:

Facility ID:	8625415	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132471151	Discovery Date:	04/17/90
Tracking Number:	Not reported	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

### UST:

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VEHICLE LEASING CORP.		
	P O DRAWER "C"		
	TAMPA, FL 33675		
Owner's Phone:	8132471151	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VEHICLE LEASING CORP. P O DRAWER "C" TAMPA, FL 33675		
Owner's Phone:	8132471151	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VEHICLE LEASING CORP. P O DRAWER "C" TAMPA, FL 33675		
Owner's Phone:	8132471151	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Gasohol	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VEHICLE LEASING CORP.		
	P O DRAWER "C"		
	TAMPA, FL 33675		
Owner's Phone:	8132471151	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

72	FLORIDA PRECAST CONCRETE INC 2705 N 35TH ST TAMPA, FL 33605	FINDS	1000737773 FLD984209502
72	FL PRECAST CONCRETE, INC 2705 N 35TH ST TAMPA, FL 33605	AST	A100008727 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL PRECAST CONCRETE, INC (Continued)

A100008727

### AST:

Facility ID:	298625689	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WATTS,WILLIAM JR		
Facility Phone:	8132476663	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLIAM WATTS JR		
Owner:	FL PRECAST CONCRETE INC		
	2705 N 35TH ST		
	TAMPA, FL 336053121		
Owner's Phone:	8132476663	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000400
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

Facility ID:	298625689	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WATTS,WILLIAM JR		
Facility Phone:	8132476663	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLIAM WATTS JR		
Owner:	FL PRECAST CONCRETE INC		
	2705 N 35TH ST		
	TAMPA, FL 336053121		

Owner's Phone:	8132476663	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000400
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## FL PRECAST CONCRETE, INC (Continued)

A100008727

Facility ID:	298625689	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WATTS,WILLIAM JR		
Facility Phone:	8132476663	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLIAM WATTS JR		
Owner:	FL PRECAST CONCRETE INC		
	2705 N 35TH ST		
	TAMPA, FL 336053121		
Owner's Phone:	8132476663	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000800
Tank Content:	Leaded gas	Contaminated media indicator:	Not reported
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

72	WEIL CHEMICAL TAMPA (CANCEL 1980) 2714 35TH STREET-PO BOX 5527 TAMPA, FL 33605	FINDS	1000932234 FL0000600858
73	DANNY'S GENERATORS 1023 E COLUMBUS DR TAMPA, FL 33605	UST LUST	U001353917 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DANNY'S GENERATORS (Continued)

U001353917

### LUST:

Facility ID:	8508982	Facility Type:	RETAIL STATION
Alias Name:	LATIN AMERICAN SERVICE		
Telephone:	8132291059	Discovery Date:	03/29/91
Tracking Number:	293316	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DANNY'S GENERATORS (Continued)

U001353917

### UST:

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	LATIN AMERICAN STATION		
	1023 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132291059	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	LATIN AMERICAN STATION		
	1023 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132291059	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000200	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	LATIN AMERICAN STATION		
	1023 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132291059	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	LATIN AMERICAN STATION 1023 E COLUMBUS DR TAMPA, FL 33605		
Owner's Phone:	8132291059	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	LATIN AMERICAN STATION		
	1023 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132291059	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000560	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	LATIN AMERICAN STATION		
	1023 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132291059	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000560	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	LATIN AMERICAN STATION 1023 E COLUMBUS DR TAMPA, FL 33605		
Owner's Phone:	8132291059	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000200	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	LATIN AMERICAN STATION		
	1023 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132291059	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000560	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	LATIN AMERICAN STATION 1023 E COLUMBUS DR TAMPA, FL 33605		
Owner's Phone:	8132291059	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	LATIN AMERICAN STATION		
	1023 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132291059	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

74

JD GARAGE  
2701 E COLUMBUS DR  
TAMPA, FL 33605

UST

U001355065  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## JD GARAGE (Continued)

U001355065

### UST:

Facility ID:	298626956	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JADIE SINGLETARY		
Contact:	Not reported	Facility Phone:	8132482592
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861023	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JADIE SINGLETARY		
Owner:	SINGLETARY, JADIE		
	171 LEWIS RD		
	THONOTOSASSA, FL 335929320		
Owner's Phone:	8132482592	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

75

**CLOROX CO**  
**3702 E COLUMBUS DR**  
**TAMPA, FL 33601**

**FINDS** 1000368352  
**RCRIS-LQG** FLD984171470

### RCRIS:

Owner: JOHN PRIEN, ENV COORD  
(813) 248-1161

Contact: DENNIS DONALSON  
(813) 626-3125

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

75

**INTERSTATE WAREHOUSES, LTD.**  
**3701 E COLUMBUS DR**  
**TAMPA, FL 33605**

**UST** U001354108  
**LUST** N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INTERSTATE WAREHOUSES,LTD. (Continued)

U001354108

### LUST:

Facility ID:	8624850	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	06/23/92
Tracking Number:	Not reported	Score:	029 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	04761		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
------------	------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INTERSTATE WAREHOUSES,LTD. (Continued)

U001354108

### UST:

Facility ID:	298624850	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	INTERSTATE WAREHOUSES,LTD.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE W. LACKEY		
Owner:	GEORGIA-PACIFIC CORP.		
	815 S 56TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8136211351	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## INTERSTATE WAREHOUSES,LTD. (Continued)

U001354108

Facility ID:	298624850	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	INTERSTATE WAREHOUSES,LTD.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE W. LACKEY		
Owner:	GEORGIA-PACIFIC CORP.		
	815 S 56TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8136211351	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

76

HILLSBOROUGH CNTY SCHOOL BD-INSTR SERV  
707 E COLUMBUS DR  
TAMPA, FL 33602

UST  
AST

U001355693  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY SCHOOL BD-INSTR SERV (Continued)

U001355693

### UST:

Facility ID:	298736992	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	COUNTERMAN, TOMMY		
Contact:	Not reported	Facility Phone:	8132724710
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871223	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT J AGUIS		
Owner:	HILLSBOROUGH CNTY SCHOOL BD		
	901 E KENNEDY BLVD		
	TAMPA, FL 33601		
Owner's Phone:	8139876994	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

### AST:

Facility ID:	298736992	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	COUNTERMAN, TOMMY		
Facility Phone:	8132724710	Permit Section:	Not reported
Date entered:	871223	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ROBERT J AGUIS		
Owner:	HILLSBOROUGH CNTY SCHOOL BD		
	901 E KENNEDY BLVD		
	TAMPA, FL 33601		
Owner's Phone:	8139876994	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	90/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

77	<b>EMMA BODY PAINT SHOP</b> <b>209 E COLUMBUS ST</b> <b>TAMPA, FL 33602</b>	<b>RCRIS-SQG</b> <b>FINDS</b>	<b>1000141754</b> <b>FLD163275001</b>
----	---	----------------------------------	--

## RCRIS:

Owner: PEDRO AMADOR, OWNER  
(813) 228-7916

Contact: PEDRO AMADOR  
(813) 228-7916

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

78	<b>GAS KWICK #13</b> <b>2601 N TAMPA ST</b> <b>TAMPA, FL 33602</b>	<b>UST</b>	<b>U001354021</b> <b>N/A</b>
----	--	------------	---------------------------------

## UST:

Facility ID:	298624757	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GAS KWICK, INC.	Facility Phone:	8132214312
Contact:	Not reported	Region:	Not reported
Permit Section:	Not reported	Financial responsibility:	Not reported
Facility Code:	No violation	District:	Southwest
Date entered:	860505		
Tank ID:	1		
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GAS KWICK #13 (Continued)

U001354021

Facility ID:	298624757	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GAS KWICK, INC.		
Contact:	Not reported	Facility Phone:	8132214312
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GAS KWICK #13 (Continued)

U001354021

Facility ID:	298624757	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GAS KWICK, INC.		
Contact:	Not reported	Facility Phone:	8132214312
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GAS KWICK #13 (Continued)

U001354021

Facility ID:	298624757	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GAS KWICK, INC.		
Contact:	Not reported	Facility Phone:	8132214312
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

78

C MART #644  
2600 N TAMPA ST  
TAMPA, FL 33602

UST  
LUST

U001355247  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C MART #644 (Continued)

U001355247

### LUST:

Facility ID:	8627683	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8136843844	Discovery Date:	10/01/87
Tracking Number:	292114	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		
INCIDENT GENERAL INFORMATION -			
Source Description:	EDI		
Lead:	LOCAL PROGRAM		
Incident 17-770 Cleanup:	NEW C/U REQUIRED		
INCIDENT POLLUTANT INFORMATION -			
Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
INCIDENT PROGRAM INFORMATION -			
Incident Program:	EARLY DETECTION INCENTIVE		
Incident Program Type:	REIMBURSEMENT CLEANUP		
Incident Eligible Status:	ELIGIBLE		
Incident Ineligible Reason:	Not Reported		
Incident Ineligible Description:	Not reported		
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Y	Alt. Process Date:	Not reported
Soil Treatment:	Y	Alternative Status:	Not reported
Other Treatment:	2ND IRA/12-93. 1 DOD		
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:	Not reported		
Response Record Type:	Not reported		
Response Remedial Action Plan Type:	Not reported		
Response Status:	Not reported		
Extension Record Type:	Not reported		
Extension Status:	Not reported		
Extension Comments:	Not reported		
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:	Not reported		
Response Record Type:	Not reported		
Response Remedial Action Plan Type:	Not reported		
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:	Not reported		
Estimated Completion Year:	Not reported		
Actual Year to Complete:	Not reported		
Report Type:	Not reported		
Report Comments:	Not reported		
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:	Not reported		
Region:	STATE		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C MART #644 (Continued)

U001355247

### UST:

Facility ID:	298627683	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	SAN ANN FOOD STORES INC		
	205 S HOOVER ST #400		
	TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	292114
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## C MART #644 (Continued)

U001355247

Facility ID:	298627683	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	SAN ANN FOOD STORES INC		
	205 S HOOVER ST #400		
	TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	292114
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## C MART #644 (Continued)

U001355247

Facility ID:	298627683	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	SAN ANN FOOD STORES INC		
	205 S HOOVER ST #400		
	TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	292114
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Gasohol	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

79

GOLDSTAR FOODS  
2317 N NEBRASKA AVE  
TAMPA, FL 33605

UST

U001356047  
N/A

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GOLDSTAR FOODS (Continued)

U001356047

### UST:

Facility ID:	298944840	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SHAM RAMCHARAN		
Contact:	Not reported	Facility Phone:	8132235724
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890920	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	SHAM RAMCHARAN		
Owner:	MANGROO, HANSRAJ		
	2317 N NEBRASKA AVE		
	TAMPA, FL 33605		
Owner's Phone:	8132235724	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GOLDSTAR FOODS (Continued)

U001356047

Facility ID:	298944840	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SHAM RAMCHARAN		
Contact:	Not reported	Facility Phone:	8132235724
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890920	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	SHAM RAMCHARAN		
Owner:	MANGROO, HANSRAJ		
	2317 N NEBRASKA AVE		
	TAMPA, FL 33605		
Owner's Phone:	8132235724	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GOLDSTAR FOODS (Continued)

U001356047

Facility ID:	298944840	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SHAM RAMCHARAN		
Contact:	Not reported	Facility Phone:	8132235724
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890920	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	SHAM RAMCHARAN		
Owner:	MANGROO, HANSRAJ 2317 N NEBRASKA AVE TAMPA, FL 33605		
Owner's Phone:	8132235724	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GOLDSTAR FOODS (Continued)

U001356047

Facility ID:	298944840	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SHAM RAMCHARAN		
Contact:	Not reported	Facility Phone:	8132235724
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890920	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	SHAM RAMCHARAN		
Owner:	MANGROO, HANSRAJ 2317 N NEBRASKA AVE TAMPA, FL 33605		
Owner's Phone:	8132235724	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Kerosene	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

79

GENES SERVICE  
2318 N NEBRASKA AVE  
TAMPA, FL 33602

UST

U001354940  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GENES SERVICE (Continued)

U001354940

### UST:

Facility ID:	298625737	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DE LA PARTE EUGENE		
Contact:	Not reported	Facility Phone:	8132287172
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	EUGENE DE LA PARTE		
Owner:	DE LA PARTE, EUGENE		
	2318 N NEBRASKA AVE		
	TAMPA, FL 336021724		
Owner's Phone:	8132287172	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GENES SERVICE (Continued)

U001354940

Facility ID:	298625737	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DE LA PARTE EUGENE		
Contact:	Not reported	Facility Phone:	8132287172
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	EUGENE DE LA PARTE		
Owner:	DE LA PARTE, EUGENE		
	2318 N NEBRASKA AVE		
	TAMPA, FL 336021724		
Owner's Phone:	8132287172	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GENES SERVICE (Continued)

U001354940

Facility ID:	298625737	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DE LA PARTE EUGENE		
Contact:	Not reported	Facility Phone:	8132287172
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	EUGENE DE LA PARTE		
Owner:	DE LA PARTE, EUGENE		
	2318 N NEBRASKA AVE		
	TAMPA, FL 336021724		
Owner's Phone:	8132287172	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001036	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Unknown/not reported		

80

TAMPA,CITY-FIRE DEPT SUPPLY DIVISION  
2611 N 12TH ST  
TAMPA, FL 33605

UST

U001355930  
N/A

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA,CITY-FIRE DEPT SUPPLY DIVISION (Continued)

U001355930

### UST:

Facility ID:	298842520	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881229	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

81

C MART #643  
2309 N NEBRASKA AVE  
TAMPA, FL 33602

UST

U001353894  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C MART #643 (Continued)

U001353894

### UST:

Facility ID:	298508941	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	7138771400
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	EASTERN OIL CO		
	205 S HOOVER ST #400		
	TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## C MART #643 (Continued)

U001353894

Facility ID:	298508941	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	7138771400
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	EASTERN OIL CO		
	205 S HOOVER ST #400		
	TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C MART #643 (Continued)

U001353894

Facility ID:	298508941	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	7138771400
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	EASTERN OIL CO		
	205 S HOOVER ST #400		
	TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C MART #643 (Continued)

U001353894

Facility ID:	298508941	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	7138771400
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	EASTERN OIL CO		
	205 S HOOVER ST #400		
	TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## C MART #643 (Continued)

U001353894

Facility ID:	298508941	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	7138771400
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	J STYLES WILSON		
Owner:	EASTERN OIL CO		
	205 S HOOVER ST #400		
	TAMPA, FL 336093521		
Owner's Phone:	8132862323	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

82

KASH N KARRY FOOD STORE  
2301 N FLORIDA AVE  
TAMPA, FL 33602

UST

U001356130  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N KARRY FOOD STORE (Continued)

U001356130

### UST:

Facility ID:	299046103	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N KARRY FOOD STORES INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARK STEWART		
Owner:	KASH N KARRY FOOD STORES INC		
	6422 HARNEY RD		
	TAMPA, FL 33680		
Owner's Phone:	8136210297	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N KARRY FOOD STORE (Continued)

U001356130

Facility ID:	299046103	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N KARRY FOOD STORES INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MARK STEWART		
Owner:	KASH N KARRY FOOD STORES INC		
	6422 HARNEY RD		
	TAMPA, FL 33680		
Owner's Phone:	8136210297	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N KARRY FOOD STORE (Continued)

U001356130

Facility ID:	299046103	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N KARRY FOOD STORES INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MARK STEWART		
Owner:	KASH N KARRY FOOD STORES INC		
	6422 HARNEY RD		
	TAMPA, FL 33680		
Owner's Phone:	8136210297	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

83

MCEWEN LUMBER CO.  
2620 N 36TH ST  
TAMPA, FL 33605

UST  
LUST

U001355095  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MCEWEN LUMBER CO. (Continued)

U001355095

## LUST:

Facility ID:	8627033	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	10/29/87
Tracking Number:	292224	Score:	009 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07115		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
------------	------------------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	DISTRICT OFFICE
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## MCEWEN LUMBER CO. (Continued)

U001355095

### UST:

Facility ID:	298627033	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MCEWEN LUMBER CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIMI IPPOLITO		
Owner:	MCEWEN LUMBER CO #2		
	2620 N 36TH ST		
	TAMPA, FL 336053114		
Owner's Phone:	8132484111	Tracking #:	292224
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MCEWEN LUMBER CO. (Continued)

U001355095

Facility ID:	298627033	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MCEWEN LUMBER CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JIMI IPPOLITO		
Owner:	MCEWEN LUMBER CO #2		
	2620 N 36TH ST		
	TAMPA, FL 336053114		
Owner's Phone:	8132484111	Tracking #:	292224
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

84

**OLD 97 COMPANY**  
2306 35TH ST  
TAMPA, FL 33605

**FINDS**

1000496908  
FLD004091427

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

84

**REDI STRIP OF CENTRAL FLORIDA**  
2402 N 35TH ST  
TAMPA, FL 33605

**RCRIS-SQG**  
**FINDS**

1000245031  
FLD021115837

85

**WEYERHAEUSER CO.**  
2307 N 36TH ST  
TAMPA, FL 33605

**UST**  
**LUST**

U001354504  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WEYERHAEUSER CO. (Continued)

U001354504

### LUST:

Facility ID:	8625274	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132476671	Discovery Date:	01/10/90
Tracking Number:	Not reported	Score:	009 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	08492		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## WEYERHAEUSER CO. (Continued)

U001354504

### UST:

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO		
	PO BOX 16909		
	TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WEYERHAEUSER CO. (Continued)

U001354504

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO		
	PO BOX 16909		
	TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## WEYERHAEUSER CO. (Continued)

U001354504

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO		
	PO BOX 16909		
	TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## WEYERHAEUSER CO. (Continued)

U001354504

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO		
	PO BOX 16909		
	TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WEYERHAEUSER CO. (Continued)

U001354504

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO PO BOX 16909 TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

86

**KAMALA AUTO TRADE**  
**2211 N 38TH ST**  
**TAMPA, FL 33603**

**RCRIS-SQG 1000821508**  
**FINDS FLD984244780**

RCRIS:

Owner: MIKE JERRORICH  
(813) 247-5811

Contact: MIKE JERRORICH  
(813) 247-5811

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D007	.00000 (T)	Notification	D008	.00000 (T)	Notification
D018	.00000 (T)	Notification	D021	.00000 (T)	Notification
D027	.00000 (T)	Notification	D039	.00000 (T)	Notification
D040	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

87

**TAMPA INDEPENDENT DAIRY**  
**3725 E 10TH AVE**  
**TAMPA, FL 33605**

**UST**  
**LUST**

**U001354964**  
**N/A**



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

### LUST:

Facility ID:	8625761	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132231999	Discovery Date:	08/15/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

### UST:

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Abvgrnd-no contact w/soil, Cathod prot steel, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Abvgrnd-no contact w/soil, Cathod prot steel, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Dbl/wall=primary matl		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	5R1
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	5R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	5	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

88

## TARGET AUTO & TRUCK SERVICE 2104 34TH ST N TAMPA, FL 33605

RCRIS-SQG 1000821269  
FINDS FLD984241885

### RCRIS:

Owner: JOHN CORRICA  
(813) 248-5145

Contact:JOHN CORRICA  
(813) 248-5145

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D007	.00000 (T)	Notification	D008	.00000 (T)	Notification
D021	.00000 (T)	Notification	D027	.00000 (T)	Notification
D039	.00000 (T)	Notification	D040	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

89

## TAMPA ELECTRO PLATING INC 3005 E 10TH AVE TAMPA, FL 33605

RCRIS-SQG 1000344862  
FINDS FLD982117871

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number						
90	<b>AMERICAN FLEET SVC</b> <b>2326 E 7TH AV</b> <b>TAMPA, FL 33675</b>  RCRIS: Owner: RICK FAULKENBERG (813) 248-6510  Contact: RICK FAULKENBERG (813) 248-6510  <table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D001</td><td>.00000 (T)</td><td>Notification</td></tr></table> (P) = Pounds ,    (K) = Kilograms ,    (M) = Metric Tons ,    (T) = Tons ,    (N) = Not Reported	Waste	Quantity	Info Source	D001	.00000 (T)	Notification	<b>RCRIS-SQG</b> <b>FINDS</b>	<b>1000359166</b> <b>FLD982138885</b>
Waste	Quantity	Info Source							
D001	.00000 (T)	Notification							
90	<b>GARCIA'S INSTANT SERVICE</b> <b>2323 E 7TH AVE</b> <b>TAMPA, FL 33605</b>	<b>UST</b> <b>LUST</b>	<b>U001354646</b> <b>N/A</b>						

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARCIA'S INSTANT SERVICE (Continued)

U001354646

### LUST:

Facility ID:	8625427	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8139337851	Discovery Date:	03/18/91
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	OTHER

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARCIA'S INSTANT SERVICE (Continued)

U001354646

### UST:

Facility ID:	298625427	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KEY BANK OF FL		
Contact:	Not reported	Facility Phone:	8139337851
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOSIE C KINNEY		
Owner:	KEY BANK OF FLORIDA		
	PO BOX 151317		
	TAMPA, FL 336841317		
Owner's Phone:	8139337851	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	62/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GARCIA'S INSTANT SERVICE (Continued)

U001354646

Facility ID:	298625427	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KEY BANK OF FL		
Contact:	Not reported	Facility Phone:	8139337851
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOSIE C KINNEY		
Owner:	KEY BANK OF FLORIDA		
	PO BOX 151317		
	TAMPA, FL 336841317		
Owner's Phone:	8139337851	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	62/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GARCIA'S INSTANT SERVICE (Continued)

U001354646

Facility ID:	298625427	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KEY BANK OF FL		
Contact:	Not reported	Facility Phone:	8139337851
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOSIE C KINNEY		
Owner:	KEY BANK OF FLORIDA		
	PO BOX 151317		
	TAMPA, FL 336841317		
Owner's Phone:	8139337851	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	62/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

90

FLORIDA BUILDERS - VACANT  
1701 N 20TH ST  
TAMPA, FL 33605

UST  
LUST

U001823379  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FLORIDA BUILDERS - VACANT (Continued)

U001823379

### LUST:

Facility ID:	9400234	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	FLORIDA BUILDERS - VACANT		
Telephone:	8136848402	Discovery Date:	12/01/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	KEROSENE	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FLORIDA BUILDERS - VACANT (Continued)

U001823379

### UST:

Facility ID:	299400234	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LOUISE JACKSON		
Contact:	Not reported	Facility Phone:	8136848402
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940221	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LOUISE JACKSON		
Owner:	DIAZ, LOUSIE PROPERTY		
	2401 BAYSHORE BLVD		
	TAMPA, FL 33629		
Owner's Phone:	8139612727	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## FLORIDA BUILDERS - VACANT (Continued)

U001823379

Facility ID:	299400234	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LOUISE JACKSON		
Contact:	Not reported	Facility Phone:	8136848402
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940221	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	LOUISE JACKSON		
Owner:	DIAZ, LOUSIE PROPERTY 2401 BAYSHORE BLVD TAMPA, FL 33629		
Owner's Phone:	8139612727	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000250	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

91

**MACALUSO & MACALUSO**  
**2915 E 7TH AVE**  
**TAMPA, FL 33605**

UST  
LUST

U001356231  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MACALUSO & MACALUSO (Continued)

U001356231

### LUST:

Facility ID:	9100495	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132381429	Discovery Date:	02/01/91
Tracking Number:	Not reported	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06571		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MACALUSO & MACALUSO (Continued)

U001356231

### UST:

Facility ID:	299100495	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MACALUSO, LENA		
Contact:	Not reported	Facility Phone:	8132381429
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910222	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LENA MACALUSO		
Owner:	MACALUSO, LENA		
	4810 N SHIRLEY DR		
	TAMPA, FL 336031724		
Owner's Phone:	8132381429	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## MACALUSO & MACALUSO (Continued)

U001356231

Facility ID:	299100495	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MACALUSO, LENA		
Contact:	Not reported	Facility Phone:	8132381429
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910222	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	LENA MACALUSO		
Owner:	MACALUSO, LENA 4810 N SHIRLEY DR TAMPA, FL 336031724		
Owner's Phone:	8132381429	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

91

ANTHONY DISTRIBUTORS, INC.  
2900 E 7TH AVE  
TAMPA, FL 33605

UST  
LUST

U001354664  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANTHONY DISTRIBUTORS, INC. (Continued)

U001354664

### LUST:

Facility ID:	8625445	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132474000	Discovery Date:	09/15/93
Tracking Number:	292469	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANTHONY DISTRIBUTORS, INC. (Continued)

U001354664

### UST:

Facility ID:	298625445	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	ANTHONY DISTRIBUTORS, INC.		
Contact:	Not reported	Facility Phone:	8132474000
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE SANDS		
Owner:	ANTHONY DISTRIBUTORS INC		
	2900 EAST 7TH AVE		
	TAMPA, FL 33605		
Owner's Phone:	8132297191	Tracking #:	292469
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ANTHONY DISTRIBUTORS, INC. (Continued)

U001354664

Facility ID:	298625445	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	ANTHONY DISTRIBUTORS, INC.		
Contact:	Not reported	Facility Phone:	8132474000
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE SANDS		
Owner:	ANTHONY DISTRIBUTORS INC 2900 EAST 7TH AVE TAMPA, FL 33605		
Owner's Phone:	8132297191	Tracking #:	292469
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ANTHONY DISTRIBUTORS, INC. (Continued)

U001354664

Facility ID:	298625445	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	ANTHONY DISTRIBUTORS, INC.		
Contact:	Not reported	Facility Phone:	8132474000
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	GEORGE SANDS		
Owner:	ANTHONY DISTRIBUTORS INC		
	2900 EAST 7TH AVE		
	TAMPA, FL 33605		
Owner's Phone:	8132297191	Tracking #:	292469
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

92

## CHAMPION FLEET SERVICE INC 3313 E 7TH AVE TAMPA, FL 33605

RCRIS-SQG 1000501844  
FINDS FLD984219865

### RCRIS:

Owner: JIM CHAMPION  
(813) 247-3971

Contact: JIM CHAMPION  
(813) 247-3971

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D008	.00000 (T)	Notification
D018	.00000 (T)	Notification	D039	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

92

## CHAMPION FLEET SERVICE 3304 E 7TH AVE TAMPA, FL 33605

UST U001355348  
LUST N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHAMPION FLEET SERVICE (Continued)

U001355348

### LUST:

Facility ID:	8628880	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132475964	Discovery Date:	12/04/89
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	KEROSENE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHAMPION FLEET SERVICE (Continued)

U001355348

### UST:

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPON JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHAMPION FLEET SERVICE (Continued)

U001355348

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPON JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CHAMPION FLEET SERVICE (Continued)

U001355348

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPON JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CHAMPION FLEET SERVICE (Continued)

U001355348

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPON JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CHAMPION FLEET SERVICE (Continued)

U001355348

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPON JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CHAMPION FLEET SERVICE (Continued)

U001355348

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPON JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

93	<b>RALSTON PURINA</b> 3615 E 7TH AVE TAMPA, FL 33605	<b>FINDS</b>	1000496906 FLD004090742
	Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act		
94	<b>AAA METAL REFINISHING &amp; CHROME</b> 3012 E 7TH AVE TAMPA, FL 33605	<b>FINDS</b>	1000933569 FL0000890491
94	<b>AAA METAL REFINISHING &amp; CHROME</b> 3012 E 7TH AVE TAMPA, FL 33605	<b>RCRIS-SQG</b>	1000978634 FL0000890491

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## AAA METAL REFINISHING & CHROME (Continued)

1000978634

### RCRIS:

Owner: JAIME REGALADO OWNER  
(813) 247-2190

Contact: JAIME REGALADO  
(813) 247-2190

Waste	Quantity	Info Source
-------	----------	-------------

D000	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

95

**CSX TRANSPORTATION INC-RALSTON PURINA**  
**3702 E BROADWAY AVE**  
**TAMPA, FL 33605**

AST

A100008991  
N/A

### AST:

Facility ID:	299101417	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CSX TRANSPORTATION INC		
Facility Phone:	9043591651	Permit Section:	Not reported
Date entered:	910401	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	K W RICHARDSON JR		
Owner:	CSX TRANSPORTATION INC J275		
	500 WATER ST		
	JACKSONVILLE, FL 32202		
Owner's Phone:	9043591986	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	91/03	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

96

**FLORAL DRY CLEANERS & LAUNDRY**  
**3810 EAST 7TH AVE**  
**TAMPA, FL**

RCRIS-SQG

1000700386  
FLD982106544

96

**FLORAL DRY CLEANERS & LAUNDRY**  
**3810 E 7TH AVE**  
**TAMPA, FL 33691**

FINDS  
UST

1000735137  
FLD982106544

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FLORAL DRY CLEANERS & LAUNDRY (Continued)

1000735137

### UST:

Facility ID:	299500880	Facility Type:	1
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	JISUNG LEE		
Contact:	Not reported	Facility Phone:	8132486439
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	850601	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	FONTE, JOE		
Owner:	JOE FONTE		
	3916 WATROUS AVE		
	TAMPA, FL 33609		
Owner's Phone:	8132890212	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

97	<b>KAISER AGRICULTURAL CHEMICALS</b> 1606 35TH ST TAMPA, FL 33605	<b>FINDS</b>	1000933451 FLD000682989
98	<b>GRACE W R &amp; CO PESTICIDES WARE</b> 1604 36TH ST TAMPA, FL 33601  Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	<b>FINDS</b>	1000732723 FLD000653477
98	<b>FLORIDA IRON &amp; METAL</b> 1603 36TH ST TAMPA, FL 33601  Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	<b>FINDS</b>	1000497138 FLD032759656

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
98	<b>KIMMINS RECYCLING (TAMPA)</b> 1604 N 36TH ST TAMPA, FL	SWF/LF	S101011585 N/A
	LF: Facility ID: 4029P30087 Population Served: 750,000 PERSONS Amount Daily Waste: 200 TON Facility Telephone: (813) 248-3878	Facility Status: ACTIVE Design Capacity: 0.0000 Number of Monitoring Wells: 0 WELLS Facility Contact: KIMMINS CONTRACTING CORP	
98	<b>GRACE &amp; CO,WR</b> 1604 N 36TH ST TAMPA, FL 33605	UST	U001354950 N/A
	UST: Facility ID: 298625747 Is fac. regulated: Not regulated facility Operator: GRACE & CO,WR Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860523 Tank ID: 1 Owner's Contact: MARTIN A.STRICKLER Owner: W R GRACE & CO TAMPA PO BOX 1210 FORT PIERCE, FL 349541210 Owner's Phone: 8132483101 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00002000 Tank position: Underground Tank Content: Unleaded gas Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Eligibility: Not reported Permit Number: Not reported Class: Not reported Category: Not reported Tank Constr.: Bare/asph steel Tank Piping: Unprotoc metal Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132483101 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: Not reported Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported Eligible Date: Not reported	

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GRACE & CO,WR (Continued)

U001354950

Facility ID:	298625747	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132483101
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA PO BOX 1210 FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GRACE & CO,WR (Continued)

U001354950

Facility ID:	298625747	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132483101
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA		
	PO BOX 1210		
	FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GRACE & CO,WR (Continued)

U001354950

Facility ID:	298625747	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132483101
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA PO BOX 1210 FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	40/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

98

KIMMINS RECYCLING FACILITY OF TAMPA  
1604 N 36TH ST  
TAMPA, FL 33605

UST

U002113435  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KIMMINS RECYCLING FACILITY OF TAMPA (Continued)

U002113435

### UST:

Facility ID:	299501536	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	CHARLES A BAKER JR		
Contact:	Not reported	Facility Phone:	8132483878
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950306	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	WINA WHITE		
Owner:	KIMMINS RECYCLING CORP 790 HILLBRATH DR LANTANA, FL 33462		
Owner's Phone:	8132483878	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

99

**KAISER ALUMINUM & CHEMICAL**  
1601 34TH ST  
TAMPA, FL 33605

FINDS

1000497717  
FLD087505806

100

**ALL AMERICAN CUSTOM CHROME INC**  
3211 5TH AVE  
TAMPA, FL 33605

RCRIS-SQG

1000859231  
FLD984220418

### RCRIS:

Owner: MIKE REYNOLDS, PLT MGR  
(813) 248-6221

Contact: MIKE REYNOLDS  
(813) 248-6221

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D007	.00000 (T)	Notification
F006	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ALL AMERICAN CUSTOM CHROME INC (Continued)

1000859231

There are 4 compliance/violation record(s) reported at this site:

Evaluation	Date	Violations
COMPLIANCE SCHEDULE EVALUATION (CSE)	12-JAN-95	YES
COMPLIANCE SCHEDULE EVALUATION (CSE)	22-SEP-94	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	23-AUG-94	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	07-JUL-93	YES

100	ALL AMERICAN CUSTOM CHROME INC 3211 E 5TH AVENUE TAMPA, FL 33605	FINDS	1000501895 FLD984220418
-----	--	-------	----------------------------

100	CROWN WINDOW CO. 3204 E 5TH AVE TAMPA, FL 33605	UST	U001354371 N/A
-----	---	-----	-------------------

### UST:

Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO. 3204 E 5TH AVE TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CROWN WINDOW CO. (Continued)

U001354371

Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO.		
	3204 E 5TH AVE		
	TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CROWN WINDOW CO. (Continued)

U001354371

Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO.		
	3204 E 5TH AVE		
	TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CROWN WINDOW CO. (Continued)

U001354371

Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO.		
	3204 E 5TH AVE		
	TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

101 FL MISCELLANEOUS STEEL PRODUCTS INC  
2710 E 5TH AVE  
TAMPA, FL 33605

AST

A100008728  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL MISCELLANEOUS STEEL PRODUCTS INC (Continued)

A100008728

### AST:

Facility ID:	298625694	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL MISCELLANEOUS STEEL PRODUCTS		
Facility Phone:	8132485222	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE DONALDSON		
Owner:	FL MISCELLANEOUS STEEL PRODUCTS		
	PO BOX 5208		
	TAMPA, FL 336755208		
Owner's Phone:	8132485222	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00003000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	84/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	89/09	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

Facility ID:	298625694	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL MISCELLANEOUS STEEL PRODUCTS		
Facility Phone:	8132485222	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE DONALDSON		
Owner:	FL MISCELLANEOUS STEEL PRODUCTS		
	PO BOX 5208		
	TAMPA, FL 336755208		
Owner's Phone:	8132485222	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00003000
Tank Content:	Unleaded gas	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	84/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	89/09	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

101

FLORIDA STRUCTURAL STEEL  
2710 5TH AVE  
TAMPA, FL 33675

RCRIS-SQG 1000700607  
FLD982134470

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FLORIDA STRUCTURAL STEEL (Continued)

1000700607

RCRIS:

Owner: STEPHEN MCGEE, OP MGR  
(813) 623-2675

Contact: STEPHEN MCGEE  
(813) 248-5222

Waste	Quantity	Info Source	Waste	Quantity	Info Source
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

There are 2 compliance/violation record(s) reported at this site:

Evaluation	Date	Violations
COMPLIANCE SCHEDULE EVALUATION (CSE)	07-OCT-94	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	07-JUL-94	YES

102

**TAMPA BAY CLEANERS SUPPLY**  
**2302 E 5TH AVE**  
**TAMPA, FL 33605**

**RCRIS-SQG**  
**FINDS**  
**UST**

**1000461142**  
**FLD984188482**

RCRIS:

Owner: DICK QUEIPO, MGR  
(813) 247-6332

Contact: DICK QUEIPO  
(813) 247-6332

Waste	Quantity	Info Source
F002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA BAY CLEANERS SUPPLY (Continued)

1000461142

### UST:

Facility ID:	299502055	Facility Type:	2
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	DAVID PILGER		
Contact:	Not reported	Facility Phone:	3053240410
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950706	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	PILGER, DAVID		
Owner:	DAVID & WILLIAM PILGER		
	2055 NW 7TH AVE		
	MIAMI, FL 33127		
Owner's Phone:	3053240410	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

103

KEN ROBINSON OF FL INC  
3225 E 4TH AVE  
TAMPA, FL 33605

UST  
LUST

U001355860  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KEN ROBINSON OF FL INC (Continued)

U001355860

### LUST:

Facility ID:	8841810	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132481711	Discovery Date:	05/19/92
Tracking Number:	Not reported	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported

Rank: 06114

Class: Not reported

Category: Not reported

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

COMBINED C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

RESPONSIBLE PARTY-NO CLAIM

Not reported

Not reported

Not Reported

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KEN ROBINSON OF FL INC (Continued)

U001355860

### UST:

Facility ID:	298841810	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROBINSON KEN		
Contact:	Not reported	Facility Phone:	8132481711
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881017	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	KEN ROBINSON		
Owner:	ROBINSON, CHRIS & KEN PO BOX 75302 TAMPA, FL 336750302		
Owner's Phone:	8132481711	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

104

RED HOGAN ENTERPRISES INC  
3109 E 4TH AVE  
TAMPA, FL 33605

UST  
LUST

U001356338  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RED HOGAN ENTERPRISES INC (Continued)

U001356338

### LUST:

Facility ID:	9101913	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132483428	Discovery Date:	06/17/92
Tracking Number:	Not reported	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RED HOGAN ENTERPRISES INC (Continued)

U001356338

### UST:

Facility ID:	299101913	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HOGAN, THOMAS L	Facility Phone:	8132483428
Contact:	Not reported	Region:	Not reported
Permit Section:	Not reported	Financial responsibility:	None
Facility Code:	No violation	District:	Southwest
Date entered:	910430		
Tank ID:	1		
Owner's Contact:	THOMAS L HOGAN		
Owner:	HOGAN, THOMAS L		
	PO BOX 13201		
	TAMPA, FL 33681		
Owner's Phone:	8132483428	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

105

**AUTOMATIC SPRINKLERS INC**  
**2625 E 4TH AVE**  
**TAMPA, FL 33605**

**UST**  
**LUST**

**U001962955**  
**N/A**

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AUTOMATIC SPRINKLERS INC (Continued)

U001962955

### LUST:

Facility ID:	9401418	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138373009	Discovery Date:	07/19/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION

STATE CLEANUP

ELIGIBLE

Not Reported

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AUTOMATIC SPRINKLERS INC (Continued)

U001962955

### UST:

Facility ID:	299401418	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	8138373009
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940812	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	W A KRUZEN		
Owner:	GENERAL MANAGEMENT DEVELOPMENT		
	2909 BAY TO BAY BLVD #600		
	TAMPA, FL 33629		
Owner's Phone:	8138373009	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

106	<b>AUTH APPLIANCE RECYCLING CTR</b> 2403 4TH AVE TAMPA, FL 33609	<b>FINDS</b>	1000931762 FL0000304279
-----	--	--------------	----------------------------

107	<b>SCRAP ALL</b> 2801 4TH AVE TAMPA, FL 33602	<b>FINDS</b>	1000497504 FLD067220566
-----	---	--------------	----------------------------

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act

108	<b>PITCH PINE LUMBER</b> 1607 N 43RD ST TAMPA, FL 33605	<b>SHWS</b>	S101136993 N/A
-----	---	-------------	-------------------

### SHWS:

Facility ID:	99	NPL/State Site:	STATE
Permit Section:	Not reported	Cleanup Date:	Not reported
Cleanup Phase:	Not reported	Facility Status:	DENIED
Discharge Violation:	Not reported		

109	<b>GTE OF FL TAMPA</b> 3704 E 3RD AVE TAMPA, FL 33605	<b>UST LUST</b>	U001355733 N/A
-----	---	---------------------	-------------------

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GTE OF FL TAMPA (Continued)

U001355733

### LUST:

Facility ID: 8837677 Facility Type: NON-RETAIL BUSINESS  
Alias Name: GENERAL TELEPHONE CO OF FL  
Telephone: 8136214931 Discovery Date: 09/10/93  
Tracking Number: Not reported Score: 000 (LOW)  
Facility Code: Not reported Status: Not reported

Rank: 00000  
Class: Not reported  
Category: Not reported

### INCIDENT GENERAL INFORMATION -

Source Description: CLOSURE REPORT  
Lead: LOCAL PROGRAM  
Incident 17-770 Cleanup: NO C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program: RESPONSIBLE PARTY-NO CLAIM  
Incident Program Type: Not reported  
Incident Eligible Status: Not reported  
Incident Ineligible Reason: Not Reported  
Incident Ineligible Description: Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product: Cleanup Responsible: Not reported  
Soil Removal: Alt. Process Date: Not reported  
Soil Treatment: Alternative Status: Not reported  
Other Treatment:

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible: Not reported  
Response Record Type: Not reported  
Response Remedial Action Plan Type: Not reported  
Response Status: Not reported  
Extension Record Type: Not reported  
Extension Status: Not reported  
Extension Comments: Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible: Not reported  
Response Record Type: Not reported  
Response Remedial Action Plan Type: Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible: Not reported  
Estimated Completion Year: Not reported  
Actual Year to Complete: Not reported  
Report Type: Not reported  
Report Comments: Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action: Not reported  
Region: STATE



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GTE OF FL TAMPA (Continued)

U001355733

### UST:

Facility ID:	298837677	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GENERAL TELEPHONE CO OF FL	Facility Phone:	8136214931
Contact:	Not reported	Region:	Not reported
Permit Section:	Not reported	Financial responsibility:	Oth Apprvd Coverage
Facility Code:	No violation	District:	Southwest
Date entered:	880115		
Tank ID:	1		
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	87/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Dbl walled=primary matl		
Tank Piping:	Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Piping/auto shut off, Piping/flow restrictor		

110

GRACE & CO,WR-CONSTRUCTION PROD DIV  
3501 E 3RD AVE  
TAMPA, FL 33605

UST

U001355271  
N/A

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GRACE & CO,WR-CONSTRUCTION PROD DIV (Continued)

U001355271

### UST:

Facility ID:	298627813	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132481554
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA		
	PO BOX 1210		
	FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	87/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

111

LALA PRODUCE CO.  
1402 N 25TH ST  
TAMPA, FL 33605

UST

U001354571  
N/A

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## LALA PRODUCE CO. (Continued)

U001354571

### UST:

Facility ID:	298625349	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LALA PRODUCE CO.	Facility Phone:	8132473168
Contact:	Not reported	Region:	Not reported
Permit Section:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Facility Code:	No violation	District:	Southwest
Date entered:	860516		
Tank ID:	1		
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	82/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

112	QUALITY ELECTRIC SUPPLY INC 1400 N 34TH ST TAMPA, FL 33605	FINDS	1000933527 FL0000748079
113	BLISS PRODUCE 3119 E 3RD AVE TAMPA, FL 33605	UST LUST	U001355081 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BLISS PRODUCE (Continued)

U001355081

### LUST:

Facility ID:	8627006	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	09/29/89
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BLISS PRODUCE (Continued)

U001355081

### UST:

Facility ID:	298627006	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BLISS, CHARLES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BLISS PRODUCE (Continued)

U001355081

Facility ID:	298627006	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BLISS, CHARLES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BLISS PRODUCE (Continued)

U001355081

Facility ID:	298627006	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BLISS, CHARLES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

114

DEL RIO PRODUCTS  
2601 E 2ND AVE  
TAMPA, FL 33605

UST

U001354313  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEL RIO PRODUCTS (Continued)

U001354313

### UST:

Facility ID:	298625072	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEL RIO PRODUCTS		
Contact:	Not reported	Facility Phone:	8132474534
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAN TRIPLETT		
Owner:	DEL RIO PRODUCTS		
	PO BOX 75245		
	TAMPA, FL 336750245		
Owner's Phone:	8132474534	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

115

WALKER CO./SOL  
1110 N 35TH ST  
TAMPA, FL 33605

UST

U001354591  
N/A



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## WALKER CO./SOL (Continued)

U001354591

### UST:

Facility ID:	298625371	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOL WALKER & CO.		
Contact:	Not reported	Facility Phone:	8132485796
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARY T. CACKLING		
Owner:	SOL WALKER & CO		
	PO BOX 5447		
	TAMPA, FL 336755447		
Owner's Phone:	8132485796	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	70/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

116

DIXIE PLYWOOD CO OF TAMPA INC  
3021 ADAMO DR  
TAMPA, FL 33605

UST  
LUST

U001354314  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DIXIE PLYWOOD CO OF TAMPA INC (Continued)

U001354314

### LUST:

Facility ID:	8625073	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132484107	Discovery Date:	01/17/90
Tracking Number:	Not reported	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06719		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DIXIE PLYWOOD CO OF TAMPA INC (Continued)

U001354314

### UST:

Facility ID:	298625073	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DIXIE PLYWOOD CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132484107
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ED CAMPBELL		
Owner:	DIXIE PLYWOOD CO TAMPA PO BOX 5718 TAMPA, FL 336755718		
Owner's Phone:	8132484107	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	84/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## DIXIE PLYWOOD CO OF TAMPA INC (Continued)

U001354314

Facility ID:	298625073	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DIXIE PLYWOOD CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132484107
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ED CAMPBELL		
Owner:	DIXIE PLYWOOD CO TAMPA		
	PO BOX 5718		
	TAMPA, FL 336755718		
Owner's Phone:	8132484107	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	84/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

117 UNION CARBIDE CORP.-LINDE DIVISION  
ADAMO DR & 31ST ST  
TAMPA, FL 33605

UST

U001355413  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNION CARBIDE CORP.-LINDE DIVISION (Continued)

U001355413

### UST:

Facility ID:	298732613	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNION CARBIDE CORP.		
Contact:	Not reported	Facility Phone:	8132476467
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	W.J. WESTFALL		
Owner:	UNION CARBIDE CORP. 39 OLD RIDGEBURY RD DANBURY, CT 068170001		
Owner's Phone:	8132476467	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

117

**PRAYAIR INC**  
**3100 ADAMO DR**  
**TAMPA, FL 33605**

**RCRIS-SQG**  
**FINDS**

**1000986052**  
**FL0001046275**

### RCRIS:

Owner: ARTHUR THOMAS, OPERA SUPV  
(813) 247-5317

Contact: Not reported

Waste	Quantity	Info Source
-------	----------	-------------

NONE	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

118

**3520 ADAMO DR**  
**TAMPA, FL**

**HMIRS**

**91090588**  
**N/A**

118

**INDUSTRIAL CHEMICAL & SUPPLY CO**  
**3520 ADAMO DR**  
**TAMPA, FL 33605**

**AST**

**A100008750**  
**N/A**

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

### AST:

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00006000
Tank Content:	Mineral acid	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	90/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00012000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	90/03
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	11	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00040000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	93/10
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Aprvd alt sys		
Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00005000
Tank Content:	Mineral acid	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00005000
Tank Content:	Mineral acid	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		
Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00005000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00005000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		
Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00003500
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001200
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		
Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

118

INDUSTRIAL CHEMICAL & SUPPLY  
3520 ADAMO DRIVE  
TAMPA, FL 33675

RCRIS-SQG 1000698743  
UST FLD032783003  
LUST

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY (Continued)

1000698743

### LUST:

Facility ID:	8627232	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132477354	Discovery Date:	12/12/88
Tracking Number:	297406	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO MONITOR WELL/OVERFILL W/SCHED
Incident Ineligible Description:	NO MONITOR WELL

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## INDUSTRIAL CHEMICAL & SUPPLY (Continued)

1000698743

### UST:

Facility ID:	298627232	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	INDUSTRIAL CHEMICAL & SUPPLY		
Contact:	Not reported	Facility Phone:	8132477354
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	297406
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Auto sample wells		

118	SAUNDERS SYSTEM INC 1201 N 34TH ST TAMPA, FL 33605	FINDS	1000733837 FLD163283443
118	ROLLINS LEASING CORP #363 1201 N 34TH ST TAMPA, FL 19803	RCRIS-SQG UST LUST AST	1000699288 FLD163283443

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

### LUST:

Facility ID:	8625768	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132473411	Discovery Date:	11/21/91
Tracking Number:	Not reported	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

### UST:

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	6	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	7	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

### AST:

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Facility Phone:	8132473411	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	8	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-flow shut off		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Auto tank gauging		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Facility Phone:	8132473411	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	9	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/02
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Spill cnmt, Op-flow shut off		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	GW monitoring		

119	BAY FORD TRUCK SALES INC 3214 ADAMO DR TAMPA, FL 33675	RCRIS-SQG FINDS	1000498413 FLD981868839
119	BAY FORD TRUCK SALES,INC 3214 ADAMO DR TAMPA, FL 33605	UST LUST	U001354810 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

### LUST:

Facility ID:	8625601	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8139803673	Discovery Date:	12/16/88
Tracking Number:	295751	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported

Rank: 07135

Class: Not reported

Category: Not reported

### INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: WASTE OIL

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Region:

STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

### UST:

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

120

FL DEPT OF TRANSPORTATION CROSSTOWN EX  
39TH ST WESTBOUND ENTRY RAMP  
TAMPA, FL

UST  
LUST

U001963248  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL DEPT OF TRANSPORTATION CROSSTOWN EX (Continued)

U001963248

### LUST:

Facility ID: 9401655 Facility Type: STATE GOVERNMENT  
Alias Name: FL DEPT OF TRANSPORTATION CROSSTOWN EX  
Alias Name 2: FL DEPT OF TRANSPORTATION CROSSTOWN EX  
Alias Name 3: FL DEPT OF TRANSPORTATION CROSSTOWN EX  
Alias Name 4: FL DEPT OF TRANSPORTATION CROSSTOWN EX  
Telephone: 8139756585 Discovery Date: 09/01/94  
Tracking Number: Not reported Score: 000 (LOW)  
Facility Code: Not reported Status: Not reported  
Rank: 00000  
Class: Not reported  
Category: Not reported

### INCIDENT GENERAL INFORMATION -

Source Description: DISCHARGE NOTIFICATION  
Lead: LOCAL PROGRAM  
Incident 17-770 Cleanup: NO C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: DIESEL-EMERG GENE Est. Gallons Lost: 00000025

### INCIDENT PROGRAM INFORMATION -

Incident Program: RESPONSIBLE PARTY-NO CLAIM  
Incident Program Type: N  
Incident Eligible Status: Not reported  
Incident Ineligible Reason: Not Reported  
Incident Ineligible Description: Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product: Cleanup Responsible: Not reported  
Soil Removal: Alt. Process Date: Not reported  
Soil Treatment: Alternative Status: Not reported  
Other Treatment:

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible: Not reported  
Response Record Type: Not reported  
Response Remedial Action Plan Type: Not reported  
Response Status: Not reported  
Extension Record Type: Not reported  
Extension Status: Not reported  
Extension Comments: Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible: Not reported  
Response Record Type: Not reported  
Response Remedial Action Plan Type: Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible: Not reported  
Estimated Completion Year: Not reported  
Actual Year to Complete: Not reported  
Report Type: Not reported  
Report Comments: Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action: Not reported  
Region: STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL DEPT OF TRANSPORTATION CROSSTOWN EX (Continued)

U001963248

### UST:

Facility ID:	299401655	Facility Type:	State Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	KARL D FLEMING		
Contact:	Not reported	Facility Phone:	8139756585
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940830	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	NONE	District:	Southwest
Owner's Contact:	CHARLES W GILLIARD		
Owner:	FL DEPT OF TRANSPORTATION TAMPA 3350 W BUSCH BLVD #120 TAMPA, FL 33618		
Owner's Phone:	8139716585	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	No
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

121

SOUTHEASTERN BOLT & SCREW  
815 N 26TH ST  
TAMPA, FL 33605

UST

U001354907  
N/A

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SOUTHEASTERN BOLT & SCREW (Continued)

U001354907

### UST:

Facility ID:	298625702	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHEASTERN BOLT & SCREW		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	74/11
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

122	TDSI BIDS TAMPA 504 N 34TH ST TAMPA, FL 33675	RCRIS-SQG	1000822327 FLD984253534
122	TDSI BIDS TAMPA 504 N 34TH ST TAMPA, FL 33675	FINDS	1000740043 FLD984253534
123	AFFILIATED OF FL, INC.-J.H.WILLIAMS 1102 N 28TH ST TAMPA, FL 33605	UST	U001354686 N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

### UST:

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	81/11
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	67/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

## MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	61/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	62/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	73/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	79/08
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

123

AFFILIATED OF FLORIDA INC  
1102 N 28TH ST  
TAMPA, FL 33631

RCRIS-SQG  
FINDS

1000498457  
FLD982077984

123

AFFILIATED OF FL,INC.  
1102 N 28TH ST  
TAMPA, FL 33605

AST

A100008880  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL,INC. (Continued)

A100008880

### AST:

Facility ID:	298840679	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RAY BLACK		
Facility Phone:	8132485781	Permit Section:	Not reported
Date entered:	880601	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN TRIVENTO		
Owner:	AFFILIATED OF FL INC 1102 N 28TH ST TAMPA, FL 336316246		
Owner's Phone:	8132485781	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	88/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

Facility ID:	298840679	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RAY BLACK		
Facility Phone:	8132485781	Permit Section:	Not reported
Date entered:	880601	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN TRIVENTO		
Owner:	AFFILIATED OF FL INC 1102 N 28TH ST TAMPA, FL 336316246		
Owner's Phone:	8132485781	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	88/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

124

**SWIFT ADHESIVES AND COATINGS**  
605 N 26TH ST  
TAMPA, FL 33605

RCRIS-SQG 1000230730  
FINDS FLD064687577  
CERC-NFRAP  
UST

### CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported  
Ownership Status: OTHER  
EPA Notes: Not reported

Federal Facility: NO  
NPL Status: NOT ON NPL

### CERCLIS-NFRAP Assessment History:

Assessment: PRELIMINARY ASSESSMENT

Completed: 11/01/82

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SWIFT ADHESIVES AND COATINGS (Continued)

1000230730

Assessment:	DISCOVERY	Completed:	08/01/80
Assessment:	SCREENING SITE INSPECTION	Completed:	01/25/91
CERCLIS-NFRAP Alias Name(s):			
SWIFT ADHESIVES & COATINGS			
UST:			
Facility ID:	298944024	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SWIFT ADHESIVES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890503	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN W KNAUB		
Owner:	REICHHOLD		
	3100 WOODCREEK DR		
	DOWNERS GROVE, IL 605155424		
Owner's Phone:	3129607254	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	58/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	85/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

124

SWIFT ADHESIVES & COATINGS  
605 N. 26 ST.  
TAMPA, FL 33605

FI Sites

S100889047  
N/A



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SWIFT ADHESIVES & COATINGS (Continued)

S100889047

### FL Sites:

Facility ID:	000386	EPA ID:	FLD064687577
Facility District:	SOUTHWEST	Monthly Update:	February
Lead Unit:	Not reported	Support Unit	3012
Air Contam:	Not reported	Soil Contam:	Not reported
Surface Water Contam:	Not reported	Ground Water Contam:	Not reported
Cleanup Started ?:	No	Cleanup Completed ?:	No
Deletion Recommended ?:	No	Other:	Not reported
Warning Letter Status:	Not reported	Notice of Violation Status:	No
Consent Order Status:	No	Admin Hearing Status:	No
Court Status:	No	Final Order Status:	No
Comments:	EPA PRELIMINARY ASSESSMENT COMPLETED 11-82. EPA/CERCLA SITE SCREENING CATEGORIZATION REVIEW COMPLETED 11/87 RESULTED IN A MEDIUM PRIORITY DETERMINATION FOR SITE SCREENING INVESTIGATION. EPA/FDER INVESTIGATION TO BE SCHEDULED ON A PRIORITY BASIS.		

125	SPARTAN OIL CO 2815 LONG ST TAMPA, FL 33605	UST LUST AST	U001353963 N/A
-----	---	--------------------	-------------------

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

### LUST:

Facility ID:	8509056	Facility Type:	INLAND BULK PETROLEUM
Alias Name:	Not reported		
Telephone:	8132473417	Discovery Date:	10/21/92
Tracking Number:	Not reported	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	KEROSENE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	QTR 1

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SPARTAN OIL CO (Continued)

U001353963

### UST:

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnrmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00020000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00025000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnrmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

### AST:

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	Not reported
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	10	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Small use tank		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, Man tank gauging		

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	Not reported
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	11	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Small use tank		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells, GW mon plan, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	Not reported
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00070000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-flow shut off, Field erected		
Tank Piping:	Abvgrrnd-no contact w/soil, Unprotec metal, Fiberglass, Suction piping		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, Man tank gauging		

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	Not reported
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00070000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-flow shut off, Field erected		
Tank Piping:	Abvgrrnd-no contact w/soil, Unprotec metal, Fiberglass, Suction piping		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, Man tank gauging		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	Not reported
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	9	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Small use tank		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells, GW mon plan, Man tank gauging		

126

CSX TRANSPORTATION-CLARK ST SITE  
30TH ST / CLARK ST  
TAMPA, FL

LUST  
AST

S101265163  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CSX TRANSPORTATION-CLARK ST SITE (Continued)

S101265163

### LUST:

Facility ID:	9101429	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	9043593693	Discovery Date:	03/27/91
Tracking Number:	Not reported	Score:	009 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	08492		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION

REIMBURSEMENT CLEANUP

ELIGIBLE

Not Reported

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CSX TRANSPORTATION-CLARK ST SITE (Continued)

S101265163

### AST:

Facility ID:	299101429	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CSX TRANSPORTATION		
Facility Phone:	9043593693	Permit Section:	Not reported
Date entered:	910401	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	K W RICHARDSON JR		
Owner:	CSX TRANSPORTATION INC J275		
	500 WATER ST		
	JACKSONVILLE, FL 32202		
Owner's Phone:	9043591986	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299101429	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CSX TRANSPORTATION		
Facility Phone:	9043593693	Permit Section:	Not reported
Date entered:	910401	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	K W RICHARDSON JR		
Owner:	CSX TRANSPORTATION INC J275		
	500 WATER ST		
	JACKSONVILLE, FL 32202		
Owner's Phone:	9043591986	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00012000
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

126	GENERAL CHEMICAL TAMPA WORKS 3004 E CLARK ST TAMPA, FL 33605	FINDS	1000498787 FLD984180703
126	GENERAL CHEMICAL CORP. TAMPA WORKS 3004 E. CLARK ST. TAMPA, FL 33605	TRIS	1000901806 NA

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
126	<b>GENERAL CHEMICAL</b> <b>3004 CLARK ST</b> <b>TAMPA, FL 33605</b>  Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	<b>FINDS</b>	<b>1000498516</b> <b>FLD982089617</b>
126	<b>GENERAL CHEMICAL CORP-TAMPA WORKS</b> <b>3004 CLARK ST</b> <b>TAMPA, FL 33605</b>  AST: Facility ID: 299101959 Facility Type: Industrial Plan Is fac. regulated: Regulated facility Is facility open: Open Operator: COOPER, DONALD Facility Phone: 8132481643 Permit Section: Not reported Date entered: 910510 Financial responsibility: None Tank ID: 1 District: Southwest Owner's Contact: BARRY A SWIHART Owner: GENERAL CHEMICAL CORP 1427 CENTRAL AVE EAST POINT, GA 30344  Owner's Phone: 4047611370 Tracking #: Not reported Drink. Wat. Well: Not reported Any contaminated soil: Not reported Cleanup Status: Not reported Any contaminated surface water: Not reported Tank position: Aboveground Tank Cap. (Gals): 00030086 Tank Content: Mineral acid Contaminated media indicator: Not reported Disposal Method: In service Install. Date: 83/XX Is tank regulated: Regulated tank Content Category: Hazardous/other Last used Date: Not reported Any contaminated groundwater: Not reported RPT Tank #: Not reported RPT by Tank #: Not reported Tank Constr.: Bare/asph steel, AST containment area, Level gauges/hi level alarms, Field erected Tank Piping: Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Suction piping Petro. Monitoring: Auto tank gauging	<b>AST</b>	<b>A100008998</b> <b>N/A</b>

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GENERAL CHEMICAL CORP-TAMPA WORKS (Continued)

A100008998

Facility ID:	299101959	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COOPER, DONALD		
Facility Phone:	8132481643	Permit Section:	Not reported
Date entered:	910510	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	BARRY A SWIHART		
Owner:	GENERAL CHEMICAL CORP		
	1427 CENTRAL AVE		
	EAST POINT, GA 30344		
Owner's Phone:	4047611370	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00030138
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	FRP clad steel, AST containment area, Level gauges/hi level alarms, Field erected		
Tank Piping:	Abvgrnd-no contact w/soil, Fiberglass, Secondary containment, Suction piping		
Petro. Monitoring:	Man tank gauging		
Facility ID:	299101959	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COOPER, DONALD		
Facility Phone:	8132481643	Permit Section:	Not reported
Date entered:	910510	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	BARRY A SWIHART		
Owner:	GENERAL CHEMICAL CORP		
	1427 CENTRAL AVE		
	EAST POINT, GA 30344		
Owner's Phone:	4047611370	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00030138
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	FRP clad steel, AST containment area, Level gauges/hi level alarms, Field erected		
Tank Piping:	Abvgrnd-no contact w/soil, Fiberglass, Secondary containment, Suction piping		
Petro. Monitoring:	Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GENERAL CHEMICAL CORP-TAMPA WORKS (Continued)

A100008998

Facility ID:	299101959	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COOPER, DONALD		
Facility Phone:	8132481643	Permit Section:	Not reported
Date entered:	910510	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	BARRY A SWIHART		
Owner:	GENERAL CHEMICAL CORP 1427 CENTRAL AVE EAST POINT, GA 30344		
Owner's Phone:	4047611370	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00030628
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	FRP clad steel, AST containment area, Level gauges/hi level alarms, Field erected		
Tank Piping:	Abvgrnd-no contact w/soil, Fiberglass, Secondary containment, Suction piping		
Petro. Monitoring:	Man tank gauging		

127

## TAMPA MCKAY BAY REFUSE TO ENERGY 34TH & CLARK ST TAMPA, FL 33675

FINDS  
SWF/LF

1000735789  
FLD982168775

LF:

Facility ID:	4029M30071	Facility Status:	ACTIVE
Population Served:	285,000 PERSONS	Design Capacity:	1,300.0000 TPD
Amount Daily Waste:	1,300 TON	Number of Monitoring Wells:	0 WELLS
Facility Telephone:	(813) 223-8337	Facility Contact:	CITY OF TAMPA SANITATION DEPT

127

## TAMPA MUNICIPAL INCINERATOR 107 N 34TH ST TAMPA, FL 33605

CERCLIS  
FINDS

1000344888  
FLD000865451

CERCLIS Classification Data:

Site Incident Category:	Not reported	Federal Facility:	NO
Ownership Status:	OTHER	NPL Status:	NOT ON NPL
EPA Notes:	Not reported		

CERCLIS Assessment History:

Assessment:	DISCOVERY	Completed:	02/12/1988
Assessment:	PRELIMINARY ASSESSMENT	Completed:	04/15/1988
Assessment:	SCREENING SITE INSPECTION	Completed:	08/06/1985

CERCLIS Site Status:

This site is currently under investigation by the government to assess the extent of further action

CERCLIS Alias Name(s):

TAMPA MUNICIPAL INCINERATOR

Other Pertinent Environmental Activity Identified at Site:

facility has active water discharge permits  
civil judicial and administrative enforcement cases against facility



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

127	<b>TAMPA PATHOLOGICAL INCINERATOR</b> <b>107 N 34TH ST</b> <b>TAMPA, FL</b>	SWF/LF	S101011596 N/A
LF:			
Facility ID: 4029M30070		Facility Status:	INACTIVE
Population Served: Not reported		Design Capacity:	0.0000
Amount Daily Waste: Not reported		Number of Monitoring Wells:	0 WELLS
Facility Telephone: (813) 223-8337		Facility Contact:	CITY OF TAMPA SANITATION DEPT
127	<b>WHEELABRATOR MCKAY BAY INC</b> <b>107 N 34TH ST</b> <b>TAMPA, FL 33605</b>	AST	A100008928 N/A
AST:			
Facility ID: 298943764		Facility Type:	Non-retail Business
Is fac. regulated: Regulated facility		Is facility open:	Open
Operator: JOHN NEIL		Permit Section:	Not reported
Facility Phone: 8132481457		Financial responsibility:	Oth Apprvd Coverage
Date entered: 890411		District:	Southwest
Tank ID: 1			
Owner's Contact: JOHN NEIL			
Owner: WHEELABRATOR MCKAY BAY INC			
107 N 34TH ST			
TAMPA, FL 33605			
Owner's Phone: 8132481457		Tracking #:	Not reported
Drink. Wat. Well: Not reported		Any contaminated soil:	Not reported
Cleanup Status: Not reported		Any contaminated surface water:	Not reported
Tank position: Aboveground		Tank Cap. (Gals):	00000550
Tank Content: Vehic diesel		Contaminated media indicator:	Not reported
Disposal Method: In service		Install. Date:	Not reported
Is tank regulated: Not regulated tank		Content Category:	Vehicular
Last used Date: Not reported		Any contaminated groundwater:	Not reported
RPT Tank #: Not reported		RPT by Tank #:	Not reported
Tank Constr.: Overfill-ball check, AST containment area			
Tank Piping: Unknown/not reported			
Petro. Monitoring: Not required			

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## WHEELABRATOR MCKAY BAY INC (Continued)

A100008928

Facility ID:	298943764	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN NEIL		
Facility Phone:	8132481457	Permit Section:	Not reported
Date entered:	890411	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN NEIL		
Owner:	WHEELABRATOR MCKAY BAY INC		
	107 N 34TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132481457	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000550
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, AST containment area		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

Facility ID:	298943764	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN NEIL		
Facility Phone:	8132481457	Permit Section:	Not reported
Date entered:	890411	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN NEIL		
Owner:	WHEELABRATOR MCKAY BAY INC		
	107 N 34TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132481457	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000550
Tank Content:	Leaded gas	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, AST containment area		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WHEELABRATOR MCKAY BAY INC (Continued)

A100008928

Facility ID:	298943764	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN NEIL		
Facility Phone:	8132481457	Permit Section:	Not reported
Date entered:	890411	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN NEIL		
Owner:	WHEELABRATOR MCKAY BAY INC		
	107 N 34TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132481457	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000280
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, AST containment area		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

Facility ID:	298943764	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN NEIL		
Facility Phone:	8132481457	Permit Section:	Not reported
Date entered:	890411	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN NEIL		
Owner:	WHEELABRATOR MCKAY BAY INC		
	107 N 34TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132481457	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00005000
Tank Content:	Mineral acid	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Int lined steel, Bare/asph steel, AST containment area, Spill		
	cnmt		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Corrosion resis coated,		
	Pressurized piping		
Petro. Monitoring:	Man tank gauging, None		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## WHEELABRATOR MCKAY BAY INC (Continued)

A100008928

Facility ID:	298943764	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN NEIL		
Facility Phone:	8132481457	Permit Section:	Not reported
Date entered:	890411	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN NEIL		
Owner:	WHEELABRATOR MCKAY BAY INC		
	107 N 34TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132481457	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Int lined steel, Bare/asph steel, AST containment area, Spill		
	cnmt		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Corrosion resis coated,		
	Pressurized piping		
Petro. Monitoring:	Man tank gauging, None		

127

## TAMPA CITY INCINERATOR 107 N. 34TH ST. TAMPA, FL 33605

FI Sites

S100889051  
N/A

### FL Sites:

Facility ID:	000390	EPA ID:	FLD000865451
Facility District:	SOUTHWEST	Monthly Update:	June
Lead Unit:	DIST	Support Unit:	3012
Air Contam:	Not reported	Soil Contam:	Not reported
Surface Water Contam:	Not reported	Ground Water Contam:	Not reported
Cleanup Started ?:	No	Cleanup Completed ?:	No
Deletion Recommended ?:	No	Other:	Not reported
Warning Letter Status:	Not reported	Notice of Violation Status:	No
Consent Order Status:	No	Admin Hearing Status:	No
Court Status:	No	Final Order Status:	No
Comments:	3012 SITE INSPECTION CONDUCTED AUG. 1984. REPORT COMPLETED 1-85 AND FORWARDED TO EPA 2-85. CONTAMINATION CONFIRMED BUT NOT IN VIOLATION OF STATE STANDARDS. REPORT FORWARDED 1-86 TO DISTRICT FOR REVIEW. LOW PRIORITY FOR DISTRICT ENFORCEMENT. DISTRICT TO REVIEW FILE AND PERMIT STATUS TO DETERMINE NEXT ACTION.		

128

## TAMPA SAND & MATERIAL 3214 E CLARK ST TAMPA, FL 33605

FINDS

1000497186  
FLD039568126

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

128

**FL MINING & MATERIALS**  
**3212 CLARK ST**  
**TAMPA, FL 33605**

**UST**  
**LUST**  
**AST**

**U001354037**  
**N/A**

## LUST:

Facility ID:	8624773	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8139336711	Discovery Date:	12/22/86
Tracking Number:	290590	Score:	035
Facility Code:	Not reported	Status:	Not reported
Rank:	03230		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	ED!
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
------------	------------------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	REMEDIAL ACTION PLAN
Extension Status:	APPROVED
Extension Comments:	ADDITIONAL EXT.

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL MINING & MATERIALS (Continued)

U001354037

### UST:

Facility ID:	298624773	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FL MINING & MATERIALS		
Contact:	Not reported	Facility Phone:	8139336711
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DENISE CORRALES		
Owner:	FL MINING & MATERIALS CORP		
	PO BOX 31965		
	TAMPA, FL 33631		
Owner's Phone:	8139336711	Tracking #:	290590
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## FL MINING & MATERIALS (Continued)

U001354037

Facility ID:	298624773	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FL MINING & MATERIALS		
Contact:	Not reported	Facility Phone:	8139336711
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DENISE CORRALES		
Owner:	FL MINING & MATERIALS CORP		
	PO BOX 31965		
	TAMPA, FL 33631		
Owner's Phone:	8139336711	Tracking #:	290590
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

### AST:

Facility ID:	298624773	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FL MINING & MATERIALS		
Facility Phone:	8139336711	Permit Section:	Not reported
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DENISE CORRALES		
Owner:	FL MINING & MATERIALS CORP		
	PO BOX 31965		
	TAMPA, FL 33631		
Owner's Phone:	8139336711	Tracking #:	290590
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Completed	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

129

TAMPA,CITY-FIRE DEPT TRAINING  
116 S 34TH ST  
TAMPA, FL 33605

UST  
LUST  
AST

U001355891  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT TRAINING (Continued)

U001355891

### LUST:

Facility ID:	8842214	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	12/12/88
Tracking Number:	295359	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA,CITY-FIRE DEPT TRAINING (Continued)

U001355891

### UST:

Facility ID:	298842214	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FIRE DEPT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT		
	808 E ZACK ST		
	TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295359
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT TRAINING (Continued)

U001355891

Facility ID:	298842214	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FIRE DEPT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT		
	808 E ZACK ST		
	TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295359
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT TRAINING (Continued)

U001355891

Facility ID:	298842214	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FIRE DEPT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT		
	808 E ZACK ST		
	TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295359
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT TRAINING (Continued)

U001355891

Facility ID:	298842214	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FIRE DEPT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295359
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Fiberglass		
Petro. Monitoring:	Unknown/not reported		

### AST:

Facility ID:	298842214	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FIRE DEPT		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295359
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	91/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Dbl walled=primary matl, AST containment area, Spill cnmt, Op-tight fill, Concrete		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	DW tank space		

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
BARTOW	100999522	FDEP SOUTHWEST DIST TSA POLK CO	2740 HWY 60 W (A)	33610	FINDS	
BRANDON	94244483	SE CORNER OF MYRTLE AND BELL SHOALS RDS		33602	ERNS	
MULBERRY	100905916	TAMPA ELECTRIC CO POLK POWER STATIO	9995 SR 37 SOUTH	33602	RCRIS-SQG, FINDS	
PLANT CITY	94236289	HIGHWAY 37 AND HARPER		33602	ERNS	
POMPANO	1000450165	FEDERAL EXPRESS CORP	2280 NW 33RD CT	33604	RCRIS-SQG, FINDS	
SEFFNER	1000738384	HILLSBORO CO ARMWOOD HIGH SCH	12000 US HWY 92	33605	FINDS	
ST. PETERSBURG	94240064			33602	ERNS	
TAMPA	95316504				ERNS	
TAMPA	95316502				ERNS	
TAMPA	95315777				ERNS	
TAMPA	95315498				ERNS	
TAMPA	95315014				ERNS	
TAMPA	95312952				ERNS	
TAMPA	95311412				ERNS	
TAMPA	95311403				ERNS	
TAMPA	95308988				ERNS	
TAMPA	95309793				ERNS	
TAMPA	95308987				ERNS	
TAMPA	95308064				ERNS	
TAMPA	95306689				ERNS	
TAMPA	95306185				ERNS	
TAMPA	95306184				ERNS	
TAMPA	95304245				ERNS	
TAMPA	95303902				ERNS	
TAMPA	95302927				ERNS	
TAMPA	95300771				ERNS	
TAMPA	95296922				ERNS	
TAMPA	95291801				ERNS	
TAMPA	95293250				ERNS	
TAMPA	95285083				ERNS	
TAMPA	95279210				ERNS	
TAMPA	95282435				ERNS	
TAMPA	95277769				ERNS	
TAMPA	S100021000	SPE RECYCLING C & D FACIL			SWF/LF	
TAMPA	8906506	TAMPA GENERAL HOSPITAL			ERNS	
TAMPA	9001491	MARITIME BLVD AND SHORELINE			ERNS	
TAMPA	9003707	MARITIME AND SHORELINE AVENUE			ERNS	
TAMPA	9003701	I-275/HOWARD AVENUE			ERNS	
TAMPA	9101451	ANCLOTE ICE PLANT ANCLOTE RIVER			ERNS	
TAMPA	9009719	HOOKER'S POINT STATION HEMLOCH ST.			ERNS	
TAMPA	9007043	STATE ROUTE 41 AND BIG BEND RD.			ERNS	
TAMPA	9006743	5881 IMGRAHM ST			ERNS	
TAMPA	9003271	FILTER CLEAN INC.			ERNS	

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	9001049	YEOMAN YARD			ERNS	
TAMPA	9002940	NORTH OF 275			ERNS	
TAMPA	9001875	HIMES AND COLUMBUS			ERNS	
TAMPA	93001510	4700 WHITEWAY DR.			ERNS	
TAMPA	94254708	3701 CAUSEWAY BLVD			ERNS	
TAMPA	9202434	RESIDENCE-161 GROVE ST			ERNS	
TAMPA	8705033	TRANSUS TRUCKING CO. 9801 PALM RIVER RD.			ERNS	
TAMPA	8701952	800 BLOCK WEST BRADDOCK AND ALFRED			ERNS	
TAMPA	8806268	I-4 AT 36TH STREET WEST BOUND LANES			ERNS	
TAMPA	8905266	GARDINIER FERTILIZER PLANT			ERNS	
TAMPA	8911109	22ND STREET OF BUFFALO AVENUE			ERNS	
TAMPA	8911118	ADAMS & 50TH STREET			ERNS	
TAMPA	8911094	SAN PADREO STREET AND CHURCH AVENUE			ERNS	
TAMPA	8904757	SAN PADRO ST AND CHURCH AVE			ERNS	
TAMPA	8911063	NORTH WEST SHORE BOULEVARD AND WEST GRA			ERNS	
TAMPA	93000920	ROCK PORT			ERNS	
TAMPA	95010228				HMIRS	
TAMPA	8800753	15746 GARDENSIDE LN			ERNS	
TAMPA	8804062	AL LOPEZ STADIUM			ERNS	
TAMPA	94215061				ERNS	
TAMPA	94257720	TOWN AND COUNTRY 6707 LEEWARD ISLAND WAY			ERNS	
TAMPA	8705439	CORK RD AND THONOASSASSO RD			ERNS	
TAMPA	8704914	40TH ST AND 21ST AVE			ERNS	
TAMPA	8701807	INTERSECTION OF GUNN HWY AND HENDERSON RI			ERNS	
TAMPA	8702450	J.D. SMITH EXTERMINATORS			ERNS	
TAMPA	8901968	DALE MABRY EXIT RAMP ONTO BUSH BLVD			ERNS	
TAMPA	8705049	CAMELOT APARTMENTS			ERNS	
TAMPA	8700833	3000FT SOUTH OF RUNWAY 22			ERNS	
TAMPA	9200444	HWY 361			ERNS	
TAMPA	8705674	MACINTOSH RD AND US 301			ERNS	
TAMPA	8705671	NEBRASKA AVE AND BEARESS RD			ERNS	
TAMPA	94236234	YULMAN YARD			ERNS	
TAMPA	9110837	88 E HAMLIN ST EAST SHORE OF LAKE UNION			ERNS	
TAMPA	8800210	PARKING LOT OF AYRES DINER, CORNER OF DALE			ERNS	
		MAVRY RD AND GRAC				
TAMPA	92050480				HMIRS	
TAMPA	9200518	PO BOX 547			ERNS	
TAMPA	94252488				ERNS	
TAMPA	8800445	ON HIWAY 674			ERNS	
TAMPA	9109740	2600 FEDERAL AVE			ERNS	
TAMPA	9108829	PO BOX 849 HWY 366 AND 32ND ST.			ERNS	
TAMPA	94247034	MANATEE PORT			ERNS	
TAMPA	8702464	NITRAN			ERNS	
TAMPA	8701693	TAMPA AIR PORT, NEAR POLICEMAN HANGER			ERNS	
TAMPA	9108869	1150 MURPHY AVE GROUND/PARKING LOT/SEWER			ERNS	
TAMPA	9106525	PLATFORM A			ERNS	
TAMPA	94272866	200 MILES OUT OF COZUMEL ENROUTE TO TAMPA			ERNS	

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	94267760	PEIR 251			ERNS	
TAMPA	94269396	5881 INGRAHAM			ERNS	
TAMPA	90020086				HMIRS	
TAMPA	94120774				HMIRS	
TAMPA	8703008	7512 PAULA DRIVE AND TOWN AND COUNTRY BLVD			ERNS	
TAMPA	94242206	TAMPA PORT AUTHORITY BERTH 227			ERNS	
TAMPA	94241873	INTERSTATE 4 EASTBOUND AT MILE 13-14			ERNS	
TAMPA	94263239	AMERADA HESS TERMINAL			ERNS	
TAMPA	94263238	ARMADA HESS CORP 504 NORTH 19TH STREET			ERNS	
TAMPA	94272690	AGRICOLA BIG BEN TERMINAL			ERNS	
TAMPA	94260843	PORT MANATEE			ERNS	
TAMPA	8705589	INTERSECTION OF STATE RD 39 AND SAM ALLUN RD. NE SECTION OF			ERNS	
TAMPA	94266954	INTERSTATE 75 NORTHBOUND MILE MARKER 277			ERNS	
TAMPA	94266514	SADCO NO 220			ERNS	
TAMPA	94264027	ENROUTE FM PUERTO RICO TO TAMPA			ERNS	
TAMPA	94234604	CF INDUSTRIES AMMONIA TERMINAL 3222 MARITIME BLVD			ERNS	
TAMPA	94272974	5910 BRECKENRIDGE PKWY SUITE H		33610	ERNS	
TAMPA	94250879	6803 PARK EAST BLVD		33610	ERNS	
TAMPA	95274989			33605	ERNS	
TAMPA	94272493	SOLOMON BROTHERS INVEST. 8800 HIDDEN RIVER PKWY		33605	ERNS	
TAMPA	94231499	8500 HIDDEN RIVER PKWY		33605	ERNS	
TAMPA	9111006	1724 KOPPERS ROAD		33605	ERNS	
TAMPA	95318546			33602	ERNS	
TAMPA	95318539			33602	ERNS	
TAMPA	95317009			33602	ERNS	
TAMPA	95315360			33602	ERNS	
TAMPA	95313273			33602	ERNS	
TAMPA	95312631			33602	ERNS	
TAMPA	95294931			33602	ERNS	
TAMPA	94251595	ROY JENKINS POOL 154 COLUMBIA DR		33605	SWF/LF	
TAMPA	S100021008	WASTE MANAGMT INC HW TRANSFER STA	US301 / I-4		RCRIS-SQG, FINDS	
TAMPA	1000383814	CONSOLIDATED BATTERY SERVICES	4101A E 12TH AVE UNIT 2		UST, LUST	8626344
TAMPA	U001377986	COCA-COLA BOTTLING CO-TAMPA	13TH & YORK ST		UST, LUST, AST	8509068
TAMPA	U002313159	STAR ENTERPRISE TERMINAL	519 S 19TH ST		UST, LUST, AST	9100107
TAMPA	U001356198	HESS TERMINAL	504 N 19TH ST		FINDS, UST, AST	298624988
TAMPA	1000497861	CARGILL INC	200 N 19TH ST		FINDS, RCRIS-LQG, TSCA, UST	299100050
TAMPA	1000433691	CHEVRON USA INC	500 N 19TH ST		FINDS	
TAMPA	1000498857	MUSSELMAN STEEL	1711 S 20TH STREET{	33610	FINDS	
TAMPA	94020790		22ND ST CAUSEWAY		HMIRS	
TAMPA	90050311		22ND ST CAUSEWAY		HMIRS	
TAMPA	1000498853	FLORIDA PETROLEUM SERVICE	22ND ST & SLUGH AVE	33604	FINDS	
TAMPA	1000281758	ROWLETT PARK LANDFILL #39	22ND STREET @ HILLSBOROUGH RIVER	33604	FINDS, CERC-NFRAP	
TAMPA	U001354642	FLEET TRANSPORT CO INC	4012 N 22ND ST CAUSEWAY BLVD	33610	UST, LUST	8625423
TAMPA	1000497294	CSX TRANSPORTATION	22ND ST CAUSEWAY	33605	FINDS	

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	1000299254	CHEMICAL WASTE MANAGEMENT	6015 HWY 301 N	33610	FINDS, CERC-NFRAP	
TAMPA	1000821729	ENGINE LAB	1150 N 34TH ST	33605	RCRIS-SQG, FINDS	
TAMPA	U001963249	FL DEPT OF TRANSPORTATION CROSSTOWN EX	39TH ST EASTBOUND EXIT RAMP		UST	299401656
TAMPA	U001045078	FL ROCK & TANK LINES	US 41 S		UST, LUST, AST	8519988
TAMPA	U001377984	MCKESSON CHEMICAL CO.	6051 HWY 41-A		UST	298625120
TAMPA	9106962	530 N. WITTER ST.	HWY 49		ERNS	
TAMPA	1000497537	MANNA PRO CORP	1235 NN 4TH AVE	33605	FINDS	
TAMPA	U001963247	FL DEPT OF TRANSPORTATION CROSSTOWN EX	50TH ST EASTBOUND EXIT RAMP		UST	299401651
TAMPA	U002217714	USE 9401651	50TH ST EASTBOUND EXIT RAMP		UST	299501714
TAMPA	U001963246	FL DEPT OF TRANSPORTATION-S CROSSTOWN	50TH ST WESTBOUND ENTRY RAMP		UST	299401649
TAMPA	1000498149	FLORIDA ROCK IND	50TH ST	33610	FINDS	
TAMPA	1000733003	WEYERHAUSER TAMPA SHIPPING	53RD ST AND SLIGH AVE	33610	FINDS	
TAMPA	U001378058	FL DEPT OF TRANSPORTATION	SR 580 - PIPER'S MARINE		UST, LUST	9102666
TAMPA	U001378030	CSX TRANSPORTATION INC-JACOB'S TRUCK	78TH ST		UST, LUST	9101415
TAMPA	U001356268	DIDDEN SHEET METAL	3514 E 7TH AVE	33605	UST, LUST	9100992
TAMPA	U001356108	TURLEY JAMES	4315 E 7TH AVE	33605	UST, LUST	9045817
TAMPA	U001354309	J W CONNER & SONS INC	4100 E 7TH AVE	33605	UST, LUST	8625068
TAMPA	U000687124	GARCIA, JOSEPH	4316 E 7TH AVE	33605	UST, LUST	9101517
TAMPA	U000119026	GARDNER-MARTIN ASPHALT CORP.	4001 E 7TH AVE	33605	UST, LUST	8628181
TAMPA	S101264762	CSX TRANSPORTATION INC-RALSTON PURINA	3702 E 7TH AVE	33605	LUST	9101417
TAMPA	9103256	7016 WINONA DRIVE	MP 84.5		ERNS	
TAMPA	94060625		S 86TH ST		HMIRS	
TAMPA	U001355102	HILLSBOROUGH CNTY-VANDENBERG APRT.	RT 9 BOX 14	33610	UST, LUST	8627053
TAMPA	U001378113	ACCENT MARINE	10410 HWY 92 E		UST, LUST	9201893
TAMPA	1000735187	CONSUMER PRODUCTS INC	10824 US 92 E		FINDS	
TAMPA	S101011579	A & D RECYCLING TRANSFER STATION	7006 E 9TH AVE	33602	SWF/LF	
TAMPA	8901982	MARINA N OF SKYWAY BRIDGE,EAST OF I-275 BRIDGE	ON A DOCK PILING		ERNS	
TAMPA	92080269		5100 ACLINE AVE		HMIRS	
TAMPA	92080115		5100 ACLINE AVE		HMIRS	
TAMPA	U001546806	DEROSE INDUSTRIES	8504 E ADAMO DR		UST, LUST	9103587
TAMPA	1000735831	SGS CONTROL SERVICES INC.	4951 E ADAMO DR SUITE 210	33603	FINDS	
TAMPA	1000502072	IND CHEM & SUP CO	3520 ADAMO DR	33605	FINDS	
TAMPA	91040182		5056 ADAMS DR		HMIRS	
TAMPA	U001356163	NORTHWEST AIRLINES	AIRSIDE D TAMPA INTL AIRPORT	33607	UST, Ind Waste	299047054
TAMPA	91080614		ANDERSON RD		HMIRS	
TAMPA	1000450164	TAMPA PATHOLOGY LABORATORY	6515 ARMENIA AVE N	33603	RCRIS-SQG, FINDS	
TAMPA	1000738376	OAK GROVE JUNIOR HIGH SCHOOL	6315 N ARMENIA AVE/ A	33604	FINDS	
TAMPA	S100990555	GARRISON CHANNEL	631 S ASHLEY ST		LUST	9301000
TAMPA	U001378037	BARNETT BANK BLDG-FORMER	2000 ASHLEY DR		UST, LUST	9101785
TAMPA	1000161395	NCNB TYPESETTING & COPY CENTER	400 N ASHLEY ST 16 FLOOR	33602	RCRIS-SQG, FINDS, UST	299045676
TAMPA	1000225516	PUREX CORPORATION	ATTN: GEORGE MILLS, PLANT MGR.	33610	TSCA	
TAMPA	U002113431	ALL POINTS WAREHOUSE-OLD GAS STATION	4701 7TH AVE		UST, LUST	9501491
TAMPA	U001823385	PEPES TRUCK STOP & AUTO REPAIR	2109 4TH AVE E	33603	UST	299400306
TAMPA	U001823406	TAMPA MOBILE REPAIR	4701 7TH AVE	33605	UST, LUST	9400547
TAMPA	1000361426	FLORIDA STEEL CORP	5TH AVE & 28TH ST	33605	FINDS	
TAMPA	1000738361	HILLSBOROUGH BUCHANAN JR HIGH SCHOO	1001 BEARS AVE	33605	FINDS	



## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	U001378101	USE 9201677	3001 NORTH BLVD		UST, LUST	9200783
TAMPA	1000235060	JOHN NAUGHTON FORD INC	5014 E BONACHER RD	33610	RCRIS-SQG, FINDS	
TAMPA	U001356374	AUBURN PLASTICS INC	6008 BONACKER DR	33610	UST, LUST	9103281
TAMPA	S100020977	BOUGAINVILLEA TRASH LF	BOUGAINVILLEA / 46TH ST		SWF/LF	
TAMPA	U001355730	GENERAL RENT-A-CAR	4606 W BOY SCOUT BLVD	33607	UST, LUST	8837593
TAMPA	U001355309	J CLIFFORD MACDONALD CENTER	4304 W BOYSCOUT BLVD	33607	UST, LUST	8627987
TAMPA	1000500016	ENSECO WADSWORTH ALERT LABORATORIES	5910 H BRECKENRIDGE PKWY	33610	RCRIS-SQG, FINDS	
TAMPA	1000450179	CONTRAVES USA	5902 BRECKENRIDGE PKW	33610	RCRIS-SQG, FINDS	
TAMPA	1000396433	ED TAYLOR CONSTRUCTION	5909 C BRECKENRIDGE PKWY	33610	RCRIS-SQG, FINDS	
TAMPA	1000348719	PUMPCO INC	5013 E BROADWAY	33605	RCRIS-SQG, FINDS	
TAMPA	1000262320	LEWIS PAINT CO	6503 E BROADWAY	33605	RCRIS-SQG, FINDS	
TAMPA	U001356316	MONEY SAVER QUALITY GAS	2902 E BUFFALO AVE	33610	UST, LUST	9101592
TAMPA	U001354005	BENTON BROS FILM EXPRESS	3725 E BUFFALO AVE	33610	UST, LUST	8521255
TAMPA	U001354081	TEXACO #208-24-203-1332	2720 W BUFFALO AVE	33607	UST, LUST	8624821
TAMPA	1000335909	UNION CARBIDE CORP/SOLVENTS TE	3202 CARBIDE AVE	33605	RCRIS-SQG, FINDS, CERC-NFRAP	
TAMPA	94110828		41S CARGILL		HMIRS	
TAMPA	90020623		CAUSEWAY BLVD		HMIRS	
TAMPA	1000733829	LEASEWAY TRANSP CORP	4212 22ST CAUSEWAY BLVD	33605	FINDS	
TAMPA	1000243609	ANTHONY DISTRIBUTORS INC	201 S CEASAR	33605	RCRIS-SQG, FINDS	
TAMPA	U001378008	TAMPA DOWNTOWN INVEST LTD PROPERTY	CITY BLK WASHINGTON N MORGAN W		UST, LUST	8943604
TAMPA	1000735504	MARK J FALTUS	5020 N CLARK	33605	FINDS	
TAMPA	1000414330	MYRTLE HILL CEMETERY	4701 EAST CNELSEA	33610	RCRIS-SQG, FINDS	
TAMPA	U001378083	CONTINENTAL AIRLINES RESERVATIONS	4101 W COLUMBUS DR		UST	299103404
TAMPA	90030513		COMMERCE BLVD		HMIRS	
TAMPA	1000344847	TAMPA BAY WHOLESALE CLEANERS	5452 56TH COMMERCE PARK DR	33610	RCRIS-SQG, FINDS	
TAMPA	S100563782	KASSOUF KIMMERLING/AKA TIMBERLAKE	NE COR 58 / COLUMBUS DR		SHWS	
TAMPA	S101137001	SIXTY-SECOND STREET DUMP	NW COR OF COLUMBUS / 62 ST		SHWS	
TAMPA	1000986074	SPORTS INDUSTRIAL WASTE	4812 N CORTEZ ST	33604	RCRIS-SQG, FINDS, RCRIS-TSD	
TAMPA	1000450177	XEROX CORP	5680 W CYPRESS SUITE A	33607	RCRIS-SQG, FINDS	
TAMPA	1000261528	ENVIRONMENTAL SCIENCE & ENGINEERING	5840 WEST CYPRESS ST SUITE A	33607	RCRIS-SQG, FINDS	
TAMPA	U001378078	YOUR ATTIC	4510 S DALE MABRY AVE		UST	299103154
TAMPA	1000333237	JERRY ULM DODGE	2966 N DALE MABRY HWY	33607	RCRIS-SQG, FINDS	
TAMPA	900330047		DAVIS ISLAND		HMIRS	
TAMPA	U001544419	JEWISH CENTER TOWERS INC	3001 DELEON ST		UST, LUST	9301024
TAMPA	8802523	TAMPA INTERNATIONAL AIRPORT EAST SIDE OF AIRPORT	DELTA MAINTENANCE HANGAR		ERNS	
TAMPA	94091101		6 DOING RACK		HMIRS	
TAMPA	S101547649	EDWARD DOROUGH SITE	1806 DOWNING CIR		SHWS	
TAMPA	1000858717	BUFFALO CHEVRON INC	802 E DR MLK JR BLVD	33603	RCRIS-SQG, FINDS	
TAMPA	U001353965	CHEVRON #48083	2735 W DR MARTIN LUTHER KING JR	33607	UST, LUST	8509058
TAMPA	U000738375	HILLSBOROUGH CO N B YOUNG JR HIGH S	1807 E DR MARTIN LUTHER KING	33605	FINDS	
TAMPA	1000737266	RADIANT OIL CO OF TAMPA INC	2004A DURHAM	33605	FINDS	
TAMPA	1000737264	GAS KWICK INC	2004C DURHAM ST	33605	FINDS	
TAMPA	1000501788	WESTERN AUTO #50740	2209 EASTGATE PLAZA	33610	RCRIS-SQG, FINDS	
TAMPA	U001378041	REDWING CARRIERS INC	EISENHOWER BLVD & COURTNEY CSWY		UST	299101830
TAMPA	U001378026	TAMPA CITY-S REGIONAL PARKING FACILITY	ELLA MAE ST		UST	299100404
TAMPA	U001378110	TAMPA PORT AUTHORITY-GARRISON CHANNEL	1301 ELLA MAE ST		UST, LUST	9201835

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	1000498063	GARRISON STEVEDORES	1101 E ELLAMAE	33605	FINDS	
TAMPA	U002217727	TWIN LAKES	E END OF BLOOMINGDALE AVE		UST, LUST	9502111
TAMPA	91090759		ERLICH & HUTCHENSON		HMIRS	
TAMPA	U001378033	ELI WITT CO	EUNICE		UST, LUST	9101430
TAMPA	S100020986	NORTHEAST HILLSBOROUGH LF	EUREKA SP RD / HAMILTON RD		SWF/LF	
TAMPA	S100300529	FALKENBURG RD YARD TRASH PROCESSING	FALKENBURG RD, 1MI N SR-60		SWF/LF	
TAMPA	U001354218	MAJIK MARKET #414-08	5320 N FALKENBURG RD	33610	UST, LUST	8624968
TAMPA	9106432	DUTCH HARBOR MAGONE MARINE SERVICE	FALLS		ERNS	
TAMPA	S100020982	HILLS COUNTY WASTE-TO-ENERGY PLANT	210 FAULKENBURG RD		SWF/LF	
TAMPA	U001544418	CRAFTSMAN ROOFERS	4704 N FL AVE		UST, LUST	9301008
TAMPA	1000411987	AUSTIN & SON AUTO ELECTRIC	3909 FLA AVE	33603	RCRIS-SQG, FINDS	
TAMPA	1000732754	TAMPA ELEC CO HOOKERS POINT ST	FOOT OF HEMLOCK RD	33604	FINDS	
TAMPA	U001378027	RENFROE PROPERTY	9402 E FOWLER AVE		UST	
TAMPA	U000136451	COLONY SHOPS OF FL INC	3415 E FRONTAGE RD	33607	UST, LUST	
TAMPA	S101011580	AUTHORIZED APPLIANCE RECLAIMING CTR	2420 GELMAN PLACE, .5MI E US41		SWF/LF	299100524
TAMPA	1000733904	STEEL SERVICES TAMPA	GRANT & S SLIP TPA PT AUTH		FINDS	9063924
TAMPA	1000999514	HILLSBOROUGH CO CUSTODIAL OPERATION	1475 GREEN ST	33605	FINDS	
TAMPA	U001354260	CF INDUSTRIES INC-TAMPA PHOSPHATE	2520 GUY VERGER BLVD	33605	FINDS	
TAMPA	1000255916	C F INDUSTRIES TAMPA TERMINAL	2520 GUY VERGER BLVD	33605	UST, AST	8625014
TAMPA	U001377993	HILLSBOROUGH CNTY SCHOOL BD-FURNITURE	1801 N HABANA & UNION	33605	RCRIS-SQG, FINDS	
TAMPA	1000172051	PDMA CORP	5909C HAMPTON OAKS PKWY		UST, LUST	8736478
TAMPA	1000740182	COUCH INC	6701 E HANNA AVENUE "B"	33610	RCRIS-SQG, FINDS	
TAMPA	1000498064	CITY READY MIX	HANNA RD	33610	FINDS	
TAMPA	1000502102	SUN ENVIRONMENTAL INC	E HEMLOCK AVE HOOKERS PT PW PL		FINDS	
TAMPA	1000735829	STERLING CLEANERS	3710 HENDERSON AVE	33605	FINDS	
TAMPA	1000235059	PERFORMANCE FORD	6202 E. HILLBOROUGH AVE.	33602	FINDS	
TAMPA	U001355655	R L N CORPORATION	2803 E HILLSBORO AVE	33610	RCRIS-SQG, FINDS	
TAMPA	U001355373	FIRESTONE #46-EASTGATE	2401 E HILLSBORO AVE	33610	UST, LUST	8736669
TAMPA	1000740305	CIRCLE K #8532	7220 E HILLSBORO	33610	UST, LUST	8731771
TAMPA	1000380858	MASSEY CLEANERS	3209 E HILLSBORO AVE		FINDS	
TAMPA	U001378035	DISCOUNT TIRE TOWN	701 HILLSBOROUGH AVE	33610	RCRIS-SQG, FINDS	
TAMPA	U001546669	EXXON #4-0490	11292 HILLSBOROUGH BLVD		UST, LUST	9101615
TAMPA	U001355895	LES' SALES & SERVICE	203 W HILLSBOROUGH AVE	33604	UST, LUST	299102024
TAMPA	1000932229	ESTECH, INC	5226 E HILLSBOROUGH P. O. BOX 11308		8842287	
TAMPA	1000733668	SHERWIN WILLIAMS CO	4835 W HILLSBOROUGH AVENUE	33610	FINDS	
TAMPA	1000497895	LAFARGE CORP	HILLSBOROUGH AV	33610	FINDS	
TAMPA	1000344927	TAMPA UNKNOWN SPILL	HILLSBOROUGH COUNTY	33602	CERCLUS, FINDS	
TAMPA	1000292187	HILLSBOROUGH RIVER ABANDONED D	HILLSBOROUGH COUNTY	33602	CERCLUS, FINDS	
TAMPA	1000498505	MACCO AUTO PAINTING	6012 E HILLSBOROUGH	33610	RCRIS-SQG, FINDS	
TAMPA	1000449766	NEW CIGAR CITY INC	6804 E HILLSBOROUGH	33610	RCRIS-SQG, FINDS	
TAMPA	91070743		HOOKERS POINT		HMIRS	
TAMPA	94120986		4700 N HOOVER BLVD		HMIRS	
TAMPA	1000734634	U S VIGGO INC	7906 HOPI PLACE	33607	FINDS	
TAMPA	U001378036	HUMBLE OIL CORP	US HWY 301 N & ALONZO RD		UST, LUST	9101724
TAMPA	U001354420	RACETRAC #278	4911 N HWY 301	33610	UST, LUST	8625186
TAMPA	U001354016	SOUTHWEST FL WATER MGMT DIST.	US HWY 301	33610	UST, LUST, AST	8624752
TAMPA	1000498617	ROLLERCOAT IND INC	10135 US HWY 92 E	33610	RCRIS-SQG, FINDS	

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	1000822586	CIRCLE K #7494	2820 US HWY 301 S	33605	RCRIS-SQG, FINDS, UST, LUST	8840559
TAMPA	1000881223	MURPHY OIL USA INC	1306 INGRAM AVE	33605	RCRIS-SQG, LUST, AST	8625598
TAMPA	1000497143	MURPHY OIL USA	1306 INGRAM AVE	33605	FINDS	
TAMPA	U001355929	TAMPA,CITY-FIRE STATION #19	4916 INGRAM	33602	UST, LUST	8842519
TAMPA	90020271		INTERBAY AND DALE MABRY		HMIRS	
TAMPA	U001355133	HALL OF FAME INN-GOLF COURSE MAINT	INTERNATIONAL PLAZA	33607	UST, LUST	8627185
TAMPA	1000436995	REDWING CARRIERS FUEL SPILL	INTERSECTION EISENHOWER BLVD & FL S.R.€	33607	FINDS, CERC-NFRAP	
TAMPA	9100947	PORT OF BEAUMONT CARROL ST. WHARF	ST. JOHN ST.		ERNS	
TAMPA	8700298	1220 U.S. STATE ROAD 301 AT	JUST EAST OF TAMPA		ERNS	
		WHAREHOUSE SUPPLY 813-621-3				
TAMPA	S100020984	KINGSWAY RD LF (DAVID J JOSEPH)	KINGSWAY RD, 0.5MI N OF 14		SWF/LF	
TAMPA	1000932731	ERNY SUPPLY CO	8302 LAUREL FAIR CIRCLE/SUITE 130	33610	FINDS	
TAMPA	1000216731	INTERNATIONAL TECHNICAL INST	8407 LAUREL FAIR CIRCLE	33610	RCRIS-SQG, FINDS	
TAMPA	1000335902	PATHOLOGY ASSOC	5415 LAUREL BLVD	33607	RCRIS-SQG, FINDS	
TAMPA	S101716587	NORTHWEST HILLSBORO CLASS III LF	LINEBAUGH AVE, E OF SHELDON RD		SWF/LF	
TAMPA	S100020988	NORTHWEST HILLSBOROUGH SLF	LINEBAUGH AVE		SWF/LF	
TAMPA	S101011591	RECYCLED WOOD PRODUCTS COMPOST FAC	S LOIS AVE, .25MI N INTERBAY		SWF/LF	
TAMPA	S101011588	OLD MANHATTAN AVE CLASS I LF	S MANAHATTAN AVE / RICHARDSON		SWF/LF	
TAMPA	1000699637	INTERPAK INC	6932 SOUTH MANHATTEN STREET		RCRIS-SQG	
TAMPA	9101545	OFF OF I-70 BOX BURGER LEASE	MARINA DR		ERNS	
TAMPA	U001378034	MARIANI ASPHALT PARCEL	MARITIME BLVD		UST, LUST	9101518
TAMPA	90080774		MARITIME BLVD		HMIRS	
TAMPA	1000498153	AMCON CONCRETE	MARITIME BLVD	33605	FINDS	
TAMPA	91060740		MARITIME BLVD		FINDS	
TAMPA	94051530		8950 MARSLIN DR		HMIRS	
TAMPA	U001378107	GOOD SHEPHERD BAPTIST CHURCH INC	MARTIN LUTHER KING BLVD		HMIRS	
TAMPA	U002313271	MAJESTIC IDEAL DRY CLEANERS	8119 E MARTIN LUTHER KING JR		UST, LUST	9201207
TAMPA	1000931328	PETROLEUM PACKERS INC	1411 E MARTIN LUTHER KING BLVD	33603	UST	299502251
TAMPA	1000733391	SULPHUR TERMINALS CO INC TAMPA	1601 MCCLOSKEY BLVD	33605	FINDS	
TAMPA	S100705159	CITGO PETROLEUM CORP	1015 MCCLOSKEY BLVD HOOKERS PT	33605	FINDS	
TAMPA	1000359119	AMERICAN PETROFINA MARKETING INC	801 MCCLOSKEY BLVD	33605	LUST, AST	8625797
TAMPA	U000125105	AMOCO OIL CO-TERMINAL TAMPA	801 MCCLOSKEY BOULEVARD	33605	FINDS, RCRIS-LQG, CERC-NFRAP	
TAMPA	1000498532	MCKAY BAY RTE PROJ	848 MCCLUSKY BLVD	33605	UST, LUST	8735210
TAMPA	U001378052	RISSEER PETROLEUM TANKER SPILL	MCKAY BAY & ADAMS DR	33605	FINDS	
TAMPA	94070231		I-275 MILE MARKER 57		UST	299102311
TAMPA	S100020990	NORTHWEST REGIONAL SLUDGE MGMT FAC	14 MILEMARKER 13		HMIRS	
TAMPA	U001355878	COMMERCE PLAZA	NEAR SHELDON RD / MOBLEY RD		SWF/LF	
TAMPA	1000199364	MIKES DRIVELINES INC	12811 N NEBRASKA AVE	33602	UST, LUST	8842069
TAMPA	U001356274	CSX TRANSPORTATION-UNION STATION	13213B N NEBRASKA AVE	33604	RCRIS-SQG, FINDS	
TAMPA	1000344857	TAMPA ELECTRIC CO CENTRAL TEST	601 NEBRASKA AVE	33602	UST, LUST	9101044
TAMPA	1000736938	YBOR DATA CTR	1898 NUCCIO PKY	33607	RCRIS-SQG, FINDS	
TAMPA	1000933622	POLLUTION PREVENTION SVC INC	1898 NUCCIO PKWY	33605	FINDS	
TAMPA	8802486	PAY-LESS SERVICE STATION	4515 OAK FAIR BLVD STE 103	33610	FINDS	
			SOUTH OF COOPER'S POND APARTMENT BUILDING		ERNS	
TAMPA	S100021003	TECO COMPOSTING FACILITY	W OF SHELDON RD N OF WATERS AV		SWF/LF	
TAMPA	9105702	EAST LEVEE OF THE CHAIN OF ROCKS CANAL	OHIO RIVER MILE 241.5		ERNS	
TAMPA	U001378012	GTE OF FL OLDSMAR	12750 OLD MEMORIAL HWY		UST	299045723

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	90040283		OLD HOPEWELL RD		HMIRS	
TAMPA	1000498843	REED MINERALS	OLD HWY 41 & JENSEN		FINDS	
TAMPA	U001356447	HARBOR ISLAND	ONE HARBOUR PLACE #270	33602	UST, LUST, AST	9202003
TAMPA	U001378105	SHELL STATION	8210 PARKEDGE DR		UST	299201084
TAMPA	91080428		PENDOLA POINT RD		HMIRS	
TAMPA	91050674		PENDOLA POINT DRIVE		HMIRS	
TAMPA	1000497834	IDEAL BASIC IND	PENNDOLA POINT RD	33602	FINDS	
TAMPA	1000740400	TECNUM	2411 PLYMOUTH RD	33602	FINDS	
TAMPA	1000733612	PREDELIVERY SVC CORP	1803 E POINT DR	33605	FINDS	
TAMPA	1000843480	GENERAL SERVICES ADMINISTRATION	501 E POLK ST ROOM 600	33602	FINDS	
TAMPA	U001378002	GRACE,W.R.	PORT SUTTON RD		UST	
TAMPA	8905271	IMC TERMINAL	PORT SUTTON AREA		ERNS	298840906
TAMPA	92100051		PORT TAMPA		HMIRS	
TAMPA	1000932117	CARGILL FERT.-TAMPA AMM TERM	PORT SUTTON RD IE	33605	FINDS	
TAMPA	8805677	MP AZA886.9	POWELL MEADOW SUBDIVISION		ERNS	
TAMPA	1000501577	SUBURBAN PROPANE	5618 POWHATTAN AVE	33610	RCRIS-SQG, FINDS	
TAMPA	1000902018	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902017	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902016	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902015	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902014	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902013	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902012	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000498756	THEOCHEM LABORATORIES INC	7373 ROWELETT PARK DR	33610	FINDS	
TAMPA	1000300124	KIMMINS ENVIRONMENTAL SERVICE CORP	1501 SECOND AVENUE	33605	RCRIS-SQG, FINDS	
TAMPA	U001379124	HUMANA GAS STATION	SEMINOLE BLVD / BLOSSOM LAKE DR		UST, LUST	9103454
TAMPA	1000350946	YBOR CENTRAL LTD	1616 EAST SEVENTH AVENUE		RCRIS-SQG, FINDS	
TAMPA	8910558	SHELDON RD. SUBSTATION	SHELDON RD. AND LINEBAUGH AVE.	33605	ERNS	
TAMPA	8805616		SHELL TERMINAL		ERNS	
TAMPA	1000259958	NATL SEA PRODUCTS CORP TP DIV	1356 SHORELINE DR	33605	RCRIS-SQG, FINDS, UST, AST	298942800
TAMPA	U001378011	TAMPA CITY-NW REPUMP STATION	5602 SITKA		UST, AST	298945433
TAMPA	U001356092	VALUE RENT-A-CAR	5202/5210 SPRUCE ST	33607	UST, LUST	9045619
TAMPA	U001355159	ALAMO RENT-A-CAR	5124 W SPRUCE ST	33607	UST, LUST	8627265
TAMPA	U001354879	ENTERPRISE RENT A CAR	4912 W SPRUCE ST	33607	UST, LUST	8625673
TAMPA	U001354876	CENTRAL TRUCK LINES	3902 W SPRUCE ST	33607	UST, LUST	8625670
TAMPA	U001354812	ALAMO RENT-A-CAR #030	5402 W SPRUCE ST	33607	UST, LUST	8625604
TAMPA	U001354138	DOLLAR RENT-A-CAR	4720 W SPRUCE ST	33607	UST, LUST	8624882
TAMPA	1000498850	JOHN CARLO INC	SPRUCE ST	33605	FINDS	
TAMPA	U001378122	CENTRAL SOD & LANDSCAPING	4419 SOUTH ST		UST, LUST	9202389
TAMPA	95020737		14516 22ND ST SKIPPER RD		HMIRS	
TAMPA	U001356238	REGENT TRUCK SALES	6707 68TH ST	33610	UST, LUST	9100542
TAMPA	U001355604	HILLSBOROUGH CNTY SCHOOL BD-GROUNDS	3838 50TH ST	33605	UST, LUST	8736494
TAMPA	U001355028	MCCLENDON OIL CO. INC./W.K.	1409 22ND ST	33605	UST, LUST	8626340
TAMPA	1000165021	DIBBS PRODUCTS INC	5812 22ND STREET NORTH	33604	RCRIS-SQG, FINDS	
TAMPA	U001378024	USE 298841046	N TAMPA ST		UST, LUST	9100014
TAMPA	1000265433	KHAJEHNOORI HAZARDOUS WASTE	2740 NORTH TAMPA ST SUITE C	33603	RCRIS-SQG, FINDS	
TAMPA	U002313169	DELTA AIR LINES AIRSIDES	TAMPA INTERNATIONAL AIRPORT	33607	UST, LUST, AST	8625408

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	S101284751	TAMPA,CITY-AIRPORT PUMPING STATION	4450 S TAMPA AIRPORT BLVD	33607	LUST, AST	8841127
TAMPA	1000687596	AMERICAN AIRLINES	TAMPA INTL AIRPORT AIRSIDE E	33607	RCRIS-SQG, FINDS	
TAMPA	U001545547	PIONEER PROPERTIES ASSOCIATES,LTD	100 TAMPA ST	33602	UST, LUST	8942888
TAMPA	1000821146	HYATT REGENCY TAMPA	2 TAMPA CITY CENTER	33602	RCRIS-SQG, FINDS	
TAMPA	8705675	8401 N. HWY 301	TEXACO GAS STATION		ERNS	
TAMPA	8703010	1333 W. BRANDEN BLVD	THE PAITO SHOP		ERNS	
TAMPA	9108492	140 SILVESTER RD.	ON THE JAMES RIVER		ERNS	
TAMPA	1000361440	FLORIDA GRAPHIC PRODUCTS INC	3209 E THIRD AVE	33605	RCRIS-SQG, FINDS	
TAMPA	U001544411	VETERANS EXWY ROW SITES	NORTH TO SOUTH TO TAMPA		UST	299300656
TAMPA	92110135		4537 TRANSPORT DR		HMIRS	
TAMPA	94030979		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92070317		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91030415		4537 TRANSPORT DR		HMIRS	
TAMPA	92060357		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	93010192		4537 TRANSPORT DR		HMIRS	
TAMPA	92070304		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	90070446		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	U001545548	COURIER DISPATCH	4111 TRASK AVE		UST, LUST	8942841
TAMPA	U001355901	STANDARD GYPSUM	UNKNOWN	33605	UST, LUST	8842369
TAMPA	1000700432	CONSUMER PRODUCTS INC	10824 US92E		RCRIS-SQG	
TAMPA	1000933010	VANDENBERG AIRPORT INC	9334 VANDENBERG AIRPORT RD B	33610	FINDS	
TAMPA	S100563798	UNIVERSAL DOOR / DOT LF	VETERANS EXPWY @ BENJAMIN RD		SWF/LF	
TAMPA	S101136987	PEAK OIL/BAY DRUM	1/4 MI W OF FAULKENBERG RD, S OF SR 574		SHWS	
TAMPA	U001378016	BUDGET RENT A CAR	1110 N WEST SHORE BLVD		UST, LUST	9046115
TAMPA	92110055		WESTSHORE BLVD. & TYSON ST		HMIRS	
TAMPA	U001356392	EMBASSY HOTEL	555 WESTSHORE BLVD	33602	UST, LUST, AST	9200540
TAMPA	1000265816	HAWK AIRCRAFT REFINISHING	WILKINS RD	33610	FINDS	
TAMPA	S100020989	NORTHWEST HILLSBOROUGH TRANSFER STA	WILSKY RD / LINEBAUGH AVE		SWF/LF	
TAMPA	92040092		YARD		HMIRS	
TREASURE ISLAND	95318564			33602	ERNS	

## EPA Waste Codes Addendum

Code	Description
D000	NOT DEFINED
D001	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
D002	A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
D006	CADMIUM
D007	CHROMIUM
D008	LEAD
D018	BENZENE
D021	CHLOROBENZENE
D027	1,4-DICHLOROBENZENE
D039	TETRACHLOROETHYLENE
D040	TRICHLOROETHYLENE
F001	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F002	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F003	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL

## EPA Waste Codes Addendum

Code	Description
	ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F004	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: CRESOLS AND CRESYLIC ACID, AND NITROBENZENE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F005	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F006	WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.
NONE	NONE
U002	ACETONE (I)
U002	2-PROPANONE (I)
U112	ACETIC ACID ETHYL ESTER (I)
U112	ETHYL ACETATE (I)
U159	2-BUTANONE (I,T)
U159	METHYL ETHYL KETONE (MEK) (I,T)
U220	BENZENE, METHYL-
U220	TOLUENE
U359	ETHANOL, 2-ETHOXY-
U359	ETHYLENE GLYCOL MONOETHYL ETHER