

# **The EDR Corridor Study Report**

**Study Area 3 & 5  
I-4 / SR618  
Tampa, Florida**

**April 11, 1996**

**Inquiry number 114137**



**Environmental  
Data  
Resources, Inc.**

Creators of Toxicheck®

## ***The Source For Environmental Risk Management Data***

3530 Post Road  
Southport, Connecticut 06490

**Nationwide Customer Service**

Telephone: 1-800-352-0050  
Fax: 1-800-231-6802

ZIP CODE CITY CHECK FOR 114137 - 4/11/96 11:28

<<< EDR INTERNAL USE ONLY >>>

A computer review of city names appropriate to this report suggests that the following sites may have been mis-plotted:

Map ID	EDR ID	City Name
--------	--------	-----------

***Thank you for your business.***  
Please contact EDR at 1-800-352-0050  
with any questions or comments.

**Disclaimer**

This Report contains information obtained from a variety of public sources and EDR makes no representation or warranty regarding the accuracy, reliability, quality, or completeness of said information or the information contained in this report. The customer shall assume full responsibility for the use of this report.

**No warranty of merchantability or of fitness for a particular purpose, expressed or implied, shall apply and EDR specifically disclaims the making of such warranties. In no event shall EDR be liable to anyone for special, incidental, consequential or exemplary damages.**

## GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

**Elapsed ASTM days:** Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

### FEDERAL ASTM RECORDS:

#### **CERCLIS:** Comprehensive Environmental Response, Compensation, and Liability Information System

Source: EPA/NTIS

Telephone: 703-603-8904

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 11/30/95

Date Made Active at EDR: 02/26/96

Date of Data Arrival at EDR: 01/15/96

Elapsed ASTM days: 42

#### **ERNS:** Emergency Response Notification System

Source: EPA/NTIS

Telephone: 202-260-2342

ERNS: Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/95

Date Made Active at EDR: 02/19/96

Date of Data Arrival at EDR: 01/26/96

Elapsed ASTM days: 24

#### **NPL:** National Priority List

Source: EPA

Telephone: 703-603-8852

NPL: National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, it is EDR's policy to plot NPL sites greater than approximately 500 acres in size as areas (polygons). Sites smaller in size are point-geocoded at the site's address.

Date of Government Version: 09/01/95

Date Made Active at EDR: 10/25/95

Date of Data Arrival at EDR: 10/17/95

Elapsed ASTM days: 8

#### **RCRIS:** Resource Conservation and Recovery Information System

Source: EPA/NTIS

Telephone: 703-308-7907

RCRIS: Resource Conservation and Recovery Information System. RCRIS includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Date of Government Version: 10/31/95

Date Made Active at EDR: 01/12/96

Date of Data Arrival at EDR: 12/15/95

Elapsed ASTM days: 28



# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## FEDERAL NON-ASTM RECORDS:

### CONSENT: Superfund (CERCLA) Consent Decrees

Source: EPA Regional Offices

Telephone: Varies

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: Varies

Date of Next Scheduled Update: 09/01/95

### CORRACTS: Corrective Action Report

Source: EPA

Telephone: 703-308-7907

CORRACTS: CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 04/10/95

Date of Next Scheduled Update: 06/17/96

### FINDS: Facility Index System

Source: EPA/NTIS

Telephone: 800-908-2493

FINDS: Facility Index System. FINDS contains both facility information and "pointers" to other sources that contain more detail. These include: RCRIS, PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]), CERCLIS, DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), FRDS (Federal Reporting Data System), SIA (Surface Impoundments), CICS (TSCA Chemicals in Commerce Information System), PADS, RCRA-J (medical waste transporters/disposers), TRIS and TSCA.

Date of Government Version: 09/30/95

Date of Next Scheduled Update: 07/08/96

### HMIRS: Hazardous Materials Information Reporting System

Source: U.S. Department of Transportation

Telephone: 202-366-4555

HMIRS: Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/95

Date of Next Scheduled Update: 07/29/96

### MLTS: Material Licensing Tracking System

Source: Nuclear Regulatory Commission

Telephone: 301-415-7169

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/01/95

Date of Next Scheduled Update: 07/15/96

### NPL LIENS: Federal Superfund Liens

Source: EPA

Telephone: 205-564-4267

NPL LIENS: Federal Superfund Liens. Under the authority granted the USEPA by the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner receives notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/91

Date of Next Scheduled Update: 05/27/96

### PADS: PCB Activity Database System

Source: EPA

Telephone: 202-260-3992

PADS: PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 10/14/94

Date of Next Scheduled Update: 05/20/96

## GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

**RAATS:** RCRA Administrative Action Tracking System

Source: EPA

Telephone: 202-564-4104

RAATS: RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA.

Date of Government Version: 04/17/95

Date of Next Scheduled Update: 06/17/96

**ROD:** Records Of Decision

Source: NTIS

Telephone: 703-416-0703

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 03/31/95

Date of Next Scheduled Update: 06/17/96

**TRIS:** Toxic Chemical Release Inventory System

Source: EPA/NTIS

Telephone: 202-260-2320

TRIS: Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/92

Date of Next Scheduled Update: 07/01/96

**TSCA:** Toxic Substances Control Act

Source: EPA/NTIS

Telephone: 202-260-1444

TSCA: Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site. USEPA has no current plan to update and/or re-issue this database.

Date of Government Version: 01/31/95

Date of Next Scheduled Update: 06/17/96

## GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

### STATE OF FLORIDA ASTM RECORDS:

#### LUST: PCT01 - Petroleum Contamination Detail Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

LUST: Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 01/23/96

Date Made Active at EDR: 03/25/96

Date of Data Arrival at EDR: 02/12/96

Elapsed ASTM days: 42

#### SHWS: Florida's State-Funded Action Sites

Source: Department of Environmental Protection

Telephone: 904-488-0190

SHWS: State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 08/24/95

Date Made Active at EDR: 09/13/95

Date of Data Arrival at EDR: 09/05/95

Elapsed ASTM days: 8

#### SWF/LS: Facility Directory (Solid Waste Facilities)

Source: Department of Environmental Protection

Telephone: 904-922-7121

SWF/LS: Solid Waste Facilities/Landfill Sites. SWF/LS type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Section 2004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 01/16/96

Date Made Active at EDR: 03/01/96

Date of Data Arrival at EDR: 02/05/96

Elapsed ASTM days: 25

#### UST: STI02 - Facility/Owner/Tank Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

UST: Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 01/23/96

Date Made Active at EDR: 03/14/96

Date of Data Arrival at EDR: 02/12/96

Elapsed ASTM days: 31

### STATE OF FLORIDA NON-ASTM RECORDS:

#### AST: STI02 - Facility/Owner/Tank Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

AST: Registered Aboveground Storage Tanks.

Date of Government Version: 01/23/96

Date of Next Scheduled Update: 05/06/96

#### CATTLE DIPPING VATS: Cattle Dipping Vats

Source: Department of Environmental Protection

Telephone: 904-488-3601

Date of Government Version: 05/01/94

Date of Next Scheduled Update: 05/20/96

#### FL SITES: Sites List

Source: Department of Environmental Protection

Telephone: 904-922-7121

Date of Government Version: 12/31/89

Date of Next Scheduled Update: N/A

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## FLORIDA COUNTY RECORDS

### DADE COUNTY:

#### Dade County Storage Tanks

Source: Department of Environmental Resource Management  
Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Enforcement Case Tracking System

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Industrial Waste Type 2-4

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Facilities which generate, dispose of, store, use, discharge, handle or reclaim any liquid waste other than domestic sewage, any hazardous waste or any hazardous material (except factory prepackaged products intended primarily for domestic use or consumption).

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Industrial Waste Type 5

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Facilities which generate, dispose of, store, use, discharge, handle or reclaim any liquid waste other than domestic sewage, any hazardous waste or any hazardous material (except factory prepackaged products intended primarily for domestic use or consumption).

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

#### Industrial Waste Type 6

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Sites located on a septic tank inside a well field protection area.

Date of Government Version: 11/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Industrial Waste Permit

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Date of Government Version: 11/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Air Permit

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Date of Government Version: 11/01/95

Date of Next Scheduled Update: 07/01/96

#### Dade County Fuel Spill Cases

Source: Department of Environmental Resources Management  
Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

## GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

### Dade County Hazardous Waste

Source: Department of Environmental Resources Management

Telephone: 305-372-6755

Sites with documented soil or groundwater contamination.

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 07/01/96

### BROWARD COUNTY:

#### Broward County Storage Tanks

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

Date of Government Version: 08/12/94

Date of Next Scheduled Update: 06/10/96

#### Early Detection Incentive

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

EDI sites are leaking underground petroleum tanks covered under the state cleanup program.

Date of Government Version: 01/01/96

Date of Next Scheduled Update: 06/10/96

#### Environmental Assessment

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

EA sites are contaminated sites (non-leaking underground petroleum tanks) under the state cleanup program.

Date of Government Version: 01/01/96

Date of Next Scheduled Update: 06/10/96

#### Hazmat

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

HM sites use or store greater than 25 gallons of hazardous materials per month.

Date of Government Version: 01/01/96

Date of Next Scheduled Update: 06/10/96

#### Notice Of Violation

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

Date of Government Version: 08/12/94

Date of Next Scheduled Update: 06/10/96

### ESCAMBIA COUNTY:

#### Facility/Owner/Tank/Contamination Information Report

Source: Environmental Health Services

Telephone: 904-444-8990

Date of Government Version: 02/05/96

Date of Next Scheduled Update: 05/06/96

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## Historical and Other Database(s)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

**Former Manufactured Gas (Coal Gas) Sites:** The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

## Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

### **DELISTED NPL:** Delisted NPL Sites

Source: EPA

Telephone: 703-603-8769

DELISTED NPL: The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

### **NFRAP:** No Further Remedial Action Planned

Source: EPA/NTIS

Telephone: 703-416-0702

NFRAP: As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

### **FRDS:** Federal Reporting Data System

Source: EPA/Office of Drinking Water

Telephone: 202-260-2805

FRDS provides information regarding public water supplies and their compliance with monitoring requirements, maximum contaminant levels (MCL's), and other requirements of the Safe Drinking Water Act of 1986.

**Area Radon Information:** The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

**Oil/Gas Pipelines/Electrical Transmission Lines:** This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines and electrical transmission lines.

**Sensitive Receptors:** There are individuals who, due to their fragile immune systems, are deemed to be especially sensitive to environmental discharges. These typically include the elderly, the sick, and children. While the exact location of these sensitive receptors cannot be determined, EDR indicates those facilities, such as schools, hospitals, day care centers, and nursing homes, where sensitive receptors are likely to be located.

## GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

**USGS Water Wells:** In November 1971 the United States Geological Survey (USGS) implemented a national water resource information tracking system. This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on more than 900,000 wells, springs, and other sources of groundwater.

**Flood Zone Data:** This data, available in select counties across the country, was obtained by EDR in 1994 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

**Epicenters:** World earthquake epicenters, Richter 5 or greater  
Source: Department of Commerce, National Oceanic and Atmospheric Administration

**Water Dams:** National Inventory of Dams  
Source: Federal Emergency Management Agency  
Telephone: 202-646-2801  
WATER DAMS: National computer database of more than 74,000 dams maintained by the Federal Emergency Management Agency.

**Wetlands Data:** This data was obtained by EDR from the National Wetlands Inventory (NWI) in 1994. Data depicts wetland areas as defined by NWI.

**State of Florida Water Well and Sample Database**  
Source: FL Department of Environmental Protection, Groundwater Quality Monitoring

**St. Johns River District Well Data**  
Source: St. Johns River Water Management District

**Southwest District Water Use Data**  
Source: Southwest Water Management District

**Well Construction Permitting System:** Water Well Locations in Northwest Florida Water Management District  
Source: Northwest Florida Water Management District  
Telephone: 904-539-5999

**Florida Sinkholes**  
Source: Department of Environmental Protection, Geological Survey  
The sinkhole data was gathered by the Florida Sinkhole Research Institute, University of Florida.

## MAP FINDINGS SUMMARY

<u>Database</u>	<u>Total Plotted</u>
NPL	3
Delisted NPL	0
RCRIS-TSD	4
State Haz. Waste	2
CERCLIS	9
CERC-NFRAP	1
CORRACTS	1
State Landfill	5
LUST	138
UST	206
AST	42
RAATS	1
RCRIS Sm. Quan. Gen.	84
RCRIS Lg. Quan. Gen.	8
HMIRS	73
PADS	0
ERNS	2
FINDS	133
TRIS	4
NPL Liens	0
TSCA	1
MLTS	0
Florida Sites	5
Florida Enforcement	0
Florida Ind. Waste	0
Env. Assessment	0
Florida Cattle	0
FL Haz. Mat.	0
FL Notice of Viol.	0
FL Air Permit	0
Industrial Waste Permits	0
ROD	0
CONSENT	1
Coal Gas	1

\* Sites may be listed in more than one database



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

1	JENKINS AUTO CLINIC 3202 N 40TH ST TAMPA, FL 33605	RCRIS-SQG FINDS UST LUST	1000270808 FLD981746308
---	--	-----------------------------------	----------------------------

## LUST:

Facility ID:	8508973	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	03/29/91
Tracking Number:	Not reported	Score:	014 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05757		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN

## INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## JENKINS AUTO CLINIC (Continued)

1000270808

### UST:

Facility ID:	298508973	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN C. JENKINS,SR		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN C. JENKENS,JR.		
Owner:	JENKINS, JOHN C SR		
	2927 N 40TH ST		
	TAMPA, FL 336053213		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Op-tight fill		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## JENKINS AUTO CLINIC (Continued)

1000270808

Facility ID:	298508973	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN C. JENKINS,SR		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN C. JENKENS,JR.		
Owner:	JENKINS, JOHN C SR		
	2927 N 40TH ST		
	TAMPA, FL 336053213		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Op-tight fill		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## JENKINS AUTO CLINIC (Continued)

1000270808

Facility ID:	298508973	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN C. JENKINS,SR		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN C. JENKENS,JR.		
Owner:	JENKINS, JOHN C SR 2927 N 40TH ST TAMPA, FL 336053213		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Op-tight fill		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## JENKINS AUTO CLINIC (Continued)

1000270808

Facility ID:	298508973	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN C. JENKINS,SR		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN C. JENKENS,JR.		
Owner:	JENKINS, JOHN C SR 2927 N 40TH ST TAMPA, FL 336053213		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Op-tight fill		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

1

**THOMPSON RADIATOR**  
3222 N 40TH ST  
TAMPA, FL 33605

**FINDS**

1000999518  
FL0001209832

1

**THOMPSON RADIATOR**  
3222 N 40TH ST  
TAMPA, FL 33605

**RCRIS-SQG**

1001023572  
FLR000005215

RCRIS:

Owner: NON NOTIFIED

Contact:Not reported

Waste	Quantity	Info Source
-------	----------	-------------

NONE	.00000 (N)	State Inspection
------	------------	------------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	<b>THOMPSON RADIATOR (Continued)</b>		1001023572
	There are 2 compliance/violation record(s) reported at this site:		
	Evaluation	Date	Violations
	CASE DEVELOPMENT INSPECTION (CDI)	23-AUG-95	YES
	COMPLIANCE EVALUATION INSPECTION (CEI)	28-APR-95	YES
2	<b>BAYSIDE AUTO AUCTION OF TAMPA</b> 3225 N 50TH ST TAMPA, FL 33619	<b>FINDS</b>	1000740515 FLD984258319
2	<b>BAYSIDE AUTO AUCTION OF TAMPA</b> 3225 N 50TH ST TAMPA, FL 33619	<b>RCRIS-SQG</b>	1000859349 FLD984258319
	RCRIS:		
	Owner: R SCOTT, SAILORS (813) 620-3600		
	Contact: R SCOTT (813) 620-3600		
	Waste	Quantity	Info Source
	D001	.00000 (T)	Notification
	Waste	Quantity	Info Source
	F002	.00000 (T)	Notification
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported		
3	<b>TAMPA,CITY-FIRE STATION #10</b> 3108 N 34TH ST TAMPA, FL 33605	<b>UST</b>	U001355924 N/A

3

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE STATION #10 (Continued)

U001355924

### UST:

Facility ID:	298842514	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DANIEL A. PAGE		
Owner:	TAMPA CITY DEPT SANITARY SEWERS		
	2700 MARITIME BLVD		
	TAMPA, FL 336056744		
Owner's Phone:	8132473451	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	29/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

4

**SPECIALIZED TRANSPORT**  
3001 N 36TH ST  
TAMPA, FL 33605

AST

A100008975  
N/A

4

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**SPECIALIZED TRANSPORT (Continued)**

A100008975

AST:

Facility ID:	299100518	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LARRY, L W		
Facility Phone:	8136264166	Permit Section:	Not reported
Date entered:	910225	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	L W LARRY		
Owner:	SPECIALIZED TRANSPORT PO BOX 310716 TAMPA, FL 336800716		
Owner's Phone:	8136264166	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00002000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	76/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	92/12	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Dbl walled=primary matl, AST containment area, Concrete		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man tank gauging		

Facility ID:	299100518	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LARRY, L W		
Facility Phone:	8136264166	Permit Section:	Not reported
Date entered:	910225	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	L W LARRY		
Owner:	SPECIALIZED TRANSPORT PO BOX 310716 TAMPA, FL 336800716		
Owner's Phone:	8136264166	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00001000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	74/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	92/12	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Dbl walled=primary matl, AST containment area, Concrete		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man tank gauging		

5

**HILLSBOROUGH TRANSIT AUTHORITY**  
4305 E 21ST AVE  
TAMPA, FL 33605

RCRIS-SQG 1000292179  
FINDS FLD021716816  
UST  
LUST  
AST

5



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

### LUST:

Facility ID:	8624925	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136235833	Discovery Date:	12/12/91
Tracking Number:	290502	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	NEW/LUBE OIL	Est. Gallons Lost:	00000180
------------	--------------	--------------------	----------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	OTHER
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	REC DRAW
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

5

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

### UST:

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER		
Contact:	Not reported	Facility Phone:	8136235833
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00020000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER		
Contact:	Not reported	Facility Phone:	8136235833
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	10	District:	Southwest
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Misc. Petro-base product	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/12
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Man tank gauging		

5

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER		
Contact:	Not reported	Facility Phone:	8136235833
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00020000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

5

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER		
Contact:	Not reported	Facility Phone:	8136235833
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00020000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	install. Date:	83/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

5

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER		
Contact:	Not reported	Facility Phone:	8136235833
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00020000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER		
Contact:	Not reported	Facility Phone:	8136235833
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00020000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

5

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER		
Contact:	Not reported	Facility Phone:	8136235833
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER		
Contact:	Not reported	Facility Phone:	8136235833
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/12
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER		
Contact:	Not reported	Facility Phone:	8136235833
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/12
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER		
Contact:	Not reported	Facility Phone:	8136235833
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	9	District:	Southwest
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Misc. Petro-base product	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/12
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Man tank gauging		

### AST:

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER		
Facility Phone:	8136235833	Permit Section:	Not reported
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	11	District:	Southwest
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Spill cnmt		
Tank Piping:	Abvgnd-no contact w/soil, Cathod prot steel, Pressurized piping, Appv alt material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HILLSBOROUGH TRANSIT AUTHORITY (Continued)

1000292179

Facility ID:	298624925	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RON BAKER	Permit Section:	Not reported
Facility Phone:	8136235833	Financial responsibility:	State PRGM (FLIPA/AIG)
Date entered:	860506	District:	Southwest
Tank ID:	12		
Owner's Contact:	RONALD W ASH		
Owner:	HILLSBOROUGH AREA REG TRANSIT		
	4305 E 21ST AVE		
	TAMPA, FL 336052300		
Owner's Phone:	8136235835	Tracking #:	290502
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Spill cnmt		
Tank Piping:	Abvgnd-no contact w/soil, Cathod prot steel, Suction piping, Appv alt material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

5	4305 EAST 21ST AVE	ERNS	8800535
	TAMPA, FL		N/A

6	PARTS MARKET INC	UST	U001355904
	3906 E 21ST AVE	LUST	N/A
	TAMPA, FL 33605		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PARTS MARKET INC (Continued)

U001355904

### LUST:

Facility ID:	8842418	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136212451	Discovery Date:	12/20/88
Tracking Number:	295966	Score:	032
Facility Code:	Not reported	Status:	Not reported
Rank:	03819		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## PARTS MARKET INC (Continued)

U001355904

### UST:

Facility ID:	298842418	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PARTS MARKET INC		
Contact:	Not reported	Facility Phone:	8136212451
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881222	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	FITZ RAWLS		
Owner:	PARTS MARKET,INC		
	3906 E 21ST AVE		
	TAMPA, FL 33605		
Owner's Phone:	8136212451	Tracking #:	295966
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

7	HIGH REACH CO INC 4011 E 21ST AVE TAMPA, FL 33605	RCRIS-SQG FINDS	1000238485 FLD981748056
7	PENSKE TRUCK LEASING CO 3001 N 40TH ST TAMPA, FL 33605	RCRIS-SQG FINDS UST AST	1000382887 FLD981926546

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PENSKE TRUCK LEASING CO (Continued)

1000382887

### UST:

Facility ID:	298624947	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PENSKE TRUCK LEASING		
Contact:	Not reported	Facility Phone:	8136232435
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	MARC ALTHEN		
Owner:	PENSKE TRUCK LEASING CO L P		
	PO BOX 563		
	READING, PA 196030563		
Owner's Phone:	2157756000	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	77/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt		
Tank Piping:	Dblwall=2nd material, appv synthetic material		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PENSKE TRUCK LEASING CO (Continued)

1000382887

Facility ID:	298624947	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PENSKE TRUCK LEASING		
Contact:	Not reported	Facility Phone:	8136232435
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	MARC ALTHEN		
Owner:	PENSKE TRUCK LEASING CO L P		
	PO BOX 563		
	READING, PA 196030563		
Owner's Phone:	2157756000	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	77/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt		
Tank Piping:	Dblwall=2nd material, appv synthetic material		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Auto tank gauging		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PENSKE TRUCK LEASING CO (Continued)

1000382887

Facility ID:	298624947	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PENSKE TRUCK LEASING		
Contact:	Not reported	Facility Phone:	8136232435
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	MARC ALTHEN		
Owner:	PENSKE TRUCK LEASING CO L P		
	PO BOX 563		
	READING, PA 196030563		
Owner's Phone:	2157756000	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	77/01
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PENSKE TRUCK LEASING CO (Continued)

1000382887

Facility ID:	298624947	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PENSKE TRUCK LEASING		
Contact:	Not reported	Facility Phone:	8136232435
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	MARC ALTHEN		
Owner:	PENSKE TRUCK LEASING CO L P		
	PO BOX 563		
	READING, PA 196030563		
Owner's Phone:	2157756000	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	85/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-sac anode, Spill cnmt		
Tank Piping:	Dblwall=2nd material, appv synthetic material		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PENSKE TRUCK LEASING CO (Continued)

1000382887

Facility ID:	298624947	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PENSKE TRUCK LEASING		
Contact:	Not reported	Facility Phone:	8136232435
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	6	District:	Southwest
Owner's Contact:	MARC ALTHEN		
Owner:	PENSKE TRUCK LEASING CO L P		
	PO BOX 563		
	READING, PA 196030563		
Owner's Phone:	2157756000	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	85/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-sac anode, Spill cnmt		
Tank Piping:	Dblwall=2nd material, appv synthetic material		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PENSKE TRUCK LEASING CO (Continued)

1000382887

Facility ID:	298624947	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PENSKE TRUCK LEASING		
Contact:	Not reported	Facility Phone:	8136232435
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	7	District:	Southwest
Owner's Contact:	MARC ALTHEN		
Owner:	PENSKE TRUCK LEASING CO L P		
	PO BOX 563		
	READING, PA 196030563		
Owner's Phone:	2157756000	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	New/lube oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	84/12
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Cath prot-sac anode		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

### AST:

Facility ID:	298624947	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PENSKE TRUCK LEASING		
Facility Phone:	8136232435	Permit Section:	Not reported
Date entered:	860506	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	8	District:	Southwest
Owner's Contact:	MARC ALTHEN		
Owner:	PENSKE TRUCK LEASING CO L P		
	PO BOX 563		
	READING, PA 196030563		
Owner's Phone:	2157756000	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	New/lube oil	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	92/01
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal		
Petro. Monitoring:	None		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PENSKE TRUCK LEASING CO (Continued)

1000382887

Facility ID:	298624947	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PENSKE TRUCK LEASING		
Facility Phone:	8136232435	Permit Section:	Not reported
Date entered:	860506	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	9	District:	Southwest
Owner's Contact:	MARC ALTHEN		
Owner:	PENSKE TRUCK LEASING CO L P		
	PO BOX 563		
	READING, PA 196030563		
Owner's Phone:	2157756000	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Waste oil	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	92/01
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal		
Petro. Monitoring:	None		

7 INSTRUCTIONAL SERVICES CTR  
3993 21ST AVE  
TAMPA, FL 33605

FINDS

1000999515  
FL0001209808

7 INSTRUCTIONAL SERVICES CENTER  
3993 21ST AVE  
TAMPA, FL 33605

RCRIS-SQG

1001023467  
FLR000003640

RCRIS:

Owner: PHILLIP GUFFEY, ASBESTOS COORD  
(813) 744-8300

Contact: Not reported

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D002	.00000 (T)	Notification
D005	.00000 (T)	Notification	D011	.00000 (T)	Notification
F003	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

8 HOWARD AUTOMOTIVE SERVICE  
2917 N 34TH ST  
TAMPA, FL 33605

UST  
LUST

U001356081  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

LUST:

Facility ID:	8945488	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132479533	Discovery Date:	06/24/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
------------	-----------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

8

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

### UST:

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD		
	2917 N 34TH ST		
	TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD		
	2917 N 34TH ST		
	TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

46



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD		
	2917 N 34TH ST		
	TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

8

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD		
	2917 N 34TH ST		
	TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

9

**RYDER TRUCK RENTAL**  
**2909 N 40TH ST**  
**TAMPA, FL 33675**

**FINDS**  
**UST**  
**LUST**

**1000734630**  
**FLD981860422**

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

RYDER TRUCK RENTAL (Continued)

1000734630

LUST:

Facility ID:	8625548	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136268709	Discovery Date:	06/30/89
Tracking Number:	297419	Score:	013 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05873		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	DIESEL OIL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	EVERYTHING O.K.

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

9

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

1000734630

### UST:

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RYDER TRUCK RENTAL (Continued)

1000734630

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RYDER TRUCK RENTAL (Continued)

1000734630

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	11	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	77/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

1000734630

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	12	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	77/03
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

1000734630

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RYDER TRUCK RENTAL (Continued)

1000734630

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RYDER TRUCK RENTAL (Continued)

1000734630

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC 4008 E COLUMBUS DR TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RYDER TRUCK RENTAL (Continued)

1000734630

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

1000734630

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC 4008 E COLUMBUS DR TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RYDER TRUCK RENTAL (Continued)

1000734630

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RYDER TRUCK RENTAL (Continued)

1000734630

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

1000734630

Facility ID:	298625548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RISINGER JOHNNY		
Contact:	Not reported	Facility Phone:	8136268709
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	297419
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

9	RYDER TRUCK RENTAL 2909 N 40TH ST TAMPA, FL 33675	RCRIS-SQG	1000699941 FLD981860422
10	MOBIL #02-CN0 2901 N 50TH ST TAMPA, FL 33619	UST LUST	U000116269 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MOBIL #02-CN0 (Continued)

U000116269

## LUST:

Facility ID:	8625000	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8136231605	Discovery Date:	12/27/88
Tracking Number:	297391	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04452		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL #02-CN0 (Continued)

U000116269

### UST:

Facility ID:	298625000	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8136231605
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	1A	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297391
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL #02-CN0 (Continued)

U000116269

Facility ID:	298625000	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8136231605
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	1B	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297391
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MOBIL #02-CN0 (Continued)

U000116269

Facility ID:	298625000	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8136231605
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297391
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	87/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL #02-CN0 (Continued)

U000116269

Facility ID:	298625000	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8136231605
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	2A	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP.		
	3225 GALLOWS RD		
	FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297391
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL #02-CN0 (Continued)

U000116269

Facility ID:	298625000	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8136231605
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	2B	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297391
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MOBIL #02-CN0 (Continued)

U000116269

Facility ID:	298625000	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8136231605
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297391
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	87/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL #02-CN0 (Continued)

U000116269

Facility ID:	298625000	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8136231605
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	3A	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297391
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL #02-CN0 (Continued)

U000116269

Facility ID:	298625000	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8136231605
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	3B	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297391
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	install. Date:	82/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MOBIL #02-CN0 (Continued)

U000116269

Facility ID:	298625000	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8136231605
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297391
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	87/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MOBIL #02-CN0 (Continued)

U000116269

Facility ID:	298625000	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8136231605
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297391
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL #02-CN0 (Continued)

U000116269

Facility ID:	298625000	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP		
Contact:	Not reported	Facility Phone:	8136231605
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	4R1	District:	Southwest
Owner's Contact:	CINDY BENZ		
Owner:	MOBIL OIL CORP. 3225 GALLOWS RD FAIRFAX, VA 22037		
Owner's Phone:	7038495033	Tracking #:	297391
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	87/07
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

10

**RADIANT #255 TEXACO**  
2924 N 50TH ST  
TAMPA, FL 33619

UST  
LUST

U001354096  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT #255 TEXACO (Continued)

U001354096

### LUST:

Facility ID:	8624837	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132474731	Discovery Date:	09/11/88
Tracking Number:	293802	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT #255 TEXACO (Continued)

U001354096

### UST:

Facility ID:	298624837	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293802
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Unprotec metal, Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT #255 TEXACO (Continued)

U001354096

Facility ID:	298624837	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293802
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Unprotec metal, Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

10

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT #255 TEXACO (Continued)

U001354096

Facility ID:	298624837	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293802
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Unprotec metal, Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT #255 TEXACO (Continued)

U001354096

Facility ID:	298624837	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293802
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Unprotec metal, Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

11

SEACOAST SUPPLY  
2817 N 36TH ST  
TAMPA, FL 33605

UST

U001354849  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SEACOAST SUPPLY (Continued)

U001354849

### UST:

Facility ID:	298625642	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WALT JACKSON		
Contact:	Not reported	Facility Phone:	8132475402
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ED VAN BRUNT		
Owner:	L & W SUPPLY CORP		
	2817 N 36TH ST		
	TAMPA, FL 336053127		
Owner's Phone:	8132475402	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	74/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SEACOAST SUPPLY (Continued)

U001354849

Facility ID:	298625642	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WALT JACKSON		
Contact:	Not reported	Facility Phone:	8132475402
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ED VAN BRUNT		
Owner:	L & W SUPPLY CORP 2817 N 36TH ST TAMPA, FL 336053127		
Owner's Phone:	8132475402	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	79/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

12

ARAMARK UNIFORM SERVICES  
2817 N 35TH ST  
TAMPA, FL 33605

UST

U002313284  
N/A

12

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ARAMARK UNIFORM SERVICES (Continued)

U002313284

### UST:

Facility ID:	299502463	Facility Type:	4
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KREJCI, PHIL		
Contact:	Not reported	Facility Phone:	7083979500
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	950810	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	KREJCI, PHIL		
Owner:	ARAMARK UNIFORM SERVICES		
	PO BOX 7891		
	BURBANK, CA 91510		
Owner's Phone:	7083979500	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

12

ARATEX SERVICES INC  
2817 N 35TH ST  
TAMPA, FL 33605

UST  
LUST

U001355270  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ARATEX SERVICES INC (Continued)

U001355270

### LUST:

Facility ID:	8627781	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132472116	Discovery Date:	12/14/88
Tracking Number:	295372	Score:	035
Facility Code:	Not reported	Status:	Not reported
Rank:	03338		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Y	Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

12

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ARATEX SERVICES INC (Continued)

U001355270

### UST:

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ARATEX SERVICES INC (Continued)

U001355270

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ARATEX SERVICES INC (Continued)

U001355270

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink, Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ARATEX SERVICES INC (Continued)

U001355270

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ARATEX SERVICES INC (Continued)

U001355270

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

12

CHEMEX PAINT & COATINGS INC  
2822 N 35TH ST  
TAMPA, FL 33605

UST  
AST

U001355417  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

### UST:

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006400	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006400	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

### AST:

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	11	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001500
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	12	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00001500
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	13	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00001500
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	14	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000750
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	15	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00010000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC		
	PO BOX 5449 % TONY FOSTER		
	TAMPA, FL 33675		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00002000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

12

**CHEMEX PAINT & COATINGS CO**  
**2822 N 35TH ST**  
**TAMPA, FL 33675**

FINDS

1000733512  
FLD067222265

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

13

**SIXTY-SECOND STREET DUMP**  
**N OF COLUMBUS W OF 62ND ST**  
**TAMPA, FL 33619**

CERCLIS  
FINDS  
NPL  
SWF/LF

1000184064  
FLD980728877

### CERCLIS Classification Data:

Site Incident Category: LANDFILL  
Ownership Status: OTHER  
EPA Notes: Not reported

Federal Facility: NO  
NPL Status: CURRENTLY ON THE FINAL NPL

### CERCLIS Assessment History:

Assessment:	DISCOVERY	Completed:	08/01/1982
Assessment:	PRELIMINARY ASSESSMENT	Completed:	10/01/1984
Assessment:	SCREENING SITE INSPECTION	Completed:	11/01/1984
Assessment:	HAZARD RANKING DETERMINED	Completed:	12/01/1982
Assessment:	FINAL LISTING ON NPL	Completed:	09/08/1983
Assessment:	PROPOSAL TO NPL	Completed:	12/30/1982
Assessment:	RMVL INVESTIGATION AT NPL	Completed:	09/21/1992
Assessment:	COMBINED RI/FS	Completed:	06/27/1990
Assessment:	REMEDIAL COMMUNITY RELATIONS	Completed:	Not reported
Assessment:	RECORD OF DECISION	Completed:	06/27/1990
Assessment:	HEALTH ASSESSMENT	Completed:	Not reported
Assessment:	ADMINISTRATIVE RECORD	Completed:	06/27/1990
Assessment:	FIVE YEAR REMEDY ASSESSMENT	Completed:	Not reported

### CERCLIS Site Status:

This site is currently under investigation by the government to assess the extent of further action

13

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SIXTY-SECOND STREET DUMP (Continued)

1000184064

CERCLIS Alias Name(s):

62ND STREET DUMP

SIXTY-SECOND STREET DUMP

NPL:

ID: 04FL026

Date Listed: 9/08/83 (FINAL)

EPA/ID: FLD980728877

Haz. Rank Score: 49.09

Status: LISTED ON NPL

Rank: 215

Group: 5

Ownership: Private

Permit: None

Site Activities: Landfill, Comm./Indus.

Site Condition: Contam. Ground Water

Waste Type: Metals

Waste Form: Not reported

Contaminant: Media Affected:

LEAD (PB) Ground and Surface Water

COPPER AND COMPOUNDS, NOS (CU) Surface Water

Distance to nearest Population: Not reported

Population within a 1 Mile Radius: Not reported

Population within a 2 Mile Radius: Not reported

Population within a 4 Mile Radius: Not reported

Vertical Distance to Aquifer: Not reported

Ground Water Use: Not Used as Drinking Water, Alternative Source Available

Distance to nearest Surface Water: Not reported

Other Pertinent Environmental Activity Identified at Site:

civil judicial and administrative enforcement cases against facility

LF:

Facility ID: 4029P81630

Population Served: Not reported

Amount Daily Waste: Not reported

Facility Telephone: Not reported

Facility Status: INACTIVE

Design Capacity: 0.0000

Number of Monitoring Wells: 0 WELLS

Facility Contact: LEE PILCHER

14

**CLOROX CO**  
**3601 E COLUMBUS DR**  
**TAMPA, FL 33605**

**FINDS**  
**TRIS**  
**UST**  
**LUST**  
**AST**

**1000732997**  
**FLD004097945**

Other Pertinent Environmental Activity Identified at Site:

facility is involved with pesticide/toxic substances production

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CLOROX CO (Continued)

1000732997

## LUST:

Facility ID:	8627500	Facility Type:	INDUSTRIAL PLANT
Alias Name:	Not reported		
Telephone:	8132481161	Discovery Date:	12/21/89
Tracking Number:	Not reported	Score:	029 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	04761		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CLOROX CO (Continued)

1000732997

### UST:

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Contact:	Not reported	Facility Phone:	8132481161
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	SPCC plan		

### AST:

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00015000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	82/12
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CLOROX CO (Continued)

1000732997

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	86/04
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	92/09
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CLOROX CO (Continued)

1000732997

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	5	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO 3601 E COLUMBUS DR TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	89/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	6	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO 3601 E COLUMBUS DR TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	86/04
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Pressurized piping		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CLOROX CO (Continued)

1000732997

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	7	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00016000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	52/07
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Pressurized piping		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	Not reported
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	8	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 33605		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00016000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	52/07
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Pressurized piping		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

14

VAN LEEUWEN PIPE & TUBE OF THE SE INC  
2721 N 36TH ST  
TAMPA, FL 33605

UST  
LUST

U001354634  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

LUST:

Facility ID:	8625415	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132471151	Discovery Date:	04/17/90
Tracking Number:	Not reported	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

### UST:

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VEHICLE LEASING CORP. P O DRAWER "C" TAMPA, FL 33675		
Owner's Phone:	8132471151	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VEHICLE LEASING CORP.		
	P O DRAWER "C"		
	TAMPA, FL 33675		
Owner's Phone:	8132471151	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VEHICLE LEASING CORP. P O DRAWER "C" TAMPA, FL 33675		
Owner's Phone:	8132471151	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Gasohol	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VEHICLE LEASING CORP. P O DRAWER "C" TAMPA, FL 33675		
Owner's Phone:	8132471151	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

15

YOUNGBLOOD SR./W.E.  
2708 N 56TH ST  
TAMPA, FL 33619

UST

U001355154  
N/A



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## YOUNGBLOOD SR./W.E. (Continued)

U001355154

### UST:

Facility ID:	298627250	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	W. E. YOUNGBLOOD SR.		
Contact:	Not reported	Facility Phone:	8136261017
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	W. E. YOUNGBLOOD, SR.		
Owner:	YOUNGBLOOD, W E SR		
	2708 N 56TH ST		
	TAMPA, FL 336192418		
Owner's Phone:	8136261017	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000600	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

16	FLORIDA PRECAST CONCRETE INC 2705 N 35TH ST TAMPA, FL 33605	FINDS	1000737773 FLD984209502
16	FL PRECAST CONCRETE, INC 2705 N 35TH ST TAMPA, FL 33605	AST	A100008727 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL PRECAST CONCRETE, INC (Continued)

A100008727

### AST:

Facility ID:	298625689	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WATTS,WILLIAM JR		
Facility Phone:	8132476663	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLIAM WATTS JR		
Owner:	FL PRECAST CONCRETE INC		
	2705 N 35TH ST		
	TAMPA, FL 336053121		
Owner's Phone:	8132476663	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000400
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

Facility ID:	298625689	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WATTS,WILLIAM JR		
Facility Phone:	8132476663	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLIAM WATTS JR		
Owner:	FL PRECAST CONCRETE INC		
	2705 N 35TH ST		
	TAMPA, FL 336053121		
Owner's Phone:	8132476663	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000400
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

16

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## FL PRECAST CONCRETE, INC (Continued)

A100008727

Facility ID:	298625689	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WATTS,WILLIAM JR	Permit Section:	Not reported
Facility Phone:	8132476663	Financial responsibility:	Not reported
Date entered:	860523	District:	Southwest
Tank ID:	3		
Owner's Contact:	WILLIAM WATTS JR		
Owner:	FL PRECAST CONCRETE INC		
	2705 N 35TH ST		
	TAMPA, FL 336053121		
Owner's Phone:	8132476663	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000800
Tank Content:	Leaded gas	Contaminated media indicator:	Not reported
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

16	WEIL CHEMICAL TAMPA (CANCEL 1980) 2714 35TH STREET-PO BOX 5527 TAMPA, FL 33605	FINDS	1000932234 FL0000600858
17	3 WAY CLEANERS 1420 E COLUMBUS DR TAMPA, FL 33605	RCRIS-SQG FINDS	1000202041 FLD981921794
18	SOUTHERN HYDRAULIC SERVICE 1502 E COLUMBUS DR TAMPA, FL 33605	UST LUST	U001356239 N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

LUST:

Facility ID:	9100548	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	03/22/91
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

146

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

### UST:

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE		
	1502 E COLUMBUS DR		
	TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink, Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE		
	1502 E COLUMBUS DR		
	TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE 1502 E COLUMBUS DR TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

180

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE		
	1502 E COLUMBUS DR		
	TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE		
	1502 E COLUMBUS DR		
	TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE		
	1502 E COLUMBUS DR		
	TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

196

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE		
	1502 E COLUMBUS DR		
	TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE 1502 E COLUMBUS DR TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

19

STANDARD CIGAR CO  
2701 N 16TH ST  
TAMPA, FL 33605

UST

U001356156  
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

STANDARD CIGAR CO (Continued)

U001356156

UST:

Facility ID:	299046769	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STANDARD CIGAR CO		
Contact:	Not reported	Facility Phone:	8132482124
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900719	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RAY EADY		
Owner:	STANDARD CIGAR CO		
	2701 N 16TH ST		
	TAMPA, FL 336052616		
Owner's Phone:	8132482124	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Suction piping		
Petro. Monitoring:	Not required		

20

FORMER POPEYE'S CHICKEN  
2702 N 50TH ST  
TAMPA, FL 33605

UST  
LUST

U002038287  
N/A

20

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FORMER POPEYE'S CHICKEN (Continued)

U002038287

### LUST:

Facility ID:	9402013	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	7147075408	Discovery Date:	10/26/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

20

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FORMER POPEYE'S CHICKEN (Continued)

U002038287

### UST:

Facility ID:	299402013	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	7147075408
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	941201	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	CHRISSE P. TABONE		
Owner:	HOLLY REAL ESTATE INVESTMENTS		
	23041 AVENIDA DE LA CARLOTA #210		
	LAGUNA HILLS, CA 92653		
Owner's Phone:	7147075408	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	No
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

21

**KASSAUF-KIMERLING BATTERY DISPOSAL**  
**58TH ST & COLUMBUS DR**  
**TAMPA, FL 33619**

**CERCLIS** 1000385495  
**FINDS** FLD980727820  
**NPL**  
**CONSENT**

### CERCLIS Classification Data:

Site Incident Category:	MANUFACTURING PLANT	Federal Facility:	NO
Ownership Status:	OTHER	NPL Status:	CURRENTLY ON THE FINAL NPL
EPA Notes:	Not reported		

### CERCLIS Assessment History:

Assessment:	DISCOVERY	Completed:	03/01/1981
Assessment:	PRELIMINARY ASSESSMENT	Completed:	10/01/1984
Assessment:	SCREENING SITE INSPECTION	Completed:	04/01/1981
Assessment:	HAZARD RANKING DETERMINED	Completed:	12/01/1982
Assessment:	FINAL LISTING ON NPL	Completed:	09/08/1983
Assessment:	PROPOSAL TO NPL	Completed:	10/23/1981
Assessment:	RMVL INVESTIGATION AT NPL	Completed:	09/03/1991
Assessment:	COMBINED RI/FS	Completed:	03/31/1989
Assessment:	REMEDIAL COMMUNITY RELATIONS	Completed:	Not reported
Assessment:	REMEDIAL INVESTIGATION	Completed:	09/30/1983
Assessment:	RECORD OF DECISION	Completed:	03/31/1989
Assessment:	ADMINISTRATIVE RECORD	Completed:	06/18/1989
Assessment:	COMBINED RI/FS	Completed:	03/30/1990
Assessment:	RECORD OF DECISION	Completed:	03/30/1990
Assessment:	REMEDIAL COMMUNITY RELATIONS	Completed:	Not reported
Assessment:	ADMINISTRATIVE RECORD	Completed:	03/30/1990

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

**KASSAUF-KIMERLING BATTERY DISPOSAL (Continued)**

1000385495

**CERCLIS Site Status:**

This site is currently under investigation by the government to assess the extent of further action

**CERCLIS Alias Name(s):**

KASSOUF-KIMERLING BATTERY DISPOSAL  
TIMBERLAKE BATTERY  
58TH STREET LANDFILL  
58TH STREET LANDFILL  
TIMBERLAKE BATTERY DSPL

**NPL:**

ID:	04FL009
Date Listed:	9/08/83 (FINAL)
EPA/ID:	FLD980727820
Haz. Rank Score:	53.42
Status:	LISTED ON NPL
Rank:	136
Group:	3
Ownership:	Private
Permit:	None
Site Activities:	Waste Piles
Site Condition:	Contam. Food Chain
Site Condition:	Contamination of Soil
Site Condition:	Contam. Ground Water
Waste Type:	Metals
Waste Form:	Not reported
Contaminant:	Media Affected:
LEAD (PB)	Ground and Surface Water
ZINC AND COMPOUNDS, NOS (ZN)	Not reported
Distance to nearest Population:	Not reported
Population within a 1 Mile Radius:	Not reported
Population within a 2 Mile Radius:	Not reported
Population within a 4 Mile Radius:	Not reported
Vertical Distance to Aquifer:	Not reported
Ground Water Use:	Used as Drinking Water, Alternative Source not Available
Distance to nearest Surface Water:	Not reported

**CONSENT:**

Full-text of a consent decree on this site issued by a United States District Court is available from EDR.

**Other Pertinent Environmental Activity Identified at Site:**

civil judicial and administrative enforcement cases against facility

22

**JD GARAGE**  
**2701 E COLUMBUS DR**  
**TAMPA, FL 33605**

UST

U001355065  
N/A

22



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## JD GARAGE (Continued)

U001355065

### UST:

Facility ID:	298626956	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JADIE SINGLETARY		
Contact:	Not reported	Facility Phone:	8132482592
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861023	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JADIE SINGLETARY		
Owner:	SINGLETARY, JADIE		
	171 LEWIS RD		
	THONOTOSASSA, FL 335929320		
Owner's Phone:	8132482592	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

23

**CLOROX CO**  
**3702 E COLUMBUS DR**  
**TAMPA, FL 33601**

**FINDS** 1000368352  
**RCRIS-LQG** FLD984171470

### RCRIS:

Owner: JOHN PRIEN, ENV COORD  
(813) 248-1161

Contact: DENNIS DONALSON  
(813) 626-3125

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

23

**INTERSTATE WAREHOUSES, LTD.**  
**3701 E COLUMBUS DR**  
**TAMPA, FL 33605**

**UST** U001354108  
**LUST** N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INTERSTATE WAREHOUSES,LTD. (Continued)

U001354108

### LUST:

Facility ID:	8624850	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	06/23/92
Tracking Number:	Not reported	Score:	029 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	04761		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
------------	------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## INTERSTATE WAREHOUSES,LTD. (Continued)

U001354108

### UST:

Facility ID:	298624850	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	INTERSTATE WAREHOUSES,LTD.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE W. LACKEY		
Owner:	GEORGIA-PACIFIC CORP.		
	815 S 56TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8136211351	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

INTERSTATE WAREHOUSES,LTD. (Continued)

U001354108

Facility ID:	298624850	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	INTERSTATE WAREHOUSES,LTD.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE W. LACKEY		
Owner:	GEORGIA-PACIFIC CORP.		
	815 S 56TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8136211351	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

24

C & A PROPERTIES  
4004 E COLUMBUS DR  
TAMPA, FL 33605

UST  
LUST

U001354609  
N/A

24

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C & A PROPERTIES (Continued)

U001354609

### LUST:

Facility ID:	8625389	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	PIE NATIONWIDE INC		
Telephone:	8132583631	Discovery Date:	05/21/91
Tracking Number:	Not reported	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	DISTRICT OFFICE
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C & A PROPERTIES (Continued)

U001354609

### UST:

Facility ID:	298625389	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	C & A PROPERTIES		
Contact:	Not reported	Facility Phone:	8132583631
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	PHILLIP ROVERS		
Owner:	C & A PROPERTIES		
	588 MARMORA AVE		
	TAMPA, FL 336063824		
Owner's Phone:	8132583631	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	57/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, GW mon plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## C & A PROPERTIES (Continued)

U001354609

Facility ID:	298625389	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	C & A PROPERTIES		
Contact:	Not reported	Facility Phone:	8132583631
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	PHILLIP ROVERS		
Owner:	C & A PROPERTIES		
	588 MARMORA AVE		
	TAMPA, FL 336063824		
Owner's Phone:	8132583631	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	57/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells, GW mon plan		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## C & A PROPERTIES (Continued)

U001354609

Facility ID:	298625389	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	C & A PROPERTIES		
Contact:	Not reported	Facility Phone:	8132583631
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	PHILLIP ROVERS		
Owner:	C & A PROPERTIES		
	588 MARMORA AVE		
	TAMPA, FL 336063824		
Owner's Phone:	8132583631	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## C & A PROPERTIES (Continued)

U001354609

Facility ID:	298625389	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	C & A PROPERTIES		
Contact:	Not reported	Facility Phone:	8132583631
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	PHILLIP ROVERS		
Owner:	C & A PROPERTIES		
	588 MARMORA AVE		
	TAMPA, FL 336063824		
Owner's Phone:	8132583631	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## C & A PROPERTIES (Continued)

U001354609

Facility ID:	298625389	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	C & A PROPERTIES		
Contact:	Not reported	Facility Phone:	8132583631
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	PHILLIP ROVERS		
Owner:	C & A PROPERTIES		
	588 MARMORA AVE		
	TAMPA, FL 336063824		
Owner's Phone:	8132583631	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## C & A PROPERTIES (Continued)

U001354609

Facility ID:	298625389	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	C & A PROPERTIES		
Contact:	Not reported	Facility Phone:	8132583631
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	None
Tank ID:	6	District:	Southwest
Owner's Contact:	PHILLIP ROVERS		
Owner:	C & A PROPERTIES		
	588 MARMORA AVE		
	TAMPA, FL 336063824		
Owner's Phone:	8132583631	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

24

**RYDER TRUCK RENTAL**  
**4000 E COLUMBUS DR**  
**TAMPA, FL 33605**

UST  
LUST

U001354644  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RYDER TRUCK RENTAL (Continued)

U001354644

### LUST:

Facility ID:	8625425	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136213021	Discovery Date:	06/30/89
Tracking Number:	Not reported	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	03768		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RYDER TRUCK RENTAL (Continued)

U001354644

### UST:

Facility ID:	298625425	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CREED EARL		
Contact:	Not reported	Facility Phone:	8136213021
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC 4008 E COLUMBUS DR TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

U001354644

Facility ID:	298625425	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CREED EARL		
Contact:	Not reported	Facility Phone:	8136213021
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink, Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

24

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

U001354644

Facility ID:	298625425	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CREED EARL		
Contact:	Not reported	Facility Phone:	8136213021
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

U001354644

Facility ID:	298625425	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CREED EARL		
Contact:	Not reported	Facility Phone:	8136213021
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

U001354644

Facility ID:	298625425	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CREED EARL		
Contact:	Not reported	Facility Phone:	8136213021
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

U001354644

Facility ID:	298625425	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CREED EARL		
Contact:	Not reported	Facility Phone:	8136213021
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

U001354644

Facility ID:	298625425	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CREED EARL		
Contact:	Not reported	Facility Phone:	8136213021
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

U001354644

Facility ID:	298625425	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CREED EARL		
Contact:	Not reported	Facility Phone:	8136213021
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

24

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

U001354644

Facility ID:	298625425	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CREED EARL		
Contact:	Not reported	Facility Phone:	8136213021
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC 4008 E COLUMBUS DR TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## RYDER TRUCK RENTAL (Continued)

U001354644

Facility ID:	298625425	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CREED EARL		
Contact:	Not reported	Facility Phone:	8136213021
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	BOB CORRENTE		
Owner:	RYDER TRUCK RENTAL INC		
	4008 E COLUMBUS DR		
	TAMPA, FL 336053225		
Owner's Phone:	8136213021	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

24	RYDER TRUCK RENTAL 4008 EAST COLUMBUS DRIVE TAMPA, FL 33605	RCRIS-SQG	1000211580 FLD981860497
24	RYDER TRUCK RENTAL 4008 E COLUMBUS DR TAMPA, FL 33605	FINDS	1000211570 FLD032799215
25	GUARINO PROPERTY 3916 E COLOMBUS DR TAMPA, FL 33605	UST LUST	U001823409 N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**GUARINO PROPERTY (Continued)**

U001823409

**LUST:**

Facility ID:	9400568	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138847484	Discovery Date:	Not reported
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

**INCIDENT GENERAL INFORMATION -**

Source Description:	Not reported
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

**INCIDENT POLLUTANT INFORMATION -**

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

**INCIDENT PROGRAM INFORMATION -**

Incident Program:	Not reported
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

**INCIDENT INITIAL REMEDIAL ACTION INFORMATION -**

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

**INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -**

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

**INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -**

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

**INCIDENT REMEDIAL ACTION REPORT INFORMATION -**

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

**INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -**

Site Rehab. Completion Action:	Not reported
Region:	STATE

25

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

**GUARINO PROPERTY (Continued)**

U001823409

UST:

Facility ID:	299400568	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAUL GUARINO		
Contact:	Not reported	Facility Phone:	8138847484
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940406	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PAUL GUARINO		
Owner:	GUARINO, PAUL 3815 N 40TH ST TAMPA, FL 33605		
Owner's Phone:	8138847484	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

26

**PARTS & EQUIPMENT DISTRIBUTORS,INC.**  
**4317 E COLUMBUS DR**  
**TAMPA, FL 33605**

UST  
LUST

U001355567  
N/A

26



MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

PARTS & EQUIPMENT DISTRIBUTORS,INC. (Continued)

U001355567

LUST:

Facility ID:	8735721	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136218081	Discovery Date:	11/12/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

26

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## PARTS & EQUIPMENT DISTRIBUTORS,INC. (Continued)

U001355567

### UST:

Facility ID:	298735721	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PARTS & EQUIPMENT DISTRIBUTORS		
Contact:	Not reported	Facility Phone:	8136218081
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871023	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	PARTS & EQUIPMENT DISTRIBUTING		
	4317 E COLUMBUS DR		
	TAMPA, FL 336053230		
Owner's Phone:	8136218081	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

26

TAMPA FORKLIFT INC  
4315 E COLUMBUS DR  
TAMPA, FL 33605

UST  
LUST

U002113434  
N/A

26

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

TAMPA FORKLIFT INC (Continued)

U002113434

LUST:

Facility ID:	9501517	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136235251	Discovery Date:	02/02/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	BUREAU OF WASTE CLEANUP
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

26

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA FORKLIFT INC (Continued)

U002113434

### UST:

Facility ID:	299501517	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA FORKLIFT INC		
Contact:	Not reported	Facility Phone:	8136235251
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	950302	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	LOU CAMPILLO		
Owner:	TAMPA FORKLIFT INC 4315 E COLUMBUS DR TAMPA, FL 33605		
Owner's Phone:	8136235251	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	No
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

26

BOWMAN TRANSP CO INC  
4310 E COLUMBUS DR  
TAMPA, FL 33675

RCRIS-SQG 1000295235  
FINDS FLD981858616  
UST  
LUST

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**BOWMAN TRANSP CO INC (Continued)**

1000295235

LUST:

Facility ID:	8625717	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136267156	Discovery Date:	12/10/90
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Y	Alt. Process Date:	Not reported
Soil Treatment:	Y	Alternative Status:	Not reported
Other Treatment:			

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

26

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## BOWMAN TRANSP CO INC (Continued)

1000295235

### UST:

Facility ID:	298625717	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MEL PARKER		
Contact:	Not reported	Facility Phone:	8136267156
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	P.F. GREENE,JR.		
Owner:	BOWMAN TRANSPORTATION INC		
	PO BOX 17744		
	ATLANTA, GA 303160744		
Owner's Phone:	4043610220	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## BOWMAN TRANSP CO INC (Continued)

1000295235

Facility ID:	298625717	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MEL PARKER		
Contact:	Not reported	Facility Phone:	8136267156
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	P.F. GREENE,JR.		
Owner:	BOWMAN TRANSPORTATION INC		
	PO BOX 17744		
	ATLANTA, GA 303160744		
Owner's Phone:	4043610220	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BOWMAN TRANSP CO INC (Continued)

1000295235

Facility ID:	298625717	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MEL PARKER		
Contact:	Not reported	Facility Phone:	8136267156
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	P.F. GREENE,JR.		
Owner:	BOWMAN TRANSPORTATION INC		
	PO BOX 17744		
	ATLANTA, GA 303160744		
Owner's Phone:	4043610220	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

26

## ORANGE CO TRUCK & TRAILER 4306 E COLUMBUS DR TAMPA, FL 33605

RCRIS-SQG  
FINDS

1000821917  
FLD984249383

### RCRIS:

Owner: DUANE CROUSE  
(813) 664-1441

Contact:DUANE CROUSE  
(813) 664-1441

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D006	.00000 (T)	Notification	D007	.00000 (T)	Notification
D008	.00000 (T)	Notification	D018	.00000 (T)	Notification
D021	.00000 (T)	Notification	D027	.00000 (T)	Notification
D039	.00000 (T)	Notification	D040	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

27

## GENUINE PARTS CO 4608 E COLUMBUS DR TAMPA, FL 33612

RCRIS-SQG  
FINDS

1000425188  
FLD982078180



# MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

## GENUINE PARTS CO (Continued)

1000425188

RCRIS:

Owner: RICK NELSON, MGR  
(813) 935-2742

Contact: RICK NELSON  
(813) 935-2742

Waste	Quantity	Info Source	Waste	Quantity	Info Source
-------	----------	-------------	-------	----------	-------------

D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
------	------------	--------------	------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

28

KASH N' KARRY FOOD STORE  
5028 E COLUMBUS DR  
TAMPA, FL 33619

UST  
LUST

U001354392  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N' KARRY FOOD STORE (Continued)

U001354392

### LUST:

Facility ID:	8625155	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	09/22/88
Tracking Number:	292988	Score:	040
Facility Code:	Not reported	Status:	Not reported
Rank:	02461		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	REC DRAW
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

28

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N' KARRY FOOD STORE (Continued)

U001354392

### UST:

Facility ID:	298841340	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N' KARRY FOOD STORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880826	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	C J KENNEDY		
Owner:	LUCKY STORES, INC 6422 HARNEY RD TAMPA, FL 33610		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N' KARRY FOOD STORE (Continued)

U001354392

Facility ID:	298841340	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N' KARRY FOOD STORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880826	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	C J KENNEDY		
Owner:	LUCKY STORES, INC		
	6422 HARNEY RD		
	TAMPA, FL 33610		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

206

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N' KARRY FOOD STORE (Continued)

U001354392

Facility ID:	298841340	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N' KARRY FOOD STORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880826	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	C J KENNEDY		
Owner:	LUCKY STORES, INC		
	6422 HARNEY RD		
	TAMPA, FL 33610		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

28

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N' KARRY FOOD STORE (Continued)

U001354392

Facility ID:	298841340	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N' KARRY FOOD STORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880826	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	C J KENNEDY		
Owner:	LUCKY STORES, INC 6422 HARNEY RD TAMPA, FL 33610		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N' KARRY FOOD STORE (Continued)

U001354392

Facility ID:	298625155	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N' KARRY FOOD STORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	C J KENNEDY		
Owner:	LUCKY STORES, INC		
	6422 HARNEY RD		
	TAMPA, FL 33610		
Owner's Phone:	Not reported	Tracking #:	292988
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N' KARRY FOOD STORE (Continued)

U001354392

Facility ID:	298625155	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N' KARRY FOOD STORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	C J KENNEDY		
Owner:	LUCKY STORES, INC		
	6422 HARNEY RD		
	TAMPA, FL 33610		
Owner's Phone:	Not reported	Tracking #:	292988
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

26



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N' KARRY FOOD STORE (Continued)

U001354392

Facility ID:	298625155	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N' KARRY FOOD STORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	C J KENNEDY		
Owner:	LUCKY STORES, INC		
	6422 HARNEY RD		
	TAMPA, FL 33610		
Owner's Phone:	Not reported	Tracking #:	292988
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Gasohol	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

29

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## KASH N' KARRY FOOD STORE (Continued)

U001354392

Facility ID:	298625155	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N' KARRY FOOD STORE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	C J KENNEDY		
Owner:	LUCKY STORES, INC		
	6422 HARNEY RD		
	TAMPA, FL 33610		
Owner's Phone:	Not reported	Tracking #:	292988
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Gasohol	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

29

SPEEDWAY #0090  
2602 N 50TH ST  
TAMPA, FL 33619

UST  
LUST

U001354784  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**SPEEDWAY #0090 (Continued)**

U001354784

LUST:

Facility ID:	8625572	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	4044588100	Discovery Date:	11/17/90
Tracking Number:	293189	Score:	048
Facility Code:	Not reported	Status:	Not reported
Rank:	02180		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	ANNUAL
Report Comments:	(SEMI-ANNUAL)

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

29

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPEEDWAY #0090 (Continued)

U001354784

### UST:

Facility ID:	298625572	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	R A FORTMAN		
Contact:	Not reported	Facility Phone:	4044588100
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TED M JASTAL		
Owner:	EMRO MARKETING CO SOUTHERN DIV PO BOX 1500 % CORP ENVIRONMENTAL SPRINGFIELD, OH 45501		
Owner's Phone:	5138643000	Tracking #:	293189
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/02
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-imp curr, Spill cnmt, Op-tight fill, Level gauges/hi level alarms		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

29

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPEEDWAY #0090 (Continued)

U001354784

Facility ID:	298625572	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	R A FORTMAN		
Contact:	Not reported	Facility Phone:	4044588100
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	TED M JASTAL		
Owner:	EMRO MARKETING CO SOUTHERN DIV PO BOX 1500 % CORP ENVIRONMENTAL SPRINGFIELD, OH 45501		
Owner's Phone:	5138643000	Tracking #:	293189
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/02
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-imp curr, Spill cnmt, Op-tight fill, Level gauges/hi level alarms		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

29

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPEEDWAY #0090 (Continued)

U001354784

Facility ID:	298625572	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	R A FORTMAN		
Contact:	Not reported	Facility Phone:	4044588100
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	TED M JASTAL		
Owner:	EMRO MARKETING CO SOUTHERN DIV PO BOX 1500 % CORP ENVIRONMENTAL SPRINGFIELD, OH 45501		
Owner's Phone:	5138643000	Tracking #:	293189
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/02
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-imp curr, Spill cnmt, Op-tight fill, Level gauges/hi level alarms		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

29

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SPEEDWAY #0090 (Continued)

U001354784

Facility ID:	298625572	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	R A FORTMAN		
Contact:	Not reported	Facility Phone:	4044588100
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	TED M JASTAL		
Owner:	EMRO MARKETING CO SOUTHERN DIV PO BOX 1500 % CORP ENVIRONMENTAL SPRINGFIELD, OH 45501		
Owner's Phone:	5138643000	Tracking #:	293189
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/02
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-imp curr, Spill cnmt, Op-tight fill, Level gauges/hi level alarms		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

29

EXXON CO USA #49122  
2605 N 50TH & COLUMBUS  
TAMPA, FL 33619

FINDS  
UST  
LUST

1000736459  
FLD984185710

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49122 (Continued)

1000736459

## LUST:

Facility ID:	8625560	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132871557	Discovery Date:	09/26/86
Tracking Number:	290803	Score:	047
Facility Code:	Not reported	Status:	Not reported
Rank:	02196		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	ANNUAL
Report Comments:	YR 1

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE

29



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

EXXON CO USA #49122 (Continued)

1000736459

## UST:

Facility ID:	298625560	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8132871557
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290803
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink, Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-sac anode		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

291

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49122 (Continued)

1000736459

Facility ID:	298625560	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8132871557
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290803
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

EXXON CO USA #49122 (Continued)

1000736459

Facility ID:	298625560	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8132871557
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290803
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-sac anode		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

29

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

EXXON CO USA #49122 (Continued)

1000736459

Facility ID:	298625560	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8132871557
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290803
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49122 (Continued)

1000736459

Facility ID:	298625560	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8132871557
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290803
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

291

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

EXXON CO USA #49122 (Continued)

1000736459

Facility ID:	298625560	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8132871557
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290803
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49122 (Continued)

1000736459

Facility ID:	298625560	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8132871557
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290803
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink, Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

29

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49122 (Continued)

1000736459

Facility ID:	298625560	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8132871557
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290803
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging		

29



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## EXXON CO USA #49122 (Continued)

1000736459

Facility ID:	298625560	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	EXXON CO USA		
Contact:	Not reported	Facility Phone:	8132871557
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290803
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

30

DASH IN DASH OUT FOOD MART-I-4 & 40TH  
2610 N 40TH ST  
TAMPA, FL 33605

UST  
LUST

U001354496  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DASH IN DASH OUT FOOD MART-I-4 & 40TH (Continued)

U001354496

### LUST:

Facility ID:	8625265	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8136212571	Discovery Date:	12/22/88
Tracking Number:	298183	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

30

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DASH IN DASH OUT FOOD MART-I-4 & 40TH (Continued)

U001354496

### UST:

Facility ID:	298625265	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOU BARTON		
Contact:	Not reported	Facility Phone:	8136212571
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298183
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

30

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DASH IN DASH OUT FOOD MART-I-4 & 40TH (Continued)

U001354496

Facility ID:	298625265	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOU BARTON		
Contact:	Not reported	Facility Phone:	8136212571
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1R1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298183
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Dbl walled=primary matl, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging		

30

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DASH IN DASH OUT FOOD MART-I-4 & 40TH (Continued)

U001354496

Facility ID:	298625265	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOU BARTON		
Contact:	Not reported	Facility Phone:	8136212571
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298183
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt, Op-tight fill		
Tank Piping:	Cathod prot steel, Pressurized piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Piping/flow restrictor, Man tank gauging		

36

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DASH IN DASH OUT FOOD MART-I-4 & 40TH (Continued)

U001354496

Facility ID:	298625265	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOU BARTON		
Contact:	Not reported	Facility Phone:	8136212571
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298183
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt, Op-tight fill		
Tank Piping:	Cathod prot steel, Suction piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Piping/flow restrictor, Man tank gauging		

30

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DASH IN DASH OUT FOOD MART-I-4 & 40TH (Continued)

U001354496

Facility ID:	298625265	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOU BARTON		
Contact:	Not reported	Facility Phone:	8136212571
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298183
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt, Op-tight fill		
Tank Piping:	Cathod prot steel, Suction piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

30

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

DASH IN DASH OUT FOOD MART-I-4 & 40TH (Continued)

U001354496

Facility ID:	298625265	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOU BARTON		
Contact:	Not reported	Facility Phone:	8136212571
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298183
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/03
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Dbl walled=primary matl, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dbl wall=primary matl		
Petro. Monitoring:	Not required, Man tank gauging		

30

RADIANT FOODS #262  
2611 N 40TH ST  
TAMPA, FL 33605

UST  
LUST

U001355814  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT FOODS #262 (Continued)

U001355814

### LUST:

Facility ID:	8840413	Facility Type:	RETAIL STATION
Alias Name:	SPARKY'S 303		
Alias Name 2:	DONAWAY SERVICE CENTERS,INC.		
Telephone:	8132474731	Discovery Date:	11/23/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

30

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT FOODS #262 (Continued)

U001355814

### UST:

Facility ID:	298840413	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880422	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	Z Q O INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

30

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT FOODS #262 (Continued)

U001355814

Facility ID:	298840413	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880422	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	Z Q O INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	install. Date:	88/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

30

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT FOODS #262 (Continued)

U001355814

Facility ID:	298840413	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880422	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	Z Q O INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

26

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT FOODS #262 (Continued)

U001355814

Facility ID:	298840413	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880422	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	Z Q O INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

30

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT FOODS #262 (Continued)

U001355814

Facility ID:	298840413	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880422	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	Z Q O INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

30

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT FOODS #262 (Continued)

U001355814

Facility ID:	298840413	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880422	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	Z Q O INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

30

2611 N 40TH ST  
TAMPA, FL

HMIRS

94091146  
N/A

31

UNITED 500 #507  
2502 N 50TH ST  
TAMPA, FL 33619

UST  
LUST

U001353977  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

UNITED 500 #507 (Continued)

U001353977

## LUST:

Facility ID:	8509079	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132473266	Discovery Date:	02/18/87
Tracking Number:	290494	Score:	037
Facility Code:	Not reported	Status:	Not reported
Rank:	02851		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

31



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

UNITED 500 #507 (Continued)

U001353977

## UST:

Facility ID:	298509079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LETCWORTH, MABLE		
Contact:	Not reported	Facility Phone:	8132473266
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	T D MCRAE		
Owner:	UNITED PETROLEUM INC		
	7305 ROWLETT PARK DR		
	TAMPA, FL 336101141		
Owner's Phone:	8132386491	Tracking #:	290494
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	65/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt		
Tank Piping:	Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

UNITED 500 #507 (Continued)

U001353977

Facility ID:	298509079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LETCHWORTH, MABLE		
Contact:	Not reported	Facility Phone:	8132473266
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	T D MCRAE		
Owner:	UNITED PETROLEUM INC 7305 ROWLETT PARK DR TAMPA, FL 336101141		
Owner's Phone:	8132386491	Tracking #:	290494
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	65/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt		
Tank Piping:	Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

UNITED 500 #507 (Continued)

U001353977

Facility ID:	298509079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LETCHWORTH, MABLE		
Contact:	Not reported	Facility Phone:	8132473266
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	T D MCRAE		
Owner:	UNITED PETROLEUM INC 7305 ROWLETT PARK DR TAMPA, FL 336101141		
Owner's Phone:	8132386491	Tracking #:	290494
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	65/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt		
Tank Piping:	Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

UNITED 500 #507 (Continued)

U001353977

Facility ID:	298509079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LETCHWORTH, MABLE		
Contact:	Not reported	Facility Phone:	8132473266
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	T D MCRAE		
Owner:	UNITED PETROLEUM INC 7305 ROWLETT PARK DR TAMPA, FL 336101141		
Owner's Phone:	8132386491	Tracking #:	290494
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	65/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt		
Tank Piping:	Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

31

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

UNITED 500 #507 (Continued)

U001353977

Facility ID:	298509079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LETCHWORTH, MABLE		
Contact:	Not reported	Facility Phone:	8132473266
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	T D MCRAE		
Owner:	UNITED PETROLEUM INC 7305 ROWLETT PARK DR TAMPA, FL 336101141		
Owner's Phone:	8132386491	Tracking #:	290494
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt		
Tank Piping:	Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

31

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

UNITED 500 #507 (Continued)

U001353977

Facility ID:	298509079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LETCHWORTH, MABLE		
Contact:	Not reported	Facility Phone:	8132473266
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	T D MCRAE		
Owner:	UNITED PETROLEUM INC 7305 ROWLETT PARK DR TAMPA, FL 336101141		
Owner's Phone:	8132386491	Tracking #:	290494
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt		
Tank Piping:	Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

UNITED 500 #507 (Continued)

U001353977

Facility ID:	298509079	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LETCHWORTH, MABLE		
Contact:	Not reported	Facility Phone:	8132473266
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	T D MCRAE		
Owner:	UNITED PETROLEUM INC 7305 ROWLETT PARK DR TAMPA, FL 336101141		
Owner's Phone:	8132386491	Tracking #:	290494
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Spill cnmt		
Tank Piping:	Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

31

NO HASSLE PAWN INC  
2508 N 50TH ST  
TAMPA, FL 33619

UST  
LUST

U001356191  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## NO HASSLE PAWN INC (Continued)

U001356191

### LUST:

Facility ID:	9100028	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132386491	Discovery Date:	12/06/83
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

21



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## NO HASSLE PAWN INC (Continued)

U001356191

### UST:

Facility ID:	299100028	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NO HASSLE PAWN INC		
Contact:	Not reported	Facility Phone:	8132386491
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910114	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	T D MCRAE		
Owner:	UNITED PETROLEUM INC 7305 ROWLETT PARK DR TAMPA, FL 336101141		
Owner's Phone:	8132386491	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## NO HASSLE PAWN INC (Continued)

U001356191

Facility ID:	299100028	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NO HASSLE PAWN INC		
Contact:	Not reported	Facility Phone:	8132386491
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910114	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	T D MCRAE		
Owner:	UNITED PETROLEUM INC 7305 ROWLETT PARK DR TAMPA, FL 336101141		
Owner's Phone:	8132386491	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

31

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## NO HASSLE PAWN INC (Continued)

U001356191

Facility ID:	299100028	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NO HASSLE PAWN INC		
Contact:	Not reported	Facility Phone:	8132386491
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910114	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	T D MCRAE		
Owner:	UNITED PETROLEUM INC 7305 ROWLETT PARK DR TAMPA, FL 336101141		
Owner's Phone:	8132386491	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## NO HASSLE PAWN INC (Continued)

U001356191

Facility ID:	299100028	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NO HASSLE PAWN INC		
Contact:	Not reported	Facility Phone:	8132386491
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910114	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	T D MCRAE		
Owner:	UNITED PETROLEUM INC		
	7305 ROWLETT PARK DR		
	TAMPA, FL 336101141		
Owner's Phone:	8132386491	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000250	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

31	HI ENERGY AUTO SALES 2508 N 50 ST TAMPA, FL 33619	RCRIS-SQG	1000700007 FLD981918584
31	HI ENERGY AUTO SALES 2508 N 50 ST TAMPA, FL 33619	FINDS	1000734700 FLD981918584
32	MCEWEN LUMBER CO. 2620 N 36TH ST TAMPA, FL 33605	UST LUST	U001355095 N/A

32

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MCEWEN LUMBER CO. (Continued)

U001355095

## LUST:

Facility ID:	8627033	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	10/29/87
Tracking Number:	292224	Score:	009 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07115		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
------------	------------------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	DISTRICT OFFICE
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

32

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MCEWEN LUMBER CO. (Continued)

U001355095

### UST:

Facility ID:	298627033	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MCEWEN LUMBER CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIMI IPPOLITO		
Owner:	MCEWEN LUMBER CO #2		
	2620 N 36TH ST		
	TAMPA, FL 336053114		
Owner's Phone:	8132484111	Tracking #:	292224
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

## MCEWEN LUMBER CO. (Continued)

U001355095

Facility ID:	298627033	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MCEWEN LUMBER CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JIMI IPPOLITO		
Owner:	MCEWEN LUMBER CO #2		
	2620 N 36TH ST		
	TAMPA, FL 336053114		
Owner's Phone:	8132484111	Tracking #:	292224
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

33

BP-YBOR  
2040 E 14TH AVE  
TAMPA, FL 33605

UST  
LUST

U001355280  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BP-YBOR (Continued)

U001355280

### LUST:

Facility ID:	8627858	Facility Type:	RETAIL STATION
Alias Name:	BP-ROYAL		
Alias Name 2:	ROYAL STATION		
Telephone:	8136814279	Discovery Date:	11/30/88
Tracking Number:	294951	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

33



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BP-YBOR (Continued)

U001355280

### UST:

Facility ID:	298627858	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294951
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

33

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BP-YBOR (Continued)

U001355280

Facility ID:	298627858	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294951
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

33

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BP-YBOR (Continued)

U001355280

Facility ID:	298627858	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294951
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

33

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## BP-YBOR (Continued)

U001355280

Facility ID:	298627858	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294951
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

34

2411 N 40TH ST  
TAMPA, FL

HMIRS

92020530  
N/A

35

FINA-A ONE  
2501 N 22ND ST & I-4  
TAMPA, FL 33605

UST  
LUST

U001354938  
N/A

# MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

## FINA-A ONE (Continued)

U001354938

### LUST:

Facility ID:	8625735	Facility Type:	RETAIL STATION
Alias Name:	GAS KWICK		
Telephone:	8132474731	Discovery Date:	03/25/88
Tracking Number:	292828	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

35

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## FINA-A ONE (Continued)

U001354938

### UST:

Facility ID:	298625735	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	DONALD L BODIE, JR		
Owner:	AMERICAN PETRFINA MARKETING, INC.		
	P O BOX75285		
	TAMPA, FL 33675		
Owner's Phone:	8132485505	Tracking #:	292828
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	67/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Unprotec metal, Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

35

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## FINA-A ONE (Continued)

U001354938

Facility ID:	298625735	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	DONALD L BODIE, JR		
Owner:	AMERICAN PETRFINA MARKETING,INC.		
	P O BOX75285		
	TAMPA, FL 33675		
Owner's Phone:	8132485505	Tracking #:	292828
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	67/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Unprotec metal, Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FINA-A ONE (Continued)

U001354938

Facility ID:	298625735	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	DONALD L BODIE, JR		
Owner:	AMERICAN PETRFINA MARKETING,INC.		
	P O BOX75285		
	TAMPA, FL 33675		
Owner's Phone:	8132485505	Tracking #:	292828
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	67/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Unprotec metal, Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FINA-A ONE (Continued)

U001354938

Facility ID:	298625735	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	DONALD L BODIE, JR		
Owner:	AMERICAN PETRFINA MARKETING,INC. P O BOX75285 TAMPA, FL 33675		
Owner's Phone:	8132485505	Tracking #:	292828
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	67/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Unprotec metal, Cathod prot steel, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## FINA-A ONE (Continued)

U001354938

Facility ID:	298625735	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	DONALD L BODIE, JR		
Owner:	AMERICAN PETRFINA MARKETING, INC.		
	P O BOX75285		
	TAMPA, FL 33675		
Owner's Phone:	8132485505	Tracking #:	292828
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## FINA-A ONE (Continued)

U001354938

Facility ID:	298625735	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	DONALD L BODIE, JR		
Owner:	AMERICAN PETRFINA MARKETING,INC.		
	P O BOX75285		
	TAMPA, FL 33675		
Owner's Phone:	8132485505	Tracking #:	292828
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	67/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

36

AMOCO-ALAN DALE MARTS INC  
2207 E 13TH AVE  
TAMPA, FL 33605

UST  
LUST

U001354282  
N/A

36

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO-ALAN DALE MARTS INC (Continued)

U001354282

### LUST:

Facility ID:	8625038	Facility Type:	RETAIL STATION
Alias Name:	SHELL-ALAN DALE		
Telephone:	8132485975	Discovery Date:	06/06/90
Tracking Number:	Not reported	Score:	041
Facility Code:	Not reported	Status:	Not reported
Rank:	02362		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

32

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO-ALAN DALE MARTS INC (Continued)

U001354282

### UST:

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009403	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	4
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

36

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## AMOCO-ALAN DALE MARTS INC (Continued)

U001354282

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009403	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	5
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

36

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO-ALAN DALE MARTS INC (Continued)

U001354282

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009403	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	6
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

36

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO-ALAN DALE MARTS INC (Continued)

U001354282

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

36



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO-ALAN DALE MARTS INC (Continued)

U001354282

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	2	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

36

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## AMOCO-ALAN DALE MARTS INC (Continued)

U001354282

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	3	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

37

NCJ INVESTMENT CO  
2101 E 13TH AVE  
TAMPA, FL 33605

UST  
LUST

U001354017  
N/A

37

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

NCJ INVESTMENT CO (Continued)

U001354017

LUST:

Facility ID:	8624753	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	09/14/88
Tracking Number:	293907	Score:	035
Facility Code:	Not reported	Status:	Not reported
Rank:	03338		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## NCJ INVESTMENT CO (Continued)

U001354017

### UST:

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

37

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## NCJ INVESTMENT CO (Continued)

U001354017

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO	Facility Phone:	Not reported
Contact:	Not reported	Region:	STATE
Permit Section:	Not reported	Financial responsibility:	Not reported
Facility Code:	No violation	District:	Southwest
Date entered:	860505		
Tank ID:	2		
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

37

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## NCJ INVESTMENT CO (Continued)

U001354017

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

37

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## NCJ INVESTMENT CO (Continued)

U001354017

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO	Facility Phone:	Not reported
Contact:	Not reported	Region:	STATE
Permit Section:	Not reported	Financial responsibility:	Not reported
Facility Code:	No violation	District:	Southwest
Date entered:	860505		
Tank ID:	4		
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

37

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## NCJ INVESTMENT CO (Continued)

U001354017

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

37



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## NCJ INVESTMENT CO (Continued)

U001354017

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

38	OLD 97 COMPANY 2306 35TH ST TAMPA, FL 33605	FINDS	1000496908 FLD004091427
Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production			
38	REDI STRIP OF CENTRAL FLORIDA 2402 N 35TH ST TAMPA, FL 33605	RCRIS-SQG FINDS	1000245031 FLD021115837
39	U-HAUL OF CENTRAL TAMPA 2309 N 18TH ST TAMPA, FL 33605	UST	U001354819 N/A

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## U-HAUL OF CENTRAL TAMPA (Continued)

U001354819

### UST:

Facility ID:	298625612	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	U-HAUL		
Contact:	Not reported	Facility Phone:	8132475936
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES E. KITCHIN, JR		
Owner:	U HAUL CO OF WEST COAST FL		
	2311 N 18TH ST		
	TAMPA, FL 336053847		
Owner's Phone:	8132476101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	77/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	94/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

39

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## U-HAUL OF CENTRAL TAMPA (Continued)

U001354819

Facility ID:	298625612	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	U-HAUL		
Contact:	Not reported	Facility Phone:	8132475936
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	CHARLES E. KITCHIN, JR		
Owner:	U HAUL CO OF WEST COAST FL		
	2311 N 18TH ST		
	TAMPA, FL 336053847		
Owner's Phone:	8132476101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/11
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	94/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

39

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## U-HAUL OF CENTRAL TAMPA (Continued)

U001354819

Facility ID:	298625612	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	U-HAUL		
Contact:	Not reported	Facility Phone:	8132475936
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	CHARLES E. KITCHIN, JR		
Owner:	U HAUL CO OF WEST COAST FL		
	2311 N 18TH ST		
	TAMPA, FL 336053847		
Owner's Phone:	8132476101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000700	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	94/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	None		

40

## ROYAL BUMPER SERVICE 5607 E BROADWAY TAMPA, FL 33619

CERCLIS 1000147325  
FINDS FLD042475723  
RCRIS-LQG  
RCRIS-TSD  
RAATS

### CERCLIS Classification Data:

Site Incident Category: Not reported  
Ownership Status: UNKNOWN  
EPA Notes: REMOVAL ACTION SCHEDULED.

Federal Facility: NO  
NPL Status: NOT ON NPL

### CERCLIS Assessment History:

Assessment:	DISCOVERY	Completed:	04/21/1993
Assessment:	PRELIMINARY ASSESSMENT	Completed:	07/11/1994
Assessment:	REMOVAL ACTION	Completed:	03/17/1995
Assessment:	INTEGRATED ASSESSMENT	Completed:	Not reported
Assessment:	ADMINISTRATIVE RECORD	Completed:	09/21/1994
Assessment:	INTEGRATED ASSESSMENT	Completed:	03/03/1994

### CERCLIS Site Status:

This site is currently under investigation by the government to assess the extent of further action

### CERCLIS Alias Name(s):

ROYAL BUMPER PLANTING

46

# MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
<b>ROYAL BUMPER SERVICE (Continued)</b>						1000147325
There are 3 compliance/violation record(s) reported at this site:						
			Evaluation	Date	Violations	
			SAMPLING INSPECTION	24-SEP-87	YES	
			COMPLIANCE EVALUATION INSPECTION (CEI)	16-APR-87	YES	
			COMPLIANCE EVALUATION INSPECTION (CEI)	06-APR-87	YES	
41			WEYERHAEUSER CO. 2307 N 36TH ST TAMPA, FL 33605	UST LUST	U001354504 N/A	

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WEYERHAEUSER CO. (Continued)

U001354504

### LUST:

Facility ID:	8625274	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132476671	Discovery Date:	01/10/90
Tracking Number:	Not reported	Score:	009 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	08492		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WEYERHAEUSER CO. (Continued)

U001354504

### UST:

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO PO BOX 16909 TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrrnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WEYERHAEUSER CO. (Continued)

U001354504

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO PO BOX 16909 TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

41



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WEYERHAEUSER CO. (Continued)

U001354504

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO PO BOX 16909 TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WEYERHAEUSER CO. (Continued)

U001354504

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO PO BOX 16909 TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WEYERHAEUSER CO. (Continued)

U001354504

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO PO BOX 16909 TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

42

**BOCA AUTO RADIATOR INC**  
3801 E 11TH ST  
TAMPA, FL 33605

RCRIS-SQG  
FINDS

1000141660  
FLD982129835

RCRIS:

Owner: ROBERT BOEZI  
(813) 626-7474

Contact: ROBERT BOEZI  
(813) 626-7474

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D002	.00000 (T)	Notification	D008	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

43

**SUNNY FL DAIRY**  
2209 N 40TH ST  
TAMPA, FL 33675

UST  
LUST

U001355579  
N/A

43

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUNNY FL DAIRY (Continued)

U001355579

### LUST:

Facility ID:	8736297	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132483151	Discovery Date:	10/29/91
Tracking Number:	Not reported	Score:	026 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05033		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

43

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUNNY FL DAIRY (Continued)

U001355579

### UST:

Facility ID:	298736297	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SAL GUAGLIARRO		
Contact:	Not reported	Facility Phone:	8132483151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871119	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	SAL GUAGLIARRO		
Owner:	SUNNY FLORIDA DAIRY		
	2209 N 40TH ST		
	TAMPA, FL 33675		
Owner's Phone:	8132483151	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUNNY FL DAIRY (Continued)

U001355579

Facility ID:	298736297	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SAL GUAGLIARRO		
Contact:	Not reported	Facility Phone:	8132483151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871119	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	SAL GUAGLIARRO		
Owner:	SUNNY FLORIDA DAIRY 2209 N 40TH ST TAMPA, FL 33675		
Owner's Phone:	8132483151	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	79/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

44

**KAMALA AUTO TRADE**  
2211 N 38TH ST  
TAMPA, FL 33603

RCRIS-SQG 1000821508  
FINDS FLD984244780

RCRIS:

Owner: MIKE JERRORICH  
(813) 247-5811

Contact: MIKE JERRORICH  
(813) 247-5811

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D007	.00000 (T)	Notification	D008	.00000 (T)	Notification
D018	.00000 (T)	Notification	D021	.00000 (T)	Notification
D027	.00000 (T)	Notification	D039	.00000 (T)	Notification
D040	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

45

**BARBIE'S KWEEN KLEEN LAUNDROMAT & DRY**  
5030 10TH AVE E  
TAMPA, FL 33619

UST

U002313209  
N/A

45

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**BARBIE'S KWEEN KLEEN LAUNDROMAT & DRY (Continued)**

U002313209

UST:

Facility ID:	299500576	Facility Type:	3
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	8132471355
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870101	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	Not reported		
Owner:	GRABOWSKY BARBARA A 5030 10TH AVE E TAMPA, FL 33619		
Owner's Phone:	8136891996	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

46

TAMPA,CITY-FIRE STATION #4  
2100 E 11TH AVE  
TAMPA, FL 33605

UST  
LUST

U001355927  
N/A

46

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

TAMPA,CITY-FIRE STATION #4 (Continued)

U001355927

LUST:

Facility ID:	8842517	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132255729	Discovery Date:	03/20/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

46



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE STATION #4 (Continued)

U001355927

### UST:

Facility ID:	298842517	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881229	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

416

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE STATION #4 (Continued)

U001355927

Facility ID:	298842517	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881229	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

47

TAMPA,CITY-FIRE STATION #16  
5126 E 10TH AVE  
TAMPA, FL 33619

UST  
LUST

U001355920  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE STATION #16 (Continued)

U001355920

### LUST:

Facility ID:	8842510	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132255729	Discovery Date:	12/12/88
Tracking Number:	295184	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE STATION #16 (Continued)

U001355920

### UST:

Facility ID:	298842510	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	295184
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number

EPA ID Number

## TAMPA,CITY-FIRE STATION #16 (Continued)

U001355920

Facility ID:	298842510	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	295184
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

48

OUR LADY OF PERPETUAL HELP CHURCH  
1711 E 11TH AVE  
TAMPA, FL 33605

UST

U001355335  
N/A

48

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## OUR LADY OF PERPETUAL HELP CHURCH (Continued)

U001355335

### UST:

Facility ID:	298628192	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	OUR LADY OF PERPETUAL HELP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861110	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	FRANCES M. RHODES		
Owner:	OUR LADY OF PERPETUAL HELP		
	1711 E 11TH AVE		
	TAMPA, FL 336053803		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	84/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

49

**HELENA CHEMICAL CO. (TAMPA PLANT)**  
2405 N 71TH ST  
TAMPA, FL 33675

**CERCLIS** 1000207090  
**RCRIS-SQG** FLD053502696  
**FINDS**  
**NPL**

### CERCLIS Classification Data:

Site Incident Category:	Not reported	Federal Facility:	NO
Ownership Status:	OTHER	NPL Status:	CURRENTLY ON THE FINAL NPL
EPA Notes:	Not reported		

### CERCLIS Assessment History:

Assessment:	DISCOVERY	Completed:	08/01/1980
Assessment:	PRELIMINARY ASSESSMENT	Completed:	08/01/1982
Assessment:	SCREENING SITE INSPECTION	Completed:	10/22/1990
Assessment:	LISTING SITE INSPECTION	Completed:	11/08/1991
Assessment:	HAZARD RANKING DETERMINED	Completed:	07/10/1991
Assessment:	PROPOSAL TO NPL	Completed:	02/07/1992
Assessment:	FINAL LISTING ON NPL	Completed:	10/14/1992
Assessment:	RMVL INVESTIGATION AT NPL	Completed:	12/31/1992
Assessment:	COMBINED RI/FS	Completed:	Not reported
Assessment:	REMEDIAL COMMUNITY RELATIONS	Completed:	Not reported
Assessment:	RECORD OF DECISION	Completed:	Not reported
Assessment:	ADMINISTRATIVE RECORD	Completed:	Not reported
Assessment:	COMBINED RI/FS	Completed:	Not reported

### CERCLIS Site Status:

This site is currently under investigation by the government to assess the extent of further action

### CERCLIS Alias Name(s):

HELENA CHEMICAL COMPANY

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HELENA CHEMICAL CO. (TAMPA PLANT) (Continued)

1000207090

### NPL:

ID: Not reported  
EPA/ID: FLD053502696  
Haz. Rank Score: Not reported  
Status: Not reported  
Rank: Not reported  
Group: Not reported  
Ownership: Not reported  
Permit: Not reported  
Site Activities: Not reported  
Site Condition: Not reported  
Waste Type: Not reported  
Contaminants: Not reported  
Distance to nearest Population: Not reported  
Population within a 1 Mile Radius: Not reported  
Population within a 2 Mile Radius: Not reported  
Population within a 4 Mile Radius: Not reported  
Vertical Distance to Aquifer: Not reported  
Ground Water Use: Used as Drinking Water, Alternative Source not Available  
Distance to nearest Surface Water: Not reported

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

49 ALARIC, INC. (CONCRETE EQUIP & SUPPLY)  
2110 N 71ST STREET  
TAMPA, FL

SHWS

S101547646  
N/A

50 STEELTECH ELECTROPAINTING INC  
4302 E 10TH AVE #402  
TAMPA, FL 33680

RCRIS-SQG  
FINDS

1000205470  
FLD982129959

### RCRIS:

Owner: ALEC TORRENS, OFFICE MGR  
(813) 626-9389

Contact:ALEC TORRENS  
(813) 626-9389

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F003	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

51 GULF COAST LEAD CO  
1901 NORTH 66TH ST  
TAMPA, FL 33619

CERCLIS  
FINDS  
RCRIS-LQG  
TRIS  
RCRIS-TSD  
CORRACTS  
UST  
AST

1000226742  
FLD004092839

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GULF COAST LEAD CO (Continued)

1000226742

### CERCLIS Classification Data:

Site Incident Category: Not reported  
Ownership Status: OTHER  
EPA Notes: Not reported

Federal Facility: NO  
NPL Status: NOT ON NPL

### CERCLIS Assessment History:

Assessment: DISCOVERY Completed: 03/01/1979  
Assessment: PRELIMINARY ASSESSMENT Completed: 07/01/1979  
Assessment: SCREENING SITE INSPECTION Completed: 01/01/1980

### CERCLIS Site Status:

This site is currently under investigation by the government to assess the extent of further action

### CERCLIS Alias Name(s):

GULF COAST LEAD CO  
GULF COAST RECYCLING, INC

### CORRACTS Data:

Prioritization: High  
Status: RCRA Facility Investigation Completed, CMS Report Received

### RCRIS:

Owner: JOYCE MORALES-CARAMELLA  
(813) 626-6151

Contact: JOYCE MORALES-CARAMEL  
(813) 626-6151

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (N)	State Inspection	D008	.00000 (N)	State Inspection
D001	.00000 (N)	Part A	D008	.00000 (N)	Part A

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

There are 10 compliance/violation record(s) reported at this site:

Evaluation	Date	Violations
COMPLIANCE EVALUATION INSPECTION (CEI)	18-MAY-95	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	25-FEB-93	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	16-NOV-92	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	22-SEP-92	YES
FINANCIAL RECORD REVIEW (FRR)	22-JUN-92	YES
FINANCIAL RECORD REVIEW (FRR)	15-MAY-92	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	26-JUN-91	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	26-JUN-91	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	14-SEP-89	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	09-JUN-80	YES

### Other Pertinent Environmental Activity Identified at Site:

facility has an emission permit under the Clean Air Act  
civil judicial and administrative enforcement cases against facility



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GULF COAST LEAD CO (Continued)

1000226742

### UST:

Facility ID:	298733856	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GULF COAST RECYCLING INC		
Contact:	Not reported	Facility Phone:	8132626151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	17	District:	Southwest
Owner's Contact:	WILLIS M KITCHEN		
Owner:	GULF COAST LEAD CO INC		
	1901 NN 66TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8132626151	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	65/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

### AST:

Facility ID:	298733856	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GULF COAST RECYCLING INC		
Facility Phone:	8132626151	Permit Section:	Not reported
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLIS M KITCHEN		
Owner:	GULF COAST LEAD CO INC		
	1901 NN 66TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8132626151	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000550
Tank Content:	Unleaded gas	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GULF COAST LEAD CO (Continued)

1000226742

Facility ID:	298733856	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GULF COAST RECYCLING INC		
Facility Phone:	8132626151	Permit Section:	Not reported
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLIS M KITCHEN		
Owner:	GULF COAST LEAD CO INC		
	1901 NN 66TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8132626151	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000200
Tank Content:	New/lube oil	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298733856	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GULF COAST RECYCLING INC		
Facility Phone:	8132626151	Permit Section:	Not reported
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLIS M KITCHEN		
Owner:	GULF COAST LEAD CO INC		
	1901 NN 66TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8132626151	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000200
Tank Content:	New/lube oil	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GULF COAST LEAD CO (Continued)

1000226742

Facility ID:	298733856	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GULF COAST RECYCLING INC		
Facility Phone:	8132626151	Permit Section:	Not reported
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	WILLIS M KITCHEN		
Owner:	GULF COAST LEAD CO INC		
	1901 NN 66TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8132626151	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000150
Tank Content:	New/lube oil	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298733856	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GULF COAST RECYCLING INC		
Facility Phone:	8132626151	Permit Section:	Not reported
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	WILLIS M KITCHEN		
Owner:	GULF COAST LEAD CO INC		
	1901 NN 66TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8132626151	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00003500
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	74/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GULF COAST LEAD CO (Continued)

1000226742

Facility ID:	298733856	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GULF COAST RECYCLING INC		
Facility Phone:	8132626151	Permit Section:	Not reported
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	WILLIS M KITCHEN		
Owner:	GULF COAST LEAD CO INC		
	1901 NN 66TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8132626151	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00003500
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	74/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

Facility ID:	298733856	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GULF COAST RECYCLING INC		
Facility Phone:	8132626151	Permit Section:	Not reported
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	WILLIS M KITCHEN		
Owner:	GULF COAST LEAD CO INC		
	1901 NN 66TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8132626151	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Mineral acid	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/02
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Spill cnmt		
Tank Piping:	Abvgrnd-no contact w/soil, Secondary containment, Suction piping, Pressurized piping		
Petro. Monitoring:	GW mon plan, Man tank gauging, GW monitoring		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GULF COAST LEAD CO (Continued)

1000226742

Facility ID:	298733856	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GULF COAST RECYCLING INC		
Facility Phone:	8132626151	Permit Section:	Not reported
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	WILLIS M KITCHEN		
Owner:	GULF COAST LEAD CO INC		
	1901 NN 66TH ST		
	TAMPA, FL 33619		
Owner's Phone:	8132626151	Tracking #:	Not reported
Drink, Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Mineral acid	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/02
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Spill cnmt		
Tank Piping:	Abvgrnd-no contact w/soil, Secondary containment, Suction piping, Pressurized piping		
Petro. Monitoring:	GW mon plan, Man tank gauging, GW monitoring		

52

GORDON PROPERTY  
1009 13TH ST  
TAMPA, FL

UST  
LUST

U002113438  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GORDON PROPERTY (Continued)

U002113438

### LUST:

Facility ID:	9501598	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8139204487	Discovery Date:	02/27/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

52

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GORDON PROPERTY (Continued)

U002113438

### UST:

Facility ID:	299501598	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BOB GORDON		
Contact:	Not reported	Facility Phone:	8139204487
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	950323	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	BOB GORDON		
Owner:	GORDON, BOB & LYNN		
	17912 CROWLEY RD		
	ODESSA, FL 33556		
Owner's Phone:	8139204487	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	No
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

53

TAMPA INDEPENDENT DAIRY  
3725 E 10TH AVE  
TAMPA, FL 33605

UST  
LUST

U001354964  
N/A

53

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

### LUST:

Facility ID:	8625761	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132231999	Discovery Date:	08/15/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

53



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

### UST:

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Abvgrnd-no contact w/soil, Cathod prot steel, Dbiwall=primary		
	matl		
Petro. Monitoring:	Man sample wells		

43

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Abvgnd-no contact w/soil, Cathod prot steel, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Dbiwall=primary matl		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	5R1
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	5R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink, Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	5	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS		
	PO BOX 75306		
	TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

54

## TARGET AUTO & TRUCK SERVICE 2104 34TH ST N TAMPA, FL 33605

RCRIS-SQG 1000821269  
FINDS FLD984241885

### RCRIS:

Owner: JOHN CORRICA  
(813) 248-5145

Contact: JOHN CORRICA  
(813) 248-5145

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D007	.00000 (T)	Notification	D008	.00000 (T)	Notification
D021	.00000 (T)	Notification	D027	.00000 (T)	Notification
D039	.00000 (T)	Notification	D040	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

55

## TAMPA ELECTRO PLATING INC 3005 E 10TH AVE TAMPA, FL 33605

RCRIS-SQG 1000344862  
FINDS FLD982117871

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
56	<b>PLAZA FOOD MART</b> <b>5006 E BROADWAY AVE</b> <b>TAMPA, FL 33619</b>	UST	U001355820 N/A
	UST: Facility ID: 298840566 Is fac. regulated: Regulated facility Operator: LINDA LAWRENCE Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 880517 Tank ID: 1 Owner's Contact: MARY E LAWRENCE Owner: LAWRENCE, MARY E & C COURTNEY 5012 E BROADWAY AVE TAMPA, FL 336192702 Owner's Phone: 8132473665 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00010000 Tank position: Underground Tank Content: Leaded gas Disposal Method: In service Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Eligibility: Not reported Permit Number: Not reported Class: Not reported Category: Not reported Tank Constr.: Overfill-ball check, Fiberglass Tank Piping: Fiberglass Petro. Monitoring: Man sample wells, Piping/flow restrictor, Man tank gauging	Facility Type: Retail Station Is facility open: Open Facility Phone: 8132471787 Region: STATE Financial responsibility: None District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: 90/06 Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported Eligible Date: Not reported	

56

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PLAZA FOOD MART (Continued)

U001355820

Facility ID:	298840566	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LINDA LAWRENCE		
Contact:	Not reported	Facility Phone:	8132471787
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880517	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	MARY E LAWRENCE		
Owner:	LAWRENCE, MARY E & C COURTNEY		
	5012 E BROADWAY AVE		
	TAMPA, FL 336192702		
Owner's Phone:	8132473665	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

56

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PLAZA FOOD MART (Continued)

U001355820

Facility ID:	298840566	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LINDA LAWRENCE		
Contact:	Not reported	Facility Phone:	8132471787
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880517	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	MARY E LAWRENCE		
Owner:	LAWRENCE, MARY E & C COURTNEY		
	5012 E BROADWAY AVE		
	TAMPA, FL 336192702		
Owner's Phone:	8132473665	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

56

KIRK NATIONALEASE  
5013 E BROADWAY  
TAMPA, FL 33619

RCRIS-SQG 1000699717  
UST FLD981745656  
LUST

RCRIS:

Owner: JAMES MCCULLOUGH, BRANCH MGR  
(813) 247-3534

Contact: JIM MCCULLOUGH  
(813) 247-3534

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

KIRK NATIONALEASE (Continued)

1000699717

LUST:

Facility ID:	8625436	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132473534	Discovery Date:	06/18/90
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE

56



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## KIRK NATIONALEASE (Continued)

1000699717

### UST:

Facility ID:	298625436	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KIRK NATIONAL LEASE		
Contact:	Not reported	Facility Phone:	8132473534
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM MCCOLOUGH		
Owner:	PUMPCO, INC.		
	P O BOX 75065		
	TAMPA, FL 33875		
Owner's Phone:	8132484600	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

56	KIRK NATIONALEASE 5013 E BROADWAY TAMPA, FL 33619	FINDS	1000734362 FLD981745656
57	MASSEY METALS CO 2009 N 22ND ST TAMPA, FL 33605	UST	U001354553 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MASSEY METALS CO (Continued)

U001354553

### UST:

Facility ID:	298625331	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MASSEY METALS CO		
Contact:	Not reported	Facility Phone:	8132482117
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM MASSEY		
Owner:	MASSEY METALS CO		
	PO BOX 75560		
	TAMPA, FL 336750560		
Owner's Phone:	8132482117	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001600	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

58

## AIR BRAKE CONTROLS 2001 N 40TH ST TAMPA, FL 33605

FINDS

1000497139  
FLD032760027

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act

59

## FLORIDA INK MFG COMPANY INC 1715 TEMPLE ST TAMPA, FL 33619

RCRIS-SQG  
FINDS

1000361408  
FLD982083446

### RCRIS:

Owner: NESSMITH JOHN S MGR  
(813) 247-2911

Contact: NESSMITH JOHN  
(813) 247-2911

Waste	Quantity	Info Source	Waste	Quantity	Info Source
F003	.00000 (T)	Notification	K002	.00000 (T)	Notification
K003	.00000 (T)	Notification	K086	.00000 (T)	Notification
U021	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MIAMI TRANSFER CO INC (Continued)

U001354917

### UST:

Facility ID:	298625713	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MIAMI TRANSFER CO INC		
Contact:	Not reported	Facility Phone:	8132475621
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MEL PARKER		
Owner:	MIAMI TRANSFER CO INC		
	5117 E 8TH AVE		
	TAMPA, FL 336193100		
Owner's Phone:	8132475621	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotect metal		
Petro. Monitoring:	Man sample wells		

60

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MIAMI TRANSFER CO INC (Continued)

U001354917

Facility ID:	298625713	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MIAMI TRANSFER CO INC		
Contact:	Not reported	Facility Phone:	8132475621
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MEL PARKER		
Owner:	MIAMI TRANSFER CO INC		
	5117 E 8TH AVE		
	TAMPA, FL 336193100		
Owner's Phone:	8132475621	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MIAMI TRANSFER CO INC (Continued)

U001354917

Facility ID:	298625713	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MIAMI TRANSFER CO INC		
Contact:	Not reported	Facility Phone:	8132475621
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MEL PARKER		
Owner:	MIAMI TRANSFER CO INC		
	5117 E 8TH AVE		
	TAMPA, FL 336193100		
Owner's Phone:	8132475621	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	None		

60

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## MIAMI TRANSFER CO INC (Continued)

U001354917

Facility ID:	298625713	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MIAMI TRANSFER CO INC		
Contact:	Not reported	Facility Phone:	8132475621
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MEL PARKER		
Owner:	MIAMI TRANSFER CO INC		
	5117 E 8TH AVE		
	TAMPA, FL 336193100		
Owner's Phone:	8132475621	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	None		

61

22ND ST & 8TH AVE  
TAMPA, FL

HMIRS

90040372  
N/A

62

HILLSBOROUGH CNTY SHERIFFS OFFICE  
2102 E 8TH AVE  
TAMPA, FL 33605

UST  
LUST

U001355273  
N/A

62

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

HILLSBOROUGH CNTY SHERIFFS OFFICE (Continued)

U001355273

LUST:

Facility ID:	8627827	Facility Type:	COUNTY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132478094	Discovery Date:	09/08/88
Tracking Number:	299000	Score:	034
Facility Code:	Not reported	Status:	Not reported
Rank:	03633		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	00000100
------------	--------------	--------------------	----------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

62



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY SHERIFFS OFFICE (Continued)

U001355273

### UST:

Facility ID:	298627827	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HILLSBOROUGH CNTY SHERIFFS OFC		
Contact:	Not reported	Facility Phone:	8132478094
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT		
	PO BOX 3371		
	TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	299000
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

62

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY SHERIFFS OFFICE (Continued)

U001355273

Facility ID:	298627827	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HILLSBOROUGH CNTY SHERIFFS OFC		
Contact:	Not reported	Facility Phone:	8132478094
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	299000
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

62

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY SHERIFFS OFFICE (Continued)

U001355273

Facility ID:	298627827	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HILLSBOROUGH CNTY SHERIFFS OFC		
Contact:	Not reported	Facility Phone:	8132478094
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	299000
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/01
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

62

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY SHERIFFS OFFICE (Continued)

U001355273

Facility ID:	298627827	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HILLSBOROUGH CNTY SHERIFFS OFC		
Contact:	Not reported	Facility Phone:	8132478094
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT		
	PO BOX 3371		
	TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	299000
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/01
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

62

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

HILLSBOROUGH CNTY SHERIFFS OFFICE (Continued)

U001355273

Facility ID:	298627827	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HILLSBOROUGH CNTY SHERIFFS OFC		
Contact:	Not reported	Facility Phone:	8132478094
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	299000
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	77/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Not required		

63 PARTSCO AUTOMOTIVE SUPPLY INC.  
1905 40TH ST.  
TAMPA, FL 33605

RCRIS-SQG 1000420907  
FINDS FLD982173957

64 HILLSBOROUGH CNTY-SHERIFFS OFFICE  
2008 E 8TH AVE  
TAMPA, FL 33605

UST U001356050  
LUST N/A  
AST

64

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-SHERIFFS OFFICE (Continued)

U001356050

### LUST:

Facility ID:	8944870	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132482827	Discovery Date:	07/24/89
Tracking Number:	Not reported	Score:	034
Facility Code:	Not reported	Status:	Not reported
Rank:	03633		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

COMBINED C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: FUEL OIL-ON SITE

Est. Gallons Lost: 00001700

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

PETRO. LIABILITY INS. & RESTOR.

REIMBURSEMENT CLEANUP

INELIGIBLE

NONCOMP 17-61, -761, -762 RULES

NONCOMP 17-61,

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product: Y

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: RESPONSIBLE PARTY

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

INCOMPLETE

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

64

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-SHERIFFS OFFICE (Continued)

U001356050

### UST:

Facility ID:	298944870	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DALE TUTTLE		
Contact:	Not reported	Facility Phone:	8132482827
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890922	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/10
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

### AST:

Facility ID:	298944870	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DALE TUTTLE		
Facility Phone:	8132482827	Permit Section:	Not reported
Date entered:	890922	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	93/09
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Dbl walled=primary matl, Spill cnmt, Op-tight fill, Level gauges/hi level alarms		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Suction piping		
Petro. Monitoring:	DW tank space		

64

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
65	<b>GTE OF FL YBOR EAX</b> <b>1702 E 8TH AVE</b> <b>TAMPA, FL 33605</b>	UST	<b>U001355274</b> <b>N/A</b>
	UST: Facility ID: 298627832 Is fac. regulated: Regulated facility Operator: VANN, KAREN Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 861106 Tank ID: 1 Owner's Contact: BARBARA E WILLIAMS Owner: GENERAL TELEPHONE CO OF FL PO BOX 110 MC 711 TAMPA, FL 336010110 Owner's Phone: 8132244740 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00002000 Tank position: Underground Tank Content: Diesel-emerg generator Disposal Method: In service Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Eligibility: Not reported Permit Number: Not reported Class: Not reported Category: Not reported Tank Constr.: Fiberglass Tank Piping: Unprotec metal Petro. Monitoring: Not required	Facility Type: Non-retail Business Is facility open: Open Facility Phone: 8132244721 Region: STATE Financial responsibility: Oth Apprvd Coverage District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: 80/XX Content Category: Pollutant Last used Date: Not reported RPT by Tank #: Not reported Eligible Date: Not reported	

65



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GTE OF FL YBOR EAX (Continued)

U001355274

Facility ID:	298627832	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	VANN, KAREN		
Contact:	Not reported	Facility Phone:	8132244721
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	87/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

66

**SUPERIOR FERTILIZER & CHEMICAL CO**  
4701 EAST BROADWAY  
TAMPA, FL 33605

RCRIS-SQG  
FINDS

1000215537  
FLD004090684

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

67

**AMOCO 7TH AVE GROCERY**  
901 E 7TH AVE  
TAMPA, FL 33605

UST  
LUST

U001354025  
N/A

67

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO 7TH AVE GROCERY (Continued)

U001354025

### LUST:

Facility ID:	8624761	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132474731	Discovery Date:	09/11/88
Tracking Number:	293767	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN	Est. Gallons Lost:	UNKNOWN
------------	---------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

67

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO 7TH AVE GROCERY (Continued)

U001354025

### UST:

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	1R1
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO 7TH AVE GROCERY (Continued)

U001354025

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

67

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO 7TH AVE GROCERY (Continued)

U001354025

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

67

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO 7TH AVE GROCERY (Continued)

U001354025

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Compartmented, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO 7TH AVE GROCERY (Continued)

U001354025

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

67

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO 7TH AVE GROCERY (Continued)

U001354025

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

67



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AMOCO 7TH AVE GROCERY (Continued)

U001354025

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

67

STAR #1229  
1802 N NEBRASKA AVE  
TAMPA, FL 33602

UST  
LUST

U001354863  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

STAR #1229 (Continued)

U001354863

## LUST:

Facility ID:	8625656	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132240749	Discovery Date:	03/18/91
Tracking Number:	Not reported	Score:	035
Facility Code:	Not reported	Status:	Not reported
Rank:	03338		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN

## INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		TANK REMOVAL

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

67

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

STAR #1229 (Continued)

U001354863

UST:

Facility ID:	298625656	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STAR SERVICE		
Contact:	Not reported	Facility Phone:	8132240749
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	S. J. BRADSHAW, JR.		
Owner:	KNOPF, DOROTHY & WILLIAM I		
	6744 NEOSHO ST		
	SAINT LOUIS, MO 631093035		
Owner's Phone:	3149975990	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

STAR #1229 (Continued)

U001354863

Facility ID:	298625656	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STAR SERVICE		
Contact:	Not reported	Facility Phone:	8132240749
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	S. J. BRADSHAW, JR.		
Owner:	KNOPF, DOROTHY & WILLIAM I		
	6744 NEOSHO ST		
	SAINT LOUIS, MO 631093035		
Owner's Phone:	3149975990	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

67

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## STAR #1229 (Continued)

U001354863

Facility ID:	298625656	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STAR SERVICE		
Contact:	Not reported	Facility Phone:	8132240749
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	S. J. BRADSHAW, JR.		
Owner:	KNOPF, DOROTHY & WILLIAM I		
	6744 NEOSHO ST		
	SAINT LOUIS, MO 631093035		
Owner's Phone:	3149975990	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

68

EL ENCANTO CLEANERS INC  
1818 15TH ST  
TAMPA, FL 33605

UST

U002313189  
N/A

68

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EL ENCANTO CLEANERS INC (Continued)

U002313189

UST:

Facility ID:	299500225	Facility Type:	1
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	HARRY MORADIELLOS		
Contact:	Not reported	Facility Phone:	8132483979
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860701	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	H ORADIELLOS		
Owner:	MORADIELLOS, HARRY		
	1717 ERNA DR		
	TAMPA, FL 33603		
Owner's Phone:	8132483979	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

68 EL ENCANTO CLEANERS  
1818 15TH ST  
TAMPA, FL 33605

RCRIS-SQG  
FINDS 1000207263  
FLD089649693

69 KASH N KARRY FOOD STORES  
1811 N 22ND ST  
TAMPA, FL 33605

UST U001356131  
N/A

69

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N KARRY FOOD STORES (Continued)

U001356131

### UST:

Facility ID:	299046104	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N KARRY FOOD STORES INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARK STEWART		
Owner:	KASH N KARRY FOOD STORES INC		
	6422 HARNEY RD		
	TAMPA, FL 33680		
Owner's Phone:	8136210297	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N KARRY FOOD STORES (Continued)

U001356131

Facility ID:	299046104	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N KARRY FOOD STORES INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MARK STEWART		
Owner:	KASH N KARRY FOOD STORES INC		
	6422 HARNEY RD		
	TAMPA, FL 33680		
Owner's Phone:	8136210297	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

69



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KASH N KARRY FOOD STORES (Continued)

U001356131

Facility ID:	299046104	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N KARRY FOOD STORES INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MARK STEWART		
Owner:	KASH N KARRY FOOD STORES INC		
	6422 HARNEY RD		
	TAMPA, FL 33680		
Owner's Phone:	8136210297	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

70

TRACKS  
1430 E 7TH AVE  
TAMPA, FL 33605

UST  
LUST

U001356280  
N/A

70

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TRACKS (Continued)

U001356280

### LUST:

Facility ID:	9101102	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132474731	Discovery Date:	03/25/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

70

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TRACKS (Continued)

U001356280

### UST:

Facility ID:	299101102	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BROADWAY DEVELOPMENT INC		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910325	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS		
Owner:	BRAODWAY DEVELOPMENT INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

71

MACALUSO & MACALUSO  
2915 E 7TH AVE  
TAMPA, FL 33605

UST  
LUST

U001356231  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MACALUSO & MACALUSO (Continued)

U001356231

### LUST:

Facility ID:	9100495	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132381429	Discovery Date:	02/01/91
Tracking Number:	Not reported	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06571		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MACALUSO & MACALUSO (Continued)

U001356231

### UST:

Facility ID:	299100495	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MACALUSO, LENA		
Contact:	Not reported	Facility Phone:	8132381429
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910222	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LENA MACALUSO		
Owner:	MACALUSO, LENA		
	4810 N SHIRLEY DR		
	TAMPA, FL 336031724		
Owner's Phone:	8132381429	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MACALUSO & MACALUSO (Continued)

U001356231

Facility ID:	299100495	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MACALUSO, LENA		
Contact:	Not reported	Facility Phone:	8132381429
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910222	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	LENA MACALUSO		
Owner:	MACALUSO, LENA 4810 N SHIRLEY DR TAMPA, FL 336031724		
Owner's Phone:	8132381429	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

71

ANTHONY DISTRIBUTORS, INC.  
2900 E 7TH AVE  
TAMPA, FL 33605

UST  
LUST

U001354664  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

ANTHONY DISTRIBUTORS, INC. (Continued)

U001354664

LUST:

Facility ID:	8625445	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132474000	Discovery Date:	09/15/93
Tracking Number:	292469	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

Not reported

Incident 17-770 Cleanup:

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:

RESPONSIBLE PARTY-NO CLAIM

Incident Program Type:

Not reported

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: RESPONSIBLE PARTY

Soil Removal: Y

Alt. Process Date: Not reported

Soil Treatment: Y

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

APPROVED

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Region:

STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANTHONY DISTRIBUTORS, INC. (Continued)

U001354664

### UST:

Facility ID:	298625445	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	ANTHONY DISTRIBUTORS, INC.		
Contact:	Not reported	Facility Phone:	8132474000
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE SANDS		
Owner:	ANTHONY DISTRIBUTORS INC		
	2900 EAST 7TH AVE		
	TAMPA, FL 33605		
Owner's Phone:	8132297191	Tracking #:	292469
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANTHONY DISTRIBUTORS, INC. (Continued)

U001354664

Facility ID:	298625445	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	ANTHONY DISTRIBUTORS, INC.		
Contact:	Not reported	Facility Phone:	8132474000
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE SANDS		
Owner:	ANTHONY DISTRIBUTORS INC		
	2900 EAST 7TH AVE		
	TAMPA, FL 33605		
Owner's Phone:	8132297191	Tracking #:	292469
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

ANTHONY DISTRIBUTORS, INC. (Continued)

U001354664

Facility ID:	298625445	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	ANTHONY DISTRIBUTORS, INC.		
Contact:	Not reported	Facility Phone:	8132474000
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	GEORGE SANDS		
Owner:	ANTHONY DISTRIBUTORS INC 2900 EAST 7TH AVE TAMPA, FL 33605		
Owner's Phone:	8132297191	Tracking #:	292469
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

72

CHAMPION FLEET SERVICE INC  
3313 E 7TH AVE  
TAMPA, FL 33605

RCRIS-SQG 1000501844  
FINDS FLD984219865

RCRIS:

Owner: JIM CHAMPION  
(813) 247-3971

Contact: JIM CHAMPION  
(813) 247-3971

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D008	.00000 (T)	Notification
D018	.00000 (T)	Notification	D039	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

72

CHAMPION FLEET SERVICE  
3304 E 7TH AVE  
TAMPA, FL 33605

UST  
LUST

U001355348  
N/A

72

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHAMPION FLEET SERVICE (Continued)

U001355348

### LUST:

Facility ID:	8628880	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132475964	Discovery Date:	12/04/89
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	KEROSENE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

72

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHAMPION FLEET SERVICE (Continued)

U001355348

### UST:

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPION JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHAMPION FLEET SERVICE (Continued)

U001355348

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPON JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHAMPION FLEET SERVICE (Continued)

U001355348

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPON JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHAMPION FLEET SERVICE (Continued)

U001355348

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPON JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

72

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHAMPION FLEET SERVICE (Continued)

U001355348

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPON JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

72



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHAMPION FLEET SERVICE (Continued)

U001355348

Facility ID:	298628880	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CHAMPION JAMES E		
Contact:	Not reported	Facility Phone:	8132475964
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JAMES E CHAMPION		
Owner:	CHAMPON JAMES E		
	3304 E 7TH AVE		
	TAMPA, FL 336054304		
Owner's Phone:	8132475964	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

73

**RALSTON PURINA**  
3615 E 7TH AVE  
TAMPA, FL 33605

FINDS

1000496906  
FLD004090742

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act

74

**AGLIANO FISH MARKET**  
1821 E 7TH AVE  
TAMPA, FL 33605

UST

U001823415  
N/A

74

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AGLIANO FISH MARKET (Continued)

U001823415

### UST:

Facility ID:	299400582	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEBASTIAN AGLIANO		
Contact:	Not reported	Facility Phone:	8132482187
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940407	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

75

FL ROOFING & METAL  
2015 E 7TH AVE  
TAMPA, FL 33605

UST  
LUST

U001355786  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL ROOFING & METAL (Continued)

U001355786

### LUST:

Facility ID:	8839275	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	12/01/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS

Pollutant 2: KEROSENE

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

RESPONSIBLE PARTY-NO CLAIM

Not reported

Not reported

Not Reported

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

INCOMPLETE

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

15

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL ROOFING & METAL (Continued)

U001355786

### UST:

Facility ID:	298839275	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL ROOFING & METAL		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880219	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

76

AMERICAN FLEET SVC  
2326 E 7TH AV  
TAMPA, FL 33675

RCRIS-SQG  
FINDS

1000359166  
FLD982138885

### RCRIS:

Owner: RICK FAULKENBERG  
(813) 248-6510

Contact: RICK FAULKENBERG  
(813) 248-6510

Waste	Quantity	Info Source
D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

76

GARCIA'S INSTANT SERVICE  
2323 E 7TH AVE  
TAMPA, FL 33605

UST  
LUST

U001354646  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**GARCIA'S INSTANT SERVICE (Continued)**

U001354646

**LUST:**

Facility ID:	8625427	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8139337851	Discovery Date:	03/18/91
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

**INCIDENT GENERAL INFORMATION -**

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

**INCIDENT POLLUTANT INFORMATION -**

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

**INCIDENT PROGRAM INFORMATION -**

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

**INCIDENT INITIAL REMEDIAL ACTION INFORMATION -**

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

**INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -**

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

**INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -**

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	OTHER

**INCIDENT REMEDIAL ACTION REPORT INFORMATION -**

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

**INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -**

Site Rehab. Completion Action:	Not reported
Region:	STATE

76

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARCIA'S INSTANT SERVICE (Continued)

U001354646

### UST:

Facility ID:	298625427	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KEY BANK OF FL		
Contact:	Not reported	Facility Phone:	8139337851
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOSIE C KINNEY		
Owner:	KEY BANK OF FLORIDA		
	PO BOX 151317		
	TAMPA, FL 336841317		
Owner's Phone:	8139337851	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	62/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

76

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARCIA'S INSTANT SERVICE (Continued)

U001354646

Facility ID:	298625427	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KEY BANK OF FL		
Contact:	Not reported	Facility Phone:	8139337851
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOSIE C KINNEY		
Owner:	KEY BANK OF FLORIDA		
	PO BOX 151317		
	TAMPA, FL 336841317		
Owner's Phone:	8139337851	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	62/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

76

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARCIA'S INSTANT SERVICE (Continued)

U001354646

Facility ID:	298625427	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KEY BANK OF FL		
Contact:	Not reported	Facility Phone:	8139337851
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOSIE C KINNEY		
Owner:	KEY BANK OF FLORIDA PO BOX 151317 TAMPA, FL 336841317		
Owner's Phone:	8139337851	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	62/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

77

P D T TRUCKING  
2005 N 43RD ST  
TAMPA, FL 33601

AST

A100009081  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## P D T TRUCKING (Continued)

A100009081

### AST:

Facility ID:	299300639	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	P D T TRUCKING		
Facility Phone:	8134422688	Permit Section:	Not reported
Date entered:	930824	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	GERALD LANCASTER		
Owner:	LANCASTER OIL CO OF PINELLAS INC		
	2950 HEATHER TRL		
	CLEARWATER, FL 34623		
Owner's Phone:	8133274661	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	93/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, appv alt overfill, appv alt containment, Small use tank		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Corrosion resis coated		
Petro. Monitoring:	Aprvd alt sys		

77

PRODUCTS FOR INDUSTRY INC  
4318 E BROADWAY AVE  
TAMPA, FL 33605

UST  
LUST

U001356207  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PRODUCTS FOR INDUSTRY INC (Continued)

U001356207

### LUST:

Facility ID:	9100230	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132475977	Discovery Date:	10/24/90
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PRODUCTS FOR INDUSTRY INC (Continued)

U001356207

### UST:

Facility ID:	299100230	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WOLFE JOHN MCRAE		
Contact:	Not reported	Facility Phone:	8132475977
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910208	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN MCRAE WOLFE		
Owner:	WOLFE JOHN MCRAE		
	4318 E BROADWAY AVE		
	TAMPA, FL 336054606		
Owner's Phone:	8132475977	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PRODUCTS FOR INDUSTRY INC (Continued)

U001356207

Facility ID:	299100230	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WOLFE JOHN MCRAE		
Contact:	Not reported	Facility Phone:	8132475977
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910208	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN MCRAE WOLFE		
Owner:	WOLFE JOHN MCRAE 4318 E BROADWAY AVE TAMPA, FL 336054606		
Owner's Phone:	8132475977	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PRODUCTS FOR INDUSTRY INC (Continued)

U001356207

Facility ID:	299100230	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WOLFE JOHN MCRAE		
Contact:	Not reported	Facility Phone:	8132475977
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910208	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN MCRAE WOLFE		
Owner:	WOLFE JOHN MCRAE 4318 E BROADWAY AVE TAMPA, FL 336054606		
Owner's Phone:	8132475977	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PRODUCTS FOR INDUSTRY INC (Continued)

U001356207

Facility ID:	299100230	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WOLFE JOHN MCRAE		
Contact:	Not reported	Facility Phone:	8132475977
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910208	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN MCRAE WOLFE		
Owner:	WOLFE JOHN MCRAE		
	4318 E BROADWAY AVE		
	TAMPA, FL 336054606		
Owner's Phone:	8132475977	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

78 AAA METAL REFINISHING & CHROME  
3012 E 7TH AVE  
TAMPA, FL 33605

FINDS

1000933569  
FL0000890491

78 AAA METAL REFINISHING & CHROME  
3012 E 7TH AVE  
TAMPA, FL 33605

RCRIS-SQG

1000978634  
FL0000890491

RCRIS:

Owner: JAIME REGALADO OWNER  
(813) 247-2190

Contact: JAIME REGALADO  
(813) 247-2190

Waste	Quantity	Info Source
D000	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

79 CSX TRANSPORTATION INC-RALSTON PURINA  
3702 E BROADWAY AVE  
TAMPA, FL 33605

AST

A100008991  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CSX TRANSPORTATION INC-RALSTON PURINA (Continued)

A100008991

### AST:

Facility ID:	299101417	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CSX TRANSPORTATION INC		
Facility Phone:	9043591651	Permit Section:	Not reported
Date entered:	910401	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	K W RICHARDSON JR		
Owner:	CSX TRANSPORTATION INC J275		
	500 WATER ST		
	JACKSONVILLE, FL 32202		
Owner's Phone:	9043591986	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	91/03	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

80

KWIK STOP  
934 E HENDERSON AVE  
TAMPA, FL 33605

UST  
LUST

U001354739  
N/A

80

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KWIK STOP (Continued)

U001354739

### LUST:

Facility ID:	8625526	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132239890	Discovery Date:	11/07/88
Tracking Number:	294425	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

86



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KWIK STOP (Continued)

U001354739

### UST:

Facility ID:	298625526	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KWIK STOP		
Contact:	Not reported	Facility Phone:	8132239890
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	KWIK STOP		
	934 E HENDERSON AVE		
	TAMPA, FL 336054806		
Owner's Phone:	Not reported	Tracking #:	294425
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KWIK STOP (Continued)

U001354739

Facility ID:	298625526	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KWIK STOP		
Contact:	Not reported	Facility Phone:	8132239890
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	KWIK STOP		
	934 E HENDERSON AVE		
	TAMPA, FL 336054806		
Owner's Phone:	Not reported	Tracking #:	294425
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	install. Date:	82/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KWIK STOP (Continued)

U001354739

Facility ID:	298625526	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KWIK STOP		
Contact:	Not reported	Facility Phone:	8132239890
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	Not reported		
Owner:	KWIK STOP		
	934 E HENDERSON AVE		
	TAMPA, FL 336054806		
Owner's Phone:	Not reported	Tracking #:	294425
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

81

**GARDNER ASPHALT CORP**  
4001 E 7TH AVE  
TAMPA, FL 33675

FINDS

1000498460  
FLD982078263

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act  
facility is involved with pesticide/toxic substances production

81

**GARDNER-MARTIN ASPHALT CORP.**  
4001 E BROADWAY AVE  
TAMPA, FL 33605

AST

A100008753  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARDNER-MARTIN ASPHALT CORP. (Continued)

A100008753

### AST:

Facility ID:	298628181	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BELCASTRO, TIM		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	861110	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00015000
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

Facility ID:	298628181	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BELCASTRO, TIM		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	861110	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	10	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00030000
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	91/08	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARDNER-MARTIN ASPHALT CORP. (Continued)

A100008753

Facility ID:	298628181	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BELCASTRO, TIM		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	861110	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00020000
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

Facility ID:	298628181	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BELCASTRO, TIM		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	861110	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00007500
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**GARDNER-MARTIN ASPHALT CORP. (Continued)**

A100008753

Facility ID:	298628181	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BELCASTRO, TIM		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	861110	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

Facility ID:	298628181	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BELCASTRO, TIM		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	861110	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	5	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARDNER-MARTIN ASPHALT CORP. (Continued)

A100008753

Facility ID:	298628181	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BELCASTRO, TIM		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	861110	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	6	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

Facility ID:	298628181	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BELCASTRO, TIM		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	861110	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	7	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00007500
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARDNER-MARTIN ASPHALT CORP. (Continued)

A100008753

Facility ID:	298628181	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BELCASTRO, TIM		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	861110	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	8	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00050000
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	91/08	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

Facility ID:	298628181	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BELCASTRO, TIM		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	861110	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	9	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00030000
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	91/08	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

81

GARDNER ASPHALT CORP  
4001 E BROADWAY AVE  
TAMPA, FL 33605

AST

A100009038  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARDNER ASPHALT CORP (Continued)

A100009038

### AST:

Facility ID:	299200554	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TIM BELCASTRO		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	920224	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1P	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00007500
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

Facility ID:	299200554	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TIM BELCASTRO		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	920224	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2E	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP PO BOX 5449 TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00050000
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	91/08	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARDNER ASPHALT CORP (Continued)

A100009038

Facility ID:	299200554	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TIM BELCASTRO		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	920224	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2P	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP		
	PO BOX 5449		
	TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

Facility ID:	299200554	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TIM BELCASTRO		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	920224	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP		
	PO BOX 5449		
	TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00015000
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARDNER ASPHALT CORP (Continued)

A100009038

Facility ID:	299200554	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TIM BELCASTRO		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	920224	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3E	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP		
	PO BOX 5449		
	TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00030000
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	91/08	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

Facility ID:	299200554	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TIM BELCASTRO		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	920224	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3P	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP		
	PO BOX 5449		
	TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARDNER ASPHALT CORP (Continued)

A100009038

Facility ID:	299200554	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TIM BELCASTRO		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	920224	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4E	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP		
	PO BOX 5449		
	TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00030000
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	91/08	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

Facility ID:	299200554	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TIM BELCASTRO		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	920224	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4P	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP		
	PO BOX 5449		
	TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARDNER ASPHALT CORP (Continued)

A100009038

Facility ID:	299200554	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TIM BELCASTRO		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	920224	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	5P	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP		
	PO BOX 5449		
	TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00007500
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

Facility ID:	299200554	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TIM BELCASTRO		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	920224	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	7	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP		
	PO BOX 5449		
	TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00020000
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARDNER ASPHALT CORP (Continued)

A100009038

Facility ID:	299200554	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TIM BELCASTRO		
Facility Phone:	8132482101	Permit Section:	Not reported
Date entered:	920224	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	8	District:	Southwest
Owner's Contact:	BELCASTRO, TIM		
Owner:	GARDNER ASPHALT CORP		
	PO BOX 5449		
	TAMPA, FL 336755449		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	85/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping,		
	Bulk product piping		
Petro. Monitoring:	Man tank gauging		

82

**J W CONNER & SONS INC**  
**4100 E BROADWAY AVE**  
**TAMPA, FL 33605**

AST

A100008696  
N/A

AST:

Facility ID:	298625068	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CONNER J W & SONS INC		
Facility Phone:	8132476458	Permit Section:	Not reported
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	BILL FURNEY		
Owner:	J W CONNER & SONS INC		
	PO BOX 2522		
	TAMPA, FL 336012522		
Owner's Phone:	8132476458	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002500
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## J W CONNER & SONS INC (Continued)

A100008696

Facility ID:	298625068	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CONNER J W & SONS INC		
Facility Phone:	8132476458	Permit Section:	Not reported
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	4R1	District:	Southwest
Owner's Contact:	BILL FURNEY		
Owner:	J W CONNER & SONS INC		
	PO BOX 2522		
	TAMPA, FL 336012522		
Owner's Phone:	8132476458	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

Facility ID:	298625068	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CONNER J W & SONS INC		
Facility Phone:	8132476458	Permit Section:	Not reported
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	BILL FURNEY		
Owner:	J W CONNER & SONS INC		
	PO BOX 2522		
	TAMPA, FL 336012522		
Owner's Phone:	8132476458	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00018500
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	65/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	89/07	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## J W CONNER & SONS INC (Continued)

A100008696

Facility ID:	298625068	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CONNER J W & SONS INC		
Facility Phone:	8132476458	Permit Section:	Not reported
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	BILL FURNEY		
Owner:	J W CONNER & SONS INC		
	PO BOX 2522		
	TAMPA, FL 336012522		
Owner's Phone:	8132476458	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

Facility ID:	298625068	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CONNER J W & SONS INC		
Facility Phone:	8132476458	Permit Section:	Not reported
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	BILL FURNEY		
Owner:	J W CONNER & SONS INC		
	PO BOX 2522		
	TAMPA, FL 336012522		
Owner's Phone:	8132476458	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

83 FLORAL DRY CLEANERS & LAUNDRY  
3810 EAST 7TH AVE  
TAMPA, FL

RCRIS-SQG 1000700386  
FLD982106544

83 FLORAL DRY CLEANERS & LAUNDRY  
3810 E 7TH AVE  
TAMPA, FL 33691

FINDS 1000735137  
UST FLD982106544

83



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FLORAL DRY CLEANERS & LAUNDRY (Continued)

1000735137

### UST:

Facility ID:	299500880	Facility Type:	1
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	JISUNG LEE		
Contact:	Not reported	Facility Phone:	8132486439
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	850601	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	FONTE, JOE		
Owner:	JOE FONTE		
	3916 WATROUS AVE		
	TAMPA, FL 33609		
Owner's Phone:	8132890212	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

84

**ACTION PRESSURE CLEANING SYSTE**  
**4203 E 7TH AVE**  
**TAMPA, FL 33505**

**FINDS**

**1000498226**  
**FLD980800130**

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

85

**TOUCH OF CLASS**  
**813 E HENDERSON AVE**  
**TAMPA, FL 33602**

**RCRIS-SQG**  
**FINDS**

**1000821350**  
**FLD984242693**

### RCRIS:

Owner: ALFRED ORTEGA III, OWNER  
(813) 229-0083

Contact: ALFRED ORTEGA  
(813) 229-0083

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D035	.00000 (T)	Notification
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

85



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BEI SEL INC (Continued)

U002313283

### UST:

Facility ID:	299502448	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	9047247596
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	950808	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	ILA S BEIGHLEY		
Owner:	BEIGHLEY, ILA S		
	5705 CLIFTON AVE		
	JACKSONVILLE, FL 32211		
Owner's Phone:	9047247596	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	1
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

87

MAC PAPERS, INC.  
1701 N 50TH ST  
TAMPA, FL 33619

UST

U001355225  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MAC PAPERS, INC. (Continued)

U001355225

### UST:

Facility ID:	298627472	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MAC PAPERS, INC.		
Contact:	Not reported	Facility Phone:	8132473461
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861103	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JEFF C ASHCRAFT		
Owner:	MAC PAPERS INC		
	PO BOX 5369		
	JACKSONVILLE, FL 322475369		
Owner's Phone:	9043965312	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

88

FORMER FL BREWERY SITE  
1211 6TH AVE  
TAMPA, FL 33605

UST  
LUST

U002038275  
N/A

4686

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FORMER FL BREWERY SITE (Continued)

U002038275

### LUST:

Facility ID:	9401813	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132734201	Discovery Date:	08/31/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

88

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FORMER FL BREWERY SITE (Continued)

U002038275

### UST:

Facility ID:	299401813	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	8132734201
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940929	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	VANCE SMITH		
Owner:	JAMANCO INC		
	PO BOX 1531		
	TAMPA, FL 33601		
Owner's Phone:	8132734201	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	1
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

89

CONTINENTAL CAN CO., INC. #58  
1601 N 39TH ST  
TAMPA, FL 33605

UST  
LUST

U001545773  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CONTINENTAL CAN CO., INC. #58 (Continued)

U001545773

## LUST:

Facility ID:	8628775	Facility Type:	INDUSTRIAL PLANT
Alias Name:	Not reported		
Telephone:	8132476591	Discovery Date:	Not reported
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	Not reported
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	Not reported
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

g/g

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONTINENTAL CAN CO., INC. #58 (Continued)

U001545773

### UST:

Facility ID:	298628775	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CONTINENTAL CAN CO., INC.		
Contact:	Not reported	Facility Phone:	8132476591
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	R. TORRITO		
Owner:	CONTINENTAL CAN CO INC		
	PO BOX 5410		
	NORWALK, CT 068565410		
Owner's Phone:	2038555065	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Unprotec metal, Secondary containment		
Petro. Monitoring:	Not required		

5/1



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CONTINENTAL CAN CO., INC. #58 (Continued)

U001545773

Facility ID:	298628775	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CONTINENTAL CAN CO., INC.		
Contact:	Not reported	Facility Phone:	8132476591
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	R. TORRITO		
Owner:	CONTINENTAL CAN CO INC		
	PO BOX 5410		
	NORWALK, CT 068565410		
Owner's Phone:	2038555065	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Unprotec metal, Secondary containment		
Petro. Monitoring:	Not required		

5/9

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONTINENTAL CAN CO., INC. #58 (Continued)

U001545773

Facility ID:	298628775	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CONTINENTAL CAN CO., INC.		
Contact:	Not reported	Facility Phone:	8132476591
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	R. TORRITO		
Owner:	CONTINENTAL CAN CO INC		
	PO BOX 5410		
	NORWALK, CT 068565410		
Owner's Phone:	2038555065	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Unprotec metal, Secondary containment		
Petro. Monitoring:	Not required		

889

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONTINENTAL CAN CO., INC. #58 (Continued)

U001545773

Facility ID:	298628775	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CONTINENTAL CAN CO., INC.		
Contact:	Not reported	Facility Phone:	8132476591
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	R. TORRITO		
Owner:	CONTINENTAL CAN CO INC		
	PO BOX 5410		
	NORWALK, CT 068565410		
Owner's Phone:	2038555065	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	53/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

89

CONTINENTAL CAN CO. USA  
1601 39TH STREET  
TAMPA, FL 33605

FI Sites

S100888972  
N/A

### FL Sites:

Facility ID:	000448	EPA ID:	FLD004092441
Facility District:	SOUTHWEST	Monthly Update:	January
Lead Unit:	DIST	Support Unit:	Not reported
Air Contam:	Not reported	Soil Contam:	Confirmed
Surface Water Contam:	Not reported	Ground Water Contam:	Confirmed
Cleanup Started ?:	Yes	Cleanup Completed ?:	No
Deletion Recommended ?:	No	Other:	Not reported
Warning Letter Status:	Not reported	Notice of Violation Status:	No
Consent Order Status:	No	Admin Hearing Status:	No
Court Status:	No	Final Order Status:	No
Comments:	NEW SITE 9-86. CLOSURE PERMIT ISSUED 10-85 FOR UNDERGROUND STORAGE TANKS CONTAINING SPENT SOLVENTS. EXCAVATION STARTED 11-85, BUT STRONG SOLVENT ODOR OBSERVED IN SOIL. CONTAMINATED SOIL EXCAVATED 12-85. PCAP SUBMITTED 5-86. PCAR SUBMITTED 6-86 CONFIRMEDSOIL AND GROUNDWATER CONTAMINATION. CAP SUBMITTED 1-87. DRAFT CONSENT ORDER TO OGC 5-87. CAP APPROVED 5-87. CONTAMINATION ASSESSMENT REPORT (CAR) SUBMITTED 5-87; APPROVED 6-87. REMEDIAL ACTION PLAN (RAP) APPROVED; GW RECOVERY AND TREATMENT ONGOING 11-88.		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

89	<b>NUTMEG MILLS</b> 1601 39TH ST TAMPA, FL 33605	<b>RCRIS-SQG</b> <b>FINDS</b>	1000412537 FLD004092441
----	--	----------------------------------	----------------------------

## RCRIS:

Owner: CLIFTON GRIMES, ENV SPEC  
(904) 488-0190

Contact: MICHAEL DOCHSTADER  
(813) 247-6044

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D001	.00000 (N)	EPA Inspection			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

89	<b>CONTINENTAL CAN CO.</b> 1601 N 39TH ST TAMPA, FL 33605	<b>UST</b>	U001545772 N/A
----	---	------------	-------------------

## UST:

Facility ID:	298628772	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CONTINENTAL CAN CO.		
Contact:	Not reported	Facility Phone:	8132476591
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	R. TORRITO		
Owner:	CONTINENTAL CAN CO INC PO BOX 5410 NORWALK, CT 068565410		
Owner's Phone:	2038555065	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

90	<b>KAISER AGRICULTURAL CHEMICALS</b> 1606 35TH ST TAMPA, FL 33605	<b>FINDS</b>	1000933451 FL0000682989
----	---	--------------	----------------------------

90

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
91	<b>COLUMBIA JOBBING CO INC</b> 1702 E 5TH AVE YBOR CITY, FL 33605	UST	U001356111 N/A
UST:			
Facility ID:	299045854	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GARCIA CARLOS		
Contact:	Not reported	Facility Phone:	8132484142
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900207	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	NELSON LAZZARA		
Owner:	COLUMBIA JOBBING CO INC 1702 E 5TH AVE YBOR CITY, FL 336055116		
Owner's Phone:	8132484142	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	82/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

91

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## COLUMBIA JOBBING CO INC (Continued)

U001356111

Facility ID:	299045854	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GARCIA CARLOS		
Contact:	Not reported	Facility Phone:	8132484142
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900207	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	NELSON LAZZARA		
Owner:	COLUMBIA JOBBING CO INC		
	1702 E 5TH AVE		
	YBOR CITY, FL 336055116		
Owner's Phone:	8132484142	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	82/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

92

PETE & FRANKS GARAGE  
1602 N 15TH ST  
TAMPA, FL 33605

UST  
LUST

U001355210  
N/A

912

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

PETE & FRANKS GARAGE (Continued)

U001355210

LUST:

Facility ID:	8627430	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132483312	Discovery Date:	03/05/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	OPERATING AFTER 3/90
Incident Ineligible Description:	OPERATING AFTER

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

92

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PETE & FRANKS GARAGE (Continued)

U001355210

### UST:

Facility ID:	298627430	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIDEL J. GONZALEZ		
Contact:	Not reported	Facility Phone:	8132483312
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	F. U. CASTELLADO		
Owner:	PERRICONE, ROSIE C		
	3108 W NASSAU ST		
	TAMPA, FL 336075143		
Owner's Phone:	8138764946	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	77/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotac metal		
Petro. Monitoring:	Man sample wells		

92



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PETE & FRANKS GARAGE (Continued)

U001355210

Facility ID:	298627430	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIDEL J. GONZALEZ		
Contact:	Not reported	Facility Phone:	8132483312
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	F. U. CASTELLADO		
Owner:	PERRICONE, ROSIE C		
	3108 W NASSAU ST		
	TAMPA, FL 336075143		
Owner's Phone:	8138764946	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	77/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

92

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PETE & FRANKS GARAGE (Continued)

U001355210

Facility ID:	298627430	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIDEL J. GONZALEZ		
Contact:	Not reported	Facility Phone:	8132483312
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	F. U. CASTELLADO		
Owner:	PERRICONE, ROSIE C		
	3108 W NASSAU ST		
	TAMPA, FL 336075143		
Owner's Phone:	8138764946	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

92

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PETE & FRANKS GARAGE (Continued)

U001355210

Facility ID:	298627430	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIDEL J. GONZALEZ		
Contact:	Not reported	Facility Phone:	8132483312
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	F. U. CASTELLADO		
Owner:	PERRICONE, ROSIE C 3108 W NASSAU ST TAMPA, FL 336075143		
Owner's Phone:	8138764946	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

93	<b>FLORIDA IRON &amp; METAL</b> 1603 36TH ST TAMPA, FL 33601	<b>FINDS</b>	1000497138 FLD032759656
	Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act		
93	<b>GRACE W R &amp; CO PESTICIDES WARE</b> 1604 36TH ST TAMPA, FL 33601	<b>FINDS</b>	1000732723 FLD000653477
	Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act		
93	<b>GRACE &amp; CO,WR</b> 1604 N 36TH ST TAMPA, FL 33605	<b>UST</b>	U001354950 N/A

93

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GRACE & CO,WR (Continued)

U001354950

### UST:

Facility ID:	298625747	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132483101
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA		
	PO BOX 1210		
	FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

93

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GRACE & CO,WR (Continued)

U001354950

Facility ID:	298625747	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132483101
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA		
	PO BOX 1210		
	FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

93

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GRACE & CO,WR (Continued)

U001354950

Facility ID:	298625747	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132483101
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA		
	PO BOX 1210		
	FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

93

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GRACE & CO,WR (Continued)

U001354950

Facility ID:	298625747	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132483101
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA PO BOX 1210 FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unknown/not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	40/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

93

**KIMMINS RECYCLING FACILITY OF TAMPA**  
1604 N 36TH ST  
TAMPA, FL 33605

UST

U002113435  
N/A

93

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KIMMINS RECYCLING FACILITY OF TAMPA (Continued)

U002113435

### UST:

Facility ID:	299501536	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	CHARLES A BAKER JR		
Contact:	Not reported	Facility Phone:	8132483878
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	950306	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	WINA WHITE		
Owner:	KIMMINS RECYCLING CORP		
	790 HILLBRATH DR		
	LANTANA, FL 33462		
Owner's Phone:	8132483878	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

93

**KIMMINS RECYCLING (TAMPA)**  
**1604 N 36TH ST**  
**TAMPA, FL**

SWF/LF

S101011585  
N/A

### LF:

Facility ID:	4029P30087	Facility Status:	ACTIVE
Population Served:	750,000 PERSONS	Design Capacity:	0.0000
Amount Daily Waste:	200 TON	Number of Monitoring Wells:	0 WELLS
Facility Telephone:	(813) 248-3878	Facility Contact:	KIMMINS CONTRACTING CORP

94

**US BRAKE INC**  
**1205 5TH AVE**  
**TAMPA, FL 33605**

RCRIS-SQG  
FINDS

1000164565  
FLD982168486

### RCRIS:

Owner: ANDREW CASTANHEIRO  
(813) 229-7304

Contact: ANDREW CASTANHEIRO  
(813) 229-7304

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act



# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
---------------------------------	------	-------------	--------------------------------

95	<b>DRUM TECH INC</b> 1315 5TH AVE E TAMPA, FL 33605	RCRIS-SQG FINDS	1000821718 FLD984247163
----	---	--------------------	----------------------------

## RCRIS:

Owner: JOHN SWEATLOCK  
(813) 247-5123

Contact: JOHN SWEATLOCK  
(813) 247-5123

Waste	Quantity	Info Source
-------	----------	-------------

D001	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

96	<b>KAISER ALUMINUM &amp; CHEMICAL</b> 1601 34TH ST TAMPA, FL 33605	FINDS	1000497717 FLD087505806
----	--	-------	----------------------------

97	<b>ALL AMERICAN CUSTOM CHROME INC</b> 3211 E 5TH AVENUE TAMPA, FL 33605	FINDS	1000501895 FLD984220418
----	---	-------	----------------------------

97	<b>ALL AMERICAN CUSTOM CHROME INC</b> 3211 5TH AVE TAMPA, FL 33605	RCRIS-SQG	1000859231 FLD984220418
----	--	-----------	----------------------------

## RCRIS:

Owner: MIKE REYNOLDS, PLT MGR  
(813) 248-6221

Contact: MIKE REYNOLDS  
(813) 248-6221

Waste	Quantity	Info Source	Waste	Quantity	Info Source
-------	----------	-------------	-------	----------	-------------

D000	.00000 (T)	Notification	D007	.00000 (T)	Notification
F006	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

There are 4 compliance/violation record(s) reported at this site:

Evaluation	Date	Violations
COMPLIANCE SCHEDULE EVALUATION (CSE)	12-JAN-95	YES
COMPLIANCE SCHEDULE EVALUATION (CSE)	22-SEP-94	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	23-AUG-94	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	07-JUL-93	YES

97	<b>CROWN WINDOW CO.</b> 3204 E 5TH AVE TAMPA, FL 33605	UST	U001354371 N/A
----	--	-----	-------------------

97

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CROWN WINDOW CO. (Continued)

U001354371

### UST:

Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO.		
	3204 E 5TH AVE		
	TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

97

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CROWN WINDOW CO. (Continued)

U001354371

Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO. 3204 E 5TH AVE TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

97

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CROWN WINDOW CO. (Continued)

U001354371

Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO. 3204 E 5TH AVE TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

97

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CROWN WINDOW CO. (Continued)

U001354371

Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO.		
	3204 E 5TH AVE		
	TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

98

FL MISCELLANEOUS STEEL PRODUCTS INC  
2710 E 5TH AVE  
TAMPA, FL 33605

AST

A100008728  
N/A

9186

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

FL MISCELLANEOUS STEEL PRODUCTS INC (Continued)

A100008728

AST:

Facility ID:	298625694	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL MISCELLANEOUS STEEL PRODUCTS		
Facility Phone:	8132485222	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE DONALDSON		
Owner:	FL MISCELLANEOUS STEEL PRODUCTS		
	PO BOX 5208		
	TAMPA, FL 336755208		
Owner's Phone:	8132485222	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00003000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	84/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	89/09	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

Facility ID:	298625694	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL MISCELLANEOUS STEEL PRODUCTS		
Facility Phone:	8132485222	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE DONALDSON		
Owner:	FL MISCELLANEOUS STEEL PRODUCTS		
	PO BOX 5208		
	TAMPA, FL 336755208		
Owner's Phone:	8132485222	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00003000
Tank Content:	Unleaded gas	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	84/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	89/09	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

98

FLORIDA STRUCTURAL STEEL  
2710 5TH AVE  
TAMPA, FL 33675

RCRIS-SQG 1000700607  
FLD982134470

98

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FLORIDA STRUCTURAL STEEL (Continued)

1000700607

RCRIS:

Owner: STEPHEN MCGEE, OP MGR  
(813) 623-2675

Contact: STEPHEN MCGEE  
(813) 248-5222

Waste	Quantity	Info Source	Waste	Quantity	Info Source
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

There are 2 compliance/violation record(s) reported at this site:

Evaluation	Date	Violations
COMPLIANCE SCHEDULE EVALUATION (CSE)	07-OCT-94	YES
COMPLIANCE EVALUATION INSPECTION (CEI)	07-JUL-94	YES

99

**TAMPA BAY CLEANERS SUPPLY**  
**2302 E 5TH AVE**  
**TAMPA, FL 33605**

**RCRIS-SQG 1000461142**  
**FINDS FLD984188482**  
**UST**

RCRIS:

Owner: DICK QUEIPO, MGR  
(813) 247-6332

Contact: DICK QUEIPO  
(813) 247-6332

Waste	Quantity	Info Source
F002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

99

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA BAY CLEANERS SUPPLY (Continued)

1000461142

### UST:

Facility ID:	299502055	Facility Type:	2
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	DAVID PILGER		
Contact:	Not reported	Facility Phone:	3053240410
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	950706	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	PILGER, DAVID		
Owner:	DAVID & WILLIAM PILGER		
	2055 NW 7TH AVE		
	MIAMI, FL 33127		
Owner's Phone:	3053240410	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

100

**SPARKLE CORP**  
**4934 DISTRIBUTION DR**  
**TAMPA, FL 33622**

**FINDS**

**1000733576**  
**FLD076813302**

100

**SPARKLE CORP**  
**4934 DISTRIBUTION DRIVE**  
**TAMPA, FL 33622**

**RCRIS-LQG**  
**RCRIS-TSD**  
**AST**

**1000978559**  
**FLD076813302**

### RCRIS:

Owner: PAUL LUTH  
(813) 626-4099

Contact: PAUL LUTH  
(813) 626-4099

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (N)	State Inspection	F001	.00000 (N)	State Inspection
D001	231.10000 (T)	Part A	F001	231.10000 (T)	Part A

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARKLE CORP (Continued)

1000978559

### AST:

Facility ID:	298732614	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SPARKLE CORP		
Facility Phone:	8136264090	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID C BROWN		
Owner:	SPARKLE CORP		
	PO BOX 25456		
	TAMPA, FL 336225456		
Owner's Phone:	8136264099	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00002500
Tank Content:	Unknown/not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	89/03	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298732614	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SPARKLE CORP		
Facility Phone:	8136264090	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVID C BROWN		
Owner:	SPARKLE CORP		
	PO BOX 25456		
	TAMPA, FL 336225456		
Owner's Phone:	8136264099	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000600
Tank Content:	Unknown/not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	89/03	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARKLE CORP (Continued)

1000978559

Facility ID:	298732614	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SPARKLE CORP		
Facility Phone:	8136264090	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DAVID C BROWN		
Owner:	SPARKLE CORP		
	PO BOX 25456		
	TAMPA, FL 336225456		
Owner's Phone:	8136264099	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00004000
Tank Content:	Unknown/not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	89/03	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		
Facility ID:	298732614	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SPARKLE CORP		
Facility Phone:	8136264090	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DAVID C BROWN		
Owner:	SPARKLE CORP		
	PO BOX 25456		
	TAMPA, FL 336225456		
Owner's Phone:	8136264099	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000550
Tank Content:	Unknown/not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	89/03	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARKLE CORP (Continued)

1000978559

Facility ID:	298732614	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SPARKLE CORP		
Facility Phone:	8136264090	Permit Section:	Not reported
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	DAVID C BROWN		
Owner:	SPARKLE CORP		
	PO BOX 25456		
	TAMPA, FL 336225456		
Owner's Phone:	8136264099	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00001000
Tank Content:	Unknown/not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	89/03	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

100	ALLES SOUTHEAST CORP 4930 DISTRIBUTION DR TAMPA, FL 33605	RCRIS-SQG FINDS	1000221594 FLD072537392
-----	---	--------------------	----------------------------

101	NATL PRINTING INK CO 4775 DISTRIBUTION DR TAMPA, FL 33605	RCRIS-SQG FINDS	1000259964 FLD981855695
-----	---	--------------------	----------------------------

101	PHENIX SUPPLY CO OF FLORIDA INC 4763 DISTRIBUTION DR TAMPA, FL 33605	RCRIS-SQG	1000316529 FLD032795635
-----	--	-----------	----------------------------

RCRIS:

Owner: JAMES HARTLEY, ASST MGR  
(813) 248-1001

Contact: JAMES HARTLEY  
(813) 248-1001

Waste	Quantity	Info Source
-------	----------	-------------

F002	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

101	PHENIX SUPPLY CO OF FLORIDA INC 4763 DISTRIBUTION DR TAMPA, FL 33605	FINDS UST	1000733183 FLD032795635
-----	--	--------------	----------------------------

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## PHENIX SUPPLY CO OF FLORIDA INC (Continued)

1000733183

### UST:

Facility ID:	299502336	Facility Type:	2
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	JAMES HARTLEY		
Contact:	Not reported	Facility Phone:	8132481001
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	950726	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	SCOTT E HOLMAN		
Owner:	METROPOLITAN LIFE INSURANCE CO		
	4010 BOY SCOUT BLVD #200		
	TAMPA, FL 336074015		
Owner's Phone:	8138723814	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

102

**KEN ROBINSON OF FL INC**  
**3225 E 4TH AVE**  
**TAMPA, FL 33605**

UST  
LUST

U001355860  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KEN ROBINSON OF FL INC (Continued)

U001355860

### LUST:

Facility ID:	8841810	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132481711	Discovery Date:	05/19/92
Tracking Number:	Not reported	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported

Rank: 06114

Class: Not reported

Category: Not reported

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

COMBINED C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

RESPONSIBLE PARTY-NO CLAIM

Not reported

Not reported

Not Reported

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

102

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**KEN ROBINSON OF FL INC (Continued)**

**U001355860**

**UST:**

Facility ID:	298841810	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROBINSON KEN		
Contact:	Not reported	Facility Phone:	8132481711
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881017	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	KEN ROBINSON		
Owner:	ROBINSON, CHRIS & KEN		
	PO BOX 75302		
	TAMPA, FL 336750302		
Owner's Phone:	8132481711	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

103

**RED HOGAN ENTERPRISES INC**  
**3109 E 4TH AVE**  
**TAMPA, FL 33605**

**UST**  
**LUST**

**U001356338**  
**N/A**

103

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RED HOGAN ENTERPRISES INC (Continued)

U001356338

### LUST:

Facility ID:	9101913	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132483428	Discovery Date:	06/17/92
Tracking Number:	Not reported	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

103

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RED HOGAN ENTERPRISES INC (Continued)

U001356338

### UST:

Facility ID:	299101913	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HOGAN, THOMAS L		
Contact:	Not reported	Facility Phone:	8132483428
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910430	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	THOMAS L HOGAN		
Owner:	HOGAN, THOMAS L		
	PO BOX 13201		
	TAMPA, FL 33681		
Owner's Phone:	8132483428	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

104

**AUTOMATIC SPRINKLERS INC**  
2625 E 4TH AVE  
TAMPA, FL 33605

UST  
LUST

U001962955  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AUTOMATIC SPRINKLERS INC (Continued)

U001962955

### LUST:

Facility ID:	9401418	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138373009	Discovery Date:	07/19/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION

STATE CLEANUP

ELIGIBLE

Not Reported

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## AUTOMATIC SPRINKLERS INC (Continued)

U001962955

### UST:

Facility ID:	299401418	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	8138373009
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940812	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	W A KRUZEN		
Owner:	GENERAL MANAGEMENT DEVELOPMENT		
	2909 BAY TO BAY BLVD #600		
	TAMPA, FL 33629		
Owner's Phone:	8138373009	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

105	<b>AUTH APPLIANCE RECYCLING CTR</b> 2403 4TH AVE TAMPA, FL 33609	<b>FINDS</b>	1000931762 FL0000304279
106	<b>SCRAP ALL</b> 2801 4TH AVE TAMPA, FL 33602  Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	<b>FINDS</b>	1000497504 FLD067220566
107	<b>PHILLIPS 66-ANDY'S SPARTAN OIL</b> 2202 E 4TH AVE TAMPA, FL 33605	<b>UST</b> <b>LUST</b> <b>AST</b>	U001354848 N/A

107

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PHILLIPS 66-ANDY'S SPARTAN OIL (Continued)

U001354848

### LUST:

Facility ID:	8625641	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132426404	Discovery Date:	10/10/88
Tracking Number:	299146	Score:	019 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05548		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

107

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PHILLIPS 66-ANDY'S SPARTAN OIL (Continued)

U001354848

### UST:

Facility ID:	298625641	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANDREW LOPEZ		
Contact:	Not reported	Facility Phone:	8132426404
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	299146
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

107

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PHILLIPS 66-ANDY'S SPARTAN OIL (Continued)

U001354848

Facility ID:	298625641	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANDREW LOPEZ		
Contact:	Not reported	Facility Phone:	8132426404
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	299146
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PHILLIPS 66-ANDY'S SPARTAN OIL (Continued)

U001354848

Facility ID:	298625641	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANDREW LOPEZ		
Contact:	Not reported	Facility Phone:	8132426404
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	299146
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

### AST:

Facility ID:	298625641	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANDREW LOPEZ		
Facility Phone:	8132426404	Permit Section:	Not reported
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	299146
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000150
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	90/09	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

107

LONNIE'S BODY SHOP  
2201 E 4TH AVE  
TAMPA, FL 33605

UST  
LUST

U001356067  
N/A

107

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## LONNIE'S BODY SHOP (Continued)

U001356067

### LUST:

Facility ID:	8945277	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132486820	Discovery Date:	12/30/88
Tracking Number:	298562	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

107

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## LONNIE'S BODY SHOP (Continued)

U001356067

### UST:

Facility ID:	298945277	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS LONNIE		
Contact:	Not reported	Facility Phone:	8132486820
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	891107	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LONNIE WILLIAMS		
Owner:	WILLIAMS, LONNIE		
	PO BOX 5504		
	TAMPA, FL 336755504		
Owner's Phone:	8132486820	Tracking #:	298562
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	59/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

108

PEPE'S TRUCK REPAIR  
2109 4TH AVE  
TAMPA, FL 33605

UST

U001823380  
N/A

1086



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PEPE'S TRUCK REPAIR (Continued)

U001823380

### UST:

Facility ID:	299400235	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CARLOS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940221	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CARLOS		
Owner:	JOMITO CORP		
	2109 4TH AVE		
	TAMPA, FL 33605		
Owner's Phone:	8130000000	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

108

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

PEPE'S TRUCK REPAIR (Continued)

U001823380

Facility ID:	299400235	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CARLOS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940221	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CARLOS		
Owner:	JOMITO CORP 2109 4TH AVE TAMPA, FL 33605		
Owner's Phone:	8130000000	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

108

RICHARD'S STATION  
2102 E 4TH AVE  
TAMPA, FL 33605

UST  
LUST

U001356095  
N/A

108

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RICHARD'S STATION (Continued)

U001356095

### LUST:

Facility ID:	9045640	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8139851877	Discovery Date:	06/26/92
Tracking Number:	298750	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

108

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RICHARD'S STATION (Continued)

U001356095

### UST:

Facility ID:	299045640	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	GUZMAN RICHARD		
Contact:	Not reported	Facility Phone:	8139851877
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900111	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	GUZMAN RICHARD		
	2102 E 4TH AVE		
	TAMPA, FL 336055305		
Owner's Phone:	8139851877	Tracking #:	298750
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RICHARD'S STATION (Continued)

U001356095

Facility ID:	299045640	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	GUZMAN RICHARD		
Contact:	Not reported	Facility Phone:	8139851877
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900111	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	GUZMAN RICHARD		
	2102 E 4TH AVE		
	TAMPA, FL 336055305		
Owner's Phone:	8139851877	Tracking #:	298750
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Man sample wells		

109

TAMBORELLO STATION  
1715 E 4TH AVE  
TAMPA, FL 33605

UST  
LUST

U001354083  
N/A

109

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMBORELLO STATION (Continued)

U001354083

### LUST:

Facility ID:	8624823	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132482781	Discovery Date:	09/11/88
Tracking Number:	293765	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMBORELLO STATION (Continued)

U001354083

### UST:

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	RADIANT OIL CO		
	PO BOX 5751		
	TAMPA, FL 33605		
Owner's Phone:	Not reported	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	RADIANT OIL CO PO BOX 5751 TAMPA, FL 33605		
Owner's Phone:	Not reported	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

169



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	Not reported		
Owner:	RADIANT OIL CO		
	PO BOX 5751		
	TAMPA, FL 33605		
Owner's Phone:	Not reported	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

109

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	Not reported		
Owner:	RADIANT OIL CO		
	PO BOX 5751		
	TAMPA, FL 33605		
Owner's Phone:	Not reported	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	Not reported		
Owner:	RADIANT OIL CO PO BOX 5751 TAMPA, FL 33605		
Owner's Phone:	Not reported	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	Not reported		
Owner:	RADIANT OIL CO PO BOX 5751 TAMPA, FL 33605		
Owner's Phone:	Not reported	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

109

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	Not reported		
Owner:	RADIANT OIL CO		
	PO BOX 5751		
	TAMPA, FL 33605		
Owner's Phone:	Not reported	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

109

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	Not reported		
Owner:	RADIANT OIL CO PO BOX 5751 TAMPA, FL 33605		
Owner's Phone:	Not reported	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

109

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	9	District:	Southwest
Owner's Contact:	Not reported		
Owner:	RADIANT OIL CO		
	PO BOX 5751		
	TAMPA, FL 33605		
Owner's Phone:	Not reported	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

110

TAMPA BRAKE & SUPPLY CO., INC.  
1419 E 4TH AVE  
TAMPA, FL 33605

UST

U001355415  
N/A

110

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## TAMPA BRAKE & SUPPLY CO., INC. (Continued)

U001355415

### UST:

Facility ID:	298732615	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA BRAKE & SUPPLY CO., INC.		
Contact:	Not reported	Facility Phone:	8132473444
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	ARTHUR W. SCHILLING		
Owner:	TAMPA BRAKE & SUPPLY CO., INC.		
	1419 E 4TH AVE		
	TAMPA, FL 336055015		
Owner's Phone:	8132473444	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

110

TAMPA BRAKE & SUPPLY CO INC  
1419 4 AVE  
TAMPA, FL 33605

RCRIS-SQG  
FINDS

1000344842  
FLD064691223

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act

111

MANNA PRO CORP.  
1306 E 4TH AVE  
TAMPA, FL 33605

UST

U001354051  
N/A



MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**MANNA PRO CORP. (Continued)**

**U001354051**

**UST:**

Facility ID:	298624788	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANNA PRO CORP.		
Contact:	Not reported	Facility Phone:	8132475678
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BILL SNELLING		
Owner:	CARNATION CO.		
	P O BOX 2442		
	TAMPA, FL 33601		
Owner's Phone:	8132475678	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	76/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

111

**EAGLE SUPPLY, INC.**  
1301 E 4TH AVE  
TAMPA, FL 33605

UST

**U001355237**  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**EAGLE SUPPLY, INC. (Continued)**

**U001355237**

**UST:**

Facility ID:	298627636	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RALPH MARSHALL		
Contact:	Not reported	Facility Phone:	8132484911
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RALPH MARSHALL		
Owner:	EAGLE SUPPLY, INC.		
	P O BOX 75305		
	TAMPA, FL 33675		
Owner's Phone:	8132484911	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

112

**PITCH PINE LUMBER**  
**1607 N 43RD ST**  
**TAMPA, FL 33605**

**SHWS**

**S101136993**  
**N/A**

**SHWS:**

Facility ID:	99	NPL/State Site:	STATE
Permit Section:	Not reported	Cleanup Date:	Not reported
Cleanup Phase:	Not reported	Facility Status:	DENIED
Discharge Violation:	Not reported		

112

**CONTECH CONSTRUCTION PRODUCTS, INC.**  
**1601 N 43RD ST**  
**TAMPA, FL 33605**

**UST**  
**LUST**

**U001354298**  
**N/A**

112

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CONTECH CONSTRUCTION PRODUCTS,INC. (Continued)

U001354298

LUST:

Facility ID:	8625057	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132481544	Discovery Date:	05/08/90
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

112

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONTECH CONSTRUCTION PRODUCTS,INC. (Continued)

U001354298

### UST:

Facility ID:	298625057	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CONTECH CONSTRUCTION PRODUCTS		
Contact:	Not reported	Facility Phone:	8132481544
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DANIEL CHANEY		
Owner:	GATOR CULVERT CO. 1601 N 43RD ST TAMPA, FL 33605		
Owner's Phone:	3055822558	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONTECH CONSTRUCTION PRODUCTS,INC. (Continued)

U001354298

Facility ID:	298625057	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CONTECH CONSTRUCTION PRODUCTS		
Contact:	Not reported	Facility Phone:	8132481544
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DANIEL CHANEY		
Owner:	GATOR CULVERT CO. 1601 N 43RD ST TAMPA, FL 33605		
Owner's Phone:	3055822558	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

112

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CONTECH CONSTRUCTION PRODUCTS,INC. (Continued)

U001354298

Facility ID:	298625057	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CONTECH CONSTRUCTION PRODUCTS		
Contact:	Not reported	Facility Phone:	8132481544
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DANIEL CHANEY		
Owner:	GATOR CULVERT CO. 1601 N 43RD ST TAMPA, FL 33605		
Owner's Phone:	3055822558	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000600	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

112

**WEEKLY LUMBER**  
**1607 NORTH 43RD STREET**  
**TAMPA, FL 33605**

CERCLIS

1000893428  
FLD004114393

CERCLIS Classification Data:

Site Incident Category:	Not reported	Federal Facility:	NO
Ownership Status:	UNKNOWN	NPL Status:	NOT ON NPL
EPA Notes:	THE SITE IS AN ABANDONED LUMBER TREATMENT FACILITY WHICH OPERATED UNDER TWO SEPARATE OWNERS FROM 1963 TO 1989. COPPER, CHROMIUM, ARSENIC IN SOIL, SURFACE WATER, AND GW. (DLR 7-19-94)		

CERCLIS Assessment History:

Assessment:	DISCOVERY	Completed:	07/19/1994
Assessment:	PRELIMINARY ASSESSMENT	Completed:	10/06/1994
Assessment:	SCREENING SITE INSPECTION	Completed:	04/12/1995
Assessment:	HAZARD RANKING DETERMINED	Completed:	Not reported
Assessment:	REMOVAL ACTION	Completed:	Not reported
Assessment:	INTEGRATED ASSESSMENT	Completed:	03/06/1995

CERCLIS Site Status:

This site is currently under investigation by the government to assess the extent of further action

CERCLIS Alias Name(s):

PITCH PINE LUMBER

112

**PITCH PINE LUMBER COMPANY**  
**1607 N 43RD ST**  
**TAMPA, FL 33605**

UST  
LUST  
AST

U001354787  
N/A

112

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PITCH PINE LUMBER COMPANY (Continued)

U001354787

### LUST:

Facility ID:	8625575	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132484953	Discovery Date:	02/28/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

112

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PITCH PINE LUMBER COMPANY (Continued)

U001354787

### UST:

Facility ID:	298625575	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	PITCH PINE LUMBER COMPANY		
Contact:	Not reported	Facility Phone:	8132484953
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	R. E. DONALDSON		
Owner:	PITCH PINE LUMBER CO		
	1607 N 43RD ST		
	TAMPA, FL 336055937		
Owner's Phone:	8132484953	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

112



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PITCH PINE LUMBER COMPANY (Continued)

U001354787

Facility ID:	298625575	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	PITCH PINE LUMBER COMPANY		
Contact:	Not reported	Facility Phone:	8132484953
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	R. E. DONALDSON		
Owner:	PITCH PINE LUMBER CO 1607 N 43RD ST TAMPA, FL 336055937		
Owner's Phone:	8132484953	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

### AST:

Facility ID:	298625575	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	PITCH PINE LUMBER COMPANY		
Facility Phone:	8132484953	Permit Section:	Not reported
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	R. E. DONALDSON		
Owner:	PITCH PINE LUMBER CO 1607 N 43RD ST TAMPA, FL 336055937		
Owner's Phone:	8132484953	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000500
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

112

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PITCH PINE LUMBER COMPANY (Continued)

U001354787

Facility ID:	298625575	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	PITCH PINE LUMBER COMPANY		
Facility Phone:	8132484953	Permit Section:	Not reported
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	R. E. DONALDSON		
Owner:	PITCH PINE LUMBER CO		
	1607 N 43RD ST		
	TAMPA, FL 336055937		
Owner's Phone:	8132484953	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000500
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

112

WEEKLEY LUMBER CO  
1607 N 43RD ST  
TAMPA, FL 33605

RCRIS-SQG  
FINDS

1000271307  
FLD004114393

113

WOODRUFF & SONS, INC.  
1502 N 50TH ST  
TAMPA, FL 33619

UST  
LUST

U001354497  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WOODRUFF & SONS, INC. (Continued)

U001354497

### LUST:

Facility ID:	8625267	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8137561871	Discovery Date:	03/05/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

113

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WOODRUFF & SONS, INC. (Continued)

U001354497

### UST:

Facility ID:	298625267	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WOODRUFF & SONS, INC.		
Contact:	Not reported	Facility Phone:	8137561871
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BRUCE WOODRUFF		
Owner:	WOODRUFF & SONS INC		
	PO BOX 10127		
	BRADENTON, FL 342820127		
Owner's Phone:	8137561871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010152	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

113

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WOODRUFF & SONS, INC. (Continued)

U001354497

Facility ID:	298625267	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WOODRUFF & SONS, INC.		
Contact:	Not reported	Facility Phone:	8137561871
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BRUCE WOODRUFF		
Owner:	WOODRUFF & SONS INC		
	PO BOX 10127		
	BRADENTON, FL 342820127		
Owner's Phone:	8137561871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010152	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

113

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WOODRUFF & SONS, INC. (Continued)

U001354497

Facility ID:	298625267	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WOODRUFF & SONS, INC.		
Contact:	Not reported	Facility Phone:	8137561871
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BRUCE WOODRUFF		
Owner:	WOODRUFF & SONS INC		
	PO BOX 10127		
	BRADENTON, FL 342820127		
Owner's Phone:	8137561871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010152	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

113

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WOODRUFF & SONS, INC. (Continued)

U001354497

Facility ID:	298625267	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WOODRUFF & SONS, INC.		
Contact:	Not reported	Facility Phone:	8137561871
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	BRUCE WOODRUFF		
Owner:	WOODRUFF & SONS INC		
	PO BOX 10127		
	BRADENTON, FL 342820127		
Owner's Phone:	8137561871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010152	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

113

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WOODRUFF & SONS, INC. (Continued)

U001354497

Facility ID:	298625267	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WOODRUFF & SONS, INC.		
Contact:	Not reported	Facility Phone:	8137561871
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	BRUCE WOODRUFF		
Owner:	WOODRUFF & SONS INC		
	PO BOX 10127		
	BRADENTON, FL 342820127		
Owner's Phone:	8137561871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010152	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

1 B



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WOODRUFF & SONS, INC. (Continued)

U001354497

Facility ID:	298625267	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WOODRUFF & SONS, INC.		
Contact:	Not reported	Facility Phone:	8137561871
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	BRUCE WOODRUFF		
Owner:	WOODRUFF & SONS INC		
	PO BOX 10127		
	BRADENTON, FL 342820127		
Owner's Phone:	8137561871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010152	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

114

AETNA STEEL CO J H WILLIAMS OIL CO  
5113 UCETA RD  
TAMPA, FL 33619

UST  
LUST  
AST

U001355787  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

AETNA STEEL CO J H WILLIAMS OIL CO (Continued)

U001355787

LUST:

Facility ID:	8839277	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	04/22/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AETNA STEEL CO J H WILLIAMS OIL CO (Continued)

U001355787

### UST:

Facility ID:	298839277	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AETNA STEEL CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880219	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000560	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

### AST:

Facility ID:	298839277	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AETNA STEEL CO.		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	880219	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000550
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	90/XX	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
114	<b>TRANSFER-ONE INC TRANSFER STATION</b> <b>5113 UCETA RD</b> <b>TAMPA, FL</b> LF: Facility ID: 4029P30089 Population Served: Not reported Amount Daily Waste: Not reported Facility Telephone: (813) 248-5244	<b>SWF/LF</b>    ACTIVE 0.0000 0 WELLS TRANSFER-ONE INC	<b>S100021005</b> <b>N/A</b>
115	<b>GTE OF FL TAMPA</b> <b>3704 E 3RD AVE</b> <b>TAMPA, FL 33605</b>	<b>UST</b> <b>LUST</b>	<b>U001355733</b> <b>N/A</b>

115

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GTE OF FL TAMPA (Continued)

U001355733

### LUST:

Facility ID:	8837677	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	GENERAL TELEPHONE CO OF FL		
Telephone:	8136214931	Discovery Date:	09/10/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NO C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

115

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GTE OF FL TAMPA (Continued)

U001355733

### UST:

Facility ID:	298837677	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GENERAL TELEPHONE CO OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880115	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	87/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Dbl walled=primary matl		
Tank Piping:	Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Piping/auto shut off, Piping/flow restrictor		

116

GRACE & CO,WR-CONSTRUCTION PROD DIV  
3501 E 3RD AVE  
TAMPA, FL 33605

UST

U001355271  
N/A

116

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GRACE & CO,WR-CONSTRUCTION PROD DIV (Continued)

U001355271

### UST:

Facility ID:	298627813	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132481554
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA		
	PO BOX 1210		
	FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	87/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

117

LALA PRODUCE CO.  
1402 N 25TH ST  
TAMPA, FL 33605

UST

U001354571  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**LALA PRODUCE CO. (Continued)**

U001354571

UST:

Facility ID:	298625349	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LALA PRODUCE CO.		
Contact:	Not reported	Facility Phone:	8132473168
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	82/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Spill cnmt		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Man sample wells		

118 **QUALITY ELECTRIC SUPPLY INC**  
1400 N 34TH ST  
TAMPA, FL 33605

FINDS

1000933527  
FL0000748079

119 **BLISS PRODUCE**  
3119 E 3RD AVE  
TAMPA, FL 33605

UST  
LUST

U001355081  
N/A

119



MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BLISS PRODUCE (Continued)

U001355081

LUST:

Facility ID:	8627006	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	09/29/89
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BLISS PRODUCE (Continued)

U001355081

### UST:

Facility ID:	298627006	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BLISS, CHARLES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BLISS PRODUCE (Continued)

U001355081

Facility ID:	298627006	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BLISS, CHARLES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BLISS PRODUCE (Continued)

U001355081

Facility ID:	298627006	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BLISS, CHARLES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

120	4527 TRANSPORT DRIVE TAMPA, FL	HMIRS	91080686 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	91020161 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	91030485 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	91060250 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	92080315 N/A

120

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	91030489 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	91020476 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	91060556 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	90090173 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	91070642 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	92040371 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	92080058 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	91060569 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	91050521 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	92030691 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	92070492 N/A
120	4537 TRANSPORT TAMPA, FL	HMIRS	90080098 N/A

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	92020652 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	91030395 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	91081091 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	90080785 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	90080573 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	90080099 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	90080097 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	94070616 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	91020163 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	92080328 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	92110127 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	92040377 N/A

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	94081583 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	94101155 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	90090383 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	90080794 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	92070272 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	91070266 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	91080671 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	94051433 N/A
120	4537 TRANSPORT DR. TAMPA, FL	HMIRS	93010285 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	92080973 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	92020741 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	92120072 N/A

120

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
120	4537 TRANSPORT DR. TAMPA, FL	HMIRS	93010296 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	92090348 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	92070498 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	90080096 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	91070638 N/A
120	4536 TRANSPORT DRIVE TAMPA, FL	HMIRS	94100377 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	94080967 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	92110418 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	94110676 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	94070618 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	91081114 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	94020596 N/A

120



# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
120	4537 TRANSPORT DR. TAMPA, FL	HMIRS	92100744 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	90080105 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	92090588 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	94080073 N/A
120	4537 TRANSPORT DR TAMPA, FL	HMIRS	94101167 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	94090107 N/A
120	4537 TRANSPORT DRIVE TAMPA, FL	HMIRS	92070493 N/A
120	4537 TRANSPORT DR. TAMPA, FL	HMIRS	93010564 N/A
121	TAMPA GAS CO. 1300 BLOCK OF 13TH ST. TAMPA, FL 33605  COAL GAS SITE DESCRIPTION: 1899, Tampa Gas Co. is located on the western side of 13th St., south of 3 rd. site continues south to the end of 1st St. Site is bordered to the west by railroad tracks.  ©Copyright 1993 Real Property Scan, Inc.	Coal Gas	G000001449 N/A
122	SOWELL CORP,L B 1405 E 2ND AVE TAMPA, FL 33605	UST	U001354606 N/A

172

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**SOWELL CORP,L B (Continued)**

**U001354606**

UST:

Facility ID:	298625386	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOWELL CORP,L B		
Contact:	Not reported	Facility Phone:	8139882358
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LEO SOWELL		
Owner:	L B SOWELL CORP		
	12123 RIVERHILLS DR		
	TAMPA, FL 336171743		
Owner's Phone:	8139882358	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

123

**KIMMINS CONTRACTING CORP**  
**1616 & 1617 2ND AVE**  
**TAMPA, FL 33605**

**UST**  
**LUST**  
**AST**

**U001355323**  
**N/A**

123

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KIMMINS CONTRACTING CORP (Continued)

U001355323

### LUST:

Facility ID:	8628039	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132483878	Discovery Date:	09/28/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	CONTAMINATION ASSESSMENT REPORT
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**KIMMINS CONTRACTING CORP (Continued)**

U001355323

UST:

Facility ID:	298628039	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KIMMINS CORP.		
Contact:	Not reported	Facility Phone:	8132483878
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	WINA WHITE		
Owner:	KIMMINS RECYCLING CORP 790 HILLBRATH DR LANTANA, FL 33462		
Owner's Phone:	8132483878	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

123

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KIMMINS CONTRACTING CORP (Continued)

U001355323

Facility ID:	298628039	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KIMMINS CORP.		
Contact:	Not reported	Facility Phone:	8132483878
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WINA WHITE		
Owner:	KIMMINS RECYCLING CORP		
	790 HILLBRATH DR		
	LANTANA, FL 33462		
Owner's Phone:	8132483878	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

123

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KIMMINS CONTRACTING CORP (Continued)

U001355323

Facility ID:	298628039	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KIMMINS CORP.		
Contact:	Not reported	Facility Phone:	8132483878
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	WINA WHITE		
Owner:	KIMMINS RECYCLING CORP		
	790 HILLBRATH DR		
	LANTANA, FL 33462		
Owner's Phone:	8132483878	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

1 23

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

KIMMINS CONTRACTING CORP (Continued)

U001355323

Facility ID:	298628039	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KIMMINS CORP.		
Contact:	Not reported	Facility Phone:	8132483878
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	WINA WHITE		
Owner:	KIMMINS RECYCLING CORP 790 HILLBRATH DR LANTANA, FL 33462		
Owner's Phone:	8132483878	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

AST:

Facility ID:	298628039	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KIMMINS CORP.		
Facility Phone:	8132483878	Permit Section:	Not reported
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	WINA WHITE		
Owner:	KIMMINS RECYCLING CORP 790 HILLBRATH DR LANTANA, FL 33462		
Owner's Phone:	8132483878	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000500
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

123

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**KIMMINS CONTRACTING CORP (Continued)**

**U001355323**

Facility ID:	298628039	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KIMMINS CORP.		
Facility Phone:	8132483878	Permit Section:	Not reported
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	WINA WHITE		
Owner:	KIMMINS RECYCLING CORP		
	790 HILLBRATH DR		
	LANTANA, FL 33462		
Owner's Phone:	8132483878	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	91/02
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

124

**THOMPSON FABRICATED METALS INC**  
2103 2ND AVE  
TAMPA, FL

UST  
LUST

**U001057909**  
**N/A**

124



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## THOMPSON FABRICATED METALS INC (Continued)

U001057909

### LUST:

Facility ID:	9102303	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132483456	Discovery Date:	08/26/91
Tracking Number:	Not reported	Score:	056
Facility Code:	Not reported	Status:	Not reported
Rank:	01712		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

124

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

THOMPSON FABRICATED METALS INC (Continued)

U001057909

UST:

Facility ID:	299102303	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	THOMPSON FABRICATED METALS		
Contact:	Not reported	Facility Phone:	8132483456
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910614	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LESLIE V THOMPSON		
Owner:	THOMPSON FABRICATED METALS INC		
	2103 2ND AVE		
	TAMPA, FL 33605		
Owner's Phone:	8132483456	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

125

DEL RIO PRODUCTS  
2601 E 2ND AVE  
TAMPA, FL 33605

UST

U001354313  
N/A

125

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

DEL RIO PRODUCTS (Continued)

U001354313

UST:

Facility ID:	298625072	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEL RIO PRODUCTS		
Contact:	Not reported	Facility Phone:	8132474534
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAN TRIPLET		
Owner:	DEL RIO PRODUCTS		
	PO BOX 75245		
	TAMPA, FL 336750245		
Owner's Phone:	8132474534	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

126

BAZARTE/RENE  
801 E SCOTT ST  
TAMPA, FL 33602

UST  
LUST

U001355389  
N/A

126

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BAZARTE/RENE (Continued)

U001355389

LUST:

Facility ID:	8732385	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132239000	Discovery Date:	12/04/86
Tracking Number:	290297	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	DISTRICT OFFICE
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	DISTRICT OFFICE
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	QTR 1

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

126

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BAZARTE/RENE (Continued)

U001355389

UST:

Facility ID:	298732385	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RENE BAZARTE		
Contact:	Not reported	Facility Phone:	8132239000
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870410	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RENE BAZARTE		
Owner:	BAZARTE, RENE		
	801 E SCOTT ST		
	TAMPA, FL 33602		
Owner's Phone:	8132239000	Tracking #:	290297
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

126

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAZARTE/RENE (Continued)

U001355389

Facility ID:	298732385	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RENE BAZARTE		
Contact:	Not reported	Facility Phone:	8132239000
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870410	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	RENE BAZARTE		
Owner:	BAZARTE, RENE 801 E SCOTT ST TAMPA, FL 33602		
Owner's Phone:	8132239000	Tracking #:	290297
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

126

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAZARTE/RENE (Continued)

U001355389

Facility ID:	298732385	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RENE BAZARTE		
Contact:	Not reported	Facility Phone:	8132239000
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870410	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	RENE BAZARTE		
Owner:	BAZARTE, RENE 801 E SCOTT ST TAMPA, FL 33602		
Owner's Phone:	8132239000	Tracking #:	290297
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

127

ADAMO DRIVE INC  
1909 ADAMO DR  
TAMPA, FL 33601

UST  
LUST

U001354425  
N/A

127

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ADAMO DRIVE INC (Continued)

U001354425

### LUST:

Facility ID:	8625191	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132287776	Discovery Date:	12/23/88
Tracking Number:	298291	Score:	075 (HIGH)
Facility Code:	Not reported	Status:	Not reported
Rank:	00538		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	O.K.

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

127



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ADAMO DRIVE INC (Continued)

U001354425

### UST:

Facility ID:	298625191	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	J.H. WILLIAMS, JR.		
Contact:	Not reported	Facility Phone:	8132287776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298291
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Fiberglass, Cathod prot steel, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging, Vapor monitoring		

127

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ADAMO DRIVE INC (Continued)

U001354425

Facility ID:	298625191	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	J.H. WILLIAMS, JR.		
Contact:	Not reported	Facility Phone:	8132287776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298291
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Fiberglass, Cathod prot steel, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging, Vapor monitoring		

127

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

ADAMO DRIVE INC (Continued)

U001354425

Facility ID:	298625191	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	J.H. WILLIAMS, JR.		
Contact:	Not reported	Facility Phone:	8132287776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298291
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Fiberglass, Cathod prot steel, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging, Vapor monitoring		

127

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ADAMO DRIVE INC (Continued)

U001354425

Facility ID:	298625191	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	J.H. WILLIAMS, JR.		
Contact:	Not reported	Facility Phone:	8132287776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298291
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground ✓	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Cath		
	prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Fiberglass, Cathod prot steel, Dblwall=primary		
	matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man		
	tank gauging, Vapor monitoring		

127

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ADAMO DRIVE INC (Continued)

U001354425

Facility ID:	298625191	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	J.H. WILLIAMS, JR.		
Contact:	Not reported	Facility Phone:	8132287776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298291
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Cath prot-sac anode, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal, Fiberglass, Cathod prot steel, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging, Vapor monitoring		

127

LINDA PLASTICS OF FLORIDA INC  
1207 N 19TH ST  
TAMPA, FL 33605

FINDS

1000497765  
FLD094606381

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

128

PEOPLES GAS SYSTEM, INC.  
1200 N 13TH ST  
TAMPA, FL 33605

UST

U001354488  
N/A

128

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PEOPLES GAS SYSTEM, INC. (Continued)

U001354488

### UST:

Facility ID:	298625257	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PEOPLES GAS SYSTEM, INC.		
Contact:	Not reported	Facility Phone:	8132289743
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GLYN HAZELDEN		
Owner:	PEOPLES GAS SYSTEM INC		
	PO BOX 2562		
	TAMPA, FL 336012562		
Owner's Phone:	8132289743	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	82/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

128

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

PEOPLES GAS SYSTEM, INC. (Continued)

U001354488

Facility ID:	298625257	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PEOPLES GAS SYSTEM, INC.		
Contact:	Not reported	Facility Phone:	8132289743
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GLYN HAZELDEN		
Owner:	PEOPLES GAS SYSTEM INC PO BOX 2562 TAMPA, FL 336012562		
Owner's Phone:	8132289743	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000400	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	86/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

128

PEOPLES GAS SYSTEM, INC.  
1200 NORTH 13TH ST.  
TAMPA, FL 33605

FI Sites

S100889025  
N/A

FL Sites:

Facility ID:	000480	EPA ID:	Not reported
Facility District:	SOUTHWEST	Monthly Update:	January
Lead Unit:	DIST	Support Unit:	Not reported
Air Contam:	Not reported	Soil Contam:	Not reported
Surface Water Contam:	Not reported	Ground Water Contam:	Confirmed
Cleanup Started ?:	No	Cleanup Completed ?:	No
Deletion Recommended ?:	No	Other:	Not reported
Warning Letter Status:	Not reported	Notice of Violation Status:	No
Consent Order Status:	No	Admin Hearing Status:	No
Court Status:	No	Final Order Status:	No
Comments:	NEW SITE 5-87. NATURAL GAS MANUFACTURED AT THE PROPERTY PRIOR TO 1950. GROUND WATER SAMPLES COLLECTED 12-86 CONFIRM CONTAMINATION OF SURFICIAL AQUIFER BY VOC'S AND OTHER ORGANIC COMPOUNDS. DRAFT CONSENT ORDER REQUIRING CONTAMINATION ASSESMENT AND REMEDIAL ACTION PLANS (CAP/RAP) FORWARDED TO RESPONDENT 7-87. RESPONDENT OBTAINED CONSULTANT TO PREPARE CAP 9-88. CAP DUE 11-88. CO NEGOTIATIONS PENDING APPROVAL OF CAP.		

128

PEOPLE'S GAS SYSTEM  
1200 NORTH 13TH STREET  
TAMPA, FL 33601

CERCLIS  
FINDS

1000348068  
FLD982119653

128

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## PEOPLE'S GAS SYSTEM (Continued)

1000348068

### CERCLIS Classification Data:

Site Incident Category: Not reported

Federal Facility: D

Ownership Status: UNKNOWN

NPL Status: NOT ON NPL

EPA Notes: ALLEGED PARA-CHEM SOUTHERN DUMP SITE. STEEL AND FIBER DRUMS IN TRENCH (275X13X16 FEET). REPORTED EXPLOSIONS, FIRES.

### CERCLIS Assessment History:

Assessment: DISCOVERY

Completed: 09/03/1987

Assessment: PRELIMINARY ASSESSMENT

Completed: 10/25/1988

Assessment: SCREENING SITE INSPECTION

Completed: 10/22/1991

### CERCLIS Site Status:

EPA has conducted a preliminary assessment on this site and has determined that no further action is necessary and no hazard was identified

### CERCLIS Alias Name(s):

PEOPLE'S GAS SYSTEM

129	RADIANT DISCOUNT TIRES 2105 ADAMO DRIVE TAMPA, FL 33675	RCRIS-SQG	1000698916 FLD053996294
129	RADIANT DISCOUNT TIRES 2105 ADAMO DR TAMPA, FL 33675	FINDS	1000733384 FLD053996294
129	EXXON CO USA #49121 2105 E ADAMO & 21ST ST E TAMPA, FL 77210	FINDS UST LUST	1000736457 FLD984185694

129



MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49121 (Continued)

1000736457

LUST:

Facility ID:	8624826	Facility Type:	RETAIL STATION
Alias Name:	EXXON #4-9121		
Telephone:	4076473776	Discovery Date:	06/26/90
Tracking Number:	292829	Score:	057
Facility Code:	Not reported	Status:	Not reported
Rank:	01641		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	MOP CANCELLED

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

129

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49121 (Continued)

1000736457

## UST:

Facility ID:	298624826	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	292829
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

129

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49121 (Continued)

1000736457

Facility ID:	298624826	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	292829
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill		
	cnmt		
Tank Piping:	Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

129

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49121 (Continued)

1000736457

Facility ID:	298624826	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	292829
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

129

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49121 (Continued)

1000736457

Facility ID:	298624826	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	292829
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt		
Tank Piping:	Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells		

129

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49121 (Continued)

1000736457

Facility ID:	298624826	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	292829
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

129

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49121 (Continued)

1000736457

Facility ID:	298624826	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	292829
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-bail check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells		

129

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49121 (Continued)

1000736457

Facility ID:	298624826	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	292829
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

129



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49121 (Continued)

1000736457

Facility ID:	298624826	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	292829
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

129

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

EXXON CO USA #49121 (Continued)

1000736457

Facility ID:	298624826	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BYRD, ROGER		
Contact:	Not reported	Facility Phone:	4076473776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	292829
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells		

130

WALKER CO./SOL  
1110 N 35TH ST  
TAMPA, FL 33605

UST

U001354591  
N/A

130

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WALKER CO./SOL (Continued)

U001354591

### UST:

Facility ID:	298625371	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOL WALKER & CO.		
Contact:	Not reported	Facility Phone:	8132485796
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARY T. CACKLING		
Owner:	SOL WALKER & CO		
	PO BOX 5447		
	TAMPA, FL 336755447		
Owner's Phone:	8132485796	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	70/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

131

HILLSBOROUGH CNTY-MORGAN ST JAIL  
1301 N MORGAN ST  
TAMPA, FL 33602

UST

U001356353  
N/A

131

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-MORGAN ST JAIL (Continued)

U001356353

### UST:

Facility ID:	299102571	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FARMER, J R		
Contact:	Not reported	Facility Phone:	8132478425
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910806	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT		
	PO BOX 3371		
	TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	63/10
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

131

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-MORGAN ST JAIL (Continued)

U001356353

Facility ID:	299102571	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FARMER, J R		
Contact:	Not reported	Facility Phone:	8132478425
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910806	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	63/10
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-MORGAN ST JAIL (Continued)

U001356353

Facility ID:	299102571	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FARMER, J R		
Contact:	Not reported	Facility Phone:	8132478425
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910806	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	79/10
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

131

HILLSBOROUGH CNTY-JAIL SYSTEM  
1308 N MORGAN ST  
TAMPA, FL 33602

UST  
LUST

U001355249  
N/A

131

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-JAIL SYSTEM (Continued)

U001355249

### LUST:

Facility ID:	8627689	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132476411	Discovery Date:	12/19/88
Tracking Number:	297405	Score:	020 (LOW)
Facility Code:	Not reported	Status:	Not reported

Rank: 05520  
Class: Not reported  
Category: Not reported

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-JAIL SYSTEM (Continued)

U001355249

### UST:

Facility ID:	298627689	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HILLS CNTY SHERIFFS JAIL-SYSTEM		
Contact:	Not reported	Facility Phone:	8132476411
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	297405
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-JAIL SYSTEM (Continued)

U001355249

Facility ID:	298627689	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HILLS CNTY SHERIFFS JAIL-SYSTEM		
Contact:	Not reported	Facility Phone:	8132476411
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	297405
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

132

## INTERNATIONAL SHIP REPAIR 1616 PENNY ST TAMPA, FL 33605

RCRIS-SQG  
FINDS

1000858771  
FL0000014555

### RCRIS:

Owner: WAYNE REED, MATERIALS MGR  
(813) 247-1118

Contact: WAYNE REED  
(813) 247-1118

Waste	Quantity	Info Source
D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

There are 1 compliance/violation record(s) reported at this site:

Evaluation	Date	Violations
COMPLIANCE EVALUATION INSPECTION (CEI)	14-MAY-93	YES

133

## DIXIE PLYWOOD CO OF TAMPA INC 3021 ADAMO DR TAMPA, FL 33605

UST  
LUST

U001354314  
N/A

133

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DIXIE PLYWOOD CO OF TAMPA INC (Continued)

U001354314

### LUST:

Facility ID:	8625073	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132484107	Discovery Date:	01/17/90
Tracking Number:	Not reported	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06719		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: LEADED GAS

Pollutant 2: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION

REIMBURSEMENT CLEANUP

ELIGIBLE

Not Reported

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

APPROVED

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

NO FURTHER ACTION

STATE

133

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DIXIE PLYWOOD CO OF TAMPA INC (Continued)

U001354314

### UST:

Facility ID:	298625073	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DIXIE PLYWOOD CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132484107
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ED CAMPBELL		
Owner:	DIXIE PLYWOOD CO TAMPA		
	PO BOX 5718		
	TAMPA, FL 336755718		
Owner's Phone:	8132484107	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	84/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

133

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DIXIE PLYWOOD CO OF TAMPA INC (Continued)

U001354314

Facility ID:	298625073	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DIXIE PLYWOOD CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132484107
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ED CAMPBELL		
Owner:	DIXIE PLYWOOD CO TAMPA		
	PO BOX 5718		
	TAMPA, FL 336755718		
Owner's Phone:	8132484107	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	84/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Unknown/not reported		

134

UNION CARBIDE CORP.-LINDE DIVISION  
ADAMO DR & 31ST ST  
TAMPA, FL 33605

UST

U001355413  
N/A

134

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNION CARBIDE CORP.-LINDE DIVISION (Continued)

U001355413

### UST:

Facility ID:	298732613	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNION CARBIDE CORP.		
Contact:	Not reported	Facility Phone:	8132476467
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	W.J. WESTFALL		
Owner:	UNION CARBIDE CORP. 39 OLD RIDGEBURY RD DANBURY, CT 068170001		
Owner's Phone:	8132476467	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

134

**PRAYAIR INC**  
**3100 ADAMO DR**  
**TAMPA, FL 33605**

**RCRIS-SQG**  
**FINDS**

**1000986052**  
**FL0001046275**

### RCRIS:

Owner: ARTHUR THOMAS, OPERA SUPV  
(813) 247-5317

Contact: Not reported

Waste	Quantity	Info Source
-------	----------	-------------

NONE	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

135

**CAIN & BULTMAN INC**  
**4506 E ACLINE DR**  
**TAMPA, FL 33605**

**UST**  
**LUST**

**U001356006**  
**N/A**

135

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CAIN & BULTMAN INC (Continued)

U001356006

### LUST:

Facility ID:	8943983	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132474460	Discovery Date:	09/16/93
Tracking Number:	Not reported	Score:	036
Facility Code:	Not reported	Status:	Not reported
Rank:	02970		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

### DISCHARGE NOTIFICATION

Lead:

Not reported

Incident 17-770 Cleanup:

Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

RESPONSIBLE PARTY-NO CLAIM

Incident Program Type:

Not reported

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

NO FURTHER ACTION

Region:

STATE

135

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CAIN & BULTMAN INC (Continued)

U001356006

### UST:

Facility ID:	298943983	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CAIN & BULTMAN INC		
Contact:	Not reported	Facility Phone:	8132474460
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890428	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BILL POSS		
Owner:	CAIN & BULTMAN INC		
	PO BOX 2815		
	JACKSONVILLE, FL 322032815		
Owner's Phone:	9043564812	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/11
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-sac anode, Spill		
	cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

135

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## CAIN & BULTMAN INC (Continued)

U001356006

Facility ID:	298943983	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CAIN & BULTMAN INC		
Contact:	Not reported	Facility Phone:	8132474460
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890428	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BILL POSS		
Owner:	CAIN & BULTMAN INC		
	PO BOX 2815		
	JACKSONVILLE, FL 322032815		
Owner's Phone:	9043564812	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/11
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Cath prot-sac anode, Spill		
	cnmt, Op-tight fill		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

136

INDUSTRIAL CHEMICAL & SUPPLY CO  
3520 ADAMO DR  
TAMPA, FL 33605

AST

A100008750  
N/A

136



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

### AST:

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00006000
Tank Content:	Mineral acid	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	90/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00012000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	90/03
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	11	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00040000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	93/10
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Aprvd alt sys		
Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	Mineral acid	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

136

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	Mineral acid	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		
Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

136

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		
Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00003500
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

136

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001200
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		
Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

INDUSTRIAL CHEMICAL & SUPPLY CO (Continued)

A100008750

Facility ID:	298627237	Facility Type:	Other
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ANDREW AKERS		
Facility Phone:	8132477354	Permit Section:	Not reported
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/11
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area, Polyethylene		
Tank Piping:	Abvgrnd-no contact w/soil, appv synthetic material		
Petro. Monitoring:	Aprvd alt sys		

136

3520 ADAMO DR  
TAMPA, FL

HMIRS

91090588  
N/A

136

INDUSTRIAL CHEMICAL & SUPPLY  
3520 ADAMO DRIVE  
TAMPA, FL 33675

RCRIS-SQG  
UST  
LUST

1000698743  
FLD032783003

136

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY (Continued)

1000698743

### LUST:

Facility ID:	8627232	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132477354	Discovery Date:	12/12/88
Tracking Number:	297406	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO MONITOR WELL/OVERFILL W/SCHED
Incident Ineligible Description:	NO MONITOR WELL

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

136

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## INDUSTRIAL CHEMICAL & SUPPLY (Continued)

1000698743

### UST:

Facility ID:	298627232	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	INDUSTRIAL CHEMICAL & SUPPLY		
Contact:	Not reported	Facility Phone:	8132477354
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ANDREW B AKERS		
Owner:	INDUSTRIAL CHEMICAL & SUPPLY		
	PO BOX 5106		
	TAMPA, FL 33605		
Owner's Phone:	8132477354	Tracking #:	297406
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Auto sample wells		

136

ROLLINS LEASING CORP #363  
1201 N 34TH ST  
TAMPA, FL 19803

RCRIS-SQG 1000699288  
UST FLD163283443  
LUST  
AST

136



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

### LUST:

Facility ID:	8625768	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132473411	Discovery Date:	11/21/91
Tracking Number:	Not reported	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

136

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

### UST:

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

136

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

136

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

136

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

136

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	6	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

136

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	7	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

### AST:

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Facility Phone:	8132473411	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	8	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-flow shut off		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Auto tank gauging		

1 36



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ROLLINS LEASING CORP #363 (Continued)

1000699288

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Facility Phone:	8132473411	Permit Section:	Not reported
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	9	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 19899		
Owner's Phone:	3024262899	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/02
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Spill cnmt, Op-flow shut off		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	GW monitoring		

136	SAUNDERS SYSTEM INC 1201 N 34TH ST TAMPA, FL 33605	FINDS	1000733837 FLD163283443
137	BAY FORD TRUCK SALES INC 3214 ADAMO DR TAMPA, FL 33675	RCRIS-SQG FINDS	1000498413 FLD981868839
137	BAY FORD TRUCK SALES,INC 3214 ADAMO DR TAMPA, FL 33605	UST LUST	U001354810 N/A

137

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BAY FORD TRUCK SALES,INC (Continued)

U001354810

LUST:

Facility ID:	8625601	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8139803673	Discovery Date:	12/16/88
Tracking Number:	295751	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

137

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

### UST:

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

137

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

137

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

137

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BAY FORD TRUCK SALES,INC (Continued)

U001354810

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

**BAY FORD TRUCK SALES,INC (Continued)**

**U001354810**

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	CURRIE,WE & PATTISHALL,CL		
	5114 POE AVE		
	TAMPA, FL 33601		
Owner's Phone:	8138396257	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

138	<b>DEVOE &amp; RAYNOLDS CO</b> 1010-26 N 19TH ST TAMPA, FL 33605	<b>FINDS</b> <b>TRIS</b>	<b>1000733679</b> <b>FLD092715051</b>
	Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production		
138	<b>DEVOE &amp; RAYNOLDS PAINT CO</b> 1010-26 N 19TH ST TAMPA, FL 33605	<b>LUST</b> <b>AST</b>	<b>S101638055</b> <b>N/A</b>

134



MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

LUST:

Facility ID:	9102845	Facility Type:	OTHER
Alias Name:	Not reported		
Telephone:	8132473161	Discovery Date:	12/30/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	NAPTHA,MINERAL SP	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

138

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

AST:

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TOM WEHRENBERG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003775
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	TOM WEHRENBERG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

138

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	11	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	12	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

138

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	13	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00004345
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	14	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	15	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	16	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

1386

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	17	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00007295
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	18	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00004960
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

17358

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	19	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00004660
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006525
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	20	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00004660
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	21	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00004660
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

1386



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	22	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00004660
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	23	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00004500
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

B 86

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	24	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006245
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	25	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006245
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

1356

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	26	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00007920
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	27	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003000
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	91/06
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

1356

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	28	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	87/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	29	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	87/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006525
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	30	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00004345
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	88/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

1328

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	31	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00004960
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	78/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	32	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00004660
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	78/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	33	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00004660
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	78/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	34	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006245
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	88/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	35	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00004345
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	84/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	36	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	65/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	84/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

138



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	37	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	65/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	84/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	38	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	65/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	84/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	39	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	65/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	84/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00007810
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	40	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002172
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Temp out of serv	Install. Date:	65/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	84/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		
Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00005970
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

1356

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003330
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO 4000 DUPONT CIR LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003330
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

1358

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DEVOE & RAYNOLDS PAINT CO (Continued)

S101638055

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003330
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

Facility ID:	299102845	Facility Type:	Other
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	MACHADO, ARMANDO & CLARK, JIM		
Facility Phone:	8132473161	Permit Section:	Not reported
Date entered:	910923	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	TOM WEHRENBURG		
Owner:	DEVOE & RAYNOLDS CO		
	4000 DUPONT CIR		
	LOUISVILLE, KY 40207		
Owner's Phone:	5028979861	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003330
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	61/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Bulk product piping		
Petro. Monitoring:	Auto tank gauging		

138

DEVOE & RAYNOLDS COMPANY AKA GROW GROUP  
1010-26 NORTH 19TH STREET  
TAMPA, FL

FI Sites

S100888976  
N/A

# MAP FINDINGS

Map ID			
Direction			
Distance	Site	Database(s)	EDR ID Number EPA ID Number

## DEVOE & RAYNOLDS COMPANY AKA GROW GROUP (Continued)

S100888976

### FL Sites:

Facility ID:	000451	EPA ID:	FLD130010176
Facility District:	SOUTHWEST	Monthly Update:	January
Lead Unit:	DIST	Support Unit	Not reported
Air Contam	Not reported	Soil Contam:	Not reported
Surface Water Contam:	Confirmed	Ground Water Contam:	Confirmed
Cleanup Started ?:	No	Cleanup Completed ?:	No
Deletion Recommended ?:	No	Other:	Not reported
Warning Letter Status:	Not reported	Notice of Violation Status:	No
Consent Order Status:	No	Admin Hearing Status:	No
Court Status:	No	Final Order Status:	No

Comments: NEW SITE 9-86. PRIOR TO 1984 PAINT MANUFACTURING WASHWATERS WERE DISCHARGED TO HOLDING POND. EPA SAMPLED SLUDGE IN POND 12-84, SLUDGE NOT EP TOXIC. PCAR SUBMITTED 11-85 SHOWED VOC AND METAL CONTAMINATION. CONTAMINATION ASSESSMENT PLAN (CAP) SUBMITTED 4-86. COMMENTS FORWARDED TO RESPONDENT 9-86. REVISIONS SUBMITTED 1-87. CAP APPROVED 3-87. DRAFT CONSENT ORDER FORWARDED TO RESPONDENT 8-87. CONTAMINATION ASSESSMENT REPORT SUBMITTED; REVIEW COMPLETED AND COMMENTS FORWARDED TO RESPONDENT. DISTRICT AWAITING RESPONSE 10-88.

138	DEVOE & RAYNOLDS CO 1010-26 NORTH 19TH STREET TAMPA, FL 33631	RCRIS-LQG	1000699154 FLD092715051
138	USE 299102845 1010-26 19TH ST TAMPA, FL	UST LUST	U001378085 N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

USE 299102845 (Continued)

U001378085

LUST:

Facility ID:	9103447	Facility Type:	TANKLESS FACILITY
Alias Name:	Not reported		
Telephone:	8132473161	Discovery Date:	11/06/85
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN	Est. Gallons Lost:	UNKNOWN
------------	---------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NOT PETROLEUM STORAGE SYSTEM
Incident Ineligible Description:	NOT PETROLEUM S

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

1350

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

USE 299102845 (Continued)

U001378085

UST:

Facility ID:	299103447	Facility Type:	Tankless facility
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JONES HENRY		
Contact:	Not reported	Facility Phone:	8132473161
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	911120	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	HENRY JONES		
Owner:	GROW GROUP INC		
	4000 DUPONT CIRCLE		
	LOUISVILLE, KY 40207		
Owner's Phone:	8132473161	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Yes
Tank Cap. (Gals):	Not reported	Any monit. wells:	1
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

138

DEVOE AND RAYNOLDS CO.,INC.  
1010 NORTH 19TH STREET  
TAMPA, FL 33622

CERCLIS

1000332265  
FLD092715051

CERCLIS Classification Data:

Site Incident Category:	Not reported	Federal Facility:	NO
Ownership Status:	OTHER	NPL Status:	NOT ON NPL
EPA Notes:	Not reported		

CERCLIS Assessment History:

Assessment:	DISCOVERY	Completed:	01/23/1987
Assessment:	PRELIMINARY ASSESSMENT	Completed:	06/30/1987
Assessment:	SCREENING SITE INSPECTION	Completed:	01/25/1991

CERCLIS Site Status:

EPA has conducted a preliminary assessment on this site and has determined that no further action is necessary and no hazard was identified

CERCLIS Alias Name(s):

DEVOE AND RAYNOLDS CO.,INC.

139

5100 ACLINE  
TAMPA, FL

HMIRS

91040253  
N/A

139



# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
139	5100 ACLINE TAMPA, FL	HMIRS	92070571 N/A
139	5100 ACLINE DR. TAMPA, FL	HMIRS	92120516 N/A
139	5100 ACLINE DR TAMPA, FL	HMIRS	92090246 N/A
139	UNITED PARCEL SERVICE 5101 ACLINE TAMPA, FL 33619	FINDS	1000736549 FLD984187195
139	5100 ACLINE DR. TAMPA, FL	HMIRS	92120513 N/A
139	5100 ACLINE DRIVE TAMPA, FL	HMIRS	92090965 N/A
139	5100 ACLINE DR TAMPA, FL	HMIRS	92090729 N/A
139	5100 ACLINE DR TAMPA, FL	HMIRS	92090245 N/A
139	UNITED PARCEL SERVICE 5100 ACLINE ST TAMPA, FL 33619	UST LUST	U001058711 N/A

139

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNITED PARCEL SERVICE (Continued)

U001058711

### LUST:

Facility ID:	8629920	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132411028	Discovery Date:	12/22/93
Tracking Number:	Not reported	Score:	034
Facility Code:	Not reported	Status:	Not reported
Rank:	03633		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

### CLOSURE REPORT

Not reported

Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

PETRO. LIABILITY INS. & RESTOR.

REIMBURSEMENT CLEANUP

PARTIAL

OTHER

OTHER

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

INCOMPLETE

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

NO FURTHER ACTION

STATE

12/29/93

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNITED PARCEL SERVICE (Continued)

U001058711

### UST:

Facility ID:	298629920	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DON HARTIG		
Contact:	Not reported	Facility Phone:	8132411028
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861208	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DISTRICT PLANT ENGINEERING MGR		
Owner:	UNITED PARCEL SERVICE % MAINT		
	PO BOX 593803		
	ORLANDO, FL 328593803		
Owner's Phone:	4078268014	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	85/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matt, Pressurized piping, Dispenser liners		
Petro. Monitoring:	DW piping space, Auto tank gauging		

1739

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNITED PARCEL SERVICE (Continued)

U001058711

Facility ID:	298629920	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DON HARTIG		
Contact:	Not reported	Facility Phone:	8132411028
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861208	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DISTRICT PLANT ENGINEERING MGR		
Owner:	UNITED PARCEL SERVICE % MAINT PO BOX 593803 ORLANDO, FL 328593803		
Owner's Phone:	4078268014	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	85/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	DW piping space, Auto tank gauging		

1359

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNITED PARCEL SERVICE (Continued)

U001058711

Facility ID:	298629920	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DON HARTIG		
Contact:	Not reported	Facility Phone:	8132411028
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861208	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DISTRICT PLANT ENGINEERING MGR		
Owner:	UNITED PARCEL SERVICE % MAINT PO BOX 593803 ORLANDO, FL 328593803		
Owner's Phone:	4078268014	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	85/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/08
RPT Tank #:	Not reported	RPT by Tank #:	3R
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

139

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNITED PARCEL SERVICE (Continued)

U001058711

Facility ID:	298629920	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DON HARTIG		
Contact:	Not reported	Facility Phone:	8132411028
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861208	Financial responsibility:	Not reported
Tank ID:	3R	District:	Southwest
Owner's Contact:	DISTRICT PLANT ENGINEERING MGR		
Owner:	UNITED PARCEL SERVICE % MAINT		
	PO BOX 593803		
	ORLANDO, FL 328593803		
Owner's Phone:	4078268014	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	93/08
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	3	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Dbl walled=primary matl, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	DW piping space, Auto tank gauging, Aprvd alt sys		

139

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNITED PARCEL SERVICE (Continued)

U001058711

Facility ID:	298629920	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DON HARTIG		
Contact:	Not reported	Facility Phone:	8132411028
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861208	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DISTRICT PLANT ENGINEERING MGR		
Owner:	UNITED PARCEL SERVICE % MAINT PO BOX 593803 ORLANDO, FL 328593803		
Owner's Phone:	4078268014	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	85/10
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

1359

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNITED PARCEL SERVICE (Continued)

U001058711

Facility ID:	298629920	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DON HARTIG		
Contact:	Not reported	Facility Phone:	8132411028
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861208	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	DISTRICT PLANT ENGINEERING MGR		
Owner:	UNITED PARCEL SERVICE % MAINT		
	PO BOX 593803		
	ORLANDO, FL 328593803		
Owner's Phone:	4078268014	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	85/10
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

140

FL DEPT OF TRANSPORTATION CROSSTOWN EX  
39TH ST WESTBOUND ENTRY RAMP  
TAMPA, FL

UST  
LUST

U001963248  
N/A

1740



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL DEPT OF TRANSPORTATION CROSSTOWN EX (Continued)

U001963248

### LUST:

Facility ID:	9401655	Facility Type:	STATE GOVERNMENT
Alias Name:	FL DEPT OF TRANSPORTATION CROSSTOWN EX		
Alias Name 2:	FL DEPT OF TRANSPORTATION CROSSTOWN EX		
Alias Name 3:	FL DEPT OF TRANSPORTATION CROSSTOWN EX		
Alias Name 4:	FL DEPT OF TRANSPORTATION CROSSTOWN EX		
Telephone:	8139756585	Discovery Date:	09/01/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NO C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	DIESEL-EMERG GENE	Est. Gallons Lost:	00000025
------------	-------------------	--------------------	----------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	N
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

140

**MAP FINDINGS**

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**FL DEPT OF TRANSPORTATION CROSSTOWN EX (Continued)**

U001963248

**UST:**

Facility ID:	299401655	Facility Type:	State Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	KARL D FLEMING		
Contact:	Not reported	Facility Phone:	8139756585
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940830	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	NONE	District:	Southwest
Owner's Contact:	CHARLES W GILLIARD		
Owner:	FL DEPT OF TRANSPORTATION TAMPA 3350 W BUSCH BLVD #120 TAMPA, FL 33618		
Owner's Phone:	8139716585	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	No
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

141

**PRODUCTION BLAST  
610 HARBOR STREET  
TAMPA, FL 33605**

**FINDS** 1000501413  
**RCRIS-LQG** FLD984215418

**RCRIS:**

Owner: DANA NEER  
(813) 225-1136

Contact: DANA NEER  
(813) 225-1136

Waste	Quantity	Info Source	Waste	Quantity	Info Source
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

There are 1 compliance/violation record(s) reported at this site:

Evaluation	Date	Violations
COMPLIANCE EVALUATION INSPECTION (CEI)	17-MAY-93	YES

141

**SCAGLIONE PROPERTY-ESTUARY SUBDIVISION  
704 N 13TH ST  
TAMPA, FL 33602**

**UST** U001355957  
**LUST** N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

### LUST:

Facility ID:	8942924	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8139682959	Discovery Date:	12/29/88
Tracking Number:	298097	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06571		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

### UST:

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE, ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE		
	7619 LAKE CYPRESS DR		
	ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE		
	7619 LAKE CYPRESS DR		
	ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE, ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE		
	7619 LAKE CYPRESS DR		
	ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE		
	7619 LAKE CYPRESS DR		
	ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

141

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE		
	7619 LAKE CYPRESS DR		
	ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

141



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE		
	7619 LAKE CYPRESS DR		
	ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE, ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE		
	7619 LAKE CYPRESS DR		
	ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

141

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE 7619 LAKE CYPRESS DR ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

142 DETSCO TERMINALS INC  
739 NORTH 14TH STREET  
TAMPA, FL 33601

RCRIS-SQG 1000698780  
FLD040214710

142 DETSCO TERMINALS INC  
739 N 14TH ST  
TAMPA, FL 33602

FINDS 1000733227  
UST FLD040214710  
LUST  
AST

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act

14/2

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

DETSO TERMINALS INC (Continued)

1000733227

LUST:

Facility ID:	8625085	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132291184	Discovery Date:	10/25/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

142

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DETSO TERMINALS INC (Continued)

1000733227

### UST:

Facility ID:	298625085	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DETSO TERMINALS, INC.		
Contact:	Not reported	Facility Phone:	8132291184
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	J.D. WILSON		
Owner:	DETSO TERMINALS INC		
	PO BOX 437		
	MULBERRY, FL 338600437		
Owner's Phone:	8132291184	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

### AST:

Facility ID:	298625085	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DETSO TERMINALS, INC.		
Facility Phone:	8132291184	Permit Section:	Not reported
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	J.D. WILSON		
Owner:	DETSO TERMINALS INC		
	PO BOX 437		
	MULBERRY, FL 338600437		
Owner's Phone:	8132291184	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001500
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	91/08	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

142

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
143	<b>SOUTHEASTERN BOLT &amp; SCREW</b> 815 N 26TH ST TAMPA, FL 33605	UST	U001354907 N/A
	UST: Facility ID: 298625702 Is fac. regulated: Not regulated facility Operator: SOUTHEASTERN BOLT & SCREW Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860523 Tank ID: 1 Owner's Contact: MIKE SILCOTT Owner: J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439 Owner's Phone: 8132287776 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00001000 Tank position: Underground Tank Content: Leaded gas Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Eligibility: Not reported Permit Number: Not reported Class: Not reported Category: Not reported Tank Constr.: Bare/asph steel Tank Piping: Unprotec metal Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132473411 Region: STATE Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: 74/11 Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported Eligible Date: Not reported	
144	<b>TDSI BIDS TAMPA</b> 504 N 34TH ST TAMPA, FL 33675	FINDS	1000740043 FLD984253534
144	<b>TDSI BIDS TAMPA</b> 504 N 34TH ST TAMPA, FL 33675	RCRIS-SQG	1000822327 FLD984253534
145	<b>WILLIAMS TELECOMMUNICATIONS GROUP</b> 1103 N 22ND ST TAMPA, FL 33605	UST	U001355304 N/A

145

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WILLIAMS TELECOMMUNICATIONS GROUP (Continued)

U001355304

### UST:

Facility ID:	298627972	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MILLER, JACK		
Contact:	Not reported	Facility Phone:	8132482862
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM RUPINSKI		
Owner:	WILLIAMS TELECOMMUNICATION GROUP		
	PO BOX 21348		
	TULSA, OK 741211348		
Owner's Phone:	9185885610	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	84/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Suction piping		
Petro. Monitoring:	Not required, Auto tank gauging		

145

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**WILLIAMS TELECOMMUNICATIONS GROUP (Continued)**

**U001355304**

Facility ID:	298627972	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MILLER, JACK		
Contact:	Not reported	Facility Phone:	8132482862
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JIM RUPINSKI		
Owner:	WILLIAMS TELECOMMUNICATION GROUP		
	PO BOX 21348		
	TULSA, OK 741211348		
Owner's Phone:	9185885610	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	89/04
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Dbl walled=primary matl		
Tank Piping:	Dblwall=primary matl, Suction piping		
Petro. Monitoring:	Man sample wells, DW tank space, Not required, DW piping space, Auto tank gauging		

145

**TAMPA INTERNATIONAL CENTER**  
1103 N 22ND ST  
TAMPA, FL 33605

UST  
LUST

U001356097  
N/A

145



MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

TAMPA INTERNATIONAL CENTER (Continued)

U001356097

LUST:

Facility ID:	9045667	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	01/24/90
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant: DIESEL FUEL

Est. Gallons Lost: UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

RESPONSIBLE PARTY-NO CLAIM

STATE CLEANUP

Not reported

Not Reported

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

INCOMPLETE

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

NO FURTHER ACTION

STATE

145

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INTERNATIONAL CENTER (Continued)

U001356097

### UST:

Facility ID:	299045667	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NATIONAL PROPERTY ADVISORS CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900119	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MICHAEL GROVER		
Owner:	NATIONAL LIFE INSURANCE CO		
	100 GALLERIA PKWY #1620		
	ATLANTA, GA 303395948		
Owner's Phone:	4049889008	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

TAMPA INTERNATIONAL CENTER (Continued)

U001356097

Facility ID:	299045667	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NATIONAL PROPERTY ADVISORS CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900119	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MICHAEL GROVER		
Owner:	NATIONAL LIFE INSURANCE CO		
	100 GALLERIA PKWY #1620		
	ATLANTA, GA 303395948		
Owner's Phone:	4049889008	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

145

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA INTERNATIONAL CENTER (Continued)

U001356097

Facility ID:	299045667	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NATIONAL PROPERTY ADVISORS CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900119	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MICHAEL GROVER		
Owner:	NATIONAL LIFE INSURANCE CO		
	100 GALLERIA PKWY #1620		
	ATLANTA, GA 303395948		
Owner's Phone:	4049889008	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

146

TAMPA ELECTRIC CO.-CASS ST  
1214 E CASS ST  
TAMPA, FL 33602

UST  
LUST

U001355722  
N/A

146

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA ELECTRIC CO.-CASS ST (Continued)

U001355722

### LUST:

Facility ID:	8837435	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132284111	Discovery Date:	07/15/90
Tracking Number:	Not reported	Score:	042
Facility Code:	Not reported	Status:	Not reported
Rank:	02299		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS

Est. Gallons Lost: 00001575

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

PETRO. LIABILITY INS. & RESTOR.

REIMBURSEMENT CLEANUP

ELIGIBLE

Not Reported

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: STATE

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

INCOMPLETE

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

RESPONSIBLE PARTY

REMEDIAL ACTION PLAN

GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

RESPONSIBLE PARTY

00

00

QUARTERLY

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

SITE REHABILITATION COMPLETION REPORT

STATE

146

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA ELECTRIC CO.-CASS ST (Continued)

U001355722

### UST:

Facility ID:	298837435	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA ELECTRIC CO.		
Contact:	Not reported	Facility Phone:	8132284111
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880112..	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BILL GOINS		
Owner:	TAMPA ELECTRIC CO		
	PO BOX 111 % ENVIR PLANNING		
	TAMPA, FL 336010111		
Owner's Phone:	8132281111	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	88/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Dbl walled=primary matl, Spill cnmt		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping		
Petro. Monitoring:	DW tank space, DW piping space		

147

THORNTON LABORATORIES INC  
1145 E CASS  
TAMPA, FL 33602

RCRIS-SQG  
FINDS

1000365501  
FLD045000346

148

HENDERSON PROPERTY  
1111 E CASS ST  
TAMPA, FL 33602

UST  
LUST

U001823417  
N/A

148

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HENDERSON PROPERTY (Continued)

U001823417

### LUST:

Facility ID:	9400587	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132287551	Discovery Date:	04/13/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HENDERSON PROPERTY (Continued)

U001823417

### UST:

Facility ID:	299400587	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BETTY HENDERSON		
Contact:	Not reported	Facility Phone:	8132287551
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940407	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BETTY HENDERSON		
Owner:	HENDERSON, BETTY		
	3704 LEONA ST		
	TAMPA, FL 33629		
Owner's Phone:	8132287551	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

1406



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HENDERSON PROPERTY (Continued)

U001823417

Facility ID:	299400587	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BETTY HENDERSON		
Contact:	Not reported	Facility Phone:	8132287551
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940407	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BETTY HENDERSON		
Owner:	HENDERSON, BETTY		
	3704 LEONA ST		
	TAMPA, FL 33629		
Owner's Phone:	8132287551	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

14/06

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HENDERSON PROPERTY (Continued)

U001823417

Facility ID:	299400587	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BETTY HENDERSON		
Contact:	Not reported	Facility Phone:	8132287551
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940407	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BETTY HENDERSON		
Owner:	HENDERSON, BETTY		
	3704 LEONA ST		
	TAMPA, FL 33629		
Owner's Phone:	8132287551	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

149 AFFILIATED OF FLORIDA INC  
1102 N 28TH ST  
TAMPA, FL 33631

RCRIS-SQG  
FINDS 1000498457  
FLD982077984

149 AFFILIATED OF FL, INC.-J.H.WILLIAMS  
1102 N 28TH ST  
TAMPA, FL 33605

UST U001354686  
N/A

149

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

### UST:

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	8/1/11
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	67/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

1491

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	61/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

149

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	62/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

149

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	73/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

149

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	79/08
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

149

AFFILIATED OF FL,INC.  
1102 N 28TH ST  
TAMPA, FL 33605

AST

A100008880  
N/A

149



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AFFILIATED OF FL,INC. (Continued)

A100008880

### AST:

Facility ID:	298840679	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RAY BLACK		
Facility Phone:	8132485781	Permit Section:	Not reported
Date entered:	880601	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN TRIVENTO		
Owner:	AFFILIATED OF FL INC 1102 N 28TH ST TAMPA, FL 336316246		
Owner's Phone:	8132485781	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	88/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

Facility ID:	298840679	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RAY BLACK		
Facility Phone:	8132485781	Permit Section:	Not reported
Date entered:	880601	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN TRIVENTO		
Owner:	AFFILIATED OF FL INC 1102 N 28TH ST TAMPA, FL 336316246		
Owner's Phone:	8132485781	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	88/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

150

TAMPA,CITY-DPW FLEET MAINT DIV #1  
612 N 12TH ST  
TAMPA, FL 33607

UST  
LUST

U001354868  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

### LUST:

Facility ID:	8625662	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132238696	Discovery Date:	04/20/95
Tracking Number:	292525	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

Not reported

Incident 17-770 Cleanup:

Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

PETRO. LIABILITY INS. & RESTOR.

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Region:

STATE

150

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

### UST:

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dbllwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	10	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

150

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells		

150

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink, Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells		

150

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

150

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	6	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	7	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

150

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	8	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink, Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	9	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

150

TAMPA CITY-DPW STORE USE #298625662  
612 N 12TH ST  
TAMPA, FL 33602

UST

U001355537  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA CITY-DPW STORE USE #298625662 (Continued)

U001355537

### UST:

Facility ID:	298735278	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238013
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870922	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

150

**JOBBERS SUPPLY OF FLORIDA INC**  
**629 N 12TH ST**  
**TAMPA, FL 33602**

RCRIS-SQG  
FINDS

1000162651  
FLD982077190

### RCRIS:

Owner: JOHN WOLFE, SEC  
(813) 223-3288

Contact: JOHN WOLFE  
(813) 223-3288

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
F001	.00000 (T)	Notification	F002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

151

**CONNER PROPERTIES SERVICE STATION**  
**715 E CASS ST**  
**TAMPA, FL 33602**

UST

U001354408  
N/A

151

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONNER PROPERTIES SERVICE STATION (Continued)

U001354408

### UST:

Facility ID:	298625171	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLIAM G. FURNEY		
Owner:	ARIDROME TIRE WAREHOUSE		
	P O BOX 2522		
	TAMPA, FL 33601		
Owner's Phone:	8132476458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

151

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONNER PROPERTIES SERVICE STATION (Continued)

U001354408

Facility ID:	298625171	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLIAM G. FURNEY		
Owner:	ARIDROME TIRE WAREHOUSE		
	P O BOX 2522		
	TAMPA, FL 33601		
Owner's Phone:	8132476458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

151

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONNER PROPERTIES SERVICE STATION (Continued)

U001354408

Facility ID:	298625171	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLIAM G. FURNEY		
Owner:	ARIDROME TIRE WAREHOUSE		
	P O BOX 2522		
	TAMPA, FL 33601		
Owner's Phone:	8132476458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

151



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONNER PROPERTIES SERVICE STATION (Continued)

U001354408

Facility ID:	298625171	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	WILLIAM G. FURNEY		
Owner:	ARIDROME TIRE WAREHOUSE		
	P O BOX 2522		
	TAMPA, FL 33601		
Owner's Phone:	8132476458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000250	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Kerosene	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

151

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CONNER PROPERTIES SERVICE STATION (Continued)

U001354408

Facility ID:	298625171	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	WILLIAM G. FURNEY		
Owner:	ARIDROME TIRE WAREHOUSE		
	P O BOX 2522		
	TAMPA, FL 33601		
Owner's Phone:	8132476458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000250	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Kerosene	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	None		

151

CASS STREET INVESTORS SITE  
725 CASS ST  
TAMPA, FL 33602

RCRIS-SQG  
FINDS

1000375959  
FLD981866346

152

J H WILLIAMS OIL CO INC-MAIN BULK PLT  
1237 E TWIGGS ST  
TAMPA, FL 33602

LUST  
AST

S101264745  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

J H WILLIAMS OIL CO INC-MAIN BULK PLT (Continued)

S101264745

## LUST:

Facility ID:	8736356	Facility Type:	INLAND BULK PETROLEUM
Alias Name:	Not reported		
Telephone:	8132287776	Discovery Date:	04/20/92
Tracking Number:	297429	Score:	105 (HIGH)
Facility Code:	Not reported	Status:	Not reported
Rank:	00014		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	KEROSENE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN

## INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	CONTAMINATION ASSESSMENT REPORT
Extension Status:	APPROVED
Extension Comments:	LIMITED CAR

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	REC DRAW
Report Comments:	PHASE 1 - VAPORS

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

152

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## J H WILLIAMS OIL CO INC-MAIN BULK PLT (Continued)

S101264745

### AST:

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	Not reported
Date entered:	871123	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00020000
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	Not reported
Date entered:	871123	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00020000
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## J H WILLIAMS OIL CO INC-MAIN BULK PLT (Continued)

S101264745

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	Not reported
Date entered:	871123	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00018000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	Not reported
Date entered:	871123	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00018000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## J H WILLIAMS OIL CO INC-MAIN BULK PLT (Continued)

S101264745

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	Not reported
Date entered:	871123	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00018000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	Not reported
Date entered:	871123	Financial responsibility:	None
Tank ID:	6	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00018000
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

152

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## J H WILLIAMS OIL CO INC-MAIN BULK PLT (Continued)

S101264745

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	Not reported
Date entered:	871123	Financial responsibility:	None
Tank ID:	7	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00018000
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	Not reported
Date entered:	871123	Financial responsibility:	None
Tank ID:	8	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00018000
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

153

SEABOARD PARTS DISTRIBUTOR  
1105 E TWIGGS  
TAMPA, FL 33602

RCRIS-SQG 1000821872  
FINDS FLD984248906

153

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

SEABOARD PARTS DISTRIBUTOR (Continued)

1000821872

RCRIS:

Owner: DOROTHY SLAIMAN, OWNER  
(813) 221-5566

Contact: DOROTHY SLAIMAN  
(813) 221-5566

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D006	.00000 (T)	Notification	D007	.00000 (T)	Notification
D008	.00000 (T)	Notification	D018	.00000 (T)	Notification
D039	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

153

TYRESOLER OF TAMPA, INC.  
1127 E TWIGGS ST  
TAMPA, FL 33602

UST

U001355328  
N/A

UST:

Facility ID:	298628060	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	W. L. GRIFFIN		
Contact:	Not reported	Facility Phone:	8132298444
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	W. L. GRIFFIN		
Owner:	TYRESOLER OF TAMPA, INC. 1127 E TWIGGS ST TAMPA, FL 336023135		
Owner's Phone:	8132298444	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	69/02
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

153

LIVINGSTONS BUSINESS FURNITURE CENTER  
1123 E TWIGGS ST  
TAMPA, FL 33602

UST  
LUST

U001354621  
N/A

153



## MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## LIVINGSTONS BUSINESS FURNITURE CENTER (Continued)

U001354621

## LUST:

Facility ID:	8625401	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	12/20/90
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05554		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN

## INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

153

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## LIVINGSTONS BUSINESS FURNITURE CENTER (Continued)

U001354621

### UST:

Facility ID:	298625401	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LIVINGSTONS BUSINESS FURNITURE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860519	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ARTHUR STUCKEY		
Owner:	STUCKEY, ARTHUR		
	420 MONTROSE AVE		
	TEMPLE TERRACE, FL 336174238		
Owner's Phone:	8139855764	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## LIVINGSTONS BUSINESS FURNITURE CENTER (Continued)

U001354621

Facility ID:	298625401	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LIVINGSTONS BUSINESS FURNITURE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860519	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ARTHUR STUCKEY		
Owner:	STUCKEY, ARTHUR		
	420 MONTROSE AVE		
	TEMPLE TERRACE, FL 336174238		
Owner's Phone:	8139855764	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

154

AIR DROME TIRE  
612 E CASS ST  
TAMPA, FL 33602

UST

U001354064  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## AIR DROME TIRE (Continued)

U001354064

### UST:

Facility ID:	298624801	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AIR DROME TIRE		
Contact:	Not reported	Facility Phone:	8132290631
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	64/06
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

155 RINALDI PRINTING COMPANY  
4514 ADAMO DRIVE  
TAMPA, FL 33605

RCRIS-SQG  
FINDS 1000148774  
FLD004093928

155 DAVIES CAN COMPANY  
4502 ADAMO DR  
TAMPA, FL 33605

RCRIS-SQG  
FINDS 1000249478  
FLD984169938

### RCRIS:

Owner: FOLDESI SEBASTIAN  
(813) 248-6291

Contact: FOLDESI SEBASTIAN  
(813) 248-6291

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

156 SUN BANK PROPERTY  
605 N 19TH ST  
TAMPA, FL 33605

UST  
LUST U001354360  
N/A

156

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUN BANK PROPERTY (Continued)

U001354360

### LUST:

Facility ID:	8625122	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132482151	Discovery Date:	08/02/89
Tracking Number:	Not reported	Score:	081 (HIGH)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	OTHER
Incident Ineligible Description:	OTHER

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

156

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUN BANK PROPERTY (Continued)

U001354360

### UST:

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA 315 E MADISON TAMPA, FL 33602		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-sac anode		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

156

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUN BANK PROPERTY (Continued)

U001354360

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA		
	315 E MADISON		
	TAMPA, FL 33602		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-sac anode		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

156

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUN BANK PROPERTY (Continued)

U001354360

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA		
	315 E MADISON		
	TAMPA, FL 33602		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-sac anode		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

156



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUN BANK PROPERTY (Continued)

U001354360

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA		
	315 E MADISON		
	TAMPA, FL 33602		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-sac anode		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUN BANK PROPERTY (Continued)

U001354360

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA		
	315 E MADISON		
	TAMPA, FL 33602		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-sac anode		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

156

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUN BANK PROPERTY (Continued)

U001354360

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA		
	315 E MADISON		
	TAMPA, FL 33602		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

157

## SWIFT ADHESIVES & COATINGS

FI Sites

S100889047

605 N. 26 ST.

N/A

TAMPA, FL 33605

### FL Sites:

Facility ID:	000386	EPA ID:	FLD064687577
Facility District:	SOUTHWEST	Monthly Update:	February
Lead Unit:	Not reported	Support Unit:	3012
Air Contam:	Not reported	Soil Contam:	Not reported
Surface Water Contam:	Not reported	Ground Water Contam:	Not reported
Cleanup Started ?:	No	Cleanup Completed ?:	No
Deletion Recommended ?:	No	Other:	Not reported
Warning Letter Status:	Not reported	Notice of Violation Status:	No
Consent Order Status:	No	Admin Hearing Status:	No
Court Status:	No	Final Order Status:	No
Comments:	EPA PRELIMINARY ASSESSMENT COMPLETED 11-82. EPA/CERCLA SITE SCREENING CATEGORIZATION REVIEW COMPLETED 11/87 RESULTED IN A MEDIUM PRIORITY DETERMINATION FOR SITE SCREENING INVESTIGATION. EPA/FDER INVESTIGATION TO BE SCHEDULED ON A PRIORITY BASIS.		

157

## SWIFT ADHESIVES AND COATINGS

605 N 26TH ST

TAMPA, FL 33605

RCRIS-SQG  
FINDS  
CERC-NFRAP  
UST

1000230730  
FLD064687577

157

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SWIFT ADHESIVES AND COATINGS (Continued)

1000230730

### CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported

Ownership Status: OTHER

EPA Notes: Not reported

Federal Facility: NO

NPL Status: NOT ON NPL

### CERCLIS-NFRAP Assessment History:

Assessment: PRELIMINARY ASSESSMENT

Completed: 11/01/82

Assessment: DISCOVERY

Completed: 08/01/80

Assessment: SCREENING SITE INSPECTION

Completed: 01/25/91

### CERCLIS-NFRAP Alias Name(s):

SWIFT ADHESIVES & COATINGS

### UST:

Facility ID: 298944024

Facility Type:

Non-retail Business

Is fac. regulated: Not regulated facility

Is facility open:

Closed

Operator: SWIFT ADHESIVES

Contact: Not reported

Facility Phone:

Not reported

Permit Section: Not reported

Region:

STATE

Facility Code: No violation

Date entered: 890503

Financial responsibility:

Not reported

Tank ID: 1

District:

Southwest

Owner's Contact: JOHN W KNAUB

Owner: REICHHOLD

3100 WOODCREEK DR

DOWNERS GROVE, IL 605155424

Owner's Phone: 3129607254

Tracking #:

Not reported

Cleanup Status: Not reported

Any contaminated soil:

Not reported

Drink. Wat. Well: Not reported

Any contaminated surface water:

Not reported

Tank Cap. (Gals): 00001500

Any monit. wells:

Not reported

Tank position: Underground

Any contam. groundwater:

Not reported

Tank Content: Fuel oil-on site heat

Contaminated media indicator:

No

Disposal Method: Removed

Instal. Date:

58/XX

Is tank regulated: Not regulated tank

Content Category:

Pollutant

Facility Status: Not reported

Last used Date:

85/XX

RPT Tank #: Not reported

RPT by Tank #:

Not reported

Eligibility: Not reported

Eligible Date:

Not reported

Permit Number: Not reported

Class: Not reported

Category: Not reported

Tank Constr.: Unknown/not reported

Tank Piping: Unknown/not reported

Petro. Monitoring: Unknown/not reported

158

GORMAN CO OF TAMPA INC  
4910 ADAMO DR  
TAMPA, FL 33605

UST  
LUST

U001355211  
N/A

158

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GORMAN CO OF TAMPA INC (Continued)

U001355211

### LUST:

Facility ID:	8627442	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132476681	Discovery Date:	12/07/89
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: LEADED GAS

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

PETRO. LIABILITY INS. & RESTOR.

STATE CLEANUP

INELIGIBLE

NONCOMPLAINE 17-769 RULE

NONCOMPLIANCE 1

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal: Y

Soil Treatment:

Other Treatment:

Cleanup Responsible: RESPONSIBLE PARTY

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

APPROVED

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

NO FURTHER ACTION

STATE

158

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GORMAN CO OF TAMPA INC (Continued)

U001355211

### UST:

Facility ID:	298627442	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GORMAN CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132476681
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DONALD SLACK		
Owner:	GORMAN CO TAMPA		
	PO BOX 2939		
	TAMPA, FL 336012939		
Owner's Phone:	8132476681	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

158

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GORMAN CO OF TAMPA INC (Continued)

U001355211

Facility ID:	298627442	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GORMAN CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132476681
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DONALD SLACK		
Owner:	GORMAN CO TAMPA PO BOX 2939 TAMPA, FL 336012939		
Owner's Phone:	8132476681	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

158	GORMAN CO DIV OF HAJOCA CORP 4910 ADAMO DR TAMPA, FL 33605	FINDS	1000932439 FL0000621714
159	GREATER TAMPA BAY AUTO AUCTION 401 S 50TH ST TAMPA, FL 33675	FINDS	1000735422 FLD982135998
159	GREATER TAMPA BAY AUTO AUCTION 401 S 50TH ST TAMPA, FL 33675	RCRIS-SQG AST	1000700631 FLD982135998

RCRIS:  
Owner: CHARLES WHITE, MGR  
(813) 247-1666

Contact: CHARLES WHITE  
(813) 247-1666

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F003	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

159

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GREATER TAMPA BAY AUTO AUCTION (Continued)

1000700631

### AST:

Facility ID:	299046200	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TOM HAMMER		
Facility Phone:	8132471666	Permit Section:	Not reported
Date entered:	900413	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	TOM HAMMER		
Owner:	GREATER TAMPA BAY AUTO AUCTION		
	PO BOX 75325		
	TAMPA, FL 336750325		
Owner's Phone:	8132471666	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00001000
Tank Content:	Unleaded gas	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	90/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Dblwall=primary matl		
Petro. Monitoring:	Not required		

159

CHEVRON #48104  
602 N 50TH ST  
TAMPA, FL 33619

UST  
LUST

U001354578  
N/A

159



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEVRON #48104 (Continued)

U001354578

### LUST:

Facility ID:	8625358	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132472069	Discovery Date:	05/26/88
Tracking Number:	295242	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

159

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEVRON #48104 (Continued)

U001354578

### UST:

Facility ID:	298625358	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AMERICAN PERSONNEL SERV.		
Contact:	Not reported	Facility Phone:	8132472069
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	295242
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

159

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CHEVRON #48104 (Continued)

U001354578

Facility ID:	298625358	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AMERICAN PERSONNEL SERV.		
Contact:	Not reported	Facility Phone:	8132472069
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	295242
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

159

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CHEVRON #48104 (Continued)

U001354578

Facility ID:	298625358	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AMERICAN PERSONNEL SERV.		
Contact:	Not reported	Facility Phone:	8132472069
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	295242
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

159

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CHEVRON #48104 (Continued)

U001354578

Facility ID:	298625358	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AMERICAN PERSONNEL SERV.		
Contact:	Not reported	Facility Phone:	8132472069
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	7709843000	Tracking #:	295242
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

160

**MANTUA MANUFACTURING**  
6911 ADAMO DRIVE  
TAMPA, FL 33619

**FINDS**  
**UST**  
**LUST**

1000498856  
FLD984182303

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MANTUA MANUFACTURING (Continued)

1000498856

### LUST:

Facility ID:	8733894	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136213714	Discovery Date:	11/13/92
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	N
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MANTUA MANUFACTURING (Continued)

1000498856

### UST:

Facility ID:	298733894	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BOSLER, MIKE		
Contact:	Not reported	Facility Phone:	8136213714
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870730	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE BOSTER		
Owner:	WEINTRAUB, ED		
	6911 ADAMO DR		
	TAMPA, FL 33619		
Owner's Phone:	8136213714	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Misc. Petro-base product	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

160

MANTUA MFG CO  
6911 ADAMO DR  
TAMPA, FL 33619

RCRIS-SQG

1000701445  
FLD984182303

### RCRIS:

Owner: MICHAEL BOSLER, PLT MGR  
(813) 621-3714

Contact: Not reported

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D028	.00000 (T)	Notification	D029	.00000 (T)	Notification
F001	.00000 (T)	Notification	U076	.00000 (T)	Notification
U077	.00000 (T)	Notification	U078	.00000 (T)	Notification
U080	.00000 (T)	Notification	U226	.00000 (T)	Notification
U228	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

161

3 FLAGS  
6807 ADAMO DR  
TAMPA, FL 33619

RCRIS-SQG  
FINDS

1000201940  
FLD004113197

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

161

**CRAFT USED EQUIPMENT**  
**6805 ADAMO DR**  
**TAMPA, FL 33619**

UST  
LUST

U001354236  
N/A

## LUST:

Facility ID:	8624989	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136236064	Discovery Date:	03/04/91
Tracking Number:	Not reported	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06571		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

COMBINED C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant: LEADED GAS

Est. Gallons Lost: UNKNOWN

## INCIDENT PROGRAM INFORMATION -

Incident Program:

RESPONSIBLE PARTY-NO CLAIM

Incident Program Type:

Not reported

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Region:

STATE

161



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CRAFT USED EQUIPMENT (Continued)

U001354236

### UST:

Facility ID:	298624989	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CRAFT USED EQUIPMENT		
Contact:	Not reported	Facility Phone:	8136236064
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860507	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CARL BETZ		
Owner:	CRAFT USED EQUIPMENT		
	922 W BRANDON BLVD		
	BRANDON, FL 33511		
Owner's Phone:	8136261491	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

162

TAMPA TANK & WELDING, INC.  
5205 ADAMO DR  
TAMPA, FL 33619

AST

A100008717  
N/A

162

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA TANK & WELDING, INC. (Continued)

A100008717

### AST:

Facility ID:	298625564	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CAL REED		
Facility Phone:	8136232675	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HUBERT ALLEN		
Owner:	TAMPA TANK & WELDING INC		
	PO BOX 5062		
	TAMPA, FL 336753251		
Owner's Phone:	8136232675	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00001000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

Facility ID:	298625564	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CAL REED		
Facility Phone:	8136232675	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	HUBERT ALLEN		
Owner:	TAMPA TANK & WELDING INC		
	PO BOX 5062		
	TAMPA, FL 336753251		
Owner's Phone:	8136232675	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00001000
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

162

STUART DIESEL SERVICE  
6515 ADAMO DR  
TAMPA, FL 33619

RCRIS-SQG 1000156178  
FINDS FLD076785880  
UST  
LUST

162

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

STUART DIESEL SERVICE (Continued)

1000156178

LUST:

Facility ID:	8625307	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136231551	Discovery Date:	12/07/90
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE

162

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## STUART DIESEL SERVICE (Continued)

1000156178

### UST:

Facility ID:	298625307	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STUART DIESEL SERVICE,INC		
Contact:	Not reported	Facility Phone:	8136231551
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PAUL DAILEY		
Owner:	STUART DIESEL SERVICE,INC.		
	6515 ADAMO DR		
	TAMPA, FL 336193413		
Owner's Phone:	8136231551	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink, Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	8/2/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	9/1/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

163

SHELL STATION  
5100 ADAMO DR  
TAMPA, FL 33619

UST  
LUST

U001354326  
N/A

163

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SHELL STATION (Continued)

U001354326

### LUST:

Facility ID:	8625086	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132475040	Discovery Date:	01/20/92
Tracking Number:	Not reported	Score:	032
Facility Code:	Not reported	Status:	Not reported
Rank:	03819		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

163

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SHELL STATION (Continued)

U001354326

### UST:

Facility ID:	298625086	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAN ZOHAR		
Contact:	Not reported	Facility Phone:	8132475040
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009520	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SHELL STATION (Continued)

U001354326

Facility ID:	298625086	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAN ZOHAR		
Contact:	Not reported	Facility Phone:	8132475040
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO PO BOX 20427 TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009520	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

163

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SHELL STATION (Continued)

U001354326

Facility ID:	298625086	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAN ZOHAR		
Contact:	Not reported	Facility Phone:	8132475040
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN CARSON		
Owner:	SHELL OIL CO		
	PO BOX 20427		
	TAMPA, FL 33622		
Owner's Phone:	8132824153	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00009520	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Fiberglass, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

164

FRUEHAUF CORP  
6310 ADAMO DRIVE  
TAMPA, FL 33619

RCRIS-SQG 1000202754  
FINDS FLD004912481  
UST  
LUST

164



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

FRUEHAUF CORP (Continued)

1000202754

## LUST:

Facility ID:	8627349	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136214941	Discovery Date:	11/18/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
------------	-----------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FRUEHAUF CORP (Continued)

1000202754

### UST:

Facility ID:	298627349	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	FRUEHAUF CORP.		
Contact:	Not reported	Facility Phone:	8136214941
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861030	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RICHARD F. LYNEN		
Owner:	FRUEHAUF CORP TAMPA 3368 MORELAND AVE CONLEY, GA 300271114		
Owner's Phone:	8136214941	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	72/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

165

SCHMIDT & CO,HUGO  
6222 ADAMO DR  
TAMPA, FL 33619

UST

U001354006  
N/A

165

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SCHMIDT & CO,HUGO (Continued)

U001354006

### UST:

Facility ID:	298521256	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCHMIDT & CO,HUGO		
Contact:	Not reported	Facility Phone:	8136215821
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	851104	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

166 POPS PAINTING INC  
5205 ADAMO DRIVE  
TAMPA, FL 33619

FINDS

1000734917  
FLD982088007

167 SUN STATE INTERNATIONAL TRUCKS  
6020 ADAMO DR  
TAMPA, FL 33619

RCRIS-SQG  
FINDS  
UST  
LUST

1000132396  
FLD071730477

167

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUN STATE INTERNATIONAL TRUCKS (Continued)

1000132396

### LUST:

Facility ID:	9201308	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136211331	Discovery Date:	05/04/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NO C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	00000020
------------	--------------	--------------------	----------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

167

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUN STATE INTERNATIONAL TRUCKS (Continued)

1000132396

### UST:

Facility ID:	299201308	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HOEFFNER, ROBERT		
Contact:	Not reported	Facility Phone:	8136211331
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	920528	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT HOEFFNER		
Owner:	SUN STATE INTER TRUCKS INC		
	6020 ADAMO DR		
	TAMPA, FL 33619		
Owner's Phone:	8136211331	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SUN STATE INTERNATIONAL TRUCKS (Continued)

1000132396

Facility ID:	299201308	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HOEFFNER, ROBERT		
Contact:	Not reported	Facility Phone:	8136211331
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	920528	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ROBERT HOEFFNER		
Owner:	SUN STATE INTER TRUCKS INC		
	6020 ADAMO DR		
	TAMPA, FL 33619		
Owner's Phone:	8136211331	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

167

UNIFIRST CORP  
6010 E ADAMO DR  
TAMPA, FL 33619

RCRIS-SQG  
FINDS  
UST

1000229524  
FLD982101123

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNIFIRST CORP (Continued)

1000229524

### UST:

Facility ID:	298627405	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNIFIRST CORP.		
Contact:	Not reported	Facility Phone:	8136214741
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GARY E. AUGUSTIN		
Owner:	UNIFIRST CORP		
	15 OLYMPIA AVE		
	WOBURN, MA 018016307		
Owner's Phone:	6179335800	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00015000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	85/08
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

167

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNIFIRST CORP (Continued)

1000229524

Facility ID:	298627405	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNIFIRST CORP.		
Contact:	Not reported	Facility Phone:	8136214741
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GARY E AUGUSTIN		
Owner:	UNIFIRST CORP 15 OLYMPIA AVE WOBURN, MA 018016307		
Owner's Phone:	6179335800	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	85/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNIFIRST CORP (Continued)

1000229524

Facility ID:	298627405	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNIFIRST CORP.		
Contact:	Not reported	Facility Phone:	8136214741
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	GARY E AUGUSTIN		
Owner:	UNIFIRST CORP		
	15 OLYMPIA AVE		
	WOBURN, MA 018016307		
Owner's Phone:	6179335800	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Gasohol	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	85/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## UNIFIRST CORP (Continued)

1000229524

Facility ID:	298627405	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNIFIRST CORP.		
Contact:	Not reported	Facility Phone:	8136214741
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	GARY E. AUGUSTIN		
Owner:	UNIFIRST CORP 15 OLYMPIA AVE WOBURN, MA 018016307		
Owner's Phone:	6179335800	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	85/08
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

168

## PRIME EQUIPMENT #616 5907 E ADAMO DR TAMPA, FL 33619

RCRIS-SQG

1000859568  
FLD984260554

### RCRIS:

Owner: STEPHEN MILLER, DIR  
(713) 578-8600

Contact: STEPHEN MILLER  
(713) 578-8600

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D018	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

168

## PRIME EQUIPMENT #616 5907 E ADAMO DR TAMPA, FL 33619

FINDS  
UST  
LUST  
AST

1000843194  
FLD984260554

1656

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PRIME EQUIPMENT #616 (Continued)

1000843194

### LUST:

Facility ID:	8628829	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8134414555	Discovery Date:	03/11/91
Tracking Number:	295890	Score:	033
Facility Code:	Not reported	Status:	Not reported
Rank:	03711		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

168

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PRIME EQUIPMENT #616 (Continued)

1000843194

### UST:

Facility ID:	298628829	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PRIMECO INC		
Contact:	Not reported	Facility Phone:	8134414555
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM VILL		
Owner:	ALL AMERICAN EQUIP RENTAL		
	5907 E ADAMO DR		
	TAMPA, FL 33619		
Owner's Phone:	8136218696	Tracking #:	295890
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PRIME EQUIPMENT #616 (Continued)

1000843194

Facility ID:	298628829	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PRIMECO INC		
Contact:	Not reported	Facility Phone:	8134414555
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JIM VILL		
Owner:	ALL AMERICAN EQUIP RENTAL		
	5907 E ADAMO DR		
	TAMPA, FL 33619		
Owner's Phone:	8136218696	Tracking #:	295890
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PRIME EQUIPMENT #616 (Continued)

1000843194

Facility ID:	298628829	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PRIMECO INC		
Contact:	Not reported	Facility Phone:	8134414555
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JIM VILL		
Owner:	ALL AMERICAN EQUIP RENTAL		
	5907 E ADAMO DR		
	TAMPA, FL 33619		
Owner's Phone:	8136218696	Tracking #:	295890
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

1686

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PRIME EQUIPMENT #616 (Continued)

1000843194

Facility ID:	298628829	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PRIMECO INC		
Contact:	Not reported	Facility Phone:	8134414555
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	JIM VILL		
Owner:	ALL AMERICAN EQUIP RENTAL		
	5907 E ADAMO DR		
	TAMPA, FL 33619		
Owner's Phone:	8136218696	Tracking #:	295890
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

1456

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## PRIME EQUIPMENT #616 (Continued)

1000843194

Facility ID:	298628829	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PRIMECO INC		
Contact:	Not reported	Facility Phone:	8134414555
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JIM VILL		
Owner:	ALL AMERICAN EQUIP RENTAL		
	5907 E ADAMO DR		
	TAMPA, FL 33619		
Owner's Phone:	8136218696	Tracking #:	295890
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

### AST:

Facility ID:	298628829	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PRIMECO INC		
Facility Phone:	8134414555	Permit Section:	Not reported
Date entered:	861118	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JIM VILL		
Owner:	ALL AMERICAN EQUIP RENTAL		
	5907 E ADAMO DR		
	TAMPA, FL 33619		
Owner's Phone:	8136218696	Tracking #:	295890
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000560
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

169

HERTZ EQUIPMENT  
5725 ADAMO DR  
TAMPA, FL 33619

RCRIS-SQG 1000501720  
FINDS FLD984218537  
UST  
LUST



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HERTZ EQUIPMENT (Continued)

1000501720

RCRIS:

Owner: ADAMS DREW

Contact: ADAMS DREW

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D008	.00000 (T)	Notification	D018	.00000 (T)	Notification
D039	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

169

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

HERTZ EQUIPMENT (Continued)

1000501720

LUST:

Facility ID:	8627244	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	11/13/89
Tracking Number:	Not reported	Score:	035
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROLEUM STORAGE SYSTEM
Incident Ineligible Description:	NOT PETROLEUM S

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

169

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HERTZ EQUIPMENT (Continued)

1000501720

### UST:

Facility ID:	298627244	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HERTZ EQUIPMENT RENTAL CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PAUL WOODS		
Owner:	HERTZ CORP TAMPA		
	5725 ADAMO DR		
	TAMPA, FL 336193241		
Owner's Phone:	2129802276	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

169

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HERTZ EQUIPMENT (Continued)

1000501720

Facility ID:	298627244	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HERTZ EQUIPMENT RENTAL CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	PAUL WOODS		
Owner:	HERTZ CORP TAMPA 5725 ADAMO DR TAMPA, FL 336193241		
Owner's Phone:	2129802276	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

169

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HERTZ EQUIPMENT (Continued)

1000501720

Facility ID:	298627244	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HERTZ EQUIPMENT RENTAL CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	PAUL WOODS		
Owner:	HERTZ CORP TAMPA 5725 ADAMO DR TAMPA, FL 336193241		
Owner's Phone:	2129802276	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Diesel-gen/pump	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

169

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HERTZ EQUIPMENT (Continued)

1000501720

Facility ID:	298627244	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HERTZ EQUIPMENT RENTAL CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	PAUL WOODS		
Owner:	HERTZ CORP TAMPA		
	5725 ADAMO DR		
	TAMPA, FL 336193241		
Owner's Phone:	2129802276	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Diesel-gen/pump	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HERTZ EQUIPMENT (Continued)

1000501720

Facility ID:	298627244	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HERTZ EQUIPMENT RENTAL CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	PAUL WOODS		
Owner:	HERTZ CORP TAMPA 5725 ADAMO DR TAMPA, FL 336193241		
Owner's Phone:	2129802276	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HERTZ EQUIPMENT (Continued)

1000501720

Facility ID:	298627244	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HERTZ EQUIPMENT RENTAL CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	PAUL WOODS		
Owner:	HERTZ CORP TAMPA		
	5725 ADAMO DR		
	TAMPA, FL 336193241		
Owner's Phone:	2129802276	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping		
Petro. Monitoring:	Auto tank gauging		



# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## HERTZ EQUIPMENT (Continued)

1000501720

Facility ID:	298627244	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HERTZ EQUIPMENT RENTAL CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	PAUL WOODS		
Owner:	HERTZ CORP TAMPA 5725 ADAMO DR TAMPA, FL 336193241		
Owner's Phone:	2129802276	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt, Op-flow shut off		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping		
Petro. Monitoring:	Auto tank gauging		

170	5656 ADAMO DR. TAMPA, FL	ERNS	9004548 N/A
-----	-----------------------------	------	----------------

170	CSX TRANSPORTATION 5656 ADAMO DR TAMPA, FL 33619	UST LUST AST	U001356271 N/A
-----	--	--------------------	-------------------

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CSX TRANSPORTATION (Continued)

U001356271

### LUST:

Facility ID:	9101036	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8136646226	Discovery Date:	04/08/92
Tracking Number:	Not reported	Score:	029 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	04795		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: LOCOMOTIVE DIESEL

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION

REIMBURSEMENT CLEANUP

ELIGIBLE

Not Reported

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

APPROVED

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

DISTRICT OFFICE

REMEDIAL ACTION PLAN

MONITORING ONLY PLAN

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

RESPONSIBLE PARTY

00

00

QUARTERLY

QTR 1

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

NO FURTHER ACTION

STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CSX TRANSPORTATION (Continued)

U001356271

### UST:

Facility ID:	299101036	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MCGAHA, M R		
Contact:	Not reported	Facility Phone:	8136646226
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910322	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	K W RICHARDSON JR		
Owner:	CSX TRANSPORTATION INC J275		
	500 WATER ST		
	JACKSONVILLE, FL 32202		
Owner's Phone:	9043591986	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotac metal		
Petro. Monitoring:	Unknown/not reported		

### AST:

Facility ID:	299101036	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MCGAHA, M R		
Facility Phone:	8136646226	Permit Section:	Not reported
Date entered:	910322	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	K W RICHARDSON JR		
Owner:	CSX TRANSPORTATION INC J275		
	500 WATER ST		
	JACKSONVILLE, FL 32202		
Owner's Phone:	9043591986	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Completed	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00020000
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

171 CLEAN HARBORS OF KINGSTON INC  
5615 E ADAMO DR  
TAMPA, FL 33619

RCRIS-SQG  
FINDS

1000150458  
FLD982164220

RCRIS:

Owner: KAHLER BILL MANAGER  
(813) 622-8870

Contact: KAHLER BILL  
(813) 622-8870

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D002	.00000 (T)	Notification	F001	.00000 (T)	Notification
F002	.00000 (T)	Notification	F003	.00000 (T)	Notification
F004	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

172 CASTELLANO PROPERTY  
512 E CASS ST  
TAMPA, FL 33602

UST  
LUST

U001356301  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CASTELLANO PROPERTY (Continued)

U001356301

### LUST:

Facility ID:	9101375	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8139497776	Discovery Date:	02/26/91
Tracking Number:	Not reported	Score:	021 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05497		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

112

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CASTELLANO PROPERTY (Continued)

U001356301

### UST:

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

P 12

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unknown/not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	6	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000560	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

173

MOBIL DISTRIBUTION CENTER  
501 N 20TH ST  
TAMPA, FL 33605

UST  
LUST

U001354310  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL DISTRIBUTION CENTER (Continued)

U001354310

### LUST:

Facility ID:	8625069	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132473911	Discovery Date:	03/21/95
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

### DISCHARGE NOTIFICATION

Lead:

Not reported

Incident 17-770 Cleanup:

Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

PETRO. LIABILITY INS. & RESTOR.

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Region:

STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL DISTRIBUTION CENTER (Continued)

U001354310

### UST:

Facility ID:	298625069	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP.		
Contact:	Not reported	Facility Phone:	8132473911
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES A BLESSIN		
Owner:	MOBIL OIL CORP		
	1901 W CYPRESS CREEK RD #102		
	FT LAUDERDALE, FL 33309		
Owner's Phone:	3055630331	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MOBIL DISTRIBUTION CENTER (Continued)

U001354310

Facility ID:	298625069	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP.		
Contact:	Not reported	Facility Phone:	8132473911
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JAMES A BLESSIN		
Owner:	MOBIL OIL CORP		
	1901 W CYPRESS CREEK RD #102		
	FT LAUDERDALE, FL 33309		
Owner's Phone:	3055630331	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass, Spill cnmt		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

174

**BAY DRUM & STEEL INC**  
**1211 E MADISON ST**  
**TAMPA, FL 33605**

RCRIS-SQG  
FINDS

1000460754  
FLD984184309

RCRIS:

Owner: GARY BLAKE, OWNER  
(813) 247-1144

Contact: GARY BLAKE  
(813) 247-1144

Waste	Quantity	Info Source
-------	----------	-------------

D001	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

174

**FIVE STAR TOURS**  
**1211 E MADISON ST**  
**TAMPA, FL 33602**

UST  
LUST

U001355286  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FIVE STAR TOURS (Continued)

U001355286

### LUST:

Facility ID:	8627884	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132231912	Discovery Date:	01/18/90
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

1774

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FIVE STAR TOURS (Continued)

U001355286

### UST:

Facility ID:	298627884	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIVE STAR TOURS		
Contact:	Not reported	Facility Phone:	8132231912
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLIAM F LANG		
Owner:	LANG, WILLIAM F		
	3906 FONTAINEBLEAU DR		
	TAMPA, FL 33634		
Owner's Phone:	8132231912	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

174



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FIVE STAR TOURS (Continued)

U001355286

Facility ID:	298627884	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIVE STAR TOURS		
Contact:	Not reported	Facility Phone:	8132231912
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLIAM F LANG		
Owner:	LANG, WILLIAM F		
	3906 FONTAINEBLEAU DR		
	TAMPA, FL 33634		
Owner's Phone:	8132231912	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

174

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FIVE STAR TOURS (Continued)

U001355286

Facility ID:	298627884	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIVE STAR TOURS		
Contact:	Not reported	Facility Phone:	8132231912
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLIAM F LANG		
Owner:	LANG, WILLIAM F 3906 FONTAINEBLEAU DR TAMPA, FL 33634		
Owner's Phone:	8132231912	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FIVE STAR TOURS (Continued)

U001355286

Facility ID:	298627884	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIVE STAR TOURS		
Contact:	Not reported	Facility Phone:	8132231912
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	WILLIAM F LANG		
Owner:	LANG, WILLIAM F		
	3906 FONTAINEBLEAU DR		
	TAMPA, FL 33634		
Owner's Phone:	8132231912	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

175

**YALE TIRE & BATTERY SERVICE**  
1227 E MADISON ST  
TAMPA, FL 33602

RCRIS-SQG  
FINDS

1000502870  
FLD984230417

RCRIS:

Owner: ROBERT ARNOLD, OWNER  
(813) 229-0043

Contact: ROBERT ARNOLD  
(813) 229-0043

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

176

**SPARTAN OIL CO**  
2815 LONG ST  
TAMPA, FL 33605

UST  
LUST  
AST

U001353963  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

### LUST:

Facility ID:	8509056	Facility Type:	INLAND BULK PETROLEUM
Alias Name:	Not reported		
Telephone:	8132473417	Discovery Date:	10/21/92
Tracking Number:	Not reported	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	KEROSENE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	QTR 1

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

176

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

### UST:

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

176

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnrmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

176

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00020000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00025000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Int lined steel, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

### AST:

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	Not reported
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	10	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Small use tank		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, Man tank gauging		

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	Not reported
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	11	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Small use tank		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells, GW mon plan, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	Not reported
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00070000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-flow shut off, Field erected		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Fiberglass, Suction piping		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, Man tank gauging		

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	Not reported
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00070000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-flow shut off, Field erected		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Fiberglass, Suction piping		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	Not reported
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	9	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC		
	PO BOX 76359		
	TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Small use tank		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells, GW mon plan, Man tank gauging		

177

TAMPA,CITY-DPW FLEET MAINT. FIRE #1  
808 E ZACK ST  
TAMPA, FL 33602

UST

U001354377  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT. FIRE #1 (Continued)

U001354377

### UST:

Facility ID:	298625140	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAIN GUMMOE		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Suction piping		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT. FIRE #1 (Continued)

U001354377

Facility ID:	298625140	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAIN GUMMOE		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Suction piping		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-DPW FLEET MAINT. FIRE #1 (Continued)

U001354377

Facility ID:	298625140	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAIN GUMMOE		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Suction piping		
Petro. Monitoring:	Man sample wells		

178

GREYHOUND LINES INC  
610 E POLK ST  
TAMPA, FL 33602

UST

U001962937  
N/A



MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

GREYHOUND LINES INC (Continued)

U001962937

UST:

Facility ID:	299401206	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	8132292174
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940725	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	NONE	District:	Southwest
Owner's Contact:	VAN HARTNITT		
Owner:	GREYHOUND LINES INC		
	PO BOX 660362 % ENVIRONMENTAL		
	DALLAS, TX 752660362		
Owner's Phone:	2146984674	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

179

HILLSBORO CO FALKENBURG VALRICO WWTP  
925 E TWIGGS ST  
TAMPA, FL 33602

FINDS

1000498714  
FLD984170837

Other Pertinent Environmental Activity Identified at Site:  
facility has active water discharge permits

180

TAMPA CITY ADMINISTRATIVE SERVICES  
720 E ZACK ST  
TAMPA, FL 33602

UST

U001356048  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA CITY ADMINISTRATIVE SERVICES (Continued)

U001356048

### UST:

Facility ID:	298944858	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA CITY		
Contact:	Not reported	Facility Phone:	8132238892
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	890921	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JACK AMBROSE		
Owner:	TAMPA CITY ADMIN SERVICES		
	720 E ZACK ST		
	TAMPA, FL 336024002		
Owner's Phone:	8132238892	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

181

USGSA  
501 E POLK ST #600  
TAMPA, FL 33602

RCRIS-SQG 1000859199  
FL3470000008

### RCRIS:

Owner: JAMES BENNETT, FIELD OFF MGR  
(813) 228-2351

Contact: JAMES BENNETT  
(813) 228-2351

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D008	.00000 (T)	Notification	F001	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

181

US DEPT OF GENERAL SVCS-ADMIN BLDG  
501 E POLK ST  
TAMPA, FL 33602

UST

U001356228  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## US DEPT OF GENERAL SVCS-ADMIN BLDG (Continued)

U001356228

### UST:

Facility ID:	299100449	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BENNETT, JAMES F		
Contact:	Not reported	Facility Phone:	8132282351
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910220	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES F BENNETT		
Owner:	US DEPT OF GENERAL SERVICES		
	501 E POLK ST #600		
	TAMPA, FL 336023926		
Owner's Phone:	8132282351	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	88/08
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Auto tank gauging		

182

US COURTHOUSE  
801 N FLORIDA AVE  
TAMPA, FL 33602

UST

U002217718  
N/A

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## US COURTHOUSE (Continued)

U002217718

### UST:

Facility ID:	299501854	Facility Type:	Tankless facility
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	950510	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	KLOU MANCUSO		
Owner:	GENERAL SERVICES ADMINISTRATION		
	401 W PEACHTREE ST		
	ATLANTA, GA 303652550		
Owner's Phone:	4043313125	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

183	VENTO OIL CO 2004D DURHAM TAMPA, FL 33675	FINDS	1000737263 FLD984200113
183	N C J INVESTMENT CO INC 2004 DURHAM STREET TAMPA, FL 33605	FINDS	1000737265 FLD984200139
183	RADIANT OIL CO OF TAMPA INC 2004 DURHAM ST TAMPA, FL 33605	UST LUST AST	U001354762 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

### LUST:

Facility ID:	8625549	Facility Type:	TERMINAL FACILITY
Alias Name:	Not reported		
Telephone:	8132474731	Discovery Date:	10/13/86
Tracking Number:	290690	Score:	061
Facility Code:	Not reported	Status:	Not reported
Rank:	01178		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: NOT ENTERED

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Y	Alt. Process Date:	Not reported
Soil Treatment:	Y	Alternative Status:	Not reported
Other Treatment:	540 TONS INCINERATED		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	ANNUAL
Report Comments:	YR 1

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

### UST:

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

183

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	17	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Dblwall=primary matl, Suction piping		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Instal. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

### AST:

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	10	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	11	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003500
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	12	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	13	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	14	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

1463

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	15	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	16	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

183

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	18	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00105000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00025000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00105000
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	66/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

180



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	Not reported
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	9	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003500
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

184

AMERADA HESS  
402 N 22ND ST  
TAMPA, FL 33675

RCRIS-SQG

1000699140  
FLD088776588

184

AMERADA HESS  
402 N 22ND ST  
TAMPA, FL 33675

FINDS

1000733662  
FLD088776588

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act

185

GTE OF FL TAMPA EAX  
610 E ZACK ST  
TAMPA, FL 33602

UST

U001355398  
N/A

185

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GTE OF FL TAMPA EAX (Continued)

U001355398

### UST:

Facility ID:	298732443	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO. OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870415	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00020000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	75/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotect metal		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

GTE OF FL TAMPA EAX (Continued)

U001355398

Facility ID:	298732443	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO. OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870415	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00020000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	75/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

186

BP-METRO  
1239 E KENNEDY BLVD  
TAMPA, FL 33602

UST  
LUST

U001354186  
N/A

186

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BP-METRO (Continued)

U001354186

LUST:

Facility ID:	8624933	Facility Type:	RETAIL STATION
Alias Name:	PHILLIPS 66-METRO		
Telephone:	8136814279	Discovery Date:	11/30/88
Tracking Number:	294953	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
------------	-------------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

186

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BP-METRO (Continued)

U001354186

## UST:

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	7
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	Man sample wells		

186

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	8
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	Man sample wells		

186

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	Man sample wells		

166

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	Man sample wells		

186



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	93/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill, dbllwall=2nd material		
Tank Piping:	Fiberglass, Dbllwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	DW tank space, Piping/flow restrictor, DW piping space		

186

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U PO BOX 1110 BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00012000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	93/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	2	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Compartmented, Spill cnmt, Op-tight fill, dblwall=2nd material		
Tank Piping:	Fiberglass, Dblwall=primary matl, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space		

186

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	9	District:	Southwest
Owner's Contact:	JOHN KNIGHTLY		
Owner:	AUTOMATED PETROLEUM & ENERGY - U		
	PO BOX 1110		
	BRANDON, FL 33509		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

187

SEL MADURO FL,INC.  
401 N 13TH ST  
TAMPA, FL 33602

UST  
LUST

U001354648  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SEL MADURO FL,INC. (Continued)

U001354648

### LUST:

Facility ID:	8625429	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132234721	Discovery Date:	06/19/92
Tracking Number:	Not reported	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04494		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SEL MADURO FL,INC. (Continued)

U001354648

### UST:

Facility ID:	298625429	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEL MADURO FL,INC.		
Contact:	Not reported	Facility Phone:	8132234721
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	SAM ZAGARIA		
Owner:	GULF FL TERMINAL		
	PO BOX 2481		
	TAMPA, FL 336012481		
Owner's Phone:	8135763050	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

187

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SEL MADURO FL,INC. (Continued)

U001354648

Facility ID:	298625429	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEL MADURO FL,INC.		
Contact:	Not reported	Facility Phone:	8132234721
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	SAM ZAGARIA		
Owner:	GULF FL TERMINAL		
	PO BOX 2481		
	TAMPA, FL 336012481		
Owner's Phone:	8135763050	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

187

WARE DEVELOPMENTS  
KENNEDY BLVD & 13TH ST  
TAMPA, FL 33602

UST  
LUST

U001356178  
N/A

187



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WARE DEVELOPMENTS (Continued)

U001356178

### LUST:

Facility ID:	9063897	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132249624	Discovery Date:	04/03/90
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WARE DEVELOPMENTS (Continued)

U001356178

### UST:

Facility ID:	299063897	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WARE DEVELOPMENTS		
Contact:	Not reported	Facility Phone:	8132249624
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	901205	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	EARL H WARE		
Owner:	WARE DEVELOPMENTS		
	404 N 13TH ST #101		
	TAMPA, FL 336023610		
Owner's Phone:	8132249624	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000750	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	83/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

187

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WARE DEVELOPMENTS (Continued)

U001356178

Facility ID:	299063897	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WARE DEVELOPMENTS		
Contact:	Not reported	Facility Phone:	8132249624
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	901205	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	EARL H WARE		
Owner:	WARE DEVELOPMENTS		
	404 N 13TH ST #101		
	TAMPA, FL 336023610		
Owner's Phone:	8132249624	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000750	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	83/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

WARE DEVELOPMENTS (Continued)

U001356178

Facility ID:	299063897	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WARE DEVELOPMENTS		
Contact:	Not reported	Facility Phone:	8132249624
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	901205	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	EARL H WARE		
Owner:	WARE DEVELOPMENTS		
	404 N 13TH ST #101		
	TAMPA, FL 336023610		
Owner's Phone:	8132249624	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000750	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	83/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

188

HILLSBOROUGH CNTY HEALTH DEPT  
1105 E KENNEDY BLVD  
TAMPA, FL 33602

FINDS

1000497533  
FLD069672137

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

189

USE 298733857  
601 N MORGAN ST  
TAMPA, FL 33602

UST  
LUST

U001356128  
N/A

189

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

USE 298733857 (Continued)

U001356128

## LUST:

Facility ID:	9046057	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132290874	Discovery Date:	Not reported
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	Not reported
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	Not reported
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

USE 298733857 (Continued)

U001356128

## UST:

Facility ID:	299046057	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRANDOFF INVESTMENTS INC		
Contact:	Not reported	Facility Phone:	8132290874
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	900329	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	DEBBIE DEVOE		
Owner:	GRANDOFF INVESTMENTS INC		
	412 E MADISON ST #1100		
	TAMPA, FL 336024697		
Owner's Phone:	8132290874	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	1
Tank position:	Not reported	Any contam. groundwater:	Yes
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

189

KAUFFMAN TIRE SERVICE OF GA., INC.  
601 N MORGAN ST  
TAMPA, FL 33602

UST  
LUST

U001355480  
N/A

189

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KAUFFMAN TIRE SERVICE OF GA., INC. (Continued)

U001355480

### LUST:

Facility ID:	8733857	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132290874	Discovery Date:	12/08/89
Tracking Number:	Not reported	Score:	020 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05520		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: GENERIC GAS

Pollutant 2: WASTE OIL

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION

REIMBURSEMENT CLEANUP

PARTIAL

NOT PETROL/PETROL PRODUCT

NOT PETROL/PETR

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

INCOMPLETE

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

Not reported

STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KAUFFMAN TIRE SERVICE OF GA., INC. (Continued)

U001355480

### UST:

Facility ID:	298733857	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRANDOFF INVESTMENTS		
Contact:	Not reported	Facility Phone:	8132290874
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870730	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	MARTIN G TREMBLY		
Owner:	GOODYEAR TIRE & RUBBER CO		
	1144 E MARKET ST		
	AKRON, OH 443160001		
Owner's Phone:	2167961837	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/12
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

190

TAMPA ELEC CO  
702 N FRANKLIN ST  
TAMPA, FL 33602

FINDS

1000502104  
FLD984222547

191

GTE OF FL TAMPA MAIN  
615 N MARION ST  
TAMPA, FL 33601

AST

A100008755  
N/A

191



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GTE OF FL TAMPA MAIN (Continued)

A100008755

### AST:

Facility ID:	298630164	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO. OF FL.		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	861211	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	63/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

192

HILLSBOROUGH CNTY-FLEET MGMT #5  
311 N NEBRASKA AVE  
TAMPA, FL 33602

UST  
LUST

U001354206  
N/A

192

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-FLEET MGMT #5 (Continued)

U001354206

### LUST:

Facility ID:	8624955	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8136232485	Discovery Date:	12/19/88
Tracking Number:	294731	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NO C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-FLEET MGMT #5 (Continued)

U001354206

### UST:

Facility ID:	298624955	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HILLSBOROUGH CNTY-FLEET MGMT		
Contact:	Not reported	Facility Phone:	8136232485
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	294731
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

193

HILLSBOROUGH CNTY-HEALTH DEPT  
309 N BRUSH ST  
TAMPA, FL 33602

UST

U002313162  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY-HEALTH DEPT (Continued)

U002313162

### UST:

Facility ID:	298624952	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ED DANIELS		
Contact:	Not reported	Facility Phone:	8132726900
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005200	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	67/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

194

TAMPA ELECTRIC CO.-TECO PLAZA  
700 N TAMPA ST  
TAMPA, FL 33602

UST  
LUST

U001355397  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA ELECTRIC CO.-TECO PLAZA (Continued)

U001355397

### LUST:

Facility ID:	8732442	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132284111	Discovery Date:	11/01/86
Tracking Number:	293582	Score:	021 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05497		
Class:	Not reported		
Category:	Not reported		
INCIDENT GENERAL INFORMATION -			
Source Description:		EDI	
Lead:		LOCAL PROGRAM	
Incident 17-770 Cleanup:		NEW C/U REQUIRED	
INCIDENT POLLUTANT INFORMATION -			
Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
INCIDENT PROGRAM INFORMATION -			
Incident Program:		EARLY DETECTION INCENTIVE	
Incident Program Type:		REIMBURSEMENT CLEANUP	
Incident Eligible Status:		ELIGIBLE	
Incident Ineligible Reason:		Not Reported	
Incident Ineligible Description:		Not reported	
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:		Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:		RESPONSIBLE PARTY	
Response Record Type:		CONTAMINATION ASSESSMENT REPORT	
Response Remedial Action Plan Type:		Not reported	
Response Status:		INCOMPLETE	
Extension Record Type:		Not reported	
Extension Status:		Not reported	
Extension Comments:		Not reported	
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:		RESPONSIBLE PARTY	
Response Record Type:		REMEDIAL ACTION PLAN	
Response Remedial Action Plan Type:		RISK ASSESSMENT	
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:		Not reported	
Estimated Completion Year:		Not reported	
Actual Year to Complete:		Not reported	
Report Type:		Not reported	
Report Comments:		Not reported	
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:		Not reported	
Region:		STATE	

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA ELECTRIC CO.-TECO PLAZA (Continued)

U001355397

### UST:

Facility ID:	298732442	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA ELECTRIC CO		
Contact:	Not reported	Facility Phone:	8132284111
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870415	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BILL GOINS		
Owner:	TAMPA ELECTRIC CO		
	PO BOX 111 % ENVIR PLANNING		
	TAMPA, FL 336010111		
Owner's Phone:	8132281111	Tracking #:	293582
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

1741

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA ELECTRIC CO.-TECO PLAZA (Continued)

U001355397

Facility ID:	298732442	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA ELECTRIC CO		
Contact:	Not reported	Facility Phone:	8132284111
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870415	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BILL GOINS		
Owner:	TAMPA ELECTRIC CO		
	PO BOX 111 % ENVIR PLANNING		
	TAMPA, FL 336010111		
Owner's Phone:	8132281111	Tracking #:	293582
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

195	AMERADA HESS CORP.-TAMPA TERM 504 N 19TH ST TAMPA, FL 33605	FINDS	1000931963 FL0000477091
195	CHEVRON 500 N 19TH ST TAMPA, FL 33605	TSCA	1000995380 N/A
195	PHILLIPS PETROLEUM 504 N 19TH ST TAMPA, FL 33605	FINDS	1000931537 FL0000262717
195	STAR ENTERPRISE 519 19TH ST TAMPA, FL 33601  Other Pertinent Environmental Activity Identified at Site: facility has active water discharge permits	FINDS	1000733594 FLD079197711
196	CSX TRANSPORTATION-CLARK ST SITE 30TH ST / CLARK ST TAMPA, FL	LUST AST	S101265163 N/A

196

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CSX TRANSPORTATION-CLARK ST SITE (Continued)

S101265163

LUST:

Facility ID:	9101429	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	9043593693	Discovery Date:	03/27/91
Tracking Number:	Not reported	Score:	009 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	08492		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

196



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CSX TRANSPORTATION-CLARK ST SITE (Continued)

S101265163

### AST:

Facility ID:	299101429	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CSX TRANSPORTATION		
Facility Phone:	9043593693	Permit Section:	Not reported
Date entered:	910401	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	K W RICHARDSON JR		
Owner:	CSX TRANSPORTATION INC J275		
	500 WATER ST		
	JACKSONVILLE, FL 32202		
Owner's Phone:	9043591986	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299101429	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CSX TRANSPORTATION		
Facility Phone:	9043593693	Permit Section:	Not reported
Date entered:	910401	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	K W RICHARDSON JR		
Owner:	CSX TRANSPORTATION INC J275		
	500 WATER ST		
	JACKSONVILLE, FL 32202		
Owner's Phone:	9043591986	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00012000
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

196

GENERAL CHEMICAL  
3004 CLARK ST  
TAMPA, FL 33605

FINDS

1000498516  
FLD982089617

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act

196

# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
196	GENERAL CHEMICAL CORP. TAMPA WORKS 3004 E. CLARK ST. TAMPA, FL 33605	TRIS	1000901806 NA
196	GENERAL CHEMICAL TAMPA WORKS 3004 E CLARK ST TAMPA, FL 33605	FINDS	1000498787 FLD984180703
196	GENERAL CHEMICAL CORP-TAMPA WORKS 3004 CLARK ST TAMPA, FL 33605	AST	A100008998 N/A
AST:			
Facility ID: 299101959 Facility Type: Industrial Plan			
Is fac. regulated: Regulated facility Is facility open: Open			
Operator: COOPER, DONALD			
Facility Phone: 8132481643 Permit Section: Not reported			
Date entered: 910510 Financial responsibility: None			
Tank ID: 1 District: Southwest			
Owner's Contact: BARRY A SWIHART			
Owner: GENERAL CHEMICAL CORP			
1427 CENTRAL AVE			
EAST POINT, GA 30344			
Owner's Phone: 4047611370 Tracking #: Not reported			
Drink. Wat. Well: Not reported Any contaminated soil: Not reported			
Cleanup Status: Not reported Any contaminated surface water: Not reported			
Tank position: Aboveground Tank Cap. (Gals): 00030086			
Tank Content: Mineral acid Contaminated media indicator: Not reported			
Disposal Method: In service Install. Date: 83/XX			
Is tank regulated: Regulated tank Content Category: Hazardous/other			
Last used Date: Not reported Any contaminated groundwater: Not reported			
RPT Tank #: Not reported RPT by Tank #: Not reported			
Tank Constr.: Bare/asph steel, AST containment area, Level gauges/hi level			
alarms, Field erected			
Tank Piping: Abvgnd-no contact w/soil, Unprotec metal, Secondary containment,			
Suction piping			
Petro. Monitoring: Auto tank gauging			

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GENERAL CHEMICAL CORP-TAMPA WORKS (Continued)

A100008998

Facility ID:	299101959	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COOPER, DONALD		
Facility Phone:	8132481643	Permit Section:	Not reported
Date entered:	910510	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	BARRY A SWIHART		
Owner:	GENERAL CHEMICAL CORP		
	1427 CENTRAL AVE		
	EAST POINT, GA 30344		
Owner's Phone:	4047611370	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00030138
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	FRP clad steel, AST containment area, Level gauges/hi level alarms, Field erected		
Tank Piping:	Abvgrnd-no contact w/soil, Fiberglass, Secondary containment, Suction piping		
Petro. Monitoring:	Man tank gauging		
Facility ID:	299101959	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COOPER, DONALD		
Facility Phone:	8132481643	Permit Section:	Not reported
Date entered:	910510	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	BARRY A SWIHART		
Owner:	GENERAL CHEMICAL CORP		
	1427 CENTRAL AVE		
	EAST POINT, GA 30344		
Owner's Phone:	4047611370	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00030138
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	FRP clad steel, AST containment area, Level gauges/hi level alarms, Field erected		
Tank Piping:	Abvgrnd-no contact w/soil, Fiberglass, Secondary containment, Suction piping		
Petro. Monitoring:	Man tank gauging		

196

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GENERAL CHEMICAL CORP-TAMPA WORKS (Continued)

A100008998

Facility ID:	299101959	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COOPER, DONALD		
Facility Phone:	8132481643	Permit Section:	Not reported
Date entered:	910510	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	BARRY A SWIHART		
Owner:	GENERAL CHEMICAL CORP		
	1427 CENTRAL AVE		
	EAST POINT, GA 30344		
Owner's Phone:	4047611370	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00030628
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	FRP clad steel, AST containment area, Level gauges/hi level alarms, Field erected		
Tank Piping:	Abvgrnd-no contact w/soil, Fiberglass, Secondary containment, Suction piping		
Petro. Monitoring:	Man tank gauging		

197	HILLSBOROUGH CNTY PUB SCH 901 E KENNEDY BLVD TAMPA, FL 33602	FINDS	1000502054 FLD984222034
197	FIRESTONE #1889-004146 900 E KENNEDY BLVD TAMPA, FL 33602	UST LUST	U001355452 N/A

197

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**FIRESTONE #1889-004146 (Continued)**

**U001355452**

## LUST:

Facility ID:	8733809	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132292626	Discovery Date:	12/22/88
Tracking Number:	297373	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06114		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	REMEDIAL ACTION PLAN
Extension Status:	APPROVED
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

9/7

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FIRESTONE #1889-004146 (Continued)

U001355452

### UST:

Facility ID:	298733809	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	FIRESTONE		
Contact:	Not reported	Facility Phone:	8132292626
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870729	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	KATHLEEN SCHEUTZOW		
Owner:	BRIDGESTONE-FIRESTONE INC		
	2550 W GOLF RD		
	ROLLING MEADOWS, IL 60008		
Owner's Phone:	2163793737	Tracking #:	297373
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000300	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

197

HILLSBOROUGH CNTY SCHOOL BD-ADMIN CTR  
901 E KENNEDY BLVD  
TAMPA, FL 33605

UST

U001355685  
N/A

197

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## HILLSBOROUGH CNTY SCHOOL BD-ADMIN CTR (Continued)

U001355685

### UST:

Facility ID:	298736984	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TORRES, LUIS		
Contact:	Not reported	Facility Phone:	8132724000
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871223	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT J AGUIS		
Owner:	HILLSBOROUGH CNTY SCHOOL BD		
	901 E KENNEDY BLVD		
	TAMPA, FL 33601		
Owner's Phone:	8139876994	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

198

USGSA  
601 N FLORIDA AVE  
TAMPA, FL 33602

RCRIS-SQG 1000858795  
FINDS FL0000015081

### RCRIS:

Owner: JAMES BENNETT, FIELD OFFICE MGR  
(813) 228-2351

Contact: JAMES BENNETT  
(813) 228-2351

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D008	.00000 (T)	Notification	F001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

198

BANKSHARES PROPERTIES INC  
600 N FLORIDA AVE  
TAMPA, FL 33602

UST

U001356182  
N/A

1986

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BANKSHARES PROPERTIES INC (Continued)

U001356182

UST:

Facility ID:	299063982	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BANKSHARES PROPERTIES INC		
Contact:	Not reported	Facility Phone:	8138810488
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	901219	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOSEPH SERAVALLI		
Owner:	BARCHESTER CORP		
	1000 WALKER ST		
	HOLLY HILL, FL 32117		
Owner's Phone:	9042384076	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Man sample wells		

198

US POSTAL SERVICE-COURTHOUSE  
601 N FLORIDA AVE  
TAMPA, FL 33602

UST

U001355086  
N/A

198



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## US POSTAL SERVICE-COURTHOUSE (Continued)

U001355086

### UST:

Facility ID:	298627017	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	GENERAL SERVICES ADMINISTRATION		
Contact:	Not reported	Facility Phone:	8132282351
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES F. BENNETT		
Owner:	GENERAL SERVICES ADMIN		
	500 ZACK ST #733		
	TAMPA, FL 33602		
Owner's Phone:	8132282351	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-distribution	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Auto tank gauging		

199

**TAMPA MCKAY BAY REFUSE TO ENERGY**  
**34TH & CLARK ST**  
**TAMPA, FL 33675**

**FINDS**  
**SWF/LF**

**1000735789**  
**FLD982168775**

### LF:

Facility ID:	4029M30071	Facility Status:	ACTIVE
Population Served:	285,000 PERSONS	Design Capacity:	1,300.0000 TPD
Amount Daily Waste:	1,300 TON	Number of Monitoring Wells:	0 WELLS
Facility Telephone:	(813) 223-8337	Facility Contact:	CITY OF TAMPA SANITATION DEPT

199

**TAMPA CITY INCINERATOR**  
**107 N. 34TH ST.**  
**TAMPA, FL 33605**

**FI Sites**

**S100889051**  
**N/A**

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA CITY INCINERATOR (Continued)

S100889051

### FL Sites:

Facility ID:	000390	EPA ID:	FLD000865451
Facility District:	SOUTHWEST	Monthly Update:	June
Lead Unit:	DIST	Support Unit:	3012
Air Contam:	Not reported	Soil Contam:	Not reported
Surface Water Contam:	Not reported	Ground Water Contam:	Not reported
Cleanup Started ?:	No	Cleanup Completed ?:	No
Deletion Recommended ?:	No	Other:	Not reported
Warning Letter Status:	Not reported	Notice of Violation Status:	No
Consent Order Status:	No	Admin Hearing Status:	No
Court Status:	No	Final Order Status:	No
Comments:	3012 SITE INSPECTION CONDUCTED AUG. 1984. REPORT COMPLETED 1-85 AND FORWARDED TO EPA 2-85. CONTAMINATION CONFIRMED BUT NOT IN VIOLATION OF STATE STANDARDS. REPORT FORWARDED 1-86 TO DISTRICT FOR REVIEW. LOW PRIORITY FOR DISTRICT ENFORCEMENT. DISTRICT TO REVIEW FILE AND PERMIT STATUS TO DETERMINE NEXT ACTION.		

199

WHEELABRATOR MCKAY BAY INC  
107 N 34TH ST  
TAMPA, FL 33605

AST

A100008928  
N/A

### AST:

Facility ID:	298943764	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN NEIL		
Facility Phone:	8132481457	Permit Section:	Not reported
Date entered:	890411	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN NEIL		
Owner:	WHEELABRATOR MCKAY BAY INC 107 N 34TH ST TAMPA, FL 33605		
Owner's Phone:	8132481457	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000550
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, AST containment area		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

199

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WHEELABRATOR MCKAY BAY INC (Continued)

A100008928

Facility ID:	298943764	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN NEIL		
Facility Phone:	8132481457	Permit Section:	Not reported
Date entered:	890411	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN NEIL		
Owner:	WHEELABRATOR MCKAY BAY INC		
	107 N 34TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132481457	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000550
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, AST containment area		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

Facility ID:	298943764	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN NEIL		
Facility Phone:	8132481457	Permit Section:	Not reported
Date entered:	890411	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN NEIL		
Owner:	WHEELABRATOR MCKAY BAY INC		
	107 N 34TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132481457	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000550
Tank Content:	Leaded gas	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, AST containment area		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

199

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WHEELABRATOR MCKAY BAY INC (Continued)

A100008928

Facility ID:	298943764	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN NEIL		
Facility Phone:	8132481457	Permit Section:	Not reported
Date entered:	890411	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN NEIL		
Owner:	WHEELABRATOR MCKAY BAY INC		
	107 N 34TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132481457	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000280
Tank Content:	Other	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, AST containment area		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

Facility ID:	298943764	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN NEIL		
Facility Phone:	8132481457	Permit Section:	Not reported
Date entered:	890411	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN NEIL		
Owner:	WHEELABRATOR MCKAY BAY INC		
	107 N 34TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132481457	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	Mineral acid	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Int lined steel, Bare/asph steel, AST containment area, Spill		
	cnmt		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Corrosion resis coated,		
	Pressurized piping		
Petro. Monitoring:	Man tank gauging, None		

19

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WHEELABRATOR MCKAY BAY INC (Continued)

A100008928

Facility ID:	298943764	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN NEIL		
Facility Phone:	8132481457	Permit Section:	Not reported
Date entered:	890411	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN NEIL		
Owner:	WHEELABRATOR MCKAY BAY INC		
	107 N 34TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132481457	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Int lined steel, Bare/asph steel, AST containment area, Spill		
	cnmt		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Corrosion resis coated,		
	Pressurized piping		
Petro. Monitoring:	Man tank gauging, None		

199

## TAMPA PATHOLOGICAL INCINERATOR 107 N 34TH ST TAMPA, FL

SWF/LF

S101011596  
N/A

LF:

Facility ID:	4029M30070	Facility Status:	INACTIVE
Population Served:	Not reported	Design Capacity:	0.0000
Amount Daily Waste:	Not reported	Number of Monitoring Wells:	0 WELLS
Facility Telephone:	(813) 223-8337	Facility Contact:	CITY OF TAMPA SANITATION DEPT

199

## TAMPA MUNICIPAL INCINERATOR 107 N 34TH ST TAMPA, FL 33605

CERCLIS  
FINDS

1000344888  
FLD000865451

CERCLIS Classification Data:

Site Incident Category: Not reported  
Ownership Status: OTHER  
EPA Notes: Not reported

Federal Facility: NO  
NPL Status: NOT ON NPL

CERCLIS Assessment History:

Assessment:	DISCOVERY	Completed:	02/12/1988
Assessment:	PRELIMINARY ASSESSMENT	Completed:	04/15/1988
Assessment:	SCREENING SITE INSPECTION	Completed:	08/06/1985

CERCLIS Site Status:

This site is currently under investigation by the government to assess the extent of further action

CERCLIS Alias Name(s):

TAMPA MUNICIPAL INCINERATOR

Other Pertinent Environmental Activity Identified at Site:

facility has active water discharge permits  
civil judicial and administrative enforcement cases against facility

199

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

200 HAYMAN-FUENTES CATTLE CO.  
606 N FRANKLIN ST  
TAMPA, FL 33602 AST A100008878  
N/A

## AST:

Facility ID:	298839888	Facility Type:	Agribusiness
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	HAYMAN-FUENTES CATTLE CO.		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	880325	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000550
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298839888	Facility Type:	Agribusiness
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	HAYMAN-FUENTES CATTLE CO.		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	880325	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000550
Tank Content:	Leaded gas	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

201 BIRDWELL EQUIPMENT CO  
202 N 11TH ST  
TAMPA, FL 33602 UST  
LUST U001354903  
N/A

201

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BIRDWELL EQUIPMENT CO (Continued)

U001354903

### LUST:

Facility ID:	8625698	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132296571	Discovery Date:	09/30/91
Tracking Number:	Not reported	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

201

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BIRDWELL EQUIPMENT CO (Continued)

U001354903

### UST:

Facility ID:	298625698	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BIRDWELL EQUIPMENT CO		
Contact:	Not reported	Facility Phone:	8132296571
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	HERBERT SOMERSON		
Owner:	WEISSMAN, IRVING TRUSTEE GRANDWA		
	1400 GULF BLVD #810		
	CLEARWATER, FL 34630		
Owner's Phone:	8135965106	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		



MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

BIRDWELL EQUIPMENT CO (Continued)

U001354903

Facility ID:	298625698	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BIRDWELL EQUIPMENT CO		
Contact:	Not reported	Facility Phone:	8132296571
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	HERBERT SOMERSON		
Owner:	WEISSMAN, IRVING TRUSTEE GRANDWA 1400 GULF BLVD #810 CLEARWATER, FL 34630		
Owner's Phone:	8135965106	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

201

VENTO OIL CO  
207 N 11TH ST  
TAMPA, FL 33602

UST  
LUST

U001354885  
N/A

## MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## VENTO OIL CO (Continued)

U001354885

## LUST:

Facility ID:	8625679	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132210339	Discovery Date:	09/11/88
Tracking Number:	293751	Score:	040
Facility Code:	Not reported	Status:	Not reported
Rank:	02456		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	DISTRICT OFFICE
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

201

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## VENTO OIL CO (Continued)

U001354885

### UST:

Facility ID:	298625679	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VENTO OIL CO		
Contact:	Not reported	Facility Phone:	8132210339
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CATHERINE VENTO		
Owner:	VENTO, CATHERINE		
	712 GRAND CIR		
	TEMPLE TERRACE, FL 33617		
Owner's Phone:	8139801101	Tracking #:	293751
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

201

BONANNI SHIP SUPPLY, INC.  
217 N 11TH ST  
TAMPA, FL 33602

UST

U001354957  
N/A

201

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## BONANNI SHIP SUPPLY, INC. (Continued)

U001354957

### UST:

Facility ID:	298625754	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BONANNI SHIP SUPPLY, INC.		
Contact:	Not reported	Facility Phone:	8132296411
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAN LABARBERA		
Owner:	BONANNI SHIP SUPPLY INC		
	PO BOX 3208		
	TAMPA, FL 336013208		
Owner's Phone:	8132296411	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

202

**TAMPA SAND & MATERIAL**  
3214 E CLARK ST  
TAMPA, FL 33605

FINDS

1000497186  
FLD039568126

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act

202

**FL MINING & MATERIALS**  
3212 CLARK ST  
TAMPA, FL 33605

UST  
LUST  
AST

U001354037  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

FL MINING & MATERIALS (Continued)

U001354037

LUST:

Facility ID:	8624773	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8139336711	Discovery Date:	12/22/86
Tracking Number:	290590	Score:	035
Facility Code:	Not reported	Status:	Not reported
Rank:	03230		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
------------	------------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	REMEDIAL ACTION PLAN
Extension Status:	APPROVED
Extension Comments:	ADDITIONAL EXT.

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	SITE REHABILITATION COMPLETION REPORT
Region:	STATE

202

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL MINING & MATERIALS (Continued)

U001354037

### UST:

Facility ID:	298624773	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FL MINING & MATERIALS		
Contact:	Not reported	Facility Phone:	8139336711
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DENISE CORRALES		
Owner:	FL MINING & MATERIALS CORP		
	PO BOX 31965		
	TAMPA, FL 33631		
Owner's Phone:	8139336711	Tracking #:	290590
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

202

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

FL MINING & MATERIALS (Continued)

U001354037

Facility ID:	298624773	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FL MINING & MATERIALS		
Contact:	Not reported	Facility Phone:	8139336711
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DENISE CORRALES		
Owner:	FL MINING & MATERIALS CORP PO BOX 31965 TAMPA, FL 33631		
Owner's Phone:	8139336711	Tracking #:	290590
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00006000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

AST:

Facility ID:	298624773	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FL MINING & MATERIALS		
Facility Phone:	8139336711	Permit Section:	Not reported
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DENISE CORRALES		
Owner:	FL MINING & MATERIALS CORP PO BOX 31965 TAMPA, FL 33631		
Owner's Phone:	8139336711	Tracking #:	290590
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Completed	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

203

ALLEY & ALLEY, CHARTERED  
205 N BRUSH ST  
TAMPA, FL 33602

UST  
LUST

U001545324  
N/A

203

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ALLEY & ALLEY,CHARTERED (Continued)

U001545324

### LUST:

Facility ID:	8841244	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8138795333	Discovery Date:	12/14/88
Tracking Number:	295239	Score:	011 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	06571		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

203



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ALLEY & ALLEY,CHARTERED (Continued)

U001545324

### UST:

Facility ID:	298841244	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ALLEY & ALLEY,CHARTERED		
Contact:	Not reported	Facility Phone:	8138795333
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880819	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN EDWARD ALLEY		
Owner:	ALLEY & ALLEY CHARTERED		
	205 N BRUSH ST		
	TAMPA, FL 336024103		
Owner's Phone:	8138795333	Tracking #:	295239
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	56/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

204

ANCO INC  
102 N 20TH ST  
TAMPA, FL 33605

UST

U001355004  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANCO INC (Continued)

U001355004

### UST:

Facility ID:	298625805	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANCO INC		
Contact:	Not reported	Facility Phone:	8132486248
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM COKER		
Owner:	ANCO INC		
	102 N 20TH ST		
	TAMPA, FL 336056014		
Owner's Phone:	8132486248	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	8/2/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

205

SEABOARD COLD STORAGE  
101 N BRUSH ST  
TAMPA, FL 33602

UST  
LUST

U001354183  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

SEABOARD COLD STORAGE (Continued)

U001354183

LUST:

Facility ID:	8624930	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132233791	Discovery Date:	05/16/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant: UNLEADED GAS

Pollutant 2: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION

STATE CLEANUP

INELIGIBLE

FEDERAL FACILITY

FEDERAL FACILIT

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal: Y

Soil Treatment:

Other Treatment:

Cleanup Responsible: RESPONSIBLE PARTY

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

APPROVED

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Region:

NO FURTHER ACTION

STATE

205

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SEABOARD COLD STORAGE (Continued)

U001354183

### UST:

Facility ID:	298624930	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEABOARD COLD STORAGE		
Contact:	Not reported	Facility Phone:	8132233791
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	R MINNER		
Owner:	SOUTHEAST BANK OF TAMPA 1 TAMPA CITY CENTER TAMPA, FL 33602		
Owner's Phone:	8132297951	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass, Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

205

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SEABOARD COLD STORAGE (Continued)

U001354183

Facility ID:	298624930	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEABOARD COLD STORAGE		
Contact:	Not reported	Facility Phone:	8132233791
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	R MINNER		
Owner:	SOUTHEAST BANK OF TAMPA 1 TAMPA CITY CENTER TAMPA, FL 33602		
Owner's Phone:	8132297951	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass, Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

205

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## SEABOARD COLD STORAGE (Continued)

U001354183

Facility ID:	298624930	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEABOARD COLD STORAGE		
Contact:	Not reported	Facility Phone:	8132233791
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	R MINNER		
Owner:	SOUTHEAST BANK OF TAMPA 1 TAMPA CITY CENTER TAMPA, FL 33602		
Owner's Phone:	8132297951	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass, Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

206

TAMPA TRIBUNE CO  
805 E JACKSON ST  
TAMPA, FL 33602

UST

U001355366  
N/A

206

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA TRIBUNE CO (Continued)

U001355366

### UST:

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 33606		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA TRIBUNE CO (Continued)

U001355366

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 33606		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001300	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA TRIBUNE CO (Continued)

U001355366

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 33606		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA TRIBUNE CO (Continued)

U001355366

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 33606		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA TRIBUNE CO (Continued)

U001355366

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO		
	202 S PARKER ST		
	TAMPA, FL 33606		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA TRIBUNE CO (Continued)

U001355366

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 33606		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**TAMPA TRIBUNE CO (Continued)**

U001355366

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 33606		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

207

**DELUXE PLASTIC CARD CO**  
202 S 22ND ST  
TAMPA, FL 33605

**RCRIS-SQG** 1000428902  
**FINDS** FLD122637861

RCRIS:

Owner: KENT LARSON  
(813) 248-2196

Contact: KENT LARSON  
(813) 248-2196

Waste	Quantity	Info Source	Waste	Quantity	Info Source
F002	.00000 (T)	Notification	F003	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

208

**USN NAVAL RESERVE CENTER**  
1325 YORK ST  
TAMPA, FL 33602

**RCRIS-SQG** 1000503289  
**FINDS** FL1170022742

208

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

**USN NAVAL RESERVE CENTER (Continued)**

1000503289

RCRIS:

Owner: DANNY KENNEDY, SUPPLY CPO  
(813) 228-2689

Contact: DANNY KENNEDY  
(813) 228-2689

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F003	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

209 **HIGH TECH FINISHING SERVICES INC**  
**132 NORTH 13 ST**  
**TAMPA, FL 33602**

**RCRIS-SQG**  
**FINDS**

1000238636  
FLD981860547

210 **SIR SPEEDY**  
**501 E JACKSON ST**  
**TAMPA, FL 33602**

**RCRIS-SQG**  
**FINDS**

1000502617  
FLD984227843

RCRIS:

Owner: PAUL GRAVES, DEALER  
(813) 228-8811

Contact: PAUL GRAVES  
(813) 228-8811

Waste	Quantity	Info Source
D011	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

210 **TAMPA CITY-DPW FLEET MAINT-DIV #7**  
**310 N MARION ST**  
**TAMPA, FL 33602**

**UST**  
**LUST**

U001354877  
N/A

210

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

### LUST:

Facility ID:	8625671	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8138763536	Discovery Date:	01/22/88
Tracking Number:	292535	Score:	012 (LOW)
Facility Code:	Not reported	Status:	Not reported

Rank: 06114

Class: Not reported

Category: Not reported

### INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant: NOT ENTERED

Est. Gallons Lost: UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Region:

STATE

210

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

### UST:

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

210



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Unknown/not reported		

211

**CONAGRA**  
**110 S NEBRASKA AVE**  
**TAMPA, FL 33602**

**FINDS**

**1000497436**  
**FLD061431920**

Other Pertinent Environmental Activity Identified at Site:  
facility has an emission permit under the Clean Air Act  
facility is involved with pesticide/toxic substances production

211

**CON AGRA, INC.**  
**110 S NEBRASKA AVE**  
**TAMPA, FL 33602**

**UST**  
**LUST**

**U001355126**  
**N/A**

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CON AGRA, INC. (Continued)

U001355126

## LUST:

Facility ID:	8627167	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132279444	Discovery Date:	11/14/90
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	Not reported	Est. Gallons Lost:	Not reported
------------	--------------	--------------------	--------------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CON AGRA, INC. (Continued)

U001355126

## UST:

Facility ID:	298627167	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BURRIS,DAN		
Contact:	Not reported	Facility Phone:	8132279444
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861028	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RANDY GARVERT		
Owner:	CON AGRA INC		
	110 S NEBRASKA AVE		
	TAMPA, FL 336025530		
Owner's Phone:	8132234741	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CON AGRA, INC. (Continued)

U001355126

Facility ID:	298627167	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BURRIS,DAN		
Contact:	Not reported	Facility Phone:	8132279444
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861028	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	RANDY GARVERT		
Owner:	CON AGRA INC 110 S NEBRASKA AVE TAMPA, FL 336025530		
Owner's Phone:	8132234741	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

CON AGRA, INC. (Continued)

U001355126

Facility ID:	298627167	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BURRIS,DAN		
Contact:	Not reported	Facility Phone:	8132279444
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861028	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	RANDY GARVERT		
Owner:	CON AGRA INC		
	110 S NEBRASKA AVE		
	TAMPA, FL 336025530		
Owner's Phone:	8132234741	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CON AGRA, INC. (Continued)

U001355126

Facility ID:	298627167	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BURRIS,DAN		
Contact:	Not reported	Facility Phone:	8132279444
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861028	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	RANDY GARVERT		
Owner:	CON AGRA INC		
	110 S NEBRASKA AVE		
	TAMPA, FL 336025530		
Owner's Phone:	8132234741	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00008000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

212

TAMPA,CITY-FIRE DEPT TRAINING  
116 S 34TH ST  
TAMPA, FL 33605

UST  
LUST  
AST

U001355891  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT TRAINING (Continued)

U001355891

### LUST:

Facility ID:	8842214	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	12/12/88
Tracking Number:	295359	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	04379		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
------------	-------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

712

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT TRAINING (Continued)

U001355891

### UST:

Facility ID:	298842214	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FIRE DEPT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT		
	808 E ZACK ST		
	TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295359
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT TRAINING (Continued)

U001355891

Facility ID:	298842214	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FIRE DEPT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT		
	808 E ZACK ST		
	TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295359
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT TRAINING (Continued)

U001355891

Facility ID:	298842214	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FIRE DEPT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT		
	808 E ZACK ST		
	TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295359
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE DEPT TRAINING (Continued)

U001355891

Facility ID:	298842214	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FIRE DEPT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT		
	808 E ZACK ST		
	TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295359
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal, Fiberglass		
Petro. Monitoring:	Unknown/not reported		

### AST:

Facility ID:	298842214	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FIRE DEPT		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT		
	808 E ZACK ST		
	TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295359
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00001000
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	91/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Dbl walled=primary matl, AST containment area,		
	Spill cnmt, Op-tight fill, Concrete		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	DW tank space		



# MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
213	GARRISON STEVEDORING,INC. 101 S 13TH ST TAMPA, FL 33602	UST LUST	U001355392 N/A
LUST:			
Facility ID: 8732411		Facility Type:	NON-RETAIL BUSINESS
Alias Name: Not reported		Discovery Date:	05/02/95
Telephone: 8132291958		Score:	000 (LOW)
Tracking Number: Not reported		Status:	Not reported
Facility Code: Not reported			
Rank: 00000			
Class: Not reported			
Category: Not reported			
INCIDENT GENERAL INFORMATION -			
Source Description:		CLOSURE REPORT	
Lead:		Not reported	
Incident 17-770 Cleanup:		Not reported	
INCIDENT POLLUTANT INFORMATION -			
Pollutant: VEHIC DIESEL		Est. Gallons Lost:	UNKNOWN
INCIDENT PROGRAM INFORMATION -			
Incident Program:		RESPONSIBLE PARTY-NO CLAIM	
Incident Program Type:		Not reported	
Incident Eligible Status:		Not reported	
Incident Ineligible Reason:		Not Reported	
Incident Ineligible Description:		Not reported	
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:		Cleanup Responsible:	Not reported
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:		RESPONSIBLE PARTY	
Response Record Type:		CONTAMINATION ASSESSMENT REPORT	
Response Remedial Action Plan Type:		Not reported	
Response Status:		INCOMPLETE	
Extension Record Type:		Not reported	
Extension Status:		Not reported	
Extension Comments:		Not reported	
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:		Not reported	
Response Record Type:		Not reported	
Response Remedial Action Plan Type:		Not reported	
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:		Not reported	
Estimated Completion Year:		Not reported	
Actual Year to Complete:		Not reported	
Report Type:		Not reported	
Report Comments:		Not reported	
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:		Not reported	
Region:		STATE	

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARRISON STEVEDORING,INC. (Continued)

U001355392

### UST:

Facility ID:	298732411	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GARRISON STEVEDORING,INC.		
Contact:	Not reported	Facility Phone:	8132291958
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870413	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE H. PATE		
Owner:	GARRISON STEVEDORING INC		
	101 S 13TH ST		
	TAMPA, FL 336024213		
Owner's Phone:	8132291958	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

213

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARRISON STEVEDORING,INC. (Continued)

U001355392

Facility ID:	298732411	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GARRISON STEVEDORING,INC.		
Contact:	Not reported	Facility Phone:	8132291958
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	870413	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE H. PATE		
Owner:	GARRISON STEVEDORING INC		
	101 S 13TH ST		
	TAMPA, FL 336024213		
Owner's Phone:	8132291958	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

213

**BRULIN & CO INC**  
104 N 13TH ST  
TAMPA, FL 33602

RCRIS-SQG  
FINDS

1000497798  
FLD097382808

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

214

**TAMPA,CITY-FIRE STATION #6**  
311 S 22ND ST  
TAMPA, FL 33605

UST  
LUST

U001355926  
N/A

214

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

TAMPA,CITY-FIRE STATION #6 (Continued)

U001355926

LUST:

Facility ID:	8842516	Facility Type:	LOCAL, CITY GOVERNMENT
Alias Name:	Not reported		
Telephone:	8132255729	Discovery Date:	12/12/88
Tracking Number:	295181	Score:	040
Facility Code:	Not reported	Status:	Not reported
Rank:	02461		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	FIRST QTR

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE STATION #6 (Continued)

U001355926

### UST:

Facility ID:	298842516	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	295181
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000500	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA,CITY-FIRE STATION #6 (Continued)

U001355926

Facility ID:	298842516	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	295181
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

214

CONVENIENCE CENTER  
301 S 22ND ST  
TAMPA, FL 33605

UST  
LUST

U001354826  
N/A

214

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONVENIENCE CENTER (Continued)

U001354826

### LUST:

Facility ID:	8625619	Facility Type:	RETAIL STATION
Alias Name:	PHILLIPS 66-JOE PASCIUTAS		
Telephone:	8132471116	Discovery Date:	03/27/91
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

214

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONVENIENCE CENTER (Continued)

U001354826

### UST:

Facility ID:	298625619	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PEGUERO, LUIS A		
Contact:	Not reported	Facility Phone:	8132471116
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	JOE PASCIUTA		
Owner:	PASCIUTA, JOE		
	301 S 22ND ST		
	TAMPA, FL 33605		
Owner's Phone:	8132472015	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	50/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Unprotec metal, Corrosion resis coated		
Petro. Monitoring:	Man sample wells		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONVENIENCE CENTER (Continued)

U001354826

Facility ID:	298625619	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PEGUERO, LUIS A		
Contact:	Not reported	Facility Phone:	8132471116
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	JOE PASCIUTA		
Owner:	PASCIUTA, JOE		
	301 S 22ND ST		
	TAMPA, FL 33605		
Owner's Phone:	8132472015	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	50/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Unprotec metal, Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## CONVENIENCE CENTER (Continued)

U001354826

Facility ID:	298625619	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PEGUERO, LUIS A		
Contact:	Not reported	Facility Phone:	8132471116
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	JOE PASCIUTA		
Owner:	PASCIUTA, JOE		
	301 S 22ND ST		
	TAMPA, FL 33605		
Owner's Phone:	8132472015	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	75/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Int lined steel, Bare/asph steel		
Tank Piping:	Unprotec metal, Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

215

FL BLUEPRINT  
101 S 12TH ST  
TAMPA, FL 33602

UST

U001355277  
N/A

215

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL BLUEPRINT (Continued)

U001355277

### UST:

Facility ID:	298627847	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL BLUEPRINT		
Contact:	Not reported	Facility Phone:	8132212094
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	AMOCO OIL CO. P O BOX 3488 OAK BROOK, IL 60522		
Owner's Phone:	3127894940	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

215

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FL BLUEPRINT (Continued)

U001355277

Facility ID:	298627847	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL BLUEPRINT		
Contact:	Not reported	Facility Phone:	8132212094
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	AMOCO OIL CO. P O BOX 3488 OAK BROOK, IL 60522		
Owner's Phone:	3127894940	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

215

B&R INDUSTRIAL FOODS,INC  
102 N 12TH ST  
TAMPA, FL 33602

UST

U001354562  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## B&R INDUSTRIAL FOODS,INC (Continued)

U001354562

### UST:

Facility ID:	298625340	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BERGER & RACHELSON		
Contact:	Not reported	Facility Phone:	8136590008
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	EDGAR W.SAPP		
Owner:	J. H. WILLIAMS OIL CO.,INC. 1237 E TWIGGS TAMPA, FL 33602		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/01
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	88/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Fiberglass		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

216

SOUTHEAST FINANCIAL CTR ASSOC  
FLORIDA AVE & JACKSON ST  
TAMPA, FL 33602

FINDS  
UST  
LUST

1000739074  
FLD984243725

Other Pertinent Environmental Activity Identified at Site:  
facility has active water discharge permits

216

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SOUTHEAST FINANCIAL CTR ASSOC (Continued)

1000739074

### LUST:

Facility ID:	9102164	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132899491	Discovery Date:	07/23/90
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		
INCIDENT GENERAL INFORMATION -			
Source Description:		DISCHARGE NOTIFICATION	
Lead:		LOCAL PROGRAM	
Incident 17-770 Cleanup:		NEW C/U REQUIRED	
INCIDENT POLLUTANT INFORMATION -			
Pollutant:	GENERIC GAS	Est. Gallons Lost:	00000050
INCIDENT PROGRAM INFORMATION -			
Incident Program:		RESPONSIBLE PARTY-NO CLAIM	
Incident Program Type:		Not reported	
Incident Eligible Status:		Not reported	
Incident Ineligible Reason:		Not Reported	
Incident Ineligible Description:		Not reported	
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:		Cleanup Responsible:	Not reported
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:		RESPONSIBLE PARTY	
Response Record Type:		CONTAMINATION ASSESSMENT REPORT	
Response Remedial Action Plan Type:		Not reported	
Response Status:		APPROVED	
Extension Record Type:		Not reported	
Extension Status:		Not reported	
Extension Comments:		Not reported	
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:		RESPONSIBLE PARTY	
Response Record Type:		REMEDIAL ACTION PLAN	
Response Remedial Action Plan Type:		MONITORING ONLY PLAN	
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:		RESPONSIBLE PARTY	
Estimated Completion Year:		00	
Actual Year to Complete:		00	
Report Type:		QUARTERLY	
Report Comments:		Q1	
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:		NO FURTHER ACTION	
Region:		STATE	

2.16

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## SOUTHEAST FINANCIAL CTR ASSOC (Continued)

1000739074

### UST:

Facility ID:	299102164	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD E MAYER		
Contact:	Not reported	Facility Phone:	8132899491
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910530	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	RICHARD E MAYER		
Owner:	SOUTHEAST FINANCIAL CENTER		
	401 EAST JACKSON ST		
	TAMPA, FL		
Owner's Phone:	8132899491	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	No
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

217

**PILGRIM PERMOCOAT INC**  
402 S 22ND ST  
TAMPA, FL 33605

FINDS

1000496919  
FLD004100756

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

218

**ALLRIGHT FLORIDA INC**  
403 WASHINGTON E  
TAMPA, FL 33602

UST

U001823410  
N/A

713

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ALLRIGHT FLORIDA INC (Continued)

U001823410

### UST:

Facility ID:	299400569	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM PAUL		
Contact:	Not reported	Facility Phone:	8132292111
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940406	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLIAM R PAUL		
Owner:	LAURALEA LTD		
	101 E KENNEDY BLVD SUITE 2000		
	TAMPA, FL 33602		
Owner's Phone:	8132292111	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	New/lube oil	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

218



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ALLRIGHT FLORIDA INC (Continued)

U001823410

Facility ID:	299400569	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM PAUL		
Contact:	Not reported	Facility Phone:	8132292111
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940406	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLIAM R PAUL		
Owner:	LAURALEA LTD		
	101 E KENNEDY BLVD SUITE 2000		
	TAMPA, FL 33602		
Owner's Phone:	8132292111	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	New/lube oil	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

218

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ALLRIGHT FLORIDA INC (Continued)

U001823410

Facility ID:	299400569	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM PAUL		
Contact:	Not reported	Facility Phone:	8132292111
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940406	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLIAM R PAUL		
Owner:	LAURALEA LTD		
	101 E KENNEDY BLVD SUITE 2000		
	TAMPA, FL 33602		
Owner's Phone:	8132292111	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	New/lube oil	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

219	MARATHON OIL CO 20TH & GRANT STREETS TAMPA, FL 33605	FINDS	1000498624 FLD984166272
-----	--	-------	----------------------------

219	MARATHON OIL CO 425 S 20TH ST TAMPA, FL 46222	RCRIS-LQG UST LUST AST	1000892606 FLD065919763
-----	---	---------------------------------	----------------------------

RCRIS:  
Owner: NELSON ALMOND, ENV COOR  
(317) 244-9551

Contact: G SHEELY  
(419) 422-2121

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D018	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

### LUST:

Facility ID:	8837986	Facility Type:	TERMINAL FACILITY
Alias Name:	MARATHON PETROLEUM CO		
Telephone:	8132471459	Discovery Date:	02/19/93
Tracking Number:	291252	Score:	041
Facility Code:	Not reported	Status:	Not reported
Rank:	02362		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	00000100
------------	--------------	--------------------	----------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	N
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

219

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

### UST:

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Contact:	Not reported	Facility Phone:	8132471459
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	OWS1	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/01
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Contact:	Not reported	Facility Phone:	8132471459
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	OWS2	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/01
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

### AST:

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	11-30	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00413868
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	41/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	13-27	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00534156
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	57/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		
Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	17-31	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00632478
Tank Content:	Aviation gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	64/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	17-32	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00642138
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	59/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		
Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	21-2	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00877338
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	39/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	91/03	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	21-8	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00904344
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	39/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	SPCC plan		
Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	24-24	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00901866
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	60/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	25-12	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00922908
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	39/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		
Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	27-23	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00878724
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	54/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

219

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	30-13	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01026606
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	49/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		
Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	30-9	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01160754
Tank Content:	Kerosene	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	54/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	33-26	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01230642
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	60/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	33-29	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01157142
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	59/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Man sample wells, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	35-7	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01168272
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	70/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	93/04	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	SPCC plan		
Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	38-25	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01473696
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	20/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	43-21	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	01522374
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	54/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		
Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	43-28	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	01523130
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	59/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Man sample wells, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	54-22	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	02043384
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	66/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	55-10	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	01954596
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	54/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	55-14	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01951698
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	54/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	91/12	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Int lined steel, Cath prot-sac anode, Cath prot-imp curr, Spill cnmt, Field erected		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan, Auto tank gauging		
Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	55-3	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01961610
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	55/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	93/05	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	55-4	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	01957704
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	55/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-11	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	03151638
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	65/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-15	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	02849700
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	55/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Man sample wells, Auto tank gauging		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-16	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	02877588
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	55/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Man sample wells, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-17	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	02939538
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	57/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		
Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-18	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	02906946
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	59/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-19	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	03112536
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-6	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	02954532
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	59/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	AA10-2	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Field erected		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	AA10-3	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Field erected		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	AA84	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Field erected		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	AA85	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Cath prot-imp curr, AST containment area, Op-flow shut off		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	SPCC plan, Man tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## MARATHON OIL CO (Continued)

1000892606

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	Not reported
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	T-5	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00019488
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Field erected		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

219

MARATHON OIL CO  
425 S 20TH ST  
TAMPA, FL 33675

FINDS

1000733506  
FLD065919763

220

ANTHONY DISTRIBUTORS INC  
201 S CAESAR ST  
TAMPA, FL 33602

UST

U001962949  
N/A

220

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ANTHONY DISTRIBUTORS INC (Continued)

U001962949

### UST:

Facility ID:	299401349	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	8132297191
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	940810	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	NONE	District:	Southwest
Owner's Contact:	GEORGE SANDS		
Owner:	ANTHONY DISTRIBUTORS INC		
	2900 EAST 7TH AVE		
	TAMPA, FL 33605		
Owner's Phone:	8132297191	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

221

ONE TAMPA CITY CENTER  
201 N FRANKLIN ST #1766  
TAMPA, FL 33602

RCRIS-SQG 1000687555  
FINDS FLD984238154

### RCRIS:

Owner: CLIFFORD FISH, ASST CHIEF ENG  
(813) 223-5008

Contact: CLIFFORD FISH  
(813) 223-5008

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

221

TAMPA,CITY-CITY CENTER  
201 N FRANKLIN  
TAMPA, FL 33602

UST

U001355143  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

TAMPA,CITY-CITY CENTER (Continued)

U001355143

UST:

Facility ID:	298627221	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN HORN		
Contact:	Not reported	Facility Phone:	8132235008
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN C HORN		
Owner:	TAMPA CITY CENTER ASSOCIATES ONE TAMPA CITY CENTER #1766 TAMPA, FL 336025193		
Owner's Phone:	8132235008	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003200	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Unknown/not reported		

222

KENNEY PROPERTY  
209 S 12TH ST  
TAMPA, FL

UST  
LUST

U001378129  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KENNEY PROPERTY (Continued)

U001378129

### LUST:

Facility ID:	9300022	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	9046346124	Discovery Date:	08/11/93
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KENNEY PROPERTY (Continued)

U001378129

### UST:

Facility ID:	299300022	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNEY, MICHAEL C		
Contact:	Not reported	Facility Phone:	9046346124
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	930119	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	MICHAEL KENNEY		
Owner:	KENNEY, MICHAEL C		
	7595 BAYMEADOWS CIR W #2305		
	JACKSONVILLE, FL 32215		
Owner's Phone:	9047319979	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KENNEY PROPERTY (Continued)

U001378129

Facility ID:	299300022	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNEY, MICHAEL C		
Contact:	Not reported	Facility Phone:	9046346124
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	930119	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	MICHAEL KENNEY		
Owner:	KENNEY, MICHAEL C		
	7595 BAYMEADOWS CIR W #2305		
	JACKSONVILLE, FL 32215		
Owner's Phone:	9047319979	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

222

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KENNEY PROPERTY (Continued)

U001378129

Facility ID:	299300022	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNEY, MICHAEL C		
Contact:	Not reported	Facility Phone:	9046346124
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	930119	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	MICHAEL KENNEY		
Owner:	KENNEY, MICHAEL C		
	7595 BAYMEADOWS CIR W #2305		
	JACKSONVILLE, FL 32215		
Owner's Phone:	9047319979	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KENNEY PROPERTY (Continued)

U001378129

Facility ID:	299300022	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNEY, MICHAEL C		
Contact:	Not reported	Facility Phone:	9046346124
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	930119	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	MICHAEL KENNEY		
Owner:	KENNEY, MICHAEL C		
	7595 BAYMEADOWS CIR W #2305		
	JACKSONVILLE, FL 32215		
Owner's Phone:	9047319979	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

2 2 2

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## KENNEY PROPERTY (Continued)

U001378129

Facility ID:	299300022	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNEY, MICHAEL C		
Contact:	Not reported	Facility Phone:	9046346124
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	930119	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	MICHAEL KENNEY		
Owner:	KENNEY, MICHAEL C		
	7595 BAYMEADOWS CIR W #2305		
	JACKSONVILLE, FL 32215		
Owner's Phone:	9047319979	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000888	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

223

TAMPA ELECTRIC CO-TECO PLAZA  
702 N FRANKLIN ST  
TAMPA, FL 33602

AST

A100008924  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TAMPA ELECTRIC CO-TECO PLAZA (Continued)

A100008924

### AST:

Facility ID:	298943539	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	TAMPA ELECTRIC CO		
Facility Phone:	8132284111	Permit Section:	Not reported
Date entered:	890314	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BILL GOINS		
Owner:	TAMPA ELECTRIC CO		
	PO BOX 111 % ENVIR PLANNING		
	TAMPA, FL 336010111		
Owner's Phone:	8132281111	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000550
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

224

FLORIDA AQUARIUM  
300 S 13TH ST  
TAMPA, FL 33602

UST

U002313303  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FLORIDA AQUARIUM (Continued)

U002313303

### UST:

Facility ID:	299502817	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	JOHN FISHER		
Contact:	Not reported	Facility Phone:	8132298861
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	951114	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	NONE	District:	Southwest
Owner's Contact:	JOHN FISHER		
Owner:	FLORIDA AQUARIUM 300 S 13TH ST TAMPA, FL 33602		
Owner's Phone:	8132298861	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

225

FOGARTY VAN LINES-OFFICE  
1103 E CUMBERLAND ST  
TAMPA, FL 33601

UST  
LUST

U002113437  
N/A



MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

FOGARTY VAN LINES-OFFICE (Continued)

U002113437

LUST:

Facility ID:	9501591	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132287481	Discovery Date:	12/06/94
Tracking Number:	Not reported	Score:	000 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	00000		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## FOGARTY VAN LINES-OFFICE (Continued)

U002113437

### UST:

Facility ID:	299501591	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FOGARTY VAN LINES		
Contact:	Not reported	Facility Phone:	8132287481
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	950322	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	JERRY FOGARTY		
Owner:	FOGARTY, JERRY EUGENE SR		
	PO BOX 3402		
	TAMPA, FL 33601		
Owner's Phone:	8132287481	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	Not reported	Any monit. wells:	0
Tank position:	Not reported	Any contam. groundwater:	No
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

225 FOGARTY VAN LINES  
1103 CUMBERLAND AVE  
TAMPA, FL 33602

FINDS

1000737077  
FLD984196949

226 DIXIE NEON CO  
608 S 22ND ST  
TAMPA, FL 33605

RCRIS-SQG  
FINDS  
UST  
LUST

1000450168  
FLD984177238

### RCRIS:

Owner: JOE WEST  
(813) 248-2531

Contact:JOE WEST  
(813) 248-2531

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F003	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

226

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

DIXIE NEON CO (Continued)

1000450168

## LUST:

Facility ID:	8625074	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132482531	Discovery Date:	12/28/88
Tracking Number:	298534	Score:	010 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	07135		
Class:	Not reported		
Category:	Not reported		
INCIDENT GENERAL INFORMATION -			
Source Description:		EDI	
Lead:		LOCAL PROGRAM	
Incident 17-770 Cleanup:		NEW C/U REQUIRED	
INCIDENT POLLUTANT INFORMATION -			
Pollutant:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
INCIDENT PROGRAM INFORMATION -			
Incident Program:		EARLY DETECTION INCENTIVE	
Incident Program Type:		REIMBURSEMENT CLEANUP	
Incident Eligible Status:		ELIGIBLE	
Incident Ineligible Reason:		Not Reported	
Incident Ineligible Description:		Not reported	
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:		Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:		RESPONSIBLE PARTY	
Response Record Type:		CONTAMINATION ASSESSMENT REPORT	
Response Remedial Action Plan Type:		Not reported	
Response Status:		INCOMPLETE	
Extension Record Type:		Not reported	
Extension Status:		Not reported	
Extension Comments:		Not reported	
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:		RESPONSIBLE PARTY	
Response Record Type:		REMEDIAL ACTION PLAN	
Response Remedial Action Plan Type:		MONITORING ONLY PLAN	
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:		RESPONSIBLE PARTY	
Estimated Completion Year:		00	
Actual Year to Complete:		00	
Report Type:		QUARTERLY	
Report Comments:		Q1	
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:		Not reported	
Region:		STATE	

726

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## DIXIE NEON CO (Continued)

1000450168

### UST:

Facility ID:	298625074	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FREDDIE NEVIA, JR.		
Contact:	Not reported	Facility Phone:	8132482531
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	FREDDIE NEVIA, JR.		
Owner:	DIXIE NEON CO INC		
	608 S 22ND ST		
	TAMPA, FL 336056316		
Owner's Phone:	8132482531	Tracking #:	298534
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00003000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## DIXIE NEON CO (Continued)

1000450168

Facility ID:	298625074	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FREDDIE NEVIA, JR.		
Contact:	Not reported	Facility Phone:	8132482531
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	FREDDIE NEVIA, JR.		
Owner:	DIXIE NEON CO INC		
	608 S 22ND ST		
	TAMPA, FL 336056316		
Owner's Phone:	8132482531	Tracking #:	298534
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00005000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

227	TAMPA PRINTING COMPANY 503 SOUTH CAESAR STREET TAMPA, FL 33602	RCRIS-SQG FINDS	1000344900 FLD004103495
228	KAL-MAR CONSTRUCTION INC 908 E EUNICE ST TAMPA, FL 33602	UST AST	U001355238 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KAL-MAR CONSTRUCTION INC (Continued)

U001355238

### UST:

Facility ID:	298627640	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KAL-MAR CONSTRUCTION INC		
Contact:	Not reported	Facility Phone:	8132234219
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LENNON MARTIN		
Owner:	KAL MAR CONSTRUCTION INC		
	PO BOX 1371		
	TAMPA, FL 336011371		
Owner's Phone:	8132234219	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	80/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KAL-MAR CONSTRUCTION INC (Continued)

U001355238

Facility ID:	298627640	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KAL-MAR CONSTRUCTION INC		
Contact:	Not reported	Facility Phone:	8132234219
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	LENNON MARTIN		
Owner:	KAL MAR CONSTRUCTION INC		
	PO BOX 1371		
	TAMPA, FL 336011371		
Owner's Phone:	8132234219	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Kerosene	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	80/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

### AST:

Facility ID:	298627640	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KAL-MAR CONSTRUCTION INC		
Facility Phone:	8132234219	Permit Section:	Not reported
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	LENNON MARTIN		
Owner:	KAL MAR CONSTRUCTION INC		
	PO BOX 1371		
	TAMPA, FL 336011371		
Owner's Phone:	8132234219	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Unleaded gas	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	89/02
Is tank regulated:	Regulated tank	Content Category:	Vehicle
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## KAL-MAR CONSTRUCTION INC (Continued)

U001355238

Facility ID:	298627640	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KAL-MAR CONSTRUCTION INC		
Facility Phone:	8132234219	Permit Section:	Not reported
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	LENNON MARTIN		
Owner:	KAL MAR CONSTRUCTION INC		
	PO BOX 1371		
	TAMPA, FL 336011371		
Owner's Phone:	8132234219	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000550
Tank Content:	Kerosene	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	89/02
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

229

TEXACO-NEYDAS BUY & FLY  
540 S 50TH ST  
TAMPA, FL 33619

UST  
LUST

U001354035  
N/A



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEXACO-NEYDAS BUY & FLY (Continued)

U001354035

### LUST:

Facility ID:	8624771	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	8132485506	Discovery Date:	09/11/88
Tracking Number:	293769	Score:	030
Facility Code:	Not reported	Status:	Not reported
Rank:	03768		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEXACO-NEYDAS BUY & FLY (Continued)

U001354035

### UST:

Facility ID:	298624771	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	NEYDA FERNANDEZ		
Contact:	Not reported	Facility Phone:	8132485506
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	NEYDA FERNANDEZ		
Owner:	MARIN, VERENA JULIA		
	3409 47TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132485506	Tracking #:	293769
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	5
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEXACO-NEYDAS BUY & FLY (Continued)

U001354035

Facility ID:	298624771	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	NEYDA FERNANDEZ		
Contact:	Not reported	Facility Phone:	8132485506
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	NEYDA FERNANDEZ		
Owner:	MARIN, VERENA JULIA		
	3409 47TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132485506	Tracking #:	293769
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	6
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEXACO-NEYDAS BUY & FLY (Continued)

U001354035

Facility ID:	298624771	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	NEYDA FERNANDEZ		
Contact:	Not reported	Facility Phone:	8132485506
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	NEYDA FERNANDEZ		
Owner:	MARIN, VERENA JULIA		
	3409 47TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132485506	Tracking #:	293769
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00001000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEXACO-NEYDAS BUY & FLY (Continued)

U001354035

Facility ID:	298624771	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	NEYDA FERNANDEZ		
Contact:	Not reported	Facility Phone:	8132485506
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	NEYDA FERNANDEZ		
Owner:	MARIN, VERENA JULIA		
	3409 47TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132485506	Tracking #:	293769
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEXACO-NEYDAS BUY & FLY (Continued)

U001354035

Facility ID:	298624771	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	NEYDA FERNANDEZ		
Contact:	Not reported	Facility Phone:	8132485506
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	NEYDA FERNANDEZ		
Owner:	MARIN, VERENA JULIA		
	3409 47TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132485506	Tracking #:	293769
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Compartmented, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## TEXACO-NEYDAS BUY & FLY (Continued)

U001354035

Facility ID:	298624771	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	NEYDA FERNANDEZ		
Contact:	Not reported	Facility Phone:	8132485506
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	NEYDA FERNANDEZ		
Owner:	MARIN, VERENA JULIA		
	3409 47TH ST		
	TAMPA, FL 33605		
Owner's Phone:	8132485506	Tracking #:	293769
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	2	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	FRP clad steel, Spill cnmt, Op-flow shut off, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

230

ESPINET TRUCK REPAIRS  
901 E PLATT ST  
TAMPA, FL 33602

UST  
LUST

U000102993  
N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ESPINET TRUCK REPAIRS (Continued)

U000102993

### LUST:

Facility ID:	9102527	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132899318	Discovery Date:	06/19/92
Tracking Number:	Not reported	Score:	022 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	05478		
Class:	Not reported		
Category:	Not reported		

### INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

### INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	KEROSENE	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	WASTE OIL	Est. Gallons Lost:	UNKNOWN

### INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

### INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

### INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

### INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

### INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

### INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ESPINET TRUCK REPAIRS (Continued)

U000102993

### UST:

Facility ID:	299102527	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ESPINET TRUCK REPAIRS		
Contact:	Not reported	Facility Phone:	8132899318
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910801	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	CARTER B MCCAIN		
Owner:	TAMPA BAY ARENA %CARTER B MCCAIN		
	111 E MADISON ST #2300		
	TAMPA, FL 33602		
Owner's Phone:	8132734226	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ESPINET TRUCK REPAIRS (Continued)

U000102993

Facility ID:	299102527	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ESPINET TRUCK REPAIRS		
Contact:	Not reported	Facility Phone:	8132899318
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910801	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	CARTER B MCCAIN		
Owner:	TAMPA BAY ARENA %CARTER B MCCAIN		
	111 E MADISON ST #2300		
	TAMPA, FL 33602		
Owner's Phone:	8132734226	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## ESPINET TRUCK REPAIRS (Continued)

U000102993

Facility ID:	299102527	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ESPINET TRUCK REPAIRS		
Contact:	Not reported	Facility Phone:	8132899318
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	910801	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	CARTER B MCCAIN		
Owner:	TAMPA BAY ARENA %CARTER B MCCAIN		
	111 E MADISON ST #2300		
	TAMPA, FL 33602		
Owner's Phone:	8132734226	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00000550	Any monit. wells:	0
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

230	PRESTIGE TAXI 901 PLATT ST TAMPA, FL 33602	RCRIS-SQG FINDS	1000388838 FLD146749783
231	WD FARMS,INC. 1010 E PLATT ST TAMPA, FL 33602	UST	U001355561 N/A

231

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WD FARMS,INC. (Continued)

U001355561

### UST:

Facility ID:	298735617	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WD FARMS,INC.		
Contact:	Not reported	Facility Phone:	8132291912
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871020	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	WILL WILLIAMS		
Owner:	W D FARMS INC		
	PO BOX 81		
	RIVERVIEW, FL 335690081		
Owner's Phone:	8132291912	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WD FARMS,INC. (Continued)

U001355561

Facility ID:	298735617	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WD FARMS,INC.		
Contact:	Not reported	Facility Phone:	8132291912
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871020	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WILL WILLIAMS		
Owner:	W D FARMS INC		
	PO BOX 81		
	RIVERVIEW, FL 335690081		
Owner's Phone:	8132291912	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WD FARMS,INC. (Continued)

U001355561

Facility ID:	298735617	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WD FARMS,INC.		
Contact:	Not reported	Facility Phone:	8132291912
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871020	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	WILL WILLIAMS		
Owner:	W D FARMS INC		
	PO BOX 81		
	RIVERVIEW, FL 335690081		
Owner's Phone:	8132291912	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

291

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WD FARMS,INC. (Continued)

U001355561

Facility ID:	298735617	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WD FARMS,INC.		
Contact:	Not reported	Facility Phone:	8132291912
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871020	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	WILL WILLIAMS		
Owner:	W D FARMS INC		
	PO BOX 81		
	RIVERVIEW, FL 335690081		
Owner's Phone:	8132291912	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Fuel oil-on site heat	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## WD FARMS,INC. (Continued)

U001355561

Facility ID:	298735617	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WD FARMS,INC.		
Contact:	Not reported	Facility Phone:	8132291912
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871020	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	WILL WILLIAMS		
Owner:	W D FARMS INC		
	PO BOX 81		
	RIVERVIEW, FL 335690081		
Owner's Phone:	8132291912	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

232

GARRISON STEVEDORING,INC.  
1101 E ELLA MAE ST  
TAMPA, FL 33602

UST  
LUST

U001354527  
N/A



MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

GARRISON STEVEDORING,INC. (Continued)

U001354527

LUST:

Facility ID:	8625300	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	8132291958	Discovery Date:	02/01/93
Tracking Number:	Not reported	Score:	035
Facility Code:	Not reported	Status:	Not reported
Rank:	03338		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	CONTAMINATION ASSESSMENT REPORT
Extension Status:	APPROVED
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## GARRISON STEVEDORING,INC. (Continued)

U001354527

### UST:

Facility ID:	298625300	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GARRISON STEVEDORING,INC.		
Contact:	Not reported	Facility Phone:	8132291958
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE H. PATE		
Owner:	PATE STEVEDORING CO.		
	1101 ELLA MAE AVE		
	TAMPA, FL 33602		
Owner's Phone:	8132291958	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

GARRISON STEVEDORING,INC. (Continued)

U001354527

Facility ID:	298625300	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GARRISON STEVEDORING,INC.		
Contact:	Not reported	Facility Phone:	8132291958
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE H. PATE		
Owner:	PATE STEVEDORING CO. 1101 ELLA MAE AVE TAMPA, FL 33602		
Owner's Phone:	8132291958	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00004000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

## GARRISON STEVEDORING,INC. (Continued)

U001354527

Facility ID:	298625300	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GARRISON STEVEDORING,INC.		
Contact:	Not reported	Facility Phone:	8132291958
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	GEORGE H. PATE		
Owner:	PATE STEVEDORING CO. 1101 ELLA MAE AVE TAMPA, FL 33602		
Owner's Phone:	8132291958	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00002000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	No
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Man sample wells		

233

SUN OIL  
1021 E ELLA MAE ST  
TAMPA, FL 33602

LUST  
AST

S101264766  
N/A

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

SUN OIL (Continued)

S101264766

LUST:

Facility ID:	9300570	Facility Type:	NON-RETAIL BUSINESS
Alias Name:	Not reported		
Telephone:	Not reported	Discovery Date:	03/12/93
Tracking Number:	Not reported	Score:	006 (LOW)
Facility Code:	Not reported	Status:	Not reported
Rank:	09432		
Class:	Not reported		
Category:	Not reported		

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

INCIDENT PROGRAM INFORMATION -

Incident Program:	Not reported
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	APPROVED
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	CONTAMINATION ASSESSMENT REPORT
Extension Status:	APPROVED
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

233

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

SUN OIL (Continued)

S101264766

AST:

Facility ID:	299300570	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA PORT AUTHORITY		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	930622	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	HAROLD PEMBERTON		
Owner:	TAMPA PORT AUTHORITY PO BOX 2192 TAMPA, FL 336012192		
Owner's Phone:	8132481924	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000888
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299300570	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA PORT AUTHORITY		
Facility Phone:	Not reported	Permit Section:	Not reported
Date entered:	930622	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	HAROLD PEMBERTON		
Owner:	TAMPA PORT AUTHORITY PO BOX 2192 TAMPA, FL 336012192		
Owner's Phone:	8132481924	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000888
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

233

SUNMARK PETROLEUM MARKETING TERM  
1021 ELLAMAE AVE  
TAMPA, FL 33601

RCRIS-SQG  
FINDS

1000497566  
FLD073194490

Other Pertinent Environmental Activity Identified at Site:  
facility is involved with pesticide/toxic substances production

233

# MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

233	SUN OIL CO OF PA. TAMPA TERM 1021 ELLAMAE ST TAMPA, FL 33602	FINDS	1000932231 FL0000597443
-----	--	-------	----------------------------

234	7-ELEVEN FOOD STORE #27433 5007 PALM RIVER RD TAMPA, FL 33619	UST LUST	U001355558 N/A
-----	---	-------------	-------------------

## LUST:

Facility ID:	8735552	Facility Type:	RETAIL STATION
Alias Name:	Not reported		
Telephone:	4072950979	Discovery Date:	09/24/87
Tracking Number:	291938	Score:	031
Facility Code:	Not reported	Status:	Not reported
Rank:	03984		
Class:	Not reported		
Category:	Not reported		

## INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

## INCIDENT POLLUTANT INFORMATION -

Pollutant:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
------------	--------------	--------------------	---------

## INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

## INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

## INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

## INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

## INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

## INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Region:	STATE

234

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## 7-ELEVEN FOOD STORE #27433 (Continued)

U001355558

### UST:

Facility ID:	298735552	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLO SMITH		
Contact:	Not reported	Facility Phone:	4072950979
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871016	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLO SMITH		
Owner:	SOUTHLAND CORP		
	1304 LEE RD		
	ORLANDO, FL 32810		
Owner's Phone:	4072950979	Tracking #:	291938
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	87/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		



# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## 7-ELEVEN FOOD STORE #27433 (Continued)

U001355558

Facility ID:	298735552	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLO SMITH		
Contact:	Not reported	Facility Phone:	4072950979
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871016	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLO SMITH		
Owner:	SOUTHLAND CORP		
	1304 LEE RD		
	ORLANDO, FL 32810		
Owner's Phone:	4072950979	Tracking #:	291938
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	87/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## 7-ELEVEN FOOD STORE #27433 (Continued)

U001355558

Facility ID:	298735552	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLO SMITH		
Contact:	Not reported	Facility Phone:	4072950979
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	871016	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLO SMITH		
Owner:	SOUTHLAND CORP 1304 LEE RD ORLANDO, FL 32810		
Owner's Phone:	4072950979	Tracking #:	291938
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	No
Tank Cap. (Gals):	00010000	Any monit. wells:	1
Tank position:	Underground	Any contam. groundwater:	Yes
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	87/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Overfill-ball check, FRP clad steel, Spill cnmt, Op-tight fill		
Tank Piping:	Fiberglass, Pressurized piping, Dispenser liners		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

235	FREE PRESS PUBLISHING CO INC 401 E PLATT ST TAMPA, FL 33601	FINDS	1000734946 FLD982090938
235	FREE PRESS PUBLISHING CO INC 401 E PLATT ST TAMPA, FL 33601	RCRIS-SQG	1000700209 FLD982090938
236	RAYBRO ELECTRIC SUPPLIES,INC 907 E ELLA MAE ST TAMPA, FL 33602	UST	U001354466 N/A

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RAYBRO ELECTRIC SUPPLIES,INC (Continued)

U001354466

### UST:

Facility ID:	298625233	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RAYBRO ELECTRIC SUPPLIES,INC		
Contact:	Not reported	Facility Phone:	8132288571
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	W E HALSEY		
Owner:	RAYBRO ELECTRIC SUPPLIES INC		
	PO BOX 1351		
	TAMPA, FL 336011351		
Owner's Phone:	8132288571	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	75/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

236

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## RAYBRO ELECTRIC SUPPLIES,INC (Continued)

U001354466

Facility ID:	298625233	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RAYBRO ELECTRIC SUPPLIES,INC		
Contact:	Not reported	Facility Phone:	8132288571
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	W E HALSEY		
Owner:	RAYBRO ELECTRIC SUPPLIES INC		
	PO BOX 1351		
	TAMPA, FL 336011351		
Owner's Phone:	8132288571	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	75/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

236

MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

RAYBRO ELECTRIC SUPPLIES,INC (Continued)

U001354466

Facility ID:	298625233	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RAYBRO ELECTRIC SUPPLIES,INC		
Contact:	Not reported	Facility Phone:	8132288571
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	W E HALSEY		
Owner:	RAYBRO ELECTRIC SUPPLIES INC		
	PO BOX 1351		
	TAMPA, FL 336011351		
Owner's Phone:	8132288571	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	75/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Man sample wells		

237

ROYAL CROWN BOTTLING  
701 E ELLA MAE ST  
TAMPA, FL 33602

UST

U001354474  
N/A

237

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROYAL CROWN BOTTLING (Continued)

U001354474

### UST:

Facility ID:	298625242	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROYAL CROWN BOTTLING		
Contact:	Not reported	Facility Phone:	8132290101
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	C. ANDERSON		
Owner:	ROYAL CROWN BOTTLING		
	701 ELLAMAE AVE		
	TAMPA, FL 33602		
Owner's Phone:	8132290101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

237

# MAP FINDINGS

Map ID  
Direction  
Distance

Site

Database(s)

EDR ID Number  
EPA ID Number

## ROYAL CROWN BOTTLING (Continued)

U001354474

Facility ID:	298625242	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROYAL CROWN BOTTLING		
Contact:	Not reported	Facility Phone:	8132290101
Permit Section:	Not reported	Region:	STATE
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	C. ANDERSON		
Owner:	ROYAL CROWN BOTTLING		
	701 ELLAMAE AVE		
	TAMPA, FL 33602		
Owner's Phone:	8132290101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Underground	Any contam. groundwater:	Not reported
Tank Content:	Leaded gas	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Eligibility:	Not reported	Eligible Date:	Not reported
Permit Number:	Not reported		
Class:	Not reported		
Category:	Not reported		
Tank Constr.:	Bare/asph steel		
Tank Piping:	Corrosion resis coated		
Petro. Monitoring:	Man sample wells		

238

## DIVERSIFIED ENVIRONMENTAL SERVICES 1825 KNOX RD TAMPA, FL 33675

RCRIS-LQG 1000978565  
RCRIS-TSD FLD984183566

### RCRIS:

Owner: CURT LESSL, VP  
(813) 248-3256

Contact: CURT LESSL  
(813) 248-3256

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (N)	State Inspection	D001	.00000 (T)	Notification
D001	.00000 (N)	Part A			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

There are 3 compliance/violation record(s) reported at this site:

Evaluation	Date	Violations
OTHER EVALUATION	24-JUN-92	YES
COMPLIANCE SCHEDULE EVALUATION (CSE)	09-JUN-92	YES

MAP FINDINGS

Map ID Direction Distance	Site		Database(s)	EDR ID Number EPA ID Number
<b>DIVERSIFIED ENVIRONMENTAL SERVICES (Continued)</b>				
	COMPLIANCE EVALUATION INSPECTION (CEI)	18-MAY-92	YES	1000978565



ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
ARCADIA	1000740229	CIRCLE K #7082	516 S BREVARD	33619	FINDS	
ARCADIA	1000740226	CIRCLE K #7136	1401 E OAK ST	33619	FINDS	
ASTATULA	1000740214	CIRCLE K #7416	13512 GEORGIA AVE	33619	FINDS	
AUBURNDALE	1000739883	CIRCLE K #7289	SR 546 THORNHILL RD	33619	FINDS	
AUBURNDALE	1000739884	CIRCLE K #7286	GANDY DAIRY RD	33619	FINDS	
AVON PARK	1000740192	CIRCLE K #7350	3061 US HWY 64TH E	33619	FINDS	
AVON PARK	1000740193	CIRCLE K #7186	1499 N LAKE AVE	33619	FINDS	
BARTOW	1000739894	CIRCLE K #7267	SR 60/80 FT RD	33619	FINDS	
BIG COPPIT	1000740091	CIRCLE K #1707	1190 OVERSEAS HWY	33619	FINDS	
BITHLO	1000739839	CIRCLE K #7502	16959 E COLONIAL DR	33619	FINDS	
BITHLO	1000739838	CIRCLE K #7340	18620 E COLONIAL DR	33619	FINDS	
BITHLO	1000739760	CIRCLE K #7190	18001 E COLONIAL DR	33619	FINDS	
BONITA SPRINGS	1000739997	CIRCLE K #7356	13550 US HWY 41 WIGGINS	33619	FINDS	
BOWLING GREEN	1000740230	CIRCLE K #7203	US HWY 17/HARDY RD	33619	FINDS	
BRADENTON	1000740251	CIRCLE K #7464	5913 SR 70	33619	FINDS	
BRADENTON	1000740249	CIRCLE K #7520	100 W GULF DR	33619	FINDS	
BRADENTON	1000740256	CIRCLE K #1686	6410 64TH ST E	33619	FINDS	
BRANDON	94244483	SE CORNER OF MYRTLE AND BELL SHOALS RDS		33602	ERNS	
BRANDON	1000735508	JAMES PONTIAC	9740 SR 60	33619	FINDS	
BRANDON	1000703415	HILLSBOROUGH CO MCLANE JR HIGH SCHO	306 KNIGHTS AVE	33605	RCRIS-SQG	
BROWNVILLE	1000740227	CIRCLE K #7256	US HWY 17 SR 660	33619	FINDS	
CAPE CORAL	1000740001	CIRCLE K #7463	NE 3 PINE ISLAND RD	33619	FINDS	
CASSIA	1000740121	CIRCLE K #7426	US HWY 44/OAK ST	33619	FINDS	
CHIEFLAND	1000740201	CIRCLE K #2812	MAIN ST/US HWY 19-98	33619	FINDS	
CLAIR MEL	U001354733	7-ELEVEN FOOD STORE #24223	7711 22ND AVE	33619	UST, LUST	8625520
COCOA	1000740149	CIRCLE K #7423	4665 N US HWY 1	33619	FINDS	
DADE CITY	1000740176	CIRCLE K #7038	US 301/52A	33619	FINDS	
DADE CITY	1000740172	CIRCLE K #7070	US HWY 301/SR 575 S	33619	FINDS	
DAVENPORT	1000739897	CIRCLE K #7360	US HWY 17-92 N	33619	FINDS	
DOVER	1000739811	CIRCLE K #7031	6049 US HWY 60	33619	FINDS	
EAGLE LAKE	1000739902	CIRCLE K #7001	1105 S HOLLAN	33619	FINDS	
ESTERO	1000739878	CIRCLE K #7445	20260 US HWY 41 N	33619	FINDS	
EVERGLADES	1000739996	CIRCLE K #7330	CR CAMELIA COLLIER	33619	FINDS	
FLORAL CITY	1000740098	CIRCLE K #7211	5601 S FLORIDA AVE	33619	FINDS	
FORT LAUDERDALE	1000740285	CIRCLE K #4865	5724 W COMMERCIAL B	33619	FINDS	
FORT MYERS	1000739981	CIRCLE K #7399	19451 SR 31	33619	FINDS	
FORT MYERS	1000739982	CIRCLE K #7400	15500 HENDRY DR	33619	FINDS	
FORT MYERS	1000740295	CIRCLE K #4850	16768 MCGREGOR BLVD	33619	FINDS	
FORT MYERS	1000740003	CIRCLE K #4752	1709 SAN CARLOS BLVD	33619	FINDS	
GIBSONTON	1000739829	CIRCLE K #7032	12130 US HWY 41 S G	33619	FINDS	
GOLDEN GATE	1000739995	CIRCLE K #7332	4744 GOLDEN GATE PKWY	33619	FINDS	
HAINES CITY	1000739886	CIRCLE K #7279	SR 580 MARION CREEK	33619	FINDS	
HERNANDO	1000740099	CIRCLE K #7298	6695 N CARL G ROSE	33619	FINDS	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
HOBE SOUND	1000740207	CIRCLE K #7410	8755 SE FEDERAL HWY	33619	FINDS	
HOMOSASSA	1000740104	CIRCLE K #7235	7160 W GROVER CLEVELAND	33619	FINDS	
HOMOSASSA	1000740105	CIRCLE K #7497	6775 S SUNCOAST BLVD	33619	FINDS	
HUDSON	1000740262	CIRCLE K #1861	12834 SR 52	33619	FINDS	
HUDSON	1000740261	CIRCLE K #8541	10011 HAMILTON RD	33619	FINDS	
HUDSON	1000740265	CIRCLE K #7447	15831 US HWY 19	33619	FINDS	
HUDSON	1000740264	CIRCLE K #7096	14011 US HWY 19	33619	FINDS	
HUDSON	1000740263	CIRCLE K #4012	12838 US HWY 19 N	33619	FINDS	
IMMOKALEE	1000739985	CIRCLE K #7311	2307 LAKE TRAFFORD	33619	FINDS	
INGLIS	1000740200	CIRCLE K #7234	SR 40 A MI W US HWY 19	33619	FINDS	
KEY WEST	1000740097	CIRCLE K #8815	32 N ROOSEVELT BLVD	33619	FINDS	
KEYSVILLE	1000739825	CIRCLE K #7323	SR 640 E	33619	FINDS	
KISSIMMEE	1000740119	CIRCLE K #7466	3280 BOGGY CREEK RD	33619	FINDS	
KISSIMMEE	1000740118	CIRCLE K #7124	2680 N MAIN ST	33619	FINDS	
LA BELLE	1000740220	CIRCLE K #7374	3109 SR 29	33619	FINDS	
LAKE PLACID	1000740185	CIRCLE K #7451	US HWY 70/HWY 27 S	33619	FINDS	
LAKE WALES	1001023845	PHENIX SUPPLY	SR 60 & INDIAN LAKE ESTATES	33605	RCRIS-LQG	
LAKELAND	U001370913	NICKS DISCOUNT BEVERAGE	114 E EDGEWOOD DR	33619	UST, LUST	8624263
LAKELAND	1000739875	CIRCLE K #7334	US HWY 98 ROCK RIDGE RD	33619	FINDS	
LAKELAND	1000739874	CIRCLE K #7347	US HWY 92 W CO LINE RD	33619	FINDS	
LAKELAND	1000739895	CIRCLE K #8817	100 E MEMORIAL BLVD	33619	FINDS	
LAKELAND	1000739866	CIRCLE K #7020	8324 N RD 98	33619	FINDS	
LAKELAND	1000739868	CIRCLE K #7088	SWC OLD US HWY 37 PIPK	33619	FINDS	
LAKEPORT	1000740205	CIRCLE K #7348	APEX SR 78/SR S-721	33619	FINDS	
LAND O LAKES	1000740171	CIRCLE K #7273	US HWY 41/CYPRESS B	33619	FINDS	
LAND O LAKES	1000740178	CIRCLE K #8540	4337 LAND O LAKES	33619	FINDS	
LECANTO	1000740100	CIRCLE K #7504	CR 491/44	33619	FINDS	
LITHIA	1000739827	CIRCLE K #7202	SEC US HWY 39/HWY 640	33619	FINDS	
LONGWOOD	1000739910	CIRCLE K #7460	1450 SR 427	33619	FINDS	
MADERA BEACH	95305083			33606	ERNS	
MANGO	1000739823	CIRCLE K #7027	11505 E SR 574	33619	FINDS	
MARATHON	1000740093	CIRCLE K #2386	11100 OVERSEAS HWY	33619	FINDS	
MERRITT ISLAND	1000740160	CIRCLE K #4724	4282 N COURTENAY PK	33619	FINDS	
MONTVERDE	1000740213	CIRCLE K #7351	SR 455/RR AVE	33619	FINDS	
MOORE HAVEN	1000740203	CIRCLE K #7276	284 US HWY 27	33619	FINDS	
MOUNT DORA	1000739837	CIRCLE K #7444	6551 N US HWY 441	33619	FINDS	
MULBERRY	1000905916	TAMPA ELECTRIC CO POLK POWER STATIO	9995 SR 37 SOUTH	33602	RCRIS-SQG, FINDS	
NAPLES	1000739845	CIRCLE K #7488	488 HUNTER BLVD	33619	FINDS	
NAPLES	1000739843	CIRCLE K #8813	155 VANDERBILT BEACH	33619	FINDS	
NEW PORT RICHEY	1000735396	NEW PORT RICHEY GARAGE	1205 REES ST	33619	FINDS	
NOBLETON	1000740221	CIRCLE K #7157	SR 476/RIVER RD	33619	FINDS	
NORTH FORT MYERS	1000739991	CIRCLE K #7262	2171 LAUREL LA	33619	FINDS	
OCALA	1000740110	CIRCLE K #8614	917 N W PINE AVE	33619	FINDS	
OCOEEE	1000739764	CIRCLE K #7440	437 APOPKA OCOEE RD	33619	FINDS	
OCOEEE	1000739762	CIRCLE K #7185	1485 WURST RD	33619	FINDS	
OKEECHOBEE	1000740218	CIRCLE K #7313	SEC 14TH BUCKHEAD RD	33619	FINDS	
ORLANDO	1000739772	CIRCLE K #1801	1349 N MILLS AVE	33619	FINDS	

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
ORLANDO	1000739779	CIRCLE K #7510	6201 N ORANGE BLOSSOM TR	33619	FINDS	
ORLANDO	1000739741	CIRCLE K #8513	2705 SILVER STAR RD	33619	FINDS	
PALM HARBOR	1000740271	CIRCLE K #8530	2770 US HWY 19 N	33619	FINDS	
PALMETTO	1000740259	CIRCLE K #1583	1111 US HWY 301	33619	FINDS	
PEMBROKE PINES	1000740283	CIRCLE K #8526	3990 W HALLENDALE B	33619	FINDS	
PINE ISLAND	1000739880	CIRCLE K #4321	10521 SPRINGFELLOW	33619	FINDS	
PLANT CITY	94236289	HIGHWAY 37 AND HARPER		33602	ERNS	
PLANT CITY	1000703438	HILLSBOROUGH CO TURKEY CREEK JR HI	5005 S TURKEY CREEK RD	33605	RCRIS-SQG	
PLANT CITY	1000687515	HILLSBOROUGH CO TOMLIN JR HIGH SCHO	501 WOODROW WILSON ST	33605	RCRIS-SQG	
PORT CHARLOTTE	1000739818	CIRCLE K #7459	41 TAMiami TR	33619	FINDS	
PORT CHARLOTTE	1000739816	CIRCLE K #7413	2512 TAMiami TR	33619	FINDS	
PORT ST LUCIE	1000740137	CIRCLE K #7430	26010 US HWY 1	33619	FINDS	
PORT ST LUCIE	1000740142	CIRCLE K #7405	2902 SW PORT ST LUCIE	33619	FINDS	
PUNTA GORDA	1000739819	CIRCLE K #7409	11161 US HWY 41	33619	FINDS	
RIDGE MANOR	1000740202	CIRCLE K #7296	US HWY 50/HWY 301	33619	FINDS	
RIVERVIEW	1000739830	CIRCLE K #7149	11401 US HWY 301 S	33619	FINDS	
RIVERVIEW	1000739854	CIRCLE K #7288	7502 RIVERVIEW DR	33619	FINDS	
SANFORD	1000739914	CIRCLE K #7507	2201 W 1ST ST	33619	FINDS	
SANFORD	1000739908	CIRCLE K #7498	2501 AIRPORT BLVD	33619	FINDS	
SEBRING	1000740187	CIRCLE K #7515	US HWY 27/HWY 98	33619	FINDS	
SEFFNER	1000736384	HILLSBORO CO ARMWOOD HIGH SCH	12000 US HWY 92	33605	FINDS	
SEFFNER	1000703425	HILLSBORO CO ARMWOOD HIGH SCHOOL	12000 US HWY 92	33605	RCRIS-SQG	
SEFFNER	1000739851	CIRCLE K #7401	6301 US HWY 579	33619	FINDS	
SILVER SPRINGS	1000740107	CIRCLE K #5048	5182 E US HWY 40	33619	FINDS	
SORRENTO	1000740211	CIRCLE K #7275	24520 SR 44	33619	FINDS	
SPRING HILL	1000822390	CIRCLE K #7486	13077 CORTEZ BLVD	33619	RCRIS-SQG, FINDS	
ST. PETERSBURG	94240064			33602	ERNS	
SUNRISE	1000740195	CIRCLE K #8534	1140 SW 160TH AVE	33619	FINDS	
TAFT	1000739835	CIRCLE K #7199	32 2ND AVE	33619	FINDS	
TAMPA	95316504				ERNS	
TAMPA	95316502				ERNS	
TAMPA	95315777				ERNS	
TAMPA	95315498				ERNS	
TAMPA	95315014				ERNS	
TAMPA	95312952				ERNS	
TAMPA	95311412				ERNS	
TAMPA	95311403				ERNS	
TAMPA	95308988				ERNS	
TAMPA	95309793				ERNS	
TAMPA	95308987				ERNS	
TAMPA	95308064				ERNS	
TAMPA	95306689				ERNS	
TAMPA	95306185				ERNS	
TAMPA	95306184				ERNS	
TAMPA	95304245				ERNS	
TAMPA	95303902				ERNS	
TAMPA	95302927				ERNS	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	95300771				ERNS	
TAMPA	95296922				ERNS	
TAMPA	95291801				ERNS	
TAMPA	95293250				ERNS	
TAMPA	95285083				ERNS	
TAMPA	95279210				ERNS	
TAMPA	95282435				ERNS	
TAMPA	95277769				ERNS	
TAMPA	S100021000	SPE RECYCLING C & D FACIL			SWF/LF	
TAMPA	8806506	TAMPA GENERAL HOSPITAL			ERNS	
TAMPA	9001491	MARITIME BLVD AND SHORELINE			ERNS	
TAMPA	9003707	MARITIME AND SHORELINE AVENUE			ERNS	
TAMPA	9003701	I-275/HOWARD AVENUE			ERNS	
TAMPA	9101451	ANCLOTE ICE PLANT ANCLOTE RIVER			ERNS	
TAMPA	9009719	HOOKER'S POINT STATION HEMLOCH ST.			ERNS	
TAMPA	9007043	STATE ROUTE 41 AND BIG BEND RD.			ERNS	
TAMPA	9006743	5881 IMGRAHM ST			ERNS	
TAMPA	9003271	FILTER CLEAN INC.			ERNS	
TAMPA	9001049	YEOMAN YARD			ERNS	
TAMPA	9002940	NORTH OF 275			ERNS	
TAMPA	9001875	HIMES AND COLUMBUS			ERNS	
TAMPA	93001510	4700 WHITEWAY DR.			ERNS	
TAMPA	94254708	3701 CAUSEWAY BLVD			ERNS	
TAMPA	9202434	RESIDENCE-161 GROVE ST			ERNS	
TAMPA	8705033	TRANSUS TRUCKING CO. 9801 PALM RIVER RD.			ERNS	
TAMPA	8701952	800 BLOCK WEST BRADDOCK AND ALFRED			ERNS	
TAMPA	8806268	I-4 AT 36TH STREET WEST BOUND LANES			ERNS	
TAMPA	8905266	GARDINIER FERTILIZER PLANT			ERNS	
TAMPA	8911109	22ND STREET OF BUFFALO AVENUE			ERNS	
TAMPA	8911118	ADAMS & 50TH STREET			ERNS	
TAMPA	8911094	SAN PADREO STREET AND CHURCH AVENUE			ERNS	
TAMPA	8904757	SAN PADRO ST AND CHURCH AVE			ERNS	
TAMPA	8911063	NORTH WEST SHORE BOULEVARD AND WEST GRAV			ERNS	
TAMPA	93000920	ROCK PORT			ERNS	
TAMPA	95010228				HMIRS	
TAMPA	8800753	15746 GARDENSIDE LN			ERNS	
TAMPA	8804062	AL LOPEZ STADIUM			ERNS	
TAMPA	94215061				ERNS	
TAMPA	94257720	TOWN AND COUNTRY 6707 LEEWARD ISLAND WAY			ERNS	
TAMPA	8705439	CORK RD AND THONOAASSASSO RD			ERNS	
TAMPA	8704914	40TH ST AND 21ST AVE			ERNS	
TAMPA	8701807	INTERSECTION OF GUNN HWY AND HENDERSON R			ERNS	
TAMPA	8702450	J.D. SMITH EXTERMINATORS			ERNS	
TAMPA	8901968	DALE MABRY EXIT RAMP ONTO BUSH BLVD			ERNS	
TAMPA	8705049	CAMELOT APARTMENTS			ERNS	
TAMPA	8700833	3000FT SOUTH OF RUNWAY 22			ERNS	
TAMPA	9200444	HWY 361			ERNS	

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	8705674	MACINTOSH RD AND US 301			ERNS	
TAMPA	8705671	NEBRASKA AVE AND BEARESS RD			ERNS	
TAMPA	94236234	YULMAN YARD			ERNS	
TAMPA	9110837	88 E HAMLIN ST EAST SHORE OF LAKE UNION			ERNS	
TAMPA	8800210	PARKING LOT OF AYRES DINER, CORNER OF DALE MAVRY RD AND GRAC			ERNS	
TAMPA	92050480				HMIRS	
TAMPA	9200518	PO BOX 547			ERNS	
TAMPA	94252488				ERNS	
TAMPA	8800445	ON HIWAY 674			ERNS	
TAMPA	9109740	2600 FEDERAL AVE			ERNS	
TAMPA	9108829	PO BOX 849 HWY 366 AND 32ND ST.			ERNS	
TAMPA	94247034	MANATEE PORT			ERNS	
TAMPA	8702464	NITRAN			ERNS	
TAMPA	8701693	TAMPA AIR PORT, NEAR POLICEMAN HANGER			ERNS	
TAMPA	9108969	1150 MURPHY AVE GROUND/PARKING LOT/SEWER			ERNS	
TAMPA	9106525	PLATFORM A			ERNS	
TAMPA	94272866	200 MILES OUT OF COZUMEL ENROUTE TO TAMPA			ERNS	
TAMPA	94267760	PEIR 251			ERNS	
TAMPA	94269396	5881 INGRAHAM			ERNS	
TAMPA	90020086				HMIRS	
TAMPA	94120774				HMIRS	
TAMPA	8703008	7512 PAULA DRIVE AND TOWN AND COUNTRY BLVD			ERNS	
TAMPA	94242206	TAMPA PORT AUTHORITY BERTH 227			ERNS	
TAMPA	94241873	INTERSTATE 4 EASTBOUND AT MILE 13-14			ERNS	
TAMPA	94263239	AMERADA HESS TERMINAL			ERNS	
TAMPA	94263238	ARMADA HESS CORP 504 NORTH 19TH STREET			ERNS	
TAMPA	94272690	AGRICO BIG BEN TERMINAL			ERNS	
TAMPA	94260843	PORT MANATEE			ERNS	
TAMPA	8705589	INTERSECTION OF STATE RD 39 AND SAM ALLUN RD, NE SECTION OF			ERNS	
TAMPA	94266954	INTERSTATE 75 NORTHBOUND MILE MARKER 277			ERNS	
TAMPA	94266514	SADCO NO 220			ERNS	
TAMPA	94264027	ENROUTE FM PUERTO RICO TO TAMPA			ERNS	
TAMPA	94234604	CF INDUSTRIES AMMONIA TERMINAL 3222 MARITIME BLVD			ERNS	
TAMPA	95274989			33605	ERNS	
TAMPA	94272493	SOLOMON BROTHERS INVEST. 8800 HIDDEN RIVER PKWY		33605	ERNS	
TAMPA	94231499	8500 HIDDEN RIVER PKWY		33605	ERNS	
TAMPA	9111006	1724 KOPPERS ROAD		33605	ERNS	
TAMPA	95312807			33619	ERNS	
TAMPA	95297184			33619	ERNS	
TAMPA	95294313			33619	ERNS	
TAMPA	94266601	5321 HARTFORD ST		33619	ERNS	
TAMPA	94221105			33619	ERNS	
TAMPA	93001031	7105 6TH AVE		33619	ERNS	

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	95318546			33602	ERNS	
TAMPA	95318539			33602	ERNS	
TAMPA	95317009			33602	ERNS	
TAMPA	95315360			33602	ERNS	
TAMPA	95313273			33602	ERNS	
TAMPA	95312631			33602	ERNS	
TAMPA	95294931			33602	ERNS	
TAMPA	94251595	ROY JENKINS POOL 154 COLUMBIA DR	1102 N "B" ST	33606	UST, LUST	8627003
TAMPA	U001355079	BRINKS OF FL	US301 / I-4		SWF/LF	
TAMPA	S100021008	WASTE MANAGMT INC HW TRANSFER STA	4101A E 12TH AVE UNIT 2	33605	RCRIS-SQG, FINDS	
TAMPA	U00383814	CONSOLIDATED BATTERY SERVICES	13TH & YORK ST		UST, LUST	8626344
TAMPA	U001377986	COCA-COLA BOTTLING CO-TAMPA	519 S 19TH ST	33605	UST, LUST, AST	8509068
TAMPA	U002313159	STAR ENTERPRISE TERMINAL	504 N 19TH ST	33605	UST, LUST, AST	9100107
TAMPA	U001356198	HESS TERMINAL	200 N 19TH ST	33605	FINDS, UST, AST	298624988
TAMPA	1000497861	CARGILL INC	500 N 19TH ST	33605	FINDS, RCRIS-LOG, TSCA, UST	299100050
TAMPA	1000433691	CHEVRON USA INC	1701 N 20TH ST	33605	UST, LUST	9400234
TAMPA	U001823379	FLORIDA BUILDERS - VACANT	1711 S 20TH ST	33605	UST, LUST	8735470
TAMPA	U001355551	MUSSELMAN STEEL CORP.	425 S 20TH ST	33605	AST	
TAMPA	A100009024	MOBIL OIL CORP-MARATHON OIL CO TERMINA	1011 NO 21ST STREET		RCRIS-SQG, FINDS	
TAMPA	1000359135	AMERICAN FRAME & AXLE INC	22ND ST CAUSEWAY	33605	HMIRS	
TAMPA	94020790		22ND ST CAUSEWAY		HMIRS	
TAMPA	90050311		22ND ST CAUSEWAY		FINDS	
TAMPA	1000497294	CSX TRANSPORTATION	4012 S 22ND ST CAUSEWAY BLVD	33619	FINDS	
TAMPA	1000733273	FLEET TRANSPORT COMPANY INC	1101 N 29TH ST	33605	UST	298628836
TAMPA	U001355343	DURO BAY MFG. CO.	RT 3 BOX 24	33619	FINDS	
TAMPA	1000933557	PEAK OIL CO	ROUTE 3 BOX 511	33619	FINDS	
TAMPA	1000498864	TAMPA STEEL ERECTING	RT 3, BOX 498	33619	FINDS	
TAMPA	1000932294	CAREY SALT INC.	3315 HWY 301	33619	UST, LUST	8624783
TAMPA	U001354046	FL & SOUTH AMERICA HOLDINGS INC	1930 N 301	33619	RCRIS-SQG, FINDS	
TAMPA	1000498563	ENGINE SOURCE	US 301 AND STATE RD 60	33619	RCRIS-SQG, FINDS	
TAMPA	1000496573	SUNOCO SVC STA	1150 N 34TH ST	33605	RCRIS-SQG, FINDS	
TAMPA	1000821729	ENGINE LAB	1400 N 37TH ST	33605	RCRIS-SQG	
TAMPA	1000978616	QUALITY ELECTRIC SUPPLY INC	39TH ST EASTBOUND EXIT RAMP		UST	299401656
TAMPA	U001963249	FL DEPT OF TRANSPORTATION CROSSTOWN EX	US 41 S		UST, LUST, AST	8519988
TAMPA	U001045078	FL ROCK & TANK LINES	RT 41 / CR 41A	33619	UST	8735431
TAMPA	S101264744	NORTH AMERICAN SALT CO	6051 HWY 41-A		UST	298625120
TAMPA	U001377984	MCKESSON CHEMICAL CO.	HWY 41A	33619	FINDS	
TAMPA	1000932241	MCKESSON CHEMICAL CO	6049 HWY 41A S	33619	FINDS	
TAMPA	1000136097	VAN WATERS & ROGERS	6051 HWY 41AS	33619	FINDS	
TAMPA	1000932224	VAN WATERS & ROGERS INC	HWY 49		ERNS	
TAMPA	9106962	530 N. WITTER ST.	1235 NN 4TH AVE	33605	FINDS	
TAMPA	1000497537	MANNA PRO CORP	50TH ST EASTBOUND EXIT RAMP		UST	299401651
TAMPA	U001963247	FL DEPT OF TRANSPORTATION CROSSTOWN EX	50TH ST EASTBOUND EXIT RAMP		UST	299501714
TAMPA	U002217714	USE 9401651	50TH ST WESTBOUND ENTRY RAMP		UST	299401649
TAMPA	U001963246	FL DEPT OF TRANSPORTATION-S CROSSTOWN	4333 S 50TH ST	33619	UST, LUST	9102192
TAMPA	U001546653	ENERGY AMMONIA	50TH ST & END OF UCETA RD	33619	UST, LUST, AST	8734656
TAMPA	U001355521	SEABOARD SYSTEM RAILROAD, INC.				

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	U001355346	TEXACO-TURLEY'S	513 S 50TH ST	33619	UST, LUST	8628873
TAMPA	U001353957	CIRCLE K #7443	10039 HWY 574	33619	UST, LUST	8509050
TAMPA	1000111185	BAY DRUM	SR 574	33619	CERCLIS, FINDS	
TAMPA	1000733041	CAST CRETE CORP	SR 579.3/4 MI NORTH OF I-4	33619	FINDS	
TAMPA	U001378058	FL DEPT OF TRANSPORTATION	SR 580 - PIPER'S MARINE		UST, LUST	9102666
TAMPA	U001378030	CSX TRANSPORTATION INC-JACOB'S TRUCK	78TH ST		UST, LUST	9101415
TAMPA	1000310893	BRANDON BATTERY CO	1202B S 78TH ST	33619	RCRIS-SQG, FINDS	
TAMPA	U001356268	DIDDEN SHEET METAL	3514 E 7TH AVE	33605	UST, LUST	9100992
TAMPA	U001356108	TURLEY JAMES	4315 E 7TH AVE	33605	UST, LUST	9045817
TAMPA	U001355059	STRICK LEASING CORP.	4444 E 7TH AVE	33605	UST	298626940
TAMPA	U001354309	J W CONNER & SONS INC	4100 E 7TH AVE	33605	UST, LUST	8625068
TAMPA	U000687124	GARCIA, JOSEPH	4316 E 7TH AVE	33605	UST, LUST	9101517
TAMPA	U000119026	GARDNER-MARTIN ASPHALT CORP.	4001 E 7TH AVE	33605	UST, LUST	8628181
TAMPA	S101264762	CSX TRANSPORTATION INC-RALSTON PURINA	3702 E 7TH AVE	33605	LUST	9101417
TAMPA	1001023847	INDUSTRIAL AUTOMOTIVE PARTS INC	4002 E 7TH AVE	33605	RCRIS-SQG	
TAMPA	1000497117	THONI OIL MAGIC BENZOL GASOLIN	3012 SW 8 ST	33619	FINDS	
TAMPA	9103256	7016 WINONA DRIVE	MP 84.5		ERNS	
TAMPA	94060625		S 86TH ST		HMIRS	
TAMPA	U001378113	ACCENT MARINE	10410 HWY 92 E		UST, LUST	9201893
TAMPA	1000735187	CONSUMER PRODUCTS INC	10824 US 92 E	33602	FINDS	
TAMPA	S101011579	A & D RECYCLING TRANSFER STATION	7006 E 9TH AVE	33619	SWF/LF	
TAMPA	1000931875	GULF COAST METALS CO INC	6192 E 9TH AVE	33619	FINDS	
TAMPA	8901982	MARINA N OF SKYWAY BRIDGE,EAST OF I-275	ON A DOCK PILING		ERNS	
TAMPA	92080269		5100 ACLINE AVE		HMIRS	
TAMPA	92080115		5100 ACLINE AVE		HMIRS	
TAMPA	U001354513	USE #298623920	5100 ACLINE ST	33619	UST, LUST	8625284
TAMPA	U001546606	DEROSE INDUSTRIES	8504 E ADAMO DR		UST, LUST	9103587
TAMPA	1000502072	IND CHEM & SUP CO	3520 ADAMO DR	33605	FINDS	
TAMPA	1000735831	SGS CONTROL SERVICES INC.	4951 E ADAMO DR SUITE 210	33603	FINDS	
TAMPA	1000985923	SOUTH FLORIDA TANK WASH INC	7015A ADAMO DR RT 60	33619	RCRIS-SQG, FINDS	
TAMPA	1000502129	ALL TUNE & LUBE	9017 G ADAMO DR	33619	RCRIS-SQG, FINDS	
TAMPA	1000497732	PECKS PRODUCTS CO	7501 ADAMO DR HWY 60 E	33619	FINDS	
TAMPA	1000295223	FERMAN CHEVROLET	9751 ADAMO DRIVE	33619	RCRIS-SQG, FINDS, UST, LUST, AS1	8625458
TAMPA	1000116877	MAD HATTER MUFFLER TRANSMISSION	9017 C&D ADAMO DR	33619	RCRIS-SQG, FINDS	
TAMPA	91040182		5056 ADAMS DR		HMIRS	
TAMPA	1000376740	NISSAN OF BRANDON	9920 AFAMO DR	33619	RCRIS-SQG, FINDS	
TAMPA	91080614		ANDERSON RD		HMIRS	
TAMPA	1000736551	COASTAL FLEET FUELING	5805 ANDERSON RD	33619	FINDS	
TAMPA	1000450164	TAMPA PATHOLOGY LABORATORY	6515 ARMENIA AVE N	33603	RCRIS-SQG, FINDS	
TAMPA	S100990555	GARRISON CHANNEL	631 S ASHLEY ST		LUST	9301000
TAMPA	U001378037	BARNETT BANK BLDG-FORMER	2000 ASHLEY DR		UST, LUST	9101785
TAMPA	1000161395	NCNB TYPESETTING & COPY CENTER	400 N ASHLEY ST 16 FLOOR	33602	RCRIS-SQG, FINDS, UST	299045676
TAMPA	1000341443	CHLORIDE INCORPORATED	ATTN: D. REDIN	33619	CERCLIS, FINDS, TSCA	
TAMPA	1000298862	USAMEX FERTILIZERS, INC.	ATTN: G. HULL	33619	FINDS, TSCA	
TAMPA	1000388527	KOESTER BUICK INC	101 AUTO ROW	33619	RCRIS-SQG, FINDS	
TAMPA	U002113431	ALL POINTS WAREHOUSE-OLD GAS STATION	4701 7TH AVE		UST, LUST	9501491

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	U001823406	TAMPA MOBILE REPAIR	4701 7TH AVE	33605	UST, LUST	9400547
TAMPA	1000361426	FLORIDA STEEL CORP	5TH AVE & 28TH ST	33605	FINDS	
TAMPA	1000703413	HILLSBOROUGH CO JAMES MADISON JR HI	4444 BAYVISTA	33605	RCRIS-SQG	
TAMPA	1000738361	HILLSBOROUGH BUCHANAN JR HIGH SCHOO	1001 BEARS AVE	33605	FINDS	
TAMPA	1000703402	HILLSBOROUGH CO BUCHANAN JR HIGH SCHOO	1001 BEARS AVE	33605	RCRIS-SQG	
TAMPA	U001378101	USE 9201677	3001 NORTH BLVD		UST, LUST	9200783
TAMPA	1000243419	PATHOLOGISTS REFERENCE LAB	402 SOUTH BLVD	33606	RCRIS-SQG, FINDS	
TAMPA	S100020977	BOUGAINVILLEA TRASH LF	BOUGAINVILLEA / 46TH ST		SWF/LF	
TAMPA	1000348719	PUMPCO INC	5013 E BROADWAY	33605	RCRIS-SQG, FINDS	
TAMPA	1000262320	LEWIS PAINT CO	6503 E BROADWAY	33605	RCRIS-SQG, FINDS	
TAMPA	U001355161	ROUNTREE TRANSPORT INC	7021 E BROADWAY AVE	33619	UST, LUST	8627285
TAMPA	U001354960	ECOL #9854	6901 E BROADWAY AVE	33619	UST, LUST	8625757
TAMPA	U001354353	COMMERCIAL CARRIER CORP	6801 E BROADWAY AVE	33619	UST, LUST	8625113
TAMPA	1000822594	CIRCLE K #7073	6925 E BROADWAY	33619	UST, LUST	8625170
TAMPA	1000372715	LARRY'S AUTO BODY REPAIR	7203 E BROADWAY		RCRIS-SQG, FINDS, UST, LUST	
TAMPA	1000320213	TRANSMISSION TO GO INC	8004B E BROADWAY	33619	RCRIS-SQG, FINDS	
TAMPA	1000298007	COMMERCIAL CARRIER CORP	6801 E BROADWAY	33619	RCRIS-SQG, FINDS	
TAMPA	1000195106	MIKE & DAVES AUTO BODY	7212 EAST BROADWAY	33619	RCRIS-SQG, FINDS	
TAMPA	1000184810	JORDON AUTO REPAIR	52003 EAST BROADWAY	33619	RCRIS-SQG, FINDS	
TAMPA	U001356404	GREAT SOUTHERN PROPERTIES	4522 W BUFFALO AVE	33619	UST, LUST	9200943
TAMPA	U001355117	SOUTH FL ENGINEERS, INC.	5911 E BUFFALO AVE	33619	UST, LUST, AST	8627140
TAMPA	U001354869	UNITED 500 #541-KWICK PACK FOODS	5121 E BUFFALO AVE	33619	UST, LUST	8625663
TAMPA	U001354093	EXXON #4-9128	7227 E BUFFALO AVE	33619	UST, LUST	8624833
TAMPA	S100889060	UNION CARBIDE CORP-SOLVENTS	3202 CARBIDE AVE.	33605	FI Sites	
TAMPA	1000335909	UNION CARBIDE CORP/SOLVENTS TE	3202 CARBIDE AVE	33605	RCRIS-SQG, FINDS, CERC-NFRAP	
TAMPA	94110828		41S CARGILL		HMIRS	
TAMPA	90020623		CAUSEWAY BLVD		HMIRS	
TAMPA	1000733829	LEASEWAY TRANSP CORP	4212 22ST CAUSEWAY BLVD	33605	FINDS	
TAMPA	1000699280	LEASEWAY TRANSPORTATION CORP	4212 22ST CAUSEWAY BLVD	33605	RCRIS-SQG	
TAMPA	1000243609	ANTHONY DISTRIBUTORS INC	201 S CEASAR	33605	RCRIS-SQG, FINDS	
TAMPA	1000500823	AT&T TAMPA CUSTOMER SUPPORT CTR	6802 CITICORP BLVD STE 700	33619	RCRIS-SQG, FINDS	
TAMPA	U001378008	TAMPA DOWNTOWN INVEST LTD PROPERTY	CITY BLK WASHINGTON N MORGAN W		UST, LUST	8943604
TAMPA	1000735504	MARK J FALTUS	5020 N CLARK	33605	FINDS	
TAMPA	U001378083	CONTINENTAL AIRLINES RESERVATIONS	4101 W COLUMBUS DR		UST	299103404
TAMPA	90030513		COMMERCE BLVD		HMIRS	
TAMPA	S100563782	KASSOUF KIMMERLING/KA TIMBERLAKE	NE COR 58 / COLUMBUS DR		SHWS	
TAMPA	S101137001	SIXTY-SECOND STREET DUMP	NW COR OF COLUMBUS / 62 ST		SHWS	
TAMPA	U001354406	CIRCLE K #7441	SE CORNER OF BUFFALO & HWY 301	33619	UST, LUST	8625169
TAMPA	1000116138	VWR GRAPHICS INC	3902 CORPOREX PARK DR STE 150	33619	RCRIS-SQG, FINDS	
TAMPA	1000502813	BRANDON DODGE INC	9815 CURRIE DAVIS DR	33619	RCRIS-SQG, FINDS	
TAMPA	U001355241	CONTINENTAL BAKING CO	420 S DAKOTA AVE	33606	UST, LUST, AST	8627646
TAMPA	U001378078	YOUR ATTIC	4510 S DALE MABRY AVE		UST	299103154
TAMPA	90030047		DAVIS ISLAND		HMIRS	
TAMPA	1000732921	HILLSBOROUGH CNTY HOSP AUTH DBA TAMPA GEN HSP	DAVIS ISLAND	33606	FINDS	
TAMPA	U001544419	JEWISH CENTER TOWERS INC	3001 DELEON ST		UST, LUST	9301024
TAMPA	8802523	TAMPA INTERNATIONAL/AIRPORT EAST SIDE OF AIRPORT	DELTA MAINTENANCE HANGAR		ERNS	



## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	94091101	EDWARD DOROUGH SITE	6 DOING RACK		HMIRS	
TAMPA	S101547649	HILLSBOROUGH CO N B YOUNG JR HIGH S	1806 DOWNING CIR		SHWS	
TAMPA	1000738375	HILLSBOROUGH CO N B YOUNG JR HIGH S	1807 E DR MARTIN LUTHER KING	33605	FINDS	
TAMPA	1000703416	HILLSBOROUGH CO N B YOUNG JR HIGH S	1807 E DR MARTIN LUTHER KING	33605	RCRIS-SQG	
TAMPA	1000858717	BUFFALO CHEVRON INC	802 E DR MLK JR BLVD	33603	RCRIS-SQG, FINDS	
TAMPA	U001354559	FIFE-FL SUPPLY, INC.	1600 DRAWER B	33605	UST	298625337
TAMPA	1000737266	RADIANT OIL CO OF TAMPA INC	2004A DURHAM	33605	FINDS	
TAMPA	1000737264	GAS KWICK INC	2004C DURHAM ST	33605	FINDS	
TAMPA	U001378026	TAMPA CITY-S REGIONAL PARKING FACILITY	ELLA MAE ST	33605	UST	
TAMPA	U001378110	TAMPA PORT AUTHORITY-GARRISON CHANNEL	1301 ELLA MAE ST	33605	UST, LUST	299100404
TAMPA	1000498063	GARRISON STEVEDORES	1101 E ELLAMAE	33605	FINDS	9201835
TAMPA	U002217727	TWIN LAKES	E END OF BLOOMINGDALE AVE		UST, LUST	
TAMPA	91090759		ERLICH & HUTCHENSON		HMIRS	9502111
TAMPA	U001378033	ELI WITT CO	EUNICE		UST, LUST	
TAMPA	S100202986	NORTHEAST HILLSBOROUGH LF	EUREKA SP RD / HAMILTON RD		SWF/LF	9101430
TAMPA	S100300529	FALKENBURG RD YARD TRASH PROCESSING	FALKENBURG RD, 1MI N SR-60		SWF/LF	
TAMPA	U001356265	HILLSBOROUGH CNTY-FIRE DEPT #9	3225 N FALKENBURG RD	33619	UST, LUST	9100963
TAMPA	9106432	DUTCH HARBOR MAGONE MARINE SERVICE	FALLS		ERNS	
TAMPA	U001355554	GOTTFREED OIL CO	211 FAULKENBERG RD	33619	UST, LUST, AST	8735513
TAMPA	S100020982	HILLS COUNTY WASTE-TO-ENERGY PLANT	210 FAULKENBURG RD		SWF/LF	
TAMPA	U001380173	LOOMIS ARMORED INC	505A FAULKENBURG RD	33619	UST, LUST	9046273
TAMPA	U000906162	WASTE AID SYSTEMS	509 FAULKENBURG RD	33619	UST, LUST	8842355
TAMPA	U001544418	FLORIDA CAST PRODUCT INC	3110 FAULKENBURG RD	33619	RCRIS-SQG, FINDS	
TAMPA	U000411987	CRAFTSMAN ROOFERS	4704 N FL AVE		UST, LUST	9301008
TAMPA	U000411987	AUSTIN & SON AUTO ELECTRIC	3909 FLA AVE	33603	RCRIS-SQG, FINDS	
TAMPA	U001378027	RENFROE PROPERTY	9402 E FOWLER AVE		UST	299100524
TAMPA	1000739754	CIRCLE K #8533	5601 E FOWLER	33619	FINDS	
TAMPA	S101011580	AUTHORIZED APPLIANCE RECLAIMING CTR	2420 GELMAN PLACE, 5MI E US41		SWF/LF	
TAMPA	1000733904	STEEL SERVICES TAMPA	GRANT & S SLIP TPA PT AUTH		FINDS	
TAMPA	U001023466	HILLSBOROUGH CO CUSTODIAL OPERATION	1475 GREEN ST	33605	RCRIS-SQG	
TAMPA	1000999514	HILLSBOROUGH CO CUSTODIAL OPERATION	1475 GREEN ST	33605	FINDS	
TAMPA	U001354260	CF INDUSTRIES INC-TAMPA PHOSPHATE	2520 GUY VERGER BLVD	33605	UST, LUST, AST	8625014
TAMPA	1000255916	C F INDUSTRIES TAMPA TERMINAL	2520 GUY VERGER BLVD	33605	RCRIS-SQG, FINDS	
TAMPA	1001023731	HILLSBOROUGH CO CUST OP WH	1801 N HABANA	33605	RCRIS-SQG	
TAMPA	1000502102	SUN ENVIRONMENTAL INC	E HEMLOCK AVE HOOKERS PT PW PL	33605	FINDS	
TAMPA	1000735829	STERLING CLEANERS	3710 HENDERSON AVE	33602	FINDS	
TAMPA	1000703418	HILLSBOROUGH CO PIERCE JR HIGH SCHO	5511 N HESPERIDES	33605	RCRIS-SQG	
TAMPA	1000737480	MOBIL OIL CORP SS# A67	902 E HILLSBORO AVE	33606	FINDS, UST, LUST	8625031
TAMPA	U001378035	DISCOUNT TIRE TOWN	701 HILLSBOROUGH AVE		UST, LUST	9101615
TAMPA	U001546669	EXXON #4-0490	11292 HILLSBOROUGH BLVD		UST	299102024
TAMPA	1000740326	CIRCLE K #4146	10111 W HILLSBOROUGH	33619	FINDS	
TAMPA	1000102294	PRB AREA WIDE GROUNDWATER STUDY	HILLSBOROUGH CNTY	33619	FINDS, CERC-NFRAP	
TAMPA	1000344927	TAMPA UNKNOWN SPILL	HILLSBOROUGH COUNTY	33602	CERCLIS, FINDS	
TAMPA	1000292187	HILLSBOROUGH RIVER ABANDONED D	HILLSBOROUGH COUNTY	33602	CERCLIS, FINDS	
TAMPA	91070743		HOOKERS POINT		HMIRS	
TAMPA	94120986		4700 N HOOVER BLVD		HMIRS	
TAMPA	U001356211	KWIK PEP STATION	HOWARD APTS	33606	UST, LUST	9100288

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	U001378036	HUMBLE OIL CORP	US HWY 301 N & ALONZO RD		UST, LUST	9101724
TAMPA	1000822586	CIRCLE K #7494	2820 US HWY 301 S	33605	RCRIS-SQG, FINDS, UST, LUST	8840559
TAMPA	1000881220	SIMS CRANE & EQUIPMENT CO INC	1219 N HWY 301	33619	RCRIS-SQG, LUST, AST	8943355
TAMPA	1000822580	CIRCLE K #7443	10039 US HWY 574	33619	RCRIS-SQG, FINDS	
TAMPA	1000733110	HUCO INC	US HWY 41 S	33619	FINDS	
TAMPA	1000298775	CHEMETRON CORPORATION	INDUSTRIAL GASES DIVISION	33619	RCRIS-SQG, FINDS, TSCA	
TAMPA	1000292184	HILLSBOROUGH CO TRAFFIC	8420 INDUSTRIAL BLVD	33619	RCRIS-SQG, FINDS	
TAMPA	1000881223	MURPHY OIL USA INC	1306 INGRAM AVE	33605	RCRIS-SQG, LUST, AST	8625598
TAMPA	1000497143	MURPHY OIL USA	1306 INGRAM AVE	33605	FINDS	
TAMPA	U001355929	TAMPA CITY-FIRE STATION #19	4916 INGRAM	33602	UST, LUST	8842519
TAMPA	90020271		INTERBAY AND DALE MABRY		HMIRS	
TAMPA	U001046264	DAVE MITCHELL'S GRAND CENTRAL GARAGE	1901 W. JF KENNEDY BLVD	33606	UST, LUST	9201715
TAMPA	9100947	PORT OF BEAUMONT CARROL ST. WHARF	ST. JOHN ST.		ERNS	
TAMPA	8700298	1220 U.S. STATE ROAD 301 AT WHAREHOUSE SUPPLY 813-621-3	JUST EAST OF TAMPA		ERNS	
TAMPA	1000932537	B-L NETWORK INC DBA BLN	121-B KELSEY LANE	33619	FINDS	
TAMPA	1000735816	PHILIPS CIRCUIT ASSEMBLIES	203-G KELSEY LANE	33619	FINDS	
TAMPA	1000499706	WESTINGHOUSE ELECTRIC CORP	111 KELSEY LA STE B - E	33619	RCRIS-SQG, FINDS	
TAMPA	S100020984	KINGSWAY RD LF (DAVID J JOSEPH)	KINGSWAY RD, 0.5MI N OF 14		SWF/LF	
TAMPA	U001355406	K FOOD STORE	535 LADY MAYDELL DR	33619	UST, LUST	8732469
TAMPA	S101716587	NORTHWEST HILLSBORO CLASS III LF	LINEBAUGH AVE. E OF SHELTON RD		SWF/LF	
TAMPA	S100020988	NORTHWEST HILLSBOROUGH SLF	LINEBAUGH AVE		SWF/LF	
TAMPA	S101011591	RECYCLED WOOD PRODUCTS COMPOST FAC	S LOIS AVE, .25MI N INTERBAY	33606	UST, LUST	9200229
TAMPA	U001356382	PALMA CEIA VILLAGE SHOPPING CTR	3225 MACDILL AVE		SWF/LF	
TAMPA	S101011588	OLD MANHATTAN AVE CLASS I LF	S MANHATTAN AVE / RICHARDSON	33619	RCRIS-SQG, FINDS	
TAMPA	1000123400	GTE MANHATTAN GARAGE	5110 MANHATTAN AVE		RCRIS-SQG	
TAMPA	1000699637	INTERPAK INC	6932 SOUTH MANHATTEN STREET		ERNS	
TAMPA	9101545	OFF OF I-70 BOX BURGER LEASE	MARINA DR		UST, LUST	9101518
TAMPA	U001378034	MARIANI ASPHALT PARCEL	MARITIME BLVD		HMIRS	
TAMPA	90080774		MARITIME BLVD		FINDS	
TAMPA	1000498153	AMCON CONCRETE	MARITIME BLVD	33605	FINDS	
TAMPA	1000932223	FMC CORP., ACG, ATTN.:DELIA D. MC GOEY	2000 MARKET ST	33619	FINDS	
TAMPA	91060740		8950 MARSLIN DR		HMIRS	
TAMPA	94051530		MARTIN LUTHER KING BLVD		HMIRS	
TAMPA	U001378107	GOOD SHEPHERD BAPTIST CHURCH INC	8119 E MARTIN LUTHER KING JR		UST, LUST	9201207
TAMPA	U001544089	USE 298625797	801 MCCLOSKEY BLVD	33605	UST	299300581
TAMPA	1000931328	PETROLEUM PACKERS INC	1601 MCCLOSKEY BLVD	33605	FINDS	
TAMPA	1000733391	SULPHUR TERMINALS CO INC TAMPA	1015 MCCLOSKEY BLVD HOOKERS PT	33605	FINDS	
TAMPA	S100705159	CITGO PETROLEUM CORP	801 MCCLOSKEY BLVD	33605	LUST, AST	8625797
TAMPA	A100008777	AMOCO OIL CO-TERMINAL TAMPA	848 MCCLOSKEY BLVD	33605	AST	
TAMPA	1000359119	AMERICAN PETROFINA MARKETING INC	801 MCCLOSKEY BOULEVARD	33605	FINDS, RCRIS-LQG, CERC-NFRAP	
TAMPA	U000125105	AMOCO OIL CO-TERMINAL TAMPA	848 MCCLOSKEY BLVD	33605	UST, LUST	8735210
TAMPA	1000736103	TEXACO #242041342	3102 S MCDILL AVE	33606	FINDS	
TAMPA	1000498532	MCKAY BAY RTE PROJ	MCKAY BAY & ADAMS DR	33605	FINDS	
TAMPA	U001354829	FOGARTY VAN LINES-TRUCK SERVICE	N MERIDIAN & PLATT	33605	UST, LUST	8625622
TAMPA	U001378052	RISSER PETROLEUM TANKER SPILL	I-275 MILE MARKER 57	33602	UST	299102311
TAMPA	94070231		14 MILEMARKER 13		HMIRS	

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	1000906176	BURNUP & SIMS COM TECH	7221 E MLK BLVD	33619	RCRIS-SQG, FINDS, UST, LUST, AS1	8625121
TAMPA	S10020390	NORTHWEST REGIONAL SLUDGE MGMT FAC	NEAR SHELDON RD / MOBLEY RD		SWFLF	
TAMPA	U001355878	COMMERCE PLAZA	12811 N NEBRAKSA AVE	33602	UST, LUST	8842089
TAMPA	U001356274	CSX TRANSPORTATION-UNION STATION	601 NEBRASKA AVE	33602	UST, LUST	9101044
TAMPA	1000736938	YBOR DATA CTR	1898 NUCCIO PKWY	33605	FINDS	
TAMPA	8802486	PAY-LESS SERVICE STATION	SOUTH OF COOPER'S POND APARTMENT BUILDING		ERNS	
TAMPA	S10021003	TECO COMPOSTING FACILITY	W OF SHELDON RD N OF WATERS AV		SWFLF	
TAMPA	9105702	EAST LEVEE OF THE CHAIN OF ROCKS CANAL	OHIO RIVER MILE 241.5		ERNS	
TAMPA	90040283		OLD HOPEWELL RD		HMIRS	
TAMPA	1000498843	REED MINERALS	OLD HWY 41 & JENSEN		FINDS	
TAMPA	1000899180	TRADEMARK NITROGEN CORP.	1216 OLD HOPEWELL RD.	33619	TRIS	
TAMPA	U001356447	HARBOR ISLAND	ONE HARBOUR PLACE #270	33602	UST, LUST, AST	9202003
TAMPA	U001356395	GRIFFIN INDUSTRIES INC-OLD FUEL SITE	ORIENT RD	33619	UST, LUST	9200641
TAMPA	U001378105	SHELL STATION	8210 PARKEDGE DR		UST	299201084
TAMPA	U001354652	UNIVERSAL ERECTORS, INC.	5208 ST PAULS ST	33619	UST, LUST	8625433
TAMPA	91080428		PENDOLA POINT RD		HMIRS	
TAMPA	91050674		PENDOLA POINT DRIVE		HMIRS	
TAMPA	1000503138	BOLIDEN CHEMICALS INC	4118 PENDOLA POINT RD	33619	FINDS	
TAMPA	1000497834	IDEAL BASIC IND	PENNDOLA POINT RD	33602	FINDS	
TAMPA	U001356119	J H WILLIAMS OIL CO-BULK LUBE FACILITY	PENNY ST & 17TH ST	33605	UST, AST	299045969
TAMPA	1000344923	TAMPA TRIBUNE	1712 N PLATT	33606	RCRIS-SQG, FINDS	
TAMPA	1000740400	TECNUM	2411 PLYMOUTH RD	33602	FINDS	
TAMPA	1000733612	PREDELIVERY SVC CORP	1803 E POINT DR	33605	FINDS	
TAMPA	1000843480	GENERAL SERVICES ADMINISTRATION	501 E POLK ST ROOM 600	33602	FINDS	
TAMPA	U001378002	GRACE,W.R.	PORT SUTTON RD		UST	
TAMPA	8905271	IMC TERMINAL	PORT SUTTON AREA		ERNS	298840906
TAMPA	92100051		PORT TAMPA		HMIRS	
TAMPA	1000932117	CARGILL FERT.-TAMPA AMM TERM	PORT SUTTON RD	33605	FINDS	
TAMPA	U001354811	TAMPA ELECTRIC CO-GANNON STATION	PORT SUTTON RD	33619	UST, LUST, AST	8625602
TAMPA	1000732803	IMC TERMINAL	PORT SUTTON RD	33619	FINDS	
TAMPA	1000732744	TAMPA ELEC CO FRANCIS J GANNON	PORT SUTTON RD	33619	FINDS	
TAMPA	1000498897	SHIP BARGE LOADING FAC	PORT SUTTON RD	33619	FINDS	
TAMPA	8805677	MP AZA886.9	POWELL MEADOW SUBDIVISION		ERNS	
TAMPA	1000496757	ADAMO ACRES STP	411 RIVERBAY DR	33619	FINDS	
TAMPA	1000155425	CANARIIS CORP.	8918 SABAL IND. BLVD.	33619	RCRIS-SQG, FINDS	
TAMPA	1000300124	KIMMINS ENVIRONMENTAL SERVICE CORP	1501 SECOND AVENUE	33605	RCRIS-SQG, FINDS	
TAMPA	U001379124	HUMANA GAS STATION	SEMINOLE BLVD / BLOSSOM LAKE DR		UST, LUST	9103454
TAMPA	1000350946	YBOR CENTRAL LTD	1616 EAST SEVENTH AVENUE	33605	RCRIS-SQG, FINDS	
TAMPA	8910558	SHELDON RD. SUBSTATION	SHELDON RD. AND LINEBAUGH AVE.		ERNS	
TAMPA	8805616		SHELL TERMINAL		ERNS	
TAMPA	1000259958	NATL SEA PRODUCTS CORP TP DIV	1356 SHORELINE DR	33605	RCRIS-SQG, FINDS, UST, AST	298942800
TAMPA	1000933601	HILLSBOROUGH COUNTY RESOURCE RECOVERY	S SIDE RALEIGH ST	33619	CERCLIS, FINDS	
TAMPA	U001378011	TAMPA,CITY-NW REPUMP STATION	5602 SITKA		UST, AST	298945433
TAMPA	1000498850	JOHN CARLO INC	SPRUCE ST	33605	FINDS	
TAMPA	U001378122	CENTRAL SOD & LANDSCAPING	4419 SOUTH ST		UST, LUST	9202389
TAMPA	95020737		14516 22ND ST SKIPPER RD		HMIRS	

## ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	U001355604	HILLSBOROUGH CNTY SCHOOL BD-GROUNDS	3838 50TH ST	33605	UST, LUST	8736494
TAMPA	U001355028	MCCLENDON OIL CO, INC./W.K.	1409 22ND ST	33605	UST, LUST	8626340
TAMPA	U001354412	CAR CHEK	7002 22ND ST CAUSEWAY	33619	UST, LUST	8625175
TAMPA	U000496555	SUNOCO SVC STA	2518 50TH ST	33619	RCRIS-SQG, FINDS	
TAMPA	U001378024	USE 298841046	N TAMPA ST		UST, LUST	9100014
TAMPA	U000265433	KHAJEHNOORI HAZARDOUS WASTE	2740 NORTH TAMPA ST SUITE C	33603	RCRIS-SQG, FINDS	
TAMPA	U001545547	PIONEER PROPERTIES ASSOCIATES,LTD	100 TAMPA ST	33602	UST, LUST	8942888
TAMPA	U000821146	HYATT REGENCY TAMPA	2 TAMPA CITY CENTER	33602	RCRIS-SQG, FINDS	
TAMPA	8705675	8401 N. HWY 301	TEXACO GAS STATION		ERNS	
TAMPA	8703010	1333 W. BRANDEN BLVD	THE PAITO SHOP BEHIND ABOVE ADDRESS		ERNS	
TAMPA	9108492	140 SILVESTER RD.	ON THE JAMES RIVER		ERNS	
TAMPA	U000361440	FLORIDA GRAPHIC PRODUCTS INC	3209 E THIRD AVE	33605	RCRIS-SQG, FINDS	
TAMPA	U001544411	VETERANS EXWY ROW SITES	NORTH TO SOUTH TO TAMPA		UST	299300656
TAMPA	92110135		4537 TRANSPORT DR		HMIRS	
TAMPA	94030979		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92070317		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91030415		4537 TRANSPORT DR		HMIRS	
TAMPA	92060357		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	93010192		4537 TRANSPORT DR		HMIRS	
TAMPA	92070304		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	90070446		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	U001545548	COURIER DISPATCH	4111 TRASK AVE		UST, LUST	8942841
TAMPA	U001355901	STANDARD GYPSUM	UNKNOWN	33605	UST, LUST	8842369
TAMPA	U000700432	CONSUMER PRODUCTS INC	10824 US92E		RCRIS-SQG	
TAMPA	S100563798	UNIVERSAL DOOR / DOT LF	VETERANS EXPWY @ BENJAMIN RD		SWF/LF	
TAMPA	S101136987	PEAK OIL/BAY DRUM	1/4 MI W OF FAULKENBERG RD, S OF SR 574		SHWS	
TAMPA	U000739748	CIRCLE K #4235	3635 W WATERS AVE	33619	FINDS	9046115
TAMPA	U001378016	BUDGET RENT A CAR	1110 N WEST SHORE BLVD		UST, LUST	
TAMPA	92110055		WESTSHORE BLVD. & TYSON ST		HMIRS	
TAMPA	U001355392	EMBASSY HOTEL	555 WESTSHORE BLVD	33602	UST, LUST, AST	9200540
TAMPA	S100020989	NORTHWEST HILLSBOROUGH TRANSFER STA	WILSKY RD / LINEBAUGH AVE		SWF/LF	
TAMPA	92040092		YARD		HMIRS	
TARPON SPRINGS	U000735395	TARPON SPRINGS GARAGE	1905 PLAZA DR	33619	FINDS	
TAVERNIER	U000740092	CIRCLE K #2382	92720 OVERSEAS	33619	FINDS	
THONOTOSASSA	U000739824	CIRCLE K #7074	SEC MAIN ST/SR 579	33619	FINDS	
TREASURE ISLAND	95318564			33602	ERNS	
VALRICO	U000703406	HILLSBOROUGH CO BLOOMINGDALE HIGH S	1700 E BLOOMINGDALE AVE	33605	RCRIS-SQG	
VENICE	U000735044	GTE VENICE FLEET CTR	1290 VENICE BY PASS S	33619	FINDS	
VERO BEACH	U000859174	SHELL OIL CO	1901 US HWY 1	33619	RCRIS-SQG, FINDS	
WAUCHULA	U000740089	CIRCLE K #7034	SR 64A/OLD AVON PARK	33619	FINDS	
WILDWOOD	U000740223	CIRCLE K #0189	309 S MAIN ST	33619	FINDS	
WIMAUMA	U000739826	CIRCLE K #7169	5133 US HWY 674	33619	FINDS	
WINTER GARDEN	U000739766	CIRCLE K #7456	1498 GOODHOMES RD	33619	FINDS	
WINTER GARDEN	U000739767	CIRCLE K #7490	1240 US HWY 545	33619	FINDS	
WINTER GARDEN	U000739765	CIRCLE K #8529	599 E US HWY 50	33619	FINDS	
WINTER HAVEN	U000739888	CIRCLE K #8703	999 1ST ST S	33619	FINDS	
WINTER SPRINGS	U000739912	CIRCLE K #7113	320 W ST RD 434	33619	FINDS	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
ZEPHYRHILLS	1000740164	CIRCLE K #0180	1507 GALL BLVD	33619	FINDS	
ZEPHYRHILLS	1000740163	CIRCLE K #7130	1201 US HWY 54A E	33619	FINDS	
ZEPHYRHILLS	1000740162	CIRCLE K #7475	US HWY 54/I-75	33619	FINDS	
ZEPHYRHILLS	1000740165	CIRCLE K #7100	1021 W US HWY 54	33619	FINDS	
ZOLFO SPRINGS	1000740086	CIRCLE K #7285	US HWY 177TH AVE	33619	FINDS	
ZOLFO SPRINGS	1000740087	CIRCLE K #7085	3RD ST/US HWY 17	33619	FINDS	

## EPA Waste Codes Addendum

Code	Description
D000	NOT DEFINED
D001	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
D002	A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
D005	BARIUM
D006	CADMIUM
D007	CHROMIUM
D008	LEAD
D011	SILVER
D018	BENZENE
D021	CHLOROBENZENE
D027	1,4-DICHLOROBENZENE
D028	1,2-DICHLOROETHANE
D029	1,1-DICHLOROETHYLENE
D035	METHYL ETHYL KETONE
D039	TETRACHLOROETHYLENE
D040	TRICHLOROETHYLENE
F001	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F002	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE

## EPA Waste Codes Addendum

Code	Description
	CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F003	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F004	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: CRESOLS AND CRESYLIC ACID, AND NITROBENZENE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F005	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F006	WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.
K002	WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME YELLOW AND ORANGE PIGMENTS.
K003	WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF MOLYBDATE ORANGE PIGMENTS
K086	SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.
NONE	NONE
U021	BENZIDINE
U021	[1,1'-BIPHENYL]-4,4'-DIAMINE

## EPA Waste Codes Addendum

Code	Description
U076	ETHANE, 1,1-DICHLORO-
U076	ETHYLIDENE DICHLORIDE
U077	ETHANE, 1,2-DICHLORO-
U077	ETHYLENE DICHLORIDE
U078	1,1-DICHLOROETHYLENE
U078	ETHENE, 1,1-DICHLORO-
U080	METHANE, DICHLORO-
U080	METHYLENE CHLORIDE
U226	ETHANE, 1,1,1-TRICHLORO-
U226	METHYL CHLOROFORM
U228	ETHENE, TRICHLORO-
U228	TRICHLOROETHYLENE