

The EDR Corridor Study Report

**Study Area
I-275 / I-4 Interchange
Tampa, Florida**

December 7, 1995

Inquiry number 99711

EDR Environmental
Data
Resources, Inc.
Creators of Toxicheck®

The Source For Environmental Risk Management Data

3530 Post Road
Southport, Connecticut 06490

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer

This Report contains information obtained from a variety of public sources and EDR makes no representation or warranty regarding the accuracy, reliability, quality, or completeness of said information or the information contained in this report. The customer shall assume full responsibility for the use of this report.

No warranty of merchantability or of fitness for a particular purpose, expressed or implied, shall apply and EDR specifically disclaims the making of such warranties. In no event shall EDR be liable to anyone for special, incidental, consequential or exemplary damages.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM RECORDS:

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

Source: EPA/NTIS

Telephone: 703-416-0702

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 08/31/95

Date Made Active at EDR: 12/04/95

Date of Data Arrival at EDR: 11/02/95

Elapsed ASTM days: 32

ERNS: Emergency Response Notification System

Source: EPA

Telephone: 202-260-2342

ERNS: Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/94

Date Made Active at EDR: 05/25/95

Date of Data Arrival at EDR: 04/11/95

Elapsed ASTM days: 44

NPL: National Priority List

Source: EPA

Telephone: 703-603-8852

NPL: National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, it is EDR's policy to plot NPL sites greater than approximately 500 acres in size as areas (polygons). Sites smaller in size are point-geocoded at the site's address.

Date of Government Version: 09/01/95

Date Made Active at EDR: 10/25/95

Date of Data Arrival at EDR: 10/17/95

Elapsed ASTM days: 8

RCRIS: Resource Conservation and Recovery Information System

Source: EPA/NTIS

Telephone: 703-308-7907

RCRIS: Resource Conservation and Recovery Information System. RCRIS includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Date of Government Version: 05/31/95

Date Made Active at EDR: 08/22/95

Date of Data Arrival at EDR: 06/28/95

Elapsed ASTM days: 55

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FEDERAL NON-ASTM RECORDS:

CONSENT: Superfund (CERCLA) Consent Decrees

Source: EPA Regional Offices

Telephone: Varies

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: Varies

Date of Next Scheduled Update: 09/01/95

CORRACTS: Corrective Action Report

Source: EPA

Telephone: 703-308-7907

CORRACTS: CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 04/10/95

Date of Next Scheduled Update: 12/18/95

FINDS: Facility Index System

Source: EPA/NTIS

Telephone: 800-908-2493

FINDS: Facility Index System. FINDS contains both facility information and "pointers" to other sources that contain more detail. These include: RCRIS, PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]), CERCLIS, DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), FRDS (Federal Reporting Data System), SIA (Surface Impoundments), CICIS (TSCA Chemicals in Commerce Information System), PADS, RCRA-J (medical waste transporters/disposers), TRIS and TSCA.

Date of Government Version: 07/27/94

Date of Next Scheduled Update: 01/08/96

HMIRS: Hazardous Materials Information Reporting System

Source: U.S. Department of Transportation

Telephone: 202-366-4555

HMIRS: Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/94

Date of Next Scheduled Update: 01/29/96

MLTS: Material Licensing Tracking System

Source: Nuclear Regulatory Commission

Telephone: 301-415-7169

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/01/95

Date of Next Scheduled Update: 01/15/96

NPL LIENS: Federal Superfund Liens

Source: EPA

Telephone: 202-260-8969

NPL LIENS: Federal Superfund Liens. Under the authority granted the USEPA by the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner receives notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/91

Date of Next Scheduled Update: 02/26/96

PADS: PCB Activity Database System

Source: EPA

Telephone: 202-260-3992

PADS: PCB Activity Database. PADS identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 10/14/94

Date of Next Scheduled Update: 02/19/96

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

RAATS: RCRA Administrative Action Tracking System

Source: EPA

Telephone: 202-564-4104

RAATS: RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA.

Date of Government Version: 04/17/95

Date of Next Scheduled Update: 12/18/95

ROD: Records Of Decision

Source: NTIS

Telephone: 703-416-0703

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 03/31/95

Date of Next Scheduled Update: 03/04/96

TRIS: Toxic Chemical Release Inventory System

Source: EPA/NTIS

Telephone: 202-260-2320

TRIS: Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/92

Date of Next Scheduled Update: 01/01/96

TSCA: Toxic Substances Control Act

Source: EPA/NTIS

Telephone: 202-260-1444

TSCA: Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site. USEPA has no current plan to update and/or re-issue this database.

Date of Government Version: 01/31/95

Date of Next Scheduled Update: 03/18/96

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STATE OF FLORIDA ASTM RECORDS:

LUST: PCT01 - Petroleum Contamination Detail Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

LUST: Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 10/02/95

Date Made Active at EDR: 11/22/95

Date of Data Arrival at EDR: 10/23/95

Elapsed ASTM days: 30

SHWS: Florida's State-Funded Action Sites

Source: Department of Environmental Protection

Telephone: 904-488-0190

SHWS: State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 08/24/95

Date Made Active at EDR: 09/13/95

Date of Data Arrival at EDR: 09/05/95

Elapsed ASTM days: 8

SWF/LS: Facility Directory (Solid Waste Facilities)

Source: Department of Environmental Protection

Telephone: 904-922-7121

SWF/LS: Solid Waste Facilities/Landfill Sites. SWF/LS type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Section 2004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 07/11/95

Date Made Active at EDR: 08/31/95

Date of Data Arrival at EDR: 08/03/95

Elapsed ASTM days: 28

UST: STI02 - Facility/Owner/Tank Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

UST: Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 07/26/95

Date Made Active at EDR: 09/13/95

Date of Data Arrival at EDR: 08/08/95

Elapsed ASTM days: 36

STATE OF FLORIDA NON-ASTM RECORDS:

AST: STI02 - Facility/Owner/Tank Report

Source: Department of Environmental Protection

Telephone: 904-922-7121

AST: Aboveground Storage Tanks.

Date of Government Version: 07/26/95

Date of Next Scheduled Update: 12/11/95

CATTLE DIPPING VATS: Cattle Dipping Vats

Source: Department of Environmental Protection

Telephone: 904-488-3601

Date of Government Version: 05/01/94

Date of Next Scheduled Update: 02/19/96

FL SITES: Sites List

Source: Department of Environmental Protection

Telephone: 904-922-7121

Date of Government Version: 12/31/89

Date of Next Scheduled Update: N/A

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FLORIDA COUNTY RECORDS

DADE COUNTY:

Dade County Storage Tanks

Source: Department of Environmental Resource Management

Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 01/01/96

Dade County Enforcement Case Tracking System

Source: Department of Environmental Resources Management

Telephone: 305-372-6755

Date of Government Version: 04/01/95

Date of Next Scheduled Update: 01/01/96

Dade County Industrial Waste Type 5

Source: Department of Environmental Resources Management

Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 01/01/96

Dade County Industrial Waste Type 2-4

Source: Department of Environmental Resources Management

Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 01/01/96

Dade County Fuel Spill Cases

Source: Department of Environmental Resources Management

Telephone: 305-372-6755

Date of Government Version: 09/01/95

Date of Next Scheduled Update: 01/01/96

BROWARD COUNTY:

Broward County Storage Tanks

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

Date of Government Version: 08/12/94

Date of Next Scheduled Update: 02/20/96

Early Detection Incentive

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

EDI sites are leaking underground petroleum tanks covered under the state cleanup program.

Date of Government Version: 08/12/94

Date of Next Scheduled Update: 03/11/96

Environmental Assessment

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

EA sites are contaminated sites (non-leaking underground petroleum tanks) under the state cleanup program.

Date of Government Version: 08/12/94

Date of Next Scheduled Update: 03/11/96

Hazmat

Source: Department of Natural Resources Protection

Telephone: 305-519-1251

HM sites use or store greater than 25 gallons of hazardous materials per month.

Date of Government Version: 08/12/94

Date of Next Scheduled Update: 03/11/96

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Notice Of Violation

Source: Department of Natural Resources Protection
Telephone: 305-519-1251

Date of Government Version: 08/12/94

Date of Next Scheduled Update: 03/11/96

ESCAMBIA COUNTY:

Facility/Owner/Tank/Contamination Information Report

Source: Environmental Health Services
Telephone: 904-444-8990

Date of Government Version: 08/11/95

Date of Next Scheduled Update: 02/05/96

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Historical and Other Database(s)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Former Manufactured Gas (Coal Gas) Sites: The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

DELISTED NPL: Delisted NPL Sites

Source: EPA

Telephone: 703-603-8769

DELISTED NPL: The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

NFRAP: No Further Remedial Action Planned

Source: EPA/NTIS

Telephone: 703-416-0702

NFRAP: As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

FRDS: Federal Reporting Data System

Source: EPA/Office of Drinking Water

Telephone: 202-260-2805

FRDS provides information regarding public water supplies and their compliance with monitoring requirements, maximum contaminant levels (MCL's), and other requirements of the Safe Drinking Water Act of 1986.

Area Radon Information: The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

Oil/Gas Pipelines/Electrical Transmission Lines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines and electrical transmission lines.

Sensitive Receptors: There are individuals who, due to their fragile immune systems, are deemed to be especially sensitive to environmental discharges. These typically include the elderly, the sick, and children. While the exact location of these sensitive receptors cannot be determined, EDR indicates those facilities, such as schools, hospitals, day care centers, and nursing homes, where sensitive receptors are likely to be located.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

USGS Water Wells: In November 1971 the United States Geological Survey (USGS) implemented a national water resource information tracking system. This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on more than 900,000 wells, springs, and other sources of groundwater.

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1994 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Water Dams: National Inventory of Dams
Source: Federal Emergency Management Agency
Telephone: 202-646-2801
WATER DAMS: National computer database of more than 74,000 dams maintained by the Federal Emergency Management Agency.

Wetlands Data: This data was obtained by EDR from the National Wetlands Inventory (NWI) in 1994. Data depicts wetland areas as defined by NWI.

State of Florida Water Well and Sample Database
Source: FL Department of Environmental Protection, Groundwater Quality Monitoring

St. Johns River District Well Data
Source: St. Johns River Water Management District

Southwest District Water Use Data
Source: Southwest Water Management District

Well Construction Permitting System: Water Well Locations in Northwest Florida Water Management District
Source: Northwest Florida Water Management District
Telephone: 904-539-5999

Florida Sinkholes
Source: Department of Environmental Protection, Geological Survey
The sinkhole data was gathered by the Florida Sinkhole Research Institute, University of Florida.

MAP FINDINGS SUMMARY

<u>Database</u>	<u>Total Plotted</u>
NPL	0
Delisted NPL	0
RCRIS-TSD	1
State Haz. Waste	0
CERCLIS	2
CERC-NFRAP	1
CORRACTS	0
State Landfill	1
LUST	160
UST	272
AST	24
RAATS	0
RCRIS Sm. Quan. Gen.	120
RCRIS Lg. Quan. Gen.	10
HMIRS	1
PADS	1
ERNS	1
FINDS	156
TRIS	3
NPL Liens	0
TSCA	1
MLTS	0
Florida Sites	2
Florida Enforcement	0
Florida Ind. Waste	0
Env. Assessment	0
Florida Cattle	0
FL Haz. Mat.	0
FL Notice of Viol.	0
ROD	0
CONSENT	0
Coal Gas	1

* Sites may be listed in more than one database

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
1			JUSTER'S RITE-WAY SERVICE 4402 N NEBRASKA AVE TAMPA, FL 33603	UST	U001354179	N/A
UST:						
Facility ID:		298624926	Facility Type:	Retail Station		
Is fac. regulated:		Not regulated facility	Is facility open:	Closed		
Operator:		JUSTER PETRALIA				
Contact:		Not reported	Facility Phone:	8132399119		
Permit Section:		Not reported	Region:	Not reported		
Facility Code:		No violation				
Date entered:		860506	Financial responsibility:	Not reported		
Tank ID:		1	District:	Southwest		
Owner's Contact:		JUSTER PETRALIA				
Owner:		JUSTERS RITE WAY SERVICE 4402 N NEBRASKA AVE TAMPA, FL 336034147				
Owner's Phone:		8132399119	Tracking #:	Not reported		
Cleanup Status:		Not reported	Any contaminated soil:	Not reported		
Drink. Wat. Well:		Not reported	Any contaminated surface water:	Not reported		
Tank Cap. (Gals):		00003000	Any monit. wells:	Not reported		
Tank position:		Not reported	Any contam. groundwater:	Not reported		
Tank Content:		Not reported	Contaminated media indicator:	Not reported		
Disposal Method:		Removed	Install. Date:	Not reported		
Is tank regulated:		Not regulated tank	Content Category:	Vehicular		
Facility Status:		Not reported	Last used Date:	Not reported		
RPT Tank #:		Not reported	RPT by Tank #:	Not reported		
Tank Constr.:		Not reported				
Tank Piping:		Not reported				
Petro. Monitoring:		Unknown/not reported				

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

JUSTER'S RITE-WAY SERVICE (Continued)

U001354179

Facility ID:	298624926	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JUSTER PETRALIA		
Contact:	Not reported	Facility Phone:	8132399119
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JUSTER PETRALIA		
Owner:	JUSTERS RITE WAY SERVICE 4402 N NEBRASKA AVE TAMPA, FL 336034147		
Owner's Phone:	8132399119	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624926	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JUSTER PETRALIA		
Contact:	Not reported	Facility Phone:	8132399119
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JUSTER PETRALIA		
Owner:	JUSTERS RITE WAY SERVICE 4402 N NEBRASKA AVE TAMPA, FL 336034147		
Owner's Phone:	8132399119	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

JUSTER'S RITE-WAY SERVICE (Continued)

U001354179

Facility ID:	298624926	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JUSTER PETRALIA		
Contact:	Not reported	Facility Phone:	8132399119
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JUSTER PETRALIA		
Owner:	JUSTERS RITE WAY SERVICE 4402 N NEBRASKA AVE TAMPA, FL 336034147		
Owner's Phone:	8132399119	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298624926	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JUSTER PETRALIA		
Contact:	Not reported	Facility Phone:	8132399119
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JUSTER PETRALIA		
Owner:	JUSTERS RITE WAY SERVICE 4402 N NEBRASKA AVE TAMPA, FL 336034147		
Owner's Phone:	8132399119	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000350	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

2

CAR LOT
4404 N FLORIDA AVE
TAMPA, FL 33630

UST

U001713407
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CAR LOT (Continued)

U001713407

UST:

Facility ID:	299400166	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CAR LOT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940210	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	BARNETT BANK OF PINELLAS CNTY PO BOX 30318 ATTN TIM MARTIN TAMPA, FL 336303318		
Owner's Phone:	8132252929	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

2

FORMER CAR LOT
4404 N FLORIDA AVE
TAMPA, FL 33603

UST

U001823384
N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	FORMER CAR LOT (Continued)		U001823384
	UST: Facility ID: 299400302 Is fac. regulated: Not regulated facility Operator: BARNETT BANK Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 940314 Tank ID: 1 Owner's Contact: TRICIA HOFFMAN Owner: BARNETT BANK INC PO BOX 30318 TAMPA, FL 336300000 Owner's Phone: 8132552909 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00001000 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: None	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132252909 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Pollutant Last used Date: 93/09 RPT by Tank #: Not reported	
2	TAMPA AUTO MART INC 4404 N FLORIDA AVE TAMPA, FL 33603 RCRIS: Not Reported	RCRIS-SQG FINDS	1000344831 FLD981866643
3	STAR #1230 4415 N 22ND ST TAMPA, FL 33610	UST LUST	U001354861 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STAR #1230 (Continued)

U001354861

LUST:

Facility ID:	8625654	Facility Type:	RETAIL STATION
Telephone:	8132392020	Alias Name 1:	Not reported
Discovery Date:	03/29/89	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	ODOR ONLY	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NOT CLOSED
Incident Ineligible Description:	NOT CLOSED

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STAR #1230 (Continued)

U001354861

UST:

Facility ID:	298625654	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	STAR SERVICE & PETROLEUM CO.		
Contact:	Not reported	Facility Phone:	8132392020
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	STAR SERVICE & PETROLEUM CO 158 PROGRESS PKY SAINT LOUIS, MO 63043		
Owner's Phone:	2149975990	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	64/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625654	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	STAR SERVICE & PETROLEUM CO.		
Contact:	Not reported	Facility Phone:	8132392020
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	STAR SERVICE & PETROLEUM CO 158 PROGRESS PKY SAINT LOUIS, MO 63043		
Owner's Phone:	2149975990	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	64/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STAR #1230 (Continued)

U001354861

Facility ID:	298625654	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	STAR SERVICE & PETROLEUM CO.		
Contact:	Not reported	Facility Phone:	8132392020
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	Not reported		
Owner:	STAR SERVICE & PETROLEUM CO 158 PROGRESS PKY SAINT LOUIS, MO 63043		
Owner's Phone:	2149975990	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	64/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

4

PAINTERS SUPPLY
4312 N NEBRASKA AVE
TAMPA, FL 33603

RCRIS-SQG 1000886662
FINDS FL0000228767

RCRIS:

Owner: BOB INGALLS, STORE MGR
(813) 238-9733

Contact: BOB INGALLS
(813) 238-9733

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	U002	.00000 (T)	Notification
U112	.00000 (T)	Notification	U159	.00000 (T)	Notification
U220	.00000 (T)	Notification	U359	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

5

BOB OLSENS ENGINE EXCHANGE
4230 N FLORIDA AVE
TAMPA, FL 33603

RCRIS-SQG 1000821347
FINDS FLD984242669

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

BOB OLSENS ENGINE EXCHANGE (Continued)

1000821347

RCRIS:

Owner: LOUISE OLSEN
(813) 238-0517

Contact: LOUISE OLSEN
(813) 238-0517

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D006	.00000 (T)	Notification
D007	.00000 (T)	Notification	D008	.00000 (T)	Notification
D018	.00000 (T)	Notification	D021	.00000 (T)	Notification
D027	.00000 (T)	Notification	D039	.00000 (T)	Notification
D040	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

5

STREET SOUND, INC.
4221 N FLORIDA AVE
TAMPA, FL 33603

UST
LUST

U001355349
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STREET SOUND, INC. (Continued)

U001355349

LUST:

Facility ID:	8629021	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132373991	Alias Name 1:	Not reported
Discovery Date:	12/14/88	Alias Name 2:	Not reported
Tracking Number:	295749	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NO C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: Not reported

Est. Gallons Lost: Not reported

Pollutant 2: Not reported

Est. Gallons Lost: Not reported

Pollutant 3: Not reported

Est. Gallons Lost: Not reported

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

INELIGIBLE

Incident Ineligible Reason:

NO CONTAMINATION

Incident Ineligible Description:

NO CONTAMINATIO

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STREET SOUND, INC. (Continued)

U001355349

UST:

Facility ID:	298629021	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	STREET SOUND INC.		
Contact:	Not reported	Facility Phone:	8132373991
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	STREET SOUND INC. 4221 N FLORIDA AVE TAMPA, FL 336033819		
Owner's Phone:	8132373991	Tracking #:	295749
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		
Facility ID:	298629021	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	STREET SOUND INC.		
Contact:	Not reported	Facility Phone:	8132373991
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	STREET SOUND INC. 4221 N FLORIDA AVE TAMPA, FL 336033819		
Owner's Phone:	8132373991	Tracking #:	295749
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

STREET SOUND, INC. (Continued)

U001355349

Facility ID:	298629021	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	STREET SOUND INC.		
Contact:	Not reported	Facility Phone:	8132373991
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	Not reported		
Owner:	STREET SOUND INC. 4221 N FLORIDA AVE TAMPA, FL 336033819		
Owner's Phone:	8132373991	Tracking #:	295749
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

6	STERLING CLEANERS 4214 NEBRASKA AVE. TAMPA, FL 33603	FINDS	1000735828 FLD982173528
---	--	-------	----------------------------

6	STERLING CLEANERS 4214 NEBRASKA AVE TAMPA, FL 33704	RCRIS-SQG	1000700987 FLD982173528
---	---	-----------	----------------------------

RCRIS:

Owner: BENNETT BETTY MGR
(813) 236-1791

Contact: BENNETT BETTY
(813) 236-1791

Waste	Quantity	Info Source
F002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

7	W C RAY SERVICE STATION 4102 N CENTRAL AVE TAMPA, FL 33603	UST LUST	U001356250 N/A
---	--	-------------	-------------------

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

W C RAY SERVICE STATION (Continued)

U001356250

LUST:

Facility ID:	9100814	Facility Type:	NON-RETAIL BUSINESS
Telephone:	6157810206	Alias Name 1:	Not reported
Discovery Date:	03/11/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported
Category: Not reported
Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

ABANDONED TANK RESTORATIO
LOCAL PROGRAM
NO C/U REQUIRED

Lead:

Incident 17-770 Cleanup:

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: NO CONTAMINATION
Pollutant 2: Not reported
Pollutant 3: Not reported

Est. Gallons Lost: UNKNOWN
Est. Gallons Lost: 00000000
Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program: ABANDONED TANK RESTORATION
Incident Program Type: REIMBURSEMENT CLEANUP
Incident Eligible Status: INELIGIBLE
Incident Ineligible Reason: NO CONTAMINATION
Incident Ineligible Description: NO CONTAMINATIO

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product: Cleanup Responsible: Not reported
Soil Removal: Alt. Process Date: Not reported
Soil Treatment: Alternative Status: Not reported
Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible: Not reported
Response Record Type: Not reported
Response Remedial Action Plan Type: Not reported
Response Status: Not reported
Extension Record Type: Not reported
Extension Status: Not reported
Extension Comments: Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible: Not reported
Response Record Type: Not reported
Response Remedial Action Plan Type: Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible: Not reported
Estimated Completion Year: Not reported
Actual Year to Complete: Not reported
Report Type: Not reported
Report Comments: Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action: Not reported
Flag: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

W C RAY SERVICE STATION (Continued)

U001356250

UST:

Facility ID:	299100814	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FORMAN, EUGENIA CLOUD		
Contact:	Not reported	Facility Phone:	6157810206
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910312	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	EUGENIA FORMAN		
Owner:	FORMAN, EUGENIA CLOUD		
	5453 VILLAGE WAY		
	NASHVILLE, TN 372116239		
Owner's Phone:	6153602921	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	20/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299100814	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FORMAN, EUGENIA CLOUD		
Contact:	Not reported	Facility Phone:	6157810206
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910312	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	EUGENIA FORMAN		
Owner:	FORMAN, EUGENIA CLOUD		
	5453 VILLAGE WAY		
	NASHVILLE, TN 372116239		
Owner's Phone:	6153602921	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	20/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

W C RAY SERVICE STATION (Continued)

U001356250

Facility ID:	299100814	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FORMAN, EUGENIA CLOUD		
Contact:	Not reported	Facility Phone:	6157810206
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910312	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	EUGENIA FORMAN		
Owner:	FORMAN, EUGENIA CLOUD		
	5453 VILLAGE WAY		
	NASHVILLE, TN 372116239		
Owner's Phone:	6153602921	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	20/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

8	MIDDLETON JUNIOR HIGH SCHOOL 4302 24TH STREET TAMPA, FL 33610	FINDS	1000738373 FLD984230045
---	---	-------	----------------------------

8	HILLSBOROUGH CO MIDDLETON JR HIGH S 4302 24TH ST TAMPA, FL 33604	RCRIS-SQG	1000703414 FLD984230045
---	--	-----------	----------------------------

RCRIS:

Owner: PHILLIP GUFFEY, DEALER
(813) 626-0806

Contact: PHILLIP GUFFEY
(813) 626-0806

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D002	.00000 (T)	Notification	D003	.00000 (T)	Notification
D004	.00000 (T)	Notification	D005	.00000 (T)	Notification
D006	.00000 (T)	Notification	D007	.00000 (T)	Notification
D008	.00000 (T)	Notification	D009	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

9	NB YOUNG JUNIOR HIGH SCHOOL 1807 E DR MLK JR BLVD TAMPA, FL 33610	FINDS	1000738375 FLD984230060
---	---	-------	----------------------------

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
10	TANK WELDING & SERVICE CO INC 4101 SOUTH 22ND ST CAUSEWAY TAMPA, FL 33601 RCRIS: Not Reported	RCRIS-SQG FINDS	1000496921 FLD004102992
10	LEASEWAY TRANSPORTATION CORP 4212 22ST CAUSEWAY BLVD TAMPA, FL 33605 RCRIS: Not Reported	RCRIS-SQG	1000699280 FLD150800662
11	FLEET TRANSPORT COMPANY INC 4012 S 22ND ST CAUSEWAY BLVD TAMPA, FL 33619	FINDS	1000733273 FLD044997732
12	C MART #645 702 W BUFFALO AVE TAMPA, FL 33603 UST: Facility ID: 298625219 Is fac. regulated: Regulated facility Operator: SCOURLOCK, RICK Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860514 Tank ID: 1 Owner's Contact: JOHN LEFRAVICH Owner: COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510 Owner's Phone: 7138773939 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00004000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells, SPCC plan	UST LUST	U001354452 N/A
	Facility Type: Retail Station Is facility open: Open Facility Phone: 8136843844 Region: Not reported Financial responsibility: State PRGM (Self/Other) District: Southwest Tracking #: 290929 Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: 69/12 Content Category: Vehicular Last used Date: 88/01 RPT by Tank #: Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

C MART #645 (Continued)

U001354452

Facility ID:	298625219	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SCOURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC		
	9 GREENWAY PLAZA #1994		
	HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	290929
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	88/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Piping/flow restrictor, Man tank gauging		
Facility ID:	298625219	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SCOURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC		
	9 GREENWAY PLAZA #1994		
	HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	290929
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, SPCC plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

C MART #645 (Continued)

U001354452

Facility ID:	298625219	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SCOURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2R1	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	290929
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	88/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Piping/flow restrictor, Man tank gauging		
Facility ID:	298625219	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SCOURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	290929
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, SPCC plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

C MART #645 (Continued)

U001354452

Facility ID:	298625219	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SCOURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3R1	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	290929
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	88/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Piping/flow restrictor, Man tank gauging		

Facility ID:	298625219	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SCOURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	290929
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, SPCC plan		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	C MART #645 (Continued)		U001354452
	Facility ID: 298625219 Is fac. regulated: Regulated facility Operator: SCOURLOCK, RICK Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860514 Tank ID: 5 Owner's Contact: JOHN LEFRAVICH Owner: COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510 Owner's Phone: 7138773939 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000888 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Retail Station Is facility open: Open Facility Phone: 8136843844 Region: Not reported Financial responsibility: State PRGM (Self/Other) District: Southwest Tracking #: 290929 Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: Not reported Content Category: Pollutant Last used Date: 93/09 RPT by Tank #: Not reported	
13	HUTTO'S CORNER 642 W BUFFALO AVE TAMPA, FL 33603	UST LUST	U001354172 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HUTTO'S CORNER (Continued)

U001354172

LUST:

Facility ID:	8624919	Facility Type:	RETAIL STATION
Telephone:	8132292550	Alias Name 1:	Not reported
Discovery Date:	07/20/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HUTTO'S CORNER (Continued)

U001354172

UST:

Facility ID:	298624919	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HUTTO'S CORNER		
Contact:	Not reported	Facility Phone:	8132292550
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	MARK BAKER		
Owner:	HUTTOS CORNER		
	642 W BUFFALO AVE		
	TAMPA, FL 336033452		
Owner's Phone:	8132292550	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624919	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HUTTO'S CORNER		
Contact:	Not reported	Facility Phone:	8132292550
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	MARK BAKER		
Owner:	HUTTOS CORNER		
	642 W BUFFALO AVE		
	TAMPA, FL 336033452		
Owner's Phone:	8132292550	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

14

CUMBERLAND FARMS #1003
502 E BUFFALO AVE
TAMPA, FL 33603

FINDS
UST
LUST

1000737929
FLD984218263

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CUMBERLAND FARMS #1003 (Continued)

1000737929

LUST:

Facility ID:	8625782	Facility Type:	RETAIL STATION
Telephone:	8132399031	Alias Name 1:	Not reported
Discovery Date:	10/30/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	030	Alias Name 4:	Not reported
Rank:	03967	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CUMBERLAND FARMS #1003 (Continued)

1000737929

UST:

Facility ID:	298625782	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CUMBERLAND FARMS, INC.		
Contact:	Not reported	Facility Phone:	8132399031
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	EMILE TAYEH		
Owner:	CUMBERLAND FARMS INC		
	777 DEDHAM ST		
	CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625782	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CUMBERLAND FARMS, INC.		
Contact:	Not reported	Facility Phone:	8132399031
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	EMILE TAYEH		
Owner:	CUMBERLAND FARMS INC		
	777 DEDHAM ST		
	CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CUMBERLAND FARMS #1003 (Continued)

1000737929

Facility ID:	298625782	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CUMBERLAND FARMS, INC.		
Contact:	Not reported	Facility Phone:	8132399031
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	EMILE TAYEH		
Owner:	CUMBERLAND FARMS INC 777 DEDHAM ST CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		
Facility ID:	298625782	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CUMBERLAND FARMS, INC.		
Contact:	Not reported	Facility Phone:	8132399031
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	EMILE TAYEH		
Owner:	CUMBERLAND FARMS INC 777 DEDHAM ST CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CUMBERLAND FARMS #1003 (Continued)

1000737929

Facility ID:	298625782	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CUMBERLAND FARMS, INC.		
Contact:	Not reported	Facility Phone:	8132399031
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	EMILE TAYEH		
Owner:	CUMBERLAND FARMS INC 777 DEDHAM ST CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging, Man tank gauging		

Facility ID:	298625782	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CUMBERLAND FARMS, INC.		
Contact:	Not reported	Facility Phone:	8132399031
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	6	District:	Southwest
Owner's Contact:	EMILE TAYEH		
Owner:	CUMBERLAND FARMS INC 777 DEDHAM ST CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging, Man tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CUMBERLAND FARMS #1003 (Continued)

1000737929

Facility ID:	298625782	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CUMBERLAND FARMS, INC.		
Contact:	Not reported	Facility Phone:	8132399031
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	7	District:	Southwest
Owner's Contact:	EMILE TAYEH		
Owner:	CUMBERLAND FARMS INC 777 DEDHAM ST CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging, Man tank gauging		

Facility ID:	298625782	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CUMBERLAND FARMS, INC.		
Contact:	Not reported	Facility Phone:	8132399031
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	8	District:	Southwest
Owner's Contact:	EMILE TAYEH		
Owner:	CUMBERLAND FARMS INC 777 DEDHAM ST CANTON, MA 020219118		
Owner's Phone:	6178284900	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

15

CHEVRON #48117-DEANS
802 E BUFFALO AVE
TAMPA, FL 33603

UST
LUST

U001354636
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48117-DEANS (Continued)

U001354636

LUST:

Facility ID:	8625417	Facility Type:	RETAIL STATION
Telephone:	8132391411	Alias Name 1:	Not reported
Discovery Date:	08/09/89	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48117-DEANS (Continued)

U001354636

UST:

Facility ID:	298625417	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	REYNOLDS, E T		
Contact:	Not reported	Facility Phone:	8132391411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	4049843000	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/01
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298625417	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	REYNOLDS, E T		
Contact:	Not reported	Facility Phone:	8132391411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	4049843000	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Vapor monitoring		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CHEVRON #48117-DEANS (Continued)

U001354636

Facility ID:	298625417	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	REYNOLDS, E T		
Contact:	Not reported	Facility Phone:	8132391411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	4049843000	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Vapor monitoring		

Facility ID:	298625417	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	REYNOLDS, E T		
Contact:	Not reported	Facility Phone:	8132391411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	4049843000	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Vapor monitoring		

16

RIVERSIDE LAUNDROMAT & CLEANERS
906 E BUFFALO AVE
TAMPA, FL 33603

RCRIS-SQG 1000500838
FINDS FLD984209403

RCRIS: Not Reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
17	IDEAL CLEANERS 1411 E BUFFALO AVE TAMPA, FL 33603 RCRIS: Owner: STEVE DIAZ (813) 248-2921 Contact:STEVE DIAZ (813) 248-2921 Waste Quantity Info Source F002 .00000 (T) Notification 		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

DANNYS BARBEQUE (Continued)

U001356489

Facility ID:	299300139	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNYS BARBEQUE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930225	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	EVELYN & HENRY TYRE		
Owner:	TYRE, EVELYN & HENRY		
	13501 CAPITAL DR S		
	TAMPA, FL 336130000		
Owner's Phone:	8139623227	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	299300139	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNYS BARBEQUE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930225	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	EVELYN & HENRY TYRE		
Owner:	TYRE, EVELYN & HENRY		
	13501 CAPITAL DR S		
	TAMPA, FL 336130000		
Owner's Phone:	8139623227	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

DANNYS BARBEQUE (Continued)

U001356489

Facility ID:	299300139	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNYS BARBEQUE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930225	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	EVELYN & HENRY TYRE		
Owner:	TYRE, EVELYN & HENRY		
	13501 CAPITAL DR S		
	TAMPA, FL 336130000		
Owner's Phone:	8139623227	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	299300139	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNYS BARBEQUE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930225	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	EVELYN & HENRY TYRE		
Owner:	TYRE, EVELYN & HENRY		
	13501 CAPITAL DR S		
	TAMPA, FL 336130000		
Owner's Phone:	8139623227	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000200	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

19

HILLSBOROUGH CO N B YOUNG JR HIGH S
1807 E DR MARTIN LUTHER KING
TAMPA, FL 33605

RCRIS-SQG 1000703416
FLD984230060

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CO N B YOUNG JR HIGH S (Continued)

1000703416

RCRIS:

Owner: PHILLIP GUFFEY, DEALER
(813) 626-0806

Contact: PHILLIP GUFFEY
(813) 626-0806

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D002	.00000 (T)	Notification	D003	.00000 (T)	Notification
D004	.00000 (T)	Notification	D005	.00000 (T)	Notification
D006	.00000 (T)	Notification	D007	.00000 (T)	Notification
D008	.00000 (T)	Notification	D009	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

19

HILLSBOROUGH CNTY SCHOOL BD-YOUNG
1807 E BUFFALO AVE
TAMPA, FL 33610

UST

U001355600
N/A

UST:

Facility ID:	298736489	Facility Type:	County Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HILLSBOROUGH CNTY SCHOOL BD		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871202	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT J AGUIS		
Owner:	HILLSBOROUGH CNTY SCHOOL BD 901 E KENNEDY BLVD TAMPA, FL 33601		
Owner's Phone:	8139876994	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	79/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

20

MONEY SAVER QUALITY GAS
2902 E BUFFALO AVE
TAMPA, FL 33610

UST
LUST

U001356316
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MONEY SAVER QUALITY GAS (Continued)

U001356316

LUST:

Facility ID:	9101592	Facility Type:	RETAIL STATION
Telephone:	8132541446	Alias Name 1:	Not reported
Discovery Date:	03/29/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	011 (LOW)	Alias Name 4:	Not reported
Rank:	06640	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

ABANDONED TANK RESTORATIO

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MONEY SAVER QUALITY GAS (Continued)

U001356316

UST:

Facility ID:	299101592	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MONEY SAVER QUALITY GAS		
Contact:	Not reported	Facility Phone:	8132541446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910404	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BERNARD JORDAN		
Owner:	JORDAN, BERNARD		
	2132 W MAIN ST		
	TAMPA, FL 336073438		
Owner's Phone:	8132541446	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299101592	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MONEY SAVER QUALITY GAS		
Contact:	Not reported	Facility Phone:	8132541446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910404	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BERNARD JORDAN		
Owner:	JORDAN, BERNARD		
	2132 W MAIN ST		
	TAMPA, FL 336073438		
Owner's Phone:	8132541446	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MONEY SAVER QUALITY GAS (Continued)

U001356316

Facility ID:	299101592	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MONEY SAVER QUALITY GAS		
Contact:	Not reported	Facility Phone:	8132541446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910404	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BERNARD JORDAN		
Owner:	JORDAN, BERNARD		
	2132 W MAIN ST		
	TAMPA, FL 336073438		
Owner's Phone:	8132541446	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299101592	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MONEY SAVER QUALITY GAS		
Contact:	Not reported	Facility Phone:	8132541446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910404	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	BERNARD JORDAN		
Owner:	JORDAN, BERNARD		
	2132 W MAIN ST		
	TAMPA, FL 336073438		
Owner's Phone:	8132541446	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

MONEY SAVER QUALITY GAS (Continued)

U001356316

Facility ID:	299101592	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MONEY SAVER QUALITY GAS		
Contact:	Not reported	Facility Phone:	8132541446
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910404	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	BERNARD JORDAN		
Owner:	JORDAN, BERNARD		
	2132 W MAIN ST		
	TAMPA, FL 336073438		
Owner's Phone:	8132541446	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

21

HOPE FOOD STORE
4002 N 22ND ST
TAMPA, FL 33610

UST
LUST

U001356246
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HOPE FOOD STORE (Continued)

U001356246

LUST:

Facility ID:	9100632	Facility Type:	RETAIL STATION
Telephone:	8132389385	Alias Name 1:	Not reported
Discovery Date:	04/06/93	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

CLOSURE REPORT

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

PETRO. LIABILITY INS. & RESTOR.

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

INELIGIBLE

Incident Ineligible Reason:

NO INSURANCE

Incident Ineligible Description:

NO INSURANCE

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HOPE FOOD STORE (Continued)

U001356246

UST:

Facility ID:	299100632	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	E & B ONE STOP		
Contact:	Not reported	Facility Phone:	8132389385
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910301	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	EMAD QASEM		
Owner:	QASEM, EMAD		
	4002 N 22ND ST		
	TAMPA, FL 336100000		
Owner's Phone:	8135371662	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	74/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	299100632	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	E & B ONE STOP		
Contact:	Not reported	Facility Phone:	8132389385
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910301	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	EMAD QASEM		
Owner:	QASEM, EMAD		
	4002 N 22ND ST		
	TAMPA, FL 336100000		
Owner's Phone:	8135371662	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	74/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HOPE FOOD STORE (Continued)

U001356246

Facility ID:	299100632	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	E & B ONE STOP		
Contact:	Not reported	Facility Phone:	8132389385
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910301	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	EMAD QASEM		
Owner:	QASEM, EMAD 4002 N 22ND ST TAMPA, FL 336100000		
Owner's Phone:	8135371662	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	74/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	299100632	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	E & B ONE STOP		
Contact:	Not reported	Facility Phone:	8132389385
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910301	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	EMAD QASEM		
Owner:	QASEM, EMAD 4002 N 22ND ST TAMPA, FL 336100000		
Owner's Phone:	8135371662	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HOPE FOOD STORE (Continued)

U001356246

Facility ID:	299100632	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	E & B ONE STOP		
Contact:	Not reported	Facility Phone:	8132389385
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910301	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	EMAD QASEM		
Owner:	QASEM, EMAD		
	4002 N 22ND ST		
	TAMPA, FL 336100000		
Owner's Phone:	8135371662	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

21

FLEET TRANSPORT CO INC
4012 S 22ND ST CAUSEWAY BLVD
TAMPA, FL 33675

RCRIS-SQG 1000698819
FLD044997732

RCRIS:

Owner: DAVID PATTON
(813) 248-4975

Contact: DAVID A
(813) 248-4975

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

21

ETHANOL CORP
4012 N 22ND ST
TAMPA, FL 33610

LUST
AST S101264756
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ETHANOL CORP (Continued)

S101264756

LUST:

Facility ID:	8943777	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132486303	Alias Name 1:	Not reported
Discovery Date:	12/24/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ETHANOL CORP (Continued)

S101264756

AST:

Facility ID:	298943777	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JONES MIKE		
Facility Phone:	8132486303	Permit Section:	00000
Date entered:	890411	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM WOOD		
Owner:	ETHANOL CORP		
	PO BOX 105177		
	ATLANTA, GA 303480000		
Owner's Phone:	4044317640	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00030000
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

Facility ID:	298943777	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JONES MIKE		
Facility Phone:	8132486303	Permit Section:	00000
Date entered:	890411	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JIM WOOD		
Owner:	ETHANOL CORP		
	PO BOX 105177		
	ATLANTA, GA 303480000		
Owner's Phone:	4044317640	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00030000
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/03
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

22

ZEPHYRHILLS WATER CO
3919 N HIGHLAND AVE
TAMPA, FL 33603

UST

U001355078
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ZEPHYRHILLS WATER CO (Continued)

U001355078

UST:

Facility ID:	298627002	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ZEPHYRHILLS WATER CO		
Contact:	Not reported	Facility Phone:	8132287761
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM LARSON		
Owner:	ZEPHYRHILLS WATER CO		
	6403 HARNEY RD		
	TAMPA, FL 336109593		
Owner's Phone:	8132240452	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

23

TAMPA HOUSING AUTHORITY ROBLES PK
3814 CENTRAL AVE
TAMPA, FL 33603

FINDS
RCRIS-LQG

1000886549
FL0000079921

RCRIS:

Owner: ANGELO DEPAUL, DIR
(813) 253-0551

Contact:ANGELO DEPAUL
(813) 253-0551

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (N)	State Inspection	D000	.00000 (T)	Notification
D002	.00000 (T)	Notification	D008	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

24

JESSE HONDA CAR SERVICE
3816 NEBRASKA AVE
TAMPA, FL 33603

RCRIS-SQG
FINDS

1000498501
FLD982081317

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number															
	JESSE HONDA CAR SERVICE (Continued)		1000498501															
	RCRIS: Owner: PAUL JESSE (813) 229-6218 Contact:PAUL JESSE (813) 229-6218																	
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D001</td><td>.00000 (T)</td><td>Notification</td></tr><tr><td>F004</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	D001	.00000 (T)	Notification	F004	.00000 (T)	Notification	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>F002</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	F002	.00000 (T)	Notification	
Waste	Quantity	Info Source																
D001	.00000 (T)	Notification																
F004	.00000 (T)	Notification																
Waste	Quantity	Info Source																
F002	.00000 (T)	Notification																
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported																	
25	SHERWIN WILLIAMS 920 3721 N FLORIDA AVE TAMPA, FL 33603	RCRIS-SQG FINDS	1000499386 FLD984194514															
	RCRIS: Owner: JAMES DUNN Contact:JAMES DUNN																	
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D001</td><td>.00000 (T)</td><td>Notification</td></tr><tr><td>F005</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	D001	.00000 (T)	Notification	F005	.00000 (T)	Notification	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>F003</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	F003	.00000 (T)	Notification	
Waste	Quantity	Info Source																
D001	.00000 (T)	Notification																
F005	.00000 (T)	Notification																
Waste	Quantity	Info Source																
F003	.00000 (T)	Notification																
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported																	
25	HASBROUCK, JERRY 3802 N FLORIDA AVE TAMPA, FL	UST LUST	U001378123 N/A															

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HASBROUCK, JERRY (Continued)

U001378123

LUST:

Facility ID:	9202418	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132370780	Alias Name 1:	Not reported
Discovery Date:	09/28/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	012 (LOW)	Alias Name 4:	Not reported
Rank:	06172	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HASBROUCK, JERRY (Continued)

U001378123

UST:

Facility ID:	299202418	Facility Type:	Non-retail Business
Is fac. regulated:.	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132370780
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920819	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JERRY HASBROUCK		
Owner:	HASBROUCK, JERRY		
	7304 N NEBRASKA AVE		
	TAMPA, FL 336040000		
Owner's Phone:	8138889779	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299202418	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132370780
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920819	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JERRY HASBROUCK		
Owner:	HASBROUCK, JERRY		
	7304 N NEBRASKA AVE		
	TAMPA, FL 336040000		
Owner's Phone:	8138889779	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HASBROUCK, JERRY (Continued)

U001378123

Facility ID:	299202418	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132370780
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920819	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JERRY HASBROUCK		
Owner:	HASBROUCK, JERRY 7304 N NEBRASKA AVE TAMPA, FL 336040000		
Owner's Phone:	8138889779	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299202418	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132370780
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920819	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JERRY HASBROUCK		
Owner:	HASBROUCK, JERRY 7304 N NEBRASKA AVE TAMPA, FL 336040000		
Owner's Phone:	8138889779	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

26

KEVINS FRONT WHEEL DRIVE
3707 N NEBRASKA AVE
TAMPA, FL 33603

RCRIS-SQG 1000859171
FINDS FL0000121137

MAP FINDINGS

Map ID			
Direction			
Distance	Site	Database(s)	EDR ID Number EPA ID Number

KEVINS FRONT WHEEL DRIVE (Continued)

1000859171

RCRIS:

Owner: KEVIN KIRKLAND, OWNER

Contact:KEVIN KIRKLAND

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D006	.00000 (T)	Notification	D007	.00000 (T)	Notification
D008	.00000 (T)	Notification	D018	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

27

LAKE AND CENTRAL PLAZA
3701 N CENTRAL AVE
TAMPA, FL 33603

UST
LUST

U001356296
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

LAKE AND CENTRAL PLAZA (Continued)

U001356296

LUST:

Facility ID:	9101311	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8139209702	Alias Name 1:	Not reported
Discovery Date:	02/24/93	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	CONTAMINATION ASSESSMENT REPORT
Extension Status:	APPROVED
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

LAKE AND CENTRAL PLAZA (Continued)

U001356296

UST:

Facility ID:	299101311	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MEISTER, HENRY W II		
Contact:	Not reported	Facility Phone:	8139209702
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910329	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	SCOTT MEISTER		
Owner:	MEISTER, ANNE B & HENRY W PO BOX 151529 TAMPA, FL 336841529		
Owner's Phone:	8138798825	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299101311	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MEISTER, HENRY W II		
Contact:	Not reported	Facility Phone:	8139209702
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910329	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	SCOTT MEISTER		
Owner:	MEISTER, ANNE B & HENRY W PO BOX 151529 TAMPA, FL 336841529		
Owner's Phone:	8138798825	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

28

TEXACO STATION
2802 E LAKE AVE
TAMPA, FL 33605

UST
LUST

U001355173
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO STATION (Continued)

U001355173

UST:

Facility ID:	298627321	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM FELDER		
Contact:	Not reported	Facility Phone:	8132479871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861030	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298627321	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM FELDER		
Contact:	Not reported	Facility Phone:	8132479871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861030	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TEXACO STATION (Continued)

U001355173

Facility ID:	298627321	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM FELDER		
Contact:	Not reported	Facility Phone:	8132479871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861030	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298627321	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM FELDER		
Contact:	Not reported	Facility Phone:	8132479871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861030	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

28

TEXACO-A-ONE USE 298627321
2802 E LAKE AVE
TAMPA, FL 33610

UST

U001354996
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TEXACO-A-ONE USE 298627321 (Continued)

U001354996

UST:

Facility ID:	298625796	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BENJAMIN FELDER		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		
Facility ID:	298625796	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BENJAMIN FELDER		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TEXACO-A-ONE USE 298627321 (Continued)

U001354996

Facility ID:	298625796	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BENJAMIN FELDER		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625796	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BENJAMIN FELDER		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	87/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

29

SLOOP MONUMENT & VAULT CO.,INC.
3407 E LAKE AVE
TAMPA, FL 33610

UST

U001355617
N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	SLOOP MONUMENT & VAULT CO.,INC. (Continued)		U001355617
	UST: Facility ID: 298736507 Facility Type: Non-retail Business Is fac. regulated: Regulated facility Is facility open: Open Operator: SLOOP MONUMENT & VAULT CO.,INC. Contact: Not reported Facility Phone: 8132483975 Permit Section: Not reported Region: Not reported Facility Code: No violation Date entered: 871203 Financial responsibility: Not reported Tank ID: 1 District: Southwest Owner's Contact: Not reported Owner: SLOOP MONUMENT & VAULT CO INC 3407 E LAKE AVE TAMPA, FL 336107941 Owner's Phone: 8132483975 Tracking #: Not reported Cleanup Status: Not reported Any contaminated soil: Not reported Drink. Wat. Well: Not reported Any contaminated surface water: Not reported Tank Cap. (Gals): 00000500 Any monit. wells: Not reported Tank position: Not reported Any contam. groundwater: Not reported Tank Content: Not reported Contaminated media indicator: Not reported Disposal Method: In service Install. Date: Not reported Is tank regulated: Regulated tank Content Category: Vehicular Facility Status: Not reported Last used Date: Not reported RPT Tank #: Not reported RPT by Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported		
29	REDI GROCERY 3401 E LAKE AVE TAMPA, FL 33610	UST LUST	U001354027 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

REDI GROCERY (Continued)

U001354027

LUST:

Facility ID:	8624763	Facility Type:	RETAIL STATION
Telephone:	8132483058	Alias Name 1:	Not reported
Discovery Date:	09/14/88	Alias Name 2:	Not reported
Tracking Number:	293764	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

REDI GROCERY (Continued)

U001354027

UST:

Facility ID:	298624763	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132483058
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293764
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624763	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132483058
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293764
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

REDI GROCERY (Continued)

U001354027

Facility ID:	298624763	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132483058
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293764
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624763	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132483058
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293764
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

REDI GROCERY (Continued)

U001354027

Facility ID:	298624763	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132483058
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293764
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	87/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624763	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132483058
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293764
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	87/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

REDI GROCERY (Continued)

U001354027

Facility ID:	298624763	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132483058
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293764
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	87/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

Facility ID:	298624763	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132483058
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293764
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	87/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

30

BORRELL ELECTRIC CO INC
3601 N NEBRASKA AVE
TAMPA, FL 33603

UST

U001354929
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BORRELL ELECTRIC CO INC (Continued)

U001354929

UST:

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC 3601 N NEBRASKA AVE TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC 3601 N NEBRASKA AVE TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BORRELL ELECTRIC CO INC (Continued)

U001354929

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC 3601 N NEBRASKA AVE TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC 3601 N NEBRASKA AVE TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BORRELL ELECTRIC CO INC (Continued)

U001354929

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC 3601 N NEBRASKA AVE TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625725	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CARLOS MENENDEZ		
Contact:	Not reported	Facility Phone:	8132332727
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	CARLOS MENENDEZ		
Owner:	BORRELL ELECTRIC CO INC 3601 N NEBRASKA AVE TAMPA, FL 336035011		
Owner's Phone:	8132232727	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	89/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	BORRELL ELECTRIC CO INC (Continued)		U001354929
	Facility ID: 298625725 Is fac. regulated: Regulated facility Operator: CARLOS MENENDEZ Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860523 Tank ID: 7 Owner's Contact: CARLOS MENENDEZ Owner: BORRELL ELECTRIC CO INC 3601 N NEBRASKA AVE TAMPA, FL 336035011 Owner's Phone: 8132232727 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000500 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man tank gauging	Facility Type: Non-retail Business Is facility open: Open Facility Phone: 8132332727 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Pollutant Last used Date: 92/09 RPT by Tank #: Not reported	
31	COLLEGE HILL HOMES 3606 20TH ST TAMPA, FL 33605	UST	U001823441 N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	COLLEGE HILL HOMES (Continued)		U001823441
	UST: Facility ID: 299400700 Is fac. regulated: Not regulated facility Operator: ANGELA DEPAUL Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 940412 Tank ID: 1 Owner's Contact: ANGELO DEPAUL Owner: TAMPA, CITY OF-HOUSING AUTHORITY 1514 UNION ST TAMPA, FL 336070000 Owner's Phone: 8132530551 Cleanup Status: Ongoing Drink. Wat. Well: 0014 Tank Cap. (Gals): 00003000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: None	Facility Type: Residence Is facility open: Closed Facility Phone: 8132530551 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: Not reported Content Category: Vehicular Last used Date: 93/05 RPT by Tank #: Not reported	
31	COLLEGE HILL HOMES 3606 N 20TH ST TAMPA, FL 33605	LUST	S100990448 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

COLLEGE HILL HOMES (Continued)

S100990448

LUST:

Facility ID:	9400700	Facility Type:	RESIDENCE
Telephone:	8132530551	Alias Name 1:	Not reported
Discovery Date:	05/14/93	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

CLOSURE REPORT

Lead:

Not reported

Incident 17-770 Cleanup:

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	KEROSENE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

32

TOWNE'S UNIFORM
3608 N 34TH ST
TAMPA, FL 33605

UST

U001354110
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TOWNE'S UNIFORM (Continued)

U001354110

UST:

Facility ID:	298624852	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TOWNE'S LAUNDRY & CLEANERS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARY ANN MCCULLOH		
Owner:	TOM MCDONALD OIL CO.		
	5006 W KNOX ST		
	TAMPA, FL 336348028		
Owner's Phone:	8138860777	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624852	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TOWNE'S LAUNDRY & CLEANERS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MARY ANN MCCULLOH		
Owner:	TOM MCDONALD OIL CO.		
	5006 W KNOX ST		
	TAMPA, FL 336348028		
Owner's Phone:	8138860777	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TOWNE'S UNIFORM (Continued)

U001354110

Facility ID:	298624852	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TOWNE'S LAUNDRY & CLEANERS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MARY ANN MCCULLOH		
Owner:	TOM MCDONALD OIL CO. 5006 W KNOX ST TAMPA, FL 336348028		
Owner's Phone:	8138860777	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624852	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TOWNE'S LAUNDRY & CLEANERS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MARY ANN MCCULLOH		
Owner:	TOM MCDONALD OIL CO. 5006 W KNOX ST TAMPA, FL 336348028		
Owner's Phone:	8138860777	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000250	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

33

CIRCLE AUTO SERVICE OF TAMPA
3602 N FLORIDA AVE
TAMPA, FL 33603

UST
LUST

U001354795
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CIRCLE AUTO SERVICE OF TAMPA (Continued)

U001354795

LUST:

Facility ID:	8625584	Facility Type:	RETAIL STATION
Telephone:	8132249442	Alias Name 1:	Not reported
Discovery Date:	02/03/95	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CIRCLE AUTO SERVICE OF TAMPA (Continued)

U001354795

UST:

Facility ID:	298625584	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CIRCLE AUTO SERVICE OF TAMPA		
Contact:	Not reported	Facility Phone:	8132249442
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TED LUTZ		
Owner:	TED'S SERVICE CENTER, INC. 3602 N FLORIDA AVE TAMPA, FL 336035819		
Owner's Phone:	8132249442	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	7/8/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, GW mon plan		

Facility ID:	298625584	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CIRCLE AUTO SERVICE OF TAMPA		
Contact:	Not reported	Facility Phone:	8132249442
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	TED LUTZ		
Owner:	TED'S SERVICE CENTER, INC. 3602 N FLORIDA AVE TAMPA, FL 336035819		
Owner's Phone:	8132249442	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	7/8/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, GW mon plan		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CIRCLE AUTO SERVICE OF TAMPA (Continued)

U001354795

Facility ID:	298625584	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CIRCLE AUTO SERVICE OF TAMPA		
Contact:	Not reported	Facility Phone:	8132249442
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	TED LUTZ		
Owner:	TED'S SERVICE CENTER, INC. 3602 N FLORIDA AVE TAMPA, FL 336035819		
Owner's Phone:	8132249442	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, GW mon plan		

Facility ID:	298625584	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CIRCLE AUTO SERVICE OF TAMPA		
Contact:	Not reported	Facility Phone:	8132249442
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	TED LUTZ		
Owner:	TED'S SERVICE CENTER, INC. 3602 N FLORIDA AVE TAMPA, FL 336035819		
Owner's Phone:	8132249442	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, GW mon plan		

34

SQUARE DEAL BATTERY
3512 N FLORIDA AVE
TAMPA, FL 33603

RCRIS-SQG 1000155255
FINDS FLD984166116
RCRIS-TSD

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	SQUARE DEAL BATTERY (Continued)		1000155255
	RCRIS:		
	Owner: LARRY CALHOUN, MGR (813) 223-3303		
	Contact: LARRY CALHOUN (813) 223-3303		
	Waste	Quantity	Info Source
	D002	.00000 (T)	Notification
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported		
35	ALL AMERICAN WRECKER 3400 N FLORIDA AVE TAMPA, FL 33603	RCRIS-SQG FINDS	1000821349 FLD984242685
	RCRIS:		
	Owner: L W CABLE (800) 940-8689		
	Contact: L W (800) 940-8689		
	Waste	Quantity	Info Source
	D000	.00000 (T)	Notification
	D007	.00000 (T)	Notification
	D018	.00000 (T)	Notification
	D027	.00000 (T)	Notification
	D040	.00000 (T)	Notification
	Waste	Quantity	Info Source
	D001	.00000 (T)	Notification
	D008	.00000 (T)	Notification
	D021	.00000 (T)	Notification
	D039	.00000 (T)	Notification
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported		
35	SAFETY SCHOOL TRANSPORTATION 3401 N FLORIDA AVE TAMPA, FL 33603	UST AST	U001354068 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SAFETY SCHOOL TRANSPORTATION (Continued)

U001354068

UST:

Facility ID:	298624807	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SAFETY SCHOOL TRANSPORTATION		
Contact:	Not reported	Facility Phone:	8132235389
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	AHMED KAMEL		
Owner:	SAFETY SCHOOL TRANSPORTATION		
	3401 N FLORIDA AVE		
	TAMPA, FL 336035852		
Owner's Phone:	8132235389	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	4
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624807	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SAFETY SCHOOL TRANSPORTATION		
Contact:	Not reported	Facility Phone:	8132235389
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	AHMED KAMEL		
Owner:	SAFETY SCHOOL TRANSPORTATION		
	3401 N FLORIDA AVE		
	TAMPA, FL 336035852		
Owner's Phone:	8132235389	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SAFETY SCHOOL TRANSPORTATION (Continued)

U001354068

Facility ID:	298624807	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SAFETY SCHOOL TRANSPORTATION		
Contact:	Not reported	Facility Phone:	8132235389
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	AHMED KAMEL		
Owner:	SAFETY SCHOOL TRANSPORTATION		
	3401 N FLORIDA AVE		
	TAMPA, FL 336035852		
Owner's Phone:	8132235389	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	77/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

AST:

Facility ID:	298624807	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SAFETY SCHOOL TRANSPORTATION		
Facility Phone:	8132235389	Permit Section:	00000
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	AHMED KAMEL		
Owner:	SAFETY SCHOOL TRANSPORTATION		
	3401 N FLORIDA AVE		
	TAMPA, FL 336035852		
Owner's Phone:	8132235389	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001500
Tank Content:	Vehic diesel	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	92/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Dbl walled=primary matl, Spill cnmt		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Suction piping		
Petro. Monitoring:	DW tank space		

36

DIXIE STATION
3425 N 15TH ST
TAMPA, FL 33605

UST
LUST

U001356202
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DIXIE STATION (Continued)

U001356202

LUST:

Facility ID:	9100143	Facility Type:	RETAIL STATION
Telephone:	8132482528	Alias Name 1:	Not reported
Discovery Date:	01/17/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	KEROSENE	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DIXIE STATION (Continued)

U001356202

UST:

Facility ID:	299100143	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROBERTO GOMEZ		
Contact:	Not reported	Facility Phone:	8132482528
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910129	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERTO GOMEZ		
Owner:	GOMEZ ROBERTO		
	3425 N 15TH ST		
	TAMPA, FL 336051128		
Owner's Phone:	8132482528	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299100143	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROBERTO GOMEZ		
Contact:	Not reported	Facility Phone:	8132482528
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910129	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ROBERTO GOMEZ		
Owner:	GOMEZ ROBERTO		
	3425 N 15TH ST		
	TAMPA, FL 336051128		
Owner's Phone:	8132482528	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

DIXIE STATION (Continued)

U001356202

Facility ID:	299100143	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROBERTO GOMEZ		
Contact:	Not reported	Facility Phone:	8132482528
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910129	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ROBERTO GOMEZ		
Owner:	GOMEZ ROBERTO		
	3425 N 15TH ST		
	TAMPA, FL 336051128		
Owner's Phone:	8132482528	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299100143	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROBERTO GOMEZ		
Contact:	Not reported	Facility Phone:	8132482528
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910129	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ROBERTO GOMEZ		
Owner:	GOMEZ ROBERTO		
	3425 N 15TH ST		
	TAMPA, FL 336051128		
Owner's Phone:	8132482528	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

DIXIE STATION (Continued)

U001356202

Facility ID:	299100143	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROBERTO GOMEZ		
Contact:	Not reported	Facility Phone:	8132482528
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910129	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	ROBERTO GOMEZ		
Owner:	GOMEZ ROBERTO		
	3425 N 15TH ST		
	TAMPA, FL 336051128		
Owner's Phone:	8132482528	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299100143	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROBERTO GOMEZ		
Contact:	Not reported	Facility Phone:	8132482528
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910129	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	ROBERTO GOMEZ		
Owner:	GOMEZ ROBERTO		
	3425 N 15TH ST		
	TAMPA, FL 336051128		
Owner's Phone:	8132482528	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			DIXIE STATION (Continued)		U001356202	
			Facility ID: 299100143 Is fac. regulated: Not regulated facility Operator: ROBERTO GOMEZ Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 910129 Tank ID: 7 Owner's Contact: ROBERTO GOMEZ Owner: GOMEZ ROBERTO 3425 N 15TH ST TAMPA, FL 336051128 Owner's Phone: 8132482528 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00003000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not required	Facility Type: Retail Station Is facility open: Closed Facility Phone: 8132482528 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Pollutant Last used Date: 91/01 RPT by Tank #: Not reported		
37			OUR TIRE SHOP 3431 N 22ND ST TAMPA, FL 33605	UST LUST	U001355318 N/A	

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

OUR TIRE SHOP (Continued)

U001355318

UST:

Facility ID:	298628020	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WATSON RICARDO		
Contact:	Not reported	Facility Phone:	8132485891
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RICARDO WATSON		
Owner:	WATSON, RICARDO		
	1711 E CARACAS ST		
	TAMPA, FL 336104911		
Owner's Phone:	8136233147	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	53/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298628020	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WATSON RICARDO		
Contact:	Not reported	Facility Phone:	8132485891
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	RICARDO WATSON		
Owner:	WATSON, RICARDO		
	1711 E CARACAS ST		
	TAMPA, FL 336104911		
Owner's Phone:	8136233147	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	53/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

OUR TIRE SHOP (Continued)

U001355318

Facility ID:	298628020	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WATSON RICARDO		
Contact:	Not reported	Facility Phone:	8132485891
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	RICARDO WATSON		
Owner:	WATSON, RICARDO		
	1711 E CARACAS ST		
	TAMPA, FL 336104911		
Owner's Phone:	8136233147	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	53/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298628020	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WATSON RICARDO		
Contact:	Not reported	Facility Phone:	8132485891
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	RICARDO WATSON		
Owner:	WATSON, RICARDO		
	1711 E CARACAS ST		
	TAMPA, FL 336104911		
Owner's Phone:	8136233147	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	53/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

38

TEXACO-GREENE'S
3301 N FLORIDA AVE
TAMPA, FL 33603

UST
LUST

U001355003
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TEXACO-GREENE'S (Continued)

U001355003

LUST:

Facility ID:	8625804	Facility Type:	RETAIL STATION
Telephone:	Not reported	Alias Name 1:	Not reported
Discovery Date:	08/24/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	012 (LOW)	Alias Name 4:	Not reported
Rank:	06172	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TEXACO-GREENE'S (Continued)

U001355003

UST:

Facility ID:	298625804	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GREENE,ROBERT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT GREENE		
Owner:	GREENE, ROBERT		
	3301 N FLORIDA AVE		
	TAMPA, FL 336035850		
Owner's Phone:	8132291307	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625804	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GREENE,ROBERT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ROBERT GREENE		
Owner:	GREENE, ROBERT		
	3301 N FLORIDA AVE		
	TAMPA, FL 336035850		
Owner's Phone:	8132291307	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TEXACO-GREENE'S (Continued)

U001355003

Facility ID:	298625804	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GREENE,ROBERT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ROBERT GREENE		
Owner:	GREENE, ROBERT		
	3301 N FLORIDA AVE		
	TAMPA, FL 336035850		
Owner's Phone:	8132291307	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625804	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GREENE,ROBERT		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ROBERT GREENE		
Owner:	GREENE, ROBERT		
	3301 N FLORIDA AVE		
	TAMPA, FL 336035850		
Owner's Phone:	8132291307	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

38

LINDELL MOTORS INC
3319 NORTH FLORIDA AVE
TAMPA, FL 33606

RCRIS: Not Reported

RCRIS-SQG 1000699819
FLD981755846

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
38	LINDELL MOTORS INC 3319 N FLORIDA AVE TAMPA, FL 33603	FINDS	1000734481 FLD981755846
39	SUNCOAST MEATS & CONVENIENCE 3401 N 22ND ST TAMPA, FL 33605	UST LUST	U001354009 N/A
LUST:			
Facility ID: 8622199		Facility Type:	RETAIL STATION
Telephone: 8132486864		Alias Name 1:	Not reported
Discovery Date: 04/02/91		Alias Name 2:	Not reported
Tracking Number:		Alias Name 3:	Not reported
Score: 000 (LOW)		Alias Name 4:	Not reported
Rank: 00000		Alias Name 5:	Not reported
Class: Not reported			
Category: Not reported			
Facility Code: Not reported		Status:	Not reported
INCIDENT GENERAL INFORMATION -			
Source Description:		DISCHARGE NOTIFICATION	
Lead:		LOCAL PROGRAM	
Incident 17-770 Cleanup:		Not reported	
INCIDENT POLLUTANT INFORMATION -			
Pollutant 1: UNLEADED GAS		Est. Gallons Lost:	UNKNOWN
Pollutant 2: Not reported		Est. Gallons Lost:	00000000
Pollutant 3: Not reported		Est. Gallons Lost:	00000000
INCIDENT PROGRAM INFORMATION -			
Incident Program:		RESPONSIBLE PARTY-NO CLAIM	
Incident Program Type:		Not reported	
Incident Eligible Status:		Not reported	
Incident Ineligible Reason:		Not Reported	
Incident Ineligible Description:		Not reported	
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:		Cleanup Responsible:	Not reported
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:		Not reported	
Response Record Type:		Not reported	
Response Remedial Action Plan Type:		Not reported	
Response Status:		Not reported	
Extension Record Type:		Not reported	
Extension Status:		Not reported	
Extension Comments:		Not reported	
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:		Not reported	
Response Record Type:		Not reported	
Response Remedial Action Plan Type:		Not reported	
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:		Not reported	
Estimated Completion Year:		Not reported	
Actual Year to Complete:		Not reported	
Report Type:		Not reported	
Report Comments:		Not reported	
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:		Not reported	
Flag:		Not reported	

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SUNCOAST MEATS & CONVENIENCE (Continued)

U001354009

UST:

Facility ID:	298622199	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KEON K.LEE		
Contact:	Not reported	Facility Phone:	8132486864
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860107	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLIE KIM		
Owner:	SUNCOAST GROCERY INC 3401 N 22ND ST TAMPA, FL 336051213		
Owner's Phone:	8132472822	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298622199	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KEON K.LEE		
Contact:	Not reported	Facility Phone:	8132486864
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860107	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLIE KIM		
Owner:	SUNCOAST GROCERY INC 3401 N 22ND ST TAMPA, FL 336051213		
Owner's Phone:	8132472822	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SUNCOAST MEATS & CONVENIENCE (Continued)

U001354009

Facility ID:	298622199	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KEON K.LEE		
Contact:	Not reported	Facility Phone:	8132486864
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860107	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLIE KIM		
Owner:	SUNCOAST GROCERY INC 3401 N 22ND ST TAMPA, FL 336051213		
Owner's Phone:	8132472822	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298622199	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KEON K.LEE		
Contact:	Not reported	Facility Phone:	8132486864
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860107	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	WILLIE KIM		
Owner:	SUNCOAST GROCERY INC 3401 N 22ND ST TAMPA, FL 336051213		
Owner's Phone:	8132472822	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

39

DISCOUNT DRY CLEANERS
3409 N 22ND ST
TAMPA, FL 33605

RCRIS: Not Reported

RCRIS-SQG 1000180544
FINDS FLD105964126

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
40	SUNOCO SERVICE STATION 3402 15TH STREET TAMPA, FL 33605 RCRIS: Not Reported	RCRIS-SQG FINDS	1000496548 FLD000653857
40	CRUZ BROS 3402 N 15TH ST TAMPA, FL 33205 LUST: Facility ID: 9300644 Telephone: 5132296750 Discovery Date: 01/15/93 Tracking Number: Not reported Score: 000 (LOW) Rank: 00000 Class: Not reported Category: Not reported Facility Code: Not reported INCIDENT GENERAL INFORMATION - Source Description: Lead: Incident 17-770 Cleanup: INCIDENT POLLUTANT INFORMATION - Pollutant 1: LEADED GAS Pollutant 2: UNLEADED GAS Pollutant 3: VEHIC DIESEL INCIDENT PROGRAM INFORMATION - Incident Program: Incident Program Type: Incident Eligible Status: Incident Ineligible Reason: Incident Ineligible Description: INCIDENT INITIAL REMEDIAL ACTION INFORMATION - Free Product: Soil Removal: Soil Treatment: Other Treatment: INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION - Cleanup Responsible: Response Record Type: Response Remedial Action Plan Type: Response Status: Extension Record Type: Extension Status: Extension Comments: INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION - Cleanup Responsible: Response Record Type: Response Remedial Action Plan Type: INCIDENT REMEDIAL ACTION REPORT INFORMATION - Cleanup Responsible: Estimated Completion Year: Actual Year to Complete: Report Type: Report Comments: INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION - Site Rehab. Completion Action: Flag:	UST LUST	U001544092 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CRUZ BROS (Continued)

U001544092

UST:

Facility ID:	299300644	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ABDEL QUADER		
Contact:	Not reported	Facility Phone:	5132296750
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930826	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ABDEL QUADER		
Owner:	QUADER, ABDEL		
	2210 N CENTRAL AVE		
	TAMPA, FL 336020000		
Owner's Phone:	8132296750	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		
Facility ID:	299300644	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ABDEL QUADER		
Contact:	Not reported	Facility Phone:	5132296750
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930826	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ABDEL QUADER		
Owner:	QUADER, ABDEL		
	2210 N CENTRAL AVE		
	TAMPA, FL 336020000		
Owner's Phone:	8132296750	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CRUZ BROS (Continued)

U001544092

Facility ID:	299300644	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ABDEL QUADER		
Contact:	Not reported	Facility Phone:	5132296750
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930826	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ABDEL QUADER		
Owner:	QUADER, ABDEL		
	2210 N CENTRAL AVE		
	TAMPA, FL 336020000		
Owner's Phone:	8132296750	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		
Facility ID:	299300644	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ABDEL QUADER		
Contact:	Not reported	Facility Phone:	5132296750
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930826	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ABDEL QUADER		
Owner:	QUADER, ABDEL		
	2210 N CENTRAL AVE		
	TAMPA, FL 336020000		
Owner's Phone:	8132296750	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CRUZ BROS (Continued)

U001544092

Facility ID:	299300644	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ABDEL QUADER		
Contact:	Not reported	Facility Phone:	5132296750
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930826	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	ABDEL QUADER		
Owner:	QUADER, ABDEL 2210 N CENTRAL AVE TAMPA, FL 336020000		
Owner's Phone:	8132296750	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299300644	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ABDEL QUADER		
Contact:	Not reported	Facility Phone:	5132296750
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930826	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	ABDEL QUADER		
Owner:	QUADER, ABDEL 2210 N CENTRAL AVE TAMPA, FL 336020000		
Owner's Phone:	8132296750	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000250	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

41 HILLSBOROUGH CNTY-E TAMPA SERVICE CEN.
3419 N NEBRASKA AVE
TAMPA, FL 33603

UST
LUST
AST

U001354209
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-E TAMPA SERVICE CEN. (Continued)

U001354209

LUST:

Facility ID:	8624958	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132725220	Alias Name 1:	Not reported
Discovery Date:	12/15/88	Alias Name 2:	Not reported
Tracking Number:	295247	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	04990	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NO C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HILLSBOROUGH CNTY-E TAMPA SERVICE CEN. (Continued)

U001354209

UST:

Facility ID:	298624958	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA NEIGHBORHOOD SERVICE CENT.		
Contact:	Not reported	Facility Phone:	8132725220
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	295247
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624958	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA NEIGHBORHOOD SERVICE CENT.		
Contact:	Not reported	Facility Phone:	8132725220
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	295247
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-E TAMPA SERVICE CEN. (Continued)

U001354209

Facility ID:	298624958	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA NEIGHBORHOOD SERVICE CENT.		
Contact:	Not reported	Facility Phone:	8132725220
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	295247
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624958	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA NEIGHBORHOOD SERVICE CENT.		
Contact:	Not reported	Facility Phone:	8132725220
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	295247
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000600	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HILLSBOROUGH CNTY-E TAMPA SERVICE CEN. (Continued)

U001354209

AST:

Facility ID:	298624958	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA NEIGHBORHOOD SERVICE CENT.		
Facility Phone:	8132725220	Permit Section:	00000
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	295247
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Completed	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00000600
Tank Content:	Leaded gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	88/XX	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

42

CIRCLE K #4060
3315 N NEBRASKA AVE
TAMPA, FL 33603

UST

U001353918
N/A

UST:

Facility ID:	298508984	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CIRCLE K CORP		
Contact:	Not reported	Facility Phone:	8136898161
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	STEVE BELIN		
Owner:	CIRCLE K STORES INC		
	5650 BRECKENRIDGE PARK DR #300		
	TAMPA, FL 33610		
Owner's Phone:	8137445266	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	78/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CIRCLE K #4060 (Continued)

U001353918

Facility ID:	298508984	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CIRCLE K CORP		
Contact:	Not reported	Facility Phone:	8136898161
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	STEVE BELIN		
Owner:	CIRCLE K STORES INC		
	5650 BRECKENRIDGE PARK DR #300		
	TAMPA, FL 33610		
Owner's Phone:	8137445266	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	78/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

43

MITCHELL'S COMMUNITY SERVICE
3335 N 22ND ST
TAMPA, FL 33605

UST

U001355005
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MITCHELL'S COMMUNITY SERVICE (Continued)

U001355005

UST:

Facility ID:	298625806	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN MITCHELL		
Contact:	Not reported	Facility Phone:	8132488125
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BETTY DAVIS		
Owner:	DAVIS, LEE ESTATE 3702 E OSBORNE AVE TAMPA, FL 336106650		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	69/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625806	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN MITCHELL		
Contact:	Not reported	Facility Phone:	8132488125
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BETTY DAVIS		
Owner:	DAVIS, LEE ESTATE 3702 E OSBORNE AVE TAMPA, FL 336106650		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MITCHELL'S COMMUNITY SERVICE (Continued)

U001355005

Facility ID:	298625806	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN MITCHELL		
Contact:	Not reported	Facility Phone:	8132488125
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BETTY DAVIS		
Owner:	DAVIS, LEE ESTATE 3702 E OSBORNE AVE TAMPA, FL 336106650		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625806	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN MITCHELL		
Contact:	Not reported	Facility Phone:	8132488125
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	BETTY DAVIS		
Owner:	DAVIS, LEE ESTATE 3702 E OSBORNE AVE TAMPA, FL 336106650		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

43

COMMUNITY SERVICE STATION
3335 N 22ND ST
TAMPA, FL 33605

UST
LUST

U001355939
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

COMMUNITY SERVICE STATION (Continued)

U001355939

LUST:

Facility ID:	8942608	Facility Type:	RETAIL STATION
Telephone:	8132488125	Alias Name 1:	Not reported
Discovery Date:	12/15/88	Alias Name 2:	Not reported
Tracking Number:	296236	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: NOT ENTERED

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: RESPONSIBLE PARTY

Soil Removal: Y

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

COMMUNITY SERVICE STATION (Continued)

U001355939

UST:

Facility ID:	298942608	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SEMPER,JOHN J		
Contact:	Not reported	Facility Phone:	8132488125
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN J SEMPER		
Owner:	SEMPER, JOHN J 3335 N 22ND ST TAMPA, FL 336051939		
Owner's Phone:	8132488125	Tracking #:	296236
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	61/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	94/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	GW mon plan		

Facility ID:	298942608	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SEMPER,JOHN J		
Contact:	Not reported	Facility Phone:	8132488125
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN J SEMPER		
Owner:	SEMPER, JOHN J 3335 N 22ND ST TAMPA, FL 336051939		
Owner's Phone:	8132488125	Tracking #:	296236
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	61/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	94/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	GW mon plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

COMMUNITY SERVICE STATION (Continued)

U001355939

Facility ID:	298942608	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SEMPER,JOHN J		
Contact:	Not reported	Facility Phone:	8132488125
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN J SEMPER		
Owner:	SEMPER, JOHN J		
	3335 N 22ND ST		
	TAMPA, FL 336051939		
Owner's Phone:	8132488125	Tracking #:	296236
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	61/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	94/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	GW mon plan		
Facility ID:	298942608	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	SEMPER,JOHN J		
Contact:	Not reported	Facility Phone:	8132488125
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN J SEMPER		
Owner:	SEMPER, JOHN J		
	3335 N 22ND ST		
	TAMPA, FL 336051939		
Owner's Phone:	8132488125	Tracking #:	296236
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	61/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	94/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	GW mon plan		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	COMMUNITY SERVICE STATION (Continued)		U001355939
	Facility ID: 298942608 Is fac. regulated: Regulated facility Operator: SEMPER,JOHN J Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 890104 Tank ID: 5 Owner's Contact: JOHN J SEMPER Owner: SEMPER, JOHN J 3335 N 22ND ST TAMPA, FL 336051939 Owner's Phone: 8132488125 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000500 Tank position: Not reported Tank Content: Not reported Disposal Method: In service Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not required	Facility Type: Retail Station Is facility open: Closed Facility Phone: 8132488125 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 296236 Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 61/10 Content Category: Pollutant Last used Date: Not reported RPT by Tank #: Not reported	
44	KNI LABORATORIES 3209 TAMPA ST TAMPA, FL 33603 RCRIS: Not Reported	RCRIS-SQG FINDS	1000121828 FLD981021454
45	FORD PLUMBING CO., INC. 3201 N FLORIDA AVE TAMPA, FL 33603	UST	U001355466 N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	FORD PLUMBING CO., INC. (Continued)		U001355466
	UST: Facility ID: 298733837 Is fac. regulated: Not regulated facility Operator: FORD PLUMBING CO., INC. Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 870729 Tank ID: 1 Owner's Contact: Not reported Owner: FORD PLUMBING CO INC 3201 N FLORIDA AVE TAMPA, FL 336035936 Owner's Phone: 8132233638 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000550 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: None	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132233638 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: 56/XX Content Category: Vehicular Last used Date: 91/02 RPT by Tank #: Not reported	
46	C MART #649 3115 N NEBRASKA AVE TAMPA, FL 33603	UST LUST	U001354465 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

C MART #649 (Continued)

U001354465

LUST:

Facility ID:	8625232	Facility Type:	RETAIL STATION
Telephone:	8136844183	Alias Name 1:	Not reported
Discovery Date:	12/30/88	Alias Name 2:	Not reported
Tracking Number:	297053	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

C MART #649 (Continued)

U001354465

UST:

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC		
	9 GREENWAY PLAZA #1994		
	HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, SPCC plan		

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC		
	9 GREENWAY PLAZA #1994		
	HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

C MART #649 (Continued)

U001354465

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC		
	9 GREENWAY PLAZA #1994		
	HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, SPCC plan		

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC		
	9 GREENWAY PLAZA #1994		
	HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

C MART #649 (Continued)

U001354465

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, SPCC plan		

Facility ID:	298625232	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	8136844183
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	297053
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			C MART #649 (Continued)			U001354465
			Facility ID: 298625232 Is fac. regulated: Regulated facility Operator: COASTAL MART INC Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860514 Tank ID: 4 Owner's Contact: JOHN LEFRAVICH Owner: COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510 Owner's Phone: 7138773939 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00004000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells, SPCC plan	Facility Type: Retail Station Is facility open: Open Facility Phone: 8136844183 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 297053 Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 69/12 Content Category: Vehicular Last used Date: 88/06 RPT by Tank #: Not reported		
47			CARLSTEDT FLORIST 3116 N FLORIDA AVE TAMPA, FL 33603	UST		U001823435 N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	CARLSTEDT FLORIST (Continued)		U001823435
	UST: Facility ID: 299400641 Is fac. regulated: Not regulated facility Operator: MARK INGERMAN Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 940411 Tank ID: 1 Owner's Contact: MARK INGERMAN Owner: CARLSTEDT CO 3116 N FLORIDA AVE TAMPA, FL 336030000 Owner's Phone: 8132249731 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000550 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: None	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132249731 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Vehicular Last used Date: 92/08 RPT by Tank #: Not reported	
48	TAMPA,CITY-FIRE STATION #10 3108 N 34TH ST TAMPA, FL 33605	UST	U001355924 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-FIRE STATION #10 (Continued)

U001355924

UST:

Facility ID:	298842514	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DANIEL A. PAGE		
Owner:	TAMPA CITY DEPT SANITARY SEWERS		
	2700 MARITIME BLVD		
	TAMPA, FL 336056744		
Owner's Phone:	8132473451	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	29/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

49

SUPREME MOTORS
3000 N FLORIDA AVE
TAMPA, FL 33634

UST
LUST

U002217723
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SUPREME MOTORS (Continued)

U002217723

UST:

Facility ID:	299501949	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM A WEINEL		
Contact:	Not reported	Facility Phone:	8132375289
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950609	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	WILLIAM A WEINEL		
Owner:	WEINEL, WILLIAM A & PEREZ, RICK		
	6430 LARMON ST		
	TAMPA, FL 33634		
Owner's Phone:	8132375289	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

49

SUPREME AUTO CENTER
3016 N FLORIDA AVE
TAMPA, FL 33603

RCRIS-SQG 1000355758
FINDS FLD982162281

RCRIS:

Owner: HAWKINS JIM OWNER
(813) 229-7470

Contact: HAWKINS JIM
(813) 229-7470

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

50

CENTRO ASTURIANO HOSPITAL
1302 E 21ST AVE
TAMPA, FL 33605

UST U001355509
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CENTRO ASTURIANO HOSPITAL (Continued)

U001355509

UST:

Facility ID:	298733897	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	CENTRO ASTURIANO HOSPITAL		
Contact:	Not reported	Facility Phone:	8132474771
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	IGNACIO FERNANDEZ		
Owner:	CENTRO ASTURIANO HOSPITAL		
	1302 E 21ST AVE		
	TAMPA, FL 336051714		
Owner's Phone:	8132474771	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298733897	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	CENTRO ASTURIANO HOSPITAL		
Contact:	Not reported	Facility Phone:	8132474771
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870730	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	IGNACIO FERNANDEZ		
Owner:	CENTRO ASTURIANO HOSPITAL		
	1302 E 21ST AVE		
	TAMPA, FL 336051714		
Owner's Phone:	8132474771	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

51

CUSCADEN PARK STATION
3002 N 15TH ST
TAMPA, FL 33605

UST
LUST

U001355189
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CUSCADEN PARK STATION (Continued)

U001355189

LUST:

Facility ID:	8627365	Facility Type:	RETAIL STATION
Telephone:	8132482580	Alias Name 1:	Not reported
Discovery Date:	10/30/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: LEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CUSCADEN PARK STATION (Continued)

U001355189

UST:

Facility ID:	298627365	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GUTIERREZ, OSCAR		
Contact:	Not reported	Facility Phone:	8132482580
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861030	Financial responsibility:	None
Tank ID:	A	District:	Southwest
Owner's Contact:	OSCAR GUTIERREZ		
Owner:	GUTIERREZ, OSCAR 3002 N 15TH ST TAMPA, FL 336051812		
Owner's Phone:	8132482580	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	SPCC plan		

Facility ID:	298627365	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GUTIERREZ, OSCAR		
Contact:	Not reported	Facility Phone:	8132482580
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861030	Financial responsibility:	None
Tank ID:	B	District:	Southwest
Owner's Contact:	OSCAR GUTIERREZ		
Owner:	GUTIERREZ, OSCAR 3002 N 15TH ST TAMPA, FL 336051812		
Owner's Phone:	8132482580	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	SPCC plan		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	CUSCADEN PARK STATION (Continued)		U001355189
	Facility ID: 298627365 Is fac. regulated: Regulated facility Operator: GUTIERREZ, OSCAR Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 861030 Tank ID: C Owner's Contact: OSCAR GUTIERREZ Owner: GUTIERREZ, OSCAR 3002 N 15TH ST TAMPA, FL 336051812 Owner's Phone: 8132482580 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000500 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Retail Station Is facility open: Open Facility Phone: 8132482580 Region: Not reported Financial responsibility: None District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: Not reported Content Category: Vehicular Last used Date: 91/10 RPT by Tank #: Not reported	
52	ALLSTATE AUTO-RALPH PEREZ 2926 N NEBRASKA AVE TAMPA, FL 33602	UST	U001823430 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALLSTATE AUTO-RALPH PEREZ (Continued)

U001823430

UST:

Facility ID:	299400636	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GUILLERMO CONSUEGRA		
Contact:	Not reported	Facility Phone:	8138864158
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940408	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GUILLERMO CONSUEGRA		
Owner:	CONSUEGRA, GUILLERMO 7208 N THATCHER AVE TAMPA, FL 336140000		
Owner's Phone:	8138864158	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299400636	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GUILLERMO CONSUEGRA		
Contact:	Not reported	Facility Phone:	8138864158
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940408	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GUILLERMO CONSUEGRA		
Owner:	CONSUEGRA, GUILLERMO 7208 N THATCHER AVE TAMPA, FL 336140000		
Owner's Phone:	8138864158	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ALLSTATE AUTO-RALPH PEREZ (Continued)

U001823430

Facility ID:	299400636	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GUILLERMO CONSUEGRA		
Contact:	Not reported	Facility Phone:	8138864158
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940408	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	GUILLERMO CONSUEGRA		
Owner:	CONSUEGRA, GUILLERMO 7208 N THATCHER AVE TAMPA, FL 336140000		
Owner's Phone:	8138864158	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299400636	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GUILLERMO CONSUEGRA		
Contact:	Not reported	Facility Phone:	8138864158
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940408	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	GUILLERMO CONSUEGRA		
Owner:	CONSUEGRA, GUILLERMO 7208 N THATCHER AVE TAMPA, FL 336140000		
Owner's Phone:	8138864158	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

53

ROBERTS JOHNNY OF TAMPA
2905 N FLORIDA AVE
TAMPA, FL 33602

FINDS 1000219636
RCRIS-LQG FLD073409146

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number						
	ROBERTS JOHNNY OF TAMPA (Continued)		1000219636						
	RCRIS: Owner: TERRY MCDONALD, MGR (813) 229-1949 Contact: TERRY MCDONALD (813) 229-1949								
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>F001</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	F001	.00000 (T)	Notification		
Waste	Quantity	Info Source							
F001	.00000 (T)	Notification							
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported								
54	TAMPA,CITY-FIRE DEPT COMMUNICATIONS 2904 N MITCHELL AVE TAMPA, FL 33602	UST LUST AST	U001355890 N/A						

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-FIRE DEPT COMMUNICATIONS (Continued)

U001355890

LUST:

Facility ID:	8842212	Facility Type:	LOCAL, CITY GOVERNMENT
Telephone:	8132277011	Alias Name 1:	Not reported
Discovery Date:	12/12/88	Alias Name 2:	Not reported
Tracking Number:	295180	Alias Name 3:	Not reported
Score:	030	Alias Name 4:	Not reported
Rank:	04434	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-FIRE DEPT COMMUNICATIONS (Continued)

U001355890

UST:

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	53/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	53/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-FIRE DEPT COMMUNICATIONS (Continued)

U001355890

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	53/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		
Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	6	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well.:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-FIRE DEPT COMMUNICATIONS (Continued)

U001355890

AST:

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Facility Phone:	8132277011	Permit Section:	00000
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00001000
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	83/11
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	91/03	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Fiberglass		
Petro. Monitoring:	Not required		

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Facility Phone:	8132277011	Permit Section:	00000
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	5	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00001000
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	82/04
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	91/03	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Piping/auto shut off		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-FIRE DEPT COMMUNICATIONS (Continued)

U001355890

Facility ID:	298842212	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PAUL LOGAN		
Facility Phone:	8132277011	Permit Section:	00000
Date entered:	881129	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	7	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT		
	808 E ZACK ST		
	TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	295180
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00001000
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	88/11
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Level gauges/hi level alarms, Small use tank		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal		
Petro. Monitoring:	DW piping space, Man tank gauging		

55 HOWARD AUTOMOTIVE SERVICE
2917 N 34TH ST
TAMPA, FL 33605

UST
LUST

U001356081
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

LUST:

Facility ID:	8945488	Facility Type:	RETAIL STATION
Telephone:	8132479533	Alias Name 1:	Not reported
Discovery Date:	06/24/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

UST:

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD		
	2917 N 34TH ST		
	TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD		
	2917 N 34TH ST		
	TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HOWARD AUTOMOTIVE SERVICE (Continued)

U001356081

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD		
	2917 N 34TH ST		
	TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298945488	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WILLIAMS HOWARD		
Contact:	Not reported	Facility Phone:	8132479533
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891213	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JERRY WATKINS		
Owner:	WILLIAMS, HOWARD		
	2917 N 34TH ST		
	TAMPA, FL 336053132		
Owner's Phone:	8132479533	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

56

SEACOAST SUPPLY
2817 N 36TH ST
TAMPA, FL 33605

UST

U001354849
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SEACOAST SUPPLY (Continued)

U001354849

UST:

Facility ID:	298625642	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WALT JACKSON		
Contact:	Not reported	Facility Phone:	8132475402
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ED VAN BRUNT		
Owner:	L & W SUPPLY CORP 2817 N 36TH ST TAMPA, FL 336053127		
Owner's Phone:	8132475402	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	74/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625642	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WALT JACKSON		
Contact:	Not reported	Facility Phone:	8132475402
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ED VAN BRUNT		
Owner:	L & W SUPPLY CORP 2817 N 36TH ST TAMPA, FL 336053127		
Owner's Phone:	8132475402	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	79/08
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

57

CHEMEX PAINT & COATINGS INC
2822 35TH STREET
TAMPA, FL 33675

RCRIS-LQG 1000921700
FLD067222265

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

CHEMEX PAINT & COATINGS INC (Continued)

1000921700

RCRIS:

Owner: TONY FOSTER, ENV MGR
(813) 248-2101

Contact:TIMOTHY BELCASTRO
(813) 248-2101

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D007	.00000 (T)	Notification	D008	.00000 (T)	Notification
F003	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

There are 1 compliance/violation record(s) reported at this site:

Evaluation	Date	Violations
COMPLIANCE EVALUATION INSPECTION (CEI)	19-JUL-91	YES

57	CHEMEX CHEMICALS, INC 2822 35TH STREET TAMPA, FL 33675	TSCA	1000298860 N/A
57	ARATEX SERVICES INC 2817 N 35TH ST TAMPA, FL 33605	UST LUST	U001355270 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ARATEX SERVICES INC (Continued)

U001355270

LUST:

Facility ID:	8627781	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132472116	Alias Name 1:	Not reported
Discovery Date:	12/14/88	Alias Name 2:	Not reported
Tracking Number:	295372	Alias Name 3:	Not reported
Score:	035	Alias Name 4:	Not reported
Rank:	03369	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: NOT ENTERED

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product: Y

Cleanup Responsible: RESPONSIBLE PARTY

Soil Removal: Y

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

REMEDIAL ACTION PLAN

Response Remedial Action Plan Type:

GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ARATEX SERVICES INC (Continued)

U001355270

UST:

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ARATEX SERVICES INC (Continued)

U001355270

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298627781	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RYAN SHAYNE		
Contact:	Not reported	Facility Phone:	8132472116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ALFREDO GOMEZ		
Owner:	ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704		
Owner's Phone:	3056813521	Tracking #:	295372
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	ARATEX SERVICES INC (Continued)		U001355270
	Facility ID: 298627781 Is fac. regulated: Not regulated facility Operator: RYAN SHAYNE Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 861105 Tank ID: 5 Owner's Contact: ALFREDO GOMEZ Owner: ARATEX SERVICES INC 16001 VENTURA BLVD ENCINO, CA 914362704 Owner's Phone: 3056813521 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00004000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132472116 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 295372 Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 66/XX Content Category: Pollutant Last used Date: 88/11 RPT by Tank #: Not reported	
57	CHEMEX PAINT & COATINGS INC 2822 N 35TH ST TAMPA, FL 33605	UST AST	U001355417 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEMEX PAINT & COATINGS INC (Continued)

U001355417

UST:

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Man tank gauging		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Man tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Man tank gauging		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Man tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006400	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Man tank gauging		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006400	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Man tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Man tank gauging		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Contact:	Not reported	Facility Phone:	8132486104
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Man tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CHEMEX PAINT & COATINGS INC (Continued)

U001355417

AST:

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	00000
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	00000
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	11	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001500
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	00000
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	12	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001500
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	00000
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	13	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001500
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	00000
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	14	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00000750
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotoc metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	00000
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	15	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Avoveground	Tank Cap. (Gals):	00010000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotoc metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

CHEMEX PAINT & COATINGS INC (Continued)

U001355417

Facility ID:	298732617	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	CHEMEX PAINT & COATINGS, INC.		
Facility Phone:	8132486104	Permit Section:	00000
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	TONY FOSTER		
Owner:	CHEMEX PAINT & COATINGS INC PO BOX 5449 % TONY FOSTER TAMPA, FL 336750000		
Owner's Phone:	8132482101	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Hazardous substance	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	92/05	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Bulk product piping		
Petro. Monitoring:	Man tank gauging, Unknown/not reported		

57	CHEMEX PAINT & COATINGS CO 2822 N 35TH ST TAMPA, FL 33675 Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production	FINDS	1000733512 FLD067222265
58	2818 NORTH ELMORE AV TAMPA, FL	ERNS	8801808 N/A
59	TEAGARDEN, JEFF 2706 N TAMPA ST TAMPA, FL 33602	UST	U001356259 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TEAGARDEN, JEFF (Continued)

U001356259

UST:

Facility ID:	299100904	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TEAGARDEN, JEFF	Facility Phone:	Not reported
Contact:	Not reported	Region:	Not reported
Permit Section:	Not reported	Financial responsibility:	Not reported
Facility Code:	No violation	District:	Southwest
Date entered:	910313		
Tank ID:	1		
Owner's Contact:	ROBERT G LESTER		
Owner:	TEAGARDEN, JEFF		
	2706 N TAMPA ST		
	TAMPA, FL 336021428		
Owner's Phone:	8139962121	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	40/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299100904	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TEAGARDEN, JEFF	Facility Phone:	Not reported
Contact:	Not reported	Region:	Not reported
Permit Section:	Not reported	Financial responsibility:	Not reported
Facility Code:	No violation	District:	Southwest
Date entered:	910313		
Tank ID:	2		
Owner's Contact:	ROBERT G LESTER		
Owner:	TEAGARDEN, JEFF		
	2706 N TAMPA ST		
	TAMPA, FL 336021428		
Owner's Phone:	8139962121	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	40/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	TEAGARDEN, JEFF (Continued)		U001356259
	Facility ID: 299100904 Is fac. regulated: Not regulated facility Operator: TEAGARDEN, JEFF Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 910313 Tank ID: 3 Owner's Contact: ROBERT G LESTER Owner: TEAGARDEN, JEFF 2706 N TAMPA ST TAMPA, FL 336021428 Owner's Phone: 8139962121 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000500 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: Not reported Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: 40/XX Content Category: Vehicular Last used Date: 88/05 RPT by Tank #: Not reported	
59	KHAJEHNOORI HAZARDOUS WASTE 2740 NORTH TAMPA ST SUITE C TAMPA, FL 33603 RCRIS: Not Reported	RCRIS-SQG FINDS	1000265433 FLD981931140
60	KNL 2742 N FLORIDA AVE TAMPA, FL 33601 RCRIS: Not Reported	RCRIS-SQG FINDS	1000100140 FLD981025869
61	CLOROX CO 3601 EAST COLUMBUS DRIVE TAMPA, FL 94566 RCRIS: Not Reported	RCRIS-SQG	1000698608 FLD004097945
61	CLOROX CO 3601 E COLUMBUS DR TAMPA, FL 33605	FINDS TRIS UST LUST AST	1000732997 FLD004097945
	Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CLOROX CO (Continued)

1000732997

LUST:

Facility ID:	8627500	Facility Type:	INDUSTRIAL PLANT
Telephone:	8132481161	Alias Name 1:	Not reported
Discovery Date:	12/21/89	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	029 (LOW)	Alias Name 4:	Not reported
Rank:	04832	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CLOROX CO (Continued)

1000732997

UST:

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Contact:	Not reported	Facility Phone:	8132481161
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 336050000		
Owner's Phone:	8132481161	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	SPCC plan		

AST:

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	00000
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 336050000		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00015000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	82/12
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CLOROX CO (Continued)

1000732997

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	00000
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 336050000		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	86/04
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		
Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	00000
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO		
	3601 E COLUMBUS DR		
	TAMPA, FL 336050000		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	92/09
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CLOROX CO (Continued)

1000732997

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	00000
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	5	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO 3601 E COLUMBUS DR TAMPA, FL 336050000		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	89/06
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Fiberglass, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Secondary containment, Pressurized piping, appv synthetic material		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	00000
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	6	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO 3601 E COLUMBUS DR TAMPA, FL 336050000		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00025000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	86/04
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Pressurized piping		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CLOROX CO (Continued)

1000732997

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	00000
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	7	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO 3601 E COLUMBUS DR TAMPA, FL 336050000		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00016000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	52/07
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Pressurized piping		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

Facility ID:	298627500	Facility Type:	Industrial Plan
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOEL JOINER		
Facility Phone:	8132481161	Permit Section:	00000
Date entered:	861103	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	8	District:	Southwest
Owner's Contact:	JOEL JOINER EXT 116		
Owner:	CLOROX CO 3601 E COLUMBUS DR TAMPA, FL 336050000		
Owner's Phone:	8132481161	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00016000
Tank Content:	Hazardous substance	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	52/07
Is tank regulated:	Regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Secondary containment, Pressurized piping		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

61 VAN LEEUWEN PIPE & TUBE OF THE SE INC
2721 N 36TH ST
TAMPA, FL 33605

UST
LUST

U001354634
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

LUST:

Facility ID:	8625415	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132471151	Alias Name 1:	Not reported
Discovery Date:	04/17/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	030	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

UST:

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VAN LEEUWEN PIPE & TUBE 2721 N 36TH ST TAMPA, FL 336053100		
Owner's Phone:	8132486588	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VAN LEEUWEN PIPE & TUBE 2721 N 36TH ST TAMPA, FL 336053100		
Owner's Phone:	8132486588	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

VAN LEEUWEN PIPE & TUBE OF THE SE INC (Continued)

U001354634

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VAN LEEUWEN PIPE & TUBE		
	2721 N 36TH ST		
	TAMPA, FL 336053100		
Owner's Phone:	8132486588	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625415	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VAN LEEUWEN PIPE & TUBE		
Contact:	Not reported	Facility Phone:	8132471151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CONNIE CAMPBELL		
Owner:	VAN LEEUWEN PIPE & TUBE		
	2721 N 36TH ST		
	TAMPA, FL 336053100		
Owner's Phone:	8132486588	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

62

FLORIDA PRECAST CONCRETE
2705 35TH ST
TAMPA, FL 33675

RCRIS-SQG 1000702827
FLD984209502

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FLORIDA PRECAST CONCRETE (Continued)

1000702827

RCRIS:

Owner: BILL WATTS
(813) 247-6063

Contact: BILL WATTS
(813) 247-6063

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

62	FLORIDA PRECAST CONCRETE INC 2705 N 35TH ST TAMPA, FL 33605	FINDS	1000737773 FLD984209502
----	---	-------	----------------------------

62	WEIL CHEMICAL TAMPA (CANCEL 1980) 2714 35TH STREET-PO BOX 5527 TAMPA, FL 33605	FINDS	1000932234 FL0000600858
----	--	-------	----------------------------

63	HILLSBOROUGH CNTY SCHOOL BD-INSTR SERV 707 E COLUMBUS DR TAMPA, FL 33602	UST AST	U001355693 N/A
----	--	------------	-------------------

UST:

Facility ID:	298736992	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	COUNTERMAN, TOMMY		
Contact:	Not reported	Facility Phone:	8132724710
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871223	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT J AGUIS		
Owner:	HILLSBOROUGH CNTY SCHOOL BD 901 E KENNEDY BLVD TAMPA, FL 33601		
Owner's Phone:	8139876994	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			HILLSBOROUGH CNTY SCHOOL BD-INSTR SERV (Continued)		U001355693	
			AST: Facility ID: 298736992 Is fac. regulated: Not regulated facility Operator: COUNTERMAN, TOMMY Facility Phone: 8132724710 Date entered: 871223 Tank ID: 2 Owner's Contact: ROBERT J AGUIS Owner: HILLSBOROUGH CNTY SCHOOL BD 901 E KENNEDY BLVD TAMPA, FL 33601 Owner's Phone: 8139876994 Drink. Wat. Well: Not reported Cleanup Status: Not reported Tank position: Aboveground Tank Content: Fuel oil-on site heat Disposal Method: In service Is tank regulated: Not regulated tank Last used Date: Not reported RPT Tank #: Not reported Tank Constr.: Bare/asph steel Tank Piping: Abvgrnd-no contact w/soil Petro. Monitoring: Not required Facility Type: Local, City Government Is facility open: Open Permit Section: 00000 Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Tank Cap. (Gals): 00001000 Contaminated media indicator: Not reported Install. Date: 90/XX Content Category: Pollutant Any contaminated groundwater: Not reported RPT by Tank #: Not reported			
64			DANNY'S GENERATORS 1023 E COLUMBUS DR TAMPA, FL 33605	UST LUST	U001353917 N/A	

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

DANNY'S GENERATORS (Continued)

U001353917

LUST:

Facility ID:	8508982	Facility Type:	RETAIL STATION
Telephone:	8132291059	Alias Name 1:	LATIN AMERICAN SERVICE
Discovery Date:	03/29/91	Alias Name 2:	Not reported
Tracking Number:	293316	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

ABANDONED TANK RESTORATIO

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: GENERIC GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: WASTE OIL

Est. Gallons Lost: UNKNOWN

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

DANNY'S GENERATORS (Continued)

U001353917

UST:

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	ARNIELLA, MANUEL 1918 W KENTUCKY AVE TAMPA, FL 336070000		
Owner's Phone:	8138761029	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	ARNIELLA, MANUEL 1918 W KENTUCKY AVE TAMPA, FL 336070000		
Owner's Phone:	8138761029	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000200	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	ARNIELLA, MANUEL		
	1918 W KENTUCKY AVE		
	TAMPA, FL 336070000		
Owner's Phone:	8138761029	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	ARNIELLA, MANUEL		
	1918 W KENTUCKY AVE		
	TAMPA, FL 336070000		
Owner's Phone:	8138761029	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	ARNIELLA, MANUEL		
	1918 W KENTUCKY AVE		
	TAMPA, FL 336070000		
Owner's Phone:	8138761029	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	ARNIELLA, MANUEL		
	1918 W KENTUCKY AVE		
	TAMPA, FL 336070000		
Owner's Phone:	8138761029	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	ARNIELLA, MANUEL		
	1918 W KENTUCKY AVE		
	TAMPA, FL 336070000		
Owner's Phone:	8138761029	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000200	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	ARNIELLA, MANUEL		
	1918 W KENTUCKY AVE		
	TAMPA, FL 336070000		
Owner's Phone:	8138761029	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

DANNY'S GENERATORS (Continued)

U001353917

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	ARNIELLA, MANUEL		
	1918 W KENTUCKY AVE		
	TAMPA, FL 336070000		
Owner's Phone:	8138761029	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298508982	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DANNY PEREZ		
Contact:	Not reported	Facility Phone:	8132291059
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	MANUEL ARNIELLA		
Owner:	ARNIELLA, MANUEL		
	1918 W KENTUCKY AVE		
	TAMPA, FL 336070000		
Owner's Phone:	8138761029	Tracking #:	293316
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

65

FINA-WILLIE COACHMAN
1312 E COLUMBUS DR
TAMPA, FL 33605

UST
LUST

U001354029
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FINA-WILLIE COACHMAN (Continued)

U001354029

LUST:

Facility ID:	8624765	Facility Type:	RETAIL STATION
Telephone:	8132475245	Alias Name 1:	Not reported
Discovery Date:	09/29/93	Alias Name 2:	Not reported
Tracking Number:	293771	Alias Name 3:	Not reported
Score:	012 (LOW)	Alias Name 4:	Not reported
Rank:	06172	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

PETRO. LIABILITY INS. & RESTOR.

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Ait. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA-WILLIE COACHMAN (Continued)

U001354029

UST:

Facility ID:	298624765	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COACHMAN, WILLIE		
Contact:	Not reported	Facility Phone:	8132475245
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293771
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	298624765	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COACHMAN, WILLIE		
Contact:	Not reported	Facility Phone:	8132475245
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293771
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	87/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA-WILLIE COACHMAN (Continued)

U001354029

Facility ID:	298624765	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COACHMAN, WILLIE		
Contact:	Not reported	Facility Phone:	8132475245
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293771
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624765	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COACHMAN, WILLIE		
Contact:	Not reported	Facility Phone:	8132475245
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293771
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	87/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FINA-WILLIE COACHMAN (Continued)

U001354029

Facility ID:	298624765	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COACHMAN, WILLIE		
Contact:	Not reported	Facility Phone:	8132475245
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293771
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624765	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COACHMAN, WILLIE		
Contact:	Not reported	Facility Phone:	8132475245
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293771
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	87/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			FINA-WILLIE COACHMAN (Continued)			U001354029
			Facility ID: 298624765 Is fac. regulated: Regulated facility Operator: COACHMAN, WILLIE Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860505 Tank ID: 4 Owner's Contact: JOHN P MYERS JR Owner: RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238 Owner's Phone: 8132474731 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00002000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells	Facility Type: Retail Station Is facility open: Open Facility Phone: 8132475245 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 293771 Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 77/XX Content Category: Vehicular Last used Date: 87/10 RPT by Tank #: Not reported		
66			THREE WAY CLEANERS 1420 E COLUMBUS DRIVE TAMPA, FL 33605 RCRIS: Not Reported	RCRIS-SQG FINDS	1000202041 FLD981921794	
67			SOUTHERN HYDRAULIC SERVICE 1502 E COLUMBUS DR TAMPA, FL 33605	UST LUST	U001356239 N/A	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

LUST:

Facility ID:	9100548	Facility Type:	NON-RETAIL BUSINESS
Telephone:	Not reported	Alias Name 1:	Not reported
Discovery Date:	03/22/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

UST:

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE		
	1502 E COLUMBUS DR		
	TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE		
	1502 E COLUMBUS DR		
	TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE 1502 E COLUMBUS DR TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE 1502 E COLUMBUS DR TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE 1502 E COLUMBUS DR TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE 1502 E COLUMBUS DR TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SOUTHERN HYDRAULIC SERVICE (Continued)

U001356239

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE		
	1502 E COLUMBUS DR		
	TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299100548	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN HYDRAULIC SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910226	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	MARIE LOPEZ		
Owner:	LOPEZ, MARIE		
	1502 E COLUMBUS DR		
	TAMPA, FL 336053416		
Owner's Phone:	8132482579	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

68

STANDARD CIGAR CO
2701 N 16TH ST
TAMPA, FL 33605

UST

U001356156
N/A

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			STANDARD CIGAR CO (Continued)		U001356156	
			UST:			
			Facility ID: 299046769	Facility Type: Non-retail Business		
			Is fac. regulated: Not regulated facility	Is facility open: Closed		
			Operator: STANDARD CIGAR CO			
			Contact: Not reported	Facility Phone: 8132482124		
			Permit Section: Not reported	Region: Not reported		
			Facility Code: No violation			
			Date entered: 900719	Financial responsibility: Not reported		
			Tank ID: 1	District: Southwest		
			Owner's Contact: RAY EADY			
			Owner: STANDARD CIGAR CO			
			2701 N 16TH ST			
			TAMPA, FL 336052616			
			Owner's Phone: 8132482124	Tracking #: Not reported		
			Cleanup Status: Not reported	Any contaminated soil: Not reported		
			Drink. Wat. Well: Not reported	Any contaminated surface water: Not reported		
			Tank Cap. (Gals): 00000500	Any monit. wells: Not reported		
			Tank position: Not reported	Any contam. groundwater: Not reported		
			Tank Content: Not reported	Contaminated media indicator: Not reported		
			Disposal Method: Removed	Install. Date: Not reported		
			Is tank regulated: Not regulated tank	Content Category: Pollutant		
			Facility Status: Not reported	Last used Date: 91/05		
			RPT Tank #: Not reported	RPT by Tank #: Not reported		
			Tank Constr.: Not reported			
			Tank Piping: Not reported			
			Petro. Monitoring: Not required			
69			JD GARAGE	UST	U001355065	
			2701 E COLUMBUS DR		N/A	
			TAMPA, FL 33605			

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	JD GARAGE (Continued)		U001355065
	UST: Facility ID: 298626956 Is fac. regulated: Not regulated facility Operator: JADIE SINGLETARY Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 861023 Tank ID: 1 Owner's Contact: JADIE SINGLETARY Owner: SINGLETARY, JADIE 171 LEWIS RD THONOTOSASSA, FL 335929320 Owner's Phone: 8132482592 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00001000 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132482592 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Vehicular Last used Date: 91/12 RPT by Tank #: Not reported		
70	INTERSTATE WAREHOUSES,LTD. 3701 E COLUMBUS DR TAMPA, FL 33605	UST LUST	U001354108 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

INTERSTATE WAREHOUSES,LTD. (Continued)

U001354108

LUST:

Facility ID:	8624850	Facility Type:	NON-RETAIL BUSINESS
Telephone:	0000000000	Alias Name 1:	Not reported
Discovery Date:	06/23/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	029 (LOW)	Alias Name 4:	Not reported
Rank:	04832	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

INTERSTATE WAREHOUSES,LTD. (Continued)

U001354108

UST:

Facility ID:	298624850	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	INTERSTATE WAREHOUSES,LTD.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE W. LACKEY		
Owner:	INTERSTATE WAREHOUSES LTD		
	5540 MARINER DR #201		
	TAMPA, FL 33609		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624850	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	INTERSTATE WAREHOUSES,LTD.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE W. LACKEY		
Owner:	INTERSTATE WAREHOUSES LTD		
	5540 MARINER DR #201		
	TAMPA, FL 33609		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

70

CLOROX CO
3702 E COLUMBUS DR
TAMPA, FL 33605

FINDS 1000368352
RCRIS-LQG FLD984171470

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number												
	CLOROX CO (Continued)		1000368352												
	RCRIS: Owner: DENNIS DONALSON, ENG (813) 626-3125 Contact: DENNIS DONALSON (813) 626-3125														
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D001</td><td>.00000 (T)</td><td>Notification</td><td>F001</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	Waste	Quantity	Info Source	D001	.00000 (T)	Notification	F001	.00000 (T)	Notification		
Waste	Quantity	Info Source	Waste	Quantity	Info Source										
D001	.00000 (T)	Notification	F001	.00000 (T)	Notification										
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported														
71	KINGS FOOD MART 509 W COLUMBUS DR TAMPA, FL 33602	UST LUST	U001354744 N/A												

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KINGS FOOD MART (Continued)

U001354744

LUST:

Facility ID:	8625531	Facility Type:	RETAIL STATION
Telephone:	8132298599	Alias Name 1:	PEOPLES MARKET
Discovery Date:	03/28/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	OPERATING AFTER 3/90
Incident Ineligible Description:	OPERATING AFTER

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KINGS FOOD MART (Continued)

U001354744

UST:

Facility ID:	298625531	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RIBHI HAMID		
Contact:	Not reported	Facility Phone:	8132298599
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	HILMY JABER		
Owner:	JABER, HILMY		
	5919 W LINEBAUGH AVE		
	TAMPA, FL 336240000		
Owner's Phone:	8139615489	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	73/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	5
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625531	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RIBHI HAMID		
Contact:	Not reported	Facility Phone:	8132298599
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	HILMY JABER		
Owner:	JABER, HILMY		
	5919 W LINEBAUGH AVE		
	TAMPA, FL 336240000		
Owner's Phone:	8139615489	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	73/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	6
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

KINGS FOOD MART (Continued)

U001354744

Facility ID:	298625531	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RIBHI HAMID		
Contact:	Not reported	Facility Phone:	8132298599
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	HILMY JABER		
Owner:	JABER, HILMY		
	5919 W LINEBAUGH AVE		
	TAMPA, FL 336240000		
Owner's Phone:	8139615489	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	73/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625531	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RIBHI HAMID		
Contact:	Not reported	Facility Phone:	8132298599
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	HILMY JABER		
Owner:	JABER, HILMY		
	5919 W LINEBAUGH AVE		
	TAMPA, FL 336240000		
Owner's Phone:	8139615489	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	73/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

KINGS FOOD MART (Continued)

U001354744

Facility ID:	298625531	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RIBHI HAMID		
Contact:	Not reported	Facility Phone:	8132298599
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	HILMY JABER		
Owner:	JABER, HILMY		
	5919 W LINEBAUGH AVE		
	TAMPA, FL 336240000		
Owner's Phone:	8139615489	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	91/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	DW tank space, Piping/flow restrictor, DW piping space		

Facility ID:	298625531	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	RIBHI HAMID		
Contact:	Not reported	Facility Phone:	8132298599
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	None
Tank ID:	6	District:	Southwest
Owner's Contact:	HILMY JABER		
Owner:	JABER, HILMY		
	5919 W LINEBAUGH AVE		
	TAMPA, FL 336240000		
Owner's Phone:	8139615489	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	91/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	2	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	DW tank space, Piping/flow restrictor, DW piping space		

72

OWINGS PROPERTY
201 W COLUMBUS DR
TAMPA, FL 33602

UST
LUST

U001823392
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

OWINGS PROPERTY (Continued)

U001823392

UST:

Facility ID:	299400401	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PHIL OWINGS		
Contact:	Not reported	Facility Phone:	8132231229
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940331	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PHIL OWINGS		
Owner:	OWINGS, PHIL		
	201 W COLUMBUS DR		
	TAMPA, FL 336020000		
Owner's Phone:	8132231229	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299400401	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PHIL OWINGS		
Contact:	Not reported	Facility Phone:	8132231229
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940331	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	PHIL OWINGS		
Owner:	OWINGS, PHIL		
	201 W COLUMBUS DR		
	TAMPA, FL 336020000		
Owner's Phone:	8132231229	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

OWINGS PROPERTY (Continued)

U001823392

Facility ID:	299400401	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PHIL OWINGS		
Contact:	Not reported	Facility Phone:	8132231229
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940331	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	PHIL OWINGS		
Owner:	OWINGS, PHIL 201 W COLUMBUS DR TAMPA, FL 336020000		
Owner's Phone:	8132231229	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		
Facility ID:	299400401	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PHIL OWINGS		
Contact:	Not reported	Facility Phone:	8132231229
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940331	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	PHIL OWINGS		
Owner:	OWINGS, PHIL 201 W COLUMBUS DR TAMPA, FL 336020000		
Owner's Phone:	8132231229	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			OWINGS PROPERTY (Continued)		U001823392	
			Facility ID: 299400401 Is fac. regulated: Not regulated facility Operator: PHIL OWINGS Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 940331 Tank ID: 5 Owner's Contact: PHIL OWINGS Owner: OWINGS, PHIL 201 W COLUMBUS DR TAMPA, FL 336020000 Owner's Phone: 8132231229 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000550 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Retail Station Is facility open: Closed Facility Phone: 8132231229 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Pollutant Last used Date: 93/08 RPT by Tank #: Not reported		
73			C MART #644 2600 N TAMPA ST TAMPA, FL 33602	UST LUST	U001355247 N/A	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

C MART #644 (Continued)

U001355247

LUST:

Facility ID:	8627683	Facility Type:	RETAIL STATION
Telephone:	8136843844	Alias Name 1:	Not reported
Discovery Date:	10/01/87	Alias Name 2:	Not reported
Tracking Number:	292114	Alias Name 3:	Not reported
Score:	012 (LOW)	Alias Name 4:	Not reported
Rank:	06172	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Y	Alt. Process Date:	Not reported
Soil Treatment:	Y	Alternative Status:	Not reported
Other Treatment:	2ND IRA/12-93. 1 DOD		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

C MART #644 (Continued)

U001355247

UST:

Facility ID:	298627683	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	292114
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627683	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	292114
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

C MART #644 (Continued)

U001355247

Facility ID:	298627683	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCURLOCK, RICK		
Contact:	Not reported	Facility Phone:	8136843844
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC		
	9 GREENWAY PLAZA #1994		
	HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	292114
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

73

GAS KWICK #13
2601 N TAMPA ST
TAMPA, FL 33602

UST

U001354021
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GAS KWICK #13 (Continued)

U001354021

UST:

Facility ID:	298624757	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GAS KWICK, INC.		
Contact:	Not reported	Facility Phone:	8132214312
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624757	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GAS KWICK, INC.		
Contact:	Not reported	Facility Phone:	8132214312
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GAS KWICK #13 (Continued)

U001354021

Facility ID:	298624757	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GAS KWICK, INC.		
Contact:	Not reported	Facility Phone:	8132214312
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624757	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GAS KWICK, INC.		
Contact:	Not reported	Facility Phone:	8132214312
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

74

EMMA BODY PAINT SHOP
209 E COLUMBUS ST
TAMPA, FL 33602

RCRIS-SQG 1000141754
FINDS FLD163275001

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	EMMA BODY PAINT SHOP (Continued)		1000141754
	RCRIS:		
	Owner: PEDRO AMADOR, OWNER (813) 228-7916		
	Contact: PEDRO AMADOR (813) 228-7916		
	Waste	Quantity	Info Source
	D000	.00000 (T)	Notification
	F003	.00000 (T)	Notification
	Waste	Quantity	Info Source
	D001	.00000 (T)	Notification
	F005	.00000 (T)	Notification
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported		
75	GONZALEZ PLUMBING CO.,INC./HENRY 2119 W COLUMBUS DR TAMPA, FL 33607	UST LUST	U001355101 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GONZALEZ PLUMBING CO.,INC./HENRY (Continued)

U001355101

LUST:

Facility ID:	8627050	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132511980	Alias Name 1:	Not reported
Discovery Date:	08/10/88	Alias Name 2:	Not reported
Tracking Number:	293663	Alias Name 3:	Not reported
Score:	045	Alias Name 4:	Not reported
Rank:	02225	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: LEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

STATE

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

APPROVED

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GONZALEZ PLUMBING CO.,INC./HENRY (Continued)

U001355101

UST:

Facility ID:	298627050	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GONZALEZ PLUMBING CO.,INC./HENRY		
Contact:	Not reported	Facility Phone:	8132511980
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HENRY GONZALEZ, JR.		
Owner:	HENRY GONZOLEZ PLUMBING CO INC		
	2119 W COLUMBUS DR		
	TAMPA, FL 336071639		
Owner's Phone:	8132511980	Tracking #:	293663
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627050	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GONZALEZ PLUMBING CO.,INC./HENRY		
Contact:	Not reported	Facility Phone:	8132511980
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	HENRY GONZALEZ, JR.		
Owner:	HENRY GONZOLEZ PLUMBING CO INC		
	2119 W COLUMBUS DR		
	TAMPA, FL 336071639		
Owner's Phone:	8132511980	Tracking #:	293663
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GONZALEZ PLUMBING CO.,INC./HENRY (Continued)

U001355101

Facility ID:	298627050	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GONZALEZ PLUMBING CO.,INC./HENRY		
Contact:	Not reported	Facility Phone:	8132511980
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	HENRY GONZALEZ, JR.		
Owner:	HENRY GONZOLEZ PLUMBING CO INC		
	2119 W COLUMBUS DR		
	TAMPA, FL 336071639		
Owner's Phone:	8132511980	Tracking #:	293663
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

76

GOLDSTAR FOODS
2317 N NEBRASKA AVE
TAMPA, FL 33605

UST

U001356047
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GOLDSTAR FOODS (Continued)

U001356047

UST:

Facility ID:	298944840	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SHAM RAMCHARAN		
Contact:	Not reported	Facility Phone:	8132235724
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890920	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	SHAM RAMCHARAN		
Owner:	MANGROO, HANSRAJ 2317 N NEBRASKA AVE TAMPA, FL 336050000		
Owner's Phone:	8132235724	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298944840	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SHAM RAMCHARAN		
Contact:	Not reported	Facility Phone:	8132235724
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890920	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	SHAM RAMCHARAN		
Owner:	MANGROO, HANSRAJ 2317 N NEBRASKA AVE TAMPA, FL 336050000		
Owner's Phone:	8132235724	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GOLDSTAR FOODS (Continued)

U001356047

Facility ID:	298944840	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SHAM RAMCHARAN		
Contact:	Not reported	Facility Phone:	8132235724
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890920	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	SHAM RAMCHARAN		
Owner:	MANGROO, HANSRAJ 2317 N NEBRASKA AVE TAMPA, FL 336050000		
Owner's Phone:	8132235724	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	84/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298944840	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SHAM RAMCHARAN		
Contact:	Not reported	Facility Phone:	8132235724
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890920	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	SHAM RAMCHARAN		
Owner:	MANGROO, HANSRAJ 2317 N NEBRASKA AVE TAMPA, FL 336050000		
Owner's Phone:	8132235724	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

76

GENES SERVICE
2318 N NEBRASKA AVE
TAMPA, FL 33602

UST

U001354940
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GENES SERVICE (Continued)

U001354940

UST:

Facility ID:	298625737	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DE LA PARTE EUGENE		
Contact:	Not reported	Facility Phone:	8132287172
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	EUGENE DE LA PARTE		
Owner:	DE LA PARTE, EUGENE 2318 N NEBRASKA AVE TAMPA, FL 336021724		
Owner's Phone:	8132287172	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625737	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DE LA PARTE EUGENE		
Contact:	Not reported	Facility Phone:	8132287172
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	EUGENE DE LA PARTE		
Owner:	DE LA PARTE, EUGENE 2318 N NEBRASKA AVE TAMPA, FL 336021724		
Owner's Phone:	8132287172	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GENES SERVICE (Continued)

U001354940

Facility ID:	298625737	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DE LA PARTE EUGENE		
Contact:	Not reported	Facility Phone:	8132287172
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	EUGENE DE LA PARTE		
Owner:	DE LA PARTE, EUGENE		
	2318 N NEBRASKA AVE		
	TAMPA, FL 336021724		
Owner's Phone:	8132287172	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001036	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

77

TAMPA,CITY-FIRE DEPT SUPPLY DIVISION
2611 N 12TH ST
TAMPA, FL 33605

UST

U001355930
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-FIRE DEPT SUPPLY DIVISION (Continued)

U001355930

UST:

Facility ID:	298842520	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881229	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

78

C MART #643
2309 N NEBRASKA AVE
TAMPA, FL 33602

UST

U001353894
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

C MART #643 (Continued)

U001353894

UST:

Facility ID:	298508941	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	7138771400
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC		
	9 GREENWAY PLAZA #1994		
	HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298508941	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	7138771400
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC		
	9 GREENWAY PLAZA #1994		
	HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

C MART #643 (Continued)

U001353894

Facility ID:	298508941	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	7138771400
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC		
	9 GREENWAY PLAZA #1994		
	HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	69/12
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	298508941	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	COASTAL MART INC		
Contact:	Not reported	Facility Phone:	7138771400
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN LEFRAVICH		
Owner:	COASTAL MART INC		
	9 GREENWAY PLAZA #1994		
	HOUSTON, TX 770468510		
Owner's Phone:	7138773939	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			C MART #643 (Continued)		U001353894	
			Facility ID: 298508941 Is fac. regulated: Not regulated facility Operator: COASTAL MART INC Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: Not reported Tank ID: 5 Owner's Contact: JOHN LEFRAVICH Owner: COASTAL MART INC 9 GREENWAY PLAZA #1994 HOUSTON, TX 770468510 Owner's Phone: 7138773939 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00010000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells	Facility Type: Retail Station Is facility open: Closed Facility Phone: 7138771400 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Hazardous/other Last used Date: 90/12 RPT by Tank #: Not reported		
79			KASH N KARRY FOOD STORE 2301 N FLORIDA AVE TAMPA, FL 33602	UST	U001356130	N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KASH N KARRY FOOD STORE (Continued)

U001356130

UST:

Facility ID:	299046103	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N KARRY FOOD STORES INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARK STEWART		
Owner:	KASH N KARRY FOOD STORES INC		
	6422 HARNEY RD		
	TAMPA, FL 336800000		
Owner's Phone:	8136210297	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299046103	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N KARRY FOOD STORES INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MARK STEWART		
Owner:	KASH N KARRY FOOD STORES INC		
	6422 HARNEY RD		
	TAMPA, FL 336800000		
Owner's Phone:	8136210297	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KASH N KARRY FOOD STORE (Continued)

U001356130

Facility ID:	299046103	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N KARRY FOOD STORES INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MARK STEWART		
Owner:	KASH N KARRY FOOD STORES INC		
	6422 HARNEY RD		
	TAMPA, FL 336800000		
Owner's Phone:	8136210297	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

80

ELK RIVER CORP
2531 22ND ST CAUSEWAY S
TAMPA, FL 33675

RCRIS-SQG 1000701449
FLD984182733

RCRIS:

Owner: CURT LESSL, V PRES
(813) 248-3256

Contact: CURT LESSL
(813) 248-3256

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D018	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

81

MCEWEN LUMBER CO.
2620 N 36TH ST
TAMPA, FL 33605

UST
LUST U001355095
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

MCEWEN LUMBER CO. (Continued)

U001355095

UST:

Facility ID:	298627033	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MCEWEN LUMBER CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIMI IPPOLITO		
Owner:	MCEWEN LUMBER CO #2		
	2620 N 36TH ST		
	TAMPA, FL 336053114		
Owner's Phone:	8132484111	Tracking #:	292224
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627033	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MCEWEN LUMBER CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861027	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JIMI IPPOLITO		
Owner:	MCEWEN LUMBER CO #2		
	2620 N 36TH ST		
	TAMPA, FL 336053114		
Owner's Phone:	8132484111	Tracking #:	292224
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

82

RAY WILLIAMS FUNERAL HOME
2820 N ROME AVE
TAMPA, FL 33607

UST
LUST

U001053829
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RAY WILLIAMS FUNERAL HOME (Continued)

U001053829

LUST:

Facility ID:	9063824	Facility Type:	NON-RETAIL BUSINESS
Telephone:	Not reported	Alias Name 1:	Not reported
Discovery Date:	05/10/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	021 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Flag:	Not reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	RAY WILLIAMS FUNERAL HOME (Continued)		U001053829
	UST: Facility ID: 299063824 Facility Type: Non-retail Business Is fac. regulated: Not regulated facility Is facility open: Closed Operator: RAY WILLIAMS FUNERAL HOME Contact: Not reported Facility Phone: Not reported Permit Section: Not reported Region: Not reported Facility Code: No violation Date entered: 901114 Financial responsibility: Not reported Tank ID: 1 District: Southwest Owner's Contact: ROBERT DORZBACK Owner: COURTAULDS COATINGS INC 400 S 13TH ST LOUISVILLE, KY 402031714 Owner's Phone: 5025889356 Tracking #: Not reported Cleanup Status: Completed Any contaminated soil: No Drink. Wat. Well: 0000 Any contaminated surface water: Not reported Tank Cap. (Gals): 00001000 Any monit. wells: Not reported Tank position: Not reported Any contam. groundwater: Not reported Tank Content: Not reported Contaminated media indicator: Yes Disposal Method: Removed Install. Date: Not reported Is tank regulated: Not regulated tank Content Category: Vehicular Facility Status: Not reported Last used Date: 90/04 RPT Tank #: Not reported RPT by Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported		
83	BP-YBOR 2040 E 14TH AVE TAMPA, FL 33605	UST LUST	U001355280 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BP-YBOR (Continued)

U001355280

LUST:

Facility ID:	8627858	Facility Type:	RETAIL STATION
Telephone:	8136814279	Alias Name 1:	BP-ROYAL
Discovery Date:	11/30/88	Alias Name 2:	ROYAL STATION
Tracking Number:	294951	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-YBOR (Continued)

U001355280

UST:

Facility ID:	298627858	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO		
	PO BOX 1110		
	BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294951
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

Facility ID:	298627858	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO		
	PO BOX 1110		
	BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294951
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-YBOR (Continued)

U001355280

Facility ID:	298627858	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO		
	PO BOX 1110		
	BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294951
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

Facility ID:	298627858	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HARDEE, BILL		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO		
	PO BOX 1110		
	BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294951
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

84

NCJ INVESTMENT CO
2101 E 13TH AVE
TAMPA, FL 33605

UST
LUST

U001354017
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NCJ INVESTMENT CO (Continued)

U001354017

LUST:

Facility ID:	8624753	Facility Type:	RETAIL STATION
Telephone:	0000000000	Alias Name 1:	Not reported
Discovery Date:	09/14/88	Alias Name 2:	Not reported
Tracking Number:	293907	Alias Name 3:	Not reported
Score:	035	Alias Name 4:	Not reported
Rank:	03369	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NCJ INVESTMENT CO (Continued)

U001354017

UST:

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NCJ INVESTMENT CO (Continued)

U001354017

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

NCJ INVESTMENT CO (Continued)

U001354017

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624753	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NCJ INVESTMENT CO		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MEYERS JR		
Owner:	N C J INVESTMENT CO		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293907
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

85

AMOCO-ALAN DALE MARTS INC
2207 E 13TH AVE
TAMPA, FL 33605

UST
LUST

U001354282
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO-ALAN DALE MARTS INC (Continued)

U001354282

LUST:

Facility ID:	8625038	Facility Type:	RETAIL STATION
Telephone:	8132485975	Alias Name 1:	SHELL-ALAN DALE
Discovery Date:	06/06/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	041	Alias Name 4:	Not reported
Rank:	02376	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type: *	QUARTERLY
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

AMOCO-ALAN DALE MARTS INC (Continued)

U001354282

UST:

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00009403	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	4
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00009403	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	5
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

AMOCO-ALAN DALE MARTS INC (Continued)

U001354282

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00009403	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	6
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO-ALAN DALE MARTS INC (Continued)

U001354282

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	2	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625038	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ALAN DALE MARTS INC		
Contact:	Not reported	Facility Phone:	8132485975
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	3	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

86

MARTINEZ SITE
1907 ST JOHN ST
TAMPA, FL 33601

RCRIS: Not Reported

FINDS 1000412547
RCRIS-LQG FLD982138901

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
87	OLD 97 COMPANY 2306 35TH ST TAMPA, FL 33605 Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production	FINDS	1000496908 FLD004091427
87	RED! STRIP OF CENTRAL FLORIDA 2402 N 35TH ST TAMPA, FL 33605 RCRIS: Not Reported	RCRIS-SQG FINDS	1000245031 FLD021115837
88	LYDON TIRES 2109 FLORIDA AVE TAMPA, FL 33602 RCRIS: Not Reported	RCRIS-SQG FINDS	1000337947 FLD981858376
89	U-HAUL OF CENTRAL TAMPA 2309 N 18TH ST TAMPA, FL 33605 UST: Facility ID: 298625612 Facility Type: Non-retail Business Is fac. regulated: Not regulated facility Is facility open: Closed Operator: U-HAUL Contact: Not reported Facility Phone: 8132475936 Permit Section: Not reported Region: Not reported Facility Code: No violation Date entered: 860522 Financial responsibility: State PRGM (Self/Other) Tank ID: 1 District: Southwest Owner's Contact: CHARLES E. KITCHIN, JR Owner: U HAUL CO OF WEST COAST FL 2311 N 18TH ST TAMPA, FL 336053847 Owner's Phone: 8132476101 Tracking #: Not reported Cleanup Status: Not reported Any contaminated soil: Not reported Drink. Wat. Well: Not reported Any contaminated surface water: Not reported Tank Cap. (Gals): 00004000 Any monit. wells: Not reported Tank position: Not reported Any contam. groundwater: Not reported Tank Content: Not reported Contaminated media indicator: Not reported Disposal Method: Removed Install. Date: 77/01 Is tank regulated: Not regulated tank Content Category: Vehicular Facility Status: Not reported Last used Date: 94/02 RPT Tank #: Not reported RPT by Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells	UST	U001354819 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

U-HAUL OF CENTRAL TAMPA (Continued)

U001354819

Facility ID:	298625612	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	U-HAUL		
Contact:	Not reported	Facility Phone:	8132475936
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	CHARLES E. KITCHIN, JR		
Owner:	U HAUL CO OF WEST COAST FL 2311 N 18TH ST TAMPA, FL 336053847		
Owner's Phone:	8132476101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	78/11
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	94/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625612	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	U-HAUL		
Contact:	Not reported	Facility Phone:	8132475936
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	CHARLES E. KITCHIN, JR		
Owner:	U HAUL CO OF WEST COAST FL 2311 N 18TH ST TAMPA, FL 336053847		
Owner's Phone:	8132476101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000700	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	94/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

90

WEYERHAEUSER CO.
2307 N 36TH ST
TAMPA, FL 33605

UST
LUST

U001354504
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WEYERHAEUSER CO. (Continued)

U001354504

LUST:

Facility ID:	8625274	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132476671	Alias Name 1:	Not reported
Discovery Date:	01/10/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	009 (LOW)	Alias Name 4:	Not reported
Rank:	08576	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: DIESEL

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

PETRO. LIABILITY INS. & RESTOR.

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WEYERHAEUSER CO. (Continued)

U001354504

UST:

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO		
	PO BOX 16909		
	TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	79/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO		
	PO BOX 16909		
	TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

WEYERHAEUSER CO. (Continued)

U001354504

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO PO BOX 16909 TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO PO BOX 16909 TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

WEYERHAEUSER CO. (Continued)

U001354504

Facility ID:	298625274	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WEYERHAEUSER CO.		
Contact:	Not reported	Facility Phone:	8132476671
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	CECIL HAMAKER		
Owner:	WEYERHAEUSER CO		
	PO BOX 16909		
	TAMPA, FL 336876909		
Owner's Phone:	8136213011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

91 TAMPA,CITY-DPW FLEET MAINT.-DIV. #3
2609 N ROME AVE
TAMPA, FL 33607

UST

U001354875
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT.-DIV. #3 (Continued)

U001354875

UST:

Facility ID:	298625669	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238765
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

Facility ID:	298625669	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238765
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT.-DIV. #3 (Continued)

U001354875

Facility ID:	298625669	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238765
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

Facility ID:	298625669	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238765
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	79/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

92

KAMALA AUTO TRADE
2211 N 38TH ST
TAMPA, FL 33603

RCRIS-SQG 1000821508
FINDS FLD984244780

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KAMALA AUTO TRADE (Continued)

1000821508

Owner: MIKE JERRORICH
(813) 247-5811

Contact:MIKE JERRORICH
(813) 247-5811

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D007	.00000 (T)	Notification	D008	.00000 (T)	Notification
D018	.00000 (T)	Notification	D021	.00000 (T)	Notification
D027	.00000 (T)	Notification	D039	.00000 (T)	Notification
D040	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

TAMPA,CITY-FIRE STATION #4
2100 E 11TH AVE
TAMPA, FL 33605

UST
LUST

U001355927
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-FIRE STATION #4 (Continued)

U001355927

LUST:

Facility ID:	8842517	Facility Type:	LOCAL, CITY GOVERNMENT
Telephone:	8132255729	Alias Name 1:	Not reported
Discovery Date:	03/20/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-FIRE STATION #4 (Continued)

U001355927

UST:

Facility ID:	298842517	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881229	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298842517	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881229	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

94

OUR LADY OF PERPETUAL HELP CHURCH
1711 E 11TH AVE
TAMPA, FL 33605

UST

U001355335
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

OUR LADY OF PERPETUAL HELP CHURCH (Continued)

U001355335

UST:

Facility ID:	298628192	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	OUR LADY OF PERPETUAL HELP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861110	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	FRANCES M. RHODES		
Owner:	OUR LADY OF PERPETUAL HELP		
	1711 E 11TH AVE		
	TAMPA, FL 336053803		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	84/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

95

TAMPA INDEPENDENT DAIRY
3725 E 10TH AVE
TAMPA, FL 33605

UST
LUST

U001354964
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA INDEPENDENT DAIRY (Continued)

U001354964

LUST:

Facility ID:	8625761	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132231999	Alias Name 1:	Not reported
Discovery Date:	03/03/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	VEHIC DIESEL	Est. Gallons Lost:	00000075
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA INDEPENDENT DAIRY (Continued)

U001354964

UST:

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	5R1
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	5R1	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	5	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA INDEPENDENT DAIRY (Continued)

U001354964

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625761	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA INDEPENDENT DAIRY FARMERS		
Contact:	Not reported	Facility Phone:	8132231999
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	DEAN DOREMUS		
Owner:	TAMPA INDEPENDENT DAIRY FARMERS PO BOX 75306 TAMPA, FL 336750306		
Owner's Phone:	8132231999	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

96

TAMPA ELECTRO PLATING INC
3005 E 10TH AVE
TAMPA, FL 33605

RCRIS-SQG 1000344862
FINDS FLD982117871

RCRIS: Not Reported

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
97			TARGET AUTO & TRUCK SERVICE 2104 34TH ST N TAMPA, FL 33605	RCRIS-SQG FINDS	1000821269	FLD984241885
RCRIS:						
Owner: JOHN CORRICA (813) 248-5145						
Contact:JOHN CORRICA (813) 248-5145						
Waste	Quantity	Info Source	Waste	Quantity	Info Source	
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification	
D007	.00000 (T)	Notification	D008	.00000 (T)	Notification	
D021	.00000 (T)	Notification	D027	.00000 (T)	Notification	
D039	.00000 (T)	Notification	D040	.00000 (T)	Notification	
(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported						
98			TAMPA,CITY-FORMER FIRE STATION #5 1910 N FLORIDA AVE TAMPA, FL 33602	UST	U001355981	N/A
UST:						
Facility ID:		298943538	Facility Type:		Local, City Government	
Is fac. regulated:		Not regulated facility	Is facility open:		Closed	
Operator:		TAMPA,CITY-REAL ESTATE DIVISION				
Contact:		Not reported	Facility Phone:		8132238624	
Permit Section:		Not reported	Region:		Not reported	
Facility Code:		No violation				
Date entered:		890314	Financial responsibility:		Not reported	
Tank ID:		1	District:		Southwest	
Owner's Contact:		MIKE MCCOY				
Owner:		TAMPA,CITY-REAL ESTATE DIVISION 201 E KENNEDY BLVD,STE 415 TAMPA, FL 336025823				
Owner's Phone:		8132238624	Tracking #:		Not reported	
Cleanup Status:		Not reported	Any contaminated soil:		Not reported	
Drink. Wat. Well:		Not reported	Any contaminated surface water:		Not reported	
Tank Cap. (Gals):		00000300	Any monit. wells:		Not reported	
Tank position:		Not reported	Any contam. groundwater:		Not reported	
Tank Content:		Not reported	Contaminated media indicator:		Not reported	
Disposal Method:		In service	Install. Date:		Not reported	
Is tank regulated:		Not regulated tank	Content Category:		Hazardous/other	
Facility Status:		Not reported	Last used Date:		Not reported	
RPT Tank #:		Not reported	RPT by Tank #:		Not reported	
Tank Constr.:		Not reported				
Tank Piping:		Not reported				
Petro. Monitoring:		Unknown/not reported				
99			GIGLIO PROPERTY 2007 NEBRASKA AVE TAMPA, FL	UST LUST	U001378050	N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GIGLIO PROPERTY (Continued)

U001378050

LUST:

Facility ID:	9102252	Facility Type:	RETAIL STATION
Telephone:	Not reported	Alias Name 1:	Not reported
Discovery Date:	03/21/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NO C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GIGLIO PROPERTY (Continued)

U001378050

UST:

Facility ID:	299102252	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GIGLIO, NAOMI		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910606	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DARRYL MINARDI		
Owner:	GIGLIO, NAOMI		
	502 N OREGON AVE ATTN D MINARDI		
	TAMPA, FL 336060000		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299102252	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GIGLIO, NAOMI		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910606	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DARRYL MINARDI		
Owner:	GIGLIO, NAOMI		
	502 N OREGON AVE ATTN D MINARDI		
	TAMPA, FL 336060000		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GIGLIO PROPERTY (Continued)

U001378050

Facility ID:	299102252	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GIGLIO, NAOMI		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910606	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DARRYL MINARDI		
Owner:	GIGLIO, NAOMI 502 N OREGON AVE ATTN D MINARDI TAMPA, FL 336060000		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299102252	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GIGLIO, NAOMI		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910606	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DARRYL MINARDI		
Owner:	GIGLIO, NAOMI 502 N OREGON AVE ATTN D MINARDI TAMPA, FL 336060000		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000125	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GIGLIO PROPERTY (Continued)

U001378050

Facility ID:	299102252	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GIGLIO, NAOMI		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910606	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	DARRYL MINARDI		
Owner:	GIGLIO, NAOMI 502 N OREGON AVE ATTN D MINARDI TAMPA, FL 336060000		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000125	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		
Facility ID:	299102252	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GIGLIO, NAOMI		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910606	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	DARRYL MINARDI		
Owner:	GIGLIO, NAOMI 502 N OREGON AVE ATTN D MINARDI TAMPA, FL 336060000		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000125	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GIGLIO PROPERTY (Continued)

U001378050

Facility ID:	299102252	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GIGLIO, NAOMI		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910606	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	DARRYL MINARDI		
Owner:	GIGLIO, NAOMI		
	502 N OREGON AVE ATTN D MINARDI		
	TAMPA, FL 336060000		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000125	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299102252	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GIGLIO, NAOMI		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910606	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	DARRYL MINARDI		
Owner:	GIGLIO, NAOMI		
	502 N OREGON AVE ATTN D MINARDI		
	TAMPA, FL 336060000		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000125	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GIGLIO PROPERTY (Continued)

U001378050

Facility ID:	299102252	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GIGLIO, NAOMI		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910606	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	DARRYL MINARDI		
Owner:	GIGLIO, NAOMI		
	502 N OREGON AVE ATTN D MINARDI		
	TAMPA, FL 336060000		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000125	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

100

HILLSBOROUGH COUNTY TRAFFIC
8420 INDUSTRIAL BLVD
TAMPA, FL 33619

RCRIS-SQG
FINDS

1000292184
FLD982170136

RCRIS:

Owner: ROBERT LINDBERG,MGR
(813) 621-2437

Contact:ROBERT LINDBERG,MGR
(813) 621-2437

Waste	Quantity	Info Source
-------	----------	-------------

F005	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

101

HERO PLUMBING CO.
122 W PALM AVE
TAMPA, FL 33602

UST

U001355522
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HERO PLUMBING CO. (Continued)

U001355522

UST:

Facility ID:	298734731	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	HERO PLUMBING SUPPLY		
Contact:	Not reported	Facility Phone:	8138765522
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870813	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES HERO		
Owner:	HERO, CHARLES		
	122 W PALM AVE		
	TAMPA, FL 336022120		
Owner's Phone:	3360265522	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

102

MASSEY METALS CO
2009 N 22ND ST
TAMPA, FL 33605

UST

U001354553
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

MASSEY METALS CO (Continued)

U001354553

UST:

Facility ID:	298625331	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MASSEY METALS CO		
Contact:	Not reported	Facility Phone:	8132482117
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM MASSEY		
Owner:	MASSEY METALS CO		
	PO BOX 75560		
	TAMPA, FL 336750560		
Owner's Phone:	8132482117	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001600	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

103

J MATASSINI & SONS FISH CO INC
2008 GARCIA AVE
TAMPA, FL 33601

UST

U001823414
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

J MATASSINI & SONS FISH CO INC (Continued)

U001823414

UST:

Facility ID:	299400581	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MR MATASSINI		
Contact:	Not reported	Facility Phone:	8132290829
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940407	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

104

DRIVELINE BY ACB INC
2211 NORTH HOWARD AVE
TAMPA, FL 33607

RCRIS-SQG
FINDS

1000429994
FLD984167056

RCRIS:

Owner: FRANK SUCHON, OWNER
(813) 254-4133

Contact:FRANK SUCHON
(813) 254-4133

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

105

TAMPA,CITY-MARTIN L KING REC DEPT
2300 N OREGON AVE
TAMPA, FL 33607

UST

U001356054
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-MARTIN L KING REC DEPT (Continued)

U001356054

UST:

Facility ID:	298944955	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAPY, WAYNE		
Contact:	Not reported	Facility Phone:	8132238018
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890929	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

106

GTE OF FL YBOR EAX
1702 E 8TH AVE
TAMPA, FL 33605

UST

U001355274
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GTE OF FL YBOR EAX (Continued)

U001355274

UST:

Facility ID:	298627832	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	VANN, KAREN		
Contact:	Not reported	Facility Phone:	8132244721
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL PO BOX 110 MC 711 TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298627832	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	VANN, KAREN		
Contact:	Not reported	Facility Phone:	8132244721
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL PO BOX 110 MC 711 TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	70/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	87/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

107

HILLSBOROUGH CNTY-SHERIFFS OFFICE
2008 E 8TH AVE
TAMPA, FL 33605

UST
LUST
AST

U001356050
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-SHERIFFS OFFICE (Continued)

U001356050

LUST:

Facility ID:	8944870	Facility Type:	LOCAL, CITY GOVERNMENT
Telephone:	8132482827	Alias Name 1:	Not reported
Discovery Date:	07/24/89	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	034	Alias Name 4:	Not reported
Rank:	03682	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: FUEL OIL-ON SITE

Pollutant 2: Not reported

Pollutant 3: Not reported

Est. Gallons Lost: 00001700

Est. Gallons Lost: 00000000

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

PETRO. LIABILITY INS. & RESTOR.

REIMBURSEMENT CLEANUP

INELIGIBLE

NONCOMP 17-61, -761, -762 RULES

NONCOMP 17-61,

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product: Y

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: RESPONSIBLE PARTY

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

INCOMPLETE

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Flag:

Not reported

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-SHERIFFS OFFICE (Continued)

U001356050

UST:

Facility ID:	298944870	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DALE TUTTLE		
Contact:	Not reported	Facility Phone:	8132482827
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890922	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/10
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Auto tank gauging, Man tank gauging		

AST:

Facility ID:	298944870	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DALE TUTTLE		
Facility Phone:	8132482827	Permit Section:	00000
Date entered:	890922	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	93/09
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Dbl walled=primary matl, Spill cnmt, Op-tight fill, Level gauges/hi level alarms		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Suction piping		
Petro. Monitoring:	DW tank space		

108

HILLSBOROUGH CNTY SHERIFFS OFFICE
2102 E 8TH AVE
TAMPA, FL 33605

UST
LUST

U001355273
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY SHERIFFS OFFICE (Continued)

U001355273

LUST:

Facility ID:	8627827	Facility Type:	COUNTY GOVERNMENT
Telephone:	8132478094	Alias Name 1:	Not reported
Discovery Date:	09/08/88	Alias Name 2:	Not reported
Tracking Number:	299000	Alias Name 3:	Not reported
Score:	034	Alias Name 4:	Not reported
Rank:	03682	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	00000100
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Y	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HILLSBOROUGH CNTY SHERIFFS OFFICE (Continued)

U001355273

UST:

Facility ID:	298627827	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HILLSBOROUGH CNTY SHERIFFS OFC		
Contact:	Not reported	Facility Phone:	8132478094
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	299000
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627827	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HILLSBOROUGH CNTY SHERIFFS OFC		
Contact:	Not reported	Facility Phone:	8132478094
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	299000
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY SHERIFFS OFFICE (Continued)

U001355273

Facility ID:	298627827	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HILLSBOROUGH CNTY SHERIFFS OFC		
Contact:	Not reported	Facility Phone:	8132478094
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	299000
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/01
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627827	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HILLSBOROUGH CNTY SHERIFFS OFC		
Contact:	Not reported	Facility Phone:	8132478094
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	299000
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/01
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number												
HILLSBOROUGH CNTY SHERIFFS OFFICE (Continued)			U001355273												
	Facility ID: 298627827 Is fac. regulated: Regulated facility Operator: HILLSBOROUGH CNTY SHERIFFS OFC Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 861106 Tank ID: 5 Owner's Contact: E A PULIDO Owner: HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371 Owner's Phone: 8132478880 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000500 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not required	Facility Type: County Government Is facility open: Open Facility Phone: 8132478094 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 299000 Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 77/XX Content Category: Pollutant Last used Date: 88/11 RPT by Tank #: Not reported													
109	TAMPA ARMATURE WORKS INC 1910 OLA AVENUE TAMPA, FL 33602	FINDS	1000735863 FLD984166967												
109	TAMPA ARMATURE WORKS INC 1910 OLA AVENUE TAMPA, FL 33619 RCRIS: Owner: ARNOLD HARRINGTON (813) 621-5661 Contact: ARNOLD HARRINGTON (813) 621-5661	RCRIS-SQG	1000701018 FLD984166967												
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>F001</td><td>.00000 (T)</td><td>Notification</td><td>F003</td><td>.00000 (T)</td><td>Notification</td></tr></table> (P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported	Waste	Quantity	Info Source	Waste	Quantity	Info Source	F001	.00000 (T)	Notification	F003	.00000 (T)	Notification		
Waste	Quantity	Info Source	Waste	Quantity	Info Source										
F001	.00000 (T)	Notification	F003	.00000 (T)	Notification										
110	AMOCO 7TH AVE GROCERY 901 E 7TH AVE TAMPA, FL 33605	UST LUST	U001354025 N/A												

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO 7TH AVE GROCERY (Continued)

U001354025

LUST:

Facility ID:	8624761	Facility Type:	RETAIL STATION
Telephone:	8132474731	Alias Name 1:	Not reported
Discovery Date:	09/11/88	Alias Name 2:	Not reported
Tracking Number:	293767	Alias Name 3:	Not reported
Score:	030	Alias Name 4:	Not reported
Rank:	04434	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNKNOWN

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

REMEDIAL ACTION PLAN

Response Remedial Action Plan Type:

GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO 7TH AVE GROCERY (Continued)

U001354025

UST:

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	1R1
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

AMOCO 7TH AVE GROCERY (Continued)

U001354025

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Auto tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

AMOCO 7TH AVE GROCERY (Continued)

U001354025

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624761	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	GAS KWICK INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293767
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	AMOCO 7TH AVE GROCERY (Continued)		U001354025
	Facility ID: 298624761 Is fac. regulated: Regulated facility Operator: JOHN P MYERS JR Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860505 Tank ID: 5 Owner's Contact: JOHN P MYERS JR Owner: GAS KWICK INC PO BOX 5238 TAMPA, FL 336755238 Owner's Phone: 8132474731 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00001000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells	Facility Type: Retail Station Is facility open: Open Facility Phone: 8132474731 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 293767 Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Hazardous/other Last used Date: 89/12 RPT by Tank #: Not reported	
110	STAR #1229 1802 N NEBRASKA AVE TAMPA, FL 33602	UST LUST	U001354863 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STAR #1229 (Continued)

U001354863

LUST:

Facility ID:	8625656	Facility Type:	RETAIL STATION
Telephone:	8132240749	Alias Name 1:	Not reported
Discovery Date:	03/18/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	035	Alias Name 4:	Not reported
Rank:	03369	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:	TANK REMOVAL	

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	CONTAMINATION ASSESSMENT REPORT
Extension Status:	APPROVED
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

STAR #1229 (Continued)

U001354863

UST:

Facility ID:	298625656	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STAR SERVICE		
Contact:	Not reported	Facility Phone:	8132240749
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	S. J. BRADSHAW, JR.		
Owner:	KNOPF, DOROTHY & WILLIAM I 6744 NEOSHO ST SAINT LOUIS, MO 631093035		
Owner's Phone:	3149975990	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625656	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STAR SERVICE		
Contact:	Not reported	Facility Phone:	8132240749
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	S. J. BRADSHAW, JR.		
Owner:	KNOPF, DOROTHY & WILLIAM I 6744 NEOSHO ST SAINT LOUIS, MO 631093035		
Owner's Phone:	3149975990	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	70/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			STAR #1229 (Continued)			U001354863
			Facility ID: 298625656 Is fac. regulated: Not regulated facility Operator: STAR SERVICE Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860522 Tank ID: 3 Owner's Contact: S. J. BRADSHAW, JR. Owner: KNOPF, DOROTHY & WILLIAM I 6744 NEOSHO ST SAINT LOUIS, MO 631093035 Owner's Phone: 3149975990 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00004000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells	Facility Type: Retail Station Is facility open: Closed Facility Phone: 8132240749 Region: Not reported Financial responsibility: None District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 70/03 Content Category: Vehicular Last used Date: 91/03 RPT by Tank #: Not reported		
111			TAMPA,CITY-POLICE,DEPT 1810 N HIGHLAND AVE TAMPA, FL 33602	UST LUST	U001355932	N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355932

UST:

Facility ID:	298942562	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY-POLICE DEPT		
Contact:	Not reported	Facility Phone:	8132255918
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT		
	1710 N TAMPA ST		
	TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297810
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298942562	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY-POLICE DEPT		
Contact:	Not reported	Facility Phone:	8132255918
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT		
	1710 N TAMPA ST		
	TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297810
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
111	TAMPA WTP 1810 HIGHLAND AVE TAMPA, FL 33610 Other Pertinent Environmental Activity Identified at Site: facility has active water discharge permits	FINDS	1000496814 FLD000865469
112	TAMPA RADIATOR & AIR CONDITION 1912 N TAMPA ST TAMPA, FL 33602 RCRIS: Not Reported	RCRIS-SQG FINDS	1000344909 FLD982136368
113	AUTOMOTIVE CLUTCH 1805 N FRANKLIN TAMPA, FL 33602 Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	FINDS	1000497140 FLD032762262
114	GSA MOTOR POOL FUELING STATION 1705 N FLORIDA AVE TAMPA, FL 33602 UST: Facility ID: 298732541 Is fac. regulated: Not regulated facility Operator: PAT BAILEY Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 870519 Tank ID: 1 Owner's Contact: KIRK MCGEE Owner: COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330 Owner's Phone: 9072748638 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00003000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	UST	U001355408 N/A
	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 4043312698 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GSA MOTOR POOL FUELING STATION (Continued)

U001355408

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GSA MOTOR POOL FUELING STATION (Continued)

U001355408

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		
Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GSA MOTOR POOL FUELING STATION (Continued)

U001355408

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298732541	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PAT BAILEY		
Contact:	Not reported	Facility Phone:	4043312698
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870519	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	KIRK MCGEE		
Owner:	COOK INLET REGION INC PO BOX 93330 ANCHORAGE, AK 995093330		
Owner's Phone:	9072748638	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

115

EL ENCANTO CLEANERS
1818 15TH ST
TAMPA, FL 33605

RCRIS-SQG 1000207263
FINDS FLD089649693

RCRIS: Not Reported

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
116			KASH N KARRY FOOD STORES 1811 N 22ND ST TAMPA, FL 33605	UST	U001356131	N/A
UST:						
Facility ID:		299046104	Facility Type:	Retail Station		
Is fac. regulated:		Not regulated facility	Is facility open:	Closed		
Operator:		KASH N KARRY FOOD STORES INC				
Contact:		Not reported	Facility Phone:	Not reported		
Permit Section:		Not reported	Region:	Not reported		
Facility Code:		No violation				
Date entered:		900403	Financial responsibility:	Not reported		
Tank ID:		1	District:	Southwest		
Owner's Contact:		MARK STEWART				
Owner:		KASH N KARRY FOOD STORES INC 6422 HARNEY RD TAMPA, FL 336800000				
Owner's Phone:		8136210297	Tracking #:	Not reported		
Cleanup Status:		Not reported	Any contaminated soil:	Not reported		
Drink. Wat. Well:		Not reported	Any contaminated surface water:	Not reported		
Tank Cap. (Gals):		00004000	Any monit. wells:	Not reported		
Tank position:		Not reported	Any contam. groundwater:	Not reported		
Tank Content:		Not reported	Contaminated media indicator:	Not reported		
Disposal Method:		Removed	Install. Date:	Not reported		
Is tank regulated:		Not regulated tank	Content Category:	Vehicular		
Facility Status:		Not reported	Last used Date:	Not reported		
RPT Tank #:		Not reported	RPT by Tank #:	Not reported		
Tank Constr.:		Not reported				
Tank Piping:		Not reported				
Petro. Monitoring:		Unknown/not reported				

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KASH N KARRY FOOD STORES (Continued)

U001356131

Facility ID:	299046104	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N KARRY FOOD STORES INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MARK STEWART		
Owner:	KASH N KARRY FOOD STORES INC		
	6422 HARNEY RD		
	TAMPA, FL 336800000		
Owner's Phone:	8136210297	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299046104	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	KASH N KARRY FOOD STORES INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900403	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MARK STEWART		
Owner:	KASH N KARRY FOOD STORES INC		
	6422 HARNEY RD		
	TAMPA, FL 336800000		
Owner's Phone:	8136210297	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

117

KWIK STOP
934 E HENDERSON AVE
TAMPA, FL 33605

UST
LUST

U001354739
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KWIK STOP (Continued)

U001354739

UST:

Facility ID:	298625526	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KWIK STOP		
Contact:	Not reported	Facility Phone:	8132239890
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	KWIK STOP		
	934 E HENDERSON AVE		
	TAMPA, FL 336054806		
Owner's Phone:	Not reported	Tracking #:	294425
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

Facility ID:	298625526	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KWIK STOP		
Contact:	Not reported	Facility Phone:	8132239890
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	KWIK STOP		
	934 E HENDERSON AVE		
	TAMPA, FL 336054806		
Owner's Phone:	Not reported	Tracking #:	294425
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number						
	KWIK STOP (Continued)		U001354739						
	Facility ID: 298625526 Is fac. regulated: Regulated facility Operator: KWIK STOP Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860521 Tank ID: 3 Owner's Contact: Not reported Owner: KWIK STOP 934 E HENDERSON AVE TAMPA, FL 336054806 Owner's Phone: Not reported Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00010000 Tank position: Not reported Tank Content: Not reported Disposal Method: In service Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells, Piping/flow restrictor	Facility Type: Retail Station Is facility open: Open Facility Phone: 8132239890 Region: Not reported Financial responsibility: Oth Apprvd Coverage District: Southwest Tracking #: 294425 Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 82/11 Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported							
118	YBOR CENTRAL LTD. 1616 EAST SEVENTH AVENUE TAMPA, FL 33605 RCRIS: Not Reported	RCRIS-SQG FINDS	1000350946 FLD981020191						
119	AAA METAL REFINISHING & CHROME 3012 E 7TH AVE TAMPA, FL 33605 RCRIS: Owner: JAIME REGALADO OWNER (813) 247-2190 Contact:JAIME REGALADO (813) 247-2190 <table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D000</td><td>.00000 (T)</td><td>Notification</td></tr></table> (P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported	Waste	Quantity	Info Source	D000	.00000 (T)	Notification	RCRIS-SQG	1000978634 FL0000890491
Waste	Quantity	Info Source							
D000	.00000 (T)	Notification							
119	AAA METAL REFINISHING & CHROME 3012 E 7TH AVE TAMPA, FL 33605	FINDS	1000933569 FL0000890491						
120	CHAMPION FLEET SERVICE INC 3313 E 7TH AVE TAMPA, FL 33605	RCRIS-SQG FINDS	1000501844 FLD984219865						

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number																		
	CHAMPION FLEET SERVICE INC (Continued)		1000501844																		
	RCRIS: Owner: JIM CHAMPION (813) 247-3971 Contact:JIM CHAMPION (813) 247-3971																				
	<table><tr><td>Waste</td><td>Quantity</td><td>Info Source</td><td>Waste</td><td>Quantity</td><td>Info Source</td></tr><tr><td>D001</td><td>.00000 (T)</td><td>Notification</td><td>D008</td><td>.00000 (T)</td><td>Notification</td></tr><tr><td>D018</td><td>.00000 (T)</td><td>Notification</td><td>D039</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	Waste	Quantity	Info Source	D001	.00000 (T)	Notification	D008	.00000 (T)	Notification	D018	.00000 (T)	Notification	D039	.00000 (T)	Notification		
Waste	Quantity	Info Source	Waste	Quantity	Info Source																
D001	.00000 (T)	Notification	D008	.00000 (T)	Notification																
D018	.00000 (T)	Notification	D039	.00000 (T)	Notification																
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported																				
121	RALSTON PURINA 3615 E 7TH AVE TAMPA, FL 33605 Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	FINDS	1000496906 FLD004090742																		
122	CSX TRANSPORTATION INC-RALSTON PURINA 3702 E 7TH AVE TAMPA, FL 33605 AST: Facility ID: 299101417 Facility Type: Non-retail Business Is fac. regulated: Not regulated facility Is facility open: Closed Operator: CSX TRANSPORTATION INC Facility Phone: 9043591651 Permit Section: 00000 Date entered: 910401 Financial responsibility: None Tank ID: 1 District: Southwest Owner's Contact: K W RICHARDSON JR Owner: CSX TRANSPORTATION INC J275 500 WATER ST JACKSONVILLE, FL 32202 Owner's Phone: 9043591986 Tracking #: Not reported Drink. Wat. Well: 0000 Any contaminated soil: Yes Cleanup Status: Ongoing Any contaminated surface water: No Tank position: Aboveground Tank Cap. (Gals): 00008000 Tank Content: Vehic diesel Contaminated media indicator: Yes Disposal Method: Removed Install. Date: Not reported Is tank regulated: Not regulated tank Content Category: Vehicular Last used Date: 91/03 Any contaminated groundwater: Yes RPT Tank #: Not reported RPT by Tank #: Not reported Tank Constr.: Unknown/not reported Tank Piping: Unknown/not reported Petro. Monitoring: Unknown/not reported	AST	A100008991 N/A																		
123	DIAZ PROPERTY 2101 N HOWARD AVE TAMPA, FL	UST LUST	U001378109 N/A																		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	DIAZ PROPERTY (Continued)		U001378109
	UST: Facility ID: 299201458 Is fac. regulated: Not regulated facility Operator: DIAZ, JOSEPH Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 920604 Tank ID: 1 Owner's Contact: JOSEPH DIAZ Owner: DIAZ, JOSEPH 2213 N HOWARD AVE TAMPA, FL 336220000 Owner's Phone: 8132511886 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000888 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132511886 Region: Not reported Financial responsibility: None District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Vehicular Last used Date: 91/XX RPT by Tank #: Not reported		
124	FLORAL DRY CLEANERS & LAUNDRY 3810 E 7TH AVE TAMPA, FL 33691	FINDS	1000735137 FLD982106544
124	FLORAL DRY CLEANERS & LAUNDRY 3810 EAST 7TH AVE TAMPA, FL RCRIS: Not Reported	RCRIS-SQG	1000700386 FLD982106544
125	RIVER HEIGHTS MARINA & DRYDOCK 2305 N WILLOW AVE TAMPA, FL 33607	UST LUST	U001354758 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RIVER HEIGHTS MARINA & DRYDOCK (Continued)

U001354758

LUST:

Facility ID:	8625545	Facility Type:	MARINE FACILITY
Telephone:	8132515980	Alias Name 1:	RIVER HEIGHTS MARINA
Discovery Date:	09/13/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

CLOSURE REPORT

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NO C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

RESPONSIBLE PARTY-NO CLAIM

Incident Program Type:

Not reported

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

RIVER HEIGHTS MARINA & DRYDOCK (Continued)

U001354758

UST:

Facility ID:	298625545	Facility Type:	Marine facility
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MILLARD, MICHAEL		
Contact:	Not reported	Facility Phone:	8132515980
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE OR SUSAN MILLARD		
Owner:	RIVER HEIGHTS MARINA 2305 N WILLOW AVE TAMPA, FL 336072807		
Owner's Phone:	8132515980	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Auto sample wells, Man sample wells		

Facility ID:	298625545	Facility Type:	Marine facility
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MILLARD, MICHAEL		
Contact:	Not reported	Facility Phone:	8132515980
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE OR SUSAN MILLARD		
Owner:	RIVER HEIGHTS MARINA 2305 N WILLOW AVE TAMPA, FL 336072807		
Owner's Phone:	8132515980	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	83/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Auto sample wells, Man sample wells		

126

TOUCH OF CLASS
813 E HENDERSON AVE
TAMPA, FL 33602

RCRIS-SQG 1000821350
FINDS FLD984242693

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number																		
	TOUCH OF CLASS (Continued)		1000821350																		
	RCRIS: Owner: ALFRED ORTEGA III, OWNER (813) 229-0083 Contact:ALFRED ORTEGA (813) 229-0083																				
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D001</td><td>.00000 (T)</td><td>Notification</td><td>D035</td><td>.00000 (T)</td><td>Notification</td></tr><tr><td>F003</td><td>.00000 (T)</td><td>Notification</td><td>F005</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	Waste	Quantity	Info Source	D001	.00000 (T)	Notification	D035	.00000 (T)	Notification	F003	.00000 (T)	Notification	F005	.00000 (T)	Notification		
Waste	Quantity	Info Source	Waste	Quantity	Info Source																
D001	.00000 (T)	Notification	D035	.00000 (T)	Notification																
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification																
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported																				
127	FORMER FL BREWERY SITE 1211 E 6TH AVE TAMPA, FL 33605	LUST	S101264461 N/A																		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FORMER FL BREWERY SITE (Continued)

S101264461

LUST:

Facility ID:	9401813	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132734201	Alias Name 1:	Not reported
Discovery Date:	08/31/94	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

127

FORMER FL BREWERY SITE
1211 6TH AVE
TAMPA, FL 33605

UST

U002038275
N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

FORMER FL BREWERY SITE (Continued)

U002038275

UST:

Facility ID:	299401813	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	8132734201
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940929	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	VANCE SMITH		
Owner:	JAMANCO INC		
	PO BOX 1531		
	TAMPA, FL 33601		
Owner's Phone:	8132734201	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

128	BEI SEL INC 1703 N 20TH ST TAMPA, FL 33605	LUST	S101638056 N/A
-----	--	------	-------------------

129	HW BLAKE JUNIOR HIGH SCHOOL 1125 SPRUCE STREET TAMPA, FL 33607	FINDS	1000738371 FLD984230029
-----	--	-------	----------------------------

129	HILLSBOROUGH CO H W BLAKE JR HIGH S 1125 SPRUCE ST TAMPA, FL 33605	RCRIS-SQG	1000703412 FLD984230029
-----	--	-----------	----------------------------

RCRIS:

Owner: PHILLIP GUFFEY, DEALER
(813) 626-0806

Contact: PHILLIP GUFFEY
(813) 626-0806

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D002	.00000 (T)	Notification	D003	.00000 (T)	Notification
D004	.00000 (T)	Notification	D005	.00000 (T)	Notification
D006	.00000 (T)	Notification	D007	.00000 (T)	Notification
D008	.00000 (T)	Notification	D009	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

RCRIS:

Owner: ANDREW CASTANHEIRO
(813) 229-7304

Contact: ANDREW CASTANHEIRO
(813) 229-7304

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Other Pertinent Environmental Activity Identified at Site:
facility has an emission permit under the Clean Air Act

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PETE & FRANKS GARAGE (Continued)

U001355210

LUST:

Facility ID:	8627430	Facility Type:	RETAIL STATION
Telephone:	8132483312	Alias Name 1:	Not reported
Discovery Date:	03/05/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: LEADED GAS
Pollutant 2: UNLEADED GAS
Pollutant 3: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN
Est. Gallons Lost: UNKNOWN
Est. Gallons Lost: UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

INELIGIBLE

Incident Ineligible Reason:

OPERATING AFTER 3/90

Incident Ineligible Description:

OPERATING AFTER

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

APPROVED

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PETE & FRANKS GARAGE (Continued)

U001355210

UST:

Facility ID:	298627430	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIDEL J. GONZALEZ		
Contact:	Not reported	Facility Phone:	8132483312
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	F. U. CASTELLADO		
Owner:	PERRICONE, ROSIE C 3108 W NASSAU ST TAMPA, FL 336075143		
Owner's Phone:	8138764946	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	77/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627430	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIDEL J. GONZALEZ		
Contact:	Not reported	Facility Phone:	8132483312
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	F. U. CASTELLADO		
Owner:	PERRICONE, ROSIE C 3108 W NASSAU ST TAMPA, FL 336075143		
Owner's Phone:	8138764946	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	77/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

PETE & FRANKS GARAGE (Continued)

U001355210

Facility ID:	298627430	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIDEL J. GONZALEZ		
Contact:	Not reported	Facility Phone:	8132483312
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	F. U. CASTELLADO		
Owner:	PERRICONE, ROSIE C 3108 W NASSAU ST TAMPA, FL 336075143		
Owner's Phone:	8138764946	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	80/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627430	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIDEL J. GONZALEZ		
Contact:	Not reported	Facility Phone:	8132483312
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	F. U. CASTELLADO		
Owner:	PERRICONE, ROSIE C 3108 W NASSAU ST TAMPA, FL 336075143		
Owner's Phone:	8138764946	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

134

GRACE W R & CO PESTICIDES WARE
1604 36TH ST
TAMPA, FL 33601

FINDS

1000732723
FLD000653477

Other Pertinent Environmental Activity Identified at Site:
facility has an emission permit under the Clean Air Act

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
134	KIMMINS RECYCLING (TAMPA) 1604 N 36TH ST TAMPA, FL LF: Facility ID: 4029P30087 Facility Status: ACTIVE Population Served: 750,000 PERSONS Design Capacity: 0.0000 Amount Daily Waste: 200 TON Number of Monitoring Wells: 0 WELLS Facility Telephone: (813) 248-3878 Status: Active Facility Contact: KIMMINS CONTRACTING CORP	SWF/LF	S101011585 N/A
134	W R GRACE & CO PESTICIDE WAREHOUSE 1604 36TH STREET TAMPA, FL 38103 RCRIS: Not Reported	RCRIS-SQG	1000698335 FLD000653477
134	KIMMINS RECYCLING FACILITY OF TAMPA 1604 N 36TH ST TAMPA, FL 33605 UST: Facility ID: 299501536 Facility Type: Non-retail Business Is fac. regulated: Not regulated facility Is facility open: Open Operator: CHARLES A BAKER JR Contact: Not reported Facility Phone: 8132483878 Permit Section: Not reported Region: Not reported Facility Code: No violation Date entered: 950306 Financial responsibility: None Tank ID: NONE District: Southwest Owner's Contact: WINA WHITE Owner: KIMMINS RECYCLING CORP 1501 E 2ND AVE TAMPA, FL 336055005 Owner's Phone: 8132483878 Tracking #: Not reported Cleanup Status: Not reported Any contaminated soil: Not reported Drink. Wat. Well: Not reported Any contaminated surface water: Not reported Tank Cap. (Gals): Not reported Any monit. wells: Not reported Tank position: Not reported Any contam. groundwater: Not reported Tank Content: Not reported Contaminated media indicator: Not reported Disposal Method: Not reported Install. Date: Not reported Is tank regulated: Not reported Content Category: Not reported Facility Status: Not reported Last used Date: Not reported RPT Tank #: Not reported RPT by Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not reported	UST	U002113435 N/A
134	FLORIDA IRON & METAL 1603 36TH ST TAMPA, FL 33601 Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	FINDS	1000497138 FLD032759656
134	GRACE & CO,WR 1604 N 36TH ST TAMPA, FL 33605	UST	U001354950 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRACE & CO,WR (Continued)

U001354950

UST:

Facility ID:	298625747	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132483101
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA PO BOX 1210 FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625747	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132483101
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA PO BOX 1210 FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GRACE & CO,WR (Continued)

U001354950

Facility ID:	298625747	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132483101
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA PO BOX 1210 FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625747	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132483101
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA PO BOX 1210 FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	40/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

135

TAMPA BAY CLEANERS SUPPLY
2302 E 5TH AVE
TAMPA, FL 33605

RCRIS-SQG 1000461142
FINDS FLD984188482

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	TAMPA BAY CLEANERS SUPPLY (Continued)		1000461142
	RCRIS: Owner: DICK QUEIPO, MGR (813) 247-6332 Contact:DICK QUEIPO (813) 247-6332		
	Waste Quantity Info Source		
	F002 .00000 (T) Notification		
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported		
136	FLORIDA STEEL CORP 5TH AVE & 28TH ST TAMPA, FL 33605	FINDS	1000361426 FLD982089674
	Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act		
136	FLORIDA MISC. STEEL PRODUCTS 2710 5TH AVE. TAMPA, FL 33605	FINDS	1000735398 FLD982134470
137	ALL AMERICAN CUSTOM CHROME INC 3211 5TH AVE TAMPA, FL 33605	RCRIS-SQG	1000859231 FLD984220418
	RCRIS: Owner: MIKE REYNOLDS, PLT MGR (813) 248-6221 Contact:MIKE REYNOLDS (813) 248-6221		
	Waste Quantity Info Source	Waste Quantity Info Source	
	D000 .00000 (T) Notification	D007 .00000 (T) Notification	
	F006 .00000 (T) Notification		
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported		
	There are 4 compliance/violation record(s) reported at this site:		
	Evaluation	Date	Violations
	COMPLIANCE SCHEDULE EVALUATION (CSE)	12-JAN-95	YES
	COMPLIANCE SCHEDULE EVALUATION (CSE)	22-SEP-94	YES
	COMPLIANCE EVALUATION INSPECTION (CEI)	23-AUG-94	YES
	COMPLIANCE EVALUATION INSPECTION (CEI)	07-JUL-93	YES
137	ALL AMERICAN CUSTOM CHROME INC 3211 E 5TH AVENUE TAMPA, FL 33605	FINDS	1000501895 FLD984220418

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
137	CROWN WINDOW CO. 3204 E 5TH AVE TAMPA, FL 33605	UST	U001354371 N/A
UST:			
Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO. 3204 E 5TH AVE TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CROWN WINDOW CO. (Continued)

U001354371

Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO. 3204 E 5TH AVE TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO. 3204 E 5TH AVE TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CROWN WINDOW CO. (Continued)

U001354371

Facility ID:	298625134	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CROWN WINDOW CO.		
Contact:	Not reported	Facility Phone:	8138775731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	SAMUEL E. JACOBSON		
Owner:	CROWN WINDOW CO.		
	3204 E 5TH AVE		
	TAMPA, FL 336055721		
Owner's Phone:	8138775731	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

138	KAISER ALUMINUM & CHEMICAL 1601 34TH ST TAMPA, FL 33605	FINDS	1000497717 FLD087505806
-----	---	-------	----------------------------

139	TAMPA FLEET DIV, CITY OF 1710 DOYLE CARLTON DRIVE TAMPA, FL 33607	RCRIS-SQG FINDS	1000440423 FLD982162810
-----	---	--------------------	----------------------------

RCRIS:

Owner: GENE TAYLOR
(813) 877-0566

Contact: GENE TAYLOR
(813) 877-0566

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F002	.00000 (T)	Notification
F003	.00000 (T)	Notification	F004	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

139	TAMPA,CITY-DPW FLEET MAINT-DIV #4 1710 DOYLE CARLTON DR TAMPA, FL 33607	UST LUST	U001354379 N/A
-----	---	-------------	-------------------

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT-DIV #4 (Continued)

U001354379

LUST:

Facility ID:	8625142	Facility Type:	LOCAL, CITY GOVERNMENT
Telephone:	8132238248	Alias Name 1:	Not reported
Discovery Date:	12/24/88	Alias Name 2:	Not reported
Tracking Number:	298173	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNKNOWN

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT-DIV #4 (Continued)

U001354379

UST:

Facility ID:	298625142	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238248
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 N CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298173
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

Facility ID:	298625142	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238248
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 N CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298173
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-DPW FLEET MAINT-DIV #4 (Continued)

U001354379

Facility ID:	298625142	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238248
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298173
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

Facility ID:	298625142	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8132238248
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	298173
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

140

TAMPA,CITY-POLICE DEPT
1710 N TAMPA ST
TAMPA, FL 33602

UST

U001355934
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355934

UST:

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355934

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-POLICE DEPT (Continued)

U001355934

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-POLICE DEPT (Continued)

U001355934

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT		
	1710 N TAMPA ST		
	TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298942565	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID OSTING		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT		
	1710 N TAMPA ST		
	TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297812
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

140

TAMPA,CITY-POLICE DEPT
1710 N TAMPA ST
TAMPA, FL 33602

UST
LUST

U001355933
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

UST:

Facility ID:	298942563	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	OSTING, DAVID		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297811
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298942563	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	OSTING, DAVID		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297811
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Unmaintained	Install. Date:	60/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-POLICE DEPT (Continued)

U001355933

Facility ID:	298942563	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	OSTING, DAVID		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297811
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298942563	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	OSTING, DAVID		
Contact:	Not reported	Facility Phone:	8132255986
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890103	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	HOLLIE CALLIG		
Owner:	TAMPA,CITY-POLICE DEPT 1710 N TAMPA ST TAMPA, FL 336022648		
Owner's Phone:	8132255903	Tracking #:	297811
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

141 TAMBORELLO STATION
1715 E 4TH AVE
TAMPA, FL 33605

UST
LUST U001354083
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMBORELLO STATION (Continued)

U001354083

LUST:

Facility ID:	8624823	Facility Type:	RETAIL STATION
Telephone:	8132482781	Alias Name 1:	Not reported
Discovery Date:	09/11/88	Alias Name 2:	Not reported
Tracking Number:	293765	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMBORELLO STATION (Continued)

U001354083

UST:

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMBORELLO STATION (Continued)

U001354083

Facility ID:	298624823	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HENRY TAMBORELLO		
Contact:	Not reported	Facility Phone:	8132482781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	9	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	293765
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

142

PEPE'S TRUCK REPAIR
2109 4TH AVE
TAMPA, FL 33605

UST

U001823380
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

PEPE'S TRUCK REPAIR (Continued)

U001823380

UST:

Facility ID:	299400235	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CARLOS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940221	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CARLOS		
Owner:	JOMITO CORP 2109 4TH AVE TAMPA, FL 336050000		
Owner's Phone:	8130000000	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299400235	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CARLOS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940221	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CARLOS		
Owner:	JOMITO CORP 2109 4TH AVE TAMPA, FL 336050000		
Owner's Phone:	8130000000	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

142

RICHARD'S STATION
2102 E 4TH AVE
TAMPA, FL 33605

UST
LUST

U001356095
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RICHARD'S STATION (Continued)

U001356095

LUST:

Facility ID:	9045640	Facility Type:	RETAIL STATION
Telephone:	8139851877	Alias Name 1:	Not reported
Discovery Date:	06/26/92	Alias Name 2:	Not reported
Tracking Number:	298750	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RICHARD'S STATION (Continued)

U001356095

UST:

Facility ID:	299045640	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	GUZMAN RICHARD		
Contact:	Not reported	Facility Phone:	8139851877
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900111	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	GUZMAN RICHARD 2102 E 4TH AVE TAMPA, FL 336055305		
Owner's Phone:	8139851877	Tracking #:	298750
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	299045640	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	GUZMAN RICHARD		
Contact:	Not reported	Facility Phone:	8139851877
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900111	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	GUZMAN RICHARD 2102 E 4TH AVE TAMPA, FL 336055305		
Owner's Phone:	8139851877	Tracking #:	298750
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

143

PHILLIPS 66-ANDY'S SPARTAN OIL
2202 E 4TH AVE
TAMPA, FL 33605

UST
LUST
AST

U001354848
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PHILLIPS 66-ANDY'S SPARTAN OIL (Continued)

U001354848

LUST:

Facility ID:	8625641	Facility Type:	RETAIL STATION
Telephone:	8132426404	Alias Name 1:	Not reported
Discovery Date:	10/10/88	Alias Name 2:	Not reported
Tracking Number:	299146	Alias Name 3:	Not reported
Score:	019 (LOW)	Alias Name 4:	Not reported
Rank:	05608	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

PHILLIPS 66-ANDY'S SPARTAN OIL (Continued)

U001354848

UST:

Facility ID:	298625641	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANDREW LOPEZ		
Contact:	Not reported	Facility Phone:	8132426404
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	299146
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625641	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANDREW LOPEZ		
Contact:	Not reported	Facility Phone:	8132426404
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	299146
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

PHILLIPS 66-ANDY'S SPARTAN OIL (Continued)

U001354848

Facility ID:	298625641	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANDREW LOPEZ		
Contact:	Not reported	Facility Phone:	8132426404
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	299146
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

AST:

Facility ID:	298625641	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANDREW LOPEZ		
Facility Phone:	8132426404	Permit Section:	00000
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	299146
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000150
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	90/09	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Not required		

143

LONNIE'S BODY SHOP
2201 E 4TH AVE
TAMPA, FL 33605

UST
LUST

U001356067
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

LONNIE'S BODY SHOP (Continued)

U001356067

LUST:

Facility ID:	8945277	Facility Type:	RETAIL STATION
Telephone:	8132486820	Alias Name 1:	Not reported
Discovery Date:	12/30/88	Alias Name 2:	Not reported
Tracking Number:	298562	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	<p> LONNIE'S BODY SHOP (Continued) </p> <p> UST: Facility ID: 298945277 Is fac. regulated: Regulated facility Operator: WILLIAMS LONNIE Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 891107 Tank ID: 1 Owner's Contact: LONNIE WILLIAMS Owner: WILLIAMS, LONNIE PO BOX 5504 TAMPA, FL 336755504 Owner's Phone: 8132486820 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000888 Tank position: Not reported Tank Content: Not reported Disposal Method: Unmaintained Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported </p>	<p> Facility Type: Retail Station Is facility open: Open Facility Phone: 8132486820 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 298562 Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: Not reported Content Category: Vehicular Last used Date: 59/XX RPT by Tank #: Not reported </p>	<p> U001356067 </p>
144	<p> AUTH APPLIANCE RECYCLING CTR 2403 4TH AVE TAMPA, FL 33609 </p>	<p> FINDS </p>	<p> 1000931762 FL0000304279 </p>
145	<p> AUTOMATIC SPRINKLERS INC 2625 E 4TH AVE TAMPA, FL 33605 </p>	<p> UST LUST </p>	<p> U001962955 N/A </p>

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	AUTOMATIC SPRINKLERS INC (Continued)		U001962955
	UST: Facility ID: 299401418 Is fac. regulated: Not regulated facility Operator: Not reported Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 940812 Tank ID: NONE Owner's Contact: W A KRUIZEN Owner: GENERAL MANAGEMENT DEVELOPMENT 2909 BAY TO BAY BLVD #600 TAMPA, FL 33629 Owner's Phone: 8138373009 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): Not reported Tank position: Not reported Tank Content: Not reported Disposal Method: Not reported Is tank regulated: Not reported Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8138373009 Region: Not reported Financial responsibility: None District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: Not reported Content Category: Not reported Last used Date: Not reported RPT by Tank #: Not reported	
146	SCRAP ALL 2801 4TH AVE TAMPA, FL 33602 Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	FINDS	1000497504 FLD067220566
147	RED HOGAN ENTERPRISES INC 3109 E 4TH AVE TAMPA, FL 33605	UST LUST	U001356338 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RED HOGAN ENTERPRISES INC (Continued)

U001356338

LUST:

Facility ID:	9101913	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132483428	Alias Name 1:	Not reported
Discovery Date:	06/17/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	012 (LOW)	Alias Name 4:	Not reported
Rank:	06172	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

ABANDONED TANK RESTORATIO

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

RED HOGAN ENTERPRISES INC (Continued)

U001356338

UST:

Facility ID:	299101913	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HOGAN, THOMAS L		
Contact:	Not reported	Facility Phone:	8132483428
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910430	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	THOMAS L HOGAN		
Owner:	HOGAN, THOMAS L		
	PO BOX 13201		
	TAMPA, FL 336810000		
Owner's Phone:	8132483428	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

148

KEN ROBINSON OF FL INC
3225 E 4TH AVE
TAMPA, FL 33605

UST
LUST

U001355860
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KEN ROBINSON OF FL INC (Continued)

U001355860

LUST:

Facility ID:	8841810	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132481711	Alias Name 1:	Not reported
Discovery Date:	05/19/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	012 (LOW)	Alias Name 4:	Not reported
Rank:	06172	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

RESPONSIBLE PARTY-NO CLAIM

Incident Program Type:

Not reported

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

KEN ROBINSON OF FL INC (Continued)

U001355860

UST:

Facility ID:	298841810	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROBINSON KEN		
Contact:	Not reported	Facility Phone:	8132481711
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881017	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	KEN ROBINSON		
Owner:	KEN ROBINSON OF FL INC		
	3225 E 4TH AVE		
	TAMPA, FL 336050000		
Owner's Phone:	8132481711	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

149

MANNA PRO CORP.
1306 E 4TH AVE
TAMPA, FL 33605

UST

U001354051
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MANNA PRO CORP. (Continued)

U001354051

UST:

Facility ID:	298624788	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANNA PRO CORP.		
Contact:	Not reported	Facility Phone:	8132475678
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BILL SNELLING		
Owner:	MANNA PRO CORP		
	PO BOX 2442		
	TAMPA, FL 336012442		
Owner's Phone:	8132475678	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	76/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

149

EAGLE SUPPLY, INC.
1301 E 4TH AVE
TAMPA, FL 33605

UST

U001355237
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

EAGLE SUPPLY, INC. (Continued)

U001355237

UST:

Facility ID:	298627636	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RALPH MARSHALL		
Contact:	Not reported	Facility Phone:	8132484911
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DON DAVIS		
Owner:	EAGLE SUPPLY INC		
	PO BOX 75305		
	TAMPA, FL 336750305		
Owner's Phone:	8132484911	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

150

TAMPA BRAKE & SUPPLY CO., INC.
1419 E 4TH AVE
TAMPA, FL 33605

UST

U001355415
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA BRAKE & SUPPLY CO., INC. (Continued)

U001355415

UST:

Facility ID:	298732615	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA BRAKE & SUPPLY CO., INC.		
Contact:	Not reported	Facility Phone:	8132473444
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870522	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	ARTHUR W. SCHILLING		
Owner:	TAMPA BRAKE & SUPPLY CO., INC. 1419 E 4TH AVE TAMPA, FL 336055015		
Owner's Phone:	8132473444	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

151

TAMPA HOUSING AUTHORITY
1415 UNION ST
TAMPA, FL 33607

RCRIS-SQG
FINDS

1000344881
FLD982105132

RCRIS:

Owner: JAIME ANDERSON, SITE SUPERVISOR
(813) 622-8311

Contact: WALLAE C
(813) 253-0551

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D008	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

152

LALA PRODUCE CO.
1402 N 25TH ST
TAMPA, FL 33605

UST

U001354571
N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	LALA PRODUCE CO. (Continued)		U001354571
	UST: Facility ID: 298625349 Is fac. regulated: Regulated facility Operator: LALA PRODUCE CO. Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860516 Tank ID: 1 Owner's Contact: MIKE SILCOTT Owner: J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439 Owner's Phone: 8132287776 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00003000 Tank position: Not reported Tank Content: Not reported Disposal Method: In service Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells	Facility Type: Non-retail Business Is facility open: Open Facility Phone: 8132473168 Region: Not reported Financial responsibility: State PRGM (FLIPA/AIG) District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: 82/10 Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported	
153	BLISS PRODUCE 3119 E 3RD AVE TAMPA, FL 33605	UST LUST	U001355081 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLISS PRODUCE (Continued)

U001355081

LUST:

Facility ID:	8627006	Facility Type:	NON-RETAIL BUSINESS
Telephone:	0000000000	Alias Name 1:	Not reported
Discovery Date:	09/29/89	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported
Category: Not reported
Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLISS PRODUCE (Continued)

U001355081

UST:

Facility ID:	298627006	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BLISS, CHARLES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627006	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BLISS, CHARLES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BLISS PRODUCE (Continued)

U001355081

Facility ID:	298627006	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BLISS, CHARLES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

154	FLORIDA GRAPHIC PRODUCTS INC 3209 E THIRD AVE TAMPA, FL 33605	RCRIS-SQG FINDS	1000361440 FLD982172397
-----	---	--------------------	----------------------------

RCRIS:

Owner: GARRITY DONALD PRES
(813) 248-1356

Contact: GARRITY DONALD
(813) 248-1356

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	K086	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

155	QUALITY ELECTRIC SUPPLY INC 1400 N 34TH ST TAMPA, FL 33605	FINDS	1000933527 FL0000748079
-----	--	-------	----------------------------

156	GRACE & CO,WR-CONSTRUCTION PROD DIV 3501 E 3RD AVE TAMPA, FL 33605	UST	U001355271 N/A
-----	--	-----	-------------------

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GRACE & CO,WR-CONSTRUCTION PROD DIV (Continued)

U001355271

UST:

Facility ID:	298627813	Facility Type:	Industrial Plan
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRACE & CO,WR		
Contact:	Not reported	Facility Phone:	8132481554
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MARTIN A.STRICKLER		
Owner:	W R GRACE & CO TAMPA		
	PO BOX 1210		
	FORT PIERCE, FL 349541210		
Owner's Phone:	8132483101	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	87/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

157

GTE OF FL TAMPA
3704 E 3RD AVE
TAMPA, FL 33605

UST
LUST

U001355733
N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	GTE OF FL TAMPA (Continued)		U001355733
	UST: Facility ID: 298837677 Is fac. regulated: Not regulated facility Operator: GENERAL TELEPHONE CO OF FL Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 880115 Tank ID: 1 Owner's Contact: BARBARA E WILLIAMS Owner: GENERAL TELEPHONE CO OF FL PO BOX 110 MC 711 TAMPA, FL 336010110 Owner's Phone: 8132244740 Cleanup Status: Completed Drink. Wat. Well: 0000 Tank Cap. (Gals): 00010000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Piping/auto shut off, Piping/flow restrictor	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8136214931 Region: Not reported Financial responsibility: Oth Apprvd Coverage District: Southwest Tracking #: Not reported Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 87/12 Content Category: Vehicular Last used Date: 93/06 RPT by Tank #: Not reported	
158	FELICIONE AUTO SERVICE 1746 W MAIN ST TAMPA, FL 33607	UST LUST	U001356056 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FELICIONE AUTO SERVICE (Continued)

U001356056

LUST:

Facility ID:	8945082	Facility Type:	INLAND BULK PETROLEUM
Telephone:	0000000000	Alias Name 1:	Not reported
Discovery Date:	04/29/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	045	Alias Name 4:	Not reported
Rank:	02225	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	KEROSENE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	STATE
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FELICIONE AUTO SERVICE (Continued)

U001356056

UST:

Facility ID:	298945082	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FELICIONE AUTO SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891016	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	Not reported		
Owner:	FELICIONE AUTO SERVICE		
	1746 W MAIN ST		
	TAMPA, FL 336074320		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298945082	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FELICIONE AUTO SERVICE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	891016	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	Not reported		
Owner:	FELICIONE AUTO SERVICE		
	1746 W MAIN ST		
	TAMPA, FL 336074320		
Owner's Phone:	Not reported	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	83/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
159	TAMPA GAS CO. 1300 BLOCK OF 13TH ST. TAMPA, FL 33605 COAL GAS SITE DESCRIPTION: 1899, Tampa Gas Co. is located on the western side of 13th St., south of 3 rd. site continues south to the end of 1st St. Site is bordered to the west by railroad tracks. ©Copyright 1993 Real Property Scan, Inc.	Coal Gas	G000001449 N/A
160	SOWELL CORP,L B 1405 E 2ND AVE TAMPA, FL 33605 UST: Facility ID: 298625386 Is fac. regulated: Not regulated facility Operator: SOWELL CORP,L B Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860516 Tank ID: 1 Owner's Contact: LEO SOWELL Owner: L B SOWELL CORP 12123 RIVERHILLS DR TAMPA, FL 336171743 Owner's Phone: 8139882358 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00005000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	UST	U001354606 N/A
161	KIMMINS ENVIRONMENTAL SERVICE CORP 1501 SECOND AVENUE TAMPA, FL 33605 RCRIS: Not Reported	RCRIS-SQG FINDS	1000300124 FLD982094229
162	J B P PROPERTIES/CONTINENTAL PUBLICATI 1724 2ND AVE TAMPA, FL 33602	UST	U001823433 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

J B P PROPERTIES/CONTINENTAL PUBLICATI (Continued)

U001823433

UST:

Facility ID:	299400639	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	A M PEDONE		
Contact:	Not reported	Facility Phone:	8136232000
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940411	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	A M PEDONE		
Owner:	PEDONE, A M & JOHNSON, WALLACE H		
	9270 BAY PLAZA BLVD		
	TAMPA, FL 336190000		
Owner's Phone:	8136232000	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	GW monitoring, Vapor monitoring		

163

THOMPSON FABRICATED METALS INC
2103 2ND AVE
TAMPA, FL

UST
LUST

U001057909
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

THOMPSON FABRICATED METALS INC (Continued)

U001057909

LUST:

Facility ID:	9102303	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132483456	Alias Name 1:	Not reported
Discovery Date:	08/26/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	056	Alias Name 4:	Not reported
Rank:	01720	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	WASTE OIL	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	NOT PETROL/PETROL PRODUCT
Incident Ineligible Description:	NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

THOMPSON FABRICATED METALS INC (Continued)

U001057909

UST:

Facility ID:	299102303	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	THOMPSON FABRICATED METALS		
Contact:	Not reported	Facility Phone:	8132483456
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910614	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LESLIE V THOMPSON		
Owner:	THOMPSON FABRICATED METALS INC		
	2103 2ND AVE		
	TAMPA, FL 336050000		
Owner's Phone:	8132483456	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

164

DEL RIO PRODUCTS
2601 E 2ND AVE
TAMPA, FL 33605

UST

U001354313
N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	DEL RIO PRODUCTS (Continued)		U001354313
	UST: Facility ID: 298625072 Is fac. regulated: Not regulated facility Operator: DEL RIO PRODUCTS Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860508 Tank ID: 1 Owner's Contact: DAN TRIPLETT Owner: DEL RIO PRODUCTS PO BOX 75245 TAMPA, FL 336750245 Owner's Phone: 8132474534 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00001000 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132474534 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Vehicular Last used Date: 88/05 RPT by Tank #: Not reported	
165	BAZARTE/RENE 801 E SCOTT ST TAMPA, FL 33602	UST LUST	U001355389 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BAZARTE/RENE (Continued)

U001355389

LUST:

Facility ID:	8732385	Facility Type:	RETAIL STATION
Telephone:	8132239000	Alias Name 1:	Not reported
Discovery Date:	12/04/86	Alias Name 2:	Not reported
Tracking Number:	290297	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: NOT ENTERED

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: RESPONSIBLE PARTY

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

DISTRICT OFFICE

Response Record Type:

REMEDIAL ACTION PLAN

Response Remedial Action Plan Type:

MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

DISTRICT OFFICE

Estimated Completion Year:

00

Actual Year to Complete:

00

Report Type:

QUARTERLY

Report Comments:

QTR 1

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BAZARTE/RENE (Continued)

U001355389

UST:

Facility ID:	298732385	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RENE BAZARTE		
Contact:	Not reported	Facility Phone:	8132239000
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870410	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RENE BAZARTE		
Owner:	BAZARTE, RENE		
	801 E SCOTT ST		
	TAMPA, FL 33602		
Owner's Phone:	8132239000	Tracking #:	290297
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298732385	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RENE BAZARTE		
Contact:	Not reported	Facility Phone:	8132239000
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870410	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	RENE BAZARTE		
Owner:	BAZARTE, RENE		
	801 E SCOTT ST		
	TAMPA, FL 33602		
Owner's Phone:	8132239000	Tracking #:	290297
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	BAZARTE/RENE (Continued)		U001355389
	Facility ID: 298732385 Is fac. regulated: Not regulated facility Operator: RENE BAZARTE Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 870410 Tank ID: 3 Owner's Contact: RENE BAZARTE Owner: BAZARTE, RENE 801 E SCOTT ST TAMPA, FL 33602 Owner's Phone: 8132239000 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00001000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Retail Station Is facility open: Closed Facility Phone: 8132239000 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 290297 Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported	
166	ALPINE TRUCK STOP INC 2135 W GREEN ST TAMPA, FL 33603	UST LUST	U001356030 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

LUST:

Facility ID:	8944533	Facility Type:	RETAIL STATION
Telephone:	8132544011	Alias Name 1:	EXXON #4-5298
Discovery Date:	05/18/92	Alias Name 2:	ALPINE TRUCK STOP INC.
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	DISTRICT OFFICE
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	ANNUAL
Report Comments:	YR 1 (QTR 1,2,3)

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

UST:

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Auto sample wells, DW tank space, Not required, Auto tank gauging, GW monitoring		

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	10	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL		
	2135 W GREEN ST		
	TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL 2135 W GREEN ST TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Auto sample wells, DW tank space, Not required, Auto tank gauging, GW monitoring		

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL 2135 W GREEN ST TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Auto sample wells, DW tank space, Not required, Auto tank gauging, GW monitoring		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL 2135 W GREEN ST TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Auto sample wells, DW tank space, Not required, Auto tank gauging, GW monitoring		

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL 2135 W GREEN ST TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/12
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Auto sample wells, DW tank space, Not required, Auto tank gauging, GW monitoring		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	6	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL 2135 W GREEN ST TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	68/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	7	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL 2135 W GREEN ST TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ALPINE TRUCK STOP INC (Continued)

U001356030

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	8	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL 2135 W GREEN ST TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298944533	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SUAREZ GUILLERMO		
Contact:	Not reported	Facility Phone:	8132544011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890811	Financial responsibility:	None
Tank ID:	9	District:	Southwest
Owner's Contact:	BILL SUAREZ		
Owner:	SUAREZ, BILL 2135 W GREEN ST TAMPA, FL 336075323		
Owner's Phone:	8132544011	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

166

USE #298944533
2135 W GREEN ST
TAMPA, FL 33607

UST
LUST

U001354517
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE #298944533 (Continued)

U001354517

LUST:

Facility ID:	8625289	Facility Type:	RETAIL STATION
Telephone:	8132530824	Alias Name 1:	EXXON #4-5298-INTERSTATE
Discovery Date:	12/04/88	Alias Name 2:	Not reported
Tracking Number:	294565	Alias Name 3:	Not reported
Score:	031	Alias Name 4:	Not reported
Rank:	04031	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	USE #298944533 (Continued)		U001354517
	UST: Facility ID: 298625289 Is fac. regulated: Not regulated facility Operator: COOPER,R W Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860515 Tank ID: NONE Owner's Contact: JESSIE CRITTLE Owner: EXXON CO USA PO BOX 4386 HOUSTON, TX 772104386 Owner's Phone: 8009923647 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): Not reported Tank position: Not reported Tank Content: Not reported Disposal Method: Not reported Is tank regulated: Not reported Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not reported	Facility Type: Retail Station Is facility open: Closed Facility Phone: 8132530824 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 294565 Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Not reported Last used Date: Not reported RPT by Tank #: Not reported	
167	ADAMO DRIVE INC 1909 ADAMO DR TAMPA, FL 33601	UST LUST	U001354425 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ADAMO DRIVE INC (Continued)

U001354425

LUST:

Facility ID:	8625191	Facility Type:	RETAIL STATION
Telephone:	8132287776	Alias Name 1:	Not reported
Discovery Date:	12/23/88	Alias Name 2:	Not reported
Tracking Number:	298291	Alias Name 3:	Not reported
Score:	075 (HIGH)	Alias Name 4:	Not reported
Rank:	00541	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	LOCAL PROGRAM
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	O.K.

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ADAMO DRIVE INC (Continued)

U001354425

UST:

Facility ID:	298625191	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	J.H. WILLIAMS, JR.		
Contact:	Not reported	Facility Phone:	8132287776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298291
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging, Vapor monitoring		

Facility ID:	298625191	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	J.H. WILLIAMS, JR.		
Contact:	Not reported	Facility Phone:	8132287776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298291
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging, Vapor monitoring		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ADAMO DRIVE INC (Continued)

U001354425

Facility ID:	298625191	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	J.H. WILLIAMS, JR.		
Contact:	Not reported	Facility Phone:	8132287776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298291
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging, Vapor monitoring		

Facility ID:	298625191	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	J.H. WILLIAMS, JR.		
Contact:	Not reported	Facility Phone:	8132287776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	298291
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	79/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging, Vapor monitoring		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	ADAMO DRIVE INC (Continued)		U001354425
	<div> <div> Facility ID: 298625191 Is fac. regulated: Regulated facility Operator: J.H. WILLIAMS, JR. Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860514 Tank ID: 5 Owner's Contact: MIKE SILCOTT Owner: J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439 Owner's Phone: 8132287776 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00012000 Tank position: Not reported Tank Content: Not reported Disposal Method: In service Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells, Piping/flow restrictor, DW piping space, Man tank gauging, Vapor monitoring </div> <div> Facility Type: Retail Station Is facility open: Open Facility Phone: 8132287776 Region: Not reported Financial responsibility: State PRGM (FLIPA/AIG) District: Southwest Tracking #: 298291 Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 79/12 Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported </div> </div>		
167	LINDA PLASTICS OF FLORIDA INC 1207 N 19TH ST TAMPA, FL 33605 Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production	FINDS	1000497765 FLD094606381
168	KENTUCKY FRIED CHICKEN 1602 N HOWARD AVE TAMPA, FL	UST LUST	U002217722 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

KENTUCKY FRIED CHICKEN (Continued)

U002217722

UST:

Facility ID:	299501915	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	5024548027
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950606	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	DAVID CATTELL		
Owner:	KFC NATIONAL MANAGEMENT CO		
	PO BOX 34550		
	LOUISVILLE, KY 402324550		
Owner's Phone:	5024548027	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

169

PEOPLES GAS SYSTEM, INC.
1200 N 13TH ST
TAMPA, FL 33605

UST

U001354488
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PEOPLES GAS SYSTEM, INC. (Continued)

U001354488

UST:

Facility ID:	298625257	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PEOPLES GAS SYSTEM, INC.		
Contact:	Not reported	Facility Phone:	8132289743
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GLYN HAZELDEN		
Owner:	PEOPLES GAS SYSTEM INC PO BOX 2562 TAMPA, FL 336012562		
Owner's Phone:	8132289743	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	82/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	86/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625257	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PEOPLES GAS SYSTEM, INC.		
Contact:	Not reported	Facility Phone:	8132289743
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GLYN HAZELDEN		
Owner:	PEOPLES GAS SYSTEM INC PO BOX 2562 TAMPA, FL 336012562		
Owner's Phone:	8132289743	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000400	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	86/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

169

PEOPLE'S GAS SYSTEM
1200 NORTH 13TH STREET
TAMPA, FL 33601

CERCLIS
FINDS

1000348068
FLD982119653

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	PEOPLE'S GAS SYSTEM (Continued)		1000348068
	CERCLIS Classification Data: Site Incident Category: Not reported Federal Facility: D Ownership Status: UNKNOWN NPL Status: NOT ON NPL EPA Notes: ALLEGED PARA-CHEM SOUTHERN DUMP SITE. STEEL AND FIBER DRUMS IN TRENCH (275X13X16 FEET). REPORTED EXPLOSIONS, FIRES. CERCLIS Assessment History: Assessment: DISCOVERY Completed: 09/03/1987 Assessment: PRELIMINARY ASSESSMENT Completed: 10/25/1988 Assessment: SCREENING SITE INSPECTION Completed: 10/22/1991 CERCLIS Site Status: EPA has conducted a preliminary assessment on this site and has determined that no further action is necessary and no hazard was identified CERCLIS Alias Name(s): PEOPLE'S GAS SYSTEM		
169	PEOPLES GAS SYSTEM, INC. 1200 NORTH 13TH ST. TAMPA, FL 33605	FI Sites	S100889025 N/A
	FL Sites: Facility ID: 000480 EPA ID: Not reported Facility District: SOUTHWEST Monthly Update: January Lead Unit: DIST Support Unit: Not reported Air Contam: Not reported Soil Contam: Not reported Surface Water Contam: Not reported Ground Water Contam: Confirmed Cleanup Started?: No Cleanup Completed?: No Deletion Recommended?: No Other: Not reported Warning Letter Status: Not reported Notice of Violation Status: No Consent Order Status: No Admin Hearing Status: No Court Status: No Final Order Status: No Comments: NEW SITE 5-87. NATURAL GAS MANUFACTURED AT THE PROPERTY PRIOR TO 1950. GROUND WATER SAMPLES COLLECTED 12-86 CONFIRM CONTAMINATION OF SURFICIAL AQUIFER BY VOC'S AND OTHER ORGANIC COMPOUNDS. DRAFT CONSENT ORDER REQUIRING CONTAMINATION ASSESMENT AND REMEDIAL		
170	RADIANT DISCOUNT TIRES 2105 ADAMO DRIVE TAMPA, FL 33675	RCRIS-SQG	1000698916 FLD053996294
	RCRIS: Not Reported		
170	RADIANT DISCOUNT TIRES 2105 ADAMO DR TAMPA, FL 33605	FINDS	1000733384 FLD053996294
170	EXXON CO USA #49121 2105 E ADAMO & 21ST ST E TAMPA, FL 77210	RCRIS-SQG	1000701521 FLD984185694

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number												
	EXXON CO USA #49121 (Continued)		1000701521												
	RCRIS: Owner: ALDA POOL, STAFF ASSIST (713) 656-7709 Contact: C H (713) 656-7761														
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D000</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	D000	.00000 (T)	Notification	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D018</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	D018	.00000 (T)	Notification	
Waste	Quantity	Info Source													
D000	.00000 (T)	Notification													
Waste	Quantity	Info Source													
D018	.00000 (T)	Notification													
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported														
170	EXXON #4-9121 2105 ADAMO DR TAMPA, FL 33605	LUST	U001354086 N/A												

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON #4-9121 (Continued)

U001354086

LUST:

Facility ID:	8624826	Facility Type:	RETAIL STATION
Telephone:	4076473776	Alias Name 1:	EXXON #4-9121
Discovery Date:	06/26/90	Alias Name 2:	Not reported
Tracking Number:	292829	Alias Name 3:	Not reported
Score:	057	Alias Name 4:	Not reported
Rank:	01656	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Ait. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	MOP CANCELLED

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

170

EXXON CO USA #49121
2105 E ADAMO & 21ST ST EAST
TAMPA, FL 33605

FINDS
UST

1000736457
FLD984185694

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
171	WALKER CO./SOL 1110 N 35TH ST TAMPA, FL 33605 UST: Facility ID: 298625371 Is fac. regulated: Not regulated facility Operator: SOL WALKER & CO. Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860516 Tank ID: 1 Owner's Contact: MARY T. CACKLING Owner: SOL WALKER & CO PO BOX 5447 TAMPA, FL 336755447 Owner's Phone: 8132485796 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00001000 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells	UST	U001354591 N/A
172	TAMPA CITY - PUBLICATION/RECREATION 1420 N TAMPA ST TAMPA, FL 33602	UST	U001823387 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA CITY - PUBLICATION/RECREATION (Continued)

U001823387

UST:

Facility ID:	299400333	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HALLIE CALIG		
Contact:	Not reported	Facility Phone:	8132748082
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940325	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HALLIE CALIG		
Owner:	TAMPA, CITY OF		
	CITY HALL PLAZA		
	TAMPA, FL 336020000		
Owner's Phone:	8132238282	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

173

CONVENIENT FOOD MART #5503
1424 N HOWARD AVE
TAMPA, FL 33607

UST
LUST

U001354336
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CONVENIENT FOOD MART #5503 (Continued)

U001354336

LUST:

Facility ID:	8625096	Facility Type:	RETAIL STATION
Telephone:	8132516776	Alias Name 1:	Not reported
Discovery Date:	01/27/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CONVENIENT FOOD MART #5503 (Continued)

U001354336

UST:

Facility ID:	298625096	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COX CARL & VICKI		
Contact:	Not reported	Facility Phone:	8132516776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES FELTZ		
Owner:	REMOTE SERVICES INC		
	ONE VISION DR		
	ENFIELD, CT 06082		
Owner's Phone:	2037414444	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625096	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	COX CARL & VICKI		
Contact:	Not reported	Facility Phone:	8132516776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JAMES FELTZ		
Owner:	REMOTE SERVICES INC		
	ONE VISION DR		
	ENFIELD, CT 06082		
Owner's Phone:	2037414444	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/11
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			CONVENIENT FOOD MART #5503 (Continued)			U001354336
			<div> <div> Facility ID: 298625096 Is fac. regulated: Regulated facility Operator: COX CARL & VICKI Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860508 Tank ID: 3 Owner's Contact: JAMES FELTZ Owner: REMOTE SERVICES INC ONE VISION DR ENFIELD, CT 06082 Owner's Phone: 2037414444 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00010000 Tank position: Not reported Tank Content: Not reported Disposal Method: In service Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells </div> <div> Facility Type: Retail Station Is facility open: Open Facility Phone: 8132516776 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 76/11 Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported </div> </div>			
174			HILLSBOROUGH CNTY-MORGAN ST JAIL 1301 N MORGAN ST TAMPA, FL 33602	UST		U001356353 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-MORGAN ST JAIL (Continued)

U001356353

UST:

Facility ID:	299102571	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FARMER, J R		
Contact:	Not reported	Facility Phone:	8132478425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910806	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	63/10
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299102571	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FARMER, J R		
Contact:	Not reported	Facility Phone:	8132478425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910806	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	63/10
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HILLSBOROUGH CNTY-MORGAN ST JAIL (Continued)

U001356353

Facility ID:	299102571	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FARMER, J R		
Contact:	Not reported	Facility Phone:	8132478425
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910806	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	E A PULIDO		
Owner:	HILLSBOROUGH CNTY SHERIFFS DEPT PO BOX 3371 TAMPA, FL 336013371		
Owner's Phone:	8132478880	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	79/10
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

174

HILLSBOROUGH CNTY-JAIL SYSTEM
1308 N MORGAN ST
TAMPA, FL 33602

UST
LUST

U001355249
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-JAIL SYSTEM (Continued)

U001355249

LUST:

Facility ID:	8627689	Facility Type:	LOCAL, CITY GOVERNMENT
Telephone:	8132476411	Alias Name 1:	Not reported
Discovery Date:	12/19/88	Alias Name 2:	Not reported
Tracking Number:	297405	Alias Name 3:	Not reported
Score:	020 (LOW)	Alias Name 4:	Not reported
Rank:	05579	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HILLSBOROUGH CNTY-JAIL SYSTEM (Continued)

U001355249

UST:

Facility ID:	298627689	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HILLS CNTY SHERIFFS JAIL-SYSTEM		
Contact:	Not reported	Facility Phone:	8132476411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM PO BOX 1110 TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	297405
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627689	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	HILLS CNTY SHERIFFS JAIL-SYSTEM		
Contact:	Not reported	Facility Phone:	8132476411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM PO BOX 1110 TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	297405
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

175

DEVOE & RAYNOLDS PAINT CO
1010-26 N 19TH ST
TAMPA, FL 33605

LUST

S101638055
N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number												
175	DEVOE & RAYNOLDS CO 1010-26 NORTH 19TH STREET TAMPA, FL 33631 RCRIS: Not Reported	RCRIS-LQG	1000699154 FLD092715051												
175	DEVOE & RAYNOLDS CO 1010-26 N 19TH ST TAMPA, FL 33605 Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production	FINDS TRIS	1000733679 FLD092715051												
176	INTERNATIONAL SHIP REPAIR 1616 PENNY ST TAMPA, FL 33605 RCRIS: Owner: WAYNE REED, MATERIALS MGR (813) 247-1118 Contact:WAYNE REED (813) 247-1118 <table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D001</td><td>.00000 (T)</td><td>Notification</td></tr></table> (P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported There are 1 compliance/violation record(s) reported at this site: <table><tr><th>Evaluation</th><th>Date</th><th>Violations</th></tr><tr><td>COMPLIANCE EVALUATION INSPECTION (CEI)</td><td>14-MAY-93</td><td>YES</td></tr></table>	Waste	Quantity	Info Source	D001	.00000 (T)	Notification	Evaluation	Date	Violations	COMPLIANCE EVALUATION INSPECTION (CEI)	14-MAY-93	YES	RCRIS-SQG FINDS	1000858771 FL0000014555
Waste	Quantity	Info Source													
D001	.00000 (T)	Notification													
Evaluation	Date	Violations													
COMPLIANCE EVALUATION INSPECTION (CEI)	14-MAY-93	YES													
177	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 33607	UST LUST	U001355550 N/A												

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

LUST:

Facility ID:	8735467	Facility Type:	INLAND BULK PETROLEUM
Telephone:	8132530230	Alias Name 1:	Not reported
Discovery Date:	03/19/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	038	Alias Name 4:	Not reported
Rank:	02786	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

ABANDONED TANK RESTORATIO
LOCAL PROGRAM
NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: KEROSENE

Pollutant 2: Not reported

Pollutant 3: Not reported

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: 00000000

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION
STATE CLEANUP
ELIGIBLE
Not Reported
Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY
CONTAMINATION ASSESSMENT REPORT
Not reported
APPROVED
Not reported
Not reported
Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

LOCAL PROGRAM
REMEDIAL ACTION PLAN
OTHE

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported
Not reported
Not reported
Not reported
Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Flag:

Not reported

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

UST:

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL		
	1701 W LA SALLE ST		
	TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	64/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL		
	1701 W LA SALLE ST		
	TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	64/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	68/02
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	73/08
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLANCO FUEL OIL (Continued)

U001355550

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	76/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL 1701 W LA SALLE ST TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	71/05
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BLANCO FUEL OIL (Continued)

U001355550

Facility ID:	298735467	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MANUEL J.BLANCO		
Contact:	Not reported	Facility Phone:	8132530230
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871009	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	MANUEL J.BLANCO		
Owner:	BLANCO FUEL OIL		
	1701 W LA SALLE ST		
	TAMPA, FL 336075418		
Owner's Phone:	8132530230	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	71/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

178

DIXIE PLYWOOD CO OF TAMPA INC
3021 ADAMO DR
TAMPA, FL 33605

UST
LUST

U001354314
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DIXIE PLYWOOD CO OF TAMPA INC (Continued)

U001354314

LUST:

Facility ID:	8625073	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132484107	Alias Name 1:	Not reported
Discovery Date:	01/17/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	011 (LOW)	Alias Name 4:	Not reported
Rank:	06719	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DIXIE PLYWOOD CO OF TAMPA INC (Continued)

U001354314

UST:

Facility ID:	298625073	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DIXIE PLYWOOD CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132484107
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ED CAMPBELL		
Owner:	DIXIE PLYWOOD CO TAMPA PO BOX 5718 TAMPA, FL 336755718		
Owner's Phone:	8132484107	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	84/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625073	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DIXIE PLYWOOD CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132484107
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ED CAMPBELL		
Owner:	DIXIE PLYWOOD CO TAMPA PO BOX 5718 TAMPA, FL 336755718		
Owner's Phone:	8132484107	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	84/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

179

TRAMMEL BUILDING
1313 TAMPA STREET
TAMPA, FL 33602

PADS

1000855724
FL0000060509

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
179	FL DEPT OF MGMT SERVICES-PK TRAMMEL 1313 N TAMPA ST TAMPA, FL 33602 UST: Facility ID: 298841073 Is fac. regulated: Regulated facility Operator: BOB MORALES Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 880805 Tank ID: 1 Owner's Contact: AL ROZAR Owner: FL DEPT MGMT SERVICES DIV FM 2737 CENTERVIEW DR #110 KNIGHT B TALLAHASSEE, FL 323990950 Owner's Phone: 9044885215 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000500 Tank position: Not reported Tank Content: Not reported Disposal Method: In service Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not required	UST 	

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BAY FORD TRUCK SALES,INC (Continued)

U001354810

LUST:

Facility ID:	8625601	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8139803673	Alias Name 1:	Not reported
Discovery Date:	12/16/88	Alias Name 2:	Not reported
Tracking Number:	295751	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: WASTE OIL

Est. Gallons Lost: UNKNOWN

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BAY FORD TRUCK SALES,INC (Continued)

U001354810

UST:

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	BAY FORD TRUCK SALES INC		
	5815 N DALE MABRY HWY		
	TAMPA, FL 336145605		
Owner's Phone:	8139803673	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	BAY FORD TRUCK SALES INC		
	5815 N DALE MABRY HWY		
	TAMPA, FL 336145605		
Owner's Phone:	8139803673	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BAY FORD TRUCK SALES,INC (Continued)

U001354810

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	BAY FORD TRUCK SALES INC 5815 N DALE MABRY HWY TAMPA, FL 336145605		
Owner's Phone:	8139803673	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	BAY FORD TRUCK SALES INC 5815 N DALE MABRY HWY TAMPA, FL 336145605		
Owner's Phone:	8139803673	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BAY FORD TRUCK SALES,INC (Continued)

U001354810

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	BAY FORD TRUCK SALES INC 5815 N DALE MABRY HWY TAMPA, FL 336145605		
Owner's Phone:	8139803673	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625601	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAY FORD TRUCK SALES,INC		
Contact:	Not reported	Facility Phone:	8139803673
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	VALENCIA GOWER		
Owner:	BAY FORD TRUCK SALES INC 5815 N DALE MABRY HWY TAMPA, FL 336145605		
Owner's Phone:	8139803673	Tracking #:	295751
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

180

UNION CARBIDE CORP.-LINDE DIVISION
ADAMO DR & 31ST ST
TAMPA, FL 33605

UST

U001355413
N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	UNION CARBIDE CORP.-LINDE DIVISION (Continued)		U001355413
	UST: Facility ID: 298732613 Is fac. regulated: Not regulated facility Operator: UNION CARBIDE CORP. Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 870522 Tank ID: 1 Owner's Contact: W.J. WESTFALL Owner: UNION CARBIDE CORP. 39 OLD RIDGEBURY RD DANBURY, CT 068170001 Owner's Phone: 8132476467 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00006000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported Facility Type: Industrial Plan Is facility open: Closed Facility Phone: 8132476467 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: 80/XX Content Category: Hazardous/other Last used Date: 88/11 RPT by Tank #: Not reported		
180	LINDE GASES OF FLORDIA INC ADAMO DR AND 31ST ST TAMPA, FL 33605	FINDS	1000732711 FLD000646463
180	LINDE GASES OF FLORIDA INC ADAMO DRIVE AND 31ST STREET TAMPA, FL 33675 RCRIS: Not Reported	RCRIS-SQG	1000698324 FLD000646463
180	PRAYAIR INC 3100 ADAMO DR TAMPA, FL 33605 RCRIS: Owner: ARTHUR THOMAS, OPERA SUPV (813) 247-5317 Contact: Not reported Waste Quantity Info Source NONE .00000 (T) Notification (P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported	RCRIS-SQG	1000986052 FL0001046275
181	FINA STATION 1301 N HOWARD AVE TAMPA, FL 33607	UST LUST	U001037423 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

LUST:

Facility ID:	8737181	Facility Type:	RETAIL STATION
Telephone:	8132543090	Alias Name 1:	Not reported
Discovery Date:	03/29/87	Alias Name 2:	Not reported
Tracking Number:	291132	Alias Name 3:	Not reported
Score:	030	Alias Name 4:	Not reported
Rank:	04434	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

UST:

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC		
	1301 N HOWARD AVE		
	TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC		
	1301 N HOWARD AVE		
	TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Aprvd alt sys		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	11	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Aprvd alt sys		
Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC		
	1301 N HOWARD AVE		
	TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC		
	1301 N HOWARD AVE		
	TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC 1301 N HOWARD AVE TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FINA STATION (Continued)

U001037423

Facility ID:	298737181	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DONALD HARIN		
Contact:	Not reported	Facility Phone:	8132543090
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871230	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	GUILLERMO SUAREZ		
Owner:	ALPINE OIL CO INC		
	1301 N HOWARD AVE		
	TAMPA, FL 336075323		
Owner's Phone:	8132511498	Tracking #:	291132
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man tank gauging		

181	GUNN PRINTING & LITHOGRAPHY INC 1313 N HOWARD AVE TAMPA, FL 33607	RCRIS-SQG FINDS	1000450175 FLD984179705
-----	---	--------------------	----------------------------

RCRIS:

Owner: MIKE GUNN, PRES
(813) 254-2513

Contact: MIKE GUNN
(813) 254-2513

Waste	Quantity	Info Source
-------	----------	-------------

D001	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

182	GORMAN CO OF TAMPA INC 802 12TH ST TAMPA, FL 33601	FINDS	1000497020 FLD020992988
-----	--	-------	----------------------------

Other Pertinent Environmental Activity Identified at Site:
facility is involved with pesticide/toxic substances production

183	DEVOE AND RAYNOLDS CO., INC. 1010 NORTH 19TH STREET TAMPA, FL 33622	CERCLIS	1000332265 FLD092715051
-----	---	---------	----------------------------

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	DEVOE AND RAYNOLDS CO.,INC. (Continued)		1000332265
	CERCLIS Classification Data: Site Incident Category: Not reported Ownership Status: OTHER EPA Notes: Not reported CERCLIS Assessment History: Assessment: DISCOVERY Assessment: PRELIMINARY ASSESSMENT Assessment: SCREENING SITE INSPECTION CERCLIS Site Status: EPA has conducted a preliminary assessment on this site and has determined that no further action is necessary and no hazard was identified CERCLIS Alias Name(s): DEVOE AND RAYNOLDS CO.,INC.		
184	IND CHEM & SUPPLY CO 3520 ADAMO DR TAMPA, FL 33677	FINDS	1000733182 FLD032783003
	Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production		
184	IND CHEM & SUP CO 3520 ADAMO DR TAMPA, FL 33605	FINDS UST	1000502072 FLD984222216
	UST: Facility ID: 298627232 Is fac. regulated: Not regulated facility Operator: INDUSTRIAL CHEMICAL & SUPPLY Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 861029 Tank ID: 1 Owner's Contact: ANDY Owner: INDUSTRIAL CHEMICAL & SUPPLY 3520 ADAMO DR TAMPA, FL 336055828 Owner's Phone: 8138371646 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00002000 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Auto sample wells Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132477354 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 297406 Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: 66/XX Content Category: Vehicular Last used Date: 89/11 RPT by Tank #: Not reported		
184	3520 ADAMO DR TAMPA, FL	HMIRS	91090588 N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
184	INDUSTRIAL CHEMICAL & SUPPLY 3520 ADAMO DRIVE TAMPA, FL 33675 RCRIS: Not Reported	RCRIS-SQG LUST	1000698743 FLD032783003
184	ROLLINS LEASING CORP #363 1201 N 34TH ST TAMPA, FL 19803 RCRIS: Not Reported	RCRIS-SQG LUST	1000699288 FLD163283443
184	ROLLINS LEASING CORP #363 1201 N 34TH ST TAMPA, FL 33605 UST: Facility ID: 298625768 Is fac. regulated: Regulated facility Operator: DAVE RAETZ Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860523 Tank ID: 1 Owner's Contact: RALPH E GRANT Owner: ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 198990000 Owner's Phone: 3024262899 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00006000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	UST AST	U001354971 N/A
	Facility Type: Non-retail Business Is facility open: Open Facility Phone: 8132473411 Region: Not reported Financial responsibility: State PRGM (Self/Other) District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 72/XX Content Category: Vehicular Last used Date: 91/11 RPT by Tank #: Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ROLLINS LEASING CORP #363 (Continued)

U001354971

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 198990000		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 198990000		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ROLLINS LEASING CORP #363 (Continued)

U001354971

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 198990000		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 198990000		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	80/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ROLLINS LEASING CORP #363 (Continued)

U001354971

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	6	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 198990000		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Contact:	Not reported	Facility Phone:	8132473411
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	7	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP PO BOX 1791 WILMINGTON, DE 198990000		
Owner's Phone:	3024262899	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	72/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ROLLINS LEASING CORP #363 (Continued)

U001354971

AST:

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Facility Phone:	8132473411	Permit Section:	00000
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	8	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 198990000		
Owner's Phone:	3024262899	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-flow shut off		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Auto tank gauging		

Facility ID:	298625768	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	DAVE RAETZ		
Facility Phone:	8132473411	Permit Section:	00000
Date entered:	860523	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	9	District:	Southwest
Owner's Contact:	RALPH E GRANT		
Owner:	ROLLINS LEASING CORP		
	PO BOX 1791		
	WILMINGTON, DE 198990000		
Owner's Phone:	3024262899	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/02
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Spill cnmt, Op-flow shut off		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	GW monitoring		

184

SAUNDERS SYSTEM INC
1201 N 34TH ST
TAMPA, FL 33605

RCRIS-LQG 1000310694
FLD981752223

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SAUNDERS SYSTEM INC (Continued)

1000310694

RCRIS:

Owner: RYDER TRUCK RENTAL

Contact: BILL STACY
(813) 247-4753

Waste	Quantity	Info Source
-------	----------	-------------

F001	.00000 (N)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

184 SAUNDERS SYSTEM INC
1201 N 34TH ST
TAMPA, FL 33605

FINDS

1000733837
FLD163283443

185 PRODUCTION BLAST
610 HARBOR STREET
TAMPA, FL 33605

FINDS

RCRIS-LQG

1000501413
FLD984215418

RCRIS:

Owner: DANA NEER
(813) 225-1136

Contact: DANA NEER
(813) 225-1136

Waste	Quantity	Info Source
-------	----------	-------------

F003	.00000 (T)	Notification
------	------------	--------------

Waste	Quantity	Info Source
-------	----------	-------------

F005	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

There are 1 compliance/violation record(s) reported at this site:

Evaluation	Date	Violations
COMPLIANCE EVALUATION INSPECTION (CEI)	17-MAY-93	YES

185 SCAGLIONE PROPERTY-ESTUARY SUBDIVISION
704 N 13TH ST
TAMPA, FL 33602

UST
LUST

U001355957
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

LUST:

Facility ID:	8942924	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8139682959	Alias Name 1:	Not reported
Discovery Date:	12/29/88	Alias Name 2:	Not reported
Tracking Number:	298097	Alias Name 3:	Not reported
Score:	011 (LOW)	Alias Name 4:	Not reported
Rank:	06640	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: GENERIC GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: RESPONSIBLE PARTY

Soil Removal: Y

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

UST:

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE 7619 LAKE CYPRESS DR ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE 7619 LAKE CYPRESS DR ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE 7619 LAKE CYPRESS DR ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE 7619 LAKE CYPRESS DR ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE 7619 LAKE CYPRESS DR ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE 7619 LAKE CYPRESS DR ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SCAGLIONE PROPERTY-ESTUARY SUBDIVISION (Continued)

U001355957

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE 7619 LAKE CYPRESS DR ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298942924	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SCAGLIONE,ANDY JOE		
Contact:	Not reported	Facility Phone:	8139682959
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890125	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	ANDY JOE SCAGLIONE		
Owner:	SCAGLIONE, ANDY JOE 7619 LAKE CYPRESS DR ODESSA, FL 335562751		
Owner's Phone:	8139682959	Tracking #:	298097
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

186

RECHEM TRANSPORT CORP
 1301 NORTH ROME AVENUE
 TAMPA, FL 33617

RCRIS-SQG 1000687747
 FLD991304619

RCRIS: Not Reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
186	RECHEM TRANSP CORP 1301 N ROME AVE TAMPA, FL 33617	FINDS	1000931530 FL0000260729
186	SCHLICHTE PROPERTY 1301 N ROME AVE TAMPA, FL 33607	UST	U001823399 N/A
	UST:		
	Facility ID: 299400491	Facility Type: Non-retail Business	
	Is fac. regulated: Not regulated facility	Is facility open: Closed	
	Operator: MRS SCHLICHTE		
	Contact: Not reported	Facility Phone: 8138371646	
	Permit Section: Not reported	Region: Not reported	
	Facility Code: No violation		
	Date entered: 940405	Financial responsibility: Not reported	
	Tank ID: 1	District: Southwest	
	Owner's Contact: FRED W. SCHLICHTE		
	Owner: SCHLICHTE, FRED W 5122 W POE AVE TAMPA, FL 336297527		
	Owner's Phone: 8138371646	Tracking #: Not reported	
	Cleanup Status: Not reported	Any contaminated soil: Not reported	
	Drink. Wat. Well: Not reported	Any contaminated surface water: Not reported	
	Tank Cap. (Gals): 00001000	Any monit. wells: Not reported	
	Tank position: Not reported	Any contam. groundwater: Not reported	
	Tank Content: Not reported	Contaminated media indicator: Not reported	
	Disposal Method: Removed	Install. Date: Not reported	
	Is tank regulated: Not regulated tank	Content Category: Vehicular	
	Facility Status: Not reported	Last used Date: 91/12	
	RPT Tank #: Not reported	RPT by Tank #: Not reported	
	Tank Constr.: Not reported		
	Tank Piping: Not reported		
	Petro. Monitoring: Unknown/not reported		
187	DETSCO TERMINACS, INC. 739 N 14TH ST TAMPA, FL 33602	LUST AST	U001354325 N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	DETSKO TERMINACS, INC. (Continued)		U001354325
	AST: Facility ID: 298625085 Is fac. regulated: Not regulated facility Operator: DETSCO TERMINACS, INC. Facility Phone: 8132291184 Date entered: 860508 Tank ID: 1 Owner's Contact: J.D. WILSON Owner: DETSCO TERMINACS INC PO BOX 437 MULBERRY, FL 338600437 Owner's Phone: 8132291184 Drink. Wat. Well: 0000 Cleanup Status: Ongoing Tank position: Aboveground Tank Content: Unleaded gas Disposal Method: Removed Is tank regulated: Not regulated tank Last used Date: 91/08 RPT Tank #: Not reported Tank Constr.: Unknown/not reported Tank Piping: Abvgnd-no contact w/soil Petro. Monitoring: Not required Facility Type: Non-retail Business Is facility open: Closed Permit Section: 00000 Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: No Tank Cap. (Gals): 00001500 Contaminated media indicator: No Install. Date: Not reported Content Category: Vehicular Any contaminated groundwater: No RPT by Tank #: Not reported		
187	DETSKO TERMINALS INC 739 N 14TH ST TAMPA, FL 33602 Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	FINDS UST	1000733227 FLD040214710
187	DETSKO TERMINALS INC 739 NORTH 14TH STREET TAMPA, FL 33601 RCRIS: Not Reported	RCRIS-SQG	1000698780 FLD040214710
188	TAMPA INTERNATIONAL CENTER 1103 N 22ND ST TAMPA, FL 33605	UST LUST	U001356097 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA INTERNATIONAL CENTER (Continued)

U001356097

LUST:

Facility ID:	9045667	Facility Type:	NON-RETAIL BUSINESS
Telephone:	0000000000	Alias Name 1:	Not reported
Discovery Date:	01/24/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	DIESEL FUEL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA INTERNATIONAL CENTER (Continued)

U001356097

UST:

Facility ID:	299045667	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NATIONAL PROPERTY ADVISORS CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900119	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MICHAEL GROVER		
Owner:	NATIONAL LIFE INSURANCE CO		
	100 GALLERIA PKWY #1620		
	ATLANTA, GA 303395948		
Owner's Phone:	4049889008	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299045667	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	NATIONAL PROPERTY ADVISORS CORP		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900119	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MICHAEL GROVER		
Owner:	NATIONAL LIFE INSURANCE CO		
	100 GALLERIA PKWY #1620		
	ATLANTA, GA 303395948		
Owner's Phone:	4049889008	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	TAMPA INTERNATIONAL CENTER (Continued)		U001356097
	Facility ID: 299045667 Is fac. regulated: Not regulated facility Operator: NATIONAL PROPERTY ADVISORS CORP Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 900119 Tank ID: 3 Owner's Contact: MICHAEL GROVER Owner: NATIONAL LIFE INSURANCE CO 100 GALLERIA PKWY #1620 ATLANTA, GA 303395948 Owner's Phone: 4049889008 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000888 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: Not reported Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: Not reported Content Category: Vehicular Last used Date: 90/01 RPT by Tank #: Not reported	
188	WILLIAMS TELECOMMUNICATIONS GROUP 1103 N 22ND ST TAMPA, FL 33605	UST	U001355304 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

WILLIAMS TELECOMMUNICATIONS GROUP (Continued)

U001355304

UST:

Facility ID:	298627972	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MILLER, JACK		
Contact:	Not reported	Facility Phone:	8132482862
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM RUPINSKI		
Owner:	WILLIAMS TELECOMMUNICATION GROUP		
	PO BOX 21348		
	TULSA, OK 741211348		
Owner's Phone:	9185885610	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	84/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required, Auto tank gauging		

Facility ID:	298627972	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MILLER, JACK		
Contact:	Not reported	Facility Phone:	8132482862
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1R1	District:	Southwest
Owner's Contact:	JIM RUPINSKI		
Owner:	WILLIAMS TELECOMMUNICATION GROUP		
	PO BOX 21348		
	TULSA, OK 741211348		
Owner's Phone:	9185885610	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	89/04
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, DW tank space, Not required, DW piping space, Auto tank gauging		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
188	AMERICAN FRAME & AXLE INC 1011 NO 21ST STREET TAMPA, FL 33605 RCRIS: Not Reported	RCRIS-SQG FINDS	1000359135 FLD044171015
189	SOUTHEASTERN BOLT & SCREW 815 N 26TH ST TAMPA, FL 33605 UST: Facility ID: 298625702 Is fac. regulated: Not regulated facility Operator: SOUTHEASTERN BOLT & SCREW Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860523 Tank ID: 1 Owner's Contact: MIKE SILCOTT Owner: J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439 Owner's Phone: 8132287776 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00001000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	UST 	

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	BULK INTERMODAL DISTRIBUTION SVC (Continued)		1000906166
	There are 1 compliance/violation record(s) reported at this site:		
	Evaluation	Date	Violations
	COMPLIANCE EVALUATION INSPECTION (CEI)	09-MAY-94	YES
190	TDSI-BIDS TAMPA 504 NORTH 34TH STREET TAMPA, FL 33605	FINDS	1000740043 FLD984253534
190	1ST RECOVERY 504A N 34TH ST TAMPA, FL 33675	RCRIS-SQG FINDS	1000687633 FLD984239061
	RCRIS:		
	Owner: BULK INTERMODAL DIST CTR (615) 267-5727		
	Contact: CURTIS HUCKABY (615) 267-5727		
	Waste	Quantity	Info Source
	D000	.00000 (T)	Notification
	D007	.00000 (T)	Notification
	D018	.00000 (T)	Notification
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported		
190	TDSI BIDS TAMPA 504 N 34TH ST TAMPA, FL 33675	RCRIS-SQG	1000822327 FLD984253534
	RCRIS: Not Reported		
191	USE 299045730 1112 N FLORIDA AVE TAMPA, FL 33602	UST LUST	U001355893 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

USE 299045730 (Continued)

U001355893

LUST:

Facility ID:	8842270	Facility Type:	RETAIL STATION
Telephone:	Not reported	Alias Name 1:	TELANDER'S STATION
Discovery Date:	01/08/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		TANK REMOVAL

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 299045730 (Continued)

U001355893

UST:

Facility ID:	298842270	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TELANDER'S,INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881207	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER'S,INC		
	1101 RAVENWOOD DR		
	VALRICO, FL 335942946		
Owner's Phone:	8136858340	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	65/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		
Facility ID:	298842270	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TELANDER'S,INC		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881207	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER'S,INC		
	1101 RAVENWOOD DR		
	VALRICO, FL 335942946		
Owner's Phone:	8136858340	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			USE 299045730 (Continued)			U001355893
			Facility ID: 298842270 Is fac. regulated: Not regulated facility Operator: TELANDER'S,INC Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 881207 Tank ID: 3 Owner's Contact: DON TELANDER Owner: TELANDER'S,INC 1101 RAVENWOOD DR VALRICO, FL 335942946 Owner's Phone: 8136858340 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00004000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Retail Station Is facility open: Closed Facility Phone: Not reported Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: 64/XX Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported		
191			AUTOBOND IMPORTS 1112 N FLORIDA AVE TAMPA, FL 33602	UST LUST	U001356103	N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

AUTOBOND IMPORTS (Continued)

U001356103

UST:

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

AUTOBOND IMPORTS (Continued)

U001356103

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

AUTOBOND IMPORTS (Continued)

U001356103

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299045730	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AUTOBOND IMPORTS		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900125	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	DON TELANDER		
Owner:	TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946		
Owner's Phone:	8136852906	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	64/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	AUTOBOND IMPORTS (Continued)		U001356103
	<div> <div> Facility ID: 299045730 Is fac. regulated: Not regulated facility Operator: AUTOBOND IMPORTS Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 900125 Tank ID: 7 Owner's Contact: DON TELANDER Owner: TELANDER WANDA E 1101 RAVENWOOD DR VALRICO, FL 335942946 Owner's Phone: 8136852906 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000550 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not required </div> <div> Facility Type: Retail Station Is facility open: Closed Facility Phone: Not reported Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 64/XX Content Category: Pollutant Last used Date: 89/12 RPT by Tank #: Not reported </div> </div>		
192	TAMPA,CITY-ROYAL ST PARKING LOT ROYAL ST / TAMPA ST TAMPA, FL	UST LUST	U001378004 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

LUST:

Facility ID:	8841046	Facility Type:	LOCAL, CITY GOVERNMENT
Telephone:	0000000000	Alias Name 1:	Not reported
Discovery Date:	09/29/87	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: LEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: RESPONSIBLE PARTY

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

UST:

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS 1601 N MARION ST TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS 1601 N MARION ST TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS		
	1601 N MARION ST		
	TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS		
	1601 N MARION ST		
	TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS		
	1601 N MARION ST		
	TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS		
	1601 N MARION ST		
	TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-ROYAL ST PARKING LOT (Continued)

U001378004

Facility ID:	298841046	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880726	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	JOE CHANEY		
Owner:	TAMPA,CITY-PUBLIC WORKS		
	1601 N MARION ST		
	TAMPA, FL 336022638		
Owner's Phone:	8132238733	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

193 TAMPA ELECTRIC CO.-CASS ST
1214 E CASS ST
TAMPA, FL 33602

UST
LUST

U001355722
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA ELECTRIC CO.-CASS ST (Continued)

U001355722

LUST:

Facility ID:	8837435	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132284111	Alias Name 1:	Not reported
Discovery Date:	07/15/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	042	Alias Name 4:	Not reported
Rank:	02299	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS
Pollutant 2:	Not reported
Pollutant 3:	Not reported

Est. Gallons Lost:	00001575
Est. Gallons Lost:	00000000
Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

PETRO. LIABILITY INS. & RESTOR.

REIMBURSEMENT CLEANUP

ELIGIBLE

Not Reported

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: STATE

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

INCOMPLETE

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

RESPONSIBLE PARTY

REMEDIAL ACTION PLAN

GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

RESPONSIBLE PARTY

00

00

QUARTERLY

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Flag:

SITE REHABILITATION COMPLETION REPORT

Not reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	TAMPA ELECTRIC CO.-CASS ST (Continued)		U001355722
	UST: Facility ID: 298837435 Is fac. regulated: Not regulated facility Operator: TAMPA ELECTRIC CO. Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 880112 Tank ID: 1 Owner's Contact: BILL GOINS Owner: TAMPA ELECTRIC CO PO BOX 111 % ENVIR PLANNING TAMPA, FL 336010111 Owner's Phone: 8132281111 Cleanup Status: Completed Drink. Wat. Well: 0000 Tank Cap. (Gals): 00010000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: DW tank space, DW piping space	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132284111 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 88/01 Content Category: Vehicular Last used Date: 92/04 RPT by Tank #: Not reported	
194	HENDERSON PROPERTY 1111 E CASS ST TAMPA, FL 33602	UST	U001823417 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HENDERSON PROPERTY (Continued)

U001823417

UST:

Facility ID:	299400587	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BETTY HENDERSON		
Contact:	Not reported	Facility Phone:	8132287551
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940407	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BETTY HENDERSON		
Owner:	HENDERSON, BETTY 3704 LEONA ST TAMPA, FL 336290000		
Owner's Phone:	8132287551	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

Facility ID:	299400587	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BETTY HENDERSON		
Contact:	Not reported	Facility Phone:	8132287551
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940407	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BETTY HENDERSON		
Owner:	HENDERSON, BETTY 3704 LEONA ST TAMPA, FL 336290000		
Owner's Phone:	8132287551	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HENDERSON PROPERTY (Continued)

U001823417

Facility ID:	299400587	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BETTY HENDERSON		
Contact:	Not reported	Facility Phone:	8132287551
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940407	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BETTY HENDERSON		
Owner:	HENDERSON, BETTY 3704 LEONA ST TAMPA, FL 336290000		
Owner's Phone:	8132287551	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

195	THORNTON LABORATORIES INC 1145 E CASS TAMPA, FL 33602 RCRIS: Not Reported	RCRIS-SQG FINDS	1000365501 FLD045000346
196	AFFILIATED OF FLORIDA INC 1102 N 28TH ST TAMPA, FL 33631 RCRIS: Not Reported	RCRIS-SQG FINDS	1000498457 FLD982077984
196	AFFILIATED OF FL, INC.-J.H.WILLIAMS 1102 N 28TH ST TAMPA, FL 33605	UST	U001354686 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

UST:

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	81/11
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	67/10
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	61/07
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	62/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

AFFILIATED OF FL, INC.-J.H.WILLIAMS (Continued)

U001354686

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	73/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625468	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	AFFILIATED OF FL, INC.		
Contact:	Not reported	Facility Phone:	8132485781
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	79/08
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	88/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

197 TAMPA CITY-DPW STORE USE #298625662
612 N 12TH ST
TAMPA, FL 33602

UST

U001355537
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA CITY-DPW STORE USE #298625662 (Continued)

U001355537

UST:

Facility ID:	298735278	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238013
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870922	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 N CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

197 TAMPA,CITY-DPW FLEET MAINT DIV #1
612 N 12TH ST
TAMPA, FL 33607

UST
LUST

U001354868
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

LUST:

Facility ID:	8625662	Facility Type:	LOCAL, CITY GOVERNMENT
Telephone:	8132238696	Alias Name 1:	Not reported
Discovery Date:	04/20/95	Alias Name 2:	Not reported
Tracking Number:	292525	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

UST:

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 N CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	10	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 N CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	2	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	3	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	83/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	4	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	5	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	6	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	7	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-DPW FLEET MAINT DIV #1 (Continued)

U001354868

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	8	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625662	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TAMPA,CITY-FLEET MAINTENANCE		
Contact:	Not reported	Facility Phone:	8132238696
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	9	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292525
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	58/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

197
JOBBER'S SUPPLY OF FLORIDA INC
629 N 12TH ST
TAMPA, FL 33602

RCRIS-SQG 1000162651
FINDS FLD982077190

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

JOBBER'S SUPPLY OF FLORIDA INC (Continued)

1000162651

RCRIS:

Owner: JOHN WOLFE, SEC
(813) 223-3288

Contact: JOHN WOLFE
(813) 223-3288

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
F001	.00000 (T)	Notification	F002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

198

CONNER PROPERTIES SERVICE STATION
715 E CASS ST
TAMPA, FL 33602

UST

U001354408
N/A

UST:

Facility ID:	298625171	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLIAM G. FURNEY		
Owner:	CONNER PROPERTIES		
	PO BOX 2522		
	TAMPA, FL 336012522		
Owner's Phone:	8132476458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CONNER PROPERTIES SERVICE STATION (Continued)

U001354408

Facility ID:	298625171	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLIAM G. FURNEY		
Owner:	CONNER PROPERTIES PO BOX 2522 TAMPA, FL 336012522		
Owner's Phone:	8132476458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

Facility ID:	298625171	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLIAM G. FURNEY		
Owner:	CONNER PROPERTIES PO BOX 2522 TAMPA, FL 336012522		
Owner's Phone:	8132476458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CONNER PROPERTIES SERVICE STATION (Continued)

U001354408

Facility ID:	298625171	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	WILLIAM G. FURNEY		
Owner:	CONNER PROPERTIES PO BOX 2522 TAMPA, FL 336012522		
Owner's Phone:	8132476458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000250	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

Facility ID:	298625171	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	WILLIAM G. FURNEY		
Owner:	CONNER PROPERTIES PO BOX 2522 TAMPA, FL 336012522		
Owner's Phone:	8132476458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000250	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

199

SEABOARD PARTS DISTRIBUTOR
1105 E TWIGGS
TAMPA, FL 33602

RCRIS-SQG 1000821872
FINDS FLD984248906

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SEABOARD PARTS DISTRIBUTOR (Continued)

1000821872

RCRIS:

Owner: DOROTHY SLAIMAN, OWNER
(813) 221-5566

Contact: DOROTHY SLAIMAN
(813) 221-5566

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D006	.00000 (T)	Notification	D007	.00000 (T)	Notification
D008	.00000 (T)	Notification	D018	.00000 (T)	Notification
D039	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

199

TYRESOLER OF TAMPA, INC.
1127 E TWIGGS ST
TAMPA, FL 33602

UST

U001355328
N/A

UST:

Facility ID:	298628060	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	W. L. GRIFFIN		
Contact:	Not reported	Facility Phone:	8132298444
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	W. L. GRIFFIN		
Owner:	TYRESOLER OF TAMPA, INC. 1127 E TWIGGS ST TAMPA, FL 336023135		
Owner's Phone:	8132298444	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	69/02
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

199

LIVINGSTONS BUSINESS FURNITURE CENTER
1123 E TWIGGS ST
TAMPA, FL 33602

UST
LUST

U001354621
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LIVINGSTONS BUSINESS FURNITURE CENTER (Continued)

U001354621

LUST:

Facility ID:	8625401	Facility Type:	NON-RETAIL BUSINESS
Telephone:	Not reported	Alias Name 1:	Not reported
Discovery Date:	12/20/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	05554	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

ABANDONED TANK RESTORATIO
LOCAL PROGRAM
NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: VEHIC DIESEL

Pollutant 2: GENERIC GAS

Pollutant 3: Not reported

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

ABANDONED TANK RESTORATION
REIMBURSEMENT CLEANUP
ELIGIBLE
Not Reported
Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY
CONTAMINATION ASSESSMENT REPORT
Not reported
INCOMPLETE
Not reported
Not reported
Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Flag:

NO FURTHER ACTION

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

LIVINGSTONS BUSINESS FURNITURE CENTER (Continued)

U001354621

UST:

Facility ID:	298625401	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LIVINGSTONS BUSINESS FURNITURE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860519	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ARTHUR STUCKEY		
Owner:	STUCKEY, ARTHUR 420 MONTROSE AVE TEMPLE TERRACE, FL 336174238		
Owner's Phone:	8139855764	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625401	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LIVINGSTONS BUSINESS FURNITURE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860519	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ARTHUR STUCKEY		
Owner:	STUCKEY, ARTHUR 420 MONTROSE AVE TEMPLE TERRACE, FL 336174238		
Owner's Phone:	8139855764	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

200 J H WILLIAMS OIL CO INC-MAIN BULK PLT
1237 E TWIGGS ST
TAMPA, FL 33602

LUST
AST S101264745
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

J H WILLIAMS OIL CO INC-MAIN BULK PLT (Continued)

S101264745

LUST:

Facility ID:	8736356	Facility Type:	INLAND BULK PETROLEUM
Telephone:	8132287776	Alias Name 1:	Not reported
Discovery Date:	04/20/92	Alias Name 2:	Not reported
Tracking Number:	297429	Alias Name 3:	Not reported
Score:	105 (HIGH)	Alias Name 4:	Not reported
Rank:	01186	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

PLIRP (INSURANCE)

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: KEROSENE

Est. Gallons Lost: UNKNOWN

Pollutant 2: FUEL OIL-ON SITE

Est. Gallons Lost: UNKNOWN

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

PETRO. LIABILITY INS. & RESTOR.

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

LOCAL PROGRAM

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

CONTAMINATION ASSESSMENT REPORT

Extension Status:

APPROVED

Extension Comments:

LIMITED CAR

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

LOCAL PROGRAM

Estimated Completion Year:

00

Actual Year to Complete:

00

Report Type:

REC DRAW

Report Comments:

PHASE 1 - VAPORS

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

J H WILLIAMS OIL CO INC-MAIN BULK PLT (Continued)

S101264745

AST:

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	00000
Date entered:	871123	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00020000
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	00000
Date entered:	871123	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00020000
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

J H WILLIAMS OIL CO INC-MAIN BULK PLT (Continued)

S101264745

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	00000
Date entered:	871123	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00018000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	00000
Date entered:	871123	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC		
	PO BOX 439		
	TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00018000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

J H WILLIAMS OIL CO INC-MAIN BULK PLT (Continued)

S101264745

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	00000
Date entered:	871123	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00018000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	00000
Date entered:	871123	Financial responsibility:	None
Tank ID:	6	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00018000
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

J H WILLIAMS OIL CO INC-MAIN BULK PLT (Continued)

S101264745

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	00000
Date entered:	871123	Financial responsibility:	None
Tank ID:	7	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00018000
Tank Content:	Other	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

Facility ID:	298736356	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ELMER L SINGLETARY EXT 115		
Facility Phone:	8132287776	Permit Section:	00000
Date entered:	871123	Financial responsibility:	None
Tank ID:	8	District:	Southwest
Owner's Contact:	MIKE SILCOTT		
Owner:	J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439		
Owner's Phone:	8132287776	Tracking #:	297429
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00018000
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/03
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-tight fill, Field erected		
Tank Piping:	Unprotec metal, Fiberglass, Dblwall=primary matl, Pressurized piping, Bulk product piping		
Petro. Monitoring:	Auto sample wells, Man sample wells, Man tank gauging		

201 AIR DROME TIRE
612 E CASS ST
TAMPA, FL 33602

UST

U001354064
N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	AIR DROME TIRE (Continued)		U001354064
	UST: Facility ID: 298624801 Is fac. regulated: Not regulated facility Operator: AIR DROME TIRE Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860505 Tank ID: 1 Owner's Contact: MIKE SILCOTT Owner: J H WILLIAMS OIL CO INC PO BOX 439 TAMPA, FL 336010439 Owner's Phone: 8132287776 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00001000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132290631 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: 64/06 Content Category: Hazardous/other Last used Date: Not reported RPT by Tank #: Not reported	
202	SUN BANK PROPERTY 605 N 19TH ST TAMPA, FL 33605	UST LUST	U001354360 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SUN BANK PROPERTY (Continued)

U001354360

LUST:

Facility ID:	8625122	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132482151	Alias Name 1:	Not reported
Discovery Date:	08/02/89	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	081 (HIGH)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	PARTIAL
Incident Ineligible Reason:	OTHER
Incident Ineligible Description:	OTHER

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment: Y	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SUN BANK PROPERTY (Continued)

U001354360

UST:

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA 315 E MADISON TAMPA, FL 336020000		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	79/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA 315 E MADISON TAMPA, FL 336020000		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SUN BANK PROPERTY (Continued)

U001354360

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA 315 E MADISON TAMPA, FL 336020000		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA 315 E MADISON TAMPA, FL 336020000		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SUN BANK PROPERTY (Continued)

U001354360

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA 315 E MADISON TAMPA, FL 336020000		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	82/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625122	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNKNOWN		
Contact:	Not reported	Facility Phone:	8132482151
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	BARBARA ZELLMER		
Owner:	SUN BANK OF TAMPA 315 E MADISON TAMPA, FL 336020000		
Owner's Phone:	8132242439	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

203

SWIFT ADHESIVES AND COATINGS
605 N 26TH ST
TAMPA, FL 33605

RCRIS-SQG 1000230730
FINDS FLD064687577
CERC-NFRAP
UST

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SWIFT ADHESIVES AND COATINGS (Continued)

1000230730

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported
Ownership Status: OTHER
EPA Notes: Not reported

Federal Facility: NO
NPL Status: NOT ON NPL

CERCLIS-NFRAP Assessment History:

Assessment: PRELIMINARY ASSESSMENT
Assessment: DISCOVERY
Assessment: SCREENING SITE INSPECTION

Completed: 11/01/82
Completed: 08/01/80
Completed: 01/25/91

CERCLIS-NFRAP Alias Name(s):

SWIFT ADHESIVES & COATINGS

RCRIS: Not Reported

UST:

Facility ID: 298944024
Is fac. regulated: Not regulated facility
Operator: SWIFT ADHESIVES
Contact: Not reported
Permit Section: Not reported
Facility Code: No violation
Date entered: 890503
Tank ID: 1
Owner's Contact: JOHN W KNAUB
Owner: REICHHOLD

Facility Type: Non-retail Business
Is facility open: Closed

Facility Phone: Not reported
Region: Not reported

Financial responsibility: Not reported
District: Southwest

3100 WOODCREEK DR
DOWNERS GROVE, IL 605155424

Owner's Phone: 3129607254
Cleanup Status: Not reported
Drink. Wat. Well: Not reported
Tank Cap. (Gals): 00001500
Tank position: Not reported
Tank Content: Not reported
Disposal Method: Removed
Is tank regulated: Not regulated tank
Facility Status: Not reported
RPT Tank #: Not reported
Tank Constr.: Not reported
Tank Piping: Not reported
Petro. Monitoring: Unknown/not reported

Tracking #: Not reported
Any contaminated soil: Not reported
Any contaminated surface water: Not reported
Any monit. wells: Not reported
Any contam. groundwater: Not reported
Contaminated media indicator: Not reported
Install. Date: 58/XX
Content Category: Pollutant
Last used Date: 85/XX
RPT by Tank #: Not reported

203

SWIFT ADHESIVES & COATINGS
605 N. 26 ST.
TAMPA, FL 33605

FI Sites

S100889047
N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

SWIFT ADHESIVES & COATINGS (Continued)

S100889047

FL Sites:

Facility ID:	000386	EPA ID:	FLD064687577
Facility District:	SOUTHWEST	Monthly Update:	February
Lead Unit:	Not reported	Support Unit:	3012
Air Contam:	Not reported	Soil Contam:	Not reported
Surface Water Contam:	Not reported	Ground Water Contam:	Not reported
Cleanup Started ?:	No	Cleanup Completed ?:	No
Deletion Recommended ?:	No	Other:	Not reported
Warning Letter Status:	Not reported	Notice of Violation Status:	No
Consent Order Status:	No	Admin Hearing Status:	No
Court Status:	No	Final Order Status:	No
Comments:	EPA PRELIMINARY ASSESSMENT COMPLETED 11-82. EPA/CERCLA SITE SCREENING CATEGORIZATION REVIEW COMPLETED 11/87 RESULTED IN A MEDIUM PRIORITY DETERMINATION FOR SITE SCREENING INVESTIGATION. EPA/FDER INVESTIGATION TO BE SCHEDULED ON A PRIORITY BASIS.		

204

UNITED AUTO CLINIC INC
1002 N HOWARD AVE
TAMPA, FL 33607

UST
LUST

U001354098
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED AUTO CLINIC INC (Continued)

U001354098

LUST:

Facility ID:	8624839	Facility Type:	RETAIL STATION
Telephone:	8132544459	Alias Name 1:	UNITED AUTO SERVICE
Discovery Date:	09/23/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NONCOMPLAINEE 17-769 RULE
Incident Ineligible Description:	NONCOMPLIANCE 1

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED AUTO CLINIC INC (Continued)

U001354098

UST:

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	MURRAY, HUBERT & TULAH 1002 N HOWARD AVE TAMPA, FL 336075318		
Owner's Phone:	8132544459	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	MURRAY, HUBERT & TULAH 1002 N HOWARD AVE TAMPA, FL 336075318		
Owner's Phone:	8132544459	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

UNITED AUTO CLINIC INC (Continued)

U001354098

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	MURRAY, HUBERT & TULAH 1002 N HOWARD AVE TAMPA, FL 336075318		
Owner's Phone:	8132544459	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	MURRAY, HUBERT & TULAH 1002 N HOWARD AVE TAMPA, FL 336075318		
Owner's Phone:	8132544459	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

UNITED AUTO CLINIC INC (Continued)

U001354098

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	MURRAY, HUBERT & TULAH 1002 N HOWARD AVE TAMPA, FL 336075318		
Owner's Phone:	8132544459	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	69/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624839	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	MURRAY, HUBERT & TULAH		
Contact:	Not reported	Facility Phone:	8132544459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	HUBERT MURRAY		
Owner:	MURRAY, HUBERT & TULAH 1002 N HOWARD AVE TAMPA, FL 336075318		
Owner's Phone:	8132544459	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			UNITED AUTO CLINIC INC (Continued)			U001354098
			Facility ID: 298624839 Is fac. regulated: Regulated facility Operator: MURRAY, HUBERT & TULAH Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860506 Tank ID: 7 Owner's Contact: HUBERT MURRAY Owner: MURRAY, HUBERT & TULAH 1002 N HOWARD AVE TAMPA, FL 336075318 Owner's Phone: 8132544459 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00001000 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells	Facility Type: Retail Station Is facility open: Open Facility Phone: 8132544459 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Pollutant Last used Date: 92/09 RPT by Tank #: Not reported		
205			ELLIS CONSTRUCTION CO INC 1714 W CYPRESS ST TAMPA, FL 33606	UST LUST		U001356132 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ELLIS CONSTRUCTION CO INC (Continued)

U001356132

LUST:

Facility ID:	9046106	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132518473	Alias Name 1:	Not reported
Discovery Date:	08/13/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	030	Alias Name 4:	Not reported
Rank:	04434	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

ABANDONED TANK RESTORATIO

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	ELLIS CONSTRUCTION CO INC (Continued)		U001356132
	UST: Facility ID: 299046106 Is fac. regulated: Not regulated facility Operator: ELLIS, GILBERT Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 900403 Tank ID: 1 Owner's Contact: GILBERT ELLIS Owner: ELLIS, GILBERT PO BOX 1132 TAMPA, FL 336011132 Owner's Phone: 8132518473 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000888 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132518473 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Vehicular Last used Date: 90/07 RPT by Tank #: Not reported	
206	GRAYBAR ELECTRIC CO INC 1502 W CYPRESS ST TAMPA, FL 33606	UST	U001355507 N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	GRAYBAR ELECTRIC CO INC (Continued)		U001355507
	UST: Facility ID: 298733895 Is fac. regulated: Not regulated facility Operator: GRAYBAR ELECTRIC CO INC Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 870730 Tank ID: 1 Owner's Contact: C E JENKINS Owner: GRAYBAR ELECTRIC CO INC 801 N ROME AVE TAMPA, FL 336061037 Owner's Phone: 8132538881 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000500 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not required Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132538881 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Vehicular Last used Date: 86/07 RPT by Tank #: Not reported		
207	CASTELLANO PROPERTY 512 E CASS ST TAMPA, FL 33602	UST LUST	U001356301 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CASTELLANO PROPERTY (Continued)

U001356301

LUST:

Facility ID:	9101375	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8139497776	Alias Name 1:	Not reported
Discovery Date:	02/26/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	021 (LOW)	Alias Name 4:	Not reported
Rank:	05558	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CASTELLANO PROPERTY (Continued)

U001356301

UST:

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CASTELLANO PROPERTY (Continued)

U001356301

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299101375	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	CASTELLANO, NANCY		
Contact:	Not reported	Facility Phone:	8139497776
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910401	Financial responsibility:	None
Tank ID:	6	District:	Southwest
Owner's Contact:	NANCY CASTELLANO		
Owner:	CASTELLANO, JOHN & NANCY		
	PO BOX 1526		
	LUTZ, FL 335491526		
Owner's Phone:	8139497776	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

208 PIONEER AUTO SERVICE CENTER INC
1004 N TAMPA ST
TAMPA, FL 33602

UST

U001354493
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

PIONEER AUTO SERVICE CENTER INC (Continued)

U001354493

UST:

Facility ID:	298625262	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BARR JOHN		
Contact:	Not reported	Facility Phone:	8132297772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RON MOORE		
Owner:	MOORE PROPERTIES INC PO BOX 406 TAMPA, FL 336010406		
Owner's Phone:	8138753434	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	71/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625262	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BARR JOHN		
Contact:	Not reported	Facility Phone:	8132297772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	RON MOORE		
Owner:	MOORE PROPERTIES INC PO BOX 406 TAMPA, FL 336010406		
Owner's Phone:	8138753434	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	71/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

PIONEER AUTO SERVICE CENTER INC (Continued)

U001354493

Facility ID:	298625262	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BARR JOHN		
Contact:	Not reported	Facility Phone:	8132297772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	RON MOORE		
Owner:	MOORE PROPERTIES INC PO BOX 406 TAMPA, FL 336010406		
Owner's Phone:	8138753434	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	71/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625262	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BARR JOHN		
Contact:	Not reported	Facility Phone:	8132297772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	RON MOORE		
Owner:	MOORE PROPERTIES INC PO BOX 406 TAMPA, FL 336010406		
Owner's Phone:	8138753434	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000400	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

PIONEER AUTO SERVICE CENTER INC (Continued)

U001354493

Facility ID:	298625262	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BARR JOHN		
Contact:	Not reported	Facility Phone:	8132297772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	B	District:	Southwest
Owner's Contact:	RON MOORE		
Owner:	MOORE PROPERTIES INC		
	PO BOX 406		
	TAMPA, FL 336010406		
Owner's Phone:	8138753434	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	71/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

208	PIONEER AUTO SERVICE CENTER 1004 N TAMPA ST TAMPA, FL 33602	RCRIS-SQG FINDS	1000500578 FLD984206730
-----	---	--------------------	----------------------------

RCRIS:

Owner: JOHN BARR, OWNER
(813) 229-7772

Contact: JOHN BARR
(813) 229-7772

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D002	.00000 (T)	Notification	D018	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

209	MOBIL DISTRIBUTION CENTER 501 N 20TH ST TAMPA, FL 33605	UST LUST	U001354310 N/A
-----	---	-------------	-------------------

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

MOBIL DISTRIBUTION CENTER (Continued)

U001354310

UST:

Facility ID:	298625069	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP.		
Contact:	Not reported	Facility Phone:	8132473911
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	A K TAPP		
Owner:	MOBIL OIL CORP DISTRIBUTION CTR 501 N 20TH ST TAMPA, FL 336050000		
Owner's Phone:	8132473911	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625069	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	MOBIL OIL CORP.		
Contact:	Not reported	Facility Phone:	8132473911
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860508	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	A K TAPP		
Owner:	MOBIL OIL CORP DISTRIBUTION CTR 501 N 20TH ST TAMPA, FL 336050000		
Owner's Phone:	8132473911	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	86/03
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, Man tank gauging		

210

BAY DRUM & STEEL INC
1211 E MADISON ST
TAMPA, FL 33605

RCRIS-SQG 1000460754
FINDS FLD984184309

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number						
	BAY DRUM & STEEL INC (Continued)		1000460754						
	RCRIS: Owner: GARY BLAKE, OWNER (813) 247-1144 Contact:GARY BLAKE (813) 247-1144								
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D001</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	D001	.00000 (T)	Notification		
Waste	Quantity	Info Source							
D001	.00000 (T)	Notification							
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported								
210	FIVE STAR TOURS 1211 E MADISON ST TAMPA, FL 33602	UST LUST	U001355286 N/A						

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FIVE STAR TOURS (Continued)

U001355286

LUST:

Facility ID:	8627884	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132231912	Alias Name 1:	Not reported
Discovery Date:	01/18/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

ABANDONED TANK RESTORATIO

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: LEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: WASTE OIL

Est. Gallons Lost: UNKNOWN

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FIVE STAR TOURS (Continued)

U001355286

UST:

Facility ID:	298627884	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIVE STAR TOURS		
Contact:	Not reported	Facility Phone:	8132231912
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	WILLIAM F LANG		
Owner:	LANG, WILLIAM F 3906 FONTAINEBLEAU DR TAMPA, FL 336340000		
Owner's Phone:	8132231912	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627884	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIVE STAR TOURS		
Contact:	Not reported	Facility Phone:	8132231912
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLIAM F LANG		
Owner:	LANG, WILLIAM F 3906 FONTAINEBLEAU DR TAMPA, FL 336340000		
Owner's Phone:	8132231912	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FIVE STAR TOURS (Continued)

U001355286

Facility ID:	298627884	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIVE STAR TOURS		
Contact:	Not reported	Facility Phone:	8132231912
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLIAM F LANG		
Owner:	LANG, WILLIAM F 3906 FONTAINEBLEAU DR TAMPA, FL 336340000		
Owner's Phone:	8132231912	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627884	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FIVE STAR TOURS		
Contact:	Not reported	Facility Phone:	8132231912
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	WILLIAM F LANG		
Owner:	LANG, WILLIAM F 3906 FONTAINEBLEAU DR TAMPA, FL 336340000		
Owner's Phone:	8132231912	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

211

YALE TIRE & BATTERY SERVICE
1227 E MADISON ST
TAMPA, FL 33602

RCRIS-SQG 1000502870
FINDS FLD984230417

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number		
			YALE TIRE & BATTERY SERVICE (Continued)			1000502870		
			RCRIS:					
			Owner: ROBERT ARNOLD, OWNER					
			(813) 229-0043					
			Contact:ROBERT ARNOLD					
			(813) 229-0043					
			Waste	Quantity	Info Source	Waste	Quantity	Info Source
			D001	.00000 (T)	Notification	F001	.00000 (T)	Notification
			(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported					
212			SPARTAN OIL CO			UST		U001353963
			2815 LONG ST			LUST		N/A
			TAMPA, FL 33605			AST		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SPARTAN OIL CO (Continued)

U001353963

LUST:

Facility ID:	8509056	Facility Type:	INLAND BULK PETROLEUM
Telephone:	8132473417	Alias Name 1:	Not reported
Discovery Date:	10/21/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	012 (LOW)	Alias Name 4:	Not reported
Rank:	06172	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	PLIRP (INSURANCE)
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	KEROSENE	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	FUEL OIL-ON SITE	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:	PETRO. LIABILITY INS. & RESTOR.
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	QTR 1

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SPARTAN OIL CO (Continued)

U001353963

UST:

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	76/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00020000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Contact:	Not reported	Facility Phone:	8132473417
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00025000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, DW piping space, Man tank gauging, GW monitoring		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SPARTAN OIL CO (Continued)

U001353963

AST:

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	00000
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	10	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00010000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Small use tank		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, Man tank gauging		

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	00000
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	11	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00010000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Small use tank		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Fiberglass, Dblwall=primary matl		
Petro. Monitoring:	Man sample wells, GW mon plan, Man tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	00000
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00070000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-flow shut off, Field erected		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Fiberglass, Suction piping		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, Man tank gauging		

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	00000
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00070000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Op-flow shut off, Field erected		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Fiberglass, Suction piping		
Petro. Monitoring:	Man sample wells, Piping/auto shut off, Man tank gauging		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SPARTAN OIL CO (Continued)

U001353963

Facility ID:	298509056	Facility Type:	Inland Bulk Petroleum
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	SAM A.LAZZARA		
Facility Phone:	8132473417	Permit Section:	00000
Date entered:	Not reported	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	9	District:	Southwest
Owner's Contact:	JUDY		
Owner:	SPARTAN OIL CO INC PO BOX 76359 TAMPA, FL 336756359		
Owner's Phone:	8132489212	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Small use tank		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Fiberglass, Dblwall=primary matf		
Petro. Monitoring:	Man sample wells, GW mon plan, Man tank gauging		

213 TAMPA,CITY-DPW FLEET MAINT. FIRE #1
808 E ZACK ST
TAMPA, FL 33602

UST

U001354377
N/A

UST:

Facility ID:	298625140	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAIN GUMMOE		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-DPW FLEET MAINT. FIRE #1 (Continued)

U001354377

Facility ID:	298625140	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAIN GUMMOE		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625140	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAIN GUMMOE		
Contact:	Not reported	Facility Phone:	8132277011
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860509	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

214

SHUTTERS UNLIMITED FLORIDA
902 N ROME AVENUE
TAMPA, FL 33606

RCRIS: Not Reported

RCRIS-SQG 1000421767
FINDS FLD041495284

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
215			GREYHOUND LINES INC 610 E POLK ST TAMPA, FL 33602	UST	U001962937	N/A
UST:						
Facility ID:		299401206	Facility Type:	Non-retail Business		
Is fac. regulated:		Not regulated facility	Is facility open:	Open		
Operator:		Not reported				
Contact:		Not reported	Facility Phone:	8132292174		
Permit Section:		Not reported	Region:	Not reported		
Facility Code:		No violation				
Date entered:		940725	Financial responsibility:	State PRGM (FLIPA/AIG)		
Tank ID:		NONE	District:	Southwest		
Owner's Contact:		VAN HARTNITT				
Owner:		GREYHOUND LINES INC PO BOX 660362 % ENVIRONMENTAL DALLAS, TX 752660362				
Owner's Phone:		2146984674	Tracking #:	Not reported		
Cleanup Status:		Not reported	Any contaminated soil:	Not reported		
Drink. Wat. Well:		Not reported	Any contaminated surface water:	Not reported		
Tank Cap. (Gals):		Not reported	Any monit. wells:	Not reported		
Tank position:		Not reported	Any contam. groundwater:	Not reported		
Tank Content:		Not reported	Contaminated media indicator:	Not reported		
Disposal Method:		Not reported	Install. Date:	Not reported		
Is tank regulated:		Not reported	Content Category:	Not reported		
Facility Status:		Not reported	Last used Date:	Not reported		
RPT Tank #:		Not reported	RPT by Tank #:	Not reported		
Tank Constr.:		Not reported				
Tank Piping:		Not reported				
Petro. Monitoring:		Not reported				
216			TAMPA,CITY-PERFORMING ARTS CENTER 1010 N W C MACINNES PL TAMPA, FL 33602	UST AST	U001355940	N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-PERFORMING ARTS CENTER (Continued)

U001355940

UST:

Facility ID:	298942611	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOFTEN, STEVE		
Contact:	Not reported	Facility Phone:	8132221000
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	MIKE MCCAY		
Owner:	TAMPA,CITY-REAL ESTATE 201 E KENNEDY BLVD STE 415 TAMPA, FL 336025823		
Owner's Phone:	8132238624	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	86/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

AST:

Facility ID:	298942611	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOFTEN, STEVE		
Facility Phone:	8132221000	Permit Section:	00000
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE MCCAY		
Owner:	TAMPA,CITY-REAL ESTATE 201 E KENNEDY BLVD STE 415 TAMPA, FL 336025823		
Owner's Phone:	8132238624	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000320
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-PERFORMING ARTS CENTER (Continued)

U001355940

Facility ID:	298942611	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LOFTEN, STEVE		
Facility Phone:	8132221000	Permit Section:	00000
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE MCCAY		
Owner:	TAMPA,CITY-REAL ESTATE		
	201 E KENNEDY BLVD STE 415		
	TAMPA, FL 336025823		
Owner's Phone:	8132238624	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000050
Tank Content:	Diesel-emerg generator	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	87/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel		
Tank Piping:	Unprotec metal		
Petro. Monitoring:	Not required		

217

SIR SPEEDY PRINTING #5041
202 E CASS STREET
TAMPA, FL 33602

RCRIS-SQG
FINDS

1000132111
FLD982079873

RCRIS:

Owner: ROBERT DOLAN
(813) 273-0027

Contact:ROBERT DOLAN
(813) 273-0027

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

218

TAMPA CITY ADMINISTRATIVE SERVICES
720 E ZACK ST
TAMPA, FL 33602

UST

U001356048
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA CITY ADMINISTRATIVE SERVICES (Continued)

U001356048

UST:

Facility ID:	298944858	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA CITY		
Contact:	Not reported	Facility Phone:	8132238892
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890921	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JACK AMBROSE		
Owner:	TAMPA CITY ADMIN SERVICES		
	720 E ZACK ST		
	TAMPA, FL 336024002		
Owner's Phone:	8132238892	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

219	HILLSBORO CO FALKENBURG VALRICO WWTP 925 E TWIGGS ST TAMPA, FL 33602	FINDS	1000498714 FLD984170837
-----	--	-------	----------------------------

Other Pertinent Environmental Activity Identified at Site:
facility has active water discharge permits

220	USGSA 501 E POLK ST #600 TAMPA, FL 33602	RCRIS-SQG	1000859199 FL3470000008
-----	--	-----------	----------------------------

RCRIS:

Owner: JAMES BENNETT, FIELD OFF MGR
(813) 228-2351

Contact: JAMES BENNETT
(813) 228-2351

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D008	.00000 (T)	Notification	F001	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

220	US DEPT OF GENERAL SVCS-ADMIN BLDG 501 E POLK ST TAMPA, FL 33602	UST	U001356228 N/A
-----	--	-----	-------------------

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

US DEPT OF GENERAL SVCS-ADMIN BLDG (Continued)

U001356228

UST:

Facility ID:	299100449	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	BENNETT, JAMES F		
Contact:	Not reported	Facility Phone:	8132282351
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910220	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES F BENNETT		
Owner:	US DEPT OF GENERAL SERVICES		
	501 E POLK ST #600		
	TAMPA, FL 336023926		
Owner's Phone:	8132282351	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	88/08
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Auto tank gauging		

221

US COURTHOUSE
801 N FLORIDA AVE
TAMPA, FL 33602

UST

U002217718
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

US COURTHOUSE (Continued)

U002217718

UST:

Facility ID:	299501854	Facility Type:	Tankless facility
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950510	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	KLOU MANCUSO		
Owner:	GENERAL SERVICES ADMINISTRATION		
	401 W PEACHTREE ST		
	ATLANTA, GA 303652550		
Owner's Phone:	4043313125	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

222

NCJ INVESTMENT CO
2004B DURHAM
TAMPA, FL 33675

RCRIS-SQG

1000702319
FLD984200139

RCRIS:

Owner: JOHN MYERS, TECH SERV
(813) 247-4731

Contact:JOHN MYERS
(813) 247-4731

Waste	Quantity	Info Source
D018	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

222

GAS KWICK INC
2004C DURHAM
TAMPA, FL 33675

RCRIS-SQG

1000702318
FLD984200121

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	GAS KWICK INC (Continued)		1000702318
	RCRIS: Owner: JOHN MYERS, TECH SERV (813) 247-4731 Contact:JOHN MYERS (813) 247-4731		
	Waste Quantity Info Source		
	D018 .00000 (T) Notification		
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported		
222	RADIANT OIL CO OF TAMPA INC 2004A DURHAM TAMPA, FL 33675	RCRIS-SQG	1000702320 FLD984200147
	RCRIS: Owner: JOHN MYERS, DIR TECH (813) 247-4731 Contact:JOHN MYERS (813) 247-4731		
	Waste Quantity Info Source		
	D018 .00000 (T) Notification		
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported		
222	VENTO OIL CO 2004D DURHAM TAMPA, FL 33605	FINDS	1000737263 FLD984200113
222	N C J INVESTMENT CO INC 2004 DURHAM STREET TAMPA, FL 33605	FINDS	1000737265 FLD984200139
222	RADIANT OIL CO OF TAMPA INC 2004 DURHAM ST TAMPA, FL 33605	UST LUST AST	U001354762 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

LUST:

Facility ID:	8625549	Facility Type:	TERMINAL FACILITY
Telephone:	8132474731	Alias Name 1:	Not reported
Discovery Date:	10/13/86	Alias Name 2:	Not reported
Tracking Number:	290690	Alias Name 3:	Not reported
Score:	061	Alias Name 4:	Not reported
Rank:	01186	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: NOT ENTERED

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product: Y

Cleanup Responsible: RESPONSIBLE PARTY

Soil Removal: Y

Alt. Process Date: Not reported

Soil Treatment: Y

Alternative Status: Not reported

Other Treatment: 540 TONS INCINERATED

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

REMEDIAL ACTION PLAN

Response Remedial Action Plan Type:

GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Estimated Completion Year:

00

Actual Year to Complete:

00

Report Type:

ANNUAL

Report Comments:

YR 1

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

UST:

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	17	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	89/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Contact:	Not reported	Facility Phone:	8132474731
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC PO BOX 5238 TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	66/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

AST:

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	10	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00005000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	11	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003500
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	12	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	13	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	14	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	15	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	16	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	18	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00006000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	82/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00105000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00025000
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area, Compartmented		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
/ Distance	Site	Database(s)	

RADIANT OIL CO OF TAMPA INC (Continued)

U001354762

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00105000
Tank Content:	Kerosene	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	66/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625549	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN P MYERS JR		
Facility Phone:	8132474731	Permit Section:	00000
Date entered:	860521	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	9	District:	Southwest
Owner's Contact:	JOHN P MYERS JR		
Owner:	RADIANT OIL CO OF TAMPA INC		
	PO BOX 5238		
	TAMPA, FL 336755238		
Owner's Phone:	8132474731	Tracking #:	290690
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003500
Tank Content:	New/lube oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Pressurized piping		
Petro. Monitoring:	Man sample wells		

222

VENTO OIL CO
2004D DURHAM
TAMPA, FL 33675

RCRIS-SQG 1000702317
FLD984200113

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number						
	VENTO OIL CO (Continued)		1000702317						
	RCRIS: Owner: JOHN MYERS, TECH SERV (813) 247-4731 Contact:JOHN MYERS (813) 247-4731								
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D018</td><td>.00000 (T)</td><td>Notification</td></tr></table> (P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported	Waste	Quantity	Info Source	D018	.00000 (T)	Notification		
Waste	Quantity	Info Source							
D018	.00000 (T)	Notification							
223	AMERADA HESS 402 N 22ND ST TAMPA, FL 33675 Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	FINDS	1000733662 FLD088776588						
223	AMERADA HESS 402 N 22ND ST TAMPA, FL 33675 RCRIS: Not Reported	RCRIS-SQG	1000699140 FLD088776588						
224	GTE OF FL TAMPA EAX 610 E ZACK ST TAMPA, FL 33602	UST	U001355398 N/A						

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GTE OF FL TAMPA EAX (Continued)

U001355398

UST:

Facility ID:	298732443	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO. OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870415	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL PO BOX 110 MC 711 TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00020000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	75/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298732443	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO. OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870415	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL PO BOX 110 MC 711 TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00020000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	75/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

225

BP-METRO
1239 E KENNEDY BLVD
TAMPA, FL 33602

UST
LUST

U001354186
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-METRO (Continued)

U001354186

LUST:

Facility ID:	8624933	Facility Type:	RETAIL STATION
Telephone:	8136814279	Alias Name 1:	PHILLIPS 66-METRO
Discovery Date:	11/30/88	Alias Name 2:	Not reported
Tracking Number:	294953	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-METRO (Continued)

U001354186

UST:

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO PO BOX 1110 BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	7
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO PO BOX 1110 BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	8
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	3	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO		
	PO BOX 1110		
	BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	4	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO		
	PO BOX 1110		
	BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	5	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO PO BOX 1110 BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	71/03
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	6	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO PO BOX 1110 BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	75/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	7	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO PO BOX 1110 BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	93/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	1	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	DW tank space, Piping/flow restrictor, DW piping space		

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	8	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO PO BOX 1110 BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	93/04
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	2	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor, DW piping space		

MAP FINDINGS

Map ID			
Direction			
Distance	Site	Database(s)	EDR ID Number EPA ID Number

BP-METRO (Continued)

U001354186

Facility ID:	298624933	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BILL HARDEE		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	9	District:	Southwest
Owner's Contact:	BILL HARDEE		
Owner:	AUTOMATED PETROLEUM & ENERGY CO		
	PO BOX 1110		
	BRANDON, FL 335091110		
Owner's Phone:	8136814279	Tracking #:	294953
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well.:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

226

SEL MADURO FL,INC.
401 N 13TH ST
TAMPA, FL 33602

UST
LUST

U001354648
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SEL MADURO FL,INC. (Continued)

U001354648

LUST:

Facility ID:	8625429	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132234721	Alias Name 1:	Not reported
Discovery Date:	06/19/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	030	Alias Name 4:	Not reported
Rank:	04494	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Flag:	Not reported

MAP FINDINGS

Map ID			
Direction			
Distance	Site	Database(s)	EDR ID Number EPA ID Number

SEL MADURO FL,INC. (Continued)

U001354648

UST:

Facility ID:	298625429	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEL MADURO FL,INC.		
Contact:	Not reported	Facility Phone:	8132234721
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	SAM ZAGARIA		
Owner:	GULF FL TERMINAL PO BOX 2481 TAMPA, FL 336012481		
Owner's Phone:	8135763050	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298625429	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEL MADURO FL,INC.		
Contact:	Not reported	Facility Phone:	8132234721
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860520	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	SAM ZAGARIA		
Owner:	GULF FL TERMINAL PO BOX 2481 TAMPA, FL 336012481		
Owner's Phone:	8135763050	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

226

WARE DEVELOPMENTS
KENNEDY BLVD & 13TH ST
TAMPA, FL 33602

UST
LUST

U001356178
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WARE DEVELOPMENTS (Continued)

U001356178

LUST:

Facility ID:	9063897	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132249624	Alias Name 1:	Not reported
Discovery Date:	04/03/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

ABANDONED TANK RESTORATIO

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: LEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WARE DEVELOPMENTS (Continued)

U001356178

UST:

Facility ID:	299063897	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WARE DEVELOPMENTS		
Contact:	Not reported	Facility Phone:	8132249624
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	901205	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	EARL H WARE		
Owner:	WARE DEVELOPMENTS		
	404 N 13TH ST		
	TAMPA, FL 336023610		
Owner's Phone:	8132249624	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000750	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	83/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299063897	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WARE DEVELOPMENTS		
Contact:	Not reported	Facility Phone:	8132249624
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	901205	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	EARL H WARE		
Owner:	WARE DEVELOPMENTS		
	404 N 13TH ST		
	TAMPA, FL 336023610		
Owner's Phone:	8132249624	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000750	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	83/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			WARE DEVELOPMENTS (Continued)		U001356178	
			Facility ID: 299063897 Is fac. regulated: Not regulated facility Operator: WARE DEVELOPMENTS Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 901205 Tank ID: 3 Owner's Contact: EARL H WARE Owner: WARE DEVELOPMENTS 404 N 13TH ST TAMPA, FL 336023610 Owner's Phone: 8132249624 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000750 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132249624 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Vehicular Last used Date: 83/09 RPT by Tank #: Not reported		
227			MAHONEY, MIKE 1719 W LEMON ST TAMPA, FL 33606	UST	U001355267	N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

MAHONEY, MIKE (Cqntinued)

U001355267

UST:

Facility ID:	298627773	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MAHONEY, MIKE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	MICHAEL MAHONEY		
Owner:	MAHONEY, MICHAEL		
	3241 BAYSHORE BLVD NE		
	ST PETERSBURG, FL 337030000		
Owner's Phone:	8132533424	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	79/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298627773	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	MAHONEY, MIKE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	MICHAEL MAHONEY		
Owner:	MAHONEY, MICHAEL		
	3241 BAYSHORE BLVD NE		
	ST PETERSBURG, FL 337030000		
Owner's Phone:	8132533424	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000600	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	79/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

228

GENERAL SERVICES ADMINISTRATION
501 E POLK STREET ROOM 600
TAMPA, FL 33602

FINDS

1000843480
FL3470000008

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
229	HILLSBOROUGH CNTY HEALTH DEPT 1105 E KENNEDY BLVD TAMPA, FL 33602 Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production	FINDS	1000497533 FLD069672137
230	CASS STREET INVESTORS SITE 725 CASS ST TAMPA, FL 33602 RCRIS: Not Reported	RCRIS-SQG FINDS	1000375959 FLD981866346
231	CARGILL INC 200 N 19TH ST TAMPA, FL 33605 UST: Facility ID: 298624988 Is fac. regulated: Not regulated facility Operator: CARGILL INC Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860507 Tank ID: 2 Owner's Contact: RALPH H CHRISTIANSON Owner: CARGILL INC 200 N 19TH ST TAMPA, FL 336056008 Owner's Phone: 8132473602 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000800 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	UST	U001354235 N/A
231	CARGILL INC 200 N 19TH ST TAMPA, FL 33605 Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	FINDS AST	1000497861 FLD980222244

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			CARGILL INC (Continued)		1000497861	
			AST: Facility ID: 298624988 Is fac. regulated: Not regulated facility Operator: CARGILL INC Facility Phone: 8132473602 Date entered: 860507 Tank ID: 1 Owner's Contact: RALPH H CHRISTIANSON Owner: CARGILL INC 200 N 19TH ST TAMPA, FL 336056008 Owner's Phone: 8132473602 Drink. Wat. Well: Not reported Cleanup Status: Not reported Tank position: Aboveground Tank Content: Vehic diesel Disposal Method: Removed Is tank regulated: Not regulated tank Last used Date: 89/12 RPT Tank #: Not reported Tank Constr.: Unknown/not reported Tank Piping: Unprotec metal, Fiberglass, Corrosion resis coated Petro. Monitoring: Not required Facility Type: Non-retail Business Is facility open: Closed Permit Section: 00000 Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Tank Cap. (Gals): 00003500 Contaminated media indicator: Not reported Install. Date: 74/05 Content Category: Vehicular Any contaminated groundwater: Not reported RPT by Tank #: Not reported			
232			USE 298733857 601 N MORGAN ST TAMPA, FL 33602	UST LUST	U001356128 N/A	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 298733857 (Continued)

U001356128

LUST:

Facility ID:	9046057	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132290874	Alias Name 1:	Not reported
Discovery Date:	Not reported	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

Not reported

Lead:

Not reported

Incident 17-770 Cleanup:

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: Not reported

Est. Gallons Lost: Not reported

Pollutant 2: Not reported

Est. Gallons Lost: Not reported

Pollutant 3: Not reported

Est. Gallons Lost: Not reported

INCIDENT PROGRAM INFORMATION -

Incident Program:

Not reported

Incident Program Type:

Not reported

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

USE 298733857 (Continued)

U001356128

UST:

Facility ID:	299046057	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRANDOFF INVESTMENTS INC		
Contact:	Not reported	Facility Phone:	8132290874
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	900329	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	DEBBIE DEVOE		
Owner:	GRANDOFF INVESTMENTS INC		
	412 E MADISON ST #1100		
	TAMPA, FL 336024697		
Owner's Phone:	8132290874	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

232

KAUFFMAN TIRE SERVICE OF GA., INC.
601 N MORGAN ST
TAMPA, FL 33602

UST
LUST

U001355480
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KAUFFMAN TIRE SERVICE OF GA., INC. (Continued)

U001355480

LUST:

Facility ID:	8733857	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132290874	Alias Name 1:	Not reported
Discovery Date:	12/08/89	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	020 (LOW)	Alias Name 4:	Not reported
Rank:	05579	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: GENERIC GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: WASTE OIL

Est. Gallons Lost: UNKNOWN

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

PARTIAL

Incident Ineligible Reason:

NOT PETROL/PETROL PRODUCT

Incident Ineligible Description:

NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KAUFFMAN TIRE SERVICE OF GA., INC. (Continued)

U001355480

UST:

Facility ID:	298733857	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GRANDOFF INVESTMENTS		
Contact:	Not reported	Facility Phone:	8132290874
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870730	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	DEBBIE DEVOE		
Owner:	GRANDOFF INVESTMENTS INC		
	412 E MADISON ST #1100		
	TAMPA, FL 336024697		
Owner's Phone:	8132290874	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	8/3/12
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	9/0/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

233 FREE PRESS PUBLISHING COMPANY
1010 WEST CASS STREET
TAMPA, FL 33606

FINDS

1000735254
FLD982115735

233 FREE PRESS PUBLISHING CO INC
1010 WEST CASS STREET
TAMPA, FL 33601

RCRIS-SQG

1000700497
FLD982115735

RCRIS: Not Reported

234 TAMPA ELECTRIC CO PLAZA GARAGE
702 N FRANKLIN ST
TAMPA, FL 33601

RCRIS-SQG
FINDS

1000886578
FL0000136978

RCRIS:

Owner: A AUTRY, DIR ENVT
(813) 228-4838

Contact: A AUTRY
(813) 228-4838

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F002	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
234	TAMPA ELEC CO 702 N FRANKLIN ST TAMPA, FL 33602	FINDS	1000502104 FLD984222547
235	STEVES RADIATORS 1702 W CASS ST TAMPA, FL 33606	UST LUST	U001546651 N/A
LUST:			
Facility ID: 9102162			
Telephone: 8132532060			
Discovery Date: 01/08/91			
Tracking Number: Not reported			
Score: 010 (LOW)			
Rank: 07198			
Class: Not reported			
Category: Not reported			
Facility Code: Not reported			
Status: Not reported			
INCIDENT GENERAL INFORMATION -			
Source Description:			
Lead:			
Incident 17-770 Cleanup:			
INCIDENT POLLUTANT INFORMATION -			
Pollutant 1: WASTE OIL			
Pollutant 2: GENERIC GAS			
Pollutant 3: VEHIC DIESEL			
INCIDENT PROGRAM INFORMATION -			
Incident Program:			
Incident Program Type:			
Incident Eligible Status:			
Incident Ineligible Reason:			
Incident Ineligible Description:			
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:			
Soil Removal: Y			
Soil Treatment: Y			
Other Treatment:			
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:			
Response Record Type:			
Response Remedial Action Plan Type:			
Response Status:			
Extension Record Type:			
Extension Status:			
Extension Comments:			
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:			
Response Record Type:			
Response Remedial Action Plan Type:			
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:			
Estimated Completion Year:			
Actual Year to Complete:			
Report Type:			
Report Comments:			
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:			
Flag:			

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STEVES RADIATORS (Continued)

U001546651

UST:

Facility ID:	299102162	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STEVES RADIATORS		
Contact:	Not reported	Facility Phone:	8132532060
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910529	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT BODE		
Owner:	BODE, SECUNDINO & ROBERT 3308 GRAY ST TAMPA, FL 336090000		
Owner's Phone:	8138767544	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299102162	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STEVES RADIATORS		
Contact:	Not reported	Facility Phone:	8132532060
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910529	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	ROBERT BODE		
Owner:	BODE, SECUNDINO & ROBERT 3308 GRAY ST TAMPA, FL 336090000		
Owner's Phone:	8138767544	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

STEVES RADIATORS (Continued)

U001546651

Facility ID:	299102162	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STEVES RADIATORS		
Contact:	Not reported	Facility Phone:	8132532060
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910529	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	ROBERT BODE		
Owner:	BODE, SECUNDINO & ROBERT 3308 GRAY ST TAMPA, FL 336090000		
Owner's Phone:	8138767544	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299102162	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STEVES RADIATORS		
Contact:	Not reported	Facility Phone:	8132532060
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910529	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	ROBERT BODE		
Owner:	BODE, SECUNDINO & ROBERT 3308 GRAY ST TAMPA, FL 336090000		
Owner's Phone:	8138767544	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

STEVES RADIATORS (Continued)

U001546651

Facility ID:	299102162	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	STEVES RADIATORS		
Contact:	Not reported	Facility Phone:	8132532060
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910529	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	ROBERT BODE		
Owner:	BODE, SECUNDINO & ROBERT		
	3308 GRAY ST		
	TAMPA, FL 336090000		
Owner's Phone:	8138767544	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

235	A RONNIE BOSWELL COLISION 1702 W CASS ST TAMPA, FL 33606	RCRIS-SQG	1000985791 FLR000002923
-----	--	-----------	----------------------------

RCRIS:

Owner: ALEXIS RIVERA, MGR
(813) 254-4171

Contact: Not reported

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D035	.00000 (T)	Notification
D039	.00000 (T)	Notification	F003	.00000 (T)	Notification
F005	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

235	UNITED CAB CO OF TAMPA-OFFICE COMPLEX 1701 W CASS ST TAMPA, FL 33606	UST LUST	U001354809 N/A
-----	--	-------------	-------------------

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED CAB CO OF TAMPA-OFFICE COMPLEX (Continued)

U001354809

LUST:

Facility ID:	8625600	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132532424	Alias Name 1:	Not reported
Discovery Date:	09/19/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	FIRST QTR

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNITED CAB CO OF TAMPA-OFFICE COMPLEX (Continued)

U001354809

UST:

Facility ID:	298625600	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN CASTELLANO		
Contact:	Not reported	Facility Phone:	8132532424
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN CASTELLANO		
Owner:	UNITED CAB CO. 1701 W CASS ST TAMPA, FL 336061229		
Owner's Phone:	8132532424	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	73/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625600	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN CASTELLANO		
Contact:	Not reported	Facility Phone:	8132532424
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN CASTELLANO		
Owner:	UNITED CAB CO. 1701 W CASS ST TAMPA, FL 336061229		
Owner's Phone:	8132532424	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	73/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

UNITED CAB CO OF TAMPA-OFFICE COMPLEX (Continued)

U001354809

Facility ID:	298625600	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN CASTELLANO		
Contact:	Not reported	Facility Phone:	8132532424
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN CASTELLANO		
Owner:	UNITED CAB CO. 1701 W CASS ST TAMPA, FL 336061229		
Owner's Phone:	8132532424	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000700	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	73/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625600	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	JOHN CASTELLANO		
Contact:	Not reported	Facility Phone:	8132532424
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN CASTELLANO		
Owner:	UNITED CAB CO. 1701 W CASS ST TAMPA, FL 336061229		
Owner's Phone:	8132532424	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

236 MATACS HAZARDOUS WASTE RECYCLING CO
1333 W CASS ST
TAMPA, FL 33606

RCRIS-SQG 1000985928
FL0001000652

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	MATACS HAZARDOUS WASTE RECYCLING CO (Continued)		1000985928
	RCRIS: Owner: JULIAN BELLEAU SR, PROCUREMT SPEC (813) 932-4407 Contact:Not reported		
	Waste Quantity Info Source		
	NONE .00000 (T) Notification		
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported		
237	D&V GARAGE 1301 W CASS ST TAMPA, FL 33606	UST LUST	U001355351 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

D&V GARAGE (Continued)

U001355351

LUST:

Facility ID:	8629068	Facility Type:	RETAIL STATION
Telephone:	0000000000	Alias Name 1:	Not reported
Discovery Date:	12/04/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	023 (LOW)	Alias Name 4:	Not reported
Rank:	05533	Alias Name 5:	Not reported

Class: Not reported
Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

ABANDONED TANK RESTORATIO

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS
Pollutant 2: WASTE OIL
Pollutant 3: FUEL OIL-ON SITE

Est. Gallons Lost: UNKNOWN
Est. Gallons Lost: UNKNOWN
Est. Gallons Lost: UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

PARTIAL

Incident Ineligible Reason:

NOT PETROL/PETROL PRODUCT

Incident Ineligible Description:

NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

D&V GARAGE (Continued)

U001355351

UST:

Facility ID:	298629068	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	D&V GARAGE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID MORENO		
Owner:	D & V GARAGE		
	3037 W KENNEDY BLVD		
	TAMPA, FL 336093136		
Owner's Phone:	8132518177	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298629068	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	D&V GARAGE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVID MORENO		
Owner:	D & V GARAGE		
	3037 W KENNEDY BLVD		
	TAMPA, FL 336093136		
Owner's Phone:	8132518177	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

D&V GARAGE (Continued)

U001355351

Facility ID:	298629068	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	D&V GARAGE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DAVID MORENO		
Owner:	D & V GARAGE		
	3037 W KENNEDY BLVD		
	TAMPA, FL 336093136		
Owner's Phone:	8132518177	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298629068	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	D&V GARAGE		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861119	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DAVID MORENO		
Owner:	D & V GARAGE		
	3037 W KENNEDY BLVD		
	TAMPA, FL 336093136		
Owner's Phone:	8132518177	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	85/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

238

GTE OF FL TAMPA TWIGG
609 MARION ST
TAMPA, FL 33601

UST

U001355319
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GTE OF FL TAMPA TWIGG (Continued)

U001355319

UST:

Facility ID:	298628026	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00025000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	69/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298628026	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00025000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	69/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

239

HILLSBOROUGH CNTY-FLEET MGMT #5
311 N NEBRASKA AVE
TAMPA, FL 33602

UST
LUST

U001354206
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLSBOROUGH CNTY-FLEET MGMT #5 (Continued)

U001354206

LUST:

Facility ID:	8624955	Facility Type:	LOCAL, CITY GOVERNMENT
Telephone:	8136232485	Alias Name 1:	Not reported
Discovery Date:	12/19/88	Alias Name 2:	Not reported
Tracking Number:	294731	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NO C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	Not reported	Est. Gallons Lost:	Not reported
Pollutant 2:	Not reported	Est. Gallons Lost:	Not reported
Pollutant 3:	Not reported	Est. Gallons Lost:	Not reported

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	NO CONTAMINATION
Incident Ineligible Description:	NO CONTAMINATIO

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	STATE
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

HILLSBOROUGH CNTY-FLEET MGMT #5 (Continued)

U001354206

UST:

Facility ID:	298624955	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	HILLSBOROUGH CNTY-FLEET MGMT		
Contact:	Not reported	Facility Phone:	8136232485
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	294731
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

240

TAMPA ELECTRIC CO.-TECO PLAZA
700 N TAMPA ST
TAMPA, FL 33602

UST
LUST

U001355397
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA ELECTRIC CO.-TECO PLAZA (Continued)

U001355397

LUST:

Facility ID:	8732442	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132284111	Alias Name 1:	Not reported
Discovery Date:	11/01/86	Alias Name 2:	Not reported
Tracking Number:	293582	Alias Name 3:	Not reported
Score:	021 (LOW)	Alias Name 4:	Not reported
Rank:	05558	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	NOT ENTERED	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	RISK ASSESSMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA ELECTRIC CO.-TECO PLAZA (Continued)

U001355397

UST:

Facility ID:	298732442	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA ELECTRIC CO		
Contact:	Not reported	Facility Phone:	8132284111
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870415	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BILL GOINS		
Owner:	TAMPA ELECTRIC CO PO BOX 111 % ENVIR PLANNING TAMPA, FL 336010111		
Owner's Phone:	8132281111	Tracking #:	293582
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298732442	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA ELECTRIC CO		
Contact:	Not reported	Facility Phone:	8132284111
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870415	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BILL GOINS		
Owner:	TAMPA ELECTRIC CO PO BOX 111 % ENVIR PLANNING TAMPA, FL 336010111		
Owner's Phone:	8132281111	Tracking #:	293582
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

241

HILLSBOROUGH CNTY-EMERGENCY MGMT.
309 N BRUSH ST
TAMPA, FL 33602

UST

U001354203
N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

HILLSBOROUGH CNTY-EMERGENCY MGMT. (Continued)

U001354203

UST:

Facility ID:	298624952	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	ED DANIELS		
Contact:	Not reported	Facility Phone:	8132726900
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES GORMAN		
Owner:	HILLSBOROUGH CNTY BD COMM		
	PO BOX 1110		
	TAMPA, FL 336011110		
Owner's Phone:	8135545025	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005200	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	67/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

242 HILLSBOROUGH CNTY SCHOOL BD-ADMIN CTR
901 E KENNEDY BLVD
TAMPA, FL 33605

UST

U001355685
N/A

MAP FINDINGS

Map ID			
Direction			
Distance			
Site	Database(s)	EDR ID Number	EPA ID Number

HILLSBOROUGH CNTY SCHOOL BD-ADMIN CTR (Continued)

U001355685

UST:

Facility ID:	298736984	Facility Type:	County Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	TORRES, LUIS		
Contact:	Not reported	Facility Phone:	8132724000
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871223	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT J AGUIS		
Owner:	HILLSBOROUGH CNTY SCHOOL BD		
	901 E KENNEDY BLVD		
	TAMPA, FL 33601		
Owner's Phone:	8139876994	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

242

FIRESTONE #1889-004146
900 E KENNEDY BLVD
TAMPA, FL 33602

UST
LUST

U001355452
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FIRESTONE #1889-004146 (Continued)

U001355452

LUST:

Facility ID:	8733809	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132292626	Alias Name 1:	Not reported
Discovery Date:	12/22/88	Alias Name 2:	Not reported
Tracking Number:	297373	Alias Name 3:	Not reported
Score:	012 (LOW)	Alias Name 4:	Not reported
Rank:	06172	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: LEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: WASTE OIL

Est. Gallons Lost: UNKNOWN

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: RESPONSIBLE PARTY

Soil Removal: Y

Alt. Process Date: Not reported

Soil Treatment: Y

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

REMEDIAL ACTION PLAN

Extension Status:

APPROVED

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	FIRESTONE #1889-004146 (Continued)		U001355452
	UST: Facility ID: 298733809 Is fac. regulated: Not regulated facility Operator: FIRESTONE Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 870729 Tank ID: 1 Owner's Contact: KATHLEEN SCHEUTZOW Owner: BRIDGESTONE FIRESTONE INC 2550 W GOLF RD ROLLING MEADOWS, IL 60008 Owner's Phone: 2163793737 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000300 Tank position: Not reported Tank Content: Not reported Disposal Method: In service Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not required Facility Type: Non-retail Business Is facility open: Open Facility Phone: 8132292626 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 297373 Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Hazardous/other Last used Date: Not reported RPT by Tank #: Not reported		
242	HILLSBOROUGH CNTY PUB SCHOOLS 901 E KENNEDY BLVD TAMPA, FL 33602	FINDS	1000502054 FLD984222034
243	GENERAL CHEMICAL 3004 CLARK ST TAMPA, FL 33605 Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	FINDS	1000498516 FLD982089617
243	GENERAL CHEMICAL CORP. TAMPA WORKS 3004 E. CLARK ST. TAMPA, FL 33605	TRIS	1000901806 NA
243	GENERAL CHEMICAL TAMPA WORKS 3004 E CLARK ST TAMPA, FL 33605	FINDS	1000498787 FLD984180703
244	BANKSHARES PROPERTIES INC 600 N FLORIDA AVE TAMPA, FL 33602	UST	U001356182 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BANKSHARES PROPERTIES INC (Continued)

U001356182

UST:

Facility ID:	299063982	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BANKSHARES PROPERTIES INC		
Contact:	Not reported	Facility Phone:	8138810488
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	901219	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOSEPH SERAVALLI		
Owner:	BARCHESTER CORP		
	1000 WALKER ST		
	HOLLY HILL, FL 32117		
Owner's Phone:	9042384076	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

244

US POSTAL SERVICE-COURTHOUSE
601 N FLORIDA AVE
TAMPA, FL 33602

UST

U001355086
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

US POSTAL SERVICE-COURTHOUSE (Continued)

U001355086

UST:

Facility ID:	298627017	Facility Type:	Federal Government
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	GENERAL SERVICES ADMINISTRATION		
Contact:	Not reported	Facility Phone:	8132282351
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES F. BENNETT		
Owner:	GENERAL SERVICES ADMINISTRATION		
	501 E POLK ST #600		
	TAMPA, FL 336023926		
Owner's Phone:	8132282351	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Auto tank gauging		

244

USGSA
601 N FLORIDA AVE
TAMPA, FL 33602

RCRIS-SQG 1000858795
FINDS FL0000015081

RCRIS:

Owner: JAMES BENNETT, FIELD OFFICE MGR
(813) 228-2351

Contact: JAMES BENNETT
(813) 228-2351

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D008	.00000 (T)	Notification	F001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

245

INDEPENDENT ICE CO INC
602 N ALBANY
TAMPA, FL 33606

UST
LUST

U001356377
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

INDEPENDENT ICE CO INC (Continued)

U001356377

LUST:

Facility ID:	9103664	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8138687617	Alias Name 1:	Not reported
Discovery Date:	12/20/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	030	Alias Name 4:	Not reported
Rank:	04434	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

INDEPENDENT ICE CO INC (Continued)

U001356377

UST:

Facility ID:	299103664	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RAYNOR, MARIE		
Contact:	Not reported	Facility Phone:	8138687617
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911226	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	MARIE RAYNOR		
Owner:	INDEPENDENT ICE CO INC		
	10745 FALLEN LEAF LN		
	PORT RICHEY, FL 346680000		
Owner's Phone:	8138687617	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

Facility ID:	299103664	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RAYNOR, MARIE		
Contact:	Not reported	Facility Phone:	8138687617
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911226	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	MARIE RAYNOR		
Owner:	INDEPENDENT ICE CO INC		
	10745 FALLEN LEAF LN		
	PORT RICHEY, FL 346680000		
Owner's Phone:	8138687617	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

246

ALLEY & ALLEY, CHARTERED
205 N BRUSH ST
TAMPA, FL 33602

UST
LUST

U001545324
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ALLEY & ALLEY,CHARTERED (Continued)

U001545324

LUST:

Facility ID:	8841244	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8138795333	Alias Name 1:	Not reported
Discovery Date:	12/14/88	Alias Name 2:	Not reported
Tracking Number:	295239	Alias Name 3:	Not reported
Score:	011 (LOW)	Alias Name 4:	Not reported
Rank:	06640	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal: Y

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

ALLEY & ALLEY,CHARTERED (Continued)

U001545324

UST:

Facility ID:	298841244	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ALLEY & ALLEY,CHARTERED		
Contact:	Not reported	Facility Phone:	8138795333
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880819	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN EDWARD ALLEY		
Owner:	ALLEY & ALLEY CHARTERED		
	205 N BRUSH ST		
	TAMPA, FL 336024103		
Owner's Phone:	8138795333	Tracking #:	295239
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	56/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

247

BIRDWELL EQUIPMENT CO
202 N 11TH ST
TAMPA, FL 33602

UST
LUST

U001354903
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BIRDWELL EQUIPMENT CO (Continued)

U001354903

LUST:

Facility ID:	8625698	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132296571	Alias Name 1:	Not reported
Discovery Date:	09/30/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BIRDWELL EQUIPMENT CO (Continued)

U001354903

UST:

Facility ID:	298625698	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BIRDWELL EQUIPMENT CO		
Contact:	Not reported	Facility Phone:	8132296571
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	HERBERT SOMERSON		
Owner:	WEISSMAN, IRVING TRUSTEE GRANDWA 1400 GULF BLVD #810 CLEARWATER, FL 34630		
Owner's Phone:	8135965106	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625698	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BIRDWELL EQUIPMENT CO		
Contact:	Not reported	Facility Phone:	8132296571
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	HERBERT SOMERSON		
Owner:	WEISSMAN, IRVING TRUSTEE GRANDWA 1400 GULF BLVD #810 CLEARWATER, FL 34630		
Owner's Phone:	8135965106	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	81/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

247 VENTO OIL CO
207 N 11TH ST
TAMPA, FL 33602

UST
LUST U001354885
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

VENTO OIL CO (Continued)

U001354885

LUST:

Facility ID:	8625679	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132210339	Alias Name 1:	Not reported
Discovery Date:	09/11/88	Alias Name 2:	Not reported
Tracking Number:	293751	Alias Name 3:	Not reported
Score:	040	Alias Name 4:	Not reported
Rank:	02475	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: GENERIC GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

REMEDIAL ACTION PLAN

Response Remedial Action Plan Type:

MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

DISTRICT OFFICE

Estimated Completion Year:

00

Actual Year to Complete:

00

Report Type:

QUARTERLY

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	VENTO OIL CO (Continued)		U001354885
	UST: Facility ID: 298625679 Is fac. regulated: Not regulated facility Operator: VENTO OIL CO Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860522 Tank ID: 1 Owner's Contact: CATHERINE VENTO Owner: VENTO, CATHERINE 712 GRAND CIR TEMPLE TERRACE, FL 336170000 Owner's Phone: 8139801101 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00001000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132210339 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: 293751 Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 81/09 Content Category: Vehicular Last used Date: 89/06 RPT by Tank #: Not reported	
247	BONANNI SHIP SUPPLY, INC. 217 N 11TH ST TAMPA, FL 33602	UST	U001354957 N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	BONANNI SHIP SUPPLY, INC. (Continued)		U001354957
	UST: Facility ID: 298625754 Facility Type: Non-retail Business Is fac. regulated: Not regulated facility Is facility open: Closed Operator: BONANNI SHIP SUPPLY, INC. Contact: Not reported Facility Phone: 8132296411 Permit Section: Not reported Region: Not reported Facility Code: No violation Date entered: 860523 Financial responsibility: Not reported Tank ID: 1 District: Southwest Owner's Contact: JAN LABARBERA Owner: BONANNI SHIP SUPPLY INC PO BOX 3208 TAMPA, FL 336013208 Owner's Phone: 8132296411 Tracking #: Not reported Cleanup Status: Not reported Any contaminated soil: Not reported Drink. Wat. Well: Not reported Any contaminated surface water: Not reported Tank Cap. (Gals): 00002000 Any monit. wells: Not reported Tank position: Not reported Any contam. groundwater: Not reported Tank Content: Not reported Contaminated media indicator: Not reported Disposal Method: Removed Install. Date: 78/XX Is tank regulated: Not regulated tank Content Category: Vehicular Facility Status: Not reported Last used Date: 89/XX RPT Tank #: Not reported RPT by Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported		
248	TAMPA SAND & MATERIAL 3214 E CLARK ST TAMPA, FL 33605 Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act	FINDS	1000497186 FLD039568126
248	FL MINING & MATERIALS 3212 CLARK ST TAMPA, FL 33605	UST LUST AST	U001354037 N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FL MINING & MATERIALS (Continued)

U001354037

UST:

Facility ID:	298624773	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FL MINING & MATERIALS		
Contact:	Not reported	Facility Phone:	8139336711
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DENISE CORRALES		
Owner:	FL MINING & MATERIALS CORP		
	PO BOX 31965		
	TAMPA, FL 336310000		
Owner's Phone:	8139336711	Tracking #:	290590
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624773	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FL MINING & MATERIALS		
Contact:	Not reported	Facility Phone:	8139336711
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DENISE CORRALES		
Owner:	FL MINING & MATERIALS CORP		
	PO BOX 31965		
	TAMPA, FL 336310000		
Owner's Phone:	8139336711	Tracking #:	290590
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FL MINING & MATERIALS (Continued)

U001354037

AST:

Facility ID:	298624773	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FL MINING & MATERIALS		
Facility Phone:	8139336711	Permit Section:	00000
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DENISE CORRALES		
Owner:	FL MINING & MATERIALS CORP		
	PO BOX 31965		
	TAMPA, FL 336310000		
Owner's Phone:	8139336711	Tracking #:	290590
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Completed	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Vehic diesel	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/07
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	Not required		

249

GAYLORD MILLER ELECTRIC CORP
602 N OREGON AVE
TAMPA, FL 33606

RCRIS-SQG

1000985555
FLR000000547

RCRIS:

Owner: DONALD MILLER, PRES
(813) 254-4681

Contact: Not reported

Waste	Quantity	Info Source
-------	----------	-------------

NONE	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

250

CARDINALS BODY SHOP
606 N NEWPORT
TAMPA, FL 33606

RCRIS-SQG
FINDS

1000189328
FLD982153652

RCRIS:

Owner: CHARLES CAMPER
(813) 253-5961

Contact: CHARLES CAMPER
(813) 253-5961

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
251	PAUL SMITH CONTRACTING CO INC 1202 W CARMEN ST TAMPA, FL 33606	UST LUST	U001354520 N/A
LUST:			
Facility ID: 8625292		Facility Type:	NON-RETAIL BUSINESS
Telephone: 8132535321		Alias Name 1:	Not reported
Discovery Date: 04/30/90		Alias Name 2:	Not reported
Tracking Number: Not reported		Alias Name 3:	Not reported
Score: 022 (LOW)		Alias Name 4:	Not reported
Rank: 05539		Alias Name 5:	Not reported
Class: Not reported			
Category: Not reported			
Facility Code: Not reported		Status:	Not reported
INCIDENT GENERAL INFORMATION -			
Source Description:		ABANDONED TANK RESTORATIO	
Lead:		LOCAL PROGRAM	
Incident 17-770 Cleanup:		NEW C/U REQUIRED	
INCIDENT POLLUTANT INFORMATION -			
Pollutant 1: UNLEADED GAS		Est. Gallons Lost:	UNKNOWN
Pollutant 2: Not reported		Est. Gallons Lost:	00000000
Pollutant 3: Not reported		Est. Gallons Lost:	00000000
INCIDENT PROGRAM INFORMATION -			
Incident Program:		ABANDONED TANK RESTORATION	
Incident Program Type:		STATE CLEANUP	
Incident Eligible Status:		ELIGIBLE	
Incident Ineligible Reason:		Not Reported	
Incident Ineligible Description:		Not reported	
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:		Cleanup Responsible:	Not reported
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:		Not reported	
Response Record Type:		Not reported	
Response Remedial Action Plan Type:		Not reported	
Response Status:		Not reported	
Extension Record Type:		Not reported	
Extension Status:		Not reported	
Extension Comments:		Not reported	
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:		Not reported	
Response Record Type:		Not reported	
Response Remedial Action Plan Type:		Not reported	
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:		Not reported	
Estimated Completion Year:		Not reported	
Actual Year to Complete:		Not reported	
Report Type:		Not reported	
Report Comments:		Not reported	
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:		Not reported	
Flag:		Not reported	

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

PAUL SMITH CONTRACTING CO INC (Continued)

U001354520

UST:

Facility ID:	298625292	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VERNON FLANAGAN		
Contact:	Not reported	Facility Phone:	8132535321
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PAUL H. SMITH, JR.		
Owner:	PAUL SMITH CONTRACTING CO INC		
	1202 W CARMEN ST		
	TAMPA, FL 336061303		
Owner's Phone:	8132535321	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	74/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

251

GRIFFIN SERVICE CORP
606 N GILCHRIST AVE
TAMPA, FL 33606

UST

U001354944
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GRIFFIN SERVICE CORP (Continued)

U001354944

UST:

Facility ID:	298625741	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LINGERFELT, BRYAN		
Contact:	Not reported	Facility Phone:	8132816946
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	THEODORE E. WADE		
Owner:	GRIFFIN SERVICE CORP		
	606 N GILCHRIST AVE		
	TAMPA, FL 336061320		
Owner's Phone:	8132516942	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	82/04
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

252

ANNELLO TILE & TERRAZZO, INC.
1116 W CARMEN ST
TAMPA, FL 33606

UST

U001355252
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ANNELLO TILE & TERRAZZO, INC. (Continued)

U001355252

UST:

Facility ID:	298627702	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	VITO J. ANELLO		
Contact:	Not reported	Facility Phone:	8132533458
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	VITO J. ANELLO		
Owner:	ANNELLO TILE & TERRAZZO INC		
	1116 W CARMEN ST		
	TAMPA, FL 336061302		
Owner's Phone:	8132533458	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	74/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

253

ANCO INC
102 N 20TH ST
TAMPA, FL 33605

UST

U001355004
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ANCO INC (Continued)

U001355004

UST:

Facility ID:	298625805	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANCO INC		
Contact:	Not reported	Facility Phone:	8132486248
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860527	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM COKER		
Owner:	ANCO INC		
	102 N 20TH ST		
	TAMPA, FL 336056014		
Owner's Phone:	8132486248	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	82/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/12
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

254

SEABOARD COLD STORAGE
101 N BRUSH ST
TAMPA, FL 33602

UST
LUST

U001354183
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SEABOARD COLD STORAGE (Continued)

U001354183

LUST:

Facility ID:	8624930	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132233791	Alias Name 1:	Not reported
Discovery Date:	05/16/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	VEHIC DIESEL	Est. Gallons Lost:	UNKNOWN
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	INELIGIBLE
Incident Ineligible Reason:	FEDERAL FACILITY
Incident Ineligible Description:	FEDERAL FACILIT

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	STATE
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	NO FURTHER ACTION
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SEABOARD COLD STORAGE (Continued)

U001354183

UST:

Facility ID:	298624930	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEABOARD COLD STORAGE		
Contact:	Not reported	Facility Phone:	8132233791
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	R MINNER		
Owner:	SOUTHEAST BANK OF TAMPA 1 TAMPA CITY CENTER TAMPA, FL 336020000		
Owner's Phone:	8132297951	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624930	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEABOARD COLD STORAGE		
Contact:	Not reported	Facility Phone:	8132233791
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	R MINNER		
Owner:	SOUTHEAST BANK OF TAMPA 1 TAMPA CITY CENTER TAMPA, FL 336020000		
Owner's Phone:	8132297951	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SEABOARD COLD STORAGE (Continued)

U001354183

Facility ID:	298624930	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SEABOARD COLD STORAGE		
Contact:	Not reported	Facility Phone:	8132233791
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	R MINNER		
Owner:	SOUTHEAST BANK OF TAMPA 1 TAMPA CITY CENTER TAMPA, FL 336020000		
Owner's Phone:	8132297951	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

255

HI GRADE FOOD SPECIALTIES OF FL
1705 W GRAY ST
TAMPA, FL

LUST

S101420729
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HI GRADE FOOD SPECIALTIES OF FL (Continued)

S101420729

LUST:

Facility ID:	9401696	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8136211222	Alias Name 1:	Not reported
Discovery Date:	04/08/93	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	Not reported
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Estimated Completion Year:	00
Actual Year to Complete:	00
Report Type:	QUARTERLY
Report Comments:	30 RA STATUS REPORT

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

255

HI GRADE FOOD SPECIALTIES OF FL
1705 GRAY ST
TAMPA, FL

UST

U001963223
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HI GRADE FOOD SPECIALTIES OF FL (Continued)

U001963223

UST:

Facility ID:	299401696	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	8136211222
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940902	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	ROBERT CUTTING		
Owner:	DISTRIBUTION PLUS INC		
	9860 CURRIE DAVIS DR		
	TAMPA, FL 33619		
Owner's Phone:	8136211222	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

256

YELLOW CAB COMPANY OF TAMPA, I
502 NORTH OREGON AVENUE
TAMPA, FL 33606

FINDS
UST
LUST

1000735805
FLD982170482

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

YELLOW CAB COMPANY OF TAMPA, I (Continued)

1000735805

LUST:

Facility ID:	8625621	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132538871	Alias Name 1:	Not reported
Discovery Date:	03/20/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	APPROVED
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

YELLOW CAB COMPANY OF TAMPA, I (Continued)

1000735805

UST:

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

YELLOW CAB COMPANY OF TAMPA, I (Continued)

1000735805

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

YELLOW CAB COMPANY OF TAMPA, I (Continued)

1000735805

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625621	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	YELLOW CAB CO OF TAMPA INC		
Contact:	Not reported	Facility Phone:	8132538871
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JACK BROOKE		
Owner:	YELLOW CAB CO OF TAMPA INC		
	502 N OREGON AVE		
	TAMPA, FL 336061215		
Owner's Phone:	8132538871	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

256

YELLOW CAB CO OF TAMPA INC
502 NORTH OREGON AVENUE
TAMPA, FL 33601

RCRIS-SQG 1000700968
FLD982170482

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

YELLOW CAB CO OF TAMPA INC (Continued)

1000700968

RCRIS:

Owner: TRIGG, J C SHOP FOREMAN
(813) 251-3691

Contact: TRIGG J C
(813) 251-3691

Waste	Quantity	Info Source
D001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

257

TAMPA TRIBUNE CO
805 E JACKSON ST
TAMPA, FL 33602

UST

U001355366
N/A

UST:

Facility ID: 298731693
Is fac. regulated: Not regulated facility
Operator: TRIBUNE CO.
Contact: Not reported
Permit Section: Not reported
Facility Code: No violation
Date entered: 870105
Tank ID: 10
Owner's Contact: JAMES V FERNANDEZ
Owner: TAMPA TRIBUNE CO
202 S PARKER ST
TAMPA, FL 336060000

Facility Type: Non-retail Business
Is facility open: Closed
Facility Phone: Not reported
Region: Not reported
Financial responsibility: Not reported
District: Southwest

Owner's Phone: 8132518829
Cleanup Status: Not reported
Drink. Wat. Well: Not reported
Tank Cap. (Gals): 00010000
Tank position: Not reported
Tank Content: Not reported
Disposal Method: Removed
Is tank regulated: Not regulated tank
Facility Status: Not reported
RPT Tank #: Not reported
Tank Constr.: Not reported
Tank Piping: Not reported
Petro. Monitoring: Unknown/not reported

Tracking #: Not reported
Any contaminated soil: Not reported
Any contaminated surface water: Not reported
Any monit. wells: Not reported
Any contam. groundwater: Not reported
Contaminated media indicator: Not reported
Install. Date: Not reported
Content Category: Vehicular
Last used Date: Not reported
RPT by Tank #: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA TRIBUNE CO* (Continued)

U001355366

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 336060000		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001300	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 336060000		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

TAMPA TRIBUNE CO (Continued)

U001355366

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 336060000		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 336060000		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

TAMPA TRIBUNE CO (Continued)

U001355366

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO		
	202 S PARKER ST		
	TAMPA, FL 336060000		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298731693	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TRIBUNE CO.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870105	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO		
	202 S PARKER ST		
	TAMPA, FL 336060000		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

258

NATIONAL LINEN SERVICE
507 N WILLOW AVE
TAMPA, FL 33606

UST
LUST

U001354545
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL LINEN SERVICE (Continued)

U001354545

UST:

Facility ID:	298625323	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNETH CLARK		
Contact:	Not reported	Facility Phone:	8132530431
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PAT SNIDER		
Owner:	NATIONAL LINEN SERVICE		
	507 N WILLOW AVE		
	TAMPA, FL 336061337		
Owner's Phone:	8132530431	Tracking #:	297414
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	70/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625323	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNETH CLARK		
Contact:	Not reported	Facility Phone:	8132530431
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	PAT SNIDER		
Owner:	NATIONAL LINEN SERVICE		
	507 N WILLOW AVE		
	TAMPA, FL 336061337		
Owner's Phone:	8132530431	Tracking #:	297414
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	5
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL LINEN SERVICE (Continued)

U001354545

Facility ID:	298625323	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNETH CLARK		
Contact:	Not reported	Facility Phone:	8132530431
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	PAT SNIDER		
Owner:	NATIONAL LINEN SERVICE 507 N WILLOW AVE TAMPA, FL 336061337		
Owner's Phone:	8132530431	Tracking #:	297414
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625323	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNETH CLARK		
Contact:	Not reported	Facility Phone:	8132530431
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	PAT SNIDER		
Owner:	NATIONAL LINEN SERVICE 507 N WILLOW AVE TAMPA, FL 336061337		
Owner's Phone:	8132530431	Tracking #:	297414
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NATIONAL LINEN SERVICE (Continued)

U001354545

Facility ID:	298625323	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNETH CLARK		
Contact:	Not reported	Facility Phone:	8132530431
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	PAT SNIDER		
Owner:	NATIONAL LINEN SERVICE		
	507 N WILLOW AVE		
	TAMPA, FL 336061337		
Owner's Phone:	8132530431	Tracking #:	297414
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/01
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	2	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

258

PHOTO ENGRAVING INC
502 N WILLOW AVE
TAMPA, FL 33606

RCRIS-SQG 1000859175
FINDS FL0000123125

RCRIS:

Owner: JOHN ALESSANDRINI, PROCESS ENG
(813) 253-3427

Contact: JOHN ALESSANDRINI
(813) 253-3427

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D007	.00000 (T)	Notification	F005	.00000 (T)	Notification
F006	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

258

PHOTOENGRAVING, INC.
502 N WILLOW AVE
TAMPA, FL 33606

UST

U001355463
N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	PHOTOENGRAVING, INC. (Continued)		U001355463
	UST: Facility ID: 298733831 Is fac. regulated: Not regulated facility Operator: PHOTENGRAVING, INC. Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 870729 Tank ID: 1 Owner's Contact: ED DALTON, JR. Owner: PHOTENGRAVING INC 502 N WILLOW AVE TAMPA, FL 336061338 Owner's Phone: 8132533427 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000500 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: None	Facility Type: Industrial Plan Is facility open: Closed Facility Phone: 8132533427 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: 66/XX Content Category: Pollutant Last used Date: 91/08 RPT by Tank #: Not reported	
259	PROFESSIONAL SERVICE INDUSTRIES INC 512 N DELAWARE AVE TAMPA, FL 33606	UST LUST	U001355948 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PROFESSIONAL SERVICE INDUSTRIES INC (Continued)

U001355948

LUST:

Facility ID:	8942650	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132533485	Alias Name 1:	Not reported
Discovery Date:	11/01/88	Alias Name 2:	Not reported
Tracking Number:	296240	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NO C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: Not reported

Est. Gallons Lost: Not reported

Pollutant 2: Not reported

Est. Gallons Lost: Not reported

Pollutant 3: Not reported

Est. Gallons Lost: Not reported

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

INELIGIBLE

Incident Ineligible Reason:

NO CONTAMINATION

Incident Ineligible Description:

NO CONTAMINATIO

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

PROFESSIONAL SERVICE INDUSTRIES INC (Continued)

U001355948

UST:

Facility ID:	298942650	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PROFESSIONAL SERVICE INDUSTRIES		
Contact:	Not reported	Facility Phone:	8132533485
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890104	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT WATKINS		
Owner:	PROFESSIONAL SERVICE INDUSTRIES		
	512 N DELAWARE AVE		
	TAMPA, FL 336061313		
Owner's Phone:	8132533485	Tracking #:	296240
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

260

DELUXE PLASTIC CARD CO
202 S 22ND ST
TAMPA, FL 33605

RCRIS-SQG 1000428902
FINDS FLD122637861

RCRIS:

Owner: KENT LARSON
(813) 248-2196

Contact: KENT LARSON
(813) 248-2196

Waste	Quantity	Info Source	Waste	Quantity	Info Source
F002	.00000 (T)	Notification	F003	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

261

USN NAVAL RESERVE CENTER
1325 YORK ST
TAMPA, FL 33602

RCRIS-SQG 1000503289
FINDS FL1170022742

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number																		
	USN NAVAL RESERVE CENTER (Continued)		1000503289																		
	RCRIS: Owner: DANNY KENNEDY, SUPPLY CPO (813) 228-2689 Contact: DANNY KENNEDY (813) 228-2689																				
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D001</td><td>.00000 (T)</td><td>Notification</td><td>F003</td><td>.00000 (T)</td><td>Notification</td></tr><tr><td>F005</td><td>.00000 (T)</td><td>Notification</td><td></td><td></td><td></td></tr></table>	Waste	Quantity	Info Source	Waste	Quantity	Info Source	D001	.00000 (T)	Notification	F003	.00000 (T)	Notification	F005	.00000 (T)	Notification					
Waste	Quantity	Info Source	Waste	Quantity	Info Source																
D001	.00000 (T)	Notification	F003	.00000 (T)	Notification																
F005	.00000 (T)	Notification																			
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported																				
262	NATURAL EARTH PRODUCTS INC 502 N GILCHRIST AVE TAMPA, FL 33606	FINDS	1000932301 FL0000613679																		
262	JOHNSTON LITHOGRAPH & ENGRAVIN 502 NORTH GILCHRIST AVE TAMPA, FL 33606 RCRIS: Not Reported Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production	RCRIS-SQG FINDS	1000321047 FLD982090870																		
263	FIRST FLORIDA TOWER OFFICE BUILDING 111 E MADISON ST TAMPA, FL 33602	UST	U001356235 N/A																		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

FIRST FLORIDA TOWER OFFICE BUILDING (Continued)

U001356235

UST:

Facility ID:	299100521	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JORDAN, JOHN F		
Contact:	Not reported	Facility Phone:	8132297800
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910225	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN F JORDAN		
Owner:	CLW REALTY ASSET GROUP		
	111 MADISON ST #2410		
	TAMPA, FL 336024714		
Owner's Phone:	8132297800	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	73/01
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299100521	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JORDAN, JOHN F		
Contact:	Not reported	Facility Phone:	8132297800
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910225	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN F JORDAN		
Owner:	CLW REALTY ASSET GROUP		
	111 MADISON ST #2410		
	TAMPA, FL 336024714		
Owner's Phone:	8132297800	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00015000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Temp out of serv	Install. Date:	73/01
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	93/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

264

HIGH TECH FINISHING SERVICES INC
132 NORTH 13 ST
TAMPA, FL 33602

RCRIS-SQG 1000238636
FINDS FLD981860547

RCRIS: Not Reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
265	TAMPA CITY-DPW FLEET MAINT-DIV #7 310 N MARION ST TAMPA, FL 33602	UST LUST	U001354877 N/A
LUST:			
Facility ID: 8625671		Facility Type:	LOCAL, CITY GOVERNMENT
Telephone: 8138763536		Alias Name 1:	Not reported
Discovery Date: 01/22/88		Alias Name 2:	Not reported
Tracking Number: 292535		Alias Name 3:	Not reported
Score: 012 (LOW)		Alias Name 4:	Not reported
Rank: 06172		Alias Name 5:	Not reported
Class: Not reported			
Category: Not reported			
Facility Code: Not reported		Status:	Not reported
INCIDENT GENERAL INFORMATION -			
Source Description:		EDI	
Lead:		LOCAL PROGRAM	
Incident 17-770 Cleanup:		NEW C/U REQUIRED	
INCIDENT POLLUTANT INFORMATION -			
Pollutant 1: NOT ENTERED		Est. Gallons Lost:	UNKNOWN
Pollutant 2: Not reported		Est. Gallons Lost:	00000000
Pollutant 3: Not reported		Est. Gallons Lost:	00000000
INCIDENT PROGRAM INFORMATION -			
Incident Program:		EARLY DETECTION INCENTIVE	
Incident Program Type:		STATE CLEANUP	
Incident Eligible Status:		ELIGIBLE	
Incident Ineligible Reason:		Not Reported	
Incident Ineligible Description:		Not reported	
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:		Cleanup Responsible:	STATE
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:		Not reported	
Response Record Type:		Not reported	
Response Remedial Action Plan Type:		Not reported	
Response Status:		Not reported	
Extension Record Type:		Not reported	
Extension Status:		Not reported	
Extension Comments:		Not reported	
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:		Not reported	
Response Record Type:		Not reported	
Response Remedial Action Plan Type:		Not reported	
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:		Not reported	
Estimated Completion Year:		Not reported	
Actual Year to Complete:		Not reported	
Report Type:		Not reported	
Report Comments:		Not reported	
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:		Not reported	
Flag:		Not reported	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

UST:

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 N CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 N CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY 1508 N CLARK AVE TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 N CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 N CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

TAMPA CITY-DPW FLEET MAINT-DIV #7 (Continued)

U001354877

Facility ID:	298625671	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DEPT OF PUBLIC WORKS		
Contact:	Not reported	Facility Phone:	8138763536
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	CHARLES SWARENS		
Owner:	TAMPA CITY		
	1508 N CLARK AVE		
	TAMPA, FL 336072307		
Owner's Phone:	8138781001	Tracking #:	292535
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

265

SIR SPEEDY
501 E JACKSON STREET
TAMPA, FL 33602

RCRIS-SQG 1000502617
FINDS FLD984227843

RCRIS:

Owner: PAUL GRAVES, DEALER
(813) 228-8811

Contact: PAUL GRAVES
(813) 228-8811

Waste	Quantity	Info Source
D011	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

266

CON AGRA, INC.
110 S NEBRASKA AVE
TAMPA, FL 33602

UST U001355126
LUST N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CON AGRA, INC. (Continued)

U001355126

LUST:

Facility ID:	8627167	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132279444	Alias Name 1:	Not reported
Discovery Date:	11/14/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: Not reported

Est. Gallons Lost: Not reported

Pollutant 2: Not reported

Est. Gallons Lost: Not reported

Pollutant 3: Not reported

Est. Gallons Lost: Not reported

INCIDENT PROGRAM INFORMATION -

Incident Program:

RESPONSIBLE PARTY-NO CLAIM

Incident Program Type:

Not reported

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

CON AGRA, INC. (Continued)

U001355126

UST:

Facility ID:	298627167	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BURRIS,DAN		
Contact:	Not reported	Facility Phone:	8132279444
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861028	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RANDY GARVERT		
Owner:	CON AGRA INC		
	110 S NEBRASKA AVE		
	TAMPA, FL 336025530		
Owner's Phone:	8132234741	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	79/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627167	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BURRIS,DAN		
Contact:	Not reported	Facility Phone:	8132279444
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861028	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	RANDY GARVERT		
Owner:	CON AGRA INC		
	110 S NEBRASKA AVE		
	TAMPA, FL 336025530		
Owner's Phone:	8132234741	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	79/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

CON AGRA, INC. (Continued)

U001355126

Facility ID:	298627167	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BURRIS,DAN		
Contact:	Not reported	Facility Phone:	8132279444
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861028	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	RANDY GARVERT		
Owner:	CON AGRA INC		
	110 S NEBRASKA AVE		
	TAMPA, FL 336025530		
Owner's Phone:	8132234741	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	79/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298627167	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BURRIS,DAN		
Contact:	Not reported	Facility Phone:	8132279444
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861028	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	RANDY GARVERT		
Owner:	CON AGRA INC		
	110 S NEBRASKA AVE		
	TAMPA, FL 336025530		
Owner's Phone:	8132234741	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	79/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/11
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
266	CONAGRA 110 S NEBRASKA AVE TAMPA, FL 33602 Other Pertinent Environmental Activity Identified at Site: facility has an emission permit under the Clean Air Act facility is involved with pesticide/toxic substances production	FINDS	1000497436 FLD061431920
267	TAMPA,CITY-FIRE STATION #6 311 S 22ND ST TAMPA, FL 33605	UST LUST	U001355926 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-FIRE STATION #6 (Continued)

U001355926

LUST:

Facility ID:	8842516	Facility Type:	LOCAL, CITY GOVERNMENT
Telephone:	8132255729	Alias Name 1:	Not reported
Discovery Date:	12/12/88	Alias Name 2:	Not reported
Tracking Number:	295181	Alias Name 3:	Not reported
Score:	040	Alias Name 4:	Not reported
Rank:	02475	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: LEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

STATE

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

APPROVED

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

LOCAL PROGRAM

Response Record Type:

REMEDIAL ACTION PLAN

Response Remedial Action Plan Type:

MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

LOCAL PROGRAM

Estimated Completion Year:

00

Actual Year to Complete:

00

Report Type:

QUARTERLY

Report Comments:

FIRST QTR

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

TAMPA,CITY-FIRE STATION #6 (Continued)

U001355926

UST:

Facility ID:	298842516	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	295181
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298842516	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881228	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	295181
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

267

CONVENIENCE CENTER
301 S 22ND ST
TAMPA, FL 33605

UST
LUST

U001354826
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CONVENIENCE CENTER (Continued)

U001354826

LUST:

Facility ID:	8625619	Facility Type:	RETAIL STATION
Telephone:	8132471116	Alias Name 1:	PHILLIPS 66-JOE PASCIUTAS
Discovery Date:	03/27/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

RESPONSIBLE PARTY-NO CLAIM

Incident Program Type:

Not reported

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Ait. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

CONVENIENCE CENTER (Continued)

U001354826

UST:

Facility ID:	298625619	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PEGUERO, LUIS A		
Contact:	Not reported	Facility Phone:	8132471116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	LUIS PEGUERO		
Owner:	PEGUERO, LUIS A		
	301 S 22ND ST		
	TAMPA, FL 336050000		
Owner's Phone:	8132471116	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	50/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625619	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PEGUERO, LUIS A		
Contact:	Not reported	Facility Phone:	8132471116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	LUIS PEGUERO		
Owner:	PEGUERO, LUIS A		
	301 S 22ND ST		
	TAMPA, FL 336050000		
Owner's Phone:	8132471116	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	50/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

CONVENIENCE CENTER (Continued)

U001354826

Facility ID:	298625619	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PEGUERO, LUIS A		
Contact:	Not reported	Facility Phone:	8132471116
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860522	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	LUIS PEGUERO		
Owner:	PEGUERO, LUIS A		
	301 S 22ND ST		
	TAMPA, FL 336050000		
Owner's Phone:	8132471116	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	75/12
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

268

FL BLUEPRINT
101 S 12TH ST
TAMPA, FL 33602

UST

U001355277
N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

FL BLUEPRINT (Continued)

U001355277

UST:

Facility ID:	298627847	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL BLUEPRINT		
Contact:	Not reported	Facility Phone:	8132212094
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ED MC GRAFF		
Owner:	BISSETT & MC GRAFF		
	101 E KENNEDY BLVD		
	TAMPA, FL 336025133		
Owner's Phone:	8132292929	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298627847	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL BLUEPRINT		
Contact:	Not reported	Facility Phone:	8132212094
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861106	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ED MC GRAFF		
Owner:	BISSETT & MC GRAFF		
	101 E KENNEDY BLVD		
	TAMPA, FL 336025133		
Owner's Phone:	8132292929	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	69/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

269

GARRISON STEVEDORING,INC.
101 S 13TH ST
TAMPA, FL 33602

UST
LUST

U001355392
N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

GARRISON STEVEDORING,INC. (Continued)

U001355392

UST:

Facility ID:	298732411	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GARRISON STEVEDORING,INC.		
Contact:	Not reported	Facility Phone:	8132291958
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870413	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE H. PATE		
Owner:	GARRISON STEVEDORING INC		
	101 S 13TH ST		
	TAMPA, FL 336024213		
Owner's Phone:	8132291958	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	86/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298732411	Facility Type:	Non-retail Business
Is fac. regulated.:	Not regulated facility	Is facility open:	Closed
Operator:	GARRISON STEVEDORING,INC.		
Contact:	Not reported	Facility Phone:	8132291958
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870413	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE H. PATE		
Owner:	GARRISON STEVEDORING INC		
	101 S 13TH ST		
	TAMPA, FL 336024213		
Owner's Phone:	8132291958	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00005000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	86/06
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

270

MCF SYSTEMS ATLANTA INC
101 E KENNEDY BLVD #3170
TAMPA, FL 33602

RCRIS-SQG 1000133039
FINDS FLD984171462

RCRIS: Not Reported

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
271			SOUTHEAST FINANCIAL CTR ASSOC FLORIDA AVE & JACKSON ST TAMPA, FL 33602	FINDS UST LUST	1000739074 FLD984243725	
Other Pertinent Environmental Activity Identified at Site:						
facility has active water discharge permits						
LUST:						
Facility ID: 9102164 Facility Type: NON-RETAIL BUSINESS						
Telephone: 8132899491 Alias Name 1: Not reported						
Discovery Date: 07/23/90 Alias Name 2: Not reported						
Tracking Number: Not reported Alias Name 3: Not reported						
Score: 000 (LOW) Alias Name 4: Not reported						
Rank: 00000 Alias Name 5: Not reported						
Class: Not reported						
Category: Not reported						
Facility Code: Not reported Status: Not reported						
INCIDENT GENERAL INFORMATION -						
Source Description: DISCHARGE NOTIFICATION						
Lead: LOCAL PROGRAM						
Incident 17-770 Cleanup: Not reported						
INCIDENT POLLUTANT INFORMATION -						
Pollutant 1: GENERIC GAS Est. Gallons Lost: 00000050						
Pollutant 2: Not reported Est. Gallons Lost: 00000000						
Pollutant 3: Not reported Est. Gallons Lost: 00000000						
INCIDENT PROGRAM INFORMATION -						
Incident Program: RESPONSIBLE PARTY-NO CLAIM						
Incident Program Type: Not reported						
Incident Eligible Status: Not reported						
Incident Ineligible Reason: Not Reported						
Incident Ineligible Description: Not reported						
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -						
Free Product: Cleanup Responsible: Not reported						
Soil Removal: Alt. Process Date: Not reported						
Soil Treatment: Alternative Status: Not reported						
Other Treatment:						
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -						
Cleanup Responsible: Not reported						
Response Record Type: Not reported						
Response Remedial Action Plan Type: Not reported						
Response Status: Not reported						
Extension Record Type: Not reported						
Extension Status: Not reported						
Extension Comments: Not reported						
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -						
Cleanup Responsible: Not reported						
Response Record Type: Not reported						
Response Remedial Action Plan Type: Not reported						
INCIDENT REMEDIAL ACTION REPORT INFORMATION -						
Cleanup Responsible: Not reported						
Estimated Completion Year: Not reported						
Actual Year to Complete: Not reported						
Report Type: Not reported						
Report Comments: Not reported						
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -						
Site Rehab. Completion Action: Not reported						
Flag: Not reported						

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

SOUTHEAST FINANCIAL CTR ASSOC (Continued)

1000739074

UST:

Facility ID:	299102164	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD E MAYER		
Contact:	Not reported	Facility Phone:	8132899491
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910530	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	RICHARD E MAYER		
Owner:	SOUTHEAST FINANCIAL CENTER		
	401 EAST JACKSON ST		
	TAMPA, FL		
Owner's Phone:	8132899491	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

272

LOGAN LUMBER CO.
301 N ROME AVE
TAMPA, FL 33606

UST

U001355205
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LOGAN LUMBER CO. (Continued)

U001355205

UST:

Facility ID:	298627413	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LOGAN LUMBER CO.		
Contact:	Not reported	Facility Phone:	8132533445
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	W.F. CHASTAIN, JR.		
Owner:	LOGAN LUMBER CO 301 N ROME AVE TAMPA, FL 336061641		
Owner's Phone:	8132533445	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298627413	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LOGAN LUMBER CO.		
Contact:	Not reported	Facility Phone:	8132533445
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861031	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	W.F. CHASTAIN, JR.		
Owner:	LOGAN LUMBER CO 301 N ROME AVE TAMPA, FL 336061641		
Owner's Phone:	8132533445	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
273	PILGRIM PERMOCOAT INC 402 S 22ND ST TAMPA, FL 33605 Other Pertinent Environmental Activity Identified at Site: facility is involved with pesticide/toxic substances production	FINDS	1000496919 FLD004100756
274	ALLRIGHT FLORIDA INC 403 WASHINGTON E TAMPA, FL 33602 UST: Facility ID: 299400569 Is fac. regulated: Not regulated facility Operator: WILLIAM PAUL Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 940406 Tank ID: 1 Owner's Contact: WILLIAM R PAUL Owner: LAURALEA LTD 101 E KENNEDY BLVD SUITE 2000 TAMPA, FL 336020000 Owner's Phone: 8132292111 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000550 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not required	UST	U001823410 N/A
	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132292111 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Pollutant Last used Date: 91/03 RPT by Tank #: Not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

ALLRIGHT FLORIDA INC (Continued)

U001823410

Facility ID:	299400569	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM PAUL		
Contact:	Not reported	Facility Phone:	8132292111
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940406	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WILLIAM R PAUL		
Owner:	LAURALEA LTD		
	101 E KENNEDY BLVD SUITE 2000		
	TAMPA, FL 336020000		
Owner's Phone:	8132292111	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299400569	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM PAUL		
Contact:	Not reported	Facility Phone:	8132292111
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940406	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	WILLIAM R PAUL		
Owner:	LAURALEA LTD		
	101 E KENNEDY BLVD SUITE 2000		
	TAMPA, FL 336020000		
Owner's Phone:	8132292111	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	91/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

275

BRINKS OF FL
1102 N "B" ST
TAMPA, FL 33606

UST
LUST

U001355079
N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

BRINKS OF FL (Continued)

U001355079

LUST:

Facility ID:	8627003	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132533471	Alias Name 1:	Not reported
Discovery Date:	02/13/90	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: LEADED GAS

Pollutant 2: DIESEL

Pollutant 3: Not reported

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

RESPONSIBLE PARTY-NO CLAIM

STATE CLEANUP

Not reported

Not Reported

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

CONTAMINATION ASSESSMENT REPORT

Not reported

APPROVED

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Flag:

NO FURTHER ACTION

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BRINKS OF FL (Continued)

U001355079

UST:

Facility ID:	298627003	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAEZ PETE		
Contact:	Not reported	Facility Phone:	8132533471
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	PETE BAEZ		
Owner:	BRINKS OF FL		
	1102 NORTH "B" STREET		
	TAMPA, FL 33606		
Owner's Phone:	8132533471	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	77/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298627003	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAEZ PETE		
Contact:	Not reported	Facility Phone:	8132533471
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861024	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	PETE BAEZ		
Owner:	BRINKS OF FL		
	1102 NORTH "B" STREET		
	TAMPA, FL 33606		
Owner's Phone:	8132533471	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

276

MARATHON OIL CO
425 S 20TH ST
TAMPA, FL 33675

FINDS

1000733506
FLD065919763

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

276	MARATHON OIL CO , 425 S 20TH ST TAMPA, FL 46222	RCRIS-LQG LUST	1000892606 FLD065919763
-----	---	-------------------	----------------------------

RCRIS:

Owner: NELSON ALMOND, ENV COOR
(317) 244-9551

Contact: G SHEELY
(419) 422-2121

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
D018	.00000 (T)	Notification			

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

276	MARATHON OIL CO 425 S 20TH ST TAMPA, FL 33605	UST AST	U001355739 N/A
-----	---	------------	-------------------

UST:

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Contact:	Not reported	Facility Phone:	8132471459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	OWS1	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO 539 S MAIN ST % DAVID SIEBOLD FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/01
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Contact:	Not reported	Facility Phone:	8132471459
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	OWS2	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/01
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	GW mon plan, SPCC plan		

AST:

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	11-30	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00413868
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	41/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	13-27	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00534156
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	57/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	17-31	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00632478
Tank Content:	Aviation gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	64/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	17-32	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00642138
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	59/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		
Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	21-2	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00877338
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	39/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	91/03	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	SPCC plan		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	21-8	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00904344
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	39/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	24-24	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00901866
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	60/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	25-12	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00922908
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	39/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	27-23	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	00878724
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	54/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	30-13	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO 539 S MAIN ST % DAVID SIEBOLD FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01026606
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	49/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	30-9	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO 539 S MAIN ST % DAVID SIEBOLD FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01160754
Tank Content:	Kerosene	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	54/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	SPCC plan		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	33-26	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01230642
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	60/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	33-29	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01157142
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	59/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Man sample wells, Auto tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	35-7	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01168272
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	70/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	93/04	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	38-25	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01473696
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	20/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	43-21	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01522374
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	54/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	43-28	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01523130
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	59/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	Man sample wells, Auto tank gauging		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	54-22	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	02043384
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	66/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	55-10	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01954596
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	54/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	55-14	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01951698
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	54/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	91/12	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Int lined steel, Cath prot-sac anode, Cath prot-imp curr, Spill cnmt, Field erected		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan, Auto tank gauging		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	55-3	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01961610
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	Temp out of serv	Install. Date:	55/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	93/05	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Cath prot-imp curr		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	55-4	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	01957704
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	55/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-11	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	03151638
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	65/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-17	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	02939538
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	57/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-18	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	02906946
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	59/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-19	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	03112536
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	80-6	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Avoveground	Tank Cap. (Gals):	02954532
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	59/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Cath prot-sac anode		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	AA10-2	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Field erected		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	AA10-3	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00010000
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Field erected		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	AA84	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	80/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Field erected		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	AA85	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00008000
Tank Content:	Petroleum additive	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, Cath prot-imp curr, AST containment area, Op-flow shut off		
Tank Piping:	Unprotec metal, Cathod prot steel		
Petro. Monitoring:	SPCC plan, Man tank gauging		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MARATHON OIL CO (Continued)

U001355739

Facility ID:	298837986	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY D DAVIS		
Facility Phone:	8132471459	Permit Section:	00000
Date entered:	880122	Financial responsibility:	State PRGM (Self/Other)
Tank ID:	T-5	District:	Southwest
Owner's Contact:	DAVID SIEBOLD		
Owner:	MARATHON OIL CO		
	539 S MAIN ST % DAVID SIEBOLD		
	FINDLAY, OH 458403229		
Owner's Phone:	4194212629	Tracking #:	291252
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00019488
Tank Content:	Other	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Field erected		
Tank Piping:	Cathod prot steel		
Petro. Monitoring:	GW mon plan, SPCC plan		

277

ANTHONY DISTRIBUTORS INC
201 S CEASAR
TAMPA, FL 33605

RCRIS-SQG
FINDS

1000243609
FLD032761389

RCRIS:

Owner: RICHARD ETEN
(813) 224-0438

Contact: RICHARD ETEN
(813) 224-0438

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

277

ANTHONY DISTRIBUTORS INC
201 S CAESAR ST
TAMPA, FL 33602

UST

U001962949
N/A

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			ANTHONY DISTRIBUTORS INC (Continued)		U001962949	
			UST: Facility ID: 299401349 Is fac. regulated: Not regulated facility Operator: Not reported Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 940810 Tank ID: NONE Owner's Contact: GEORGE SANDS Owner: ANTHONY DISTRIBUTORS INC 2900 EAST 7TH AVE TAMPA, FL 33605 Owner's Phone: 8132297191 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): Not reported Tank position: Not reported Tank Content: Not reported Disposal Method: Not reported Is tank regulated: Not reported Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Not reported	Facility Type: Non-retail Business Is facility open: Open Facility Phone: 8132297191 Region: Not reported Financial responsibility: Oth Apprvd Coverage District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Not reported Last used Date: Not reported RPT by Tank #: Not reported		
278			RIVER PLACE 238 W KENNEDY BLVD TAMPA, FL 33606	UST	U002038285	N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

RIVER PLACE (Continued)

U002038285

UST:

Facility ID:	299401996	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Open
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	8132734200
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	941122	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	CARTER MCCAIN		
Owner:	HILLSBOROUGH EAGLE & PARKER REAL		
	PO BOX 1531		
	TAMPA, FL 33601		
Owner's Phone:	8132734200	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

279

TAMPA,CITY-CITY CENTER
201 N FRANKLIN
TAMPA, FL 33602

UST

U001355143
N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

TAMPA,CITY-CITY CENTER (Continued)

U001355143

UST:

Facility ID:	298627221	Facility Type:	Local, City Government
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	JOHN HORN		
Contact:	Not reported	Facility Phone:	8132235008
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861029	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN C HORN		
Owner:	TAMPA CITY CENTER ASSOCIATES		
	ONE TAMPA CITY CENTER #1766		
	TAMPA, FL 336025193		
Owner's Phone:	8132235008	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003200	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

279

ONE TAMPA CITY CENTER
201 N FRANKLIN ST #1766
TAMPA, FL 33602

RCRIS-SQG 1000687555
FINDS FLD984238154

RCRIS:

Owner: CLIFFORD FISH, ASST CHIEF ENG
(813) 223-5008
Contact:CLIFFORD FISH
(813) 223-5008

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F001	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

280

KENNEY PROPERTY
209 S 12TH ST
TAMPA, FL

UST
LUST

U001378129
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KENNEY PROPERTY (Continued)

U001378129

LUST:

Facility ID:	9300022	Facility Type:	NON-RETAIL BUSINESS
Telephone:	9046346124	Alias Name 1:	Not reported
Discovery Date:	08/11/93	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

CLOSURE REPORT

Lead:

Not reported

Incident 17-770 Cleanup:

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KENNEY PROPERTY (Continued)

U001378129

UST:

Facility ID:	299300022	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNEY, MICHAEL C		
Contact:	Not reported	Facility Phone:	9046346124
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930119	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	MICHAEL KENNEY		
Owner:	KENNEY, MICHAEL C		
	7595 BAYMEADOWS CIR W #2305		
	JACKSONVILLE, FL 322150000		
Owner's Phone:	9047319979	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299300022	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNEY, MICHAEL C		
Contact:	Not reported	Facility Phone:	9046346124
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930119	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	MICHAEL KENNEY		
Owner:	KENNEY, MICHAEL C		
	7595 BAYMEADOWS CIR W #2305		
	JACKSONVILLE, FL 322150000		
Owner's Phone:	9047319979	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

KENNEY PROPERTY (Continued)

U001378129

Facility ID:	299300022	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNEY, MICHAEL C		
Contact:	Not reported	Facility Phone:	9046346124
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930119	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	MICHAEL KENNEY		
Owner:	KENNEY, MICHAEL C		
	7595 BAYMEADOWS CIR W #2305		
	JACKSONVILLE, FL 322150000		
Owner's Phone:	9047319979	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299300022	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Closed
Operator:	KENNEY, MICHAEL C		
Contact:	Not reported	Facility Phone:	9046346124
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	930119	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	MICHAEL KENNEY		
Owner:	KENNEY, MICHAEL C		
	7595 BAYMEADOWS CIR W #2305		
	JACKSONVILLE, FL 322150000		
Owner's Phone:	9047319979	Tracking #:	Not reported
Cleanup Status:	Completed	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Unmaintained	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			KENNEY PROPERTY (Continued)			U001378129
			Facility ID: 299300022 Is fac. regulated: Regulated facility Operator: KENNEY, MICHAEL C Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 930119 Tank ID: 5 Owner's Contact: MICHAEL KENNEY Owner: KENNEY, MICHAEL C 7595 BAYMEADOWS CIR W #2305 JACKSONVILLE, FL 322150000 Owner's Phone: 9047319979 Cleanup Status: Completed Drink. Wat. Well: 0000 Tank Cap. (Gals): 00000888 Tank position: Not reported Tank Content: Not reported Disposal Method: Unmaintained Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 9046346124 Region: Not reported Financial responsibility: None District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported			
281			AMFAC FLUID POWER 1529 NORTH A ST TAMPA, FL 33606 RCRIS: Not Reported	RCRIS-SQG FINDS	1000143921 FLD981866163	
282			UNIV OF TAMPA 401 W KENNEDY BLVD TAMPA, FL 33606	UST LUST	U001355568 N/A	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNIV OF TAMPA (Continued)

U001355568

LUST:

Facility ID:	8735778	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132536227	Alias Name 1:	Not reported
Discovery Date:	03/05/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

DISTRICT OFFICE

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

PETRO. LIABILITY INS. & RESTOR.

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

INELIGIBLE

Incident Ineligible Reason:

NONCOMP 17-61, -761, -762 RULES

Incident Ineligible Description:

NONCOMP 17-61,

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

UNIV OF TAMPA (Continued)

U001355568

UST:

Facility ID:	298735778	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNIVERSITY OF TAMPA		
Contact:	Not reported	Facility Phone:	8132536227
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871026	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	STEVE MAULDIN		
Owner:	UNIVERSITY OF TAMPA PO BOX 76F TAMPA, FL 336031490		
Owner's Phone:	8132536227	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	86/01
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298735778	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	UNIVERSITY OF TAMPA		
Contact:	Not reported	Facility Phone:	8132536227
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871026	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	STEVE MAULDIN		
Owner:	UNIVERSITY OF TAMPA PO BOX 76F TAMPA, FL 336031490		
Owner's Phone:	8132536227	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

282

UNIVERSITY OF TAMPA
401 W KENNEDY BLVD
TAMPA, FL 33606

RCRIS-SQG 1000821544
FINDS FLD984245142

MAP FINDINGS

Map ID				
Direction				
Distance	Site	Database(s)	EDR ID Number	EPA ID Number

UNIVERSITY OF TAMPA (Continued)

1000821544

RCRIS:

Owner: GEORGE JACKSON, PROF
(813) 253-3333

Contact: GEORGE JACKSON
(813) 253-3333

Waste	Quantity	Info Source
-------	----------	-------------

D001	.00000 (T)	Notification
------	------------	--------------

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

283

USE 298943086
1200 SERTOMA DR
TAMPA, FL 33605

UST

U001356294
N/A

UST:

Facility ID:	299101307	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GULF MARINE REPAIR CORP		
Contact:	Not reported	Facility Phone:	8132473153
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910329	Financial responsibility:	Not reported
Tank ID:	NONE	District:	Southwest
Owner's Contact:	HAROLD PEMBERTON		
Owner:	TAMPA PORT AUTHORITY PO BOX 2192 TAMPA, FL 336012192		
Owner's Phone:	8132481924	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

283

GULF MARINE REPAIR CORP
1200 SERTOMA DR
TAMPA, FL 33605

FINDS	1000821959
RCRIS-LQG	FLD984249805
UST	
LUST	
AST	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GULF MARINE REPAIR CORP (Continued)

1000821959

RCRIS:

Owner: PHILIP REUBEN, SAFETY & ENV DIR
(813) 247-3153

Contact: PHILIP REUBEN
(813) 247-3153

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	F003	.00000 (T)	Notification
F005	.00000 (T)	Notification	P028	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

There are 1 compliance/violation record(s) reported at this site:

Evaluation	Date	Violations
COMPLIANCE EVALUATION INSPECTION (CEI)	10-NOV-92	YES

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GULF MARINE REPAIR CORP (Continued)

1000821959

LUST:

Facility ID:	8943086	Facility Type:	TERMINAL FACILITY
Telephone:	8132473153	Alias Name 1:	Not reported
Discovery Date:	12/23/88	Alias Name 2:	Not reported
Tracking Number:	298690	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: Not reported

Est. Gallons Lost: Not reported

Pollutant 2: Not reported

Est. Gallons Lost: Not reported

Pollutant 3: Not reported

Est. Gallons Lost: Not reported

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: STATE

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

GULF MARINE REPAIR CORP (Continued)

1000821959

UST:

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Contact:	Not reported	Facility Phone:	8132473153
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR		
	1200 SERTOMA DR		
	TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Cleanup Status:	Ongoing	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

AST:

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Facility Phone:	8132473153	Permit Section:	00000
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR		
	1200 SERTOMA DR		
	TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00030000
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Corrosion resis coated, Suction piping		
Petro. Monitoring:	Auto tank gauging, Vapor monitoring		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GULF MARINE REPAIR CORP (Continued)

1000821959

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Facility Phone:	8132473153	Permit Section:	00000
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	11	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR 1200 SERTOMA DR TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001833
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Corrosion resis coated, Suction piping		
Petro. Monitoring:	Not required		

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Facility Phone:	8132473153	Permit Section:	00000
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	12	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR 1200 SERTOMA DR TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001833
Tank Content:	Diesel-gen/pump	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Corrosion resis coated, Suction piping		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GULF MARINE REPAIR CORP (Continued)

1000821959

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Facility Phone:	8132473153	Permit Section:	00000
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	13	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR 1200 SERTOMA DR TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000500
Tank Content:	Unleaded gas	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	89/05
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Corrosion resis coated, Suction piping		
Petro. Monitoring:	Not required		

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Facility Phone:	8132473153	Permit Section:	00000
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR 1200 SERTOMA DR TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00035000
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Corrosion resis coated, Suction piping		
Petro. Monitoring:	Auto tank gauging, Vapor monitoring		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GULF MARINE REPAIR CORP (Continued)

1000821959

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Facility Phone:	8132473153	Permit Section:	00000
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR 1200 SERTOMA DR TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00030000
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Corrosion resis coated, Suction piping		
Petro. Monitoring:	Auto tank gauging, Vapor monitoring		

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Facility Phone:	8132473153	Permit Section:	00000
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR 1200 SERTOMA DR TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003000
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgrnd-no contact w/soil, Unprotec metal, Corrosion resis coated, Suction piping		
Petro. Monitoring:	Auto tank gauging, Vapor monitoring		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GULF MARINE REPAIR CORP (Continued)

1000821959

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Facility Phone:	8132473153	Permit Section:	00000
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR		
	1200 SERTOMA DR		
	TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00003000
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Abvgnd-no contact w/soil, Unprotec metal, Corrosion resis coated, Suction piping		
Petro. Monitoring:	Auto tank gauging, Vapor monitoring		

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Facility Phone:	8132473153	Permit Section:	00000
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR		
	1200 SERTOMA DR		
	TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00007500
Tank Content:	Waste oil	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Suction piping		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GULF MARINE REPAIR CORP (Continued)

1000821959

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Facility Phone:	8132473153	Permit Section:	00000
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR 1200 SERTOMA DR TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Suction piping		
Petro. Monitoring:	Not required		

Facility ID:	298943086	Facility Type:	Terminal Facility
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	BRAUHMANN, JAMES		
Facility Phone:	8132473153	Permit Section:	00000
Date entered:	890202	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	JIM BRAUHMANN		
Owner:	GULF MARINE REPAIR 1200 SERTOMA DR TAMPA, FL 336056050		
Owner's Phone:	8132473153	Tracking #:	298690
Drink. Wat. Well:	0000	Any contaminated soil:	No
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000300
Tank Content:	Vehic diesel	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Bare/asph steel, AST containment area		
Tank Piping:	Suction piping		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			GULF MARINE REPAIR CORP (Continued)		1000821959	
			Facility ID: 298943086 Is fac. regulated: Regulated facility Operator: BRAUHMANN, JAMES Facility Phone: 8132473153 Date entered: 890202 Tank ID: 9 Owner's Contact: JIM BRAUHMANN Owner: GULF MARINE REPAIR 1200 SERTOMA DR TAMPA, FL 336056050 Owner's Phone: 8132473153 Drink. Wat. Well: 0000 Cleanup Status: Ongoing Tank position: Aboveground Tank Content: Waste oil Disposal Method: In service Is tank regulated: Regulated tank Last used Date: Not reported RPT Tank #: Not reported Tank Constr.: Bare/asph steel, AST containment area Tank Piping: Suction piping Petro. Monitoring: Not required	Facility Type: Terminal Facility Is facility open: Open Permit Section: 00000 Financial responsibility: Not reported District: Southwest Tracking #: 298690 Any contaminated soil: No Any contaminated surface water: No Tank Cap. (Gals): 00001000 Contaminated media indicator: No Install. Date: Not reported Content Category: Pollutant Any contaminated groundwater: No RPT by Tank #: Not reported		
284			PIONEER PROPERTIES ASSOCIATES,LTD 100 TAMPA ST TAMPA, FL 33602	UST LUST	U001545547 N/A	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PIONEER PROPERTIES ASSOCIATES,LTD (Continued)

U001545547

LUST:

Facility ID:	8942888	Facility Type:	NON-RETAIL BUSINESS
Telephone:	0000000000	Alias Name 1:	Not reported
Discovery Date:	09/15/89	Alias Name 2:	Not reported
Tracking Number:	296110	Alias Name 3:	Not reported
Score:	011 (LOW)	Alias Name 4:	Not reported
Rank:	06640	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	SPENT MOTOR OIL	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

PIONEER PROPERTIES ASSOCIATES,LTD (Continued)

U001545547

UST:

Facility ID:	298942888	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PIONEER PROPERTIES ASSOC,LTD		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890124	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	ROBERT A CLOYD		
Owner:	PIONEER PROPERTIES ASSOC LTD		
	101 E KENNEDY BLVD #4000		
	TAMPA, FL 336025191		
Owner's Phone:	8132217200	Tracking #:	296110
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000888	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	74/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298942888	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PIONEER PROPERTIES ASSOC,LTD		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890124	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	ROBERT A CLOYD		
Owner:	PIONEER PROPERTIES ASSOC LTD		
	101 E KENNEDY BLVD #4000		
	TAMPA, FL 336025191		
Owner's Phone:	8132217200	Tracking #:	296110
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

PIONEER PROPERTIES ASSOCIATES,LTD (Continued)

U001545547

Facility ID:	298942888	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	PIONEER PROPERTIES ASSOC,LTD		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	890124	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	ROBERT A CLOYD		
Owner:	PIONEER PROPERTIES ASSOC LTD		
	101 E KENNEDY BLVD #4000		
	TAMPA, FL 336025191		
Owner's Phone:	8132217200	Tracking #:	296110
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

285	FOGARTY VAN LINES 1103 CUMBERLAND AVE TAMPA, FL 33601	RCRIS-SQG	1000702132 FLD984196949
-----	---	-----------	----------------------------

RCRIS:

Owner: KEN NEWMAN, MGR
(813) 228-7481

Contact: KEN NEWMAN
(813) 228-7481

Waste	Quantity	Info Source	Waste	Quantity	Info Source
D001	.00000 (T)	Notification	D002	.00000 (T)	Notification
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

285	FOGARTY VAN LINES 1103 CUMBERLAND AVE TAMPA, FL 33602	FINDS	1000737077 FLD984196949
-----	---	-------	----------------------------

285	FOGARTY VAN LINES-OFFICE 1103 E CUMBERLAND ST TAMPA, FL 33601	UST LUST	U002113437 N/A
-----	---	-------------	-------------------

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FOGARTY VAN LINES-OFFICE (Continued)

U002113437

UST:

Facility ID:	299501591	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FOGARTY VAN LINES		
Contact:	Not reported	Facility Phone:	8132287481
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	950322	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	JERRY FOGARTY		
Owner:	FOGARTY, JERRY EUGENE SR		
	PO BOX 3402		
	TAMPA, FL 33601		
Owner's Phone:	8132287481	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

286

DIXIE NEON CO., INC.
608 S 22ND ST
TAMPA, FL 33605

LUST

U001354315
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DIXIE NEON CO., INC. (Continued)

U001354315

LUST:

Facility ID:	8625074	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132482531	Alias Name 1:	Not reported
Discovery Date:	12/28/88	Alias Name 2:	Not reported
Tracking Number:	298534	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

EDI

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: NOT ENTERED

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

EARLY DETECTION INCENTIVE

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: RESPONSIBLE PARTY

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

REMEDIAL ACTION PLAN

Response Remedial Action Plan Type:

MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

286

DIXIE NEON CO
608 S 22ND ST
TAMPA, FL 33605

RCRIS-SQG 1000450168
FINDS FLD984177238
UST

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number																		
	DIXIE NEON CO (Continued)		1000450168																		
	RCRIS: Owner: JOE WEST (813) 248-2531 Contact:JOE WEST (813) 248-2531																				
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D001</td><td>.00000 (T)</td><td>Notification</td><td>F003</td><td>.00000 (T)</td><td>Notification</td></tr><tr><td>F005</td><td>.00000 (T)</td><td>Notification</td><td></td><td></td><td></td></tr></table>	Waste	Quantity	Info Source	Waste	Quantity	Info Source	D001	.00000 (T)	Notification	F003	.00000 (T)	Notification	F005	.00000 (T)	Notification					
Waste	Quantity	Info Source	Waste	Quantity	Info Source																
D001	.00000 (T)	Notification	F003	.00000 (T)	Notification																
F005	.00000 (T)	Notification																			
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported																				
287	TRIBUNE CO INC 202 S. PARKER STREET TAMPA, FL 33601 RCRIS: Not Reported	RCRIS-SQG FINDS	1000497327 FLD052603206																		
288	ANTHONY DISTRIBUTORS INC 1710 W KENNEDY BLVD TAMPA, FL 33605	UST LUST	U001546601 N/A																		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

ANTHONY DISTRIBUTORS INC (Continued)

U001546601

LUST:

Facility ID:	9103523	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132240438	Alias Name 1:	Not reported
Discovery Date:	05/04/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

ABANDONED TANK RESTORATIO

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

ELIGIBLE

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ANTHONY DISTRIBUTORS INC (Continued)

U001546601

UST:

Facility ID:	299103523	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANTHONY DISTRIBUTORS INC		
Contact:	Not reported	Facility Phone:	8132240438
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911127	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	RICK ETEN		
Owner:	ANTHONY DISTRIBUTORS INC		
	2900 E 7TH AVE		
	TAMPA, FL 336054204		
Owner's Phone:	8132474000	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299103523	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ANTHONY DISTRIBUTORS INC		
Contact:	Not reported	Facility Phone:	8132240438
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	911127	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	RICK ETEN		
Owner:	ANTHONY DISTRIBUTORS INC		
	2900 E 7TH AVE		
	TAMPA, FL 336054204		
Owner's Phone:	8132474000	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

288

UNITED CHEM IND INC
110 N ROME AVE
TAMPA, FL 33606

FINDS

1000932919
FL0000651794

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
289	GTE OF FL HYDE PARK EAX CO 105 N EDISON AVE TAMPA, FL 33606	UST LUST	U001355312 N/A
	LUST:		
	Facility ID: 8627996	Facility Type: NON-RETAIL BUSINESS	
	Telephone: 8136214931	Alias Name 1: GENERAL TELE CO OF FL-HYDE PARK EAX CO	
	Discovery Date: 06/18/90	Alias Name 2: Not reported	
	Tracking Number: Not reported	Alias Name 3: Not reported	
	Score: 000 (LOW)	Alias Name 4: Not reported	
	Rank: 00000	Alias Name 5: Not reported	
	Class: Not reported		
	Category: Not reported		
	Facility Code: Not reported	Status: Not reported	
	INCIDENT GENERAL INFORMATION -		
	Source Description:	DISCHARGE NOTIFICATION	
	Lead:	LOCAL PROGRAM	
	Incident 17-770 Cleanup:	NEW C/U REQUIRED	
	INCIDENT POLLUTANT INFORMATION -		
	Pollutant 1: FUEL OIL-ON SITE	Est. Gallons Lost: UNKNOWN	
	Pollutant 2: Not reported	Est. Gallons Lost: 00000000	
	Pollutant 3: Not reported	Est. Gallons Lost: 00000000	
	INCIDENT PROGRAM INFORMATION -		
	Incident Program:	RESPONSIBLE PARTY-NO CLAIM	
	Incident Program Type:	STATE CLEANUP	
	Incident Eligible Status:	Not reported	
	Incident Ineligible Reason:	Not Reported	
	Incident Ineligible Description:	Not reported	
	INCIDENT INITIAL REMEDIAL ACTION INFORMATION -		
	Free Product:	Cleanup Responsible: Not reported	
	Soil Removal:	Alt. Process Date: Not reported	
	Soil Treatment:	Alternative Status: Not reported	
	Other Treatment:		
	INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -		
	Cleanup Responsible:	Not reported	
	Response Record Type:	Not reported	
	Response Remedial Action Plan Type:	Not reported	
	Response Status:	Not reported	
	Extension Record Type:	Not reported	
	Extension Status:	Not reported	
	Extension Comments:	Not reported	
	INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -		
	Cleanup Responsible:	Not reported	
	Response Record Type:	Not reported	
	Response Remedial Action Plan Type:	Not reported	
	INCIDENT REMEDIAL ACTION REPORT INFORMATION -		
	Cleanup Responsible:	Not reported	
	Estimated Completion Year:	Not reported	
	Actual Year to Complete:	Not reported	
	Report Type:	Not reported	
	Report Comments:	Not reported	
	INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -		
	Site Rehab. Completion Action:	Not reported	
	Flag:	Not reported	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GTE OF FL HYDE PARK EAX CO (Continued)

U001355312

UST:

Facility ID:	298627996	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO. OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001200	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	65/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	90/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	298627996	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	GENERAL TELEPHONE CO. OF FL		
Contact:	Not reported	Facility Phone:	8136214931
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861107	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1R1	District:	Southwest
Owner's Contact:	BARBARA E WILLIAMS		
Owner:	GENERAL TELEPHONE CO OF FL		
	PO BOX 110 MC 711		
	TAMPA, FL 336010110		
Owner's Phone:	8132244740	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	In service	Install. Date:	90/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	DW tank space, DW piping space		

290

DAVE MITCHELL'S GRAND CENTRAL GARAGE
1901 W. JF KENNEDY BLVD
TAMPA, FL 33606

UST
LUST

U001046264
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DAVE MITCHELL'S GRAND CENTRAL GARAGE (Continued)

U001046264

LUST:

Facility ID:	9201715	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8139337641	Alias Name 1:	GRAND CENTRAL GARAGE & BODYSHOP
Discovery Date:	06/19/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	010 (LOW)	Alias Name 4:	Not reported
Rank:	07198	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DAVE MITCHELL'S GRAND CENTRAL GARAGE (Continued)

U001046264

UST:

Facility ID:	299201715	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROTOLO, STEVE		
Contact:	Not reported	Facility Phone:	8139337641
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920623	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID M. MITCHELL		
Owner:	MITCHELL, DAVID M. 1812 E. BUSCH BLVD TAMPA, FL 33612		
Owner's Phone:	8139337641	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299201715	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROTOLO, STEVE		
Contact:	Not reported	Facility Phone:	8139337641
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920623	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVID M. MITCHELL		
Owner:	MITCHELL, DAVID M. 1812 E. BUSCH BLVD TAMPA, FL 33612		
Owner's Phone:	8139337641	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			
Direction			
Distance	Site	Database(s)	EDR ID Number EPA ID Number

DAVE MITCHELL'S GRAND CENTRAL GARAGE (Continued)

U001046264

Facility ID:	299201715	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROTOLO, STEVE		
Contact:	Not reported	Facility Phone:	8139337641
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920623	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	DAVID M. MITCHELL		
Owner:	MITCHELL, DAVID M. 1812 E. BUSCH BLVD TAMPA, FL 33612		
Owner's Phone:	8139337641	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

290

WELLS FARGO ARMORED SERVICE CORP.
1917 W KENNEDY BLVD
TAMPA, FL 33606

UST

U001355035
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

WELLS FARGO ARMORED SERVICE CORP. (Continued)

U001355035

UST:

Facility ID:	298626349	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WELLS FARGO ARMORED SERVICE CORP		
Contact:	Not reported	Facility Phone:	8132533115
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861010	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GREG BUSKO		
Owner:	WELLS FARGO ARMORED SERVICE CORP PO BOX 4313 % LEGAL DEPT ATLANTA, GA 303029981		
Owner's Phone:	4048766484	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298626349	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WELLS FARGO ARMORED SERVICE CORP		
Contact:	Not reported	Facility Phone:	8132533115
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861010	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GREG BUSKO		
Owner:	WELLS FARGO ARMORED SERVICE CORP PO BOX 4313 % LEGAL DEPT ATLANTA, GA 303029981		
Owner's Phone:	4048766484	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	81/XX
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

291

FERMAN MOTOR LEASING
1600 W KENNEDY BLVD
TAMPA, FL 33606

UST

U001355514
N/A

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	FERMAN MOTOR LEASING (Continued)		U001355514
	UST: Facility ID: 298733903 Facility Type: Non-retail Business Is fac. regulated: Not regulated facility Is facility open: Closed Operator: FERMANT MOTOR LEASING Contact: Not reported Facility Phone: 8132530681 Permit Section: Not reported Region: Not reported Facility Code: No violation Date entered: 870730 Financial responsibility: Not reported Tank ID: 1 District: Southwest Owner's Contact: STEVE SCOTT Owner: FERMANT MOTOR LEASING 1307 W KENNEDY BLVD TAMPA, FL 336061848 Owner's Phone: 8132530681 Tracking #: Not reported Cleanup Status: Not reported Any contaminated soil: Not reported Drink. Wat. Well: Not reported Any contaminated surface water: Not reported Tank Cap. (Gals): 00000550 Any monit. wells: Not reported Tank position: Not reported Any contam. groundwater: Not reported Tank Content: Not reported Contaminated media indicator: Not reported Disposal Method: Closed in place Install. Date: Not reported Is tank regulated: Not regulated tank Content Category: Vehicular Facility Status: Not reported Last used Date: 88/11 RPT Tank #: Not reported RPT by Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported		
291	DELUXE UNIFORM RENTAL SERVICE 1622 W KENNEDY BLVD TAMPA, FL 33606 RCRIS: Owner: CLARENCE BAKER, PRES (813) 254-2340 Contact: CLARENCE BAKER (813) 254-2340 Waste Quantity * Info Source F002 .00000 (T) Notification (P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported	RCRIS-SQG FINDS	1000450169 FLD984177329
292	SOUTHERN EQUIPMENT CORP. 1525 W KENNEDY BLVD TAMPA, FL 33606	UST	U001355129 N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

SOUTHERN EQUIPMENT CORP. (Continued)

U001355129

UST:

Facility ID:	298627181	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SOUTHERN EQUIPMENT CORP.		
Contact:	Not reported	Facility Phone:	8132511839
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861028	Financial responsibility:	Not reported
Tank ID:	B	District:	Southwest
Owner's Contact:	BARTON D. HARTSOCK		
Owner:	SOUTHERN EQUIPMENT CORP		
	1525 W KENNEDY BLVD		
	TAMPA, FL 336061647		
Owner's Phone:	8132511839	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

293

FERMAN OLDSMOBILE
1307 W KENNEDY BLVD
TAMPA, FL 33606

UST
LUST
AST

U001354972
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FERMAN OLDSMOBILE (Continued)

U001354972

LUST:

Facility ID:	8625770	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132530681	Alias Name 1:	Not reported
Discovery Date:	04/20/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

DISCHARGE NOTIFICATION

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

Pollutant 2: WASTE OIL

Est. Gallons Lost: UNKNOWN

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

REIMBURSEMENT CLEANUP

Incident Eligible Status:

INELIGIBLE

Incident Ineligible Reason:

OPERATING AFTER 3/90

Incident Ineligible Description:

OPERATING AFTER

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

APPROVED

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

REMEDIAL ACTION PLAN

Response Remedial Action Plan Type:

MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Estimated Completion Year:

00

Actual Year to Complete:

00

Report Type:

QUARTERLY

Report Comments:

1ST QUARTER (QTR)

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

FERMAN OLDSMOBILE (Continued)

U001354972

UST:

Facility ID:	298625770	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PHIL STUMP		
Contact:	Not reported	Facility Phone:	8132530681
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	J L FERMAN		
Owner:	FERMAN, J L SR 1307 W KENNEDY BLVD TAMPA, FL 336090000		
Owner's Phone:	8132530681	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	94/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625770	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PHIL STUMP		
Contact:	Not reported	Facility Phone:	8132530681
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	J L FERMAN		
Owner:	FERMAN, J L SR 1307 W KENNEDY BLVD TAMPA, FL 336090000		
Owner's Phone:	8132530681	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	76/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	94/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FERMAN OLDSMOBILE (Continued)

U001354972

Facility ID:	298625770	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PHIL STUMP		
Contact:	Not reported	Facility Phone:	8132530681
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	J L FERMAN		
Owner:	FERMAN, J L SR 1307 W KENNEDY BLVD TAMPA, FL 336090000		
Owner's Phone:	8132530681	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625770	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PHIL STUMP		
Contact:	Not reported	Facility Phone:	8132530681
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	J L FERMAN		
Owner:	FERMAN, J L SR 1307 W KENNEDY BLVD TAMPA, FL 336090000		
Owner's Phone:	8132530681	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	7
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FERMAN OLDSMOBILE (Continued)

U001354972

Facility ID:	298625770	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PHIL STUMP		
Contact:	Not reported	Facility Phone:	8132530681
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	None
Tank ID:	5	District:	Southwest
Owner's Contact:	J L FERMAN		
Owner:	FERMAN, J L SR 1307 W KENNEDY BLVD TAMPA, FL 336090000		
Owner's Phone:	8132530681	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/04
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298625770	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PHIL STUMP		
Contact:	Not reported	Facility Phone:	8132530681
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	None
Tank ID:	6	District:	Southwest
Owner's Contact:	J L FERMAN		
Owner:	FERMAN, J L SR 1307 W KENNEDY BLVD TAMPA, FL 336090000		
Owner's Phone:	8132530681	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FERMAN OLDSMOBILE (Continued)

U001354972

AST:

Facility ID:	298625770	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PHIL STUMP		
Facility Phone:	8132530681	Permit Section:	00000
Date entered:	860523	Financial responsibility:	None
Tank ID:	7	District:	Southwest
Owner's Contact:	J L FERMAN		
Owner:	FERMAN, J L SR		
	1307 W KENNEDY BLVD		
	TAMPA, FL 336090000		
Owner's Phone:	8132530681	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Waste oil	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	92/06
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	4	RPT by Tank #:	Not reported
Tank Constr.:	Compartmented		
Tank Piping:	Abvgrnd-no contact w/soil		
Petro. Monitoring:	None		

Facility ID:	298625770	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	PHIL STUMP		
Facility Phone:	8132530681	Permit Section:	00000
Date entered:	860523	Financial responsibility:	None
Tank ID:	8	District:	Southwest
Owner's Contact:	J L FERMAN		
Owner:	FERMAN, J L SR		
	1307 W KENNEDY BLVD		
	TAMPA, FL 336090000		
Owner's Phone:	8132530681	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00002000
Tank Content:	Unleaded gas	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	94/02
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Yes
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Overfill-ball check, Dbl walled=primary matl, AST containment area, Spill cnmt, Op-tight fill		
Tank Piping:	Abvgrnd-no contact w/soil, Suction piping		
Petro. Monitoring:	Tank liner space		

293

FERMAN OLDSMOBILE CO.
1307 W. KENNEDY BLVD
TAMPA, FL 33606

RCRIS-SQG
FINDS

1000295226
FLD124460932

RCRIS: Not Reported

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
294			THOMPSON AGGREGATE MATERIALS CO 1302 W KENNEDY BLVD TAMPA, FL 33606	UST LUST	U000117617 N/A	
LUST:						
Facility ID:		8626535	Facility Type:		NON-RETAIL BUSINESS	
Telephone:		8132533141	Alias Name 1:		Not reported	
Discovery Date:		05/06/91	Alias Name 2:		Not reported	
Tracking Number:		Not reported	Alias Name 3:		Not reported	
Score:		026 (LOW)	Alias Name 4:		Not reported	
Rank:		05095	Alias Name 5:		Not reported	
Class:		Not reported				
Category:		Not reported				
Facility Code:		Not reported	Status:		Not reported	
INCIDENT GENERAL INFORMATION -						
Source Description:			ABANDONED TANK RESTORATIO			
Lead:			LOCAL PROGRAM			
Incident 17-770 Cleanup:			NEW C/U REQUIRED			
INCIDENT POLLUTANT INFORMATION -						
Pollutant 1:		LEADED GAS	Est. Gallons Lost:		UNKNOWN	
Pollutant 2:		Not reported	Est. Gallons Lost:		00000000	
Pollutant 3:		Not reported	Est. Gallons Lost:		00000000	
INCIDENT PROGRAM INFORMATION -						
Incident Program:			ABANDONED TANK RESTORATION			
Incident Program Type:			REIMBURSEMENT CLEANUP			
Incident Eligible Status:			ELIGIBLE			
Incident Ineligible Reason:			Not Reported			
Incident Ineligible Description:			Not reported			
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -						
Free Product:			Cleanup Responsible:		Not reported	
Soil Removal:			Alt. Process Date:		Not reported	
Soil Treatment:			Alternative Status:		Not reported	
Other Treatment:						
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -						
Cleanup Responsible:			Not reported			
Response Record Type:			Not reported			
Response Remedial Action Plan Type:			Not reported			
Response Status:			Not reported			
Extension Record Type:			Not reported			
Extension Status:			Not reported			
Extension Comments:			Not reported			
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -						
Cleanup Responsible:			Not reported			
Response Record Type:			Not reported			
Response Remedial Action Plan Type:			Not reported			
INCIDENT REMEDIAL ACTION REPORT INFORMATION -						
Cleanup Responsible:			Not reported			
Estimated Completion Year:			Not reported			
Actual Year to Complete:			Not reported			
Report Type:			Not reported			
Report Comments:			Not reported			
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -						
Site Rehab. Completion Action:			Not reported			
Flag:			Not reported			

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

THOMPSON AGGREGATE MATERIALS CO (Continued)

U000117617

UST:

Facility ID:	298626535	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	THOMPSON AGGREGATE MATERIALS CO		
Contact:	Not reported	Facility Phone:	8132533141
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861016	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LESLIE THOMPSON		
Owner:	THOMPSON AGGREGATE MATERIALS CO		
	PO BOX 404		
	TAMPA, FL 336010000		
Owner's Phone:	8132533144	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	64/04
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

295

TAMPA,CITY-FIRE STATION #3
103 S NEWPORT AVE
TAMPA, FL 33606

UST

U001355888
N/A

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-FIRE STATION #3 (Continued)

U001355888

UST:

Facility ID:	298842207	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY-FIRE DEPT		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	86/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298842207	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY-FIRE DEPT		
Contact:	Not reported	Facility Phone:	8132255729
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	881129	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	BRIAN GUMMOE		
Owner:	TAMPA CITY FIRE DEPT 808 E ZACK ST TAMPA, FL 336023530		
Owner's Phone:	8132277011	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	86/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	90/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

295

SPUR #1254
1209 W KENNEDY BLVD
TAMPA, FL 33606

UST
LUST

U001354750
N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

SPUR #1254 (Continued)

U001354750

LUST:

Facility ID:	8625537	Facility Type:	RETAIL STATION
Telephone:	8139311989	Alias Name 1:	Not reported
Discovery Date:	10/14/93	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

CLOSURE REPORT

Lead:

Not reported

Incident 17-770 Cleanup:

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

PETRO. LIABILITY INS. & RESTOR.

Incident Program Type:

E

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

REMEDIAL ACTION PLAN

Response Remedial Action Plan Type:

MONITORING ONLY PLAN

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Estimated Completion Year:

00

Actual Year to Complete:

00

Report Type:

QUARTERLY

Report Comments:

O.K.

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SPUR #1254 (Continued)

U001354750

UST:

Facility ID:	298625537	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID ZAUMEYER		
Contact:	Not reported	Facility Phone:	8139311989
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	JOHN D KIRK		
Owner:	KIRK, JOHN D 62261 BIRCH DR BARNESVILLE, OH 437130000		
Owner's Phone:	6144252642	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625537	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID ZAUMEYER		
Contact:	Not reported	Facility Phone:	8139311989
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	JOHN D KIRK		
Owner:	KIRK, JOHN D 62261 BIRCH DR BARNESVILLE, OH 437130000		
Owner's Phone:	6144252642	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SPUR #1254 (Continued)

U001354750

Facility ID:	298625537	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID ZAUMEYER		
Contact:	Not reported	Facility Phone:	8139311989
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	JOHN D KIRK		
Owner:	KIRK, JOHN D 62261 BIRCH DR BARNESVILLE, OH 437130000		
Owner's Phone:	6144252642	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	60/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625537	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DAVID ZAUMEYER		
Contact:	Not reported	Facility Phone:	8139311989
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	JOHN D KIRK		
Owner:	KIRK, JOHN D 62261 BIRCH DR BARNESVILLE, OH 437130000		
Owner's Phone:	6144252642	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	85/02
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man tank gauging, GW monitoring, Vapor monitoring		

296

LEHOR, GEORGE
1100 W KENNEDY
TAMPA, FL

UST

U001963214
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LEHOR, GEORGE (Continued)

U001963214

UST:

Facility ID:	299401452	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	Not reported		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940816	Financial responsibility:	None
Tank ID:	NONE	District:	Southwest
Owner's Contact:	GEORGE LEHOR		
Owner:	LEHOR, GEORGE		
	247 MALAGA AVE		
	CORAL GABLES, FL 33134		
Owner's Phone:	3054484213	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	Not reported	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Not reported	Install. Date:	Not reported
Is tank regulated:	Not reported	Content Category:	Not reported
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not reported		

296

ASPHALT DRIVEWAY CO. OF FL,INC.
1107 W KENNEDY BLVD
TAMPA, FL 33606

UST
AST

U001355660
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ASPHALT DRIVEWAY CO. OF FL,INC. (Continued)

U001355660

UST:

Facility ID:	298736722	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ASPHALT DRIVEWAY CO. OF FL,INC.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871215	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	FRANCES L. LANE		
Owner:	LANE, FRANCES L 3001 W EUCLID AVE TAMPA, FL 336298954		
Owner's Phone:	3058311025	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298736722	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ASPHALT DRIVEWAY CO. OF FL,INC.		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871215	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	FRANCES L. LANE		
Owner:	LANE, FRANCES L 3001 W EUCLID AVE TAMPA, FL 336298954		
Owner's Phone:	3058311025	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/08
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			ASPHALT DRIVEWAY CO. OF FL,INC. (Continued)		U001355660	
			AST:			
			Facility ID: 298736722	Facility Type: Non-retail Business		
			Is fac. regulated: Not regulated facility	Is facility open: Closed		
			Operator: ASPHALT DRIVEWAY CO. OF FL,INC.			
			Facility Phone: Not reported	Permit Section: 00000		
			Date entered: 871215	Financial responsibility: Not reported		
			Tank ID: 1	District: Southwest		
			Owner's Contact: FRANCES L. LANE			
			Owner: LANE, FRANCES L			
			3001 W EUCLID AVE			
			TAMPA, FL 336298954			
			Owner's Phone: 3058311025	Tracking #: Not reported		
			Drink. Wat. Well: Not reported	Any contaminated soil: Not reported		
			Cleanup Status: Not reported	Any contaminated surface water: Not reported		
			Tank position: Aboveground	Tank Cap. (Gals): 00000500		
			Tank Content: Vehic diesel	Contaminated media indicator: Not reported		
			Disposal Method: Removed	Install. Date: Not reported		
			Is tank regulated: Not regulated tank	Content Category: Vehicular		
			Last used Date: 88/08	Any contaminated groundwater: Not reported		
			RPT Tank #: Not reported	RPT by Tank #: Not reported		
			Tank Constr.: Unknown/not reported			
			Tank Piping: Unknown/not reported			
			Petro. Monitoring: Unknown/not reported			
297			CHEVRON #48082-CHAIRES	UST	U001354585	
			901 W KENNEDY BLVD	LUST	N/A	
			TAMPA, FL 33606			

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48082-CHAIRES (Continued)

U001354585

LUST:

Facility ID:	8625365	Facility Type:	RETAIL STATION
Telephone:	Not reported	Alias Name 1:	Not reported
Discovery Date:	04/29/88	Alias Name 2:	Not reported
Tracking Number:	294583	Alias Name 3:	Not reported
Score:	020 (LOW)	Alias Name 4:	Not reported
Rank:	05579	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	EDI
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	GENERIC GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	EARLY DETECTION INCENTIVE
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CHEVRON #48082-CHAIRES (Continued)

U001354585

UST:

Facility ID:	298625365	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	E.E. CHAIRES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	4049843000	Tracking #:	294583
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	77/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625365	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	E.E. CHAIRES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO		
	PO BOX 1706		
	ATLANTA, GA 303011706		
Owner's Phone:	4049843000	Tracking #:	294583
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

CHEVRON #48082-CHAIRES (Continued)

U001354585

Facility ID:	298625365	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	E.E. CHAIRES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	CHERYL TENNEYCK		
Owner:	CHEVRON USA PRODUCTS CO PO BOX 1706 ATLANTA, GA 303011706		
Owner's Phone:	4049843000	Tracking #:	294583
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625365	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	E.E. CHAIRES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	CHERYL TENNEYCK		
Owner:	CHEVRON USA PRODUCTS CO PO BOX 1706 ATLANTA, GA 303011706		
Owner's Phone:	4049843000	Tracking #:	294583
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

CHEVRON #48082-CHAIRES (Continued)

U001354585

Facility ID:	298625365	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	E.E. CHAIRES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO PO BOX 1706 ATLANTA, GA 303011706		
Owner's Phone:	4049843000	Tracking #:	294583
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	87/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625365	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	E.E. CHAIRES		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860516	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	CHERYL TENEYCK		
Owner:	CHEVRON USA PRODUCTS CO PO BOX 1706 ATLANTA, GA 303011706		
Owner's Phone:	4049843000	Tracking #:	294583
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	63/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	87/09
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

297 TEXACO NO 242041327
900 W KENNEDY
TAMPA, FL 33606

FINDS 1000736002
UST FLD984172551

MAP FINDINGS

298

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
298	GANDY PAINT CO 606 KENNEDY BLVD TAMPA, FL 33606	UST LUST	U001356319 N/A
LUST:			
Facility ID: 9101617		Facility Type:	NON-RETAIL BUSINESS
Telephone: 8132535772		Alias Name 1:	Not reported
Discovery Date: 07/17/91		Alias Name 2:	Not reported
Tracking Number: Not reported		Alias Name 3:	Not reported
Score: 022 (LOW)		Alias Name 4:	Not reported
Rank: 05539		Alias Name 5:	Not reported
Class: Not reported			
Category: Not reported			
Facility Code: Not reported		Status:	Not reported
INCIDENT GENERAL INFORMATION -			
Source Description:		ABANDONED TANK RESTORATIO	
Lead:		LOCAL PROGRAM	
Incident 17-770 Cleanup:		NEW C/U REQUIRED	
INCIDENT POLLUTANT INFORMATION -			
Pollutant 1: UNKNOWN/NOT REPOR		Est. Gallons Lost:	UNKNOWN
Pollutant 2: Not reported		Est. Gallons Lost:	00000000
Pollutant 3: Not reported		Est. Gallons Lost:	00000000
INCIDENT PROGRAM INFORMATION -			
Incident Program:		ABANDONED TANK RESTORATION	
Incident Program Type:		REIMBURSEMENT CLEANUP	
Incident Eligible Status:		ELIGIBLE	
Incident Ineligible Reason:		Not Reported	
Incident Ineligible Description:		Not reported	
INCIDENT INITIAL REMEDIAL ACTION INFORMATION -			
Free Product:		Cleanup Responsible:	Not reported
Soil Removal:		Alt. Process Date:	Not reported
Soil Treatment:		Alternative Status:	Not reported
Other Treatment:			
INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -			
Cleanup Responsible:		Not reported	
Response Record Type:		Not reported	
Response Remedial Action Plan Type:		Not reported	
Response Status:		Not reported	
Extension Record Type:		Not reported	
Extension Status:		Not reported	
Extension Comments:		Not reported	
INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -			
Cleanup Responsible:		Not reported	
Response Record Type:		Not reported	
Response Remedial Action Plan Type:		Not reported	
INCIDENT REMEDIAL ACTION REPORT INFORMATION -			
Cleanup Responsible:		Not reported	
Estimated Completion Year:		Not reported	
Actual Year to Complete:		Not reported	
Report Type:		Not reported	
Report Comments:		Not reported	
INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -			
Site Rehab. Completion Action:		Not reported	
Flag:		Not reported	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GANDY PAINT CO (Continued)

U001356319

UST:

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000100	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	10	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GANDY PAINT CO (Continued)

U001356319

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	11	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000300	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	12	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

GANDY PAINT CO (Continued)

U001356319

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	13	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	14	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GANDY PAINT CO (Continued)

U001356319

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	15	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		
Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	16	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GANDY PAINT CO (Continued)

U001356319

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000100	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000100	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map iD
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GANDY PAINT CO (Continued)

U001356319

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000100	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

GANDY PAINT CO (Continued)

U001356319

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	6	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	7	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GANDY PAINT CO (Continued)

U001356319

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	8	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

Facility ID:	299101617	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RICHARD HOLMES		
Contact:	Not reported	Facility Phone:	8132535772
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910405	Financial responsibility:	Not reported
Tank ID:	9	District:	Southwest
Owner's Contact:	RICHARD HOLMES		
Owner:	HOLMES, RICHARD C. 109 S MAGNOLIA AVE TAMPA, FL 336061935		
Owner's Phone:	8132535772	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000560	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/07
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

298

IPPOLITO PROPERTY
608 W KENNEDY BLVD
TAMPA, FL 33606

UST
LUST

U001356411
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

IPPOLITO PROPERTY (Continued)

U001356411

LUST:

Facility ID:	9201192	Facility Type:	NON-RETAIL BUSINESS
Telephone:	Not reported	Alias Name 1:	Not reported
Discovery Date:	04/02/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	021 (LOW)	Alias Name 4:	Not reported
Rank:	05558	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	LEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

IPPOLITO PROPERTY (Continued)

U001356411

UST:

Facility ID:	299201192	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	IPPOLITO, ET AL		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920515	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	DR JOHN W ROSS		
Owner:	ROSS, JOHN W 677 CHURCH ST MARIETTA, GA 300600000		
Owner's Phone:	4044262873	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299201192	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	IPPOLITO, ET AL		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920515	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	DR JOHN W ROSS		
Owner:	ROSS, JOHN W 677 CHURCH ST MARIETTA, GA 300600000		
Owner's Phone:	4044262873	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

IPPOLITO PROPERTY (Continued)

U001356411

Facility ID:	299201192	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	IPPOLITO, ET AL		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920515	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	DR JOHN W ROSS		
Owner:	ROSS, JOHN W 677 CHURCH ST MARIETTA, GA 300600000		
Owner's Phone:	4044262873	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299201192	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	IPPOLITO, ET AL		
Contact:	Not reported	Facility Phone:	Not reported
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	920515	Financial responsibility:	None
Tank ID:	4	District:	Southwest
Owner's Contact:	DR JOHN W ROSS		
Owner:	ROSS, JOHN W 677 CHURCH ST MARIETTA, GA 300600000		
Owner's Phone:	4044262873	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

298

VALENTIA GARDENS
701 W KENNEDY BLVD
TAMPA, FL 33606

UST

U001823437
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

VALENTIA GARDENS (Continued)

U001823437

UST:

Facility ID:	299400655	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SAM AGLIANO		
Contact:	Not reported	Facility Phone:	8132533773
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940411	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	SAM AGLIANO		
Owner:	AGLIANO, SAM		
	701 W KENNEDY BLVD		
	TAMPA, FL 336060000		
Owner's Phone:	8132533773	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

Facility ID:	299400655	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SAM AGLIANO		
Contact:	Not reported	Facility Phone:	8132533773
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940411	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	SAM AGLIANO		
Owner:	AGLIANO, SAM		
	701 W KENNEDY BLVD		
	TAMPA, FL 336060000		
Owner's Phone:	8132533773	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00003000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	93/10
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	None		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	VALENTIA GARDENS (Continued)		U001823437
	Facility ID: 299400655 Is fac. regulated: Not regulated facility Operator: SAM AGLIANO Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 940411 Tank ID: 3 Owner's Contact: SAM AGLIANO Owner: AGLIANO, SAM 701 W KENNEDY BLVD TAMPA, FL 336060000 Owner's Phone: 8132533773 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000550 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: None	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132533773 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Pollutant Last used Date: 93/10 RPT by Tank #: Not reported	
299	SEAMCO LAB INC 119 S OREGON AVE TAMPA, FL 33606	FINDS	1000501763 FLD984219014
300	TAMPA PRINTING COMPANY 503 SOUTH CAESAR STREET TAMPA, FL 33602 RCRIS: Not Reported	RCRIS-SQG FINDS	1000344900 FLD004103495
301	KAL-MAR CONSTRUCTION INC 908 E EUNICE ST TAMPA, FL 33602	UST AST	U001355238 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KAL-MAR CONSTRUCTION INC (Continued)

U001355238

UST:

Facility ID:	298627640	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KAL-MAR CONSTRUCTION INC		
Contact:	Not reported	Facility Phone:	8132234219
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LENNON MARTIN		
Owner:	KAL MAR CONSTRUCTION INC		
	PO BOX 1371		
	TAMPA, FL 336011371		
Owner's Phone:	8132234219	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	80/09
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298627640	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KAL-MAR CONSTRUCTION INC		
Contact:	Not reported	Facility Phone:	8132234219
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	LENNON MARTIN		
Owner:	KAL MAR CONSTRUCTION INC		
	PO BOX 1371		
	TAMPA, FL 336011371		
Owner's Phone:	8132234219	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	80/09
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	89/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

KAL-MAR CONSTRUCTION INC (Continued)

U001355238

AST:

Facility ID:	298627640	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KAL-MAR CONSTRUCTION INC		
Facility Phone:	8132234219	Permit Section:	00000
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	LENNON MARTIN		
Owner:	KAL MAR CONSTRUCTION INC		
	PO BOX 1371		
	TAMPA, FL 336011371		
Owner's Phone:	8132234219	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00001000
Tank Content:	Unleaded gas	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	89/02
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area		
Tank Piping:	Abvgnd-no contact w/soil		
Petro. Monitoring:	Not required		

Facility ID:	298627640	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	KAL-MAR CONSTRUCTION INC		
Facility Phone:	8132234219	Permit Section:	00000
Date entered:	861105	Financial responsibility:	Not reported
Tank ID:	2R1	District:	Southwest
Owner's Contact:	LENNON MARTIN		
Owner:	KAL MAR CONSTRUCTION INC		
	PO BOX 1371		
	TAMPA, FL 336011371		
Owner's Phone:	8132234219	Tracking #:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated soil:	Not reported
Cleanup Status:	Not reported	Any contaminated surface water:	Not reported
Tank position:	Aboveground	Tank Cap. (Gals):	00000550
Tank Content:	Kerosene	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	89/02
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Last used Date:	Not reported	Any contaminated groundwater:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	AST containment area		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

302 ESPINET TRUCK REPAIRS
901 E PLATT ST
TAMPA, FL 33602

UST
LUST

U000102993
N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

ESPINET TRUCK REPAIRS (Continued)

U000102993

LUST:

Facility ID:	9102527	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132899318	Alias Name 1:	Not reported
Discovery Date:	06/19/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	022 (LOW)	Alias Name 4:	Not reported
Rank:	05539	Alias Name 5:	Not reported

Class: Not reported

Category: Not reported

Facility Code: Not reported

Status: Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

ABANDONED TANK RESTORATIO

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Est. Gallons Lost: UNKNOWN

Pollutant 2: KEROSENE

Est. Gallons Lost: UNKNOWN

Pollutant 3: WASTE OIL

Est. Gallons Lost: UNKNOWN

INCIDENT PROGRAM INFORMATION -

Incident Program:

ABANDONED TANK RESTORATION

Incident Program Type:

STATE CLEANUP

Incident Eligible Status:

PARTIAL

Incident Ineligible Reason:

NOT PETROL/PETROL PRODUCT

Incident Ineligible Description:

NOT PETROL/PETR

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: RESPONSIBLE PARTY

Soil Removal: Y

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

CONTAMINATION ASSESSMENT REPORT

Response Remedial Action Plan Type:

Not reported

Response Status:

INCOMPLETE

Extension Record Type:

Not reported

Extension Status:

Not reported

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

REMEDIAL ACTION PLAN

Response Remedial Action Plan Type:

GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ESPINET TRUCK REPAIRS (Continued)

U000102993

UST:

Facility ID:	299102527	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ESPINET TRUCK REPAIRS		
Contact:	Not reported	Facility Phone:	8132899318
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910801	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	CARTER B MCCAIN		
Owner:	TAMPA BAY ARENA %CARTER B MCCAIN 111 E MADISON ST #2300 TAMPA, FL 336020000		
Owner's Phone:	8132734226	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299102527	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ESPINET TRUCK REPAIRS		
Contact:	Not reported	Facility Phone:	8132899318
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910801	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	CARTER B MCCAIN		
Owner:	TAMPA BAY ARENA %CARTER B MCCAIN 111 E MADISON ST #2300 TAMPA, FL 336020000		
Owner's Phone:	8132734226	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			
Direction			
Distance	Site	Database(s)	EDR ID Number EPA ID Number

ESPINET TRUCK REPAIRS (Continued)

U000102993

Facility ID:	299102527	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ESPINET TRUCK REPAIRS		
Contact:	Not reported	Facility Phone:	8132899318
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910801	Financial responsibility:	None
Tank ID:	3	District:	Southwest
Owner's Contact:	CARTER B MCCAIN		
Owner:	TAMPA BAY ARENA %CARTER B MCCAIN 111 E MADISON ST #2300 TAMPA, FL 336020000		
Owner's Phone:	8132734226	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	92/05
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

303

WD FARMS,INC.
1010 E PLATT ST
TAMPA, FL 33602

UST

U001355561
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WD FARMS,INC. (Continued)

U001355561

UST:

Facility ID:	298735617	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WD FARMS,INC.		
Contact:	Not reported	Facility Phone:	8132291912
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871020	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	WILL WILLIAMS		
Owner:	W D FARMS INC		
	PO BOX 81		
	RIVERVIEW, FL 335690081		
Owner's Phone:	8132291912	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298735617	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WD FARMS,INC.		
Contact:	Not reported	Facility Phone:	8132291912
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871020	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	WILL WILLIAMS		
Owner:	W D FARMS INC		
	PO BOX 81		
	RIVERVIEW, FL 335690081		
Owner's Phone:	8132291912	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

WD FARMS,INC. (Continued)

U001355561

Facility ID:	298735617	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WD FARMS,INC.		
Contact:	Not reported	Facility Phone:	8132291912
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871020	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	WILL WILLIAMS		
Owner:	W D FARMS INC		
	PO BOX 81		
	RIVERVIEW, FL 335690081		
Owner's Phone:	8132291912	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298735617	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	WD FARMS,INC.		
Contact:	Not reported	Facility Phone:	8132291912
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	871020	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	WILL WILLIAMS		
Owner:	W D FARMS INC		
	PO BOX 81		
	RIVERVIEW, FL 335690081		
Owner's Phone:	8132291912	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	In service	Install. Date:	78/XX
Is tank regulated:	Not regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
	WD FARMS,INC. (Continued)		U001355561
	Facility ID: 298735617 Is fac. regulated: Regulated facility Operator: WD FARMS,INC. Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 871020 Tank ID: 5 Owner's Contact: WILL WILLIAMS Owner: W D FARMS INC PO BOX 81 RIVERVIEW, FL 335690081 Owner's Phone: 8132291912 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000550 Tank position: Not reported Tank Content: Not reported Disposal Method: In service Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Open Facility Phone: 8132291912 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: 78/XX Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported	
304	GARRISON STEVEDORING,INC. 1101 E ELLA MAE ST TAMPA, FL 33602	UST LUST	U001354527 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GARRISON STEVEDORING,INC. (Continued)

U001354527

LUST:

Facility ID:	8625300	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132291958	Alias Name 1:	Not reported
Discovery Date:	02/01/93	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	035	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

CLOSURE REPORT

Lead:

LOCAL PROGRAM

Incident 17-770 Cleanup:

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: VEHIC DIESEL

Est. Gallons Lost: UNKNOWN

Pollutant 2: Not reported

Est. Gallons Lost: 00000000

Pollutant 3: Not reported

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

RESPONSIBLE PARTY-NO CLAIM

Incident Program Type:

Not reported

Incident Eligible Status:

Not reported

Incident Ineligible Reason:

Not Reported

Incident Ineligible Description:

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Cleanup Responsible: Not reported

Soil Removal:

Alt. Process Date: Not reported

Soil Treatment:

Alternative Status: Not reported

Other Treatment:

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

RESPONSIBLE PARTY

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

Response Status:

Not reported

Extension Record Type:

CONTAMINATION ASSESSMENT REPORT

Extension Status:

APPROVED

Extension Comments:

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Not reported

Response Record Type:

Not reported

Response Remedial Action Plan Type:

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Not reported

Estimated Completion Year:

Not reported

Actual Year to Complete:

Not reported

Report Type:

Not reported

Report Comments:

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Not reported

Flag:

Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GARRISON STEVEDORING,INC. (Continued)

U001354527

UST:

Facility ID:	298625300	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GARRISON STEVEDORING,INC.		
Contact:	Not reported	Facility Phone:	8132291958
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GEORGE H. PATE		
Owner:	GARRISON STEVEDORING INC		
	101 S 13TH ST		
	TAMPA, FL 336024213		
Owner's Phone:	8132291958	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625300	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	GARRISON STEVEDORING,INC.		
Contact:	Not reported	Facility Phone:	8132291958
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860515	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GEORGE H. PATE		
Owner:	GARRISON STEVEDORING INC		
	101 S 13TH ST		
	TAMPA, FL 336024213		
Owner's Phone:	8132291958	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			GARRISON STEVEDORING,INC. (Continued)		U001354527	
			Facility ID: 298625300 Is fac. regulated: Not regulated facility Operator: GARRISON STEVEDORING,INC. Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860515 Tank ID: 3 Owner's Contact: GEORGE H. PATE Owner: GARRISON STEVEDORING INC 101 S 13TH ST TAMPA, FL 336024213 Owner's Phone: 8132291958 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00002000 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132291958 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: Not reported Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported		
305			TAMPA,CITY-CONVENTION CENTER 209 S FRANKLIN ST TAMPA, FL 33602	UST LUST	U001355760 N/A	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-CONVENTION CENTER (Continued)

U001355760

UST:

Facility ID:	298838723	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132238211
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880209	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	291253
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298838723	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132238211
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880209	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	291253
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-CONVENTION CENTER (Continued)

U001355760

Facility ID:	298838723	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132238211
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880209	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	291253
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		
Facility ID:	298838723	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132238211
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880209	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	291253
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

TAMPA,CITY-CONVENTION CENTER (Continued)

U001355760

Facility ID:	298838723	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132238211
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	880209	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	291253
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

306	JOE B KLAY & SONS INC 202 SOUTH ROME AVENUE TAMPA, FL 33606	RCRIS-SQG FINDS	1000103686 FLD982108599
	RCRIS: Not Reported		

306	FL STEEL CORP. 1715 W CLEVELAND ST TAMPA, FL 33606	UST	U001354759 N/A
-----	--	-----	-------------------

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FL STEEL CORP. (Continued)

U001354759

UST:

Facility ID:	298625546	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL STEEL CORP.		
Contact:	Not reported	Facility Phone:	8132518811
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TOM OWENS		
Owner:	FL STEEL CORP TAMPA 1715 W CLEVELAND ST TAMPA, FL 336061810		
Owner's Phone:	8132518811	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	73/02
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625546	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL STEEL CORP.		
Contact:	Not reported	Facility Phone:	8132518811
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	1R1	District:	Southwest
Owner's Contact:	TOM OWENS		
Owner:	FL STEEL CORP TAMPA 1715 W CLEVELAND ST TAMPA, FL 336061810		
Owner's Phone:	8132518811	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FL STEEL CORP. (Continued)

U001354759

Facility ID:	298625546	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL STEEL CORP.		
Contact:	Not reported	Facility Phone:	8132518811
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	TOM OWENS		
Owner:	FL STEEL CORP TAMPA 1715 W CLEVELAND ST TAMPA, FL 336061810		
Owner's Phone:	8132518811	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	73/02
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625546	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL STEEL CORP.		
Contact:	Not reported	Facility Phone:	8132518811
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	TOM OWENS		
Owner:	FL STEEL CORP TAMPA 1715 W CLEVELAND ST TAMPA, FL 336061810		
Owner's Phone:	8132518811	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	73/02
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

FL STEEL CORP. (Continued)

U001354759

Facility ID:	298625546	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL STEEL CORP.		
Contact:	Not reported	Facility Phone:	8132518811
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	TOM OWENS		
Owner:	FL STEEL CORP TAMPA 1715 W CLEVELAND ST TAMPA, FL 336061810		
Owner's Phone:	8132518811	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	73/02
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625546	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	FL STEEL CORP.		
Contact:	Not reported	Facility Phone:	8132518811
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860521	Financial responsibility:	Not reported
Tank ID:	5	District:	Southwest
Owner's Contact:	TOM OWENS		
Owner:	FL STEEL CORP TAMPA 1715 W CLEVELAND ST TAMPA, FL 336061810		
Owner's Phone:	8132518811	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	73/02
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

307

SUN OIL
1021 E ELLA MAE ST
TAMPA, FL 33602

LUST
AST

S101264766
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SUN OIL (Continued)

S101264766

LUST:

Facility ID:	9300570	Facility Type:	NON-RETAIL BUSINESS
Telephone:	Not reported	Alias Name 1:	Not reported
Discovery Date:	03/12/93	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:

Lead:

Incident 17-770 Cleanup:

DISCHARGE NOTIFICATION

LOCAL PROGRAM

Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1: UNLEADED GAS

Pollutant 2: Not reported

Pollutant 3: Not reported

Est. Gallons Lost: UNKNOWN

Est. Gallons Lost: 00000000

Est. Gallons Lost: 00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:

Incident Program Type:

Incident Eligible Status:

Incident Ineligible Reason:

Incident Ineligible Description:

RESPONSIBLE PARTY-NO CLAIM

Not reported

Not reported

Not Reported

Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:

Soil Removal:

Soil Treatment:

Other Treatment:

Cleanup Responsible: Not reported

Alt. Process Date: Not reported

Alternative Status: Not reported

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Response Status:

Extension Record Type:

Extension Status:

Extension Comments:

RESPONSIBLE PARTY

Not reported

Not reported

Not reported

CONTAMINATION ASSESSMENT REPORT

APPROVED

Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:

Response Record Type:

Response Remedial Action Plan Type:

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:

Estimated Completion Year:

Actual Year to Complete:

Report Type:

Report Comments:

Not reported

Not reported

Not reported

Not reported

Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:

Flag:

Not reported

Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

SUN OIL (Continued)

S101264766

AST:

Facility ID:	299300570	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA PORT AUTHORITY		
Facility Phone:	Not reported	Permit Section:	00000
Date entered:	930622	Financial responsibility:	None
Tank ID:	1	District:	Southwest
Owner's Contact:	HAROLD PEMBERTON		
Owner:	TAMPA PORT AUTHORITY PO BOX 2192 TAMPA, FL 336012192		
Owner's Phone:	8132481924	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000888
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299300570	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA PORT AUTHORITY		
Facility Phone:	Not reported	Permit Section:	00000
Date entered:	930622	Financial responsibility:	None
Tank ID:	2	District:	Southwest
Owner's Contact:	HAROLD PEMBERTON		
Owner:	TAMPA PORT AUTHORITY PO BOX 2192 TAMPA, FL 336012192		
Owner's Phone:	8132481924	Tracking #:	Not reported
Drink. Wat. Well:	0000	Any contaminated soil:	Yes
Cleanup Status:	Ongoing	Any contaminated surface water:	No
Tank position:	Aboveground	Tank Cap. (Gals):	00000888
Tank Content:	Generic gas	Contaminated media indicator:	Yes
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Last used Date:	Not reported	Any contaminated groundwater:	No
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Unknown/not reported		
Tank Piping:	Unknown/not reported		
Petro. Monitoring:	Unknown/not reported		

307 SUNMARK PETROLEUM MARKETING TE
1021 ELLAMAE AVE
TAMPA, FL 33601

RCRIS-SQG 1000497566
FINDS FLD073194490

RCRIS: Not Reported

Other Pertinent Environmental Activity Identified at Site:
facility is involved with pesticide/toxic substances production

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
307	SUN OIL CO OF PA. TAMPA TERM 1021 ELLAMAE ST TAMPA, FL 33602	FINDS	1000932231 FLD0000597443
308	FREE PRESS PUBLISHING CO INC 401 E PLATT ST TAMPA, FL 33601 RCRIS: Not Reported	RCRIS-SQG	1000700209 FLD982090938
308	FREE PRESS PUBLISHING COMPANY 401 E PLATT STREET TAMPA, FL 33602	FINDS	1000734946 FLD982090938
309	RAYBRO ELECTRIC SUPPLIES,INC 907 E ELLA MAE ST TAMPA, FL 33602 UST: Facility ID: 298625233 Is fac. regulated: Not regulated facility Operator: RAYBRO ELECTRIC SUPPLIES,INC Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860514 Tank ID: 1 Owner's Contact: W E HALSEY Owner: RAYBRO ELECTRIC SUPPLIES INC PO BOX 1351 TAMPA, FL 336011351 Owner's Phone: 8132288571 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00002000 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells	UST	U001354466 N/A Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132288571 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: 75/12 Content Category: Vehicular Last used Date: 89/01 RPT by Tank #: Not reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

RAYBRO ELECTRIC SUPPLIES,INC (Continued)

U001354466

Facility ID:	298625233	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RAYBRO ELECTRIC SUPPLIES,INC		
Contact:	Not reported	Facility Phone:	8132288571
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	W E HALSEY		
Owner:	RAYBRO ELECTRIC SUPPLIES INC		
	PO BOX 1351		
	TAMPA, FL 336011351		
Owner's Phone:	8132288571	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	75/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625233	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	RAYBRO ELECTRIC SUPPLIES,INC		
Contact:	Not reported	Facility Phone:	8132288571
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	W E HALSEY		
Owner:	RAYBRO ELECTRIC SUPPLIES INC		
	PO BOX 1351		
	TAMPA, FL 336011351		
Owner's Phone:	8132288571	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	75/12
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

310

ROYAL CROWN BOTTLING
701 E ELLA MAE ST
TAMPA, FL 33602

UST

U001354474
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ROYAL CROWN BOTTLING (Continued)

U001354474

UST:

Facility ID:	298625242	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROYAL CROWN BOTTLING		
Contact:	Not reported	Facility Phone:	8132290101
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	C. ANDERSON		
Owner:	JASON DORAN CO		
	315 E MADISON ST		
	TAMPA, FL 336024816		
Owner's Phone:	8132288150	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625242	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	ROYAL CROWN BOTTLING		
Contact:	Not reported	Facility Phone:	8132290101
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860514	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	C. ANDERSON		
Owner:	JASON DORAN CO		
	315 E MADISON ST		
	TAMPA, FL 336024816		
Owner's Phone:	8132288150	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

311

CORBAN ARMCO TAMPA PLANT
1800 KNOX ROAD
TAMPA, FL 45042

RCRIS-SQG 1000699062
FLD073208985

RCRIS: Not Reported

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
311	CORBAN ARMCO TAMPA PLANT 1800 KNOX ROAD TAMPA, FL 33605	FINDS	1000733561 FLD073208985
312	US CUSTOMS HOUSE 301 S ASHLEY DR TAMPA, FL 33602	UST	U001355519 N/A
	UST: Facility ID: 298734018 Is fac. regulated: Not regulated facility Operator: GENERAL SERVICE ADMINISTRATION Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 870805 Tank ID: 1 Owner's Contact: JAMES F. BENNETT Owner: GENERAL SERVICES ADMINISTRATION 501 E POLK ST #600 TAMPA, FL 336023926 Owner's Phone: 8132282351 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000500 Tank position: Not reported Tank Content: Not reported Disposal Method: Unmaintained Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Federal Government Is facility open: Closed Facility Phone: 8132282351 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: 38/XX Content Category: Vehicular Last used Date: 60/01 RPT by Tank #: Not reported	
312	TAMPA,CITY-CONVENTION CENTER 111 E PLATT ST TAMPA, FL 33602	UST	U001354962 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA,CITY-CONVENTION CENTER (Continued)

U001354962

UST:

Facility ID:	298625759	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132231674
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298625759	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132231674
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

TAMPA,CITY-CONVENTION CENTER (Continued)

U001354962

Facility ID:	298625759	Facility Type:	Local, City Government
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	TAMPA,CITY		
Contact:	Not reported	Facility Phone:	8132231674
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860523	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DAVID TIPPIN		
Owner:	TAMPA CITY		
	306 E JACKSON ST		
	TAMPA, FL 336025223		
Owner's Phone:	8132238663	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00006000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	88/01
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

313

GARRISON CHANNEL
631 S ASHLEY DR
TAMPA, FL 00000

LUST

S100990555
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GARRISON CHANNEL (Continued)

S100990555

LUST:

Facility ID:	9301000	Facility Type:	OTHER
Telephone:	4073511111	Alias Name 1:	Not reported
Discovery Date:	03/12/93	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	000 (LOW)	Alias Name 4:	Not reported
Rank:	00000	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	CLOSURE REPORT
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	Not reported

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

314

TAMPA TRIBUNE CO
1712 W PLATT ST
TAMPA, FL 33606

UST
LUST

U001545767
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA TRIBUNE CO (Continued)

U001545767

LUST:

Facility ID:	8628757	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132518829	Alias Name 1:	Not reported
Discovery Date:	11/13/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	032	Alias Name 4:	Not reported
Rank:	03868	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	COMBINED C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	RESPONSIBLE PARTY-NO CLAIM
Incident Program Type:	Not reported
Incident Eligible Status:	Not reported
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	CONTAMINATION ASSESSMENT REPORT
Response Remedial Action Plan Type:	Not reported
Response Status:	INCOMPLETE
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA TRIBUNE CO (Continued)

U001545767

UST:

Facility ID:	298628757	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FERNANDEZ, JAMES V		
Contact:	Not reported	Facility Phone:	8132518829
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	1	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO		
	202 S PARKER ST		
	TAMPA, FL 336060000		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	85/10
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298628757	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FERNANDEZ, JAMES V		
Contact:	Not reported	Facility Phone:	8132518829
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	2	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO		
	202 S PARKER ST		
	TAMPA, FL 336060000		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	87/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA TRIBUNE CO (Continued)

U001545767

Facility ID:	298628757	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FERNANDEZ, JAMES V		
Contact:	Not reported	Facility Phone:	8132518829
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	3	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 336060000		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00012000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	88/09
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		
Facility ID:	298628757	Facility Type:	Non-retail Business
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	FERNANDEZ, JAMES V		
Contact:	Not reported	Facility Phone:	8132518829
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861118	Financial responsibility:	Oth Apprvd Coverage
Tank ID:	4	District:	Southwest
Owner's Contact:	JAMES V FERNANDEZ		
Owner:	TAMPA TRIBUNE CO 202 S PARKER ST TAMPA, FL 336060000		
Owner's Phone:	8132518829	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000500	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	90/01
Is tank regulated:	Regulated tank	Content Category:	Pollutant
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

314

TAMPA TRIBUNE
1712 N PLATT
TAMPA, FL 33606

RCRIS-SQG 1000344923
FINDS FLD984168641

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number																		
	TAMPA TRIBUNE (Continued)		1000344923																		
	RCRIS: Owner: JAMES FERNANDEZ, GARAGE FORMER (813) 251-8829 Contact:JAMES FERNANDEZ (813) 251-8829																				
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D000</td><td>.00000 (T)</td><td>Notification</td><td>D001</td><td>.00000 (T)</td><td>Notification</td></tr><tr><td>F003</td><td>.00000 (T)</td><td>Notification</td><td>F005</td><td>.00000 (T)</td><td>Notification</td></tr></table>	Waste	Quantity	Info Source	Waste	Quantity	Info Source	D000	.00000 (T)	Notification	D001	.00000 (T)	Notification	F003	.00000 (T)	Notification	F005	.00000 (T)	Notification		
Waste	Quantity	Info Source	Waste	Quantity	Info Source																
D000	.00000 (T)	Notification	D001	.00000 (T)	Notification																
F003	.00000 (T)	Notification	F005	.00000 (T)	Notification																
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported																				
315	DURA STATIC INC 1617 WEST PLATT STREET TAMPA, FL 33606 RCRIS: Not Reported	RCRIS-SQG FINDS	1000316716 FLD065920514																		
315	DURA-STATIC INC 1617 WEST PLATT STREET TAMPA, FL 33606 RCRIS: Owner: HERNDON LINDA Contact:KIM ALDERMAN (813) 273-9441	RCRIS-SQG FINDS	1000143696 FLD981924350																		
	<table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>F005</td><td>.00000 (N)</td><td>Notification</td><td>U159</td><td>.00000 (N)</td><td>Notification</td></tr><tr><td>U220</td><td>.00000 (N)</td><td>Notification</td><td></td><td></td><td></td></tr></table>	Waste	Quantity	Info Source	Waste	Quantity	Info Source	F005	.00000 (N)	Notification	U159	.00000 (N)	Notification	U220	.00000 (N)	Notification					
Waste	Quantity	Info Source	Waste	Quantity	Info Source																
F005	.00000 (N)	Notification	U159	.00000 (N)	Notification																
U220	.00000 (N)	Notification																			
	(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported																				
316	PRESTIGE TAXI 901 PLATT ST TAMPA, FL 33602 RCRIS: Not Reported	RCRIS-SQG FINDS	1000388838 FLD146749783																		
316	AMOCO #1 901 W PLATT ST TAMPA, FL 33606	UST LUST	U001354030 N/A																		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #1 (Continued)

U001354030

LUST:

Facility ID:	8624766	Facility Type:	RETAIL STATION
Telephone:	8136814279	Alias Name 1:	Not reported
Discovery Date:	03/13/91	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	030	Alias Name 4:	Not reported
Rank:	04434	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	ABANDONED TANK RESTORATIO
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNKNOWN/NOT REPOR	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	REIMBURSEMENT CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	RESPONSIBLE PARTY
Soil Removal: Y	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	CONTAMINATION ASSESSMENT REPORT
Extension Status:	APPROVED
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	RESPONSIBLE PARTY
Response Record Type:	REMEDIAL ACTION PLAN
Response Remedial Action Plan Type:	GROUNDWATER TREATMENT

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AMOCO #1 (Continued)

U001354030

UST:

Facility ID:	298624766	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM D. MCKNIGHT		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DONALD L BODIE JR		
Owner:	VENTO OIL CO		
	207 N 11TH ST		
	TAMPA, FL 336023601		
Owner's Phone:	8132210339	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298624766	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	WILLIAM D. MCKNIGHT		
Contact:	Not reported	Facility Phone:	8136814279
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860505	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DONALD L BODIE JR		
Owner:	VENTO OIL CO		
	207 N 11TH ST		
	TAMPA, FL 336023601		
Owner's Phone:	8132210339	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00001000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number												
	AMOCO #1 (Continued)		U001354030												
	Facility ID: 298624766 Is fac. regulated: Not regulated facility Operator: WILLIAM D. MCKNIGHT Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 860505 Tank ID: 3 Owner's Contact: DONALD L BODIE JR Owner: VENTO OIL CO 207 N 11TH ST TAMPA, FL 336023601 Owner's Phone: 8132210339 Cleanup Status: Ongoing Drink. Wat. Well: 0000 Tank Cap. (Gals): 00001000 Tank position: Not reported Tank Content: Not reported Disposal Method: Removed Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Retail Station Is facility open: Closed Facility Phone: 8136814279 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Yes Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: No Install. Date: Not reported Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported													
317	TEXACO NO 242041319 818 W PLATT TAMPA, FL 33609	FINDS	1000735996 FLD984172486												
317	TEXACO #242041319 818 W PLATT TAMPA, FL 32794 RCRIS: Owner: KEN WHITE (407) 875-7600 Contact: KEN WHITE (407) 875-7600 <table><tr><th>Waste</th><th>Quantity</th><th>Info Source</th><th>Waste</th><th>Quantity</th><th>Info Source</th></tr><tr><td>D000</td><td>.00000 (T)</td><td>Notification</td><td>D018</td><td>.00000 (T)</td><td>Notification</td></tr></table> (P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported	Waste	Quantity	Info Source	Waste	Quantity	Info Source	D000	.00000 (T)	Notification	D018	.00000 (T)	Notification	RCRIS-SQG	1000701131 FLD984172486
Waste	Quantity	Info Source	Waste	Quantity	Info Source										
D000	.00000 (T)	Notification	D018	.00000 (T)	Notification										
317	TAMPA GAS STATION 818 W PLATT ST TAMPA, FL 33606	UST LUST	U001355236 N/A												

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TAMPA GAS STATION (Continued)

U001355236

UST:

Facility ID:	298627499	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY ROEOL		
Contact:	Not reported	Facility Phone:	8132867929
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861103	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	1	District:	Southwest
Owner's Contact:	MIKE CONVEY		
Owner:	TAMPA GAS INC 301 N WESTSHORE BLVD TAMPA, FL 336090000		
Owner's Phone:	8132867929	Tracking #:	292406
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

Facility ID:	298627499	Facility Type:	Retail Station
Is fac. regulated:	Regulated facility	Is facility open:	Open
Operator:	LARRY ROEOL		
Contact:	Not reported	Facility Phone:	8132867929
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861103	Financial responsibility:	State PRGM (FLIPA/AIG)
Tank ID:	2	District:	Southwest
Owner's Contact:	MIKE CONVEY		
Owner:	TAMPA GAS INC 301 N WESTSHORE BLVD TAMPA, FL 336090000		
Owner's Phone:	8132867929	Tracking #:	292406
Cleanup Status:	Completed	Any contaminated soil:	No
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00010000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Yes
Disposal Method:	In service	Install. Date:	86/05
Is tank regulated:	Regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells, Piping/flow restrictor		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			TAMPA GAS STATION (Continued)			U001355236
			Facility ID: 298627499 Is fac. regulated: Regulated facility Operator: LARRY ROEOL Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 861103 Tank ID: 3 Owner's Contact: MIKE CONVEY Owner: TAMPA GAS INC 301 N WESTSHORE BLVD TAMPA, FL 336090000 Owner's Phone: 8132867929 Cleanup Status: Completed Drink. Wat. Well: 0000 Tank Cap. (Gals): 00010000 Tank position: Not reported Tank Content: Not reported Disposal Method: In service Is tank regulated: Regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Man sample wells, Piping/flow restrictor	Facility Type: Retail Station Is facility open: Open Facility Phone: 8132867929 Region: Not reported Financial responsibility: State PRGM (FLIPA/AIG) District: Southwest Tracking #: 292406 Any contaminated soil: No Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Yes Install. Date: 86/05 Content Category: Vehicular Last used Date: Not reported RPT by Tank #: Not reported		
318			FORMER HYDE PARK FIRE STATION #3 301 S MAGNOLIA AVE TAMPA, FL 33606	UST		U001823446 N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site	Database(s)		

FORMER HYDE PARK FIRE STATION #3 (Continued)

U001823446

UST:

Facility ID:	299400842	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BRUCE REDDEN		
Contact:	Not reported	Facility Phone:	8139315828
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	940418	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	BRUCE REDDEN		
Owner:	REDDEN, BRUCE		
	8644 N HIMES #718		
	TAMPA, FL 336110000		
Owner's Phone:	8139315828	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000300	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	92/02
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Not required		

319

PALLARDY, INC./LEE
415 S HYDE PARK AVE
TAMPA, FL 33606

UST
LUST

U001355542
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PALLARDY,INC./LEE (Continued)

U001355542

LUST:

Facility ID:	8735348	Facility Type:	NON-RETAIL BUSINESS
Telephone:	8132530381	Alias Name 1:	Not reported
Discovery Date:	03/02/92	Alias Name 2:	Not reported
Tracking Number:	Not reported	Alias Name 3:	Not reported
Score:	021 (LOW)	Alias Name 4:	Not reported
Rank:	05558	Alias Name 5:	Not reported
Class:	Not reported		
Category:	Not reported		
Facility Code:	Not reported	Status:	Not reported

INCIDENT GENERAL INFORMATION -

Source Description:	DISCHARGE NOTIFICATION
Lead:	LOCAL PROGRAM
Incident 17-770 Cleanup:	NEW C/U REQUIRED

INCIDENT POLLUTANT INFORMATION -

Pollutant 1:	UNLEADED GAS	Est. Gallons Lost:	UNKNOWN
Pollutant 2:	Not reported	Est. Gallons Lost:	00000000
Pollutant 3:	Not reported	Est. Gallons Lost:	00000000

INCIDENT PROGRAM INFORMATION -

Incident Program:	ABANDONED TANK RESTORATION
Incident Program Type:	STATE CLEANUP
Incident Eligible Status:	ELIGIBLE
Incident Ineligible Reason:	Not Reported
Incident Ineligible Description:	Not reported

INCIDENT INITIAL REMEDIAL ACTION INFORMATION -

Free Product:	Cleanup Responsible:	Not reported
Soil Removal:	Alt. Process Date:	Not reported
Soil Treatment:	Alternative Status:	Not reported
Other Treatment:		

INCIDENT CONTAMINATION ASSESSMENT REPORT RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported
Response Status:	Not reported
Extension Record Type:	Not reported
Extension Status:	Not reported
Extension Comments:	Not reported

INCIDENT REMEDIAL ACTION PLAN RESPONSE INFORMATION -

Cleanup Responsible:	Not reported
Response Record Type:	Not reported
Response Remedial Action Plan Type:	Not reported

INCIDENT REMEDIAL ACTION REPORT INFORMATION -

Cleanup Responsible:	Not reported
Estimated Completion Year:	Not reported
Actual Year to Complete:	Not reported
Report Type:	Not reported
Report Comments:	Not reported

INCIDENT REMEDIAL ACTION SITE REHABILITATION COMPLETION -

Site Rehab. Completion Action:	Not reported
Flag:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PALLARDY,INC./LEE (Continued)

U001355542

UST:

Facility ID:	298735348	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	LEE F. PALLARDY		
Contact:	Not reported	Facility Phone:	8132530381
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	870924	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	LEE F. PALLARDY III OR JO WALL		
Owner:	PALLARDY, LEE F		
	415 S HYDE PARK AVE		
	TAMPA, FL 336062268		
Owner's Phone:	8132530381	Tracking #:	Not reported
Cleanup Status:	Ongoing	Any contaminated soil:	Yes
Drink. Wat. Well:	0000	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00002000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	No
Disposal Method:	Closed in place	Install. Date:	80/11
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	89/03
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

320

MICHELLE SKEEN INTERIORS
600 W AZEELE ST
TAMPA, FL 33606

UST

U001546668
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MICHELLE SKEEN INTERIORS (Continued)

U001546668

UST:

Facility ID:	299102090	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SKEEN, MICHELLE		
Contact:	Not reported	Facility Phone:	8132540900
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910524	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	GAB ARGOS		
Owner:	MICHELLE SKEEN INTERIORS		
	600 W AZEELE ST		
	TAMPA, FL 336060000		
Owner's Phone:	8132540900	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	299102090	Facility Type:	Non-retail Business
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	SKEEN, MICHELLE		
Contact:	Not reported	Facility Phone:	8132540900
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	910524	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	GAB ARGOS		
Owner:	MICHELLE SKEEN INTERIORS		
	600 W AZEELE ST		
	TAMPA, FL 336060000		
Owner's Phone:	8132540900	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00000550	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Hazardous/other
Facility Status:	Not reported	Last used Date:	90/06
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
			MICHELLE SKEEN INTERIORS (Continued)			U001546668
			Facility ID: 299102090 Is fac. regulated: Not regulated facility Operator: SKEEN, MICHELLE Contact: Not reported Permit Section: Not reported Facility Code: No violation Date entered: 910524 Tank ID: 3 Owner's Contact: GAB ARGOS Owner: MICHELLE SKEEN INTERIORS 600 W AZEELE ST TAMPA, FL 336060000 Owner's Phone: 8132540900 Cleanup Status: Not reported Drink. Wat. Well: Not reported Tank Cap. (Gals): 00000550 Tank position: Not reported Tank Content: Not reported Disposal Method: Closed in place Is tank regulated: Not regulated tank Facility Status: Not reported RPT Tank #: Not reported Tank Constr.: Not reported Tank Piping: Not reported Petro. Monitoring: Unknown/not reported	Facility Type: Non-retail Business Is facility open: Closed Facility Phone: 8132540900 Region: Not reported Financial responsibility: Not reported District: Southwest Tracking #: Not reported Any contaminated soil: Not reported Any contaminated surface water: Not reported Any monit. wells: Not reported Any contam. groundwater: Not reported Contaminated media indicator: Not reported Install. Date: Not reported Content Category: Hazardous/other Last used Date: 90/06 RPT by Tank #: Not reported		
321			SUNOCO-BAYSHORE 620 S MAGNOLIA AVE TAMPA, FL 33606	UST		U001354131 N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

SUNOCO-BAYSHORE (Continued)

U001354131

UST:

Facility ID:	298624874	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAYSHORE SUNOCO		
Contact:	Not reported	Facility Phone:	8132544135
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	TRACI MEYERS OR STEVE RAIMONDI		
Owner:	LISLE, DAVID TRUSTEE 11028 N FLORIDA AVE TAMPA, FL 336126636		
Owner's Phone:	8139337613	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00008000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

Facility ID:	298624874	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAYSHORE SUNOCO		
Contact:	Not reported	Facility Phone:	8132544135
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	TRACI MEYERS OR STEVE RAIMONDI		
Owner:	LISLE, DAVID TRUSTEE 11028 N FLORIDA AVE TAMPA, FL 336126636		
Owner's Phone:	8139337613	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

SUNOCO-BAYSHORE (Continued)

U001354131

Facility ID:	298624874	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	BAYSHORE SUNOCO		
Contact:	Not reported	Facility Phone:	8132544135
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	860506	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	TRACI MEYERS OR STEVE RAIMONDI		
Owner:	LISLE, DAVID TRUSTEE 11028 N FLORIDA AVE TAMPA, FL 336126636		
Owner's Phone:	8139337613	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Removed	Instal. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	91/XX
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Man sample wells		

322

TORINA & PURDY
701 BAYSHORE BLVD
TAMPA, FL 33606

UST

U001355027
N/A

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

TORINA & PURDY (Continued)

U001355027

UST:

Facility ID:	298626339	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DONALD L. TORINA		
Contact:	Not reported	Facility Phone:	8132530944
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861010	Financial responsibility:	Not reported
Tank ID:	1	District:	Southwest
Owner's Contact:	DONALD L TORINA		
Owner:	TORINA, DONALD L		
	243 BAYSHORE BLVD		
	TAMPA, FL 336062328		
Owner's Phone:	8132530944	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298626339	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DONALD L. TORINA		
Contact:	Not reported	Facility Phone:	8132530944
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861010	Financial responsibility:	Not reported
Tank ID:	2	District:	Southwest
Owner's Contact:	DONALD L TORINA		
Owner:	TORINA, DONALD L		
	243 BAYSHORE BLVD		
	TAMPA, FL 336062328		
Owner's Phone:	8132530944	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

MAP FINDINGS

Map ID				EDR ID Number
Direction				EPA ID Number
Distance	Site		Database(s)	

TORINA & PURDY (Continued)

U001355027

Facility ID:	298626339	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DONALD L. TORINA		
Contact:	Not reported	Facility Phone:	8132530944
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861010	Financial responsibility:	Not reported
Tank ID:	3	District:	Southwest
Owner's Contact:	DONALD L TORINA		
Owner:	TORINA, DONALD L 243 BAYSHORE BLVD TAMPA, FL 336062328		
Owner's Phone:	8132530944	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

Facility ID:	298626339	Facility Type:	Retail Station
Is fac. regulated:	Not regulated facility	Is facility open:	Closed
Operator:	DONALD L. TORINA		
Contact:	Not reported	Facility Phone:	8132530944
Permit Section:	Not reported	Region:	Not reported
Facility Code:	No violation		
Date entered:	861010	Financial responsibility:	Not reported
Tank ID:	4	District:	Southwest
Owner's Contact:	DONALD L TORINA		
Owner:	TORINA, DONALD L 243 BAYSHORE BLVD TAMPA, FL 336062328		
Owner's Phone:	8132530944	Tracking #:	Not reported
Cleanup Status:	Not reported	Any contaminated soil:	Not reported
Drink. Wat. Well:	Not reported	Any contaminated surface water:	Not reported
Tank Cap. (Gals):	00004000	Any monit. wells:	Not reported
Tank position:	Not reported	Any contam. groundwater:	Not reported
Tank Content:	Not reported	Contaminated media indicator:	Not reported
Disposal Method:	Closed in place	Install. Date:	Not reported
Is tank regulated:	Not regulated tank	Content Category:	Vehicular
Facility Status:	Not reported	Last used Date:	Not reported
RPT Tank #:	Not reported	RPT by Tank #:	Not reported
Tank Constr.:	Not reported		
Tank Piping:	Not reported		
Petro. Monitoring:	Unknown/not reported		

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
APOLLO BEACH	1000703436	TAMPA ELECTRIC CO PROD SVC CTR	6944 US HWY 41 N	33601	RCRIS-SQG	
BRANDON	942444483	SE CORNER OF MYRTLE AND BELL SHOALS RDS		33602	ERNS	
FORT GREEN SPRINGS	1000921752	HARDEE POWER STATION	CR 663 (B)	33601	RCRIS-LOG	
LAKELAND	1000699423	GENERAL TELEPHONE LAKELAND	1043 EAST LEMON ST	33601	RCRIS-SQG	
MULBERRY	1000905916	TAMPA ELECTRIC CO POLK POWER STATIO	9995 SR 37 SOUTH	33602	RCRIS-SQG, FINDS	
PLANT CITY	94236289	HIGHWAY 37 AND HARPER		33602	ERNS	
RUSKIN	94234149	BIG BEN RD AND WYNDOT RD		33601	ERNS	
SAINT PETERSBURG	A100008887	TRICO MARINE SERVICES,INC	US 19 S & SKYWAY BRIDGE N	33601	AST	
SARASOTA	1000699422	GENERAL TELEPHONE SARASOTA	2455 12TH STREET	33601	RCRIS-SQG	
SOUTH TAMPA	U001354915	APGAR MOTOR LINES, INC.	2138 MADISON AVE	33601	UST	298625710
ST PETERSBURG	U001545788	GTE OF FL GANDY	843 93 AVE N	33601	UST, AST	528630906
ST. PETERSBURG	94240064			33602	ERNS	
TAMPA	S100021000	SPE RECYCLING C & D FACIL			SWF/LF	
TAMPA	8806506	TAMPA GENERAL HOSPITAL			ERNS	
TAMPA	9001491	MARITIME BLVD AND SHORELINE			ERNS	
TAMPA	9003707	MARITIME AND SHORELINE AVENUE			ERNS	
TAMPA	9003701	I-275/HOWARD AVENUE			ERNS	
TAMPA	9101451	ANCLOTE ICE PLANT ANCLOTE RIVER			ERNS	
TAMPA	9009719	HOOKER'S POINT STATION HEMLOCH ST.			ERNS	
TAMPA	9007043	STATE ROUTE 41 AND BIG BEND RD.			ERNS	
TAMPA	9006743	5881 IMGRAHM ST			ERNS	
TAMPA	9003271	FILTER CLEAN INC.			ERNS	
TAMPA	9001049	YEOMAN YARD			ERNS	
TAMPA	9002940	NORTH OF 275			ERNS	
TAMPA	9001875	HIMES AND COLUMBUS			ERNS	
TAMPA	93001510	4700 WHITEWAY DR.			ERNS	
TAMPA	94254708	3701 CAUSEWAY BLVD			ERNS	
TAMPA	9202434	RESIDENCE-161 GROVE ST			ERNS	
TAMPA	8705033	TRANSUS TRUCKING CO. 9801 PALM RIVER RD.			ERNS	
TAMPA	8701952	800 BLOCK WEST BRADDOCK AND ALFRED			ERNS	
TAMPA	8806268	I-4 AT 36TH STREET WEST BOUND LANES			ERNS	
TAMPA	8905266	GARDINIER FERTILIZER PLANT			ERNS	
TAMPA	8911109	22ND STREET OF BUFFALO AVENUE			ERNS	
TAMPA	8911118	ADAMS & 50TH STREET			ERNS	
TAMPA	8911094	SAN PADREO STREET AND CHURCH AVENUE			ERNS	
TAMPA	8904757	SAN PADRO ST AND CHURCH AVE			ERNS	
TAMPA	8911063	NORTH WEST SHORE BOULEVARD AND WEST GRA			ERNS	
TAMPA	93000920	ROCK PORT			ERNS	
TAMPA	95010228				HMIRS	
TAMPA	8800753	15746 GARDENSIDE LN			ERNS	
TAMPA	8804062	AL LOPEZ STADIUM			ERNS	
TAMPA	94215061				ERNS	
TAMPA	94257720	TOWN AND COUNTRY 6707 LEEWARD ISLAND WAY			ERNS	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	8705439	CORK RD AND THONOASSASSO RD			ERNS	
TAMPA	8704914	40TH ST AND 21ST AVE			ERNS	
TAMPA	8701807	INTERSECTION OF GUNN HWY AND HENDERSON R			ERNS	
TAMPA	8702450	J.D. SMITH EXTERMINATORS			ERNS	
TAMPA	8901968	DALE MABRY EXIT RAMP ONTO BUSH BLVD			ERNS	
TAMPA	8705049	CAMELOT APARTMENTS			ERNS	
TAMPA	8700833	3000FT SOUTH OF RUNWAY 22			ERNS	
TAMPA	9200444	HWY 361			ERNS	
TAMPA	8705674	MACINTOSH RD AND US 301			ERNS	
TAMPA	8705671	NEBRASKA AVE AND BEARESS RD			ERNS	
TAMPA	94236234	YULMAN YARD			ERNS	
TAMPA	9110837	88 E HAMLIN ST EAST SHORE OF LAKE UNION			ERNS	
TAMPA	8800210	PARKING LOT OF AYRES DINER, CORNER OF DALE MAVRY RD AND GRAC			ERNS	
TAMPA	92050480				HMIRS	
TAMPA	9200518	PO BOX 547			ERNS	
TAMPA	94252488				ERNS	
TAMPA	8800445	ON HIWAY 674			ERNS	
TAMPA	9109740	2600 FEDERAL AVE			ERNS	
TAMPA	9108829	PO BOX 849 HWY 368 AND 32ND ST.			ERNS	
TAMPA	93002110	3605 EAST BOUGAINVILLE AV			ERNS	
TAMPA	94247034	MANATEE PORT			ERNS	
TAMPA	8702484	NITRAN			ERNS	
TAMPA	8701693	TAMPA AIR PORT, NEAR POLICEMAN HANGER			ERNS	
TAMPA	9108869	1150 MURPHY AVE GROUND/PARKING LOT/SEWER			ERNS	
TAMPA	9106525	PLATFORM A			ERNS	
TAMPA	94272866	200 MILES OUT OF COZUMEL ENROUTE TO TAMPA			ERNS	
TAMPA	94267760	PEIR 251			ERNS	
TAMPA	94269396	5881 INGRAHAM			ERNS	
TAMPA	90020086				HMIRS	
TAMPA	94120774				HMIRS	
TAMPA	8703008	7512 PAULA DRIVE AND TOWN AND COUNTRY BLVD			ERNS	
TAMPA	94242206	TAMPA PORT AUTHORITY BERTH 227			ERNS	
TAMPA	94241873	INTERSTATE 4 EASTBOUND AT MILE 13-14			ERNS	
TAMPA	94263239	AMERADA HESS TERMINAL			ERNS	
TAMPA	94263238	ARMADA HESS CORP 504 NORTH 19TH STREET			ERNS	
TAMPA	94272690	AGRICO BIG BEN TERMINAL			ERNS	
TAMPA	94260843	PORT MANATEE			ERNS	
TAMPA	8705589	INTERSECTION OF STATE RD 39 AND SAM ALLUN RD, NE SECTION OF			ERNS	
TAMPA	94266954	INTERSTATE 75 NORTHBOUND MILE MARKER 277			ERNS	
TAMPA	94266514	SADCO NO 220			ERNS	
TAMPA	94264027	ENROUTE FM PUERTO RICO TO TAMPA			ERNS	
TAMPA	94234604	CF INDUSTRIES AMMONIA TERMINAL 3222 MARITIME BLVD			ERNS	
TAMPA	94252600	12701 WEST HILLSBOROUGH AVENUE		33601	ERNS	
TAMPA	94267272	PORT OF TAMPA		33601	ERNS	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Databases(s)	Facility ID
TAMPA	94250879	6803 PARK EAST BLVD		33610	ERNS	
TAMPA	94272974	5910 BRECKENRIDGE PKWY SUITE H		33610	ERNS	
TAMPA	9111006	1724 KOPPERS ROAD		33605	ERNS	
TAMPA	94231499	8500 HIDDEN RIVER PKWY		33605	ERNS	
TAMPA	94272493	SOLOMON BROTHERS INVEST. 8800 HIDDEN RIVER PKWY		33605	ERNS	
TAMPA	94251595	ROY JENKINS POOL 154 COLUMBIA DR	US301 / I-4	33602	ERNS	
TAMPA	S100021008	WASTE MANAGMT INC HW TRANSFER STA	13TH & YORK ST		SWF/LF	
TAMPA	U001377986	COCA-COLA BOTTLING CO-TAMPA	104 N 13TH ST		UST, LUST	8626344
TAMPA	1000497798	BRULIN & CO INC	1616 & 1617 2ND AVE	33602	RCRIS-SQG, FINDS	
TAMPA	U001355323	KIMMINS CONTRACTING CORP	504 N 19TH ST	33605	UST, LUST, AST	8628039
TAMPA	U001356198	HESS TERMINAL	504 N 19TH ST	33605	UST, LUST, AST	9100107
TAMPA	1000931537	PHILLIPS PETROLEUM	504 N 19TH ST	33605	FINDS	
TAMPA	1000931963	AMERADA HESS CORP.-TAMPA TERM	504 N 19TH ST	33605	FINDS	
TAMPA	1000433691	CHEVRON USA INC	500 N 19TH ST	33605	FINDS, RCRIS-LOG, TSCA, UST	
TAMPA	1000995380	CHEVRON	500 N 19TH ST	33605	TSCA	
TAMPA	U001353970	STAR ENTERPRISE #24-203-5001	519 S 19TH ST	33605	UST, LUST, AST	8509068
TAMPA	1000498857	MUSSELMAN STEEL	1711 S 20TH STREET{	33610	FINDS	
TAMPA	U001355551	MUSSELMAN STEEL CORP.	1711 S 20TH ST	33605	UST, LUST	8735470
TAMPA	1000498624	MARATHON OIL CO	20TH & GRANT STREETS	33605	FINDS	8837986
TAMPA	94020790		22ND ST CAUSEWAY		HMIRS	
TAMPA	90040372		22ND ST & 8TH AVE		HMIRS	
TAMPA	90050311		22ND ST CAUSEWAY		HMIRS	
TAMPA	U001354642	FLEET TRANSPORT CO INC	4012 N 22ND ST CAUSEWAY BLVD	33610	UST, LUST	8625423
TAMPA	U001354938	FINA-A ONE	2501 N 22ND ST & I-4	33605	UST, LUST	8625735
TAMPA	U001354618	CITRA FRESH	HWY 301 S	33601	UST	298625398
TAMPA	U001355051	FORETRAVEL OF FLORIDA	4321 US 301 N	33610	UST, LUST	8626925
TAMPA	S101265163	CSX TRANSPORTATION-CLARK ST SITE	30TH ST / CLARK ST		LUST	9101429
TAMPA	92010445		13710 NORTH 30TH STREET		HMIRS	
TAMPA	1000821729	ENGINE LAB	1150 N 34TH ST	33605	RCRIS-SQG, FINDS	
TAMPA	U001963249	FL DEPT OF TRANSPORTATION CROSSTOWN EX	39TH ST EASTBOUND EXIT RAMP		UST	299401656
TAMPA	U001963248	FL DEPT OF TRANSPORTATION CROSSTOWN EX	39TH ST WESTBOUND ENTRY RAMP		UST, LUST	299401655
TAMPA	94091146		2611 N 40TH ST		HMIRS	
TAMPA	92020530		2411 N 40TH ST		HMIRS	
TAMPA	U001045078	FL ROCK & TANK LINES	US 41 S		UST, LUST, AST	8519988
TAMPA	U001377984	MCKESSON CHEMICAL CO.	6051 HWY 41-A		UST	298625120
TAMPA	9106962	530 N. WITTER ST.	HWY 49		ERNS	
TAMPA	U001963247	FL DEPT OF TRANSPORTATION CROSSTOWN EX	50TH ST EASTBOUND EXIT RAMP		UST	299401651
TAMPA	U002217714	USE 9401651	50TH ST EASTBOUND EXIT RAMP		UST	299501714
TAMPA	U001963246	FL DEPT OF TRANSPORTATION-S CROSSTOWN	50TH ST WESTBOUND ENTRY RAMP		UST	299401649
TAMPA	U002038287	FORMER POPEYE'S CHICKEN	2702 N 50TH ST		UST	299402013
TAMPA	U001355902	REEVES SOUTHEASTERN CORP-GALVANIZING	CR 574 & FAULKENBURG RD	33605	UST, LUST	8842373
TAMPA	U001378058	FL DEPT OF TRANSPORTATION	SR 580 - PIPER'S MARINE	33601	UST, LUST, AST	299102666
TAMPA	U001378030	CSX TRANSPORTATION INC-JACOB'S TRUCK	78TH ST		UST, LUST	9101415
TAMPA	U001354664	ANTHONY DISTRIBUTORS, INC.	2900 E 7TH AVE	33605	UST, LUST	8625445
TAMPA	U001355348	CHAMPION FLEET SERVICE	3304 E 7TH AVE	33605	UST, LUST	8628880
TAMPA	U001354646	GARCIA'S INSTANT SERVICE	2923 E 7TH AVE	33605	UST, LUST	8625427

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	U001356231	MACALUSO & MACALUSO	2915 E 7TH AVE	33605	UST, LUST	9100495
TAMPA	U001356280	TRACKS	1430 E 7TH AVE	33605	UST, LUST	9101102
TAMPA	U001823379	FLORIDA BUILDERS - VACANT	2017 E 7TH AVE	33605	UST, LUST	299400234
TAMPA	9103256	7016 WINONA DRIVE	MP 84.5		ERNS	
TAMPA	94060625		S 86TH ST		HMIRS	
TAMPA	U001355102	HILLSBOROUGH CNTY-VANDENBERG APRT.	RT 9 BOX 14	33610	UST, LUST	8627053
TAMPA	U001378113	ACCENT MARINE	10410 HWY 92 E		UST, LUST	9201893
TAMPA	S101011579	A & D RECYCLING TRANSFER STATION	7006 E 9TH AVE		SWF/LF	
TAMPA	8901982	MARINA N OF SKYWAY BRIDGE,EAST OF I-275 BRIDGE	ON A DOCK PILING		ERNS	
TAMPA	92120516		5100 ACLINE DR.		HMIRS	
TAMPA	92080269		5100 ACLINE AVE		HMIRS	
TAMPA	92080115		5100 ACLINE AVE		HMIRS	
TAMPA	92120513		5100 ACLINE DR.		HMIRS	
TAMPA	92090965		5100 ACLINE DRIVE		HMIRS	
TAMPA	92070571		5100 ACLINE		HMIRS	
TAMPA	92090246		5100 ACLINE DR		HMIRS	
TAMPA	92090245		5100 ACLINE DR		HMIRS	
TAMPA	92090729		5100 ACLINE DR		HMIRS	
TAMPA	U001546606	DEROSE INDUSTRIES	8504 E ADAMO DR		UST, LUST	9103587
TAMPA	91040182		5056 ADAMS DR		HMIRS	
TAMPA	1000412548	CONTINENTAL AIRLINES	AIRSIDE E TAMPA INTL AIRPORT	33607	RCRIS-SQG, FINDS	
TAMPA	91080614		ANDERSON RD		HMIRS	
TAMPA	U001378037	BARNETT BANK BLDG-FORMER	2000 ASHLEY DR		UST, LUST	9101785
TAMPA	1000161395	NCNB TYPESETTING & COPY CENTER	400 N ASHLEY ST 16 FLOOR	33602	RCRIS-SQG, FINDS, UST	
TAMPA	1000362459	HARRIS PAINT COMPANY	ATTN: B. WILLIAMS, TECH/DIR	33601	TSCA	
TAMPA	U001378101	USE 9201677	3001 NORTH BLVD		UST, LUST	299200783
TAMPA	U001356432	TAMPA,CITY-BD OF TRUSTEES PENSION FUND	3001 NORTH BLVD	33601	UST, LUST	9201677
TAMPA	S101264578	CRAFTSMAN ROOFERS	4704 NORTH BLVD FL AVE	33603	LUST	9301008
TAMPA	100243419	PATHOLOGIST'S REFERENCE LAB	402 SOUTH BLVD	33606	RCRIS-SQG, FINDS	
TAMPA	U001356374	AUBURN PLASTICS INC	6008 BONACKER DR	33610	UST, LUST	9103281
TAMPA	S100020977	BOUGAINVILLEA TRASH LF	BOUGAINVILLEA / 46TH ST		SWF/LF	
TAMPA	U001356315	TERRELL OIL	2101 N BOULEVARD	33602	UST, LUST	9101587
TAMPA	U001354679	MATASSINI PROPERTY	2121 N BOULEVARD	33602	UST, LUST	8625460
TAMPA	1000189543	GARDINIER, INC.	P.O. BOX 3269	33601	TSCA	
TAMPA	U001355309	J CLIFFORD MACDONALD CENTER	4304 W BOYSCOUT BLVD	33607	UST, LUST	8627987
TAMPA	1000396433	ED TAYLOR CONSTRUCTION	5909 C BRECKENRIDGE PKWY	33610	RCRIS-SQG, FINDS	
TAMPA	1000361682	CARRIER SERVICE CENTER	5911-A BRECKENRIDGE PARKWAY	33610	RCRIS-SQG, FINDS	
TAMPA	S101136997	REEVES SOUTHEAST GALVANIZING	9510-20 E BROADWAY		SHWS	
TAMPA	U001356207	PRODUCTS FOR INDUSTRY INC	4318 E BROADWAY AVE	33605	UST, LUST	9100230
TAMPA	S101264762	CSX TRANSPORTATION INC-RALSTON PURINA	3702 E BROADWAY AVE	33605	LUST	9101417
TAMPA	S100990461	TAMPA MOBILE REPAIR	4701 E BROADWAY AVE	33605	LUST	9400547
TAMPA	S101546203	ALL POINTS WAREHOUSE-OLD GAS STATION	4701 E BROADWAY AVE	33605	LUST	9501491
TAMPA	1000733847	BROLD & COUNTY DUMP	N BROWARD ST	33601	FINDS	
TAMPA	1000736529	FARM STORE #374	19707 BRUCE B DOWNS BLVD	33602	FINDS	
TAMPA	U001378091	HILLSBOROUGH TIRE & WHEEL INC	8406 E BUFFALO AVE		UST, LUST	9200417
TAMPA	U001353925	SUPER KWIK MART #1	9702 E BUFFALO AVE	33610	UST, LUST	8508993

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	U001355839	HUNTER, INC., MIKE	9516 E BUFFALO AVE	33610	UST, LUST	8841364
TAMPA	U001355124	KEARNEY DEVELOPMENT CO INC	8621 E BUFFALO AVE	33610	UST, LUST	8627162
TAMPA	1000736477	FARM STORE #390	904 BUFFALO AVENUE	33603	FINDS, UST, LUST	8630323
TAMPA	1000335909	UNION CARBIDE CORP/SOLVENTS TE	3202 CARBIDE AVE	33605	RCRIS-SQG, FINDS, CERC-NFRAP	
TAMPA	94110828		41S CARGILL		HMIRS	
TAMPA	90020623		CAUSEWAY BLVD		HMIRS	
TAMPA	91050366		10109 CEDAR RUN		HMIRS	
TAMPA	91050561		10109 CEDAR RUN		HMIRS	
TAMPA	90040012		10109 CEDAR RUN		HMIRS	
TAMPA	U001378008	TAMPA DOWNTOWN INVEST LTD PROPERTY	CITY BLK WASHINGTON N MORGAN W		UST, LUST	8943604
TAMPA	1000414330	MYRTLE HILL CEMETERY	4701 EAST CNELSEA	33610	RCRIS-SQG, FINDS	
TAMPA	U001378083	CONTINENTAL AIRLINES RESERVATIONS	4101 W COLUMBUS DR		UST	299103404
TAMPA	U001354036	SUNCOAST HELICOPTERS, INC.	4111 W COLUMBUS DR	33607	UST, LUST	298624772
TAMPA	90030513		COMMERCE BLVD		HMIRS	
TAMPA	1000344847	TAMPA BAY WHOLESALE CLEANERS	5452 56TH COMMERCE PARK DR	33610	RCRIS-SQG, FINDS	
TAMPA	U002217725	FL GUNITE & EQUIPMENT INC	4414 N COOPER		UST	299502014
TAMPA	S100563782	KASSOUF KIMMERLING/AKA TIMBERLAKE	NE COR 58 / COLUMBUS DR		SHWS	
TAMPA	S101137001	SIXTY-SECOND STREET DUMP	NW COR OF COLUMBUS / 62 ST		SHWS	
TAMPA	U001355673	FL DEPT OF TRANSPORTATION CROSSTOWN EX	7353 CROSSTOWN EXPRESSWAY E	33601	UST	298736812
TAMPA	U001355241	CONTINENTAL BAKING CO	420 S DAKOTA AVE	33606	UST, LUST, AST	8627646
TAMPA	U001378078	YOUR ATTIC	4510 S DALE MABRY AVE		UST	299103154
TAMPA	U001354244	MOBIL #02-CNH	1101 N DALE MABRY HWY & I-275	33607	UST, LUST	8624998
TAMPA	90030047		DAVIS ISLAND		HMIRS	
TAMPA	U001354932	TAMPA GENERAL HOSPITAL	DAVIS ISLANDS	33601	UST	8625729
TAMPA	1000698539	TAMPA GENERAL HOSPITAL	DAVIS ISLANDS	33601	RCRIS-SQG, LUST, AST	
TAMPA	1000732921	HILLSBOROUGH CNTY HOSP AUTH DBA TAMPA GEN HSP	DAVIS ISLAND	33606	FINDS	
TAMPA	8802523	TAMPA INTERNATIONAL AIRPORT EAST SIDE OF AIRPORT	DELTA MAINTENANCE HANGAR		ERNS	
TAMPA	94091101		6 DOING RACK		HMIRS	
TAMPA	S101547649	EDWARD DOROUGH SITE	1806 DOWNING CIR		SHWS	
TAMPA	1000858717	BUFFALO CHEVRON INC	802 E DR MLK JR BLVD	33603	RCRIS-SQG, FINDS	
TAMPA	U001353965	CHEVRON #48083	2735 W DR MARTIN LUTHER KING JR	33607	UST, LUST	8509058
TAMPA	A100008718	TAMPA BAY PILOTS	58L EGMONT KEY	33601	AST	
TAMPA	U001378041	REDWING CARRIERS INC	EISENHOWER BLVD & COURTNEY CSWY		UST	299101830
TAMPA	U001378026	TAMPA CITY-S REGIONAL PARKING FACILITY	ELLA MAE ST		UST	299100404
TAMPA	U001378110	TAMPA PORT AUTHORITY-GARRISON CHANNEL	1301 ELLA MAE ST		UST, LUST	9201835
TAMPA	1000498063	GARRISON STEVEDORES	1101 E ELLAMAE	33605	FINDS	
TAMPA	U002217727	TWIN LAKES	E END OF BLOOMINGDALE AVE		UST, LUST	299502111
TAMPA	91090759		ERLICH & HUTCHENSON		HMIRS	
TAMPA	U001378033	ELI WITT CO	EUNICE		UST, LUST	299101430
TAMPA	S100020986	NORTHEAST HILLSBOROUGH LF	EUREKA SP RD / HAMILTON RD		SWFLF	
TAMPA	S100300529	FALKENBURG RD YARD TRASH PROCESSING	FALKENBURG RD, 1MI N SR-60		SWFLF	
TAMPA	U001354218	MAJIK MARKET #414-08	5320 N FALKENBURG RD	33610	UST, LUST	8624968
TAMPA	9106432	DUTCH HARBOR MAGONE MARINE SERVICE	FALLS		ERNS	
TAMPA	S100020982	HILLS COUNTY WASTE-TO-ENERGY PLANT	210 FAULKENBURG RD		SWFLF	
TAMPA	U001544418	CRAFTSMAN ROOFERS	4704 N FL AVE		UST	299301008

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	1000411987	AUSTIN & SON AUTO ELECTRIC	3909 FLA AVE	33603	RCRIS-SQG, FINDS	
TAMPA	U001356308	SPRING PROPERTY	502 E FLORIBRASKA AVE	33603	UST, LUST	9101452
TAMPA	1000501629	TAMPA BRASS & ALUMINUM	FLORIDA MINING BLVD	33601	FINDS	
TAMPA	S101264466	TAMPA ELECTRIC CO.-HOOKERS POINT STA.	FOOT OF HEMLOCK ST	33605	LUST, AST	8839203
TAMPA	U001378027	RENFOE PROPERTY	9402 E FOWLER AVE		UST	299100524
TAMPA	U000136451	COLONY SHOPS OF FL INC	3415 E FRONTAGE RD	33607	UST, LUST	9063924
TAMPA	U001713405	GANDY AUTO AIR	3821 GANDY BLVE	33601	UST, LUST	299400143
TAMPA	94010954		100 GATX DRIVE		HMIRS	
TAMPA	S101011580	AUTHORIZED APPLIANCE RECLAIMING CTR	2420 GELMAN PLACE, .5MI E US41		SWF/LF	
TAMPA	1000733904	STEEL SERVICES TAMPA	GRANT & S SLIP	33605	FINDS	
TAMPA	1000932102	GTE-SUMTER REPORT CTR	GTE-P O BOX 110 MC 711	33601	FINDS	
TAMPA	91050244		6110 GUNN HIGHWAY		HMIRS	
TAMPA	U001355178	GTE OF FL KEYSTONE EAX	16829 GUNN HWY	33601	UST	298627332
TAMPA	S101264757	LOUISVILLE SCRAP MATERIAL CO	2799 GUY VERGER BLVD	33605	LUST, AST	9063954
TAMPA	U001354260	CF INDUSTRIES INC-TAMPA PHOSPHATE	2520 GUY VERGER BLVD	33605	LUST, LUST, AST	8625014
TAMPA	U001377993	HILLSBOROUGH CNTY SCHOOL BD-FURNITURE	1801 N HABANA & UNION		UST	298736478
TAMPA	1000498064	CITY READY MIX	HANNA RD	33610	FINDS	
TAMPA	1000502102	SUN ENVIRONMENTAL INC	E HEMLOCK AVE HOOKERS PT PW PL		FINDS	
TAMPA	U001355655	R L N CORPORATION	2803 E HILLSBORO AVE	33605	FINDS	
TAMPA	U001355373	FIRESTONE #46-EASTGATE	2401 E HILLSBORO AVE	33610	UST, LUST	8736669
TAMPA	1000737480	MOBIL OIL CORP SS# A67	902 E HILLSBORO AVE	33610	UST, LUST	8731771
TAMPA	U001378035	DISCOUNT TIRE TOWN	701 HILLSBOROUGH AVE	33606	FINDS, UST, LUST	8625031
TAMPA	U001546669	EXXON #4-0490	11292 HILLSBOROUGH BLVD		UST, LUST	9101615
TAMPA	1000932229	ESTECH, INC	5226 E HILLSBOROUGH P. O. BOX 11308	33610	UST	299102024
TAMPA	1000344927	TAMPA UNKNOWN SPILL	HILLSBOROUGH COUNTY		FINDS	
TAMPA	1000292187	HILLSBOROUGH RIVER ABANDONED D	HILLSBOROUGH COUNTY	33602	CERCLIS, FINDS	
TAMPA	91070743		HOOKERS POINT	33602	HMIRS	
TAMPA	94120986		4700 N HOOVER BLVD		HMIRS	
TAMPA	U001356211	KWIK PEP STATION	HOWARD APTS	33606	UST, LUST	299100288
TAMPA	U001378036	HUMBLE OIL CORP	US HWY 301 N & ALONZO RD		UST, LUST	9101724
TAMPA	U001354016	SOUTHWEST FL WATER MGMT DIST.	US HWY 301	33610	UST, LUST, AST	8624752
TAMPA	U001354440	TAMPA 301 TRUCK STOP	6503 US HWY 301 N	33610	UST, LUST	8625206
TAMPA	U001354420	RACETRAC #278	4911 N HWY 301	33610	UST, LUST	8625186
TAMPA	1000822586	CIRCLE K #7494	2820 US HWY 301 S	33605	RCRIS-SQG, FINDS, LUST	
TAMPA	91030636		7801 INDUSTRIAL LANE		HMIRS	
TAMPA	1000881223	MURPHY OIL USA INC	1306 INGRAM AVE	33605	RCRIS-SQG, LUST	
TAMPA	1000497143	MURPHY OIL USA	1306 INGRAM AVE	33605	FINDS, AST	8625598
TAMPA	U001355929	TAMPA,CITY-FIRE STATION #19	4916 INGRAM	33602	UST, LUST	8842519
TAMPA	90020271		INTERBAY AND DALE MABRY		HMIRS	
TAMPA	U001355133	HALL OF FAME INN-GOLF COURSE MAINT	INTERNATIONAL PLAZA	33607	UST, LUST	8627185
TAMPA	U002217720	KOTLER FALK PARTNERSHIP PROPERTY	2508 IVEY ST	33601	UST, LUST	299501877
TAMPA	U001962945	SOUTHWEST FO WATER MNGT DIST - S-159	JEFFERSON RD & HWY 301	33602	UST, LUST	299401243
TAMPA	9100947	PORT OF BEAUMONT CARROL ST. WHARF	ST. JOHN ST.		ERNS	
TAMPA	8700298	1220 U.S. STATE ROAD 301 AT	JUST EAST OF TAMPA		ERNS	
		WAREHOUSE SUPPLY 813-621-3				
TAMPA	S100020984	KINGSWAY RD LF (DAVID J JOSEPH)	KINGSWAY RD, 0.5MI N OF I4		SWF/LF	
TAMPA	1000932731	ERNY SUPPLY CO	8302 LAUREL FAIR CIRCLE/SUITE 130	33610	FINDS	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	S101646524	NORTHWEST HILLSBOROR CLASS III LF	LINEBAUGH AVE, E OF SHELDON RD		SWF/LF	
TAMPA	S10020988	NORTHWEST HILLSBOROUGH SLF	LINEBAUGH AVE		SWF/LF	
TAMPA	U001356382	PALMA CEIA VILLAGE SHOPPING CTR	3225 MACDILL AVE	33606	UST, LUST	9200229
TAMPA	94091414		8950 MAISLIN DRIVE		HMIRS	
TAMPA	92070250		8950 MAISLIN DR		HMIRS	
TAMPA	90060743		8950 MAISLIN DR		HMIRS	
TAMPA	91040581		11210 MALCOLM MCKINLEY DR		HMIRS	
TAMPA	S101011588	OLD MANHATTAN AVE CLASS I LF	S MANAHATTAN AVE / RICHARDSON		SWF/LF	
TAMPA	100089637	INTERPAK INC	6932 SOUTH MANHATTEN STREET		RCRIS-SQG	
TAMPA	9101545	OFF OF I-70 BOX BURGER LEASE	MARINA DR		ERNS	
TAMPA	A100008755	GTE OF FL TAMPA MAIN	615 MARION ST	33601	AST	9101518
TAMPA	U001378034	MARIANI ASPHALT PARCEL	MARITIME BLVD		UST, LUST	
TAMPA	90080774		MARITIME BLVD		HMIRS	
TAMPA	1000496815	TAMPA HOOKERS POINT WWTP	20700 MARITIME BLVD	33605	FINDS	
TAMPA	91060740		8950 MARSLIN DR		HMIRS	
TAMPA	94051530		MARTIN LUTHER KING BLVD		HMIRS	
TAMPA	U001378107	GOOD SHEPHERD BAPTIST CHURCH INC	8119 E MARTIN LUTHER KING JR		UST, LUST	9201207
TAMPA	U001355401	ANSWERRITE PROFESSIONAL TEL SERVICE	510 MARTIN LUTHER KING BLVD	33603	UST, LUST	298732454
TAMPA	U001546655	SAINT JOSEPHS WOMENS HOSPITAL	3030 W MARTIN L KING JR BLVD	33607	UST, LUST	299102172
TAMPA	S100705159	CITGO PETROLEUM CORP	801 MCCLOSKEY BLVD	33605	UST, AST	8625797
TAMPA	U000125105	AMOCO OIL CO-TERMINAL TAMPA	848 MCCLOSKEY BLVD	33605	UST, LUST	8735210
TAMPA	1000736103	TEXACO NO 24201342	3102 S MCDILL AVE	33606	FINDS	
TAMPA	1000498532	MCKAY BAY RTE PROJ	MCKAY BAY & ADAMS DR	33605	FINDS	
TAMPA	U001354829	FOGARTY VAN LINES-TRUCK SERVICE	N MERIDIAN & PLATT	33605	FINDS	
TAMPA	U001378052	RISSE PETROLEUM TANKER SPILL	I-275 MILE MARKER 57	33602	UST, LUST	298625622
TAMPA	94070231		14 MILEMARKER 13		UST	299102311
TAMPA	S100020990	NORTHWEST REGIONAL SLUDGE MGMT FAC	NEAR SHELDON RD / MOBLEY RD		HMIRS	
TAMPA	U001355878	COMMERCE PLAZA	12811 N NEBRASKA AVE	33602	SWF/LF	
TAMPA	U001356274	CSX TRANSPORTATION-UNION STATION	601 NEBRASKA AVE	33602	UST, LUST	8842069
TAMPA	1000344857	TAMPA ELECTRIC CO CENTRAL TEST	1898 NUCCIO PKY	33607	UST, LUST	9101044
TAMPA	1000736938	YBOR DATA CENTER	1898 NUCCIO PKWY	33605	RCRIS-SQG, FINDS	
TAMPA	1000933622	POLLUTION PREVENTION SVC INC	4515 OAK FAIR BLVD STE 103	33610	FINDS	
TAMPA	8802486	PAY-LESS SERVICE STATION	SOUTH OF COOPER'S POND APARTMENT BUILDING		ERNS	
TAMPA	S100021003	TECO COMPOSTING FACILITY	W OF SHELDON RD N OF WATERS AV		SWF/LF	
TAMPA	9105702	EAST LEVEE OF THE CHAIN OF ROCKS CANAL	OHIO RIVER MILE 241.5		ERNS	
TAMPA	U001378012	GTE OF FL OLDSMAR	12750 OLD MEMORIAL HWY		UST	299045723
TAMPA	91030541		6049 OLD 41A HWY		HMIRS	
TAMPA	90040283		OLD HOPEWELL RD		HMIRS	
TAMPA	1000498843	REED MINERALS	OLD HWY 41 & JENSEN		FINDS	
TAMPA	U001356447	HARBOR ISLAND	ONE HARBOUR PLACE #270	33602	UST, LUST, AST	9202003
TAMPA	U001823907	I-75 LTD PARTNERSHIP PROPERTY	PALM RIVER & I-75		UST	299400305
TAMPA	U001823906	I 75 LTD PARTNERSHIP PROPERTY	PALM RIVER & I 75		UST, LUST	299400291
TAMPA	U001378105	SHELL STATION	8210 PARKEDGE DR		UST	299201084
TAMPA	91080428		PENDOLA POINT RD		HMIRS	
TAMPA	91050674		PENDOLA POINT DRIVE		HMIRS	
TAMPA	U001354946	GTE OF FL MAIN FLEET	PIERCE ST & ZACK ST	33601	UST	298625743

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	1000740400	TECNUM	2411 PLYMOUTH ROAD	33602	FINDS	
TAMPA	1000733612	PREDELIVERY SERVICE CORP	1803 E POINT DR	33605	FINDS	
TAMPA	U001378002	GRACE,W.R.	PORT SUTTON RD		UST	298840906
TAMPA	8905271	IMC TERMINAL	PORT SUTTON AREA		ERNS	
TAMPA	92100051		PORT TAMPA		HMIRS	
TAMPA	1000932117	CARGILL FERT.-TAMPA AMM TERM	PORT SUTTON RD	33605	FINDS	
TAMPA	8805677	MP AZA886.9	POWELL MEADOW SUBDIVISION		ERNS	
TAMPA	1000902018	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902017	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902016	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902015	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902014	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902013	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	1000902012	THEOCHEM LABS. INC.	7373 ROWELETT PARK DR.	33610	TRIS	
TAMPA	90050525		9102 SABAL INDUSTRIAL BLVD		HMIRS	
TAMPA	U001379124	HUMANA GAS STATION	SEMINOLE BLVD / BLOSSOM LAKE DR		UST, LUST	9103454
TAMPA	8910558	SHELDON RD. SUBSTATION	SHELDON RD. AND LINEBAUGH AVE.		ERNS	
TAMPA	94050658		8425 SHELDON ROAD		HMIRS	
TAMPA	8805616		SHELL TERMINAL		ERNS	
TAMPA	1000259958	NATIONAL SEA PRODUCTS CORP TP	1356 SHORELINE DR	33605	RCRIS-SQG, FINDS, UST, AST	298942800
TAMPA	U001378011	TAMPA,CITY-NW REPUMP STATION	5602 SITKA		UST, AST	298945433
TAMPA	U001354138	DOLLAR RENT-A-CAR	4720 W SPRUCE ST	33607	UST, LUST	298624882
TAMPA	U001354812	ALAMO RENT-A-CAR #030	5402 W SPRUCE ST	33607	UST, LUST	8625604
TAMPA	U001354876	CENTRAL TRUCK LINES	3902 W SPRUCE ST	33607	UST, LUST	8625670
TAMPA	S100643330	GENERAL RENT-A-CAR	4606 W SPRUCE ST	33607	LUST	8837593
TAMPA	U001355159	ALAMO RENT-A-CAR	5124 W SPRUCE ST	33607	UST, LUST	298627265
TAMPA	U001354879	ENTERPRISE RENT A CAR	4912 W SPRUCE ST	33607	UST, LUST	8625673
TAMPA	U001356092	VALUE RENT-A-CAR	5202/5210 SPRUCE ST	33607	UST, LUST	299045619
TAMPA	U001378085	USE 299102845	1010-26 19TH ST		UST, LUST	9103447
TAMPA	U002113438	GORDON PROPERTY	1009 13TH ST		UST, LUST	299501598
TAMPA	U001378122	CENTRAL SOD & LANDSCAPING	4419 SOUTH ST		UST, LUST	9202389
TAMPA	U001544416	FORTNA, ALBERT	8813-8815 15TH ST		UST	299301002
TAMPA	95020737		14516 22ND ST SKIPPER RD		HMIRS	
TAMPA	A100009081	P D T TRUCKING	2005 43RD ST N	33601	AST	
TAMPA	1000733594	STAR ENTERPRISE	519 19TH ST	33601	FINDS	
TAMPA	U001355028	MCCLENDON OIL CO, INC./W.K.	1409 22ND ST	33605	UST, LUST	8626340
TAMPA	U001355604	HILLSBOROUGH CNTY SCHOOL BD-GROUNDS	3838 50TH ST	33605	UST, LUST	8736494
TAMPA	92081132		7125 30TH STREET		HMIRS	
TAMPA	92081131		7125 30TH STREET		HMIRS	
TAMPA	U001378024	USE 298841046	N TAMPA ST		UST, LUST	9100014
TAMPA	90040238		TAMPA INTL AIRPORT		HMIRS	
TAMPA	S101264751	TAMPA,CITY-AIRPORT PUMPING STATION	4450 S TAMPA AIRPORT BLVD	33607	LUST, AST	8841127
TAMPA	U001354628	DELTA AIR LINES INC-TPA	TAMPA INTERNATIONAL AIRPORT	33607	UST, LUST, AST	8625408
TAMPA	1000821146	HYATT REGENCY TAMPA	2 TAMPA CITY CENTER	33602	RCRIS-SQG, FINDS	
TAMPA	8705675	8401 N. HWY 301	TEXACO GAS STATION		ERNS	
TAMPA	8703010	1333 W. BRANDEN BLVD	THE PAITO SHOP		ERNS	
TAMPA	9108492	140 SILVESTER RD.	ON THE JAMES RIVER		ERNS	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	U001544411	VETERANS EXWY ROW SITES	NORTH TO SOUTH TO TAMPA		UST	299300656
TAMPA	92110135		4537 TRANSPORT DR		HMIRS	
TAMPA	94030979		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	94020596		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92080973		4537 TRANSPORT DR		HMIRS	
TAMPA	92070317		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91060250		4537 TRANSPORT DR		HMIRS	
TAMPA	90080105		4537 TRANSPORT DR		HMIRS	
TAMPA	90080099		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	90080098		4537 TRANSPORT		HMIRS	
TAMPA	90080097		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	90080096		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92080058		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92110418		4537 TRANSPORT DR		HMIRS	
TAMPA	91070642		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91070638		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	94070618		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	94070616		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	94080967		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91030415		4537 TRANSPORT DR		HMIRS	
TAMPA	91030395		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92060357		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92040377		4537 TRANSPORT DR		HMIRS	
TAMPA	92040371		4537 TRANSPORT DR		HMIRS	
TAMPA	92030691		4537 TRANSPORT DR		HMIRS	
TAMPA	90080794		4537 TRANSPORT DR		HMIRS	
TAMPA	90080785		4537 TRANSPORT DR		HMIRS	
TAMPA	93010192		4537 TRANSPORT DR		HMIRS	
TAMPA	92090348		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	94101167		4537 TRANSPORT DR		HMIRS	
TAMPA	94101155		4537 TRANSPORT DR		HMIRS	
TAMPA	92070498		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92070493		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92070492		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91080686		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91080671		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92120072		4537 TRANSPORT DR		HMIRS	
TAMPA	92100744		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92080328		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92080315		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91060569		4537 TRANSPORT DR		HMIRS	
TAMPA	91060556		4537 TRANSPORT DR		HMIRS	
TAMPA	91050521		4537 TRANSPORT DR		HMIRS	
TAMPA	91030489		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91030485		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	90090173		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	93010255		4537 TRANSPORT DR		HMIRS	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
TAMPA	94051433		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91020163		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91020161		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	90080573		4537 TRANSPORT DR		HMIRS	
TAMPA	93010564		4537 TRANSPORT DR.		HMIRS	
TAMPA	92090588		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92070272		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92020652		4537 TRANSPORT DR		HMIRS	
TAMPA	91070266		4537 TRANSPORT DR		HMIRS	
TAMPA	94080073		4537 TRANSPORT DR		HMIRS	
TAMPA	91020476		4537 TRANSPORT DR		HMIRS	
TAMPA	93010296		4537 TRANSPORT DR.		HMIRS	
TAMPA	90090383		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	92070304		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	94081583		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	90070446		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	94110676		4537 TRANSPORT DR		HMIRS	
TAMPA	92110127		4537 TRANSPORT DR		HMIRS	
TAMPA	92020741		4537 TRANSPORT DR		HMIRS	
TAMPA	91081114		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	91081091		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	94090107		4537 TRANSPORT DRIVE		HMIRS	
TAMPA	94100377		4536 TRANSPORT DRIVE		HMIRS	
TAMPA	U001545548	COURIER DISPATCH	4111 TRASK AVE		UST, LUST	298942841
TAMPA	92050223		5440 WEST TYSON		HMIRS	
TAMPA	U001355901	STANDARD GYPSUM	UNKNOWN	33605	UST, LUST	8842369
TAMPA	1000700432	CONSUMER PRODUCTS INC	10824 US92E		RCRIS-SQG	
TAMPA	1000933011	DODGE AIRCRAFT	9334 VANDENBERG AIRPORT RD A	33610	FINDS	
TAMPA	1000933010	VANDENBERG AIRPORT INC	9334 VANDENBERG AIRPORT RD B	33610	FINDS	
TAMPA	S100563798	UNIVERSAL DOOR / DOT LF	VETERANS EXPWY @ BENJAMIN RD		SWF/LF	
TAMPA	S101136987	PEAK OIL/BAY DRUM	1/4 MI W OF FAULKENBERG RD, S OF SR 574		SHWS	
TAMPA	92110055		WESTSHORE BLVD. & TYSON ST		HMIRS	
TAMPA	U001356392	EMBASSY HOTEL	555 WESTSHORE BLVD	33602	UST, LUST, AST	9200540
TAMPA	1000265816	HAWK AIRCRAFT REFINISHING	WILKINS RD	33610	FINDS	
TAMPA	S100020989	NORTHWEST HILLSBOROUGH TRANSFER STA	WILSKY RD / LINEBAUGH AVE		SWF/LF	
TAMPA	92040092		YARD		HMIRS	

EPA Waste Codes Addendum

Code	Description
D000	NOT DEFINED
D001	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
D002	A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
D003	A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.
D004	ARSENIC
D005	BARIUM
D006	CADMIUM
D007	CHROMIUM
D008	LEAD
D009	MERCURY
D011	SILVER
D018	BENZENE
D021	CHLOROBENZENE
D027	1,4-DICHLOROBENZENE
D035	METHYL ETHYL KETONE
D039	TETRACHLOROETHYLENE
D040	TRICHLOROETHYLENE
F001	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS;

EPA Waste Codes Addendum

Code	Description
	ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F002	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F003	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F004	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: CRESOLS AND CRESYLIC ACID, AND NITROBENZENE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F005	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F006	WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.
K086	SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.
NONE	NONE
P028	BENZENE, (CHLOROMETHYL)-

EPA Waste Codes Addendum

Code	Description
P028	BENZYL CHLORIDE
U002	ACETONE (I)
U002	2-PROPANONE (I)
U112	ACETIC ACID ETHYL ESTER (I)
U112	ETHYL ACETATE (I)
U159	2-BUTANONE (I,T)
U159	METHYL ETHYL KETONE (MEK) (I,T)
U220	BENZENE, METHYL-
U220	TOLUENE
U359	ETHANOL, 2-ETHOXY-
U359	ETHYLENE GLYCOL MONOETHYL ETHER